

260 N. MONTGOMERY STREET AND 255 N. AUTUMN STREETSAN JOSE, CALIFORNIA

PHASE I ENVIRONMENTAL SITE ASSESSMENT UPDATE

SUBMITTED TO

Mr. Jay Bechtel Google LLC 1600 Amphitheatre Parkway Mountain View, CA 94043

PREPARED BY

ENGEO Incorporated

March 13, 2019

PROJECT NO.

14121.000.001





Project No. **14121.000.001**

March 13, 2019

Mr. Jay Bechtel Google LLC 1600 Amphitheatre Parkway Mountain View, CA 94043

Subject: 260 N. Montgomery and 255 N. Autumn Street

San Jose, California

PHASE I ENVIRONMENTAL SITE ASSESSMENT UPDATE

Dear Mr. Bechtel:

ENGEO is pleased to present our phase I environmental site assessment update of the subject property (Property), located in San Jose, California. The attached report includes a description of the site assessment activities, along with ENGEO's findings, opinions, and conclusions regarding the Property.

ENGEO has the specific qualifications based on education, training, and experience to assess the nature, history, and setting of the Property, and has developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312 and the American Standard Testing Method (ASTM) Practice E1527-13. We declare that, to the best of our professional knowledge and belief, the responsible charge for this study meets the definition of Environmental Professional as defined in Section 312.10 of 40 CFR Part 312 and ASTM E1527-13.

We are pleased to be of service to you on this project. If you have any questions concerning the contents of our report, please contact us.

Sincerely,

ENGEO Incorporated

Divya Bhargava, PE

db/jaa/dt

Jeffrey A. Adams, PhD, PE

TABLE OF CONTENTS

1 67	TED		тол	KIC N/I	ITTAL
	IFR	\ /r		IVICIVI	

1.0	INTRO	DUCT	ION		1
	1.1	SITE LO	CATION	AND DESCRIPTION	1
2.0	PREV	IOUS E	ENVIRO	NMENTAL REPORTS	2
				RECORD SOURCES	
	3.1			/IRONMENTAL RECORDS	
		3.1.1 3.1.2	Subject F Other Pro	Propertyoperties	3
	3.2	ADDITI	ONAL EN	VIRONMENTAL RECORDS	7
		3.2.1	Subject F	Property	7
			3.2.1.1	Other Properties	8
4.0	SITE F	RECON	NAISS	ANCE	16
	4.1 4.2 4.3 4.4 4.5 4.6	GENER EXTER INTERI ASBES	RAL SITE IOR OBS OR OBSE TOS-COM	/ SETTING ERVATIONS ERVATIONS NTAINING MATERIALS AND LEAD-BASED JALITY	16 17 18 PAINT18
5.0	FINDI	NGS A	ND CO	NCLUSIONS	19
6.0	LIMIT	ATION	S AND	UNIFORMITY OF CONDITIONS	20
REFE	RENCE	ES			
FIGUR	RES				
APPEI	NDIX A	– Envi	ronmental	Data Resources, Inc., Radius Map Report	



1.0 INTRODUCTION

The scope of services for this phase I environmental site assessment (ESA) update included the following:

- A review of publicly available and practically reviewable standard local, state, tribal, and federal environmental record sources.
- A review of previous environmental reports prepared for the Property.
- A reconnaissance of the Property to review site use and current conditions. The reconnaissance was conducted to check for the storage, use, production or disposal of hazardous or potentially hazardous materials.
- Preparation of this report with our findings, opinions, and conclusions.

1.1 SITE LOCATION AND DESCRIPTION

The Property is located at 260 N. Montgomery and 255 N. Autumn Street in San Jose, California (Figures 1 and 2). The Property is comprised of two adjacent parcels, totaling approximately 0.45 acre in area, and is identified by Assessor's Parcel Numbers (APNs) 259-29-012 and 259-29-020 (Figure 3).

The Property is currently occupied by a landscaping business. There are three buildings onsite; one main building used as an office, maintenance and storage area, and hazardous materials storage; one shipping container converted to pesticide/herbicide/fertilizer storage; and an additional shipping container converted to a supply shed. The buildings are set on a concrete foundation with a single drain south of the southern side of the building. The area around the buildings is gravel.

Residential uses are present to the north of the Property. To the south of 255 N. Autumn Street parcel is a residence, to the south of the 260 N. Montgomery parcel is a motorcycle club and automotive repair shop.

According to the Federal Emergency Management Agency (FEMA)'s National Flood Hazard Layer (NFHL)¹, the Property lies within Zone D (area of undetermined but possible flood hazard).

According to the National Wetlands Inventory², there are no wetlands mapped on the Property.

² .. Fish and Wildlife Service, National Wetlands Inventory; https://www.fws.gov/wetlands/.



-

¹ <u>https://www.fema.gov/flood-zones</u>

2.0 PREVIOUS ENVIRONMENTAL REPORTS

ENGEO Incorporated; Phase I Environmental Site Assessment, 260 N. Montgomery Street and 255 N. Autumn Street, San Jose, California; September 11, 2018

ENGEO performed a phase I ESA of the Property in 2018. No Recognized Environmental Conditions (RECs), no historical RECs, and no controlled RECs were identified for the Property. ENGEO recognized that the Property had a history of hazardous chemical storage and use, and found evidence of minor violations and spills. ENGEO recommended a phase II site assessment consisting of shallow soil sampling and a Site Management Plan to outline protocols for soil and groundwater handling. Additionally, due to the age of the structures on the Property ENGEO recommended a lead-based paint survey be performed prior to demolition.

ENGEO Incorporated; Phase II Environmental Site Assessment, 260 N. Montgomery Street and 255 N. Autumn Street, San Jose, California, October 10, 2018

ENGEO conducted a phase II ESA of the Property to determine if environmental impacts were present from onsite activities, and how such impacts could present future developmental constraints and/or health risks. ENGEO collected 13 surface samples (B1 through B13) across the Property at approximately 1 foot below the ground surface. Soil samples were analyzed for metals, volatile organic compounds (VOCs), gasoline, diesel, motor oil, pesticides, and semi-volatile organic compounds (SVOCs). Concentrations of lead, chromium, and arsenic in some soil samples exceeded 50 milligrams per kilogram (mg/kg), which is 10 times the soluble threshold limit concentration (STLC) of 5 milligrams per liter (mg/L) for each metal. Similarly, concentrations of lead and arsenic in some soil samples exceeded 100 mg/kg, which is 20 times the toxicity characteristic leaching procedure (TCLP) of 5 mg/L. Soluble testing of lead, chromium, and arsenic indicated that the soil at sample locations B1, B3, B5, and B10 would be categorized as California hazardous material if it were offhauled for disposal. Concentrations of pesticides and SVOCs exceeding ESLs were mostly limited to the area of the building, and generally lower concentrations were reported south of the main building. Based on the analytical results, and the low concentrations of motor oil, gasoline, and diesel fuel noted on the Property, it appeared that operations onsite may have had minor impacts on surface soils, but are not indicative of a significant environmental issue. ENGEO concluded that further soil characterization should be conducted to further delineate soil impacts at the Property.

ENGEO Incorporated, Estimated Quantity of Impacted Material and Remedial Cost, 260 N. Montgomery and 255 N. Autumn Street, San Jose, California, October 31, 2018

ENGEO estimated the volume of hazardous-materials-impacted surface soils and summarized the estimated costs for remediation. The source of impacts was likely associated long-term use of the Property, and estimated depth of impacts was set at 3 feet below the ground surface based on sample results from 1 foot below the ground surface and assumption that attenuation would be observed with depth. The total impacted soil volume was estimated at 2,300 cubic yards (3,500 tons), and the cost to excavate and dispose the soil was estimated at \$525,000 (\$150/ton). With adjustment for the cost and disposal of clean soil (\$38/ton) associated with this volume, the total disposal cost for impacted soils at the Property was estimated at \$392,000. These estimates did not include cost of importing clean backfill.



3.0 ENVIRONMENTAL RECORD SOURCES

EDR performed a search of federal, tribal, state, and local databases regarding the Property and nearby properties. Details regarding the databases searched by EDR are provided in Appendix A. A list of the facilities documented by EDR within the approximate minimum search distance of the Property is provided below.

3.1 STANDARD ENVIRONMENTAL RECORDS

3.1.1 Subject Property

The Property is not listed on the Standard Environmental Record source databases.

3.1.2 Other Properties

The following database(s) include(s) facilities listed within the appropriate ASTM search distances of the Property on Standard Environmental Records sources.

TABLE 3.1.2-1: Standard Environmental Records - Other Properties within ASTM Radius

CALIF STEAM CLEANERS 560 W JULION ST RCRA-SQG SAN JOSE SPORTS ARENA 525 WEST SANTA CLARA STREET SAN JOSE ARENA 555 SAINT JOHN LUST PLATFORM 16 440 W JULIAN ST CPS-SLIC SAN JOSE ARENA (JULIAN ST.) 565 W JULIAN ST CPS-SLIC SAN JOSE ARENA (JULIAN ST.) 565 W JULIAN ST RCRA-SQG SOUTH BAY DRIVELINE INC 573 W JULIAN ST RCRA-SQG FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD CENTER WINCENT ELECTRIC MOTOR 341 N MONTGOMERY ST LUST, HIST LUST EBJ PARTNERS, LP 341 N MONTGOMERY ST LUST, HIST LUST FLEET BODY WORX 345 N MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PR 350 MONTGOMERY ST HIST LUST SCR-A C LABEL/BERRYMAN PR 350 MONTGOMERY ST HIST LUST SCR-A C LABEL/BERRYMAN PR 350 MONTGOMERY ST HIST LUST SCR-A C LABEL/BERRYMAN PR 350 MONTGOMERY ST HIST LUST CPS-SLIC	FACILITY	ADDRESS	DATABASE
SAN JOSE SPORTS ARENA STREET SAN JOSE ARENA 555 SAINT JOHN LUST PLATFORM 16 440 W JULIAN ST CPS-SLIC SAN JOSE ARENA (JULIAN ST.) 565 W JULIAN LUST, HIST LUST ACME SAW SALES AND SERVICE 475 W JULIAN ST RCRA-SQG SOUTH BAY DRIVELINE INC 573 W JULIAN ST RCRA-SQG FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST, UST PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD CENTER WINCENT ELECTRIC MOTOR COMPANY FLEET BODY WORX 341 N MONTGOMERY ST LUST, HIST LUST LUST, HIST LUST LUST, HIST LUST CPS-SLIC MONTGOMERY ST LUST, HIST LUST CPS-SLIC MONTGOMERY ST PROPERTY 341 N MONTGOMERY ST CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST HIST LUST	CALIF STEAM CLEANERS	560 W JULION ST	RCRA-SQG
PLATFORM 16 440 W JULIAN ST CPS-SLIC SAN JOSE ARENA (JULIAN ST.) 565 W JULIAN LUST, HIST LUST ACME SAW SALES AND SERVICE 475 W JULIAN ST RCRA-SQG SOUTH BAY DRIVELINE INC 573 W JULIAN ST RCRA-SQG FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST, UST PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST RCRA-SQG VINCENTER 65 N MONTGOMERY ST RCRA-SQG VINCENTER 141 N MONTGOMERY ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST LUST, HIST LUST COMPANY 341 N MONTGOMERY ST LUST, HIST LUST FLEET BODY WORX 345 N MONTGOMERY ST CPS-SLIC MONTGOMERY ST PROPERTY 341 MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA 555 ST JOHN ST W LUST, HIST LUST AC LABEL CO/BERRYMAN 350 NORTH MONTGOMERY PRODUCTS USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST	SAN JOSE SPORTS ARENA		ENVIROSTOR, RESPONSE
SAN JOSE ARENA (JULIAN ST.) 565 W JULIAN LUST, HIST LUST ACME SAW SALES AND SERVICE 475 W JULIAN ST RCRA-SQG SOUTH BAY DRIVELINE INC 573 W JULIAN ST RCRA-SQG FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST, UST PG&E- SAN JOSE GAS SERVICE CENTER 105 N MONTGOMERY ST RCRA-SQG MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD CENTER VINCENT ELECTRIC MOTOR 341 N MONTGOMERY ST RCRA-SQG VINCENT ELECTRIC MOTOR 341 N MONTGOMERY ST LUST, HIST LUST EBJ PARTNERS, LP 341 N MONTGOMERY ST LUST FLEET BODY WORX 345 N MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS ST USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST	SAN JOSE ARENA	555 SAINT JOHN	LUST
ACME SAW SALES AND SERVICE 475 W JULIAN ST RCRA-SQG SOUTH BAY DRIVELINE INC 573 W JULIAN ST RCRA-SQG FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST, UST PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST RCRA-SQG VINCENTER VINCENT ELECTRIC MOTOR COMPANY 341 N MONTGOMERY ST LUST, HIST LUST FLEET BODY WORX 345 N MONTGOMERY ST LUST FLEET BODY WORX 345 N MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN 350 NORTH MONTGOMERY ST CPS-SLIC USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST	PLATFORM 16	440 W JULIAN ST	CPS-SLIC
FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST, UST PG&E- SAN JOSE GAS SERVICE CENTER 105 N MONTGOMERY ST RCRA-SQG MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST RCRA-SQG VINCENTER 65 N MONTGOMERY ST LUST, HIST LUST VINCENT ELECTRIC MOTOR 341 N MONTGOMERY ST LUST, HIST LUST EBJ PARTNERS, LP 341 N MONTGOMERY ST LUST FLEET BODY WORX 345 N MONTGOMERY ST LUST MONTGOMERY ST PROPERTY 341 MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN 350 NORTH MONTGOMERY PRODUCTS ST CPS-SLIC USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST	SAN JOSE ARENA (JULIAN ST.)	565 W JULIAN	LUST, HIST LUST
FERRERAS AUTOMOTIVE 445 W JULIAN ST RCRA-SQG MILLIGAN NEWS 150 N AUTUMN ST LUST, HIST LUST SAN JOSE FOUNDRY 525 W SAINT JOHN ST LUST, HIST LUST, UST PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD CENTER VINCENT ELECTRIC MOTOR COMPANY 341 N MONTGOMERY ST LUST, HIST LUST FLEET BODY WORX 345 N MONTGOMERY ST LUST FLEET BODY WORX 341 N MONTGOMERY ST CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST CPS-SLIC	ACME SAW SALES AND SERVICE	475 W JULIAN ST	RCRA-SQG
MILLIGAN NEWS 525 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER MANADA TILE FG&E- SAN JOSE GAS LOAD CENTER VINCENT ELECTRIC MOTOR COMPANY EBJ PARTNERS, LP FLEET BODY WORX MONTGOMERY ST FLEET BODY WORX MONTGOMERY ST CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS TESTA LUST, HIST LUST LUST, HIST LUST RCRA-SQG LUST, HIST LUST LUST RCRA-SQG CPS-SLIC RCRA-SQG CPS-SLIC LUST, HIST LUST CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC LUST, HIST LUST CPS-SLIC LUST, HIST LUST HIST LUST CPS-SLIC LUST, HIST LUST ASSO NORTH MONTGOMERY CPS-SLIC LUST, HIST LUST HIST LUST CPS-SLIC LUST, HIST LUST HIST LUST CPS-SLIC LUST HIST LUST LUST HIST LUST HIST LUST LUST HIST LUST	SOUTH BAY DRIVELINE INC	573 W JULIAN ST	RCRA-SQG
SAN JOSE FOUNDRY PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER VINCENT ELECTRIC MOTOR COMPANY EBJ PARTNERS, LP 341 N MONTGOMERY ST FLEET BODY WORX MONTGOMERY ST FLEET BODY WORX MONTGOMERY ST CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST LUST, HIST LUST LUST, HIST LUST CPS-SLIC MONTGOMERY ST PROPERTY 341 MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS ST USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST	FERRERAS AUTOMOTIVE	445 W JULIAN ST	RCRA-SQG
PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE 517 W SAINT JOHN ST LUST, HIST LUST PG&E- SAN JOSE GAS LOAD CENTER 65 N MONTGOMERY ST RCRA-SQG VINCENT ELECTRIC MOTOR COMPANY 341 N MONTGOMERY ST LUST, HIST LUST EBJ PARTNERS, LP 341 N MONTGOMERY ST LUST FLEET BODY WORX 345 N MONTGOMERY CPS-SLIC MONTGOMERY ST PROPERTY 341 MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS ST CENTER 105 N MONTGOMERY ST CPS-SLIC	MILLIGAN NEWS	150 N AUTUMN ST	LUST, HIST LUST
MANADA TILE MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER VINCENT ELECTRIC MOTOR COMPANY EBJ PARTNERS, LP FLEET BODY WORX MONTGOMERY ST WONTGOMERY ST FLEET BODY WORX MONTGOMERY ST CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS MONTGOMERY ST LUST, HIST LUST LUST LUST CPS-SLIC LUST, HIST LUST LUST LUST LUST LUST LUST CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC CPS-SLIC LUST, HIST LUST CPS-SLIC LUST, HIST LUST CPS-SLIC LUST, HIST LUST AT LOST AND LUST HIST LUST AND LUST HIST LUST CPS-SLIC LUST HIST LUST LUST HIST LUST AND LUST HIST LUST LUST HIST LUST AND LUST HIST LUST	SAN JOSE FOUNDRY	525 W SAINT JOHN ST	LUST, HIST LUST, UST
PG&E- SAN JOSE GAS LOAD CENTER VINCENT ELECTRIC MOTOR COMPANY BJ PARTNERS, LP FLEET BODY WORX MONTGOMERY ST CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST RCRA-SQG LUST, HIST LUST LUST LUST LUST CPS-SLIC RCRA-SQG LUST, HIST LUST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS T LUST, HIST LUST CPS-SLIC CPS-SLIC LUST, HIST LUST CPS-SLIC LUST, HIST LUST CPS-SLIC LUST HIST LUST HIST LUST LUST HIST LUST LUST HIST LUST LUST LUST LUST HIST LUST LUST LUST HIST LUST LUST LUST LUST LUST LUST LUST LUST LUST LUST LUST LU		105 N MONTGOMERY ST	RCRA-SQG
CENTER CENTER CENTER COMPANY COMPAN	MANADA TILE	517 W SAINT JOHN ST	LUST, HIST LUST
COMPANY EBJ PARTNERS, LP 341 N MONTGOMERY ST LUST FLEET BODY WORX 345 N MONTGOMERY CPS-SLIC MONTGOMERY ST PROPERTY 341 MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS ST CPS-SLIC CPS-SLIC CPS-SLIC LUST, HIST LUST CPS-SLIC HIST LUST HIST LUST		65 N MONTGOMERY ST	RCRA-SQG
FLEET BODY WORX 345 N MONTGOMERY CPS-SLIC MONTGOMERY ST PROPERTY 341 MONTGOMERY ST RCRA-SQG CUSTOM PAD & PATTERN LA FIESTA 555 ST JOHN ST W LUST, HIST LUST AC LABEL CO/BERRYMAN PRODUCTS ST CPS-SLIC USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST		341 N MONTGOMERY ST	LUST, HIST LUST
MONTGOMERY ST PROPERTY CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS USA TOUCH-UP SERVICE 341 MONTGOMERY ST LUST, HIST LUST CPS-SLIC CPS-SLIC HIST LUST	EBJ PARTNERS, LP	341 N MONTGOMERY ST	LUST
CUSTOM PAD & PATTERN LA FIESTA AC LABEL CO/BERRYMAN PRODUCTS USA TOUCH-UP SERVICE 555 ST JOHN ST W LUST, HIST LUST CPS-SLIC LUST HIST LUST LUST LUST HIST LUST	FLEET BODY WORX	345 N MONTGOMERY	CPS-SLIC
FIESTA AC LABEL CO/BERRYMAN PRODUCTS USA TOUCH-UP SERVICE ST S55 ST JOHN ST W LUST, HIST LUST CPS-SLIC CPS-SLIC HIST LUST	MONTGOMERY ST PROPERTY	341 MONTGOMERY ST	RCRA-SQG
PRODUCTS ST CPS-SLIC USA TOUCH-UP SERVICE 350 N MONTGOMERY ST HIST LUST		555 ST JOHN ST W	LUST, HIST LUST
			CPS-SLIC
SCR-A C LABEL/BERRYMAN PR 350 MONTGOMERY CPS-SLIC	USA TOUCH-UP SERVICE	350 N MONTGOMERY ST	HIST LUST
	SCR-A C LABEL/BERRYMAN PR	350 MONTGOMERY	CPS-SLIC



FACILITY	ADDRESS	DATABASE
AC LABEL CO	350 NO MONTGOMERY	SEMS-ARCHIVE, LUST
LINCOLN PROPERTY	469 HOWARD	LUST, HIST LUST
SAN JOSE ARENA GEISLER PARCEL	80 MONTGOMERY ST N	LUST
CERULEAN GLOBAL SERVICES	250 STOCKTON AVE	AST
SAN JOSE UNIFIED SCHOOL DISTRICT	250 STOCKTON AVE	CPS-SLIC, LUST, HIST LUST
GRUTHFIELD PROPERTY	370 N MONTGOMERY	LUST, HIST LUST
VASPAIO AT DIRADON	138 STOCKTON AVENUE	CPS-SLIC
FMC CORP SAN JOSE ORDNANCE PLANT	333 JULIAN ST	CPS-SLIC, ENVIROSTOR
FMC CORP	333 JULIAN ST	SEMS-ARCHIVE, RCRA- SQG
SAN JOSE AUTO BODY	60 STOCKTON AVENUE	RCRA-SQG
RIVER STREET PROJECT	350 W JULIAN ST	LUST, HIST LUST
SAN JOSE ARENA RITCHEY PARCEL	60 MONTGOTMERY ST N	LUST
PG&E: CINNABAR SERVICE CENTER	308 STOCKTON AV	AST, LUST, UST
INTERIOR PLANT DESIGN	589 SANTA CLARA ST W	LUST, HIST LUST
SAN JOSE ARENA FOLLOSCO PARCEL	575 SANTA CLARA ST W	LUST
FOLLOSCO TRANSMISSION REPAIR	575 W SANTA CLARA ST	LUST, HIST LUST
KOSICH CONSTRUCTION COMPANY	555-561 SANTA CLARA ST W	LUST
SAN JOSE AUTO STEAM CLEANERS	32 STOCKTON AVE	RCRA-SQG
CINNABAR SERVICE CENTER	309 STOCKTON AVE	RCRA-LQG
HANOVER 715 W JULIAN MIXED USE	715 W JULIAN ST	CPS-SLIC
TIERNAN BODY SHOP INC	60 N AUTUMN	RCRA-SQG
XEROX ENGINEERING SYSTEMS	567 CINNABAR	RCRA-SQG
SCV PARAMEDICS/SAN JOSE AMBULA	58 N AUTUMN ST	LUST, HIST LUST
DISTRICT PROPERTY	361 W SANTA CLARA ST	LUST, HIST LUST
KOSICH CONSTRUCTION COMPANY	555-561 W SANTA CLARA ST	LUST
PACIFIC BELL (FUEL UNIT)	1 S MONTGOMERY ST	UST
PHILIP SAN PHILIPPO PROPERTIES	735 THE ALAMEDA	LUST, HIST LUST
CANCILLA PROPERTY	708 W JULIAN ST.	LUST
SAN JOSE ARENA	UNKNOWN UKNOWN	CPS-SLIC
DOWNTOWN TRUCK & TRAILER	405 SANTA CLARA ST W	LUST, HIST LUST
SAN JOSE BLUEPRINT SERVICE	835 W JULIAN ST	RCRA-SQG
BANK OF AMERICA/WELLS FARGO	521 W SANTA CLARA ST	LUST, HIST LUST
DOWNTOWN DATSUN	443 W SANTA CLARA ST	LUST, HIST LUST



FACILITY	ADDRESS	DATABASE
BANK OF AMERICA WELLS	521 SANTA CLARA ST W	LUST
FARGO AIR SYSTEMS INC	381 STOCKTON AVE	LUST, HIST LUST
TIM'S AUTO TRIM	369 STOCKTON AVE	LUST, HIST LUST
SUPERIOR AUTO BODY	355 STOCKTON AVE	RCRA-SQG
		CPS-SLIC, LUST, HIST
MORRISON PARK	395 STOCKTON AVENUE	LUST, BROWNFIELDS
SAN JOSE ARENA BLOCK 5A	522 W SANTA CLARA ST.	LUST, HIST LUST
SAN JOSE ARENA HOLEMAN PARCEL	443 SANTA CLARA ST W	LUST
S & W LAND COMPANY	454 W SANTA CLARA ST	LUST, HIST LUST
DEL MONTE PLANT 51	50 BUSH	CPS-SLIC, LUST, HIST LUST, CPS-SLIC
BOCARDO PROPERTY	849 THE ALAMEDA	LUST, HIST LUST
MANNING PROPERTY	35 RIVER ST N	LUST, HIST LUST
CINNABAR COMMONS	875 CINNABAR STREET	CPS-SLIC
DIRIDON STATION JV	W SANTA CLARA ST AND DELMAS AVE	CPS-SLIC
PERRUCCI PROPERTIES	53 MONTGOMERY S	CPS-SLIC
SERPA PROPERTY	435 STOCKTON ST	LUST, HIST LUST
COMERICA BANK BUILDING	333 W SANTA CLARA ST	LUST, HIST LUST
SAN JOSE ARENA (RITCHEY)	60 N MONTGOMERY ST	LUST, HIST LUST
CALTRAIN SOUTH TERMINAL IMPROVEMENTS	65 CAHILL ST	CPS-SLIC, BROWNFIELDS
VITALE BODY SHOP	52 S AUTUMN ST	LUST, HIST LUST
MARIAN JOHNSON	59 SUTUM ST S	CPS-SLIC
CARLYSLE DEVELOPMENT	76 NOTRE DAME	CPS-SLIC
LORENTZ & SONS	201 W JULIAN ST	RCRA-SQG, CPS-SLIC, LUST, HIST LUST+88:97
NORTH SAN PEDRO APARTMENTS	201 BASSETT ST	CPS-SLIC
SCVWD PROPERTY	361 SANTA CLARA ST W	LUST
SCV PARAMEDICS SJ AMBULANCE	58 AUTUMN ST N	LUST
PG&E SAN JOSE	650 LENZEN AVE	SEMS-ARCHIVE
SAN JOSE ARENA JULIAN ST	70-90 MONTGOMERY N	LUST
AUTOMATIC CAR WASH	77 S MONTGOMERY ST	HIST LUST
1-2-3 POOL SERVICE	455 COLEMAN AVE	HIST LUST, LUST
SOUTHERN PACIFIC TRANS.	595 LENZEN AVE	LUST, HIST LUST
COLLEGE PARK YARD - UP	483 COLEMAN AVE	CPS-SLIC
MR AIR SWEEPERS	483 COLEMAN AVE	RCRA-SQG, CPS-SLIC, LUST, HIST LUST
235 WEST JULIAN STREET	235 WEST JULIAN STREET	CPS-SLIC, BROWNFIELDS
PG&E	655 LENZEN AVE	HIST LUST, LUST
BRANDENBURG PROPERTIES	330 TERRAINE ST	LUST



FACILITY	ADDRESS	DATABASE
BRANDENBURG PROPERTIES	185 JULIAN W	LUST
SAN JOSE ARENA (GIESLER)	80 N MONTGOMERY	LUST, HIST LUST
CHEVRON #9-0882	955 THE ALAMEDA	LUST, HIST LUST
DERBY FOOD SERVICE	55 SUNOL ST	LUST, HIST LUST
CAMPISI TRUST	975 THE ALAMEDA	LUST
SAN JOSE ARENA PG & E PARCEL	90 MONTGOMERY ST N	LUST
WELLS FARGO ALARM SERVICES	466 VENDOME ST	LUST, HIST LUST
BRANDENBURG PROPERTIES	160 JULIAN W	LUST
NORTH SAN PEDRO SQUARE RESIDENCES	BOUNDED BY W. JULIAN, TERRAINE, BASSETT, AND N. SAN PEDRO ST	CPS-SLIC, BROWNFIELDS
COMMON GROUND LANDSCAPE MGMT	725 LENZEN AV	LUST, HIST LUST
BRANDENBERG, STAEDLER & MOORE	153 W JULIAN ST	SEMS-ARCHIVE, CPS-SLIC
BRANDENBURG PROPERTIES	160 W JULIAN ST	LUST, HIST LUST
THOMAS FALLON HOUSE	175 W SAINT JOHN ST	LUST, HIST LUST
U-HAUL MOVING & STORAGE AT THE ALAMEDA	1027 THE ALAMEDA	LUST, HIST LUST
DOWNTOWN MC	1027 THE ALAMEDA	LUST
NATIONAL RAILROAD PASSENGER CO	510 W SAN FERNANDO ST	RCRA-SQG, LUST, HIST LUST
VERIZON BUSINESS: SNTFCA	500 STOCKTON AV	AST, LUST
UNOCAL #0688	500 STOCKTON AVE	LUST, HIST LUST
BRANDENBURG PROPERTIES	355 N SAN PEDRO	LUST, HIST LUST
PG&E SUBSTATION A	17 OTTERSON ST	LUST, HIST LUST
COLLEGE PARK	190 RYLAND STREET	LUST
BRANDENBURG PROPERTIES	345 SAN PEDRO N	LUST
SAN JOSE MERCURY NEWS	211 W. SANTA CLARA ST.	LUST, HIST LUST
ADOBE NORTH TOWER	333 WEST SAN FERNANDO STREET	CPS-SLIC
DIOCESE OF SAN JOSE	855 LENZEN	LUST, HIST LUST
SAN JOSE FIRE STATION #1	201 N MARKET ST	LUST
PG & E SUBSTATION A	17 OTTERSON	LUST
FALSTAFF BREWERY	1330 THE ALAMEDA	LUST, HIST LUST
HARDCASTLE AUTOTHON	590 COLEMAN AVENUE	RCRA-SQG, LUST, HIST LUST
SCVTA RYLAND STREET PROPERTY	UNKNOWN RYLAND ST	LUST
SJRA - VILLA TORINO	340 N MARKET ST	LUST, HIST LUST
LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SENIOR APART	298 LAUREL GROVE LAND AND 370 LAUREL GROVE LAND	VCP, ENVIROSTOR
MISSION VILLAS	44 EAST JULIAN STREET	ENVIROSTOR
	· · · · · · · · · · · · · · · · · · ·	



FACILITY	ADDRESS	DATABASE
OUT OF BUSINESS	810 PARK AV SUITE STE. A	ENVIROSTOR
CIRCUIT LINK	804 A PARK AVENUE	ENVIROSTOR
FAMILY HEALTH FOUND. OF ALVISO ST. JAMES	55 E. JULIAN STREET	ENVIROSTOR
RIVER PARK DEVEL LINCOLN PROPERTIES	333 SAN CARLOS ST W	CPS-SLIC, ENVIROSTOR
CHESTNUT STREET	CHESTNUT AND TAYLOR STREETS	VCP, ENVIROSTOR
SAN JOSE STATE UNIVERSITY CHEMICAL DEPT	125 SOUTH 7TH ST	ENVIROSTOR
STATE RADIATOR SJ REDEVEL	331 GIFFORD AVE	LUST, ENVIROSTOR
DU ALL ANODIZING CO	730 CHESTNUT ST	ENVIROSTOR
WILLIAMS MANUFACTURING	560-595 EMORY ST	CPS-SLIC, BROWNFIELDS
SAN ANTONIO PLAZA BLOCK 4 NORTH	WEST SAN FERNANDO ST & 4TH STREET	VCP, ENVIROSTOR
UNIVERSITY PLATING CO	650 UNIVERSITY AVE	RCRA-LQG, ENVIROSTOR
HORACE MANN ELEMENTARY SCHOOL SITE	55 NORTH SEVENTH STREET	ENVIROSTOR

3.2 ADDITIONAL ENVIRONMENTAL RECORDS

3.2.1 Subject Property

Cagwin & Dorward (the landscaping company at the Property) is listed on the following databases:

HAZNET:

Disposal and recycling of 0.98 tons of unspecified oil-containing waste (2011)

CERS:

- 55 gallons waste ethylene glycol
- 110 gallons waste oil
- 125 gallons acetylene
- 55 gallons used oil filters
- 250 cubic feet oxygen
- 165 gallons motor oil

CERS HAZ WASTE:

 Several hazardous waste storage violations and hazardous waste management plan violations were noted for the Property.

CUPA SANTA CLARA:

HMBP Facility – 4 to 6 chemicals, generates 100 kg/year to <5 tons/year.

San Jose HAZMAT:

Auto Wrecking/ Misc Simple Facility

FINIDS:

Facility is listed in EPA's index system



3.2.1.1 Other Properties

The following database(s) include(s) facilities listed within the appropriate ASTM search distances of the Property on the Additional Environmental Record sources.

TABLE 3.2.1.1-1: Additional Environmental Records – Other Properties within ASTM Radius

FACILITY	ADDRESS	DATABASE
DE LONG CAMS	240 N MONTGOMERY ST	EDR Hist Auto
OUT OF BUSINESS (FRANK JOSEPH'S AUTOMOT)	240 N MONTGOMERY ST	CUPA Listings, SAN JOSE HAZMAT
URIBES BODY SHOP	230 N MONTGOMERY ST	CUPA Listings
FURTADO S AUTOMOTIVE	229 N MONTGOMERY ST	EDR Hist Auto
O/B (NEXTEL CA-2039 HWY 280/87)	505 W JULIAN ST SUITE 2039	SAN JOSE HAZMAT
RALPHS MACHINE SHOP INC	190 N MONTGOMERY ST	HIST UST
TRAFALGAR SPARES	566 W JULIAN ST	EDR Hist Auto
CALIF STEAM CLEANERS	560 W JULION ST	FINDS, ECHO
PROFESSIONALS BODY SHOP THE	151 N AUTUMN ST	CUPA Listings
A C E AUTO BODY	151 N AUTUMN ST	CUPA Listings
SAN JOSE SPORTS ARENA	525 WEST SANTA CLARA STREET	HIST Cal-Sites, DEED
SAP CENTER	525 W SANTA CLARA ST	CUPA Listings, HAZNET, CERS, CERS HAZ WASTE
SAN JOSE ARENA	555 SAINT JOHN	SAN JOSE HAZMAT, HIST CORTESE
PLATFORM 16	440 W JULIAN ST	CERS
SAN JOSE ARENA JULIAN PARCEL	565 JULIAN	HIST CORTESE, CERS
ACME SAW SALES & SERVICE	475 W JULIAN ST	CUPA Listings, SAN JOSE HAZMAT, CERS HAZ WASTE, FINDS, ECHO
R & L BROSAMER INC	406 W JULIAN	CUPA Listings
SOUTHBAY DRIVELINE	573 W JULIAN ST	CUPA Listings
SILICON VALLEY IRON WORK INC	573 W JULIAN ST	CUPA Listings, CERS
ROCK STAR TRUX	573 W JULIAN ST	CUPA Listings
SOUTH BAY DRIVELINE INC	573 W JULIAN ST	FINDS, ECHO, HAZNET, SAN JOSE HAZMAT
FERRERAS AUTOMOTIVE	445 W JULIAN ST	FINDS, ECHO
MILLIGAN NEWS	150 N AUTUMN ST	SWEEPS UST, HIST CORTESE, CERS
BRUNO S AUTOMOTIVE SERVICE	435 W JULIAN ST	EDR Hist Auto
C & M DIVERSIFIED	330 N MONTGOMERY ST	CUPA Listings, SAN JOSE HAZMAT, SWEEPS UST
ADVANCE AUTO DETAIL	333 N MONTGOMERY ST	EDR Hist Auto
ANTUZZI, J A CONCRETE CO,	333 N MONTGOMERY ST	SAN JOSE HAZMAT, CUPA Listings



S J FOUNDRY SAN JOSE FOUNDRY LLOYD S AUTO & TRUCK SERVICE DNT AUTOMOTIVE BRENNER'S AUTOMOTIVE JOSE FOUNDRY 338 N MONTGOMERY ST 338 N MONTGOMERY ST BRENNER'S AUTOMOTIVE JOSE FOUNDRY 338 N MONTGOMERY ST 330 N AUTUMN ST OUT OF BUSINESS JOSE FOUNDRY 330 N AUTUMN ST JOSE FOUNDRY 330 N AUTUMN ST JOSE FOUNDRY 330 AUTUMN ST SUITE A JOSE FOUNDRY 490 HOWARD STREET MANADA TILE JOSE N MONTGOMERY ST MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 517 W SAINT JOHN ST 65 N MONTGOMERY ST	SWEEPS UST HAZNET, CERS EDR Hist Auto CUPA Listings, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE CUPA Listings, SAN JOSE HAZMAT SAN JOSE HAZMAT CUPA Listings SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE FINDS, ECHO
SAN JOSE FOUNDRY LLOYD S AUTO & TRUCK SERVICE DNT AUTOMOTIVE BRENNER'S AUTOMOTIVE OUT OF BUSINESS IA 102813 SALAZAR AUTO BODY OUT OF BUSINESS ARCHITECTURAL FACADES UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 525 W SAINT JOHN ST 338 N MONTGOMERY ST 338 N MONTGOMERY ST B 330 N AUTUMN ST 330 AUTUMN ST SUITE A 490 HOWARD STREET 105 N MONTGOMERY ST 65 N MONTGOMERY ST 65 N MONTGOMERY ST	EDR Hist Auto CUPA Listings, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE CUPA Listings, SAN JOSE HAZMAT SAN JOSE HAZMAT CUPA Listings SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
SERVICE DNT AUTOMOTIVE 338 N MONTGOMERY ST BRENNER'S AUTOMOTIVE 330 N AUTUMN ST OUT OF BUSINESS IA 102813 SALAZAR AUTO BODY OUT OF BUSINESS 330 AUTUMN ST B OUT OF BUSINESS ARCHITECTURAL FACADES UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 338 N MONTGOMERY ST 338 N MONTGOMERY ST BOTH ST 490 HOWARD STREET 105 N MONTGOMERY ST 65 N MONTGOMERY ST 65 N MONTGOMERY ST	EDR Hist Auto CUPA Listings, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE CUPA Listings, SAN JOSE HAZMAT SAN JOSE HAZMAT CUPA Listings SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
BRENNER'S AUTOMOTIVE 330 N AUTUMN ST OUT OF BUSINESS 330 N AUTUMN ST SUITE A IA 102813 SALAZAR AUTO BODY 330 AUTUMN ST B OUT OF BUSINESS 330 AUTUMN ST SUITE B ARCHITECTURAL FACADES UNLIMITE 490 HOWARD STREET PG&E- SAN JOSE GAS SERVICE CENTER 105 N MONTGOMERY ST MANADA TILE 517 W SAINT JOHN ST PG&E- SAN JOSE GAS LOAD CENTER 65 N MONTGOMERY ST	HAZMAT, CERS, CERS HAZ WASTE CUPA Listings, SAN JOSE HAZMAT SAN JOSE HAZMAT CUPA Listings SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
OUT OF BUSINESS IA 102813 SALAZAR AUTO BODY OUT OF BUSINESS ARCHITECTURAL FACADES UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 330 AUTUMN ST SUITE B 490 HOWARD STREET 105 N MONTGOMERY ST 65 N MONTGOMERY ST	HAZMAT SAN JOSE HAZMAT CUPA Listings SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZWASTE
IA 102813 SALAZAR AUTO BODY 330 AUTUMN ST B OUT OF BUSINESS 330 AUTUMN ST SUITE B ARCHITECTURAL FACADES UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 65 N MONTGOMERY ST	CUPA Listings SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
OUT OF BUSINESS ARCHITECTURAL FACADES UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 330 AUTUMN ST B 490 HOWARD STREET 490 HOWARD STREET 490 HOWARD STREET 517 W SAINT JOHN ST 65 N MONTGOMERY ST	SAN JOSE HAZMAT CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
ARCHITECTURAL FACADES UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 490 HOWARD STREET 105 N MONTGOMERY ST 517 W SAINT JOHN ST 65 N MONTGOMERY ST	CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
UNLIMITE PG&E- SAN JOSE GAS SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 490 HOWARD STREET 105 N MONTGOMERY ST 517 W SAINT JOHN ST 65 N MONTGOMERY ST	HAZMAT, CĔRS, CERS HAZ WASTE
SERVICE CENTER MANADA TILE PG&E- SAN JOSE GAS LOAD CENTER 105 N MONTGOMERY ST 65 N MONTGOMERY ST	FINDS ECHO
PG&E- SAN JOSE GAS LOAD 65 N MONTGOMERY ST	i iivoo, cono
CENTER 65 N MONTGOMERY ST	CERS, SWEEPS UST
	FINDS, ECHO
ECONO-LINE 33 N MONTGOMERY ST	EDR Hist Auto
GARDEN CITY GAS WORKS W. ST JOHN AND MONTGOMERY STREETS	EDR MGP
FLEET BODYWORX 341 N MONTGOMERY ST	CUPA Listings
VINCENT ELECTRIC MOTOR CO 341 N MONTGOMERY ST	CUPA Listings
A J WASTE 345 MONTGOMERY ST	FINDS, RCRA NonGen/ NLR, ECHO
VINCENT ELECTRIC MOTOR COMPANY 341 N MONTGOMERY ST	EMI
FLEET BODYWORK 341 N MONTGOMERY ST	CERS, CERS HAZ WASTE
EBJ PARTNERS, LP 341 N MONTGOMERY ST	HAZNET, SAN JOSE HAZMAT, CERS
FLEET BODY WORX 345 N MONTGOMERY	HAZNET, CERS
MONTGOMERY ST PROPERTY 341 MONTGOMERY ST	FINDS, ECHO, HAZNET, HIST CORTESE
VALLEY AUTOMOTIVE SERVICE 125 N AUTUMN ST	EDR Hist Auto
VALAYA AUTO 447 W ST JOHN ST	CUPA Listings, SAN JOSE HAZMAT, CERS HAZ WASTE
CUSTOM PAD & PATTERN LA FIESTA 555 ST JOHN ST W	CERS, HIST UST
SAN JOSE FOUNDRY 525 JOHN ST	HIST CORTESE
BERRYMAN PRODUCTS 350 N MONTGOMERY ST	HAZNET, CERS, CERS HAZ WASTE
USA TOUCH-UP SERVICE 350 N MONTGOMERY ST	EMI
SCR-A C LABEL/BERRYMAN 350 MONTGOMERY	DEED, Cortese, HIST



FACILITY	ADDRESS	DATABASE
AC LABEL CO	350 NO MONTGOMERY	FINDS, RCRA NonGen/ NLR, ECHO, HIST UST, CUPA Listings, EMI, HAZNET, SAN JOSE HAZMAT
LINCOLN PROPERTY	469 HOWARD	HIST CORTESE, CERS
USA TOUCH-UP AUTO BODY	351 N AUTUMN ST	HAZNET, SAN JOSE HAZMAT
IA 062613 USA TOUCH-UP AUTO BODY INC	351 N AUTUMN ST	CUPA Listings
MANADA TILE	517 JOHN ST	HIST CORTESE
SAN JOSE ARENA GEISLER PARCEL	80 MONTGOMERY ST N	CERS
SAN JOSE UNIFIED SCHOOL DISTRICT	250 STOCKTON AVE	HIST CORTESE, ENF, CERS, SWEEPS UST
CERULEAN GLOBAL SERVICES	250 STOCKTON AVE	CERS, CERS TANKS, CUPA Listings, SAN JOSE HAZMAT
GRUTHFIELD PROPERTY	370 N MONTGOMERY	CUPA Listings, SAN JOSE HAZMAT, HIST CORTESE, CERS, CERS HAZ WASTE
PUCCIO MACHINE & WELDING	357 N MONTGOMERY ST	SAN JOSE HAZMAT
VASPAIO AT DIRADON	138 STOCKTON AVENUE	NPDES, CERS
CS AUTOWORKS	383 N AUTUMN ST	CUPA Listings
CAR CARE CLINIC	383 N AUTUM ST	CUPA Listings
BOSNAK AUTO CONCEPTS & SMOG	383 N AUTUMN ST UNIT 7	CUPA Listings
JOAQUIN MEDIA	385 N AUTUMN ST	CUPA Listings
SCU / PARAMEDICAL SERVICES	98 NORTH AUTUMN STREET	HIST UST
FMC CORP SAN JOSE ORDNANCE PLT	333 WEST JULIAN STREET	DEED, CERS
COUNTY OF SANTA CLARA FAF SOCIAL SERVICES AGENCY JULIAN FACI	333 JULIAN ST	HIST UST, CUPA Listings
FMC CORPORATION	333 JULIAN	Cortese, HIST CORTESE, ENF, CIWQS
SAN JOSE AUTO BODY & SERV CNTR	60 STOCKTON AV	CUPA Listings
CENTURY COLLISION & SERVICE CENTER	60 STOCKTON AV	CUPA Listings
DHT COLLISION & SERVICE CENTER	60 STOCKTON AV	CUPA Listings
SAN JOSE AUTO BODY	60 STOCKTON AVENUE	FINDS, ECHO, CUPA Listings, EMI, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
RIVER STREET PROJECT	350 W JULIAN ST	CERS
SAN JOSE ARENA RITCHEY PARCEL	60 MONTGOTMERY ST N	CERS
PACIFIC GAS & ELECTRIC CO	308 STOCKTON AVENUE VECH	SWEEPS UST
PG&E: CINNABAR SERVICE CENTER	308 STOCKTON AV	CERS, CERS TANKS, CERS HAZ WASTE, CUPA Listings,



FACILITY	ADDRESS	DATABASE
		SAN JOSE HAZMAT, CHMIRS, CERS
MASCO SWEEPERS	120 STOCKTON AV	CUPA Listings
GRIFFEL FURNITURE SHOP	165 STOCKTON AV	CUPA Listings
INTERIOR PLANT DESIGN	589 SANTA CLARA ST W	HIST CORTESE, CERS
SAN JOSE ARENA FOLLOSCO PARCEL	575 SANTA CLARA ST W	HIST CORTESE, CERS
KOSICH CONSTRUCTION COMPANY	555-561 SANTA CLARA ST W	CERS
SAN JOSE AUTO STEAM CLEANERS	32 STOCKTON AVE	FINDS, ECHO, CUPA Listings, HAZNET, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
OUT OF BUSINESS (J LOHR WINERY)	566 CINNABAR ST	CUPA Listings, SAN JOSE HAZMAT
WHOLE FOODS MARKET - THE ALAMEDA	777 THE ALAMEDA	CUPA Listings, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
TIERNAN BODY SHOP INC	60 N AUTUMN	FINDS, ECHO
XEROX ENGINEERING SYSTEMS	567 CINNABAR	FINDS, ICIS, ECHO
KOSICH CONSTRUCTION COMPA	561 SANTA CLARA	HIST CORTESE
PHILIP SAN PHILIPPO PROPERTIES	735 THE ALAMEDA	HIST CORTESE, CERS
AV MACHINE SHOP	710 W JULIAN ST	CUPA Listings, HAZNET, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE
A.A. ENGINE CO.	710-W- JULIAN ST	HIST UST
CANCILLA PROPERTY	708 W JULIAN ST.	HAZNET, CERS
AA ENGINE CO	710 W-JULIAN ST	HIST UST
CITY OF SJ-CAHILL PUMP STATION	4 CAHILL ST	CUPA Listings, CERS
DOWNTOWN TRUCK & TRAILER	405 SANTA CLARA ST W	HIST CORTESE, CERS
SAN JOSE BLUEPRINT SERVICE	835 W JULIAN ST	FINDS, ECHO, HAZNET, CUPA Listings
SMITH & MCKAY PRINTING CO, INC	96 N ALMADEN BL	CUPA Listings
DOWNTOWN DATSUN	443 W SANTA CLARA ST	HIST UST
PREMIER NISSAN	443 W SANTA CLARA ST	FINDS, RCRA NonGen / NLR, ECHO
BANK OF AMERICA WELLS FARGO	521 SANTA CLARA ST W	HIST CORTESE, CERS
BRADFORD MANUFACTURING	8 MONTGOMERY	HIST CORTESE
NATIONAL AUTO BODY REPAIR	355 STOCKTON AV	CUPA Listings
AIR SYSTEMS INC	381 STOCKTON AVE	HIST UST, HIST CORTESE, CERS
DON BOCCI MOBILE AUTO SERVICE	395 STOCKTON AVE	HIST UST



ADDRESS	DATABASE
381 STOCKTON AVENUE 1-3	SWEEPS UST
355 STOCKTON AV	CUPA Listings
355 STOCKTON AVE	FINDS, ECHO
395 STOCKTON AVENUE	HIST CORTESE, CERS
785 THE ALAMEDA STE 40	CUPA Listings
57 WHITE	HIST CORTESE
817 THE ALAMEDA	FINDS, RCRA NonGen / NLR, ECHO
522 W SANTA CLARA ST.	DEED, CERS, HIST CORTESE
443 SANTA CLARA ST W	HIST CORTESE, CERS
454 W SANTA CLARA ST	CERS
95 WHITE	HIST CORTESE
400 SANTA CLARA	HIST CORTESE
35 NORTH RIVER STREET	Notify 65
50 BUSH ST	HIST CORTESE, CERS
849 THE ALAMEDA	CERS
35 RIVER ST N	HIST CORTESE, CERS
333 SANTA CLARA	HIST CORTESE
875 CINNABAR STREET	CERS
W SANTA CLARA ST AND DELMAS AVE	CERS
53 MONTGOMERY S	CERS
435 STOCKTON ST	CERS
333 W SANTA CLARA ST	CUPA Listings, SAN JOSE HAZMAT, CERS
65 CAHILL ST	EMI, HAZNET, CHMIRS, CIWQS, CERS
52 AUTUMN	HIST CORTESE, CERS
76 NOTRE DAME	DEED, EMI, CERS
201 BASSETT ST	CIWQS
361 SANTA CLARA ST W	HIST CORTESE, CERS
58 AUTUMN ST N	HIST CORTESE, CERS
70-90 MONTGOMERY N	CERS
77 S MONTGOMERY ST	HIST UST, HIST CORTESE, CERS
455 COLEMAN AVE	HIST CORTESE, CERS
595 LENZEN	HAZNET, HIST CORTESE, CERS
483 COLEMAN AVE	FINDS, ECHO, DEED, HAZNET, SWEEPS UST, HIST CORTESE, CERS
	381 STOCKTON AVENUE 1-3 355 STOCKTON AVE 395 STOCKTON AVE 395 STOCKTON AVENUE 785 THE ALAMEDA STE 40 57 WHITE 817 THE ALAMEDA 522 W SANTA CLARA ST. 443 SANTA CLARA ST W 454 W SANTA CLARA ST 95 WHITE 400 SANTA CLARA 35 NORTH RIVER STREET 50 BUSH ST 849 THE ALAMEDA 35 RIVER ST N 333 SANTA CLARA 875 CINNABAR STREET W SANTA CLARA ST AND DELMAS AVE 53 MONTGOMERY S 435 STOCKTON ST 333 W SANTA CLARA ST 65 CAHILL ST 52 AUTUMN 76 NOTRE DAME 201 BASSETT ST 361 SANTA CLARA ST W 58 AUTUMN ST N 70-90 MONTGOMERY N 77 S MONTGOMERY ST 455 COLEMAN AVE 595 LENZEN



FACILITY	ADDRESS	DATABASE	
235 WEST JULIAN STREET	235 WEST JULIAN STREET	CERS	
PG&E	655 LENZEN AVE	HIST CORTESE, CERS	
BRANDENBURG PROPERTIES	330 TERRAINE ST	HIST UST, CDL, CERS	
BRANDENBURG PROPERTIES	185 JULIAN W	CERS	
CHEVRON #9-0882	955 THE ALAMEDA	HIST UST, HIST CORTESE, CERS	
DERBY FOOD SERVICE	55 SUNOL ST	HIST CORTESE, CERS	
CAMPISI TRUST	975 THE ALAMEDA	CERS	
SAN JOSE ARENA PG & E PARCEL	90 MONTGOMERY ST N	CERS	
SAN JOSE ARENA JULIAN PAR	70 90 MONTGOMERY	HIST CORTESE	
STOCKTON AUTOMOTIVE	465 STOCKTON AV	CUPA Listings, SAN JOSE HAZMAT, SWEEPS UST, HIST CORTESE, CERS, CERS HAZ WASTE	
WELLS FARGO ALARM SERVICES	466 VENDOME ST	HIST CORTESE, CERS	
BRANDENBURG PROPERTIES	160 JULIAN W	CERS	
COMMON GROUND LANDSCAPE MGMT	725 LENZEN AV	CUPA Listings, SAN JOSE HAZMAT, HIST CORTESE, CERS, CERS HAZ WASTE	
BRANDENBERG, STAEDLER & MOORE	153 W JULIAN ST	WDS, CERS, Cortese, HIST CORTESE, ENF	
THOMAS FALLON HOUSE	175 W SAINT JOHN ST	CERS	
U-HAUL MOVING & STORAGE AT THE ALAMEDA	1027 THE ALAMEDA	CUPA Listings, HIST CORTESE, CERS	
DOWNTOWN MC	1027 THE ALAMEDA	HIST UST, CERS	
NATIONAL RAILROAD PASSENGER CO	510 W SAN FERNANDO ST	FINDS, ECHO, CERS	
VERIZON BUSINESS: SNTFCA	500 STOCKTON AV	CUPA Listings, SAN JOSE HAZMAT, HIST CORTESE, CERS	
COLLEGE PARK	190 RYLAND STREET	CERS	
SAN JOSE MERCURY NEWS	211 SANTA CLARA	HIST CORTESE	
BRANDENBURG PROPERTIES	345 SAN PEDRO N	CERS	
SAN JOSE MERCURY NEWS	211 W. SANTA CLARA ST.	CERS	
ADOBE NORTH TOWER	333 WEST SAN FERNANDO STREET	NPDES, CERS	
DIOCESE OF SAN JOSE	855 LENZEN	HIST CORTESE, CERS	
SAN JOSE FIRE STATION #1	201 MARKET	HIST CORTESE	
PG & E SUBSTATION A	17 OTTERSON	HIST CORTESE, CERS	
FALSTAFF BREWERY	1330 THE ALAMEDA	HIST CORTESE, CERS	



FACILITY	ADDRESS	DATABASE	
HARDCASTLE AUTOTHON	590 COLEMAN AVENUE	FINDS, ECHO, EMI, HAZNET, SAN JOSE HAZMAT, HIST CORTESE, CERS	
SCVTA RYLAND STREET PROPERTY	UNKNOWN RYLAND ST	CERS	
LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SENIOR APART	298 LAUREL GROVE LAND AND 370 LAUREL GROVE LAND	CUPA Listings, HAZNET	
OUT OF BUSINESS	810 PARK AV SUITE STE. A	SAN JOSE HAZMAT	
CIRCUIT LINK	804 A PARK AVENUE	EMI	
SAFE-WAY CHEMICAL CO INC	664 STOCKTON AVE	HWP	
IONIZATION RESEARCH CO INC/ECOSOLUTIONS	820 PARK AVE	HWP, ICE, CERS	
RIVER PARK DEVEL LINCOLN PROPERTIES	333 SAN CARLOS ST W	CHMIRS, CERS	
STATE RADIATOR SJ REDEVEL	331 GIFFORD AVE	SAN JOSE HAZMAT, HIST CORTESE, CERS	
DU ALL ANODIZING CO	730 CHESTNUT ST	CUPA Listings, SAN JOSE HAZMAT, CERS, CERS HAZ WASTE	
WILLIAMS MANUFACTURING	560-595 EMORY ST	Notify 65, CERS	
SAN JOSE GAS WORKS	E. SAN FERNANDO AND S. 4TH	EDR MGP	
UNIVERSITY PLATING CO	650 UNIVERSITY AVE	CUPA Listings, SAN JOSE HAZMAT, NPDES, CIWQS, CERS, CERS HAZ WASTE	
HORACE MANN ELEMENTARY SCHOOL SITE	55 NORTH SEVENTH STREET	SCH	

Following is a summary of listings in the immediate vicinity of the Property:

• San Jose Sports Arena, 525 West Santa Clara Street (adjacent parcel west of the Property, and upgradient) is listed as a state response site with land use restrictions in place. The SAP Center complex is located in a historically industrial area near downtown San Jose. Among the historic site uses were a Pacific Gas & Electric (PG&E) coal gasification plant, various automotive repair and service businesses, gas stations and miscellaneous light industries. Several underground storage tanks and oil/water clarifiers were formerly located on the property. Industrial uses date back to 1877 when the site was a water-gas plant that used coal and crude petroleum to produce gas. In 1917, the plant was converted to an oil-gas process. The process resulted in storage of lampblack and tar-like residues. The lampblack storage was reduced in 1922 by burning residue in boilers to produce steam for plant operations. Although the plant ceased operations in 1929, the site continued to be used to store natural gas until 1951.

The City of San Jose Redevelopment Agency (SJRA) began constructing the multipurpose Arena in July 1990, beginning with the site clearing, building demolition, and site preparation. Construction included the construction of a slurry wall to a depth of 35 feet below the ground surface around the proposed Arena building site to prevent groundwater contamination from migrating into or out of the Arena. The Arena floor was excavated to a depth of 17 feet below the ground surface. During development of the arena, the existence of polycyclic aromatic



hydrocarbons (PAH) was discovered due to the former PG&E coal gasification plant operations.

A Covenant to Restrict Use of Property, Environmental Restriction between the City of San Jose and DTSC was finalized for the subject site on May 23, 2003. The covenant limits site uses to commercial, industrial, parks, and/or open space use. Restricted uses include residences, hospitals, school for persons under the age of 21 and daycare centers. Raising of food such as cattle and food crops is also prohibited. The DTSC is to be notified prior to any disturbances of the cap.

Several soil management restrictions are in place for the San Jose Sports Arena.

- No activities that will disturb the soil (e.g., excavation, grading, removal, trenching, filling, earth movement or mining) shall be allowed on the site without a Soil Management Plan and a Health and Safety Plan approved prior to the beginning of the activities by the Department.
- Any contaminated soils brought to the surface by grading, excavation, trenching or backfilling shall be managed in accordance with all applicable provisions of state and federal law.
- The Owner shall provide DTSC written notice at least fourteen (14) days prior to any building, filling, grading, mining or excavating in the site.
- Activities that may disturb the cap, including but not limited to excavation, grading, removal, trenching, filling, earth movement, or mining, shall not be permitted on the site without prior review and written approval by DTSC.
- o All uses and development of the site shall preserve the integrity of the cap.
- The cap shall not be altered without prior written approval by DTSC.

A recent soil gas sampling program performed within the area of encapsulation found elevated VOC concentrations (including benzene and naphthalene) in samples recovered adjacent to the subject Property. Based on recent soil gas data and its close proximity to the subject Property, it is conceivable that soil gas impacts have migrated offsite and thus pose an environmental risk to the subject Property.

• San Jose Foundry, located at 525 W. Saint John Street (approximately 0.1 mile southeast of the Property) (upgradient of the Property) is listed as a closed leaking underground storage tank (LUST) site. This site was occupied by the San Jose Foundry until 2008. Evidence of gasoline leakage into soils at the site was discovered when an underground gasoline storage tank (UST) was excavated in March 1987. Impacted soil was excavated and removed and groundwater monitoring was subsequently conducted. Several dual-phase extraction remediation programs were conducted at the site. The groundwater monitoring program for the case established the direction of groundwater flow to be toward northeast. Based on the stability of the petroleum hydrocarbon plume, the case was closed under the low-threat underground storage tank policy in July 2015. Based on a review of recent, publically available, this site is not likely to present an environmental concern for the Property. However, based on historical commercial/industrial uses in the surrounding area, a groundwater



management plan should be considered to outline protocols for groundwater extraction, treatment, and discharge during future construction activity at the subject Property.

- Milligan News, located at 150 N. Autumn Street (approximately 0.02 mile east of the Property) (cross-gradient of the Property) is also listed as a closed LUST site. A 10,000-gallon gasoline UST was removed from the site in 1987. Impacted soil was excavated and removed, and groundwater and soil vapor extraction was conducted. Groundwater was subsequently monitored. It was concluded that the residual petroleum hydrocarbons would naturally attenuate. The site was closed on July 24, 1997, and is not likely to present an environmental concern for the Property.
- Manda Tile, located at 517 W. Saint John Street (upgradient of the Property) (approximately 0.2 miles southeast of the Property) is also listed as a closed LUST site. Two gasoline USTs were removed from the site in 1993. Impacted soil was excavated and removed. The site was closed on May 30, 1996, and is not likely to present an environmental concern for the Property.
- American Drums, Inc., located at 345 N. Montgomery Street (approximately 0.2 mile northwest of the Property) (downgradient of the Property) is listed as an open, inactive cleanup program site. The site has been inactive since December 1, 2015. Soils impact are reportedly present from arsenic, chromium, copper, lead, and PCBs. Since impact is associated primarily with soil, this site is not likely to present an environmental concern for the Property.

Based on the distances to the identified database sites, regional topographic gradient, and the EDR findings, there are potential sources of offsite subsurface impacts in the vicinity of the Property. Properties that are on the "Orphan Summary" list appear to be located beyond the ASTM recommended radius search criteria.

4.0 SITE RECONNAISSANCE

4.1 METHODOLOGY

ENGEO conducted a reconnaissance of the Property on February 28, 2019. The reconnaissance was performed by Robert Peck, Environmental Scientist of ENGEO. The Property was viewed for hazardous materials storage, superficial staining or discoloration, debris, stressed vegetation, or other conditions that may be indicative of potential sources of soil or groundwater contamination. The Property was also checked for evidence of fill/ventilation pipes, ground subsidence, or other evidence of existing or preexisting underground storage tanks. Photographs taken during the site reconnaissance are presented in Figure 4.

4.2 GENERAL SITE SETTING

The Property is currently occupied by Cagwin and Dorward, a landscaping business. The properties to the north are residential. The property to the south of 255 N. Autumn is a residence, and to the south of 260 N. Montgomery is a commercial building. The Property is located across Montgomery Avenue from the SAP Center entrance.

The grounds are used to house fleet vehicles, compost, and trash/garden waste bins. The main building is used to store equipment, fertilizer, pesticides, herbicides, fuels for equipment, supplies, tools, waste chemicals, and includes an office.



4.3 EXTERIOR OBSERVATIONS

The following table summarizes our observations during the reconnaissance:

TABLE 4.3-1: Exterior Site Observations

FEATURE TYPE	OBSERVATIONS
Structures	Three structures are located at the Property – the main building (sheet metal and concrete floor) and two converted shipping containers used as storage sheds.
Hazardous Substances and Petroleum Products/Containers	Hazardous materials are kept throughout the main building and in the white storage container. In the main building, various drums of cleaning solutions, motor oil, waste oil, and used oil filters are kept at the northeast end of the building. Two flammable cabinets are kept onsite, one on the north end and one on the south end of the building. On the north end, the flammable cabinet contained spray paints, solvents, lubricating oils, and similar products within aerosol cans. The southern flammable cabinet contained several containers of PVC glue and five gasoline cans. Products stored in the sheds include pesticides, herbicides, fertilizers, and similar products, and it is reportedly kept locked at all times by the onsite manager.
Storage Tanks (underground and above-ground)	One above-ground storage tank (AST) containing used oil was observed in the northern portion of the building.
Odors	Minor odors of motor oil and pesticides/fertilizer were observed in the buildings.
Pools of Potentially Hazardous Liquid	Several small leaks were noted on the concrete pad of the main building, and several oil pans were noted to be full or containing some oil. Upstairs, a plywood platform where chainsaw repairs were being made appeared to be saturated in oil.
Drums	Four drums were observed in a secondary containment steel tub. One drum contained 2-cycle oil, one contained bar oil, and two contained motor oil. An additional drum of bar oil was observed adjacent to the secondary containment tub. Two drums of used oil and one drum of used antifreeze were also observed during the reconnaissance.
Polychlorinated Biphenyls (PCBs)	No transformers or other suspect PCB-containing equipment was observed onsite.
Pits, Ponds, and Lagoons	None observed.
Stained Soil/Pavement	Several oil leaks were noted indoors, near drums, or beneath equipment. Extent of the staining was minimal.
Stressed Vegetation	No stressed vegetation was observed onsite. All onsite vegetation is in pots above ground.
Solid Waste/Debris	Debris was observed near trash bins, consisting of trash bags, a microwave oven and tires.
Stockpiles/Fill Material	Stockpiles of mulch were observed in the southern and eastern corners of the Property.
Wastewater	One drain was observed outside the southern entrance to the main building near the white storage container. Water was observed in the drain.
Wells	No wells were observed onsite.
Septic Systems	No septic systems were observed onsite.



4.4 INTERIOR OBSERVATIONS

The Property includes one large elongated building with a half-cylinder corrugated metal roof, corrugated plastic windows, and a concrete floor (Nissen Hut), and two storage sheds (former shipping containers), which sit atop a concrete pad that appears to be a continuation of the foundations slab of the main building toward the Montgomery Street side of the Property. Rust was observed on the exterior cladding of the structure. The interior of the building is supported with steel sections painted red. The interior has a wooden structure on the south side consisting of offices and a restroom, stairs, and an upstairs storage area. On the north end of the building is an enclosed, open-roofed storage area with supplies. The floor area of the building is generally used for equipment storage and maintenance. An above-ground lift was observed mounted to the concrete floor of the building. The hydraulic reservoir was observed and no signs of leaks or staining were noted on or around the reservoir. De minimis staining was observed on the concrete floor throughout the building.

4.5 ASBESTOS-CONTAINING MATERIALS AND LEAD-BASED PAINT

An asbestos and lead-based paint survey was not conducted as part of this assessment. Given the age of the existing structure on the Property, it is conceivable that asbestos-containing materials and lead-based paint materials may exist within the structure.

4.6 INDOOR AIR QUALITY

An evaluation of indoor air quality, mold, or radon was not included as part of the contracted scope of services. The California Department of Health Services has conducted studies of radon risks throughout the state, sorted by zip code. Results of the studies indicate that four tests were conducted within the Property zip code, with none of the tests exceeding the current EPA action level of 4 picocuries per liter [pCi/L]³). The Federal EPA Radon Zone for the Property zip code is Zone 2, with an indoor air average radon level ranging between 2 pCi/L and 4 pCi/L.

In accordance with ASTM E2600-15 (Tier 1) (Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions); there are five potential petroleum hydrocarbon sources for vapor intrusion within 1/10 mile of the Property or volatile organic compound (VOCs) sources within 1/3 mile of the Property.

TABLE 4.6-1

FACILITY	DISTANCE	DATABASE		
San Jose Sports Arena	0.055 miles SW State and Tribal-equival ENVIROSTOR LUST			
FMC Corp San Jose Ordnance	0.0169 miles NE	ENVIROSTOR		
Milligan News Co Inc.	0.088 miles E	LUST		
San Jose Foundry	0.098 miles SE	LUST		
AC Label Co/ Berryman Products	0.121 miles NW	HIST LUST		

³ California Department of Public Health – Radon Program– (https://www.cdph.ca.gov/Programs/CEH/DRSEM/CDPH%20Document%20Library/EMB/Radon/Radon%20Test%20 Results.pdf).



Page | 18

Based on the location, current contaminant concentrations, and/or dates of closure of the above sites, the sites do not appear to pose a vapor intrusion risk to the Property.

5.0 FINDINGS AND CONCLUSIONS

The study included a review of local, state and federal environmental record sources, standard historical sources, aerial photographs, fire insurance maps and physical setting sources; a reconnaissance of the Property to review site use and current conditions to check for the storage, use, production or disposal of hazardous or potentially hazardous materials; and interview with persons knowledgeable about current and past site use.

The site reconnaissance and records review found documentation of shallow soil impairments associated with the use of the Property, but did not identify potential for groundwater impacts associated with former property use. A review of regulatory databases maintained by county, state, and federal agencies found no documentation of hazardous materials violations or discharge on the Property, but did identify inspection violations and contaminated facilities within the appropriate American Society for Testing and Materials (ASTM) search distances that would reasonably be expected to impact the Property.

Based on the orientation and nature of the nearby contaminated facilities, offsite impacts do not appear to pose an immediate environmental concern to the Property.

Based on the findings of this assessment, one REC, no historical RECs, and no controlled RECs were identified for the Property:

 Past industrial use has resulted in impacted shallow soils across the Property. Based on soil characterization activities conducted to date, some soil would be classified as California Class I hazardous material. Appropriate handling measures should be implemented if these materials are handled off-site or removed from the Property.

Based on the review of regulatory databases and site reconnaissance, we present information on features of potential environmental concern that were either contained in the databases or observed on the Property. These features were not considered to be RECs. We briefly discuss each feature below.

- The site vicinity has a long history of industrial use, which may have resulted in undocumented and currently unknown releases. Former land use in the surrounding area may have impacted groundwater regionally.
- Given the age of the existing structure, it is conceivable that both lead-based paint and asbestos-containing material are present within the structure.

ENGEO has performed a phase I environmental site assessment update in general conformance with the scope and limitations of ASTM E1527-13 and the standards and practices of the All Appropriate Inquiry – Final Rule (40 Code of Federal Regulations Part 312). Any exceptions to, or deletions from, this practice are described in Section 5.1 of this report.

Based on the findings of this assessment, ENGEO recommends the following for the Property:



- Given the age of the existing structure, it is conceivable that both lead-based paint and asbestos-containing material are present within the structure. ENGEO recommends retaining a licensed contractor to perform an asbestos and lead-based pant survey prior to demolition.
- Additional soil testing should be completed prior to site grading to determine the extent of impacted soils and waste classifications.
- A Site Management Plan should be prepared to outline protocols for soil characterization and disposal, groundwater extraction, treatment, and discharge during construction activity.

6.0 LIMITATIONS AND UNIFORMITY OF CONDITIONS

The recommendations and conclusions presented in this environmental site assessment update were based on the findings of the referenced reports, along with supplemental record research and site reconnaissance. The findings of the report are based in part on contracted database research and personal communications. ENGEO assumes no liability for the validity of the materials relied upon in the preparation of this report.

The professional staff at ENGEO strives to perform its services in a proper and professional manner with reasonable care and competence but is not infallible. The recommendations and conclusions presented in this report were based on the findings of our assessment update, which were developed solely from the contracted services.

This document must not be subject to unauthorized reuse; that is, reuse without written authorization of ENGEO. Such authorization is essential because it requires ENGEO to evaluate the document's applicability given new circumstances, not the least of which is passage of time. The findings from a phase I environmental site assessment update are typically valid for 180 days after completion of the report, particularly with regard to the regulatory database files. In some instances, the shelf life of the report can be less.

This phase I environmental site assessment update is not intended to represent a complete soil, soil gas, or groundwater characterization. This assessment update does not define the depth or extent of soil, soil gas, or groundwater contamination. It is intended to provide an evaluation of potential environmental concerns associated with the use of the Property. A more extensive assessment that would include detailed subsurface exploration with laboratory testing of soil, soil gas, and groundwater samples could provide more definitive information concerning site-specific conditions. If additional assessment activities are considered for the Property and if other entities are retained to provide such services, ENGEO cannot be held responsible for any and all claims arising from or resulting from the performance of such services by other persons or entities, and from any and all claims arising or resulting from clarifications, adjustments, modifications, discrepancies or other changes necessary to reflect changed field or other conditions.

The assessment update did not include an asbestos survey, an evaluation of lead-based paint, an inspection of light ballasts for PCBs, or a mold survey.

ENGEO would not be aware of site contamination, such as dumping and/or accidental spillage that occurred subsequent to this report.



ENGEO has prepared this report for the exclusive use of our client, Google LLC. It is recognized and agreed that ENGEO has assumed responsibility only for undertaking the assessment update for the client. The responsibility for disclosures or reports to a third party and for remedial or mitigative action shall be solely that of the Client.




REFERENCES

- California Department of Toxic Substances Control, EnviroStor (https://www.envirostor.dtsc.ca.gov/public/)
- California State Water Resources Control Board, GeoTracker (https://geotracker.waterboards.ca.gov/)
- ENGEO; Phase I Environmental Site Assessment, 260 N. Montgomery Street and 255 N. Autumn Street, San Jose, California; September 11, 2018.
- ENGEO; Phase II Environmental Site Assessment, 260 N. Montgomery Street and 255 N. Autumn Street, San Jose, California, October 10, 2018.
- ENGEO; Estimated Quantity of Impacted Material and Remedial Cost, 260 N. Montgomery and 255 N. Autumn Street, San Jose, California, October 31, 2018.

Google Maps (http://maps.google.com)






FIGURES


FIGURE 1: Vicinity Map FIGURE 2: Site Plan


FIGURE 3: Assessor's Parcel Map FIGURE 4: Site Photographs



G:\Drafting\DRAFTING2_Dwg_13000 Plus\14121\001\ESA-260 NORTH MONTGOMERY\14121001000-ESA-1-VICMAP-0319.dwg Plot Date: 3-07-19 JVergara

ORIGINAL FIGURE PRINTED IN COLOR





@ 2019 BY ENGEO INCORPORATED. THIS DOCUMENT MAY NOT BE REPRODUCED IN WHOLE OR IN PART BY ANY MEANS WHATSOEVER, NOR MAY IT BE QUOTED WITHOUT THE EXPRESS WRITTEN CONSENT OF ENGEO INCORPORATED.



EXTERIOR



PESTICIDE, HERBICIDE, INSECTICIDE STORAGE



INTERIOR OF LANDSCAPE FACILITY



FLAMMABLE CHEMICAL STORAGE



ADDITIONAL CHEMICAL STORAGE



DRUMS OF MOTOR OIL, 2-CYCLE OIL, AND BAR OIL



SITE PHOTOGRAPHS

260 N. MONTGOMERY STREET AND 255 N. AUTUMN STREET SAN JOSE, CALIFORNIA

PROJECT NUMBER: 14121.000.001

SCALE: NO SCALE

DRAWN BY: QRL CHECKED BY: JA

CHECKED BY: JAA

FIGURE NO.




DRUM OF USED ANTIFREEZE




DRUM OF USED MOTOR OIL



USED OIL STORAGE



SURFACE MOUNTED LIFT



APPENDIX A

ENVIRONMENTAL DATA RESOURCES, INC.

Radius Map Report

260 N. MONTGOMERY STREET 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

Inquiry Number: 05569778.2r

February 22, 2019

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map.	3
Map Findings Summary	4
Map Findings	
Orphan Summary	731
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map.	A-7
Physical Setting Source Map Findings.	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

260 N. MONTGOMERY STREET SAN JOSE, CA 95110

COORDINATES

Latitude (North): 37.3350850 - 37° 20' 6.30" Longitude (West): 121.9026510 - 121° 54' 9.54"

Universal Tranverse Mercator: Zone 10 UTM X (Meters): 597211.6 UTM Y (Meters): 4132406.0

Elevation: 84 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 5640416 SAN JOSE WEST, CA

Version Date: 2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from: 20140606 Source: USDA

MAPPED SITES SUMMARY

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	CAGWIN & DORWARD	255 N AUTUMN ST	CERS HAZ WASTE, HAZNET, CERS	Lower	1 ft.
A2	CAGWIN & DORWARD	255 N AUTUMN ST	CUPA Listings, SAN JOSE HAZMAT	Lower	1 ft.
A3	CAGWIN & DORWARD	255 N AUTUMN ST	FINDS	Lower	1 ft.
A4	DE LONG CAMS	240 N MONTGOMERY ST	EDR Hist Auto	Higher	39, 0.007, SSE
A5	OUT OF BUSINESS (FRA	240 N MONTGOMERY ST	CUPA Listings, SAN JOSE HAZMAT	Higher	39, 0.007, SSE
A6	URIBES BODY SHOP	230 N MONTGOMERY ST	CUPA Listings	Higher	104, 0.020, SE
B7	FURTADO S AUTOMOTIVE	229 N MONTGOMERY ST	EDR Hist Auto	Higher	113, 0.021, South
A8	O/B (NEXTEL CA-2039	505 W JULIAN ST SUIT	SAN JOSE HAZMAT	Lower	150, 0.028, North
B9	RALPHS MACHINE SHOP	190 N MONTGOMERY ST	HIST UST	Higher	196, 0.037, SE
C10	TRAFALGAR SPARES	566 W JULIAN ST	EDR Hist Auto	Higher	220, 0.042, WSW
C11	CALIF STEAM CLEANERS	560 W JULION ST	RCRA-SQG, FINDS, ECHO	Higher	256, 0.048, West
D12	PROFESSIONALS BODY S	151 N AUTUMN ST	CUPA Listings	Lower	268, 0.051, ESE
D13	A C E AUTO BODY	151 N AUTUMN ST	CUPA Listings	Lower	268, 0.051, ESE
B14	SAN JOSE SPORTS AREN	525 WEST SANTA CLARA	RESPONSE, ENVIROSTOR, HIST Cal-Sites, DEED	Higher	284, 0.054, SSW
B15	SAP CENTER	525 W SANTA CLARA ST	CERS HAZ WASTE, CUPA Listings, HAZNET, CERS	Higher	284, 0.054, SSW
B16	SAN JOSE ARENA	555 SAINT JOHN	LUST, HIST CORTESE, SAN JOSE HAZMAT	Higher	284, 0.054, SSW
E17	PLATFORM 16	440 W JULIAN ST	CPS-SLIC, CERS	Lower	326, 0.062, NNE
C18	SAN JOSE ARENA (JULI	565 W JULIAN	LUST, HIST LUST	Higher	329, 0.062, West
C19	SAN JOSE ARENA JULIA	565 JULIAN	LUST, HIST CORTESE, CERS	Higher	329, 0.062, West
E20	ACME SAW SALES & SER	475 W JULIAN ST	CERS HAZ WASTE, CUPA Listings, SAN JOSE HAZMAT	Lower	353, 0.067, North
E21	ACME SAW SALES AND S	475 W JULIAN ST	RCRA-SQG, FINDS, ECHO	Lower	353, 0.067, North
E22	R & L BROSAMER INC	406 W JULIAN	CUPA Listings	Lower	367, 0.070, NNE
C23	SOUTHBAY DRIVELINE	573 W JULIAN ST	CUPA Listings	Higher	438, 0.083, West
C24	SILICON VALLEY IRON	573 W JULIAN ST	CUPA Listings, CERS	Higher	438, 0.083, West
C25	ROCK STAR TRUX	573 W JULIAN ST	CUPA Listings	Higher	438, 0.083, West
C26	SOUTH BAY DRIVELINE	573 W JULIAN ST	RCRA-SQG, FINDS, ECHO, HAZNET, SAN JOSE HAZMA	AT Higher	438, 0.083, West
E27	FERRERAS AUTOMOTIVE	445 W JULIAN ST	RCRA-SQG, FINDS, ECHO	Lower	449, 0.085, NNE
F28	MILLIGAN NEWS	150 N AUTUMN ST	LUST, HIST LUST, SWEEPS UST, HIST CORTESE, CER	S Lower	459, 0.087, East
E29	BRUNO S AUTOMOTIVE S	435 W JULIAN ST	EDR Hist Auto	Lower	478, 0.091, NNE
G30	C & M DIVERSIFIED	330 N MONTGOMERY ST	CUPA Listings	Higher	486, 0.092, NW
G31	C & M DIVERSIFIED CO	330 N MONTGOMERY ST	SWEEPS UST, SAN JOSE HAZMAT	Higher	486, 0.092, NW
G32	ADVANCE AUTO DETAIL	333 N MONTGOMERY ST	EDR Hist Auto	Higher	492, 0.093, WNW
G33	ANTUZZI, J A CONCRET	333 N MONTGOMERY ST	SAN JOSE HAZMAT	Higher	492, 0.093, WNW
G34	ANTUZZI CONCRETE CO	333 N MONTGOMERY ST	CUPA Listings	Higher	492, 0.093, WNW
H35	S J FOUNDRY	525 W ST JOHN ST	SWEEPS UST	Higher	511, 0.097, SE
H36	SAN JOSE FOUNDRY	525 W SAINT JOHN ST	LUST, HIST LUST, HAZNET, CERS	Higher	511, 0.097, SE
H37	SAN JOSE FOUNDRY	525 W. SAINT JOHN ST	UST	Higher	511, 0.097, SE
G38	LLOYD S AUTO & TRUCK	338 N MONTGOMERY ST	EDR Hist Auto	Lower	536, 0.102, NW
G39	DNT AUTOMOTIVE	338 N MONTGOMERY ST	CERS HAZ WASTE, CUPA Listings, SAN JOSE HAZMAT	, Lower	536, 0.102, NW

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

MAP ID	SITE NAME	ADDRESS		RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
140	BRENNER'S AUTOMOTIVE	330 N AUTUMN ST	CUPA Listings, SAN JOSE HAZMAT	Lower	537, 0.102, North
I41	OUT OF BUSINESS	330 N AUTUMN ST SUIT	SAN JOSE HAZMAT	Lower	537, 0.102, North
142	IA 102813 SALAZAR AU	330 AUTUMN ST B	CUPA Listings	Lower	537, 0.102, North
143	OUT OF BUSINESS	330 AUTUMN ST SUITE	SAN JOSE HAZMAT	Lower	537, 0.102, North
144	ARCHITECTURAL FACADE	490 HOWARD STREET	CERS HAZ WASTE, CUPA Listings, EMI, SAN JOSE	Lower	552, 0.105, North
H45	PG&E- SAN JOSE GAS S	105 N MONTGOMERY ST	RCRA-SQG, FINDS, ECHO	Higher	558, 0.106, SSE
H46	MANADA TILE	517 W SAINT JOHN ST	LUST, HIST LUST, CERS	Lower	566, 0.107, SE
H47	MANADA TILE CO, INC	517 W ST JOHN ST	SWEEPS UST	Lower	566, 0.107, SE
H48	PG&E- SAN JOSE GAS L	65 N MONTGOMERY ST	RCRA-SQG, FINDS, ECHO	Higher	569, 0.108, SSE
H49	ECONO-LINE	33 N MONTGOMERY ST	EDR Hist Auto	Higher	579, 0.110, SSE
J50	GARDEN CITY GAS WORK	W. ST JOHN AND MONTG	EDR MGP	Higher	590, 0.112, SSE
G51	FLEET BODYWORX	341 N MONTGOMERY ST	CUPA Listings	Higher	591, 0.112, NW
G52	VINCENT ELECTRIC MOT	341 N MONTGOMERY ST	CUPA Listings	Higher	591, 0.112, NW
G53	A J WASTE	345 MONTGOMERY ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	591, 0.112, NW
G54	VINCENT ELECTRIC MOT	341 N MONTGOMERY ST	LUST, HIST LUST, EMI	Higher	591, 0.112, NW
G55	FLEET BODYWORK	341 N MONTGOMERY ST	CERS HAZ WASTE, CERS	Higher	591, 0.112, NW
G56	EBJ PARTNERS, LP	341 N MONTGOMERY ST	LUST, HAZNET, SAN JOSE HAZMAT, CERS	Higher	591, 0.112, NW
G57	FLEET BODY WORX	345 N MONTGOMERY	CPS-SLIC, HAZNET, CERS	Higher	591, 0.112, NW
G58	MONTGOMERY ST PROPER	341 MONTGOMERY ST	RCRA-SQG, FINDS, ECHO, HAZNET, HIST CORTESE	Higher	591, 0.112, NW
F59	VALLEY AUTOMOTIVE SE	125 N AUTUMN ST	EDR Hist Auto	Lower	599, 0.113, ESE
F60	VALAYA AUTO	447 W ST JOHN ST	CERS HAZ WASTE, CUPA Listings, SAN JOSE HAZMAT	Lower	599, 0.113, ESE
H61	CUSTOM PAD & PATTERN	555 ST JOHN ST W	LUST, CERS	Higher	606, 0.115, SE
H62	CUSTOM PAD AND PARTI	555 WEST ST JOHN STR	HIST UST	Higher	606, 0.115, SE
H63	CUSTOM PAD & PARTITI	555 W SAINT JOHN ST	LUST, HIST UST	Higher	606, 0.115, SE
H64	CUSTOMPAD&PATTERN/LA	555 W SAINT JOHN ST	HIST LUST	Higher	606, 0.115, SE
H65	SAN JOSE FOUNDRY	525 JOHN ST	HIST CORTESE	Higher	614, 0.116, SSE
G66	BERRYMAN PRODUCTS	350 N MONTGOMERY ST	CERS HAZ WASTE, HAZNET, CERS	Lower	632, 0.120, NW
G67	AC LABEL CO/BERRYMAN	350 NORTH MONTGOMERY	CPS-SLIC	Lower	632, 0.120, NW
G68	USA TOUCH-UP SERVICE	350 N MONTGOMERY ST	HIST LUST, EMI	Lower	632, 0.120, NW
G69	SCR-A C LABEL/BERRYM	350 MONTGOMERY	CPS-SLIC, DEED, Cortese, ENF, HIST CORTESE, CIWQS,	Lower	632, 0.120, NW
G70	AC LABEL CO	350 NO MONTGOMERY	SEMS-ARCHIVE, LUST, HIST UST, RCRA NonGen / NLR,	Lower	632, 0.120, NW
I71	LINCOLN PROPERTY	469 HOWARD	LUST, HIST LUST, HIST CORTESE, CERS	Lower	638, 0.121, NNW
l72	USA TOUCH-UP AUTO BO	351 N AUTUMN ST	HAZNET, SAN JOSE HAZMAT	Lower	655, 0.124, NNW
I73	IA 062613 USA TOUCH-	351 N AUTUMN ST	CUPA Listings	Lower	655, 0.124, NNW
H74	MANADA TILE	517 JOHN ST	HIST CORTESE	Lower	657, 0.124, SE
J75	SAN JOSE ARENA GEISL	80 MONTGOMERY ST N	LUST, CERS	Higher	735, 0.139, SSE
K76	CERULEAN GLOBAL SERV	250 STOCKTON AVE	AST	Higher	741, 0.140, SW
K77	SAN JOSE UNIFIED SCH	250 STOCKTON AVE	LUST, CPS-SLIC, ENF, HIST CORTESE, CERS	Higher	741, 0.140, SW
K78	SAN JOSE UNIFIED SCH	250 STOCKTON AVE	LUST, HIST LUST, SWEEPS UST	Higher	741, 0.140, SW

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

	Timap 12 to ooo ran dotain.				
MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K79	CERULEAN GLOBAL SERV	250 STOCKTON AVE	CERS TANKS, CERS	Higher	741, 0.140, SW
K80	CERULEAN GLOBAL SERV	250 STOCKTON AV	CUPA Listings, SAN JOSE HAZMAT	Higher	741, 0.140, SW
L81	GRUTHFIELD PROPERTY	370 N MONTGOMERY	LUST, HIST LUST, CERS HAZ WASTE, CUPA Listings,	Lower	800, 0.152, NW
L82	PUCCIO MACHINE & WEL	357 N MONTGOMERY ST	SAN JOSE HAZMAT	Lower	810, 0.153, NW
M83	VASPAIO AT DIRADON	138 STOCKTON AVENUE	CPS-SLIC, NPDES, CERS	Higher	835, 0.158, SSW
L84	CS AUTOWORKS	383 N AUTUMN ST	CUPA Listings	Lower	837, 0.159, NNW
L85	CAR CARE CLINIC	383 N AUTUM ST	CUPA Listings	Lower	837, 0.159, NNW
L86	BOSNAK AUTO CONCEPTS	383 N AUTUMN ST UNIT	CUPA Listings	Lower	837, 0.159, NNW
L87	JOAQUIN MEDIA	385 N AUTUMN ST	CUPA Listings	Lower	839, 0.159, NNW
N88	SCU / PARAMEDICAL SE	98 NORTH AUTUMN STRE	HIST UST	Lower	850, 0.161, SE
O89	FMC CORP SAN JOSE OR	333 JULIAN ST	CPS-SLIC	Lower	866, 0.164, NE
O90	FMC CORP SAN JOSE OR	333 WEST JULIAN STRE	ENVIROSTOR, CPS-SLIC, DEED, CERS	Lower	887, 0.168, NE
O91	FMC CORP	333 JULIAN ST	SEMS-ARCHIVE, RCRA-SQG	Lower	887, 0.168, NE
O92	COUNTY OF SANTA CLAR	333 JULIAN ST	HIST UST, CUPA Listings	Lower	887, 0.168, NE
O93	FMC CORPORATION	333 JULIAN	Cortese, ENF, HIST CORTESE, CIWQS	Lower	887, 0.168, NE
M94	SAN JOSE AUTO BODY &	60 STOCKTON AV	CUPA Listings	Higher	888, 0.168, SSW
M95	CENTURY COLLISION &	60 STOCKTON AV	CUPA Listings	Higher	888, 0.168, SSW
M96	DHT COLLISION & SERV	60 STOCKTON AV	CUPA Listings	Higher	888, 0.168, SSW
M97	SAN JOSE AUTO BODY	60 STOCKTON AVENUE	RCRA-SQG, CERS HAZ WASTE, FINDS, ECHO, CUPA	Higher	888, 0.168, SSW
98	RIVER STREET PROJECT	350 W JULIAN ST	LUST, HIST LUST, CERS	Lower	904, 0.171, ENE
N99	SAN JOSE ARENA RITCH	60 MONTGOTMERY ST N	LUST, CERS	Higher	919, 0.174, SE
P100	PG&E: CINNABAR SERVI	308 STOCKTON AV	AST	Higher	1001, 0.190, WSW
P101	PG&E CINNABAR SERVIC	308 STOCKTON AVE	LUST	Higher	1001, 0.190, WSW
P102	PACIFIC GAS & ELECTR	308 STOCKTON AVENUE	SWEEPS UST	Higher	1001, 0.190, WSW
P103	CINNABAR SERVICE CEN	308 STOCKTON AVE.	AST	Higher	1001, 0.190, WSW
P104	PG&E: CINNABAR SERVI	308 STOCKTON AV	CERS HAZ WASTE, CERS TANKS, CERS	Higher	1001, 0.190, WSW
P105	PACIFIC GAS & ELECTR	308 STOCKTON AVE	UST	Higher	1001, 0.190, WSW
P106	PG&E CINNABAR SERVIC	308 STOCKTON AVE	LUST, CHMIRS, CUPA Listings, SAN JOSE HAZMAT, CEP	RS Higher	1001, 0.190, WSW
M107	MASCO SWEEPERS	120 STOCKTON AV	CUPA Listings	Higher	1020, 0.193, SSW
Q108	GRIFFEL FURNITURE SH	165 STOCKTON AV	CUPA Listings	Higher	1021, 0.193, SW
R109	INTERIOR PLANT DESIG	589 SANTA CLARA ST W	LUST, HIST LUST, HIST CORTESE, CERS	Higher	1037, 0.196, South
R110	SAN JOSE ARENA FOLLO	575 SANTA CLARA ST W	LUST, HIST CORTESE, CERS	Higher	1038, 0.197, South
R111	FOLLOSCO TRANSMISSIO	575 W SANTA CLARA ST	LUST, HIST LUST	Higher	1038, 0.197, South
R112	KOSICH CONSTRUCTION	555-561 SANTA CLARA	LUST, CERS	Higher	1038, 0.197, South
M113	SAN JOSE AUTO STEAM	32 STOCKTON AVE	RCRA-SQG, CERS HAZ WASTE, FINDS, ECHO, CUPA	Higher	1043, 0.198, SSW
P114	CINNABAR SERVICE CEN	309 STOCKTON AVE	RCRA-LQG	Higher	1045, 0.198, WSW
S115	OUT OF BUSINESS (J L	566 CINNABAR ST	CUPA Listings, SAN JOSE HAZMAT	Lower	1079, 0.204, WNW
P116	HANOVER 715 W JULIAN	715 W JULIAN ST	CPS-SLIC	Higher	1093, 0.207, WSW
Q117	WHOLE FOODS MARKET -	777 THE ALAMEDA	CERS HAZ WASTE, CUPA Listings, SAN JOSE HAZMAT,	Higher	1115, 0.211, SW

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
T118	TIERNAN BODY SHOP IN	60 N AUTUMN	RCRA-SQG, FINDS, ECHO	Higher	1149, 0.218, SE
S119	XEROX ENGINEERING SY	567 CINNABAR	RCRA-SQG, ICIS, FINDS, ECHO	Lower	1151, 0.218, NW
T120	SCV PARAMEDICS/SAN J	58 N AUTUMN ST	LUST, HIST LUST	Higher	1153, 0.218, SE
U121	KOSICH CONSTRUCTION	561 SANTA CLARA	HIST CORTESE	Higher	1162, 0.220, SSE
122	DISTRICT PROPERTY	361 W SANTA CLARA ST	LUST, HIST LUST	Lower	1176, 0.223, ESE
T123	KOSICH CONSTRUCTION	555-561 W SANTA CLAR	LUST	Higher	1179, 0.223, SSE
R124	PACIFIC BELL (FUEL U	1 S MONTGOMERY ST	UST	Higher	1211, 0.229, SSE
V125	PHILIP SAN PHILIPPO	735 THE ALAMEDA	LUST, HIST LUST, HIST CORTESE, CERS	Higher	1240, 0.235, SSW
P126	AV MACHINE SHOP	710 W JULIAN ST	CERS HAZ WASTE, CUPA Listings, HAZNET, SAN JOSE	Higher	1241, 0.235, WSW
P127	A.A. ENGINE CO.	710-W- JULIAN ST	HIST UST	Higher	1241, 0.235, WSW
P128	CANCILLA PROPERTY	708 W JULIAN ST.	LUST, HAZNET, CERS	Higher	1241, 0.235, WSW
P129	AA ENGINE CO	710 W-JULIAN ST	HIST UST	Higher	1241, 0.235, WSW
T130	SAN JOSE ARENA	UNKNOWN UKNOWN	CPS-SLIC	Higher	1247, 0.236, SSE
R131	CITY OF SJ-CAHILL PU	4 CAHILL ST	CUPA Listings, CERS	Higher	1249, 0.237, South
T132	DOWNTOWN TRUCK & TRA	405 SANTA CLARA ST W	LUST, HIST LUST, HIST CORTESE, CERS	Higher	1252, 0.237, SE
P133	SAN JOSE BLUE	835 W JULIAN ST	CUPA Listings	Higher	1255, 0.238, WSW
P134	SAN JOSE BLUEPRINT S	835 W JULIAN ST	RCRA-SQG, FINDS, ECHO, HAZNET	Higher	1255, 0.238, WSW
135	SMITH & MCKAY PRINTI	96 N ALMADEN BL	CUPA Listings	Lower	1264, 0.239, East
T136	BANK OF AMERICA/WELL	521 W SANTA CLARA ST	LUST, HIST LUST	Higher	1274, 0.241, SE
T137	DOWNTOWN DATSUN	443 W SANTA CLARA ST	LUST, HIST UST	Higher	1274, 0.241, SE
T138	PREMIER NISSAN	443 W SANTA CLARA ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1274, 0.241, SE
T139	UNKNOWN	443 W SANTA CLARA ST	HIST LUST	Higher	1274, 0.241, SE
T140	BANK OF AMERICA WELL	521 SANTA CLARA ST W	LUST, HIST CORTESE, CERS	Higher	1274, 0.241, SE
U141	BRADFORD MANUFACTURI	8 MONTGOMERY	HIST CORTESE	Higher	1286, 0.244, SSE
W142	NATIONAL AUTO BODY R	355 STOCKTON AV	CUPA Listings	Higher	1289, 0.244, West
W143	AIR SYSTEMS INC	381 STOCKTON AVE	LUST, HIST UST, HIST CORTESE, CERS	Higher	1289, 0.244, West
W144	DON BOCCI MOBILE AUT	395 STOCKTON AVE	HIST UST	Higher	1289, 0.244, West
W145	AIR SYSTEMS	381 STOCKTON AVE	LUST, HIST LUST	Higher	1289, 0.244, West
W146	TIM'S AUTO TRIM	369 STOCKTON AVE	LUST, HIST LUST	Higher	1289, 0.244, West
W147	AIR SYSTEMS INC	381 STOCKTON AVENUE	SWEEPS UST	Higher	1289, 0.244, West
W148	MIX INTERNATIONAL AU	355 STOCKTON AV	CUPA Listings	Higher	1289, 0.244, West
W149	SUPERIOR AUTO BODY	355 STOCKTON AVE	RCRA-SQG, FINDS, ECHO	Higher	1289, 0.244, West
W150	MORRISON PARK	395 STOCKTON AVENUE	LUST, CPS-SLIC, HIST LUST, BROWNFIELDS, HIST	Higher	1289, 0.244, West
V151	DIRIDON STATION ACE	785 THE ALAMEDA STE	CUPA Listings	Higher	1300, 0.246, SW
X152	JAMES LICK HIGH SCHO	57 WHITE	HIST CORTESE	Higher	1312, 0.248, SSW
153	PACIFIC BELL	817 THE ALAMEDA	RCRA NonGen / NLR, FINDS, ECHO	Higher	1317, 0.249, SW
T154	SAN JOSE ARENA BLOCK	522 W SANTA CLARA ST	LUST, DEED, CERS	Higher	1331, 0.252, SSE
T155	SAN JOSE ARENA BLOCK	522 SANTA CLARA	LUST, HIST LUST, HIST CORTESE	Higher	1331, 0.252, SSE
T156	SAN JOSE ARENA HOLEM	443 SANTA CLARA ST W	LUST, HIST CORTESE, CERS	Lower	1378, 0.261, SE

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS EI	ELATIVE LEVATION	DIST (ft. & mi.) DIRECTION
T157	S & W LAND COMPANY	454 W SANTA CLARA ST	LUST, HIST LUST, CERS	Higher	1381, 0.262, SE
X158	EAGLE GAS AND MINI M	95 WHITE	HIST CORTESE	Higher	1396, 0.264, SSW
Y159	MILITARY FAMILY HOUS	400 SANTA CLARA	HIST CORTESE	Lower	1475, 0.279, SE
Z160	UNKNOWN	35 NORTH RIVER STREE	Notify 65	Lower	1477, 0.280, ESE
X161	DEL MONTE PLANT 51	50 BUSH	CPS-SLIC	Higher	1507, 0.285, SSW
X162	DEL MONTE PLANT 51	50 BUSH ST	LUST, HIST LUST	Higher	1507, 0.285, SSW
X163	DEL MONTE PLANT 51	50 BUSH ST	LUST, CPS-SLIC, HIST CORTESE, CERS	Higher	1507, 0.285, SSW
164	BOCARDO PROPERTY	849 THE ALAMEDA	LUST, HIST LUST, CERS	Higher	1588, 0.301, SW
Z165	MANNING PROPERTY	35 RIVER ST N	LUST, HIST LUST, HIST CORTESE, CERS	Higher	1602, 0.303, ESE
Z166	SAN JOSE SIDEWALK CI	333 SANTA CLARA	HIST CORTESE	Lower	1607, 0.304, ESE
167	CINNABAR COMMONS	875 CINNABAR STREET	CPS-SLIC, CERS	Higher	1641, 0.311, West
Y168	DIRIDON STATION JV	W SANTA CLARA ST AND	CPS-SLIC, CERS	Higher	1658, 0.314, SE
AA169	PERRUCCI PROPERTIES	53 MONTGOMERY S	CPS-SLIC, CERS	Higher	1700, 0.322, SSE
AB170	SERPA PROPERTY	435 STOCKTON ST	LUST, CERS	Higher	1711, 0.324, WNW
AB171	SERPA PROPERTY	435 STOCKTON ST	LUST, HIST LUST	Higher	1711, 0.324, WNW
172	COMERICA BANK BUILDI	333 W SANTA CLARA ST	LUST, HIST LUST, CUPA Listings, SAN JOSE HAZMAT,	Higher	1718, 0.325, East
AA173	SAN JOSE ARENA (RITC	60 N MONTGOMERY ST	LUST, HIST LUST	Higher	1764, 0.334, SSE
174	CALTRAIN SOUTH TERMI	65 CAHILL ST	CPS-SLIC, BROWNFIELDS, CHMIRS, EMI, HAZNET, CIWQ	S,Higher	1766, 0.334, South
AC175	VITALE AUTO BODY	52 AUTUMN	LUST, HIST CORTESE, CERS	Higher	1766, 0.334, SSE
AC176	VITALE BODY SHOP	52 S AUTUMN ST	LUST, HIST LUST	Higher	1766, 0.334, SSE
AC177	VITALE BODY SHOP	52 S AUTUMN ST	LUST, CERS	Higher	1766, 0.334, SSE
AA178	MARIAN JOHNSON	59 SUTUM ST S	CPS-SLIC	Higher	1826, 0.346, SSE
179	CARLYSLE DEVELOPMENT	76 NOTRE DAME	CPS-SLIC, DEED, EMI, CERS	Higher	1833, 0.347, East
AD180	LORENTZ & SONS	201 W JULIAN ST	SEMS-ARCHIVE	Lower	1843, 0.349, NE
181	NORTH SAN PEDRO APAR	201 BASSETT ST	CPS-SLIC, CIWQS	Lower	1845, 0.349, NE
182	SCVWD PROPERTY	361 SANTA CLARA ST W	LUST, HIST CORTESE, CERS	Higher	1857, 0.352, ESE
AC183	SCV PARAMEDICS SJ AM	58 AUTUMN ST N	LUST, HIST CORTESE, CERS	Higher	1880, 0.356, SSE
AE184	PG&E SAN JOSE	650 LENZEN AVE	SEMS-ARCHIVE	Higher	1898, 0.359, WNW
AA185	SAN JOSE ARENA JULIA	70-90 MONTGOMERY N	LUST, CERS	Higher	1910, 0.362, SSE
AA186	AUTOMATIC CAR WASH	77 S MONTGOMERY ST	LUST, HIST LUST, HIST UST, HIST CORTESE, CERS	Higher	1913, 0.362, South
AF187	1-2-3 POOL SERVICE	455 COLEMAN AVE	LUST, HIST LUST, HIST CORTESE, CERS	Lower	1913, 0.362, North
AE188	SOUTHERN PACIFIC TRA	595 LENZEN AVE	LUST, HIST LUST	Higher	1916, 0.363, WNW
AE189	SOUTHERN PACIFIC TRA	595 LENZEN	LUST, HAZNET, HIST CORTESE, CERS	Higher	1916, 0.363, WNW
AG190	COLLEGE PARK YARD -	483 COLEMAN AVE	CPS-SLIC	Lower	1931, 0.366, NNW
AG191	MR AIR SWEEPERS	483 COLEMAN AVE	RCRA-SQG, LUST, CPS-SLIC, HIST LUST, SWEEPS UST,	Lower	1931, 0.366, NNW
AD192	235 WEST JULIAN STRE	235 WEST JULIAN STRE	CPS-SLIC, BROWNFIELDS, CERS	Higher	1945, 0.368, NE
AE193	PG&E	655 LENZEN AVE	LUST, HIST LUST, HIST CORTESE, CERS	Higher	1950, 0.369, WNW
AD194	BRANDENBURG PROPERTI	330 TERRAINE ST	LUST, CDL, HIST UST, CERS	Lower	1975, 0.374, NE
AD195	BRANDENBURG PROPERTI	185 JULIAN W	LUST, CERS	Higher	2001, 0.379, NE
				-	

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AH196	SAN JOSE ARENA (GIES	80 N MONTGOMERY	LUST, HIST LUST	Higher	2024, 0.383, SSE
AI197	CHEVRON #9-0882	955 THE ALAMEDA	LUST, HIST UST	Higher	2048, 0.388, SW
Al198	CHEVRON	955 THE ALAMEDA	HIST CORTESE	Higher	2048, 0.388, SW
Al199	CHEVRON #9-0882	955 THE ALAMEDA	LUST, HIST LUST	Higher	2048, 0.388, SW
AI200	CHEVRON #9-0882	955 THE ALAMEDA	LUST, CERS	Higher	2048, 0.388, SW
201	DERBY FOOD SERVICE	55 SUNOL ST	LUST, HIST LUST, HIST CORTESE, CERS	Higher	2050, 0.388, SW
Al202	CAMPISI TRUST	975 THE ALAMEDA	LUST, CERS	Higher	2055, 0.389, WSW
AH203	SAN JOSE ARENA PG &	90 MONTGOMERY ST N	LUST, CERS	Higher	2072, 0.392, SSE
AH204	SAN JOSE ARENA JULIA	70 90 MONTGOMERY	HIST CORTESE	Higher	2072, 0.392, SSE
AE205	STOCKTON AUTOMOTIVE	465 STOCKTON AV	CERS HAZ WASTE, SWEEPS UST, CUPA Listings, HIS	Γ Higher	2085, 0.395, WNW
AF206	WELLS FARGO ALARM SE	466 VENDOME ST	LUST, HIST LUST, HIST CORTESE, CERS	Lower	2109, 0.399, North
AJ207	BRANDENBURG PROPERTI	160 JULIAN W	LUST, CERS	Higher	2111, 0.400, NE
AD208	NORTH SAN PEDRO SQUA	BOUNDED BY W. JULIAN	CPS-SLIC, BROWNFIELDS	Higher	2114, 0.400, NE
209	COMMON GROUND LANDSC	725 LENZEN AV	LUST, HIST LUST, CERS HAZ WASTE, CUPA Listings,	. Higher	2115, 0.401, WNW
AJ210	BRANDENBERG, STAEDLE	153 W JULIAN ST	SEMS-ARCHIVE, CPS-SLIC, WDS, CERS	Higher	2122, 0.402, NE
AJ211	BRANDENBURG FAMILY A	153 JULIAN	Cortese, ENF, HIST CORTESE	Higher	2122, 0.402, NE
AJ212	BRANDENBURG PROPERTI	160 W JULIAN ST	LUST	Higher	2123, 0.402, NE
AJ213	BRANDENBURG PROPERTI	160 W JULIAN ST	HIST LUST	Higher	2123, 0.402, NE
214	THOMAS FALLON HOUSE	175 W SAINT JOHN ST	LUST, HIST LUST, CERS	Higher	2145, 0.406, ENE
AK215	U-HAUL MOVING & STOR	1027 THE ALAMEDA	LUST, HIST LUST, CUPA Listings, HIST CORTESE, CEF	RS Higher	2185, 0.414, WSW
AK216	DOWNTOWN MC	1027 THE ALAMEDA	LUST, HIST UST, CERS	Higher	2185, 0.414, WSW
AH217	NATIONAL RAILROAD PA	510 W SAN FERNANDO S	RCRA-SQG, LUST, HIST LUST, FINDS, ECHO, CERS	Higher	2243, 0.425, SSE
AL218	VERIZON BUSINESS: SN	500 STOCKTON AV	LUST, AST, CUPA Listings, HIST CORTESE, SAN JOSE	Higher	2257, 0.427, WNW
AL219	UNOCAL #0688	500 STOCKTON AVE	LUST, HIST LUST	Higher	2257, 0.427, WNW
AM220	BRANDENBURG PROPERTI	355 N SAN PEDRO	LUST, HIST LUST	Higher	2277, 0.431, NE
AN221	PG&E SUBSTATION A	17 OTTERSON ST	LUST, HIST LUST	Higher	2291, 0.434, South
AO222	COLLEGE PARK	190 RYLAND STREET	LUST, CERS	Higher	2292, 0.434, NNE
AP223	SAN JOSE MERCURY NEW	211 SANTA CLARA	HIST CORTESE	Higher	2301, 0.436, East
AM224	BRANDENBURG PROPERTI	345 SAN PEDRO N	LUST, CERS	Higher	2324, 0.440, NE
AP225	SAN JOSE MERCURY NEW	211 W. SANTA CLARA S	LUST, HIST LUST, CERS	Higher	2328, 0.441, East
226	ADOBE NORTH TOWER	333 WEST SAN FERNAND	CPS-SLIC, NPDES, CERS	Higher	2382, 0.451, ESE
227	DIOCESE OF SAN JOSE	855 LENZEN	LUST, HIST LUST, HIST CORTESE, CERS	Higher	2382, 0.451, West
AQ228	SAN JOSE FIRE STATIO	201 MARKET	HIST CORTESE	Higher	2418, 0.458, ENE
AQ229	SAN JOSE FIRE STATIO	201 N MARKET ST	LUST	Higher	2418, 0.458, ENE
AN230	PG & E SUBSTATION A	17 OTTERSON	LUST, HIST CORTESE, CERS	Higher	2470, 0.468, South
231	FALSTAFF BREWERY	1330 THE ALAMEDA	LUST, HIST LUST, HIST CORTESE, CERS	Higher	2482, 0.470, WSW
232	HARDCASTLE AUTOTHON	590 COLEMAN AVENUE	RCRA-SQG, LUST, HIST LUST, FINDS, ECHO, EMI,	Lower	2498, 0.473, NNW
AO233	SCVTA RYLAND STREET	UNKNOWN RYLAND ST	LUST, CERS	Higher	2547, 0.482, NNE
234	SJRA - VILLA TORINO	340 N MARKET ST	LUST, HIST LUST	Higher	2615, 0.495, NE

Target Property Address: 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

MAP			-	RELATIVE	DIST (ft. & mi.)
<u>ID</u>	SITE NAME	ADDRESS	DATABASE ACRONYMS E	LEVATION	DIRECTION
235	LAUREL GROVE FAMILY	298 LAUREL GROVE LAN	ENVIROSTOR, VCP, CUPA Listings, HAZNET	Higher	2861, 0.542, South
AR236	MISSION VILLAS	44 EAST JULIAN STREE	ENVIROSTOR	Lower	3319, 0.629, NE
AS237	OUT OF BUSINESS	810 PARK AV SUITE ST	ENVIROSTOR, SAN JOSE HAZMAT	Higher	3344, 0.633, SSW
AS238	CIRCUIT LINK	804 A PARK AVENUE	ENVIROSTOR, EMI	Higher	3344, 0.633, SSW
239	SAFE-WAY CHEMICAL CO	664 STOCKTON AVE	HWP	Lower	3373, 0.639, NW
AS240	IONIZATION RESEARCH	820 PARK AVE	ICE, HWP, CERS	Higher	3378, 0.640, SSW
AR241	FAMILY HEALTH FOUND.	55 E. JULIAN STREET	ENVIROSTOR	Lower	3396, 0.643, NE
242	RIVER PARK DEVEL LIN	333 SAN CARLOS ST W	ENVIROSTOR, CPS-SLIC, CHMIRS, CERS	Higher	3449, 0.653, SE
AT243	CHESTNUT STREET	CHESTNUT AND TAYLOR	ENVIROSTOR, VCP	Lower	3669, 0.695, NW
244	SAN JOSE STATE UNIVE	125 SOUTH 7TH ST	ENVIROSTOR	Higher	3759, 0.712, East
245	STATE RADIATOR SJ RE	331 GIFFORD AVE	ENVIROSTOR, LUST, HIST CORTESE, SAN JOSE HAZMA	T,Higher	3762, 0.712, SSE
AT246	DU ALL ANODIZING CO	730 CHESTNUT ST	ENVIROSTOR, CERS HAZ WASTE, CUPA Listings, SAN	Lower	3793, 0.718, NW
247	WILLIAMS MANUFACTURI	560-595 EMORY ST	CPS-SLIC, BROWNFIELDS, Notify 65, CERS	Lower	4382, 0.830, NW
AU248	SAN JOSE GAS WORKS	E. SAN FERNANDO AND	EDR MGP	Higher	4569, 0.865, East
AU249	SAN ANTONIO PLAZA BL	WEST SAN FERNANDO ST	ENVIROSTOR, VCP	Higher	4634, 0.878, East
250	UNIVERSITY PLATING C	650 UNIVERSITY AVE	RCRA-LQG, ENVIROSTOR, CERS HAZ WASTE, CUPA	Lower	4915, 0.931, NW
251	HORACE MANN ELEMENTA	55 NORTH SEVENTH STR	ENVIROSTOR, SCH	Higher	5236, 0.992, ENE

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Fadaval NDL alta liat	
Federal NPL site list	ALC: LECTOR IN
NPL	. National Priority List . Proposed National Priority List Sites
NPL LIENS.	
Federal Delisted NPL site lis	st
Delisted NPL	National Priority List Deletions
Federal CERCLIS list	
	Federal Facility Site Information listing Superfund Enterprise Management System
OLIVIO	Superiulu Enterprise Management System
Federal RCRA CORRACTS	facilities list
CORRACTS	Corrective Action Report
	·
Federal RCRA non-CORRAG	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators li	
RCRA-CESQG	RCRA - Conditionally Exempt Small Quantity Generator
	ls / engineering controls registries
	Land Use Control Information System
US INST CONTROLS	. Engineering Controls Sites List _ Sites with Institutional Controls
Federal ERNS list	
ERNS	Emergency Response Notification System
State and tribal landfill and/	or solid waste disposal site lists
SWF/LF	Solid Waste Information System

State and	l tribal	leaking	storage	tank	lists
-----------	----------	---------	---------	------	-------

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST...... Underground Storage Tank Listing INDIAN UST...... Underground Storage Tanks on Indian Land

State and tribal voluntary cleanup sites

INDIAN VCP......Voluntary Cleanup Priority Listing VCP.....Voluntary Cleanup Program Properties

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT...... Waste Management Unit Database

SWRCY..... Recycler Database

HAULERS..... Registered Waste Tire Haulers Listing

INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

ODI...... Open Dump Inventory

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

IHS OPEN DUMPS..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL..... Delisted National Clandestine Laboratory Register

SCH......School Property Evaluation Program

US CDL...... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

CA FID UST..... Facility Inventory Database

Local Land Records

LIENS..... Environmental Liens Listing LIENS 2.... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System CHMIRS..... California Hazardous Material Incident Report System

LDS______Land Disposal Sites Listing MCS______Military Cleanup Sites Listing

SPILLS 90...... SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS....... Formerly Used Defense Sites DOD...... Department of Defense Sites

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing

US FIN ASSUR..... Financial Assurance Information

EPA WATCH LIST..... EPA WATCH LIST

2020 COR ACTION...... 2020 Corrective Action Program List

TSCA..... Toxic Substances Control Act

TRIS_____ Toxic Chemical Release Inventory System

RAATS...... RCRA Administrative Action Tracking System

ICIS...... Integrated Compliance Information System

Act)/TSCA (Toxic Substances Control Act)

COAL ASH EPA...... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER...... PCB Transformer Registration Database

RADINFO...... Radiation Information Database

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

DOT OPS..... Incident and Accident Data

CONSENT...... Superfund (CERCLA) Consent Decrees

INDIAN RESERV.....Indian Reservations

FUSRAP..... Formerly Utilized Sites Remedial Action Program

UMTRA..... Uranium Mill Tailings Sites

LEAD SMELTERS..... Lead Smelter Sites

US AIRS...... Aerometric Information Retrieval System Facility Subsystem

US MINES...... Mines Master Index File ABANDONED MINES..... Abandoned Mines

ECHO..... Enforcement & Compliance History Information DOCKET HWC..... Hazardous Waste Compliance Docket Listing

UXO...... Unexploded Ordnance Sites

FUELS PROGRAM EPA Fuels Program Registered Listing

CA BOND EXP. PLAN....... Bond Expenditure Plan
DRYCLEANERS....... Cleaner Facilities
EMI......... Emissions Inventory Data
ENF....... Enforcement Action Listing

Financial Assurance Information Listing

ICE.....ICE

HWT...... Registered Hazardous Waste Transporter Database

MINES..... Mines Site Location Listing

MWMP..... Medical Waste Management Program Listing

NPDES Permits Listing

PEST LIC..... Pesticide Regulation Licenses Listing

PROC..... Certified Processors Database

UIC......UIC Listing

UIC GEO......UIC GEO (GEOTRACKER) WASTEWATER PITS...... Oil Wastewater Pits Listing

WDS..... Waste Discharge System

MILITARY PRIV SITES..... MILITARY PRIV SITES (GEOTRACKER)

PROJECT (GEOTRACKER)

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF...... Recovered Government Archive Solid Waste Facilities List
RGA LUST...... Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for

listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 12/13/2018 has revealed that there are 5 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E SAN JOSE Site ID: 0902491 EPA Id: CAD981671886	650 LENZEN AVE	WNW 1/4 - 1/2 (0.359 mi.)	AE184	443
BRANDENBERG, STAEDLE	153 W JULIAN ST	NE 1/4 - 1/2 (0.402 mi.)	AJ210	521
Lower Elevation	Address	Direction / Distance	Map ID	Page
AC LABEL CO Site ID: 0902512 EPA Id: CAD981693492	350 NO MONTGOMERY	NW 0 - 1/8 (0.120 mi.)	G70	148
FMC CORP LORENTZ & SONS Site ID: 0903348 EPA Id: CAD982400004	333 JULIAN ST 201 W JULIAN ST	NE 1/8 - 1/4 (0.168 mi.) NE 1/4 - 1/2 (0.349 mi.)	<i>O91</i> AD180	207 436

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/01/2018 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CINNABAR SERVICE CEN EPA ID:: CAD981409725	309 STOCKTON AVE	WSW 1/8 - 1/4 (0.198 mi.)	P114	322

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 14 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CALIF STEAM CLEANERS	560 W JULION ST	W 0 - 1/8 (0.048 mi.)	C11	20

EPA ID:: CAD098540123				
SOUTH BAY DRIVELINE EPA ID:: CAR000058321	573 W JULIAN ST	W 0 - 1/8 (0.083 mi.)	C26	54
PG&E- SAN JOSE GAS S EPA ID:: CAD981159403	105 N MONTGOMERY ST	SSE 0 - 1/8 (0.106 mi.)	H45	95
PG&E- SAN JOSE GAS L EPA ID:: CAD981159411	65 N MONTGOMERY ST	SSE 0 - 1/8 (0.108 mi.)	H48	99
MONTGOMERY ST PROPER EPA ID:: CAR000002543	341 MONTGOMERY ST	NW 0 - 1/8 (0.112 mi.)	G58	121
SAN JOSE AUTO BODY EPA ID:: CAD981572985	60 STOCKTON AVENUE	SSW 1/8 - 1/4 (0.168 mi.)	M97	220
SAN JOSE AUTO STEAM EPA ID:: CAD981452808	32 STOCKTON AVE	SSW 1/8 - 1/4 (0.198 mi.)	M113	302
TIERNAN BODY SHOP IN EPA ID:: CAD029310208	60 N AUTUMN	SE 1/8 - 1/4 (0.218 mi.)	T118	330
SAN JOSE BLUEPRINT S EPA ID:: CAD983631862	835 W JULIAN ST	WSW 1/8 - 1/4 (0.238 mi.)	P134	352
SUPERIOR AUTO BODY EPA ID:: CAD053888806	355 STOCKTON AVE	W 1/8 - 1/4 (0.244 mi.)	W149	371
Lower Elevation	Address	Direction / Distance	Map ID	Page
ACME SAW SALES AND S EPA ID:: CAR000020446	475 W JULIAN ST	N 0 - 1/8 (0.067 mi.)	E21	52
FERRERAS AUTOMOTIVE EPA ID:: CAD983673104	445 W JULIAN ST	NNE 0 - 1/8 (0.085 mi.)	E27	58
FMC CORP EPA ID:: CAD009146952	333 JULIAN ST	NE 1/8 - 1/4 (0.168 mi.)	O91	207
XEROX ENGINEERING SY EPA ID:: CAR000001834	567 CINNABAR	NW 1/8 - 1/4 (0.218 mi.)	S119	332

State- and tribal - equivalent NPL

RESPONSE: Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

A review of the RESPONSE list, as provided by EDR, has revealed that there is 1 RESPONSE site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE SPORTS AREN	525 WEST SANTA CLARA	SSW 0 - 1/8 (0.054 mi.)	B14	22

Database: RESPONSE, Date of Government Version: 10/29/2018

Status: Certified O&M - Land Use Restrictions Only

Facility Id: 43730007

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifies sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 10/29/2018 has revealed that there are 15 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE SPORTS AREN Facility Id: 43730007 Status: Certified O&M - Land Use Restrict	525 WEST SANTA CLARA tions Only	SSW 0 - 1/8 (0.054 mi.)	B14	22
LAUREL GROVE FAMILY Facility Id: 60002378 Status: No Further Action	298 LAUREL GROVE LAN	S 1/2 - 1 (0.542 mi.)	235	590
OUT OF BUSINESS Facility Id: 71003686 Status: Inactive - Needs Evaluation	810 PARK AV SUITE ST	SSW 1/2 - 1 (0.633 mi.)	AS237	595
CIRCUIT LINK Facility Id: 71003660 Status: No Further Action	804 A PARK AVENUE	SSW 1/2 - 1 (0.633 mi.)	AS238	596
RIVER PARK DEVEL LIN Facility Id: 43150003 Status: Refer: RWQCB	333 SAN CARLOS ST W	SE 1/2 - 1 (0.653 mi.)	242	604
SAN JOSE STATE UNIVE Facility Id: 43820001 Status: No Further Action	125 SOUTH 7TH ST	E 1/2 - 1 (0.712 mi.)	244	620
STATE RADIATOR SJ RE Facility Id: 43750007 Status: Refer: RWQCB	331 GIFFORD AVE	SSE 1/2 - 1 (0.712 mi.)	245	621
SAN ANTONIO PLAZA BL Facility Id: 43490065 Status: Certified	WEST SAN FERNANDO ST	E 1/2 - 1 (0.878 mi.)	AU249	669
HORACE MANN ELEMENTA Facility Id: 43820007 Status: No Action Required	55 NORTH SEVENTH STR	ENE 1/2 - 1 (0.992 mi.)	251	727
Lower Elevation	Address	Direction / Distance	Map ID	Page
FMC CORP SAN JOSE OR Facility Id: 43370005 Status: Refer: RWQCB	333 WEST JULIAN STRE	NE 1/8 - 1/4 (0.168 mi.)	O90	203
MISSION VILLAS	44 EAST JULIAN STREE	NE 1/2 - 1 (0.629 mi.)	AR236	594

Facility Id: 60001042 Status: Refer: 1248 Local Agency				
FAMILY HEALTH FOUND. Facility Id: 43800004 Status: No Action Required	55 E. JULIAN STREET	NE 1/2 - 1 (0.643 mi.)	AR241	603
CHESTNUT STREET Facility Id: 60000431 Status: Active	CHESTNUT AND TAYLOR	NW 1/2 - 1 (0.695 mi.)	AT243	607
DU ALL ANODIZING CO Facility Id: 60002626 Status: Active	730 CHESTNUT ST	NW 1/2 - 1 (0.718 mi.)	AT246	625
UNIVERSITY PLATING C	650 UNIVERSITY AVE	NW 1/2 - 1 (0.931 mi.)	250	672

State and tribal leaking storage tank lists

Status: Inactive - Needs Evaluation

Facility Id: 71002255

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 92 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE ARENA Database: LUST REG 2, Date of Governing Facility Id: 43-2271 Facility Status: Preliminary site assessment		SSW 0 - 1/8 (0.054 mi.)	B16	47
SAN JOSE ARENA (JULI Database: LUST SANTA CLARA, Date or Date Closed: 04/09/1997 SCVWD ID: 07S1E07K05F	565 W JULIAN f Government Version: 03/03/2014	W 0 - 1/8 (0.062 mi.)	C18	49
SAN JOSE ARENA JULIA Database: LUST, Date of Government Verstatus: Completed - Case Closed Global Id: T0608501163	565 JULIAN ersion: 12/10/2018	W 0 - 1/8 (0.062 mi.)	C19	49
SAN JOSE FOUNDRY Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Status: Pollution Characterization Global Id: T0608501177 SCVWD ID: 07S1E07Q01F		SE 0 - 1/8 (0.097 mi.)	H36	66
VINCENT ELECTRIC MOT Database: LUST REG 2, Date of Governif Facility Status: Case Closed date9: 6/21/2001	341 N MONTGOMERY ST ment Version: 09/30/2004	NW 0 - 1/8 (0.112 mi.)	G54	104
EBJ PARTNERS, LP Database: LUST SANTA CLARA, Date of Database: LUST, Date of Government Version (1988)		NW 0 - 1/8 (0.112 mi.)	G56	115

Status: Completed - Case Closed Date Closed: 06/21/2001 Global Id: T0608501412 SCVWD ID: 07S1E07L04F **CUSTOM PAD & PATTERN** 555 ST JOHN ST W SE 0 - 1/8 (0.115 mi.) H61 128 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Id: 43-0433 Facility Status: Case Closed Global Id: T0608500483 date9: 4/9/1997 **CUSTOM PAD & PARTITI** SE 0 - 1/8 (0.115 mi.) 555 W SAINT JOHN ST H63 131 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q08F SAN JOSE ARENA GEISL 80 MONTGOMERY ST N SSE 1/8 - 1/4 (0.139 mi.) 159 J75 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Id: 43-2158 Facility Status: Case Closed Global Id: T0608501982 date9: 4/9/1997 SAN JOSE UNIFIED SCH 250 STOCKTON AVE SW 1/8 - 1/4 (0.140 mi.) K77 162 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Date Closed: 12/08/1998 Global Id: T0608501192 SCVWD ID: 07S1E07P01F SAN JOSE UNIFIED SCH 250 STOCKTON AVE SW 1/8 - 1/4 (0.140 mi.) K78 167 Database: LUST REG 2, Date of Government Version: 09/30/2004 Facility Status: Case Closed date9: 12/8/1998 SAN JOSE ARENA RITCH **60 MONTGOTMERY ST N** SE 1/8 - 1/4 (0.174 mi.) N99 241 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Id: 43-2157 Facility Status: Case Closed Global Id: T0608501981 date9: 4/9/1997 **PG&E CINNABAR SERVIC** 308 STOCKTON AVE WSW 1/8 - 1/4 (0.190 mi.) P101 244 Database: LUST REG 2, Date of Government Version: 09/30/2004 Facility Status: Case Closed date9: 12/19/2003

308 STOCKTON AVE

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

PG&E CINNABAR SERVIC

Status: Completed - Case Closed Date Closed: 12/19/2003

283

WSW 1/8 - 1/4 (0.190 mi.) P106

Global Id: T0608517440 SCVWD ID: 07S1E07L07F

INTERIOR PLANT DESIG 589 SANTA CLARA ST W S 1/8 - 1/4 (0.196 mi.) R109 294

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0727

Facility Status: Case Closed Date Closed: 04/09/1997 Global Id: T0608500754 SCVWD ID: 07S1E07Q09F

date9: 7/25/1997

SAN JOSE ARENA FOLLO 575 SANTA CLARA ST W S 1/8 - 1/4 (0.197 mi.) R110 296

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST. Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0596

Facility Status: Case Closed Global Id: T0608500632 date9: 4/10/1997

FOLLOSCO TRANSMISSIO 575 W SANTA CLARA ST S 1/8 - 1/4 (0.197 mi.) R111 299

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q05F

KOSICH CONSTRUCTION 555-561 SANTA CLARA S 1/8 - 1/4 (0.197 mi.) R112 299

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0163

Facility Status: Case Closed Global Id: T0608500229

date9: 4/9/1997

SCV PARAMEDICS/SAN J 58 N AUTUMN ST SE 1/8 - 1/4 (0.218 mi.) T120 334

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q02F

KOSICH CONSTRUCTION 555-561 W SANTA CLAR SSE 1/8 - 1/4 (0.223 mi.) T123 335

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q03F

PHILIP SAN PHILIPPO 735 THE ALAMEDA SSW 1/8 - 1/4 (0.235 mi.) V125 336

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 09/17/1997 Global Id: T0608502012 SCVWD ID: 07S1E07P02F

date9: 9/17/1997

CANCILLA PROPERTY 708 W JULIAN ST. WSW 1/8 - 1/4 (0.235 mi.) P128 343

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Global Id: T10000007704

DOWNTOWN TRUCK & TRA 405 SANTA CLARA ST W SE 1/8 - 1/4 (0.237 mi.) T132 349

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0484

Facility Status: Case Closed Date Closed: 04/09/1997 Global Id: T0608500530 SCVWD ID: 07S1E07Q04F

date9: 4/9/1997

BANK OF AMERICA/WELL 521 W SANTA CLARA ST SE 1/8 - 1/4 (0.241 mi.) T136 355

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q06F

DOWNTOWN DATSUN 443 W SANTA CLARA ST SE 1/8 - 1/4 (0.241 mi.) T137 356

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q07F

BANK OF AMERICA WELL 521 SANTA CLARA ST W SE 1/8 - 1/4 (0.241 mi.) T140 359

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0145

Facility Status: Case Closed Global Id: T0608500211

date9: 4/9/1997

AIR SYSTEMS INC 381 STOCKTON AVE W 1/8 - 1/4 (0.244 mi.) W143 362

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Global Id: T0608500108

AIR SYSTEMS 381 STOCKTON AVE W 1/8 - 1/4 (0.244 mi.) W145 366

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed

date9: 10/22/1997

TIM'S AUTO TRIM 369 STOCKTON AVE W 1/8 - 1/4 (0.244 mi.) W 146 366

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 08/24/2001 Global Id: T0608591864 SCVWD ID: 07S1E07L06F

date9: 8/24/2001

MORRISON PARK 395 STOCKTON AVENUE W 1/8 - 1/4 (0.244 mi.) W150 373

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Status: Pollution Characterization

Date Closed: 04/03/2009 Global Id: T0608500525 SCVWD ID: 07S1E07L01F

SAN JOSE ARENA BLOCK 522 W SANTA CLARA ST SSE 1/4 - 1/2 (0.252 mi.) T154 385

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Global Id: T0608500220

SAN JOSE ARENA BLOCK 522 SANTA CLARA SSE 1/4 - 1/2 (0.252 mi.) T155 390

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Post remedial action monitoring

Date Closed: 02/13/2009 SCVWD ID: 07S1E07Q12F

S & W LAND COMPANY 454 W SANTA CLARA ST SE 1/4 - 1/2 (0.262 mi.) T157 393

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 04/09/1999 Global Id: T0608502143 SCVWD ID: 07S1E07Q15F

date9: 4/9/1999

DEL MONTE PLANT 51 50 BUSH ST SSW 1/4 - 1/2 (0.285 mi.) X162 397

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed

date9: 9/6/1995

DEL MONTE PLANT 51 50 BUSH ST SSW 1/4 - 1/2 (0.285 mi.) X163 397

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Date Closed: 09/06/1995

Global Id: T0608500504 SCVWD ID: 07S1E18C02F

BOCARDO PROPERTY 849 THE ALAMEDA SW 1/4 - 1/2 (0.301 mi.) 164 400

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 08/26/2003 Global Id: T0608548658 SCVWD ID: 07S1E07P03F

date9: 9/2/2003

MANNING PROPERTY 35 RIVER ST N ESE 1/4 - 1/2 (0.303 mi.) Z165 403

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0854

date9: 3/3/1997

Facility Status: Case Closed Global Id: T0608500865

SERPA PROPERTY 435 STOCKTON ST

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

409

WNW 1/4 - 1/2 (0.324 mi.) AB170

Status: Completed - Case Closed Date Closed: 05/22/2002 Global Id: T0608502421 SCVWD ID: 07S1E07M04F SERPA PROPERTY 435 STOCKTON ST WNW 1/4 - 1/2 (0.324 mi.) AB171 413 Database: LUST REG 2, Date of Government Version: 09/30/2004 Facility Status: Case Closed date9: 5/22/2002 COMERICA BANK BUILDI 333 W SANTA CLARA ST E 1/4 - 1/2 (0.325 mi.) 172 413 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Status: Preliminary site assessment underway Date Closed: 09/01/2011 Global Id: T0608501998 SCVWD ID: 07S1E07R03F SAN JOSE ARENA (RITC **60 N MONTGOMERY ST** SSE 1/4 - 1/2 (0.334 mi.) 418 AA173 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q13F **VITALE AUTO BODY 52 AUTUMN** SSE 1/4 - 1/2 (0.334 mi.) AC175 425 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Id: 43-1611 Facility Status: Case Closed Global Id: T0608501566 date9: 7/19/1991 **VITALE BODY SHOP 52 S AUTUMN ST** SSE 1/4 - 1/2 (0.334 mi.) AC176 427 Database: LUST REG 2, Date of Government Version: 09/30/2004 Facility Status: Case Closed date9: 7/26/1991 **VITALE BODY SHOP 52 S AUTUMN ST** SSE 1/4 - 1/2 (0.334 mi.) AC177 428 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Date Closed: 07/26/1991 Global Id: T0608595685 SCVWD ID: 07S1E18B02F SCVWD PROPERTY 361 SANTA CLARA ST W ESE 1/4 - 1/2 (0.352 mi.) 182 438 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Id: 43-1712 Facility Status: Case Closed Global Id: T0608501653 date9: 3/3/1997 SCV PARAMEDICS SJ AM **58 AUTUMN ST N** SSE 1/4 - 1/2 (0.356 mi.) 441 AC183 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0072 Facility Status: Case Closed Global Id: T0608500140

date9: 4/9/1997

SAN JOSE ARENA JULIA 70-90 MONTGOMERY N SSE 1/4 - 1/2 (0.362 mi.) AA185 444

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-2213

Facility Status: Case Closed Global Id: T0608502031 date9: 4/9/1997

AUTOMATIC CAR WASH 77 S MONTGOMERY ST S 1/4 - 1/2 (0.362 mi.) AA186 447

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST. Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 11/02/1995 Global Id: T0608500198 SCVWD ID: 07S1E18B03F

date9: 11/2/1995

SOUTHERN PACIFIC TRA 595 LENZEN AVE WNW 1/4 - 1/2 (0.363 mi.) AE188 454

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed

date9: 2/11/1992

SOUTHERN PACIFIC TRA 595 LENZEN WNW 1/4 - 1/2 (0.363 mi.) AE189 455

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Date Closed: 02/11/1992

Global Id: T0608501340 SCVWD ID: 07S1E07F03F

PG&E 655 LENZEN AVE WNW 1/4 - 1/2 (0.369 mi.) AE193 467

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 02/05/1999 Global Id: T0608501053 SCVWD ID: 07S1E07L02F

date9: 2/5/1999

BRANDENBURG PROPERTI 185 JULIAN W NE 1/4 - 1/2 (0.379 mi.) AD195 473

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-2416
Facility Status: Case Closed
Global Id: T0608503496
date9: 3/27/2002

SAN JOSE ARENA (GIES 80 N MONTGOMERY SSE 1/4 - 1/2 (0.383 mi.) AH196 475

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/09/1997 SCVWD ID: 07S1E07Q14F

CHEVRON #9-0882 955 THE ALAMEDA SW 1/4 - 1/2 (0.388 mi.) Al197 475

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Global Id: T0608500403

CHEVRON #9-0882 955 THE ALAMEDA SW 1/4 - 1/2 (0.388 mi.) Al199 477

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed

date9: 4/11/1991

CHEVRON #9-0882 955 THE ALAMEDA SW 1/4 - 1/2 (0.388 mi.) Al200 478

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 04/11/1991 SCVWD ID: 07S1E07N02F

DERBY FOOD SERVICE 55 SUNOL ST SW 1/4 - 1/2 (0.388 mi.) 201 479

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 01/02/1991 Global Id: T0608500508 SCVWD ID: 07S1E18C01F

date9: 1/2/1991

CAMPISI TRUST 975 THE ALAMEDA WSW 1/4 - 1/2 (0.389 mi.) Al202 481

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Date Closed: 07/25/2012 Global Id: T0608527783 SCVWD ID: 07S1E07N05F

SAN JOSE ARENA PG & 90 MONTGOMERY ST N SSE 1/4 - 1/2 (0.392 mi.) AH203 490

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-2159
Facility Status: Case Closed
Global Id: T0608501983

date9: 10/1/1997

BRANDENBURG PROPERTI 160 JULIAN W NE 1/4 - 1/2 (0.400 mi.) AJ207 500

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-2417 Facility Status: Case Closed Global Id: T0608595937 date9: 6/11/2003

COMMON GROUND LANDSC 725 LENZEN AV WNW 1/4 - 1/2 (0.401 mi.) 209 503

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Status: Case Closed Date Closed: 10/07/2003 Global Id: T0608500684 SCVWD ID: 07S1E07M01F

date9: 10/7/2003

BRANDENBURG PROPERTI 160 W JULIAN ST NE 1/4 - 1/2 (0.402 mi.) AJ212 532

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 03/27/2002 SCVWD ID: 07S1E07H04F

THOMAS FALLON HOUSE 175 W SAINT JOHN ST ENE 1/4 - 1/2 (0.406 mi.) 214 532

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 10/03/1994 Global Id: T0608524383 SCVWD ID: 07S1E08M02F

date9: 10/3/1994

U-HAUL MOVING & STOR 1027 THE ALAMEDA WSW 1/4 - 1/2 (0.414 mi.) AK215 534

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed

date9: 8/16/1993

DOWNTOWN MC 1027 THE ALAMEDA WSW 1/4 - 1/2 (0.414 mi.) AK216 538

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Date Closed: 08/16/1993 Global Id: T0608570600

SCVWD ID: 07S1E07N03F

NATIONAL RAILROAD PA 510 W SAN FERNANDO S SSE 1/4 - 1/2 (0.425 mi.) AH217 541

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 03/30/1992 Global Id: T0608500278 SCVWD ID: 07S1E18B01F

date9: 3/30/1992

VERIZON BUSINESS: SN 500 STOCKTON AV WNW 1/4 - 1/2 (0.427 mi.) AL218 545

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Date Closed: 02/19/1998 Global Id: T0608501530 SCVWD ID: 07S1E07M02F

UNOCAL #0688 500 STOCKTON AVE WNW 1/4 - 1/2 (0.427 mi.) AL219 549

Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed

date9: 2/19/1998

BRANDENBURG PROPERTI 355 N SAN PEDRO NE 1/4 - 1/2 (0.431 mi.) AM220 549

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Date Closed: 03/27/2002 SCVWD ID: 07S1E07H02F **PG&E SUBSTATION A** 17 OTTERSON ST S 1/4 - 1/2 (0.434 mi.) 550 AN221 Database: LUST REG 2, Date of Government Version: 09/30/2004 Facility Status: Case Closed date9: 7/31/2001 **COLLEGE PARK** 190 RYLAND STREET NNE 1/4 - 1/2 (0.434 mi.) AO222 550 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Date Closed: 06/28/2005 Global Id: T0608502142 SCVWD ID: 07S1E07H07F **BRANDENBURG PROPERTI** 345 SAN PEDRO N NE 1/4 - 1/2 (0.440 mi.) AM224 553 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Id: 43-2415 Facility Status: Case Closed Global Id: T0608568823 date9: 3/27/2002 SAN JOSE MERCURY NEW 211 W. SANTA CLARA S E 1/4 - 1/2 (0.441 mi.) AP225 555 Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Open - Verification Monitoring Facility Status: Case Closed Global Id: T0608502045 SCVWD ID: 07S1E08M03F date9: 8/16/2000 **DIOCESE OF SAN JOSE** 855 LENZEN 227 564 W 1/4 - 1/2 (0.451 mi.) Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 01/08/1996 Global Id: T0608501831 SCVWD ID: 07S1E07M03F date9: 1/8/1996 SAN JOSE FIRE STATIO 201 N MARKET ST ENE 1/4 - 1/2 (0.458 mi.) AQ229 567 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed Global Id: T0608501618 PG & E SUBSTATION A S 1/4 - 1/2 (0.468 mi.) 17 OTTERSON AN230 569 Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed

1330 THE ALAMEDA

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Global Id: T0608521441

FALSTAFF BREWERY

572

WSW 1/4 - 1/2 (0.470 mi.) 231

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 06/03/1997 Global Id: T0608562859 SCVWD ID: 07S1E07N04F

date9: 6/3/1997

SCVTA RYLAND STREET UNKNOWN RYLAND ST NNE 1/4 - 1/2 (0.482 mi.) AO233 587

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-1240

Facility Status: Case Closed Global Id: T0608501218 date9: 6/27/1996

SJRA - VILLA TORINO 340 N MARKET ST NE 1/4 - 1/2 (0.495 mi.) 234 589

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

SCVWD ID: 07S1E08E01F

Lower Elevation Address Direction / Distance Map ID Page

MILLIGAN NEWS 150 N AUTUMN ST E 0 - 1/8 (0.087 mi.) F28 59

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 01/24/1997 Global Id: T0608500904 SCVWD ID: 07S1E07K03F

date9: 1/24/1997

MANADA TILE 517 W SAINT JOHN ST SE 0 - 1/8 (0.107 mi.) H46 96

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018 Status: Completed - Case Closed

Facility Status: Case Closed Date Closed: 05/30/1996 Global Id: T0608500864 SCVWD ID: 07S1E07Q10F

date9: 5/30/1996

AC LABEL CO 350 NO MONTGOMERY NW 0 - 1/8 (0.120 mi.) G70 148

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

SCVWD ID: 07S1E07K01F

LINCOLN PROPERTY 469 HOWARD NNW 0 - 1/8 (0.121 mi.) 171 154

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 02/26/1993 Global Id: T0608501646 SCVWD ID: 07S1E07K02F

date9: 2/26/1993

GRUTHFIELD PROPERTY 370 N MONTGOMERY NW 1/8 - 1/4 (0.152 mi.) L81 183

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 04/27/2000 Global Id: T0608502082 SCVWD ID: 07S1E07L05F

date9: 4/27/2000

RIVER STREET PROJECT 350 W JULIAN ST ENE 1/8 - 1/4 (0.171 mi.) 98 238

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 07/23/2001 Global Id: T0608589591 SCVWD ID: 07S1E07J01F

date9: 7/23/2001

DISTRICT PROPERTY 361 W SANTA CLARA ST ESE 1/8 - 1/4 (0.223 mi.) 122 335

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

SCVWD ID: 07S1E07R02F

SAN JOSE ARENA HOLEM 443 SANTA CLARA ST W SE 1/4 - 1/2 (0.261 mi.) T156 391

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-0704

Facility Status: Case Closed Global Id: T0608500733

date9: 4/10/1997

1-2-3 POOL SERVICE 455 COLEMAN AVE N 1/4 - 1/2 (0.362 mi.) AF187 451

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 03/02/1995 Global Id: T0608501855 SCVWD ID: 07S1E07G02F

date9: 3/2/1995

MR AIR SWEEPERS 483 COLEMAN AVE NNW 1/4 - 1/2 (0.366 mi.) AG191 458

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014 Database: LUST REG 2, Date of Government Version: 09/30/2004

Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 10/31/1995 Global Id: T0608501012 SCVWD ID: 07S1E07D04F

date9: 10/31/1995

BRANDENBURG PROPERTI 330 TERRAINE ST NE 1/4 - 1/2 (0.374 mi.) AD194 470

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed

Facility Id: 43-2418
Facility Status: Case Closed

Global Id: T0608571841 date9: 3/27/2002

WELLS FARGO ALARM SE 466 VENDOME ST N 1/4 - 1/2 (0.399 mi.) AF206 497

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 02/19/1991 Global Id: T0608501580 SCVWD ID: 07S1E07G01F

date9: 2/19/1991

HARDCASTLE AUTOTHON 590 COLEMAN AVENUE NNW 1/4 - 1/2 (0.473 mi.) 232 575

Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014

Database: LUST REG 2, Date of Government Version: 09/30/2004 Database: LUST, Date of Government Version: 12/10/2018

Status: Completed - Case Closed Facility Status: Case Closed Date Closed: 12/29/1995 Global Id: T0608500708 SCVWD ID: 07S1E07F01F date9: 12/29/1995

CPS-SLIC: Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the CPS-SLIC list, as provided by EDR, has revealed that there are 26 CPS-SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FLEET BODY WORX Database: CPS-SLIC, Date of Government Facility Status: Open - Inactive Global Id: T10000008060	345 N MONTGOMERY t Version: 12/10/2018	NW 0 - 1/8 (0.112 mi.)	G57	119
SAN JOSE UNIFIED SCH Database: CPS-SLIC, Date of Governmen Facility Status: Completed - Case Closed Global Id: T10000005262	250 STOCKTON AVE t Version: 12/10/2018	SW 1/8 - 1/4 (0.140 mi.)	K77	162
VASPAIO AT DIRADON Database: CPS-SLIC, Date of Governmen Facility Status: Open - Eligible for Closure Global Id: T10000010091	138 STOCKTON AVENUE t Version: 12/10/2018	SSW 1/8 - 1/4 (0.158 mi.)	M83	193
HANOVER 715 W JULIAN Database: CPS-SLIC, Date of Governmen Facility Status: Open - Active Global Id: T10000012367	715 W JULIAN ST t Version: 12/10/2018	WSW 1/8 - 1/4 (0.207 mi.)	P116	325
SAN JOSE ARENA Database: SLIC REG 2, Date of Government Facility Id: 43S0538	UNKNOWN UKNOWN ent Version: 09/30/2004	SSE 1/8 - 1/4 (0.236 mi.)	T130	348
MORRISON PARK Database: CPS-SLIC, Date of Government	395 STOCKTON AVENUE It Version: 12/10/2018	W 1/8 - 1/4 (0.244 mi.)	W150	373

Facility Status: Completed - Case Closed Global Id: T0608573680 **DEL MONTE PLANT 51** 50 BUSH SSW 1/4 - 1/2 (0.285 mi.) X161 396 Database: SLIC REG 2, Date of Government Version: 09/30/2004 Facility Id: 43S0956 **DEL MONTE PLANT 51** 50 BUSH ST SSW 1/4 - 1/2 (0.285 mi.) X163 397 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Open - Inactive Global Id: T0608591714 **CINNABAR COMMONS 875 CINNABAR STREET** W 1/4 - 1/2 (0.311 mi.) 167 406 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Completed - Case Closed Global Id: SL0608552906 **DIRIDON STATION JV** W SANTA CLARA ST AND SE 1/4 - 1/2 (0.314 mi.) Y168 407 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Open - Assessment & Interim Remedial Action Global Id: T10000009352 PERRUCCI PROPERTIES **53 MONTGOMERY S** SSE 1/4 - 1/2 (0.322 mi.) AA169 408 Database: SLIC REG 2, Date of Government Version: 09/30/2004 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Completed - Case Closed Facility Id: 43S0528 Global Id: T0608591654 **CALTRAIN SOUTH TERMI** 65 CAHILL ST S 1/4 - 1/2 (0.334 mi.) 174 418 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Open - Verification Monitoring Global Id: SL0608582748 MARIAN JOHNSON 59 SUTUM ST S SSE 1/4 - 1/2 (0.346 mi.) AA178 430 Database: SLIC REG 2, Date of Government Version: 09/30/2004 Facility Id: 43S0447 **CARLYSLE DEVELOPMENT 76 NOTRE DAME** E 1/4 - 1/2 (0.347 mi.) 179 430 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Completed - Case Closed Global Id: T10000003326 235 WEST JULIAN STRE 235 WEST JULIAN STRE NE 1/4 - 1/2 (0.368 mi.) AD192 466 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Open - Inactive Global Id: SL0608515396 **BOUNDED BY W. JULIAN** NE 1/4 - 1/2 (0.400 mi.) NORTH SAN PEDRO SQUA AD208 502 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Open - Assessment & Interim Remedial Action Global Id: T10000011811 BRANDENBERG, STAEDLE 153 W JULIAN ST NE 1/4 - 1/2 (0.402 mi.) AJ210 521 Database: SLIC REG 2, Date of Government Version: 09/30/2004 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Completed - Case Closed Facility Id: SL18218598 Global Id: SL18218598 ADOBE NORTH TOWER 333 WEST SAN FERNAND ESE 1/4 - 1/2 (0.451 mi.) 563 226 Database: CPS-SLIC, Date of Government Version: 12/10/2018 Facility Status: Open - Assessment & Interim Remedial Action

Global Id: T10000012042

Lower Elevation	Address	Direction / Distance	Map ID	Page
PLATFORM 16 Database: CPS-SLIC, Date of Government Facility Status: Open - Active Global Id: T10000012200	440 W JULIAN ST ent Version: 12/10/2018	NNE 0 - 1/8 (0.062 mi.)	E17	48
AC LABEL CO/BERRYMAN Database: SLIC REG 2, Date of Governing Facility Id: SL18217597	350 NORTH MONTGOMERY ment Version: 09/30/2004	NW 0 - 1/8 (0.120 mi.)	G67	138
SCR-A C LABEL/BERRYM Database: CPS-SLIC, Date of Governme Facility Status: Completed - Case Closed Global Id: SL18217597		NW 0 - 1/8 (0.120 mi.)	G69	141
FMC CORP SAN JOSE OR Database: SLIC REG 2, Date of Governing Facility Id: 43-1965	333 JULIAN ST ment Version: 09/30/2004	NE 1/8 - 1/4 (0.164 mi.)	O89	203
FMC CORP SAN JOSE OR Database: SLIC REG 2, Date of Government Database: CPS-SLIC, Date of Government Facility Status: Open - Eligible for Closur Facility Id: SL20214832 Global Id: SL20214832	ent Version: 12/10/2018	NE 1/8 - 1/4 (0.168 mi.)	O90	203
NORTH SAN PEDRO APAR Database: CPS-SLIC, Date of Government Facility Status: Open - Active Global Id: T10000011850	201 BASSETT ST ent Version: 12/10/2018	NE 1/4 - 1/2 (0.349 mi.)	181	437
COLLEGE PARK YARD - Database: SLIC REG 2, Date of Governi Facility Id: 43S0936	483 COLEMAN AVE ment Version: 09/30/2004	NNW 1/4 - 1/2 (0.366 mi.)	AG190	458
MR AIR SWEEPERS Database: CPS-SLIC, Date of Government Facility Status: Open - Verification Monit Global Id: SL18381801		NNW 1/4 - 1/2 (0.366 mi.)	AG191	458

HIST LUST: A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

A review of the HIST LUST list, as provided by EDR, and dated 03/29/2005 has revealed that there are 53 HIST LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE ARENA (JULI SCVWD ID: 07S1E07K05	565 W JULIAN	W 0 - 1/8 (0.062 mi.)	C18	49
SAN JOSE FOUNDRY SCVWD ID: 07S1E07Q01	525 W SAINT JOHN ST	SE 0 - 1/8 (0.097 mi.)	H36	66
VINCENT ELECTRIC MOT	341 N MONTGOMERY ST	NW 0 - 1/8 (0.112 mi.)	G54	104

SCVWD ID: 07S1E07L04				
CUSTOMPAD&PATTERN/LA SCVWD ID: 07S1E07Q08	555 W SAINT JOHN ST	SE 0 - 1/8 (0.115 mi.)	H64	131
SAN JOSE UNIFIED SCH SCVWD ID: 07S1E07P01	250 STOCKTON AVE	SW 1/8 - 1/4 (0.140 mi.)	K78	167
INTERIOR PLANT DESIG SCVWD ID: 07S1E07Q09	589 SANTA CLARA ST W	S 1/8 - 1/4 (0.196 mi.)	R109	294
FOLLOSCO TRANSMISSIO SCVWD ID: 07S1E07Q05	575 W SANTA CLARA ST	S 1/8 - 1/4 (0.197 mi.)	R111	299
SCV PARAMEDICS/SAN J SCVWD ID: 07S1E07Q02	58 N AUTUMN ST	SE 1/8 - 1/4 (0.218 mi.)	T120	334
PHILIP SAN PHILIPPO SCVWD ID: 07S1E07P02	735 THE ALAMEDA	SSW 1/8 - 1/4 (0.235 mi.)	V125	336
DOWNTOWN TRUCK & TRA SCVWD ID: 07S1E07Q04	405 SANTA CLARA ST W	SE 1/8 - 1/4 (0.237 mi.)	T132	349
BANK OF AMERICA/WELL SCVWD ID: 07S1E07Q06	521 W SANTA CLARA ST	SE 1/8 - 1/4 (0.241 mi.)	T136	355
UNKNOWN SCVWD ID: 07S1E07Q07	443 W SANTA CLARA ST	SE 1/8 - 1/4 (0.241 mi.)	T139	358
AIR SYSTEMS SCVWD ID: 07S1E07L03	381 STOCKTON AVE	W 1/8 - 1/4 (0.244 mi.)	W145	366
TIM'S AUTO TRIM SCVWD ID: 07S1E07L06	369 STOCKTON AVE	W 1/8 - 1/4 (0.244 mi.)	W146	366
MORRISON PARK SCVWD ID: 07S1E07L01	395 STOCKTON AVENUE	W 1/8 - 1/4 (0.244 mi.)	W150	373
SAN JOSE ARENA BLOCK SCVWD ID: 07S1E07Q12	522 SANTA CLARA	SSE 1/4 - 1/2 (0.252 mi.)	T155	390
S & W LAND COMPANY SCVWD ID: 07S1E07Q15	454 W SANTA CLARA ST	SE 1/4 - 1/2 (0.262 mi.)	T157	393
DEL MONTE PLANT 51 SCVWD ID: 07S1E18C02	50 BUSH ST	SSW 1/4 - 1/2 (0.285 mi.)	X162	397
BOCARDO PROPERTY SCVWD ID: 07S1E07P03	849 THE ALAMEDA	SW 1/4 - 1/2 (0.301 mi.)	164	400
MANNING PROPERTY SCVWD ID: 07S1E07R01	35 RIVER ST N	ESE 1/4 - 1/2 (0.303 mi.)	Z165	403
SERPA PROPERTY SCVWD ID: 07S1E07M04	435 STOCKTON ST	WNW 1/4 - 1/2 (0.324 mi.)	AB171	413
COMERICA BANK BUILDI SCVWD ID: 07S1E07R03	333 W SANTA CLARA ST	E 1/4 - 1/2 (0.325 mi.)	172	413
SAN JOSE ARENA (RITC SCVWD ID: 07S1E07Q13	60 N MONTGOMERY ST	SSE 1/4 - 1/2 (0.334 mi.)	AA173	418
VITALE BODY SHOP SCVWD ID: 07S1E18B02	52 S AUTUMN ST	SSE 1/4 - 1/2 (0.334 mi.)	AC176	427
AUTOMATIC CAR WASH SCVWD ID: 07S1E18B03	77 S MONTGOMERY ST	S 1/4 - 1/2 (0.362 mi.)	AA186	447
SOUTHERN PACIFIC TRA	595 LENZEN AVE	WNW 1/4 - 1/2 (0.363 mi.)	AE188	454

SCVWD ID: 07S1E07F03				
PG&E SCVWD ID: 07S1E07L02	655 LENZEN AVE	WNW 1/4 - 1/2 (0.369 mi.)	AE193	467
SAN JOSE ARENA (GIES SCVWD ID: 07S1E07Q14	80 N MONTGOMERY	SSE 1/4 - 1/2 (0.383 mi.)	AH196	475
CHEVRON #9-0882 SCVWD ID: 07S1E07N02	955 THE ALAMEDA	SW 1/4 - 1/2 (0.388 mi.)	AI199	477
DERBY FOOD SERVICE SCVWD ID: 07S1E18C01	55 SUNOL ST	SW 1/4 - 1/2 (0.388 mi.)	201	479
COMMON GROUND LANDSC SCVWD ID: 07S1E07M01	725 LENZEN AV	WNW 1/4 - 1/2 (0.401 mi.)	209	503
BRANDENBURG PROPERTI SCVWD ID: 07S1E07H04	160 W JULIAN ST	NE 1/4 - 1/2 (0.402 mi.)	AJ213	532
THOMAS FALLON HOUSE SCVWD ID: 07S1E08M02	175 W SAINT JOHN ST	ENE 1/4 - 1/2 (0.406 mi.)	214	532
U-HAUL MOVING & STOR SCVWD ID: 07S1E07N03	1027 THE ALAMEDA	WSW 1/4 - 1/2 (0.414 mi.)	AK215	534
NATIONAL RAILROAD PA SCVWD ID: 07S1E18B01	510 W SAN FERNANDO S	SSE 1/4 - 1/2 (0.425 mi.)	AH217	541
UNOCAL #0688 SCVWD ID: 07S1E07M02	500 STOCKTON AVE	WNW 1/4 - 1/2 (0.427 mi.)	AL219	549
BRANDENBURG PROPERTI SCVWD ID: 07S1E07H02	355 N SAN PEDRO	NE 1/4 - 1/2 (0.431 mi.)	AM220	549
PG&E SUBSTATION A SCVWD ID: 07S1E18B05	17 OTTERSON ST	S 1/4 - 1/2 (0.434 mi.)	AN221	550
SAN JOSE MERCURY NEW SCVWD ID: 07S1E08M03	211 W. SANTA CLARA S	E 1/4 - 1/2 (0.441 mi.)	AP225	555
DIOCESE OF SAN JOSE SCVWD ID: 07S1E07M03	855 LENZEN	W 1/4 - 1/2 (0.451 mi.)	227	564
FALSTAFF BREWERY SCVWD ID: 07S1E07N04	1330 THE ALAMEDA	WSW 1/4 - 1/2 (0.470 mi.)	231	572
SJRA - VILLA TORINO SCVWD ID: 07S1E08E01	340 N MARKET ST	NE 1/4 - 1/2 (0.495 mi.)	234	589
Lower Elevation	Address	Direction / Distance	Map ID	Page
MILLIGAN NEWS SCVWD ID: 07S1E07K03	150 N AUTUMN ST	E 0 - 1/8 (0.087 mi.)	F28	59
MANADA TILE SCVWD ID: 07S1E07Q10	517 W SAINT JOHN ST	SE 0 - 1/8 (0.107 mi.)	H46	96
USA TOUCH-UP SERVICE SCVWD ID: 07S1E07K01	350 N MONTGOMERY ST	NW 0 - 1/8 (0.120 mi.)	G68	138
LINCOLN PROPERTY SCVWD ID: 07S1E07K02	469 HOWARD	NNW 0 - 1/8 (0.121 mi.)	<i>1</i> 71	154
GRUTHFIELD PROPERTY SCVWD ID: 07S1E07L05	370 N MONTGOMERY	NW 1/8 - 1/4 (0.152 mi.)	L81	183
RIVER STREET PROJECT	350 W JULIAN ST	ENE 1/8 - 1/4 (0.171 mi.)	98	238

SCVWD ID: 07S1E07J01				
DISTRICT PROPERTY SCVWD ID: 07S1E07R02	361 W SANTA CLARA ST	ESE 1/8 - 1/4 (0.223 mi.)	122	335
1-2-3 POOL SERVICE SCVWD ID: 07S1E07G02	455 COLEMAN AVE	N 1/4 - 1/2 (0.362 mi.)	AF187	451
MR AIR SWEEPERS SCVWD ID: 07S1E07D04	483 COLEMAN AVE	NNW 1/4 - 1/2 (0.366 mi.)	AG191	458
WELLS FARGO ALARM SE SCVWD ID: 07S1E07G01	466 VENDOME ST	N 1/4 - 1/2 (0.399 mi.)	AF206	497
HARDCASTLE AUTOTHON SCVWD ID: 07S1E07F01	590 COLEMAN AVENUE	NNW 1/4 - 1/2 (0.473 mi.)	232	575

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there are 3 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE FOUNDRY Database: UST CLOSURE, Date of	525 W. SAINT JOHN ST f Government Version: 12/10/2018	SE 0 - 1/8 (0.097 mi.)	H37	76
PACIFIC GAS & ELECTR Database: UST, Date of Governme Facility Id: FA0208679 Facility Id: 405875	308 STOCKTON AVE nt Version: 12/10/2018	WSW 1/8 - 1/4 (0.190 mi.)	P105	283
PACIFIC BELL (FUEL U Database: UST, Date of Governme Facility Id: 402619	1 S MONTGOMERY ST nt Version: 12/10/2018	SSE 1/8 - 1/4 (0.229 mi.)	R124	335

AST: A listing of aboveground storage tank petroleum storage tank locations.

A review of the AST list, as provided by EDR, has revealed that there are 3 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CERULEAN GLOBAL SERV Database: AST, Date of Governme	250 STOCKTON AVE nt Version: 07/06/2016	SW 1/8 - 1/4 (0.140 mi.)	K76	162
PG&E: CINNABAR SERVI Database: AST, Date of Governme	308 STOCKTON AV nt Version: 07/06/2016	WSW 1/8 - 1/4 (0.190 mi.)	P100	243
CINNABAR SERVICE CEN Database: AST, Date of Governme	308 STOCKTON AVE. nt Version: 07/06/2016	WSW 1/8 - 1/4 (0.190 mi.)	P103	245

State and tribal Brownfields sites

BROWNFIELDS: A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

A review of the BROWNFIELDS list, as provided by EDR, and dated 09/24/2018 has revealed that there are 4 BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MORRISON PARK	395 STOCKTON AVENUE	W 1/8 - 1/4 (0.244 mi.)	W150	373
CALTRAIN SOUTH TERMI	65 CAHILL ST	S 1/4 - 1/2 (0.334 mi.)	174	418
235 WEST JULIAN STRE	235 WEST JULIAN STRE	NE 1/4 - 1/2 (0.368 mi.)	AD192	466
NORTH SAN PEDRO SQUA	BOUNDED BY W. JULIAN	NE 1/4 - 1/2 (0.400 mi.)	AD208	502

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

HIST Cal-Sites: Formerly known as ASPIS, this database contains both known and potential hazardous substance sites. The source is the California Department of Toxic Substance Control. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

A review of the HIST Cal-Sites list, as provided by EDR, and dated 08/08/2005 has revealed that there is 1 HIST Cal-Sites site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE SPORTS AREN	525 WEST SANTA CLARA	SSW 0 - 1/8 (0.054 mi.)	B14	22

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 10/22/2018 has revealed that there are 14 CERS HAZ WASTE sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAP CENTER	525 W SANTA CLARA ST	SSW 0 - 1/8 (0.054 mi.)	B15	37
FLEET BODYWORK	341 N MONTGOMERY ST	NW 0 - 1/8 (0.112 mi.)	G55	107
SAN JOSE AUTO BODY	60 STOCKTON AVENUE	SSW 1/8 - 1/4 (0.168 mi.)	M97	220
PG&E: CINNABAR SERVI	308 STOCKTON AV	WSW 1/8 - 1/4 (0.190 mi.)	P104	246
SAN JOSE AUTO STEAM	32 STOCKTON AVE	SSW 1/8 - 1/4 (0.198 mi.)	M113	302
WHOLE FOODS MARKET -	777 THE ALAMEDA	SW 1/8 - 1/4 (0.211 mi.)	Q117	326
AV MACHINE SHOP	710 W JULIAN ST	WSW 1/8 - 1/4 (0.235 mi.)	P126	338
Lower Elevation	Address	Direction / Distance	Map ID	Page
CAGWIN & DORWARD	255 N AUTUMN ST	0 - 1/8 (0.000 mi.)	A1	8
ACME SAW SALES & SER	475 W JULIAN ST	N 0 - 1/8 (0.067 mi.)	E20	50
DNT AUTOMOTIVE	338 N MONTGOMERY ST	NW 0 - 1/8 (0.102 mi.)	G39	77
ARCHITECTURAL FACADE	490 HOWARD STREET	N 0 - 1/8 (0.105 mi.)	144	87
VALAYA AUTO	447 W ST JOHN ST	ESE 0 - 1/8 (0.113 mi.)	F60	124

Lower Elevation	Address	Direction / Distance	Map ID	Page
BERRYMAN PRODUCTS	350 N MONTGOMERY ST	NW 0 - 1/8 (0.120 mi.)	G66	132
GRUTHFIELD PROPERTY	370 N MONTGOMERY	NW 1/8 - 1/4 (0.152 mi.)	L81	183

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 7 SWEEPS UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
C & M DIVERSIFIED CO Comp Number: 400336	330 N MONTGOMERY ST	NW 0 - 1/8 (0.092 mi.)	G31	63
S J FOUNDRY Comp Number: 400155	525 W ST JOHN ST	SE 0 - 1/8 (0.097 mi.)	H35	65
SAN JOSE UNIFIED SCH Status: A Tank Status: A Comp Number: 400616	250 STOCKTON AVE	SW 1/8 - 1/4 (0.140 mi.)	K78	167
PACIFIC GAS & ELECTR Status: A Tank Status: A Comp Number: 405875	308 STOCKTON AVENUE	WSW 1/8 - 1/4 (0.190 mi.)	P102	244
AIR SYSTEMS INC Comp Number: 403131	381 STOCKTON AVENUE	W 1/8 - 1/4 (0.244 mi.)	W147	369
Lower Elevation	Address	Direction / Distance	Map ID	Page
MILLIGAN NEWS Comp Number: 401454	150 N AUTUMN ST	E 0 - 1/8 (0.087 mi.)	F28	59
MANADA TILE CO, INC Status: A Tank Status: A Comp Number: 406904	517 W ST JOHN ST	SE 0 - 1/8 (0.107 mi.)	H47	99

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 11 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RALPHS MACHINE SHOP Facility Id: 00000049826	190 N MONTGOMERY ST	SE 0 - 1/8 (0.037 mi.)	B9	19
CUSTOM PAD AND PARTI CUSTOM PAD & PARTITI	555 WEST ST JOHN STR 555 W SAINT JOHN ST	SE 0 - 1/8 (0.115 mi.) SE 0 - 1/8 (0.115 mi.)	H62 H63	130 131

Facility Id: 0000001008				
A.A. ENGINE CO. Facility Id: 00000054620	710-W- JULIAN ST	WSW 1/8 - 1/4 (0.235 mi.)	P127	343
AA ENGINE CO DOWNTOWN DATSUN Facility Id: 00000038844	710 W-JULIAN ST 443 W SANTA CLARA ST	WSW 1/8 - 1/4 (0.235 mi.) SE 1/8 - 1/4 (0.241 mi.)	P129 T137	347 356
AIR SYSTEMS INC Facility Id: 00000058288	381 STOCKTON AVE	W 1/8 - 1/4 (0.244 mi.)	W143	362
DON BOCCI MOBILE AUT Facility Id: 00000014644	395 STOCKTON AVE	W 1/8 - 1/4 (0.244 mi.)	W144	365
Lower Elevation	Address	Direction / Distance	Map ID	Page
AC LABEL CO Facility Id: 0000000987	350 NO MONTGOMERY	NW 0 - 1/8 (0.120 mi.)	G70	148
SCU / PARAMEDICAL SE Facility Id: 00000010372	98 NORTH AUTUMN STRE	SE 1/8 - 1/4 (0.161 mi.)	N88	202
COUNTY OF SANTA CLAR Facility Id: 00000001362	333 JULIAN ST	NE 1/8 - 1/4 (0.168 mi.)	O92	210

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 10/22/2018 has revealed that there are 2 CERS TANKS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CERULEAN GLOBAL SERV	250 STOCKTON AVE	SW 1/8 - 1/4 (0.140 mi.)	K79	168
PG&E: CINNABAR SERVI	308 STOCKTON AV	WSW 1/8 - 1/4 (0.190 mi.)	P104	246

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 12/03/2018 has revealed that there are 6 DEED sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE SPORTS AREN Status: CERTIFIED O&M - LAND US Envirostor ID: 43730007	525 WEST SANTA CLARA E RESTRICTIONS ONLY	SSW 0 - 1/8 (0.054 mi.)	B14	22
SAN JOSE ARENA BLOCK Status: COMPLETED - CASE CLOSE Envirostor ID: T0608500220	522 W SANTA CLARA ST ED	SSE 1/4 - 1/2 (0.252 mi.)	T154	385
CARLYSLE DEVELOPMENT Status: COMPLETED - CASE CLOSE	76 NOTRE DAME ED	E 1/4 - 1/2 (0.347 mi.)	179	430

Envirostor ID: T10000003326

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCR-A C LABEL/BERRYM Status: COMPLETED - CASE CLOSED Envirostor ID: SL18217597	350 MONTGOMERY	NW 0 - 1/8 (0.120 mi.)	G69	141
FMC CORP SAN JOSE OR Status: OPEN - ELIGIBLE FOR CLOSUR Envirostor ID: SL20214832	333 WEST JULIAN STRE	NE 1/8 - 1/4 (0.168 mi.)	O90	203
MR AIR SWEEPERS Status: OPEN - VERIFICATION MONITO Envirostor ID: SL18381801	483 COLEMAN AVE PRING	NNW 1/4 - 1/2 (0.366 mi.)	AG191	458

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there are 4 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A J WASTE EPA ID:: CAD980735419	345 MONTGOMERY ST	NW 0 - 1/8 (0.112 mi.)	G53	103
PREMIER NISSAN EPA ID:: CAD982018699	443 W SANTA CLARA ST	SE 1/8 - 1/4 (0.241 mi.)	T138	357
PACIFIC BELL EPA ID:: CAT080024946	817 THE ALAMEDA	SW 1/8 - 1/4 (0.249 mi.)	153	383
Lower Elevation	Address	Direction / Distance	Map ID	Page
AC LABEL CO EPA ID:: CAD981693492	350 NO MONTGOMERY	NW 0 - 1/8 (0.120 mi.)	G70	148

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 11/15/2018 has revealed that there is 1

FINDS site within approximately 0.001 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CAGWIN & DORWARD	255 N AUTUMN ST	0 - 1/8 (0.000 mi.)	A3	16
Registry ID:: 110066417979				

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 09/24/2018 has revealed that there are 3 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BRANDENBURG FAMILY A	153 JULIAN	NE 1/4 - 1/2 (0.402 mi.)	AJ211	524
Lower Elevation	Address	Direction / Distance	Map ID	Page
SCR-A C LABEL/BERRYM FMC CORPORATION	350 MONTGOMERY 333 JULIAN	NW 0 - 1/8 (0.120 mi.) NE 1/8 - 1/4 (0.168 mi.)	G69 O93	141 211

CUPA Listings: A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

A review of the CUPA Listings list, as provided by EDR, has revealed that there are 46 CUPA Listings sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
	240 N MONTGOMERY ST ate of Government Version: 11/16/20	SSE 0 - 1/8 (0.007 mi.)	A5	17
	230 N MONTGOMERY ST rate of Government Version: 11/16/20	SE 0 - 1/8 (0.020 mi.) 018	A6	18
SAP CENTER Database: CUPA SANTA CLARA, D	525 W SANTA CLARA ST atte of Government Version: 11/16/20	SSW 0 - 1/8 (0.054 mi.) 018	B15	37
	573 W JULIAN ST ate of Government Version: 11/16/20	, ,	C23	54
	573 W JULIAN ST ate of Government Version: 11/16/20	'	C24	54
ROCK STAR TRUX Database: CUPA SANTA CLARA, D	573 W JULIAN ST ate of Government Version: 11/16/20		C25	54
C & M DIVERSIFIED Database: CUPA SANTA CLARA, D	330 N MONTGOMERY ST atte of Government Version: 11/16/20	NW 0 - 1/8 (0.092 mi.) 118	G30	63
	333 N MONTGOMERY ST ate of Government Version: 11/16/20	WNW 0 - 1/8 (0.093 mi.) 118	G34	65
	341 N MONTGOMERY ST ate of Government Version: 11/16/20	NW 0 - 1/8 (0.112 mi.) 118	G51	102
	341 N MONTGOMERY ST ate of Government Version: 11/16/20	NW 0 - 1/8 (0.112 mi.) 118	G52	102
	250 STOCKTON AV ate of Government Version: 11/16/20	SW 1/8 - 1/4 (0.140 mi.)	K80	182

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE AUTO BODY & Database: CUPA SANTA CLARA, Date of	60 STOCKTON AV Government Version: 11/16/2018	SSW 1/8 - 1/4 (0.168 mi.)	M94	219
CENTURY COLLISION & Database: CUPA SANTA CLARA, Date of	60 STOCKTON AV Government Version: 11/16/2018	SSW 1/8 - 1/4 (0.168 mi.)	M95	220
DHT COLLISION & SERV Database: CUPA SANTA CLARA, Date of	60 STOCKTON AV Government Version: 11/16/2018	SSW 1/8 - 1/4 (0.168 mi.)	M96	220
SAN JOSE AUTO BODY Database: CUPA SANTA CLARA, Date of	60 STOCKTON AVENUE Government Version: 11/16/2018	SSW 1/8 - 1/4 (0.168 mi.)	M97	220
PG&E CINNABAR SERVIC Database: CUPA SANTA CLARA, Date of	308 STOCKTON AVE Government Version: 11/16/2018	WSW 1/8 - 1/4 (0.190 mi.)	P106	283
MASCO SWEEPERS Database: CUPA SANTA CLARA, Date of	120 STOCKTON AV Government Version: 11/16/2018	SSW 1/8 - 1/4 (0.193 mi.)	M107	293
GRIFFEL FURNITURE SH Database: CUPA SANTA CLARA, Date of	165 STOCKTON AV Government Version: 11/16/2018	SW 1/8 - 1/4 (0.193 mi.) 3	Q108	293
SAN JOSE AUTO STEAM Database: CUPA SANTA CLARA, Date of	32 STOCKTON AVE Government Version: 11/16/2018	SSW 1/8 - 1/4 (0.198 mi.)	M113	302
WHOLE FOODS MARKET - Database: CUPA SANTA CLARA, Date of	777 THE ALAMEDA Government Version: 11/16/2018	SW 1/8 - 1/4 (0.211 mi.)	Q117	326
AV MACHINE SHOP Database: CUPA SANTA CLARA, Date of	710 W JULIAN ST Government Version: 11/16/2018	WSW 1/8 - 1/4 (0.235 mi.)	P126	338
CITY OF SJ-CAHILL PU Database: CUPA SANTA CLARA, Date of	4 CAHILL ST Government Version: 11/16/2018	S 1/8 - 1/4 (0.237 mi.)	R131	348
SAN JOSE BLUE Database: CUPA SANTA CLARA, Date of	835 W JULIAN ST Government Version: 11/16/2018	WSW 1/8 - 1/4 (0.238 mi.)	P133	352
NATIONAL AUTO BODY R Database: CUPA SANTA CLARA, Date of	355 STOCKTON AV Government Version: 11/16/2018	W 1/8 - 1/4 (0.244 mi.) 3	W142	361
MIX INTERNATIONAL AU Database: CUPA SANTA CLARA, Date of	355 STOCKTON AV Government Version: 11/16/2018	W 1/8 - 1/4 (0.244 mi.) 3	W148	371
DIRIDON STATION ACE Database: CUPA SANTA CLARA, Date of	785 THE ALAMEDA STE Government Version: 11/16/2018	SW 1/8 - 1/4 (0.246 mi.)	V151	383
Lower Elevation	Address	Direction / Distance	Map ID	Page
CAGWIN & DORWARD Database: CUPA SANTA CLARA, Date of	255 N AUTUMN ST Government Version: 11/16/2018	0 - 1/8 (0.000 mi.)	A2	16
PROFESSIONALS BODY S Database: CUPA SANTA CLARA, Date of	151 N AUTUMN ST Government Version: 11/16/2018	ESE 0 - 1/8 (0.051 mi.)	D12	21
A C E AUTO BODY Database: CUPA SANTA CLARA, Date of	151 N AUTUMN ST Government Version: 11/16/2018	ESE 0 - 1/8 (0.051 mi.)	D13	22
ACME SAW SALES & SER Database: CUPA SANTA CLARA, Date of	475 W JULIAN ST Government Version: 11/16/2018	N 0 - 1/8 (0.067 mi.) 3	E20	50
R & L BROSAMER INC Database: CUPA SANTA CLARA, Date of	406 W JULIAN Government Version: 11/16/2018	NNE 0 - 1/8 (0.070 mi.) 3	E22	53
DNT AUTOMOTIVE Database: CUPA SANTA CLARA, Date of	338 N MONTGOMERY ST Government Version: 11/16/2018	NW 0 - 1/8 (0.102 mi.) 3	G39	77
BRENNER'S AUTOMOTIVE Database: CUPA SANTA CLARA, Date of	330 N AUTUMN ST Government Version: 11/16/2018	N 0 - 1/8 (0.102 mi.) 3	140	86

Lower Elevation	Address	Direction / Distance	Map ID	Page
IA 102813 SALAZAR AU Database: CUPA SANTA CLARA, Date o	330 AUTUMN ST B f Government Version: 11/16/2018	N 0 - 1/8 (0.102 mi.)	142	86
ARCHITECTURAL FACADE Database: CUPA SANTA CLARA, Date or	490 HOWARD STREET f Government Version: 11/16/2018	N 0 - 1/8 (0.105 mi.) B	144	87
VALAYA AUTO Database: CUPA SANTA CLARA, Date o	447 W ST JOHN ST f Government Version: 11/16/2018	ESE 0 - 1/8 (0.113 mi.)	F60	124
AC LABEL CO Database: CUPA SANTA CLARA, Date o	350 NO MONTGOMERY f Government Version: 11/16/2018	NW 0 - 1/8 (0.120 mi.) 8	G70	148
IA 062613 USA TOUCH- Database: CUPA SANTA CLARA, Date o	351 N AUTUMN ST f Government Version: 11/16/2018	NNW 0 - 1/8 (0.124 mi.) 8	173	159
GRUTHFIELD PROPERTY Database: CUPA SANTA CLARA, Date or	370 N MONTGOMERY f Government Version: 11/16/2018	NW 1/8 - 1/4 (0.152 mi.) B	L81	183
CS AUTOWORKS Database: CUPA SANTA CLARA, Date o	383 N AUTUMN ST f Government Version: 11/16/2018	NNW 1/8 - 1/4 (0.159 mi.) 8	L84	201
CAR CARE CLINIC Database: CUPA SANTA CLARA, Date o		NNW 1/8 - 1/4 (0.159 mi.) 8	L85	201
BOSNAK AUTO CONCEPTS Database: CUPA SANTA CLARA, Date o	000	NNW 1/8 - 1/4 (0.159 mi.) 8	L86	201
JOAQUIN MEDIA Database: CUPA SANTA CLARA, Date o	385 N AUTUMN ST f Government Version: 11/16/2018	NNW 1/8 - 1/4 (0.159 mi.)	L87	202
COUNTY OF SANTA CLAR Database: CUPA SANTA CLARA, Date o		NE 1/8 - 1/4 (0.168 mi.) B	O92	210
OUT OF BUSINESS (J L Database: CUPA SANTA CLARA, Date o	566 CINNABAR ST f Government Version: 11/16/2018	WNW 1/8 - 1/4 (0.204 mi.) B	S115	325
SMITH & MCKAY PRINTI Database: CUPA SANTA CLARA, Date o	96 N ALMADEN BL f Government Version: 11/16/2018	E 1/8 - 1/4 (0.239 mi.)	135	355

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency. This database begins with calendar year 1993.

A review of the HAZNET list, as provided by EDR, and dated 12/31/2017 has revealed that there is 1 HAZNET site within approximately 0.001 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CAGWIN & DORWARD	255 N AUTUMN ST	0 - 1/8 (0.000 mi.)	A1	8
GEPAID: CAL000170571				

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 51 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN JOSE ARENA Reg ld: 43-2271	555 SAINT JOHN	SSW 0 - 1/8 (0.054 mi.)	B16	47
SAN JOSE ARENA JULIA Reg ld: 43-2213	565 JULIAN	W 0 - 1/8 (0.062 mi.)	C19	49
MONTGOMERY ST PROPER Reg ld: 43-1441	341 MONTGOMERY ST	NW 0 - 1/8 (0.112 mi.)	G58	121
SAN JOSE FOUNDRY Reg ld: 43-1189	525 JOHN ST	SSE 0 - 1/8 (0.116 mi.)	H65	132
SAN JOSE UNIFIED SCH Reg ld: 43-1206	250 STOCKTON AVE	SW 1/8 - 1/4 (0.140 mi.)	K77	162
INTERIOR PLANT DESIG Reg Id: 43-0727	589 SANTA CLARA ST W	S 1/8 - 1/4 (0.196 mi.)	R109	294
SAN JOSE ARENA FOLLO Reg ld: 43-0596	575 SANTA CLARA ST W	S 1/8 - 1/4 (0.197 mi.)	R110	296
KOSICH CONSTRUCTION Reg ld: 43-0163	561 SANTA CLARA	SSE 1/8 - 1/4 (0.220 mi.)	U121	335
PHILIP SAN PHILIPPO Reg ld: 43-2190	735 THE ALAMEDA	SSW 1/8 - 1/4 (0.235 mi.)	V125	336
DOWNTOWN TRUCK & TRA Reg ld: 43-0484	405 SANTA CLARA ST W	SE 1/8 - 1/4 (0.237 mi.)	T132	349
BANK OF AMERICA WELL Reg ld: 43-0145	521 SANTA CLARA ST W	SE 1/8 - 1/4 (0.241 mi.)	T140	359
BRADFORD MANUFACTURI Reg Id: 43-0198	8 MONTGOMERY	SSE 1/8 - 1/4 (0.244 mi.)	U141	361
AIR SYSTEMS INC Reg ld: 43-0038	381 STOCKTON AVE	W 1/8 - 1/4 (0.244 mi.)	W143	362
MORRISON PARK Reg ld: 43-0479	395 STOCKTON AVENUE	W 1/8 - 1/4 (0.244 mi.)	W150	373
JAMES LICK HIGH SCHO Reg Id: 43-0726	57 WHITE	SSW 1/8 - 1/4 (0.248 mi.)	X152	383
SAN JOSE ARENA BLOCK Reg ld: 43-0154	522 SANTA CLARA	SSE 1/4 - 1/2 (0.252 mi.)	T155	390
EAGLE GAS AND MINI M Reg Id: 43-2073	95 WHITE	SSW 1/4 - 1/2 (0.264 mi.)	X158	396
DEL MONTE PLANT 51 Reg ld: 43-0457	50 BUSH ST	SSW 1/4 - 1/2 (0.285 mi.)	X163	397
MANNING PROPERTY Reg ld: 43-0854	35 RIVER ST N	ESE 1/4 - 1/2 (0.303 mi.)	Z165	403
VITALE AUTO BODY Reg ld: 43-1611	52 AUTUMN	SSE 1/4 - 1/2 (0.334 mi.)	AC175	425
SCVWD PROPERTY	361 SANTA CLARA ST W	ESE 1/4 - 1/2 (0.352 mi.)	182	438

Reg ld: 43-1712 SCV PARAMEDICS SJ AM	58 AUTUMN ST N	SSE 1/4 - 1/2 (0.356 mi.)	AC183	441
Reg Id: 43-0072		, ,		
AUTOMATIC CAR WASH Reg ld: 43-0131	77 S MONTGOMERY ST	S 1/4 - 1/2 (0.362 mi.)	AA186	447
SOUTHERN PACIFIC TRA Reg ld: 43-1364	595 LENZEN	WNW 1/4 - 1/2 (0.363 mi.)	AE189	455
PG&E Reg ld: 43-1059	655 LENZEN AVE	WNW 1/4 - 1/2 (0.369 mi.)	AE193	467
CHEVRON Reg Id: 43-0347	955 THE ALAMEDA	SW 1/4 - 1/2 (0.388 mi.)	AI198	477
DERBY FOOD SERVICE Reg Id: 43-0461	55 SUNOL ST	SW 1/4 - 1/2 (0.388 mi.)	201	479
SAN JOSE ARENA JULIA Reg ld: 43-1174	70 90 MONTGOMERY	SSE 1/4 - 1/2 (0.392 mi.)	AH204	492
STOCKTON AUTOMOTIVE Reg ld: 43-1858	465 STOCKTON AV	WNW 1/4 - 1/2 (0.395 mi.)	AE205	492
COMMON GROUND LANDSC Reg Id: 43-0651	725 LENZEN AV	WNW 1/4 - 1/2 (0.401 mi.)	209	503
BRANDENBURG FAMILY A Reg Id: 2 438194N01	153 JULIAN	NE 1/4 - 1/2 (0.402 mi.)	AJ211	524
U-HAUL MOVING & STOR Reg Id: 43-1103	1027 THE ALAMEDA	WSW 1/4 - 1/2 (0.414 mi.)	AK215	534
VERIZON BUSINESS: SN Reg ld: 43-1570	500 STOCKTON AV	WNW 1/4 - 1/2 (0.427 mi.)	AL218	545
SAN JOSE MERCURY NEW Reg ld: 43-2227	211 SANTA CLARA	E 1/4 - 1/2 (0.436 mi.)	AP223	552
DIOCESE OF SAN JOSE Reg ld: 43-1987	855 LENZEN	W 1/4 - 1/2 (0.451 mi.)	227	564
SAN JOSE FIRE STATIO Reg ld: 43-1671	201 MARKET	ENE 1/4 - 1/2 (0.458 mi.)	AQ228	567
PG & E SUBSTATION A Reg Id: 43-1058	17 OTTERSON	S 1/4 - 1/2 (0.468 mi.)	AN230	569
FALSTAFF BREWERY Reg ld: 43-2167	1330 THE ALAMEDA	WSW 1/4 - 1/2 (0.470 mi.)	231	572
Lower Elevation	Address	Direction / Distance	Map ID	Page
MILLIGAN NEWS Reg ld: 43-0896	150 N AUTUMN ST	E 0 - 1/8 (0.087 mi.)	F28	59
SCR-A C LABEL/BERRYM Reg ld: 2 438235N01	350 MONTGOMERY	NW 0 - 1/8 (0.120 mi.)	G69	141
LINCOLN PROPERTY Reg ld: 43-1705	469 HOWARD	NNW 0 - 1/8 (0.121 mi.)	<i>1</i> 71	154
MANADA TILE Reg Id: 43-0853	517 JOHN ST	SE 0 - 1/8 (0.124 mi.)	H74	159
GRUTHFIELD PROPERTY	370 N MONTGOMERY	NW 1/8 - 1/4 (0.152 mi.)	L81	183

Reg Id: 43-2267				
FMC CORPORATION Reg ld: 2 438311N01	333 JULIAN	NE 1/8 - 1/4 (0.168 mi.)	O93	211
SAN JOSE ARENA HOLEM Reg ld: 43-0704	443 SANTA CLARA ST W	SE 1/4 - 1/2 (0.261 mi.)	T156	391
MILITARY FAMILY HOUS Reg Id: 2738	400 SANTA CLARA	SE 1/4 - 1/2 (0.279 mi.)	Y159	396
SAN JOSE SIDEWALK CI Reg Id: 43-2174	333 SANTA CLARA	ESE 1/4 - 1/2 (0.304 mi.)	Z166	406
1-2-3 POOL SERVICE Reg ld: 43-2013	455 COLEMAN AVE	N 1/4 - 1/2 (0.362 mi.)	AF187	451
MR AIR SWEEPERS Reg ld: 43-1017	483 COLEMAN AVE	NNW 1/4 - 1/2 (0.366 mi.)	AG191	458
WELLS FARGO ALARM SE Reg ld: 43-1628	466 VENDOME ST	N 1/4 - 1/2 (0.399 mi.)	AF206	497
HARDCASTLE AUTOTHON Reg ld: 43-0677	590 COLEMAN AVENUE	NNW 1/4 - 1/2 (0.473 mi.)	232	575

HWP: Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

A review of the HWP list, as provided by EDR, and dated 11/19/2018 has revealed that there are 2 HWP sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
IONIZATION RESEARCH EPA Id: CAL000082530 Cleanup Status: CLOSED	820 PARK AVE	SSW 1/2 - 1 (0.640 mi.)	AS240	600
Lower Elevation	Address	Direction / Distance	Map ID	Page
SAFE-WAY CHEMICAL CO EPA Id: CAD042345884 Cleanup Status: CLOSED	664 STOCKTON AVE	NW 1/2 - 1 (0.639 mi.)	239	599

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 09/19/2018 has revealed that there are 2 Notify 65 sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNKNOWN	35 NORTH RIVER STREE	ESE 1/4 - 1/2 (0.280 mi.) <i>NW 1/2 - 1 (0.830 mi.)</i>	Z160	396
WILLIAMS MANUFACTURI	560-595 EMORY ST		247	667

SAN JOSE HAZMAT: San Jose Hazmat Facilities.

A review of the SAN JOSE HAZMAT list, as provided by EDR, and dated 11/01/2018 has revealed that there are 26 SAN JOSE HAZMAT sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OUT OF BUSINESS (FRA File Num: 405138	240 N MONTGOMERY ST	SSE 0 - 1/8 (0.007 mi.)	A5	17
SAN JOSE ARENA File Num: 405614 File Num: 600352	555 SAINT JOHN	SSW 0 - 1/8 (0.054 mi.)	B16	47
SOUTH BAY DRIVELINE File Num: 401357	573 W JULIAN ST	W 0 - 1/8 (0.083 mi.)	C26	54
C & M DIVERSIFIED CO File Num: 400336	330 N MONTGOMERY ST	NW 0 - 1/8 (0.092 mi.)	G31	63
ANTUZZI, J A CONCRET File Num: 401073	333 N MONTGOMERY ST	WNW 0 - 1/8 (0.093 mi.)	G33	65
EBJ PARTNERS, LP File Num: 401902	341 N MONTGOMERY ST	NW 0 - 1/8 (0.112 mi.)	G56	115
CERULEAN GLOBAL SERV File Num: 408338	250 STOCKTON AV	SW 1/8 - 1/4 (0.140 mi.)	K80	182
SAN JOSE AUTO BODY File Num: 403223	60 STOCKTON AVENUE	SSW 1/8 - 1/4 (0.168 mi.)	M97	220
PG&E CINNABAR SERVIC File Num: 405875 File Num: 600005	308 STOCKTON AVE	WSW 1/8 - 1/4 (0.190 mi.)	P106	283
SAN JOSE AUTO STEAM File Num: 483638	32 STOCKTON AVE	SSW 1/8 - 1/4 (0.198 mi.)	M113	302
WHOLE FOODS MARKET - File Num: 602247	777 THE ALAMEDA	SW 1/8 - 1/4 (0.211 mi.)	Q117	326
AV MACHINE SHOP File Num: 402480	710 W JULIAN ST	WSW 1/8 - 1/4 (0.235 mi.)	P126	338
Lower Elevation	Address	Direction / Distance	Map ID	Page
CAGWIN & DORWARD File Num: 409749	255 N AUTUMN ST	0 - 1/8 (0.000 mi.)	A2	16
O/B (NEXTEL CA-2039 File Num: 409218	505 W JULIAN ST SUIT	N 0 - 1/8 (0.028 mi.)	A8	18
ACME SAW SALES & SER File Num: 405431	475 W JULIAN ST	N 0 - 1/8 (0.067 mi.)	E20	50
DNT AUTOMOTIVE File Num: 404835	338 N MONTGOMERY ST	NW 0 - 1/8 (0.102 mi.)	G39	77
BRENNER'S AUTOMOTIVE File Num: 405315 File Num: 410978	330 N AUTUMN ST	N 0 - 1/8 (0.102 mi.)	140	86
OUT OF BUSINESS File Num: 405315	330 N AUTUMN ST SUIT	N 0 - 1/8 (0.102 mi.)	I41	86
OUT OF BUSINESS	330 AUTUMN ST SUITE	N 0 - 1/8 (0.102 mi.)	143	87

File Num: 410978				
ARCHITECTURAL FACADE File Num: 601660	490 HOWARD STREET	N 0 - 1/8 (0.105 mi.)	144	87
VALAYA AUTO File Num: 410517	447 W ST JOHN ST	ESE 0 - 1/8 (0.113 mi.)	F60	124
AC LABEL CO File Num: 401905	350 NO MONTGOMERY	NW 0 - 1/8 (0.120 mi.)	G70	148
USA TOUCH-UP AUTO BO File Num: 410095	351 N AUTUMN ST	NNW 0 - 1/8 (0.124 mi.)	<i>1</i> 72	157
GRUTHFIELD PROPERTY File Num: 409883	370 N MONTGOMERY	NW 1/8 - 1/4 (0.152 mi.)	L81	183
PUCCIO MACHINE & WEL File Num: 401458	357 N MONTGOMERY ST	NW 1/8 - 1/4 (0.153 mi.)	L82	193
OUT OF BUSINESS (J L File Num: 403147	566 CINNABAR ST	WNW 1/8 - 1/4 (0.204 mi.)	S115	325

CERS: The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

A review of the CERS list, as provided by EDR, and dated 10/22/2018 has revealed that there is 1 CERS site within approximately 0.001 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CAGWIN & DORWARD	255 N AUTUMN ST	0 - 1/8 (0.000 mi.)	A1	8

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 2 EDR MGP sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GARDEN CITY GAS WORK	W. ST JOHN AND MONTG	SSE 0 - 1/8 (0.112 mi.)	J50	102
SAN JOSE GAS WORKS	E. SAN FERNANDO AND	E 1/2 - 1 (0.865 mi.)	AU248	669

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.


A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 8 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DE LONG CAMS FURTADO S AUTOMOTIVE TRAFALGAR SPARES ADVANCE AUTO DETAIL ECONO-LINE	240 N MONTGOMERY ST	SSE 0 - 1/8 (0.007 mi.)	A4	17
	229 N MONTGOMERY ST	S 0 - 1/8 (0.021 mi.)	B7	18
	566 W JULIAN ST	WSW 0 - 1/8 (0.042 mi.)	C10	19
	333 N MONTGOMERY ST	WNW 0 - 1/8 (0.093 mi.)	G32	64
	33 N MONTGOMERY ST	SSE 0 - 1/8 (0.110 mi.)	H49	101
Lower Elevation	Address	Direction / Distance	Map ID	Page
BRUNO S AUTOMOTIVE S	435 W JULIAN ST	NNE 0 - 1/8 (0.091 mi.)	E29	62
LLOYD S AUTO & TRUCK	338 N MONTGOMERY ST	NW 0 - 1/8 (0.102 mi.)	G38	76
VALLEY AUTOMOTIVE SE	125 N AUTUMN ST	ESE 0 - 1/8 (0.113 mi.)	F59	124

Due to poor or inadequate address information, the following sites were not mapped. Count: 2 records.

Site Name	Database(s)
	CDL
SCVTA - RYLAND STREET PROPERTY	LUST

OVERVIEW MAP - 05569778.2R



ADDRESS: 260 N. MONTGOMERY STREET SAN JOSE CA 95110 LAT/LONG:


37.335085 / 121.902651

CLIENT: Engeo Inc. CONTACT: DIVYA BHARGAVA

INQUIRY #: 05569778.2r

DATE: February 22, 2019 11:43 am

DETAIL MAP - 05569778.2R



ADDRESS: 260 N. MONTGOMERY STREET SAN JOSE CA 95110

LAT/LONG: 37.335085 / 121.902651

CLIENT: CONTACT:

INQUIRY #: 05569778.2r

DATE: February 22, 2019 11:44 am

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMEN	TAL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS	1.000 1.000 0.001		0 0 0	0 0 NR	0 0 NR	0 0 NR	NR NR NR	0 0 0
Federal Delisted NPL sit	e list							
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY SEMS	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
Federal CERCLIS NFRA	P site list							
SEMS-ARCHIVE	0.500		1	1	3	NR	NR	5
Federal RCRA CORRAC	TS facilities li	st						
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-COR	RACTS TSD fa	acilities list						
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generator	rs list							
RCRA-LQG RCRA-SQG RCRA-CESQG	0.250 0.250 0.250		0 7 0	1 7 0	NR NR NR	NR NR NR	NR NR NR	1 14 0
Federal institutional con engineering controls reg								
LUCIS US ENG CONTROLS US INST CONTROL	0.500 0.500 0.500		0 0 0	0 0 0	0 0 0	NR NR NR	NR NR NR	0 0 0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equiva	alent NPL							
RESPONSE	1.000		1	0	0	0	NR	1
State- and tribal - equiva	alent CERCLIS	3						
ENVIROSTOR	1.000		1	1	0	13	NR	15
State and tribal landfill a solid waste disposal site								
SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking	storage tank l	ists						
LUST	0.500		12	25	55	NR	NR	92

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST CPS-SLIC HIST LUST	0.500 0.500 0.500		0 4 8	0 7 14	0 15 31	NR NR NR	NR NR NR	0 26 53
State and tribal registered	d storage tar	ık lists						
FEMA UST UST AST INDIAN UST	0.250 0.250 0.250 0.250		0 1 0 0	0 2 3 0	NR NR NR NR	NR NR NR NR	NR NR NR NR	0 3 3 0
State and tribal voluntary	cleanup site	es						
INDIAN VCP VCP	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
State and tribal Brownfield	lds sites							
BROWNFIELDS	0.500		0	1	3	NR	NR	4
ADDITIONAL ENVIRONMENT	TAL RECORDS	<u>3</u>						
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / So Waste Disposal Sites	olid							
WMUDS/SWAT SWRCY HAULERS INDIAN ODI ODI DEBRIS REGION 9 IHS OPEN DUMPS	0.500 0.500 0.001 0.500 0.500 0.500 0.500		0 0 0 0 0 0	0 0 NR 0 0	0 0 NR 0 0	NR NR NR NR NR NR	NR NR NR NR NR NR	0 0 0 0 0 0
Local Lists of Hazardous Contaminated Sites	waste /							
US HIST CDL HIST Cal-Sites SCH CDL CERS HAZ WASTE Toxic Pits US CDL	0.001 1.000 0.250 0.001 0.250 1.000 0.001		0 1 0 0 8 0	NR 0 0 NR 6 0 NR	NR 0 NR NR NR 0 NR	NR 0 NR NR NR NR	NR NR NR NR NR NR	0 1 0 0 14 0
Local Lists of Registered	Storage Tan	ıks						
SWEEPS UST HIST UST CERS TANKS CA FID UST	0.250 0.250 0.250 0.250		4 4 0 0	3 7 2 0	NR NR NR NR	NR NR NR NR	NR NR NR NR	7 11 2 0
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2 DEED	0.001 0.500		0 2	NR 1	NR 3	NR NR	NR NR	0 6
Records of Emergency I	Release Repo	orts						
HMIRS CHMIRS LDS MCS SPILLS 90	0.001 0.001 0.001 0.001 0.001		0 0 0 0	NR NR NR NR NR	NR NR NR NR NR	NR NR NR NR NR	NR NR NR NR NR	0 0 0 0
Other Ascertainable Rec	cords							
RCRA NonGen / NLR FUDS DOD SCRD DRYCLEANERS US FIN ASSUR EPA WATCH LIST 2020 COR ACTION TSCA TRIS SSTS ROD RMP RAATS PRP PADS ICIS FTTS MLTS COAL ASH DOE COAL ASH DOE COAL ASH EPA PCB TRANSFORMER RADINFO HIST FTTS DOT OPS CONSENT INDIAN RESERV FUSRAP UMTRA LEAD SMELTERS	0.250 1.000 1.000 0.500 0.001 0.001 0.001 0.001 1.000 0.001		200000000000000000000000000000000000000	2 0 0 0 RR O RR O R RR O RR RR RR RR O RR NN O RR NN NN NN NN NN NN NN NN NN O NN NN NN O NN NN	NOOORRRR ORRRRRRRR ORRROROOR	NOORRAR NRORRAR NRRRRRRRRRRRRRRRRRRRRRRR	N R R R R R R R R R R R R R R R R R R R	4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
US AIRS US MINES ABANDONED MINES FINDS ECHO DOCKET HWC UXO FUELS PROGRAM	0.001 0.250 0.001 0.001 0.001 0.001 1.000 0.250		0 0 0 1 0 0	NR 0 NR NR NR NR 0	NR NR NR NR NR NR NR	NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR	0 0 0 1 0 0
CA BOND EXP. PLAN Cortese CUPA Listings	1.000 0.500 0.250		0 1 22	0 1 24	0 1 NR	0 NR NR	NR NR NR	0 3 46

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	0.001		0	NR	NR	NR	NR	0
ENF	0.001		Ő	NR	NR	NR	NR	Õ
Financial Assurance	0.001		Ö	NR	NR	NR	NR	Ö
HAZNET	0.001		1	NR	NR	NR	NR	1
ICE	0.001		0	NR	NR	NR	NR	0
HIST CORTESE	0.500		8	13	30	NR	NR	51
HWP	1.000		0	0	0	2	NR	2
HWT	0.250		0	0	NR	NR	NR	0
MINES	0.001		0	NR	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
PEST LIC	0.001		0	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	1	1	NR	2
SAN JOSE HAZMAT	0.250		17	9	NR	NR	NR	26
UIC	0.001		0	NR	NR	NR	NR	0
UIC GEO	0.001		0	NR	NR	NR	NR	0
WASTEWATER PITS WDS	0.500		0 0	0 NR	0 NR	NR NR	NR NR	0 0
MILITARY PRIV SITES	0.001 0.001		0	NR NR	NR	NR	NR	0
PROJECT	0.001		0	NR	NR	NR	NR	0
WDR	0.001		0	NR	NR	NR	NR	0
CIWQS	0.001		0	NR	NR	NR	NR	0
CERS	0.001		1	NR	NR	NR	NR	1
WIP	0.250		0	0	NR	NR	NR	0
NON-CASE INFO	0.001		Ö	NR	NR	NR	NR	Ö
OTHER OIL GAS	0.001		0	NR	NR	NR	NR	0
PROD WATER PONDS	0.001		0	NR	NR	NR	NR	0
SAMPLING POINT	0.001		0	NR	NR	NR	NR	0
WELL STIM PROJ	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICA	AL RECORDS							
EDR Exclusive Records								
EDR MGP	1.000		1	0	0	1	NR	2
EDR Hist Auto	0.125		8	NR	NR	NR	NR	8
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERN	IMENT ARCHI	VES						
Exclusive Recovered Go	vt. Archives	_ _						
			_					_
RGA LUCT	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001		0	NR	NR	NR	NR	0
- Totals		0	116	130	142	17	0	405

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Direction Distance

Elevation Site Database(s) EPA ID Number

A1 CAGWIN & DORWARD CERS HAZ WASTE S113089551

255 N AUTUMN ST HAZNET N/A SAN JOSE, CA 95110 CERS

< 1/8 SAN JOSE, CA 95110 1 ft.

Site 1 of 7 in cluster A

 Relative:
 CERS HAZ WASTE:

 Lower
 Site ID:
 101355

 Actual:
 CERS ID:
 10350571

83 ft. CERS Description: Hazardous Waste Generator

Violations:

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 01/12/2017.

_____ Facility

has not certified their HMBP annually. Submit a complete HMBP to CERS. Ensure all three HMBP sections (Facility Information, Hazardous Materials Inventory, and Emergency Response and Training Plans) are submitted by the end of the same calendar month annually to re-certify

the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes: Returned to compliance on 01/12/2017.

_____ Current

used oil filter pickup receipts were not available for review. Obtain copies of the recent receipts and ensure the last 3 years of receipts

are available for review.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(d)

Violation Description: Failure to dispose of hazardous waste within 180 days (or 270 if waste

is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.

Violation Notes: Returned to compliance on 01/12/2017.

The used

oil and waste antifreeze have been accumulated for over the 180 day allowance. Have the waste picked up immediately and submit a copy of the consolidated manifest (receipt) with the response to this report.

EDR ID Number

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

Ensure hazardous waste is not accumulated longer than the allowable

time.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes: Returned to compliance on 01/12/2017.

___ Recent

consolidated manifests for the waste antifreeze and used oil were not available for review. Obtain copies of any missing consolidated manifests. Ensure the consolidated manifests are maintained and

available for review for at least 3 years.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 02-10-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscape maintenance yard facility. Minor vehicle and equipment

repair done on site. EPA ID# CAL000170571 is active. Currently generating used oil, waste antifreeze and used oil filters. Shop rags to Aramark. Emergency equipment present and maintained. Provided Small Automotive Hazardous Waste flier during the inspection. Corrected

Minor -Posted emergency information: Emergency actions form posted.

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 02-10-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscape storage yard facility. Minor vehicle and equipment

maintenance performed on site. Currently storing used oil (110 gallons), new oil (2x 55 gallons), waste antifreeze (55 gallons), and oxygen (250 cuft). Stores herbicides and various aerosol paints and lubricants in less than HMBP quantities. NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents

retained for 3 years. Contact me for more information. A sample

training log attached with this report.

Eval Division: Santa Clara County Environmental Health Eval Program: HMRRP

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 101355

Distance Elevation Site

on Site Database(s) EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

EDR ID Number

Facility Name: CAGWIN & DORWARD

Env Int Type Code: HWG
Program ID: 10350571
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.335380 Longitude: -121.902300

Affiliation:

Affiliation Type Desc: Environmental Contact Entity Name: DAVID KEENEY
Entity Title: Not reported
Affiliation Address: PO BOX 1600
Affiliation City: NOVATO
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 94948

Affiliation Phone: (415) 726-6100

Document Preparer Affiliation Type Desc: Entity Name: DAVID KEENEY Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address **Entity Title:** Not reported Affiliation Address: P.O. BOX 1600 Affiliation City: **NOVATO** Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: 94948-1600 Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: Cagwin & Dorward **Entity Title:** Not reported Affiliation Address: Not reported Not reported Affiliation City: Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (415) 892-7710

Affiliation Type Desc: Parent Corporation Entity Name: Cagwin & Dorward Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

EDR ID Number

Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner

Entity Name: CAGWIN & DORWARD

Entity Title: Not reported
Affiliation Address: PO BOX 1600
Affiliation City: NOVATO
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94948

Affiliation Phone: (800) 892-7710

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer Entity Name: **David Keeney** Entity Title: Shop Manager Not reported Affiliation Address: Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc:
Entity Name:
Cagwin & Dorward
Entity Title:
Not reported
Affiliation Address:
P.O.BOX 1600
Affiliation City:
NOVATO
Affiliation State:
CA

Affiliation Country: United States
Affiliation Zip: 94948-1600
Affiliation Phone: (415) 892-0939

HAZNET:

envid: \$113089551 Year: 2011

GEPAID: CAL000170571

Contact: DAVID KEENEY/SHOP RESOURCE MGR

Telephone: 4158927710
Mailing Name: Not reported
Mailing Address: PO BOX 1600

Mailing City, St, Zip: NOVATO, CA 949481600

Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported

Waste Category: Unspecified oil-containing waste

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

Direction Distance

Elevation Site Database(s) EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

EDR ID Number

(H010-H129) Or (H131-H135)

Tons: 0.15

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113089551 Year: 2002

GEPAID: CAL000170571

Contact: CAREN SIGNORELLI-ADMIN ASST

Telephone: 4158927710
Mailing Name: Not reported
Mailing Address: PO BOX 1600

Mailing City, St, Zip: NOVATO, CA 949481600

Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: Recycler
Tons: 0.83
Cat Decode: Not reported

Method Decode: Not reported Facility County: Santa Clara

CERS TANKS:

Site ID: 101355 CERS ID: 10350571

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 01/12/2017.

_____ Facility has not certified their HMBP annually. Submit a complete HMBP to CERS.

Ensure all three HMBP sections (Facility Information, Hazardous Materials Inventory, and Emergency Response and Training Plans) are submitted by the end of the same calendar month annually to re-certify

the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes: Returned to compliance on 01/12/2017.

_____ Current

Map ID MAP FINDINGS
Direction

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

used oil filter pickup receipts were not available for review. Obtain copies of the recent receipts and ensure the last 3 years of receipts

are available for review.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(d)

Violation Description: Failure to dispose of hazardous waste within 180 days (or 270 if waste

is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.

Violation Notes: Returned to compliance on 01/12/2017.

The used

oil and waste antifreeze have been accumulated for over the 180 day allowance. Have the waste picked up immediately and submit a copy of the consolidated manifest (receipt) with the response to this report. Ensure hazardous waste is not accumulated longer than the allowable

time.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 101355

Site Name: CAGWIN & DORWARD

Violation Date: 02-10-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes: Returned to compliance on 01/12/2017.

Recent

consolidated manifests for the waste antifreeze and used oil were not available for review. Obtain copies of any missing consolidated manifests. Ensure the consolidated manifests are maintained and

available for review for at least 3 years.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 02-10-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscape maintenance yard facility. Minor vehicle and equipment

repair done on site. EPA ID# CAL000170571 is active. Currently generating used oil, waste antifreeze and used oil filters. Shop rags to Aramark. Emergency equipment present and maintained. Provided Small

Automotive Hazardous Waste flier during the inspection. Corrected Minor -Posted emergency information: Emergency actions form posted.

Eval Division: Santa Clara County Environmental Health

Eval Program: HW

Direction Distance

Elevation Site Database(s) EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

EDR ID Number

Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 02-10-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscape storage yard facility. Minor vehicle and equipment

maintenance performed on site. Currently storing used oil (110 gallons), new oil (2x 55 gallons), waste antifreeze (55 gallons), and oxygen (250 cuft). Stores herbicides and various aerosol paints and lubricants in less than HMBP quantities. NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents

retained for 3 years. Contact me for more information. A sample

training log attached with this report.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 101355

Facility Name: CAGWIN & DORWARD

Env Int Type Code: HWG
Program ID: 10350571
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.335380 Longitude: -121.902300

Affiliation:

Affiliation Type Desc: Environmental Contact
Entity Name: DAVID KEENEY
Entity Title: Not reported
Affiliation Address: PO BOX 1600
Affiliation City: NOVATO
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 94948

Affiliation Phone: (415) 726-6100

Document Preparer Affiliation Type Desc: Entity Name: DAVID KEENEY **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: P.O. BOX 1600
Affiliation City: NOVATO

Affiliation City. NOV.
Affiliation State: CA

Affiliation Country: Not reported

Distance Elevation

ion Site Database(s) EPA ID Number

CAGWIN & DORWARD (Continued)

S113089551

EDR ID Number

Affiliation Zip: 94948-1600
Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: Cagwin & Dorward Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (415) 892-7710

Affiliation Type Desc: Parent Corporation Cagwin & Dorward Entity Name: Entity Title: Not reported Affiliation Address: Not reported Not reported Affiliation City: Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner

Entity Name: CAGWIN & DORWARD

Entity Title: Not reported
Affiliation Address: PO BOX 1600
Affiliation City: NOVATO
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94948

Affiliation Phone: (800) 892-7710

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer Entity Name: David Keeney Entity Title: Shop Manager Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Legal Owner

Cagwin & Dorward

Not reported

P.O.BOX 1600

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CAGWIN & DORWARD (Continued)

S113089551

Affiliation City: **NOVATO** Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 94948-1600 Affiliation Phone: (415) 892-0939

A2 CAGWIN & DORWARD CUPA Listings S106091284 255 N AUTUMN ST

SAN JOSE, CA 95110 < 1/8

SAN JOSE HAZMAT N/A

1 ft.

Site 2 of 7 in cluster A

Relative: CUPA SANTA CLARA:

Lower SANTA CLARA Region: PE#: 2205

Actual: Program Description: GENERATES 100 KG YR TO <5 TONS/YR 83 ft.

> Latitude: 37.335598 Longitude: -121.902247 Record ID: PR0373068 Facility ID: FA0255469

SANTA CLARA Region: PE#: Not reported

HMBP FACILITY, 4-6 CHEMICALS Program Description:

Latitude: 37.335598 Longitude: -121.902247 Record ID: PR0397592 Facility ID: FA0255469

SAN JOSE HAZMAT:

Region: SAN JOSE 409749 File Num:

Auto Wrecking/Misc Simple Facility Class:

CAGWIN & DORWARD FINDS 1023345848 А3 255 N AUTUMN ST N/A

< 1/8 SAN JOSE, CA 95110

1 ft.

Site 3 of 7 in cluster A

FINDS: Relative:

Lower

Registry ID: 110066417979 Actual:

83 ft.

Environmental Interest/Information System

STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

Α4 **DE LONG CAMS EDR Hist Auto** 1009000737 SSE

240 N MONTGOMERY ST N/A

SAN JOSE, CA < 1/8

0.007 mi.

39 ft. Site 4 of 7 in cluster A

Relative: Higher

EDR Hist Auto

Year: Name: Type: Actual:

AUTOMOBILE REPAIRING 1970 DE LONG CAMS 85 ft. DE LONG CAMS **AUTOMOBILE REPAIRING** 1975

> 2001 RUSS JOSEPH PERFORMANCE Automotive Repair Shops, NEC, NEC 2002 **RUSS JOSEPH PERFORMANCE** Automotive Repair Shops, NEC, NEC 2003 Automotive Repair Shops, NEC, NEC **RUSS JOSEPH PERFORMANCE** Automotive Repair Shops, NEC, NEC 2004 RUSS JOSEPH PERFORMANCE 2005 RUSS JOSEPH PERFORMANCE Automotive Repair Shops, NEC, NEC 2005 FRANK JOSEPHS AUTOMOTIVE General Automotive Repair Shops 2006 **RUSS JOSEPH PERFORMANCE** Automotive Repair Shops, NEC, NEC 2006 FRANK JOSEPHS AUTOMOTIVE General Automotive Repair Shops 2007 FRANK JOSEPHS AUTOMOTIVE General Automotive Repair Shops 2007 RUSS JOSEPH PERFORMANCE Automotive Repair Shops, NEC, NEC Automotive Repair Shops, NEC, NEC 2008 RUSS JOSEPH PERFORMANCE 2008 FRANK JOSEPHS AUTOMOTIVE General Automotive Repair Shops 2009 FRANK JOSEPHS AUTOMOTIVE General Automotive Repair Shops 2010 General Automotive Repair Shops JOSEPHS FRANK AUTOMOTIVE 2011 JOSEPHS FRANK AUTOMOTIVE General Automotive Repair Shops 2012 JOSEPHS FRANK AUTOMOTIVE General Automotive Repair Shops General Automotive Repair Shops 2013 JOSEPHS FRANK AUTOMOTIVE

CUPA Listings Α5 **OUT OF BUSINESS (FRANK JOSEPH'S AUTOMOT)** S121473705 SSE 240 N MONTGOMERY ST SAN JOSE HAZMAT N/A

General Automotive Repair Shops

< 1/8 SAN JOSE, CA 95110

2014

0.007 mi.

Site 5 of 7 in cluster A 39 ft. CUPA SANTA CLARA: Relative:

Higher Region: SANTA CLARA

PE#: 2201 Actual:

GENERATES WASTE OIL ONLY Program Description: 85 ft.

JOSEPHS FRANK AUTOMOTIVE

Latitude: 37.334879 -121.902635 Longitude: Record ID: PR0381281 Facility ID: FA0260162

SANTA CLARA Region: PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.334879 Longitude: -121.902635 Record ID: PR0397087 Facility ID: FA0260162

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 405138 Class: Auto Repair

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

A6 **URIBES BODY SHOP CUPA Listings** S121469661 N/A

SE 230 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.020 mi.

104 ft. Site 6 of 7 in cluster A Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

PE#: 2202 Actual:

Program Description: GENERATES < 100 KG/YR 84 ft.

Latitude: 37.334632 Longitude: -121.902357 Record ID: PR0313547 Facility ID: FA0207864

FURTADO S AUTOMOTIVE В7 **EDR Hist Auto** 1009000813 N/A

229 N MONTGOMERY ST South

SAN JOSE, CA < 1/8

0.021 mi.

Site 1 of 5 in cluster B 113 ft.

Relative: Higher

EDR Hist Auto

Year: Name: Type: Actual:

AUTOMOBILE REPAIRING **FURTADO S AUTOMOTIVE** 1966 85 ft.

FURTADO S AUTOMOTIVE AUTOMOBILE REPAIRING 1970 1975 **FURTADO S AUTOMOTIVE AUTOMOBILE REPAIRING FURTADOS AUTOMOTIVE** Automotive Repair Shops, NEC 1977 1978 **FURTADOS AUTOMOTIVE** Automotive Repair Shops, NEC 1979 **FURTADOS AUTOMOTIVE** Automotive Repair Shops, NEC 1980 **FURTADOS AUTOMOTIVE** Automotive Repair Shops, NEC

A8 O/B (NEXTEL CA-2039 HWY 280/87) **SAN JOSE HAZMAT** S115780548

North 505 W JULIAN ST SUITE 2039

SAN JOSE, CA 95110 < 1/8

0.028 mi.

150 ft. Site 7 of 7 in cluster A

Relative: SAN JOSE HAZMAT: Lower Region: SAN JOSE

File Num: 409218 Actual:

83 ft. Class: Misc. Complex firms and labs

> Date of Data: AS OF 02/07/2014 SAN JOSE Region: File Num: 409218

Class: Misc. Complex firms and labs N/A

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

B9 RALPHS MACHINE SHOP INC HIST UST 1000347509
SE 190 N MONTGOMERY ST N/A

SE 190 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.037 mi.

196 ft. Site 2 of 5 in cluster B

Relative: HIST UST:
Higher File Number: 00020778

Actual: URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/00020778.pdf

 85 ft.
 Region:
 STATE

 Facility ID:
 00000049826

 Facility Type:
 Other

Other Type: MACHINE SHOP
Contact Name: RALPH GANNON
Telephone: 4082942902

Owner Name: RALPH'S MACHINES SHOP
Owner Address: 190 N. MONTGOMERY ST.
Owner City,St,Zip: SAN JOSE, CA 95110

Total Tanks: 0001

Tank Num: 001 Container Num: 1 Year Installed: 1968 Tank Capacity: 00000200 Tank Used for: WASTE Type of Fuel: Not reported Container Construction Thickness: Not reported Leak Detection: None

Click here for Geo Tracker PDF:

C10 TRAFALGAR SPARES EDR Hist Auto 1009002297
WSW 566 W JULIAN ST N/A

General Automotive Repair Shops

General Automotive Repair Shops General Automotive Repair Shops

< 1/8 SAN JOSE, CA

0.042 mi.

220 ft. Site 1 of 8 in cluster C

EDR Hist Auto

1989

1990

1991

Relative: Higher

Actual: Year: Name: Type:

TRAFALGAR SPARES

TRAFALGAR SPARES

TRAFALGAR SPARES

1975 **AUTOMOBILE REPAIRING** TRAFALGAR SPARES 86 ft. TRAFALGAR SPARES General Automotive Repair Shops 1976 1977 TRAFALGAR SPARES General Automotive Repair Shops 1978 TRAFALGAR SPARES General Automotive Repair Shops 1979 TRAFALGAR SPARES General Automotive Repair Shops 1980 TRAFALGAR SPARES General Automotive Repair Shops 1982 TRAFALGAR SPARES General Automotive Repair Shops 1983 TRAFALGAR SPARES General Automotive Repair Shops 1985 TRAFALGAR SPARES General Automotive Repair Shops 1986 General Automotive Repair Shops TRAFALGAR SPARES 1987 TRAFALGAR SPARES General Automotive Repair Shops 1988 General Automotive Repair Shops TRAFALGAR SPARES

TC05569778.2r Page 19

Direction Distance

Elevation Site Database(s) EPA ID Number

 C11
 CALIF STEAM CLEANERS
 RCRA-SQG
 1000249804

 West
 560 W JULION ST
 FINDS
 CAD098540123

< 1/8 SAN JOSE, CA 95110

0.048 mi.

256 ft. Site 2 of 8 in cluster C

Relative: RCRA-SQG:

Higher Date form received by agency: 09/01/1996

Actual: Facility name: CALIF STEAM CLEANERS 85 ft. Facility address: 560 W JULION ST

85 ft. Facility address: 560 W JULION ST SAN JOSE, CA 95110

EPA ID: CAD098540123 Mailing address: W JULION ST

SAN JOSE, CA 95110

Contact: Not reported Contact address: Not reported

Not reported

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CITY OF SAN JOSE & ANDERSON

Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No

EDR ID Number

ECHO

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CALIF STEAM CLEANERS (Continued)

1000249804

Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002665866

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000249804 Registry ID: 110002665866

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002665866

D12 PROFESSIONALS BODY SHOP THE S121469366 **CUPA Listings** N/A

ESE 151 N AUTUMN ST < 1/8 SAN JOSE, CA 95110

0.051 mi.

268 ft. Site 1 of 2 in cluster D Relative: CUPA SANTA CLARA:

Lower SANTA CLARA Region:

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 82 ft.

> Latitude: 37.334835 Longitude: -121.901392 Record ID: PR0313097 Facility ID: FA0206335

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

D13 A C E AUTO BODY CUPA Listings S121472563
ESE 151 N AUTUMN ST N/A

< 1/8 SAN JOSE, CA 95110

0.051 mi.

268 ft. Site 2 of 2 in cluster D

Relative: CUPA SANTA CLARA:

Lower Region: SANTA CLARA

Actual: PE#: 2202

82 ft. Program Description: GENERATES < 100 KG/YR

 Latitude:
 37.334835

 Longitude:
 -121.901392

 Record ID:
 PR0371487

 Facility ID:
 FA0254635

B14 SAN JOSE SPORTS ARENA RESPONSE \$105954447

SSW 525 WEST SANTA CLARA STREET

< 1/8 SAN JOSE, CA 95110

0.054 mi.

284 ft. Site 3 of 5 in cluster B

Relative: RESPONSE:

HigherFacility ID:43730007Actual:Site Type:State Response87 ft.Site Type Detail:State Response or NPL

Acres: 22 National Priorities List: NO

Cleanup Oversight Agencies: SMBRP, RWQCB 2 - San Francisco Bay

Lead Agency Description: DTSC - Site Cleanup Program

Project Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley

Site Code: 200154

Site Mgmt. Req.: REM, DAY, HOS, EX, GW, OIL, NOWN, NDAM, NDEV, NSUB, HS, SCH, FOOD,

COV, RES

Assembly: 27
Senate: 15
Special Program Status: Not reported

Status: Certified O&M - Land Use Restrictions Only

Status Date: 06/20/1997 Restricted Use: YES

Funding: Responsible Party Latitude: 37.33417

Latitude: 37.33417 Longitude: -121.9031

APN: 259-28-031, 259-28-041, 259-28-043, 259-28-044, 259-28-060,

 $259\hbox{-}28031,\, 259\hbox{-}37\hbox{-}004,\, 259\hbox{-}37\hbox{-}043,\, 259\hbox{-}37\hbox{-}044,\, 259\hbox{-}37\hbox{-}058,$

 $259\hbox{-}37\hbox{-}059,\, 259\hbox{-}37\hbox{-}060,\, 77\hbox{-}630\hbox{-}032$

Past Use: MANUFACTURED GAS PLANT, VEHICLE MAINTENANCE
Potential COC: Benzene Lead Polynuclear aromatic hydrocarbons (PAHs TPH-diesel

TPH-gas TPH-MOTOR OIL Ethylbenzene Toluene Xylenes

Confirmed COC: Toluene Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas

Ethylbenzene Benzene Lead TPH-MOTOR OIL Xylenes

Potential Description:
Alias Name:
Alias Type:
Alias Name:
Alias Name:
Compaq Stadium
Alias Type:
Alternate Name
Alias Name:
HP Pavillion
Alias Type:
Alternate Name
Alias Type:
Alternate Name

Alias Name: PACIFIC GAS & ELECTRIC, SAN JOSE STADIUM

ENVIROSTOR

HIST Cal-Sites

DEED

N/A

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE SPORTS ARENA (Continued)

S105954447

Alias Type: Alternate Name Alias Name: PG&E - SAN JOSE #1 Alias Type: Alternate Name

Alias Name: PG&E SAN JOSE MUNICIPAL STADIUM

Alias Type: Alternate Name Alias Name: 259-28-031 Alias Type: APN Alias Name: 259-28-041 Alias Type: APN Alias Name: 259-28-043 Alias Type: APN Alias Name: 259-28-044 Alias Type: APN Alias Name: 259-28-060 Alias Type: APN Alias Name: 259-28031 Alias Type: APN Alias Name: 259-37-004 Alias Type: APN Alias Name: 259-37-043 Alias Type: APN Alias Name: 259-37-044 Alias Type: APN 259-37-058 APN 259-37-059 APN 259-37-060

Alias Name: Alias Type: Alias Name: Alias Type: Alias Name: Alias Type: APN Alias Name: 77-630-032 Alias Type: APN

Alias Name: CAD981415904

Alias Type: **EPA Identification Number**

Alias Name: 110033609888 Alias Type: EPA (FRS#) Alias Name: 200154

Project Code (Site Code) Alias Type:

Alias Name: 43730007

Alias Type: **Envirostor ID Number**

Completed Info:

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 05/01/2006 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: 5 Year Review Reports

Completed Date: 05/02/2008

The remedy (cap) continues to be protective of public health, safety Comments:

and the aenvironment. the next 5 year review is due March 2013.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Endangerment Assessment Report

Completed Date: 06/20/1991 Map ID MAP FINDINGS
Direction

Distance Elevation S

on Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Comments: Report of Completion of Interim Remedial Measure/Removal Action

(IRM/RA). Polynuclear aromatic hydrocarbons (PAHs) contaminated soil

(23,000 cubic yards(CY)) resulting from a former PG&E gas manufacturing site was excavated and encapsulated into the nearby parking lots. Gasoline contaminated soil (17,000 CY) was also excavated and stockpiled nearby for vapor extraction treatment. The

excavated area was backfilled with clean fill.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Removal Action Completion Report

Completed Date: 06/28/1991

Comments: Completion of Phase I Construction Documentation Report. Required a

deed restriction to be filed. PNA contaminated soil from a former PG&E site was excavated and encapsulated into a nearby parking lot. Gasoline contaminated soil was also excavated and stockpiled on a nearby lot for vapor extraction treatment. The excavated areas were

backfilled with clean soil. The volume of excavation for PNA

contaminated soil was approximately 23,000 cubic yards. The volume of excavation for gasoline contaminated soil was approximately 17,000 cubic yards. Groundwater treatment was performed under San Francisco RWQCB's requirements. Current files at the RWQCB list the site closed

on 06/20/97.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction

Completed Date: 05/23/2003

Comments: A Deed Restriction limiting future use of property including the

material encapsulation areas which requires no disturbance of the encapsulated areas and the slurry wall. If the areas are disturbed, DTSC is to be notified, a health and safety plan prepared, the material from the encapsulation area will be handled properly, and

repairs to the area will be done as quickly as possible.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 04/27/2007

Comments: No problems noted during inspection.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 05/30/2012

Comments: DTSC conducted its annual site visit to check the condition of the

cap over contaminated soil and to verify compliance with the restrictions and requirements of the Land Use Covenant. During the inspection, numerous cracks were observed in the Hewlett Packard Pavilion parking lot. The cap consists of two feet of fill and clay and is overlaid with asphalt for use as a parking lot. The observed cracks appeared to only be in the asphalt, and the cap appears to remain protective of human health. There was no evidence of any

activities prohibited by the Land Use Covenant.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 05/15/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 07/16/2009

Comments: Upon inspection, soil covered, concrete and asphalt surfaces appeared

to be in good condition. There was no evidence of any activities prohibited by the Deed Restriction. No major cracks were observed on

the concrete surfaces just minor cracks.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 09/30/2010

Comments: The Site is the location of a sports arena, adjacent park, and

parking lot. Upon inspection, soil covered, concrete and asphalt surfaces appeared to be in good condition. There was no evidence of any activities prohibited by the Deed Restriction. No major cracks were observed on the concrete surfaces, just minor cracks.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 06/06/2011 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/23/2014

Comments: A letter reminding the City of San Jose to perform annual inspection

of the san jose sport arena.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 07/15/2015 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Soils Management Plan

Completed Date: 07/21/2006

Comments: Comments on the report were: a soil management plan is required;

asphalt removal, if needed and liquifaction issues for the SE corner will need to be addressed, and any other project ("Ball Park") that might involve a parking structure to be added to the parking lot at

the HP pavilion.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/27/2003

Comments: Site Screening completed which recommended No Further Action. The

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE SPORTS ARENA (Continued)

S105954447

soil remediation was completed in 1992 by a paved parking lot system, slurry wall around the Arena footprint, and soil cap at the Arena Green. The site was approved as closed by RWQCB in 1997. A deed restriction was recorded by DTSC in May 2003.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: 5 Year Review Reports

Completed Date: 08/22/2013 Comments: Not reported

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction Monitoring Report

Completed Date: 08/19/2014 Comments: Not reported

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

5 Year Review Reports Completed Document Type:

Completed Date: 08/17/2018 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: **Technical Report** Completed Date: 12/22/2015 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction Monitoring Report

Completed Date: 06/13/2016 Comments: Not reported

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction Monitoring Report

Completed Date: 06/15/2017

Comments: Joseph Lovewell performed an annual site inspection on behalf of the

City of San Jose on June 5, 2017 and submitted a report to DTSC documenting that there have been changes in land use since the last inspection and the property is in compliance with the restrictions

and requirements of the Land Use Covenant.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Other Report Completed Date: 06/15/2017 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Soils Management Plan

02/26/2018 Completed Date: Comments: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 04/28/2015

Comments: The City of San Jose notified DTSC in an email of its plans to repair

asphalt at the site, which is currently the location of the San Jose Arena (SAP Center). An attachment was included with the email shown

the locations where the asphalt repairs would be done.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 10/02/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 05/24/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/06/2018

Comments: This email is an update from the City of San Jose about a Terradex

alert for an excavation to repair a leak near a fire hydrant.

Excavation is in the street and the activity does not require a Soil

Management Plan.

Not reported Future Area Name: Future Sub Area Name: Not reported Not reported Future Document Type: Future Due Date: Not reported Not reported Schedule Area Name: Not reported Schedule Sub Area Name: Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

ENVIROSTOR:

Facility ID: 43730007

Status: Certified O&M - Land Use Restrictions Only

Status Date: 06/20/1997
Site Code: 200154
Site Type: State Response
Site Type Detailed: State Response or NPL

Acres: 22 NPL: NO

Regulatory Agencies: SMBRP, RWQCB 2 - San Francisco Bay

Lead Agency: SMBRP
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Restricted Use: YES

Site Mgmt Req: REM, DAY, HOS, EX, GW, OIL, NOWN, NDAM, NDEV, NSUB, HS, SCH, FOOD,

COV, RES

Funding: Responsible Party Latitude: 37.33417

Longitude: -121.9031

APN: 259-28-031, 259-28-041, 259-28-043, 259-28-044, 259-28-060,

259-28031, 259-37-004, 259-37-043, 259-37-044, 259-37-058,

259-37-059, 259-37-060, 77-630-032

Past Use: MANUFACTURED GAS PLANT, VEHICLE MAINTENANCE

Potential COC: Benzene Lead Polynuclear aromatic hydrocarbons (PAHs TPH-diesel

TPH-gas TPH-MOTOR OIL Ethylbenzene Toluene Xylenes

Confirmed COC: Toluene Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas

Ethylbenzene Benzene Lead TPH-MOTOR OIL Xylenes

Potential Description: OTH, SOIL

Alias Name: ARENA GREEN
Alias Type: Alternate Name
Alias Name: Compaq Stadium
Alias Type: Alternate Name
Alias Name: HP Pavillion
Alias Type: Alternate Name

Alias Name: PACIFIC GAS & ELECTRIC, SAN JOSE STADIUM

Alias Type: Alternate Name
Alias Name: PG&E - SAN JOSE #1
Alias Type: Alternate Name

Alias Name: PG&E SAN JOSE MUNICIPAL STADIUM

259-37-043

APN

Alias Type: Alternate Name Alias Name: 259-28-031 Alias Type: APN Alias Name: 259-28-041 Alias Type: APN Alias Name: 259-28-043 Alias Type: APN Alias Name: 259-28-044 Alias Type: APN Alias Name: 259-28-060 Alias Type: APN Alias Name: 259-28031 Alias Type: APN 259-37-004 Alias Name: Alias Type: APN

Alias Name: 259-37-044 Alias Type: APN Alias Name: 259-37-058 Alias Type: APN Alias Name: 259-37-059 Alias Type: APN Alias Name: 259-37-060 Alias Type: APN Alias Name: 77-630-032 Alias Type: APN

Alias Name:

Alias Type:

Alias Name: CAD981415904

Alias Type: EPA Identification Number

Alias Name: 110033609888 Alias Type: EPA (FRS #) Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Alias Name: 200154

Alias Type: Project Code (Site Code)

Alias Name: 43730007

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 05/01/2006 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: 5 Year Review Reports

Completed Date: 05/02/2008

Comments: The remedy (cap) continues to be protective of public health, safety

and the aenvironment. the next 5 year review is due March 2013.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Endangerment Assessment Report

Completed Date: 06/20/1991

Comments: Report of Completion of Interim Remedial Measure/Removal Action

(IRM/RA). Polynuclear aromatic hydrocarbons (PAHs) contaminated soil

(23,000 cubic yards(CY)) resulting from a former PG&E gas

manufacturing site was excavated and encapsulated into the nearby parking lots. Gasoline contaminated soil (17,000 CY) was also excavated and stockpiled nearby for vapor extraction treatment. The

excavated area was backfilled with clean fill.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Removal Action Completion Report

Completed Date: 06/28/1991

Comments: Completion of Phase I Construction Documentation Report. Required a

deed restriction to be filed. PNA contaminated soil from a former PG&E site was excavated and encapsulated into a nearby parking lot. Gasoline contaminated soil was also excavated and stockpiled on a nearby lot for vapor extraction treatment. The excavated areas were

backfilled with clean soil. The volume of excavation for PNA

contaminated soil was approximately 23,000 cubic yards. The volume of excavation for gasoline contaminated soil was approximately 17,000 cubic yards. Groundwater treatment was performed under San Francisco RWQCB's requirements. Current files at the RWQCB list the site closed

on 06/20/97.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 05/23/2003

Comments: A Deed Restriction limiting future use of property including the

material encapsulation areas which requires no disturbance of the encapsulated areas and the slurry wall. If the areas are disturbed, DTSC is to be notified, a health and safety plan prepared, the material from the encapsulation area will be handled properly, and

repairs to the area will be done as quickly as possible.

Map ID MAP FINDINGS Direction

Distance Elevation Site

EPA ID Number Database(s)

SAN JOSE SPORTS ARENA (Continued)

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Land Use Restriction - Site Inspection/Visit Completed Document Type:

Completed Date: 04/27/2007

Comments: No problems noted during inspection.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 05/30/2012

DTSC conducted its annual site visit to check the condition of the Comments:

> cap over contaminated soil and to verify compliance with the restrictions and requirements of the Land Use Covenant. During the inspection, numerous cracks were observed in the Hewlett Packard Pavilion parking lot. The cap consists of two feet of fill and clay and is overlaid with asphalt for use as a parking lot. The observed cracks appeared to only be in the asphalt, and the cap appears to remain protective of human health. There was no evidence of any

activities prohibited by the Land Use Covenant.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Land Use Restriction - Site Inspection/Visit Completed Document Type:

Completed Date: 05/15/2008 Comments: Not reported

Completed Area Name: **PROJECT WIDE** Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 07/16/2009

Comments: Upon inspection, soil covered, concrete and asphalt surfaces appeared

to be in good condition. There was no evidence of any activities prohibited by the Deed Restriction. No major cracks were observed on

the concrete surfaces just minor cracks.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 09/30/2010

Comments: The Site is the location of a sports arena, adjacent park, and

> parking lot. Upon inspection, soil covered, concrete and asphalt surfaces appeared to be in good condition. There was no evidence of any activities prohibited by the Deed Restriction. No major cracks were observed on the concrete surfaces, just minor cracks.

Completed Area Name: **PROJECT WIDE** Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 06/06/2011 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Correspondence Completed Date: 07/23/2014

Comments: A letter reminding the City of San Jose to perform annual inspection

of the san jose sport arena.

EDR ID Number

S105954447

Direction Distance Elevation

evation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction - Site Inspection/Visit

Completed Date: 07/15/2015 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Soils Management Plan

Completed Date: 07/21/2006

Comments: Comments on the report were: a soil management plan is required;

asphalt removal, if needed and liquifaction issues for the SE corner will need to be addressed, and any other project ("Ball Park") that might involve a parking structure to be added to the parking lot at

the HP pavilion.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/27/2003

Comments: Site Screening completed which recommended No Further Action. The

soil remediation was completed in 1992 by a paved parking lot system, slurry wall around the Arena footprint, and soil cap at the Arena Green. The site was approved as closed by RWQCB in 1997. A deed

restriction was recorded by DTSC in May 2003.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: 5 Year Review Reports

Completed Date: 08/22/2013 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction Monitoring Report

Completed Date: 08/19/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: 5 Year Review Reports

Completed Date: 08/17/2018 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 12/22/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction Monitoring Report

Completed Date: 06/13/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE

Distance Elevation Site

vation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Completed Sub Area Name: Not reported

Completed Document Type: Land Use Restriction Monitoring Report

Completed Date: 06/15/2017

Comments: Joseph Lovewell performed an annual site inspection on behalf of the

City of San Jose on June 5, 2017 and submitted a report to DTSC documenting that there have been changes in land use since the last inspection and the property is in compliance with the restrictions

and requirements of the Land Use Covenant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/15/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Soils Management Plan

Completed Date: 02/26/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 04/28/2015

Comments: The City of San Jose notified DTSC in an email of its plans to repair

asphalt at the site, which is currently the location of the San Jose Arena (SAP Center). An attachment was included with the email shown

the locations where the asphalt repairs would be done.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 10/02/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Date: 05/24/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/06/2018

Comments: This email is an update from the City of San Jose about a Terradex

alert for an excavation to repair a leak near a fire hydrant. Excavation is in the street and the activity does not require a Soil

Management Plan.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE SPORTS ARENA (Continued)

S105954447

Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

Calsite:

BERKELEY Region: Facility ID: 43730007

Facility Type: RP

Type: **RESPONSIBLE PARTY**

Branch: NC

Branch Name: NORTH COAST File Name: Not reported 06201997 State Senate District:

CERTIFIED OPERATION AND MAINTENANCE, ALL PLANNED ACTIVITIES Status:

> IMPLEMENTED, REMEDIATION CONTINUES **CERTIFIED / OPERATION & MAINTENANCE**

Status Name: Lead Agency: REGIONAL WATER QUALITY CONTROL BOARD

NPL: Not reported

SIC Code: 73

BUSINESS SERVICES SIC Name:

Controlled Access: Cortese: Not reported

Hazardous Ranking Score: Not reported Date Site Hazard Ranked: Not reported Groundwater Contamination: Not reported Staff Member Responsible for Site: **KHILF** Supervisor Responsible for Site: Not reported

Region Water Control Board: SF

Region Water Control Board Name: SAN FRANCISCO BAY

Not reported Lat/Long Direction: Lat/Long (dms): 000/000 Lat/long Method: Not reported Lat/Long Description: Not reported

State Assembly District Code: 23 State Senate District Code: 13 43730007 Facility ID: Activity: RA

Activity Name: REMOVAL ACTION

AWP Code: SOIL Proposed Budget: 0

AWP Completion Date: Not reported Revised Due Date: Not reported Comments Date: 06201991

Est Person-Yrs to complete:

Estimated Size: Not reported Request to Delete Activity: Not reported Activity Status: COM

Definition of Status: CERTIFIED / OPERATION & MAINTENANCE

Liquids Removed (Gals): 30000 Liquids Treated (Gals): 0

Action Included Capping: Not reported Well Decommissioned: Not reported Not reported Action Included Fencing:

Removal Action Certification:

PNA AND GASOLINE CONTAMINATED SOIL EXCAVATED. **Activity Comments:**

For Commercial Reuse: For Industrial Reuse: 0

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

For Residential Reuse: 0 Unknown Type: 0

Facility ID: 43730007 Activity: PEA

Activity Name: PRELIMINARY ENDANGERMENT ASSESSMENT

AWP Code: Not reported

Proposed Budget: 0

AWP Completion Date: Not reported Revised Due Date: Not reported Comments Date: 06201991

Est Person-Yrs to complete: 0

Estimated Size: Not reported Request to Delete Activity: Not reported Activity Status: COM

Definition of Status: CERTIFIED / OPERATION & MAINTENANCE

Liquids Removed (Gals): 0
Liquids Treated (Gals): 0

Action Included Capping: Not reported Well Decommissioned: Not reported Action Included Fencing: Not reported Removal Action Certification: Not reported Activity Comments: Not reported

 For Commercial Reuse:
 0

 For Industrial Reuse:
 0

 For Residential Reuse:
 0

 Unknown Type:
 0

 Facility ID:
 43730007

 Activity:
 DEED

Activity Name: DEED RESTRICTIONS

AWP Code: Not reported

Proposed Budget:

AWP Completion Date: Not reported Revised Due Date: Not reported Comments Date: 05232003

Est Person-Yrs to complete: 0

Estimated Size: Not reported Request to Delete Activity: Not reported Activity Status: COM

Definition of Status: CERTIFIED / OPERATION & MAINTENANCE

Liquids Removed (Gals): 0
Liquids Treated (Gals): 0

Action Included Capping:

Well Decommissioned:

Action Included Fencing:

Removal Action Certification:

Activity Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

 For Commercial Reuse:
 0

 For Industrial Reuse:
 0

 For Residential Reuse:
 0

 Unknown Type:
 0

 Facility ID:
 43730007

 Activity:
 5YEAR

Activity Name: FIVE-YEAR REVIEW REQUIRED BY CERCLA

AWP Code: Not reported

Proposed Budget: 0

AWP Completion Date: 05312008
Revised Due Date: Not reported

Map ID MAP FINDINGS
Direction

Direction Distance Elevation

ce EDR ID Number ion Site Database(s) EPA ID Number

SAN JOSE SPORTS ARENA (Continued)

S105954447

Comments Date: Not reported

Est Person-Yrs to complete:

Estimated Size: Not reported Request to Delete Activity: Not reported Activity Status: COM

Definition of Status: CERTIFIED / OPERATION & MAINTENANCE

Liquids Removed (Gals): 0
Liquids Treated (Gals): 0

Action Included Capping:
Well Decommissioned:
Action Included Fencing:
Removal Action Certification:
Activity Comments:
Not reported
Not reported
Not reported

For Commercial Reuse: 0
For Industrial Reuse: 0
For Residential Reuse: 0
Unknown Type: 0

Alternate Address: W. SANTA CLARA & N. AUTUMN ST

Alternate City, St, Zip: SAN JOSE, CA 95110

Alternate Address: BETWEEN SP RR AND NORTH AUTUMN

Alternate City,St,Zip: SAN JOSE, CA 95110

Alternate Address: NORTH OF WEST SANTA CLARA STREET

Alternate City, St, Zip: SAN JOSE, CA 95110

Alternate Address: WEST, JOHN & MONTGOMERY STREET

Alternate City,St,Zip: Not reported

Alternate Address: 525 WEST SANTA CLARA STREET

Alternate City,St,Zip: SAN JOSE, CA 95110
Background Info: The current address or

The current address on the building is 525 West Santa Clara Street. The site is bounded by Autumn Street to the east; West Santa Clara Street to the south; Julian Street, Montgomery Street, and St. John Street to the north; and the Southern Pacific Railroad tracks to the west. In May 1987, a site screening identified contaminants in the soil as polycyclic aromatic hydrocarbons (PAH's) from a former Pacific Gas & Electric (PG&E) site with concentrations ranging from non-detect to above 3,000 ppm in localized areas. EPA completed screening site inspection in 1989. The City of San Jose Redevelopment Agency (SJRA) acquired 22 parcels in a former industrial area in downtown San Jose that had a former Pacific Gas & Electric (PG&E) coal gasification plant, various automobile repair and service businesses, underground storage tanks, oil/water

clarifers, and drums.

Comments Date: 05041987

Comments: Site Screening Done: Contaminants - PNA's (2-180 ppm),

Comments Date: 05041987

Comments: PB (160-1400 ppm), AS (14-29 ppm), HG (less than 0.10-2.5 ppm)

Comments Date: 05041987

Comments: & CN (less than 1.0 ppm).

Comments Date: 05232003

Comments: A Deed Restriction limiting future use of property including the

Comments Date: 05232003

Comments: material encapsulation areas was filed in May 2003 which

Comments Date: 05232003

Comments: requires no disturbance of the encapsulated areas and the slurry

Comments Date: 05232003

Comments: wall. If the areas are disturbed, DTSC is to be notified, a

Comments Date: 05232003

Direction Distance

Elevation **EPA ID Number** Site Database(s)

SAN JOSE SPORTS ARENA (Continued)

S105954447

EDR ID Number

Comments: health and safety plan prepared, the material from the

Comments Date: 05232003

encapsulation area will be handled properly, and repairs to the Comments:

Comments Date: 05232003

Comments: area will be done as quickly as possible.

Comments Date: 06201991

Comments: PEA COMPLETED: DHS approval of site workplan and Health & Safety

Comments Date: 06201991

Comments: plan. RP excavated PNA and gasoline contaminated soil and

Comments Date: 06201991

backfilled with clean fill. GW treatment will be performed Comments:

06201991 Comments Date:

Comments: later by RP under SF RWQCB's requirement. Groundwater treatment

Comments Date:

Comments: was performed under San Francisco RWQCB's requirements. Current

Comments Date: 06201991

files at the RWQCB list the site closed on 06/20/97. Comments:

Comments Date: 09061989

Comments: Site Screening Done: EPA completed Screening Site Inspection

Comments Date: 09061989

(SSI) and recommends Listing Site Inspection (LSI). Comments:

Comments Date: 12201990

RA Soil: PNA contaminated soil from a former PG&E site was Comments:

Comments Date:

Comments: excavated and encapsulated into a nearby parking lot.

Comments Date: 12201990

Comments: Gasoline contaminated soil was also excavated and stockpiled

Comments Date: 12201990

Comments: on a nearby lot for vapor extraction treatment. The

Comments Date: 12201990

Comments: excavated areas were backfilled with clean soil. The

Comments Date: 12201990

volume of excavation for PNA contaminated soil was Comments:

Comments Date: 12201990

approximately 3,000 cubic yards. The volume of excavation Comments: 12201990 Comments Date:

Comments:

for gasoline contaminated soil was approximately 17,000 Comments Date: 12201990

Comments: cubic yards.

EPA IDENTIFICATION NUMBER ID Name:

ID Value: CAD981415904

SAN JOSE SPORTS ARENA Alternate Name:

Alternate Name: PG&E SAN JOSE MUNICIPAL STADIUM

PACIFIC GAS & ELECTRIC, SAN JOSE STADIUM Alternate Name:

Alternate Name: PG&E - SAN JOSE #1 Alternate Name: ARENA GREEN Not reported Alternate Name: Special Programs Code: Not reported Special Programs Name: Not reported

DEED:

Envirostor ID: 43730007 Area: PROJECT WIDE Sub Area: Not reported Site Type: STATE RESPONSE

Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY

Agency: Not reported

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

SAN JOSE SPORTS ARENA (Continued) S105954447

Covenant Uploaded: Not reported

Deed Date(s): 05/23/2003

File Name: **Envirostor Land Use Restrictions**

SAP CENTER B15 **CERS HAZ WASTE** S113124581

SSW **525 W SANTA CLARA ST CUPA Listings** N/A

SAN JOSE, CA 95113 HAZNET < 1/8 **CERS**

0.054 mi.

Site 4 of 5 in cluster B 284 ft. Relative: CERS HAZ WASTE:

Higher Site ID: 37181 CERS ID: 10353694 Actual:

CERS Description: Hazardous Waste Generator 87 ft.

Violations:

Site ID: 37181 Site Name: SAP Center Violation Date: 08-28-2017

22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter Citation:

12, Section(s) 66262.12

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

hazardous waste.

Violation Notes: Returned to compliance on 09/15/2017. EPA ID # CAL000265504 has been

inactive since 2008. Application to reactivate provided at time of

inspection.

Violation Division: Santa Clara County Environmental Health

HWViolation Program: **CERS** Violation Source:

Site ID: 37181 Site Name: SAP Center 08-28-2017 Violation Date:

HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter Citation:

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Returned to compliance on 09/15/2017. Facility failed to report the

following reportable hazardous materials: 20x10 gal sized propanes for

forklift etc.

Violation Division: Santa Clara County Environmental Health

HMRRP Violation Program: Violation Source: **CERS**

Site ID: 37181 Site Name: SAP Center Violation Date: 08-28-2017

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Returned to compliance on 09/15/2017. Facility does not have

documented training indicating employees receive initial and refresher

training

Map ID MAP FINDINGS
Direction

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

SAP CENTER (Continued) S113124581

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.95 25505.1 - California Health and Safety Code, Chapter 6.95,

Section(s) 25505.1

Violation Description: Failure to notify property owner in writing that the business is

subject to the business plan program and has complied with its

provisions.

Violation Notes: Returned to compliance on 09/15/2017. Facility has not sent a letter

to the property owner.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter

6.95, Section(s) 25508.1(a)-(f)

Violation Description: Failure to electronically update business plan within 30 days of any

one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that

requires modification to any portion of the business plan.

Violation Notes: Returned to compliance on 09/15/2017. Most recent inventory submission

indicated 30 gallons of IWC 270 (hydroxyphosphono-acetic acid) and IWC

275 (Polymeric crystal inhibitors). At time of inspection, observed 2x30 gal of IWC 270 and 2x30 gal IWC 275. Additionally, facility reported 200 gal of diesel (fire pump room) but failed to report the 750 gal of diesel for the generator. Make adjustments in CERS and

resubmit.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: 22 CCR 12 66262.23(a)(4) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.23(a)(4)

Violation Description: Failure to send a legible copy of each hazardous waste manifest to the

Department within 30 days of each shipment of hazardous waste. Returned to compliance on 09/15/2017. Facility is not submitting

generator manifest copies to DTSC.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Violation Notes:

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Map ID MAP FINDINGS
Direction

Distance EDR ID Number
Elevation Site EPA ID Number

SAP CENTER (Continued) S113124581

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: Returned to compliance on 09/15/2017. Facility unable to provide any

disposal receipts except for most recent pickup March of 2016.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Abandonment/Illegal

Disposal/Unauthorized Treatment - General

Violation Notes: Returned to compliance on 09/15/2017. Facility transfer used oil waste

from 525 W santa Clara location to a non contiguous location approximately 1 block north of the generator site. This site is

operated by the generator of the waste.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 08-28-2017 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility generates small amounts of used oil from changing equipment

and vehicles (eg. Ice resurfacer). NOTE: YOU MAY ACCUMULATE HAZARDOUS WASTE INDEFINITELY UNTIL YOU REACH 100KG (220lbs/~27 gal). ONCE 100KGS IS ACCUMULATED, YOU MUST SHIP THE WASTE OFF-SITE WITHIN 180 DAYS. The

following minor violation was corrected at time of inspection: 1x55 gal drum of used oil - unmarked. Marked. Emergency Aisle space -

obstructed. Obstacles removed. NOTE 1: Some pharmaceuticals and sharps observed in a sharps container in the medical services area. If

disposing of a pharmaceutical that meets federal (RCRA) hazardous waste criteria, collect and manage as a hazardous waste. The County may assist identifying RCRA regulated pharmaceuticals if a list of all pharmaceuticals used to treat event attendees/general public is provided. NOTE 2: When shipping used oil, generators are eligible to use the consolidated manifest in lieu of the Uniform Hazardous Waste

Manifest. NOTE [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 08-28-2017 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility submitted on CERS on 4-13-2017. Facility (SAP Center) is

operated by San Jose Arena Management and owned by the city of San Jose. Reportable hazardous materials observed on-site include but are not limited to: Diesel Fuel Refrigerants Carbon Dioxide Ethylene

Direction Distance

Elevation Site Database(s) EPA ID Number

SAP CENTER (Continued) S113124581

Glycol Oxygen Propane Water Treatment Chemicals

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 37181
Facility Name: SAP Center
Env Int Type Code: HWG
Program ID: 10353694
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.332790 Longitude: -121.902140

Affiliation:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 525 W SANTA CLARA ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95113-1507
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Legal Owner

SAN JOSE ARENA

Not reported

Affiliation Address: 525 W SANTA CLARA ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95113-1507
Affiliation Phone: (408) 999-6850

Affiliation Type Desc: Operator Entity Name: Eric Gold Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 999-5848 **EDR ID Number**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAP CENTER (Continued) S113124581

Affiliation Type Desc: Parent Corporation SAP Center at San Jose **Entity Name:**

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Entity Name: Eric Gold Entity Title: Not reported

Affiliation Address: 525 W Santa Clara St

Affiliation City: San Jose Affiliation State: CA Affiliation Country: Not reported 95113-1507 Affiliation Zip: Affiliation Phone: (408) 999-5848

CUPA SANTA CLARA:

Region: SANTA CLARA Not reported PE#:

HMBP FACILITY, 1-3 CHEMICALS Program Description:

37.3328654 Latitude: Lonaitude: -121.9010368 Record ID: PR0426153 Facility ID: FA0284132

SANTA CLARA Region:

PE#:

Program Description: GENERATES WASTE OIL ONLY

Latitude: 37.332131 Longitude: -121.900472 Record ID: PR0403825 Facility ID: FA0700794

SANTA CLARA Region: Not reported PE#:

Program Description: HMBP FACILITY, 10-15 CHEMICALS

Latitude: 37.332131 Longitude: -121.900472 Record ID: PR0397468 Facility ID: FA0700794

HAZNET:

envid: S113124581 2016 Year: GEPAID: CAL000265504

Contact: MARK MULLINS/CHIEF ENGINEER

Telephone: 4089996853 Mailing Name: Not reported

525 W SANTA CLARA ST Mailing Address: Mailing City, St, Zip: SAN JOSE, CA 951130000

Gen County: Santa Clara

Direction Distance

Elevation Site Database(s) EPA ID Number

SAP CENTER (Continued) S113124581

TSD EPA ID: CAD059494310
TSD County: Santa Clara

Waste Category: Unspecified oil-containing waste

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.3

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113124581 Year: 2007

GEPAID: CAL000265504

Contact: MARK MULLINS/CHIEF ENGINEER

Telephone: 4089996853 Mailing Name: Not reported

Mailing Address: 525 W SANTA CLARA ST Mailing City,St,Zip: SAN JOSE, CA 951130000

Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported

Waste Category: Unspecified oil-containing waste

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.12

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113124581 Year: 2006

GEPAID: CAL000265504

Contact: MELANIE MATHIS/ADMIN ASSIST ENG DEP

Telephone: 4089996847 Mailing Name: Not reported

Mailing Address: 525 W SANTA CLARA ST Mailing City,St,Zip: SAN JOSE, CA 95113

Gen County: Not reported TSD EPA ID: CAD028409019 TSD County: Not reported

Waste Category: Off-specification, aged or surplus organics

Disposal Method: Transfer Station

Tons: 2

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113124581 Year: 2003

GEPAID: CAL000265504

Contact: MELANIE MATHIS/ADMIN ASSIST ENG DEP

Telephone: 4089996847 Mailing Name: Not reported

Mailing Address: 525 W SANTA CLARA ST Mailing City,St,Zip: SAN JOSE, CA 95113

Gen County: Not reported TSD EPA ID: CAD059494310

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

SAP CENTER (Continued) S113124581

TSD County: Not reported

Waste Category: Liquids with cadmium >= 100 Mg./L

Disposal Method: Treatment, Tank

Tons: 4.34

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113124581 Year: 2003

GEPAID: CAL000265504

Contact: MELANIE MATHIS/ADMIN ASSIST ENG DEP

Telephone: 4089996847 Mailing Name: Not reported

Mailing Address: 525 W SANTA CLARA ST Mailing City,St,Zip: SAN JOSE, CA 95113

Gen County: Not reported
TSD EPA ID: UTD981552177
TSD County: Not reported

Waste Category: Liquids with cadmium >= 100 Mg./L

Disposal Method: Treatment, Incineration

Tons: 0.91

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

<u>Click this hyperlink</u> while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

CERS TANKS:

Site ID: 37181 CERS ID: 10353694

CERS Description: Chemical Storage Facilities

Violations:

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

hazardous waste.

Violation Notes: Returned to compliance on 09/15/2017. EPA ID # CAL000265504 has been

inactive since 2008. Application to reactivate provided at time of

inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

EDR ID Number

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

SAP CENTER (Continued) S113124581

at or above reportable quantities.

Violation Notes: Returned to compliance on 09/15/2017. Facility failed to report the

following reportable hazardous materials: 20x10 gal sized propanes for

forklift etc.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Returned to compliance on 09/15/2017. Facility does not have

documented training indicating employees receive initial and refresher

training

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.95 25505.1 - California Health and Safety Code, Chapter 6.95,

Section(s) 25505.1

Violation Description: Failure to notify property owner in writing that the business is

subject to the business plan program and has complied with its

provisions.

Violation Notes: Returned to compliance on 09/15/2017. Facility has not sent a letter

to the property owner.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter

6.95, Section(s) 25508.1(a)-(f)

Violation Description: Failure to electronically update business plan within 30 days of any

one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that

requires modification to any portion of the business plan.

Violation Notes: Returned to compliance on 09/15/2017. Most recent inventory submission

indicated 30 gallons of IWC 270 (hydroxyphosphono-acetic acid) and IWC 275 (Polymeric crystal inhibitors). At time of inspection, observed

2x30 gal of IWC 270 and 2x30 gal IWC 275. Additionally, facility reported 200 gal of diesel (fire pump room) but failed to report the 750 gal of diesel for the generator. Make adjustments in CERS and

resubmit.

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

SAP CENTER (Continued) S113124581

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: 22 CCR 12 66262.23(a)(4) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.23(a)(4)

Violation Description: Failure to send a legible copy of each hazardous waste manifest to the

Department within 30 days of each shipment of hazardous waste.

Violation Notes: Returned to compliance on 09/15/2017. Facility is not submitting

generator manifest copies to DTSC.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: Returned to compliance on 09/15/2017. Facility unable to provide any

disposal receipts except for most recent pickup March of 2016.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

 Site ID:
 37181

 Site Name:
 SAP Center

 Violation Date:
 08-28-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Abandonment/Illegal

Disposal/Unauthorized Treatment - General

Violation Notes: Returned to compliance on 09/15/2017. Facility transfer used oil waste

from 525 W santa Clara location to a non contiguous location approximately 1 block north of the generator site. This site is

operated by the generator of the waste.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 08-28-2017 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility generates small amounts of used oil from changing equipment

and vehicles (eg. Ice resurfacer). NOTE: YOU MAY ACCUMULATE HAZARDOUS WASTE INDEFINITELY UNTIL YOU REACH 100KG (220lbs/~27 gal). ONCE 100KGS IS ACCUMULATED, YOU MUST SHIP THE WASTE OFF-SITE WITHIN 180 DAYS. The

following minor violation was corrected at time of inspection: 1x55 gal drum of used oil - unmarked. Marked. Emergency Aisle space -

obstructed. Obstacles removed. NOTE 1: Some pharmaceuticals and sharps

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

SAP CENTER (Continued) S113124581

observed in a sharps container in the medical services area. If disposing of a pharmaceutical that meets federal (RCRA) hazardous waste criteria, collect and manage as a hazardous waste. The County may assist identifying RCRA regulated pharmaceuticals if a list of all pharmaceuticals used to treat event attendees/general public is provided. NOTE 2: When shipping used oil, generators are eligible to use the consolidated manifest in lieu of the Uniform Hazardous Waste

Manifest. NOTE [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 08-28-2017 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility submitted on CERS on 4-13-2017. Facility (SAP Center) is

operated by San Jose Arena Management and owned by the city of San Jose. Reportable hazardous materials observed on-site include but are not limited to: Diesel Fuel Refrigerants Carbon Dioxide Ethylene

Glycol Oxygen Propane Water Treatment Chemicals

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 37181
Facility Name: SAP Center
Env Int Type Code: HWG
Program ID: 10353694
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.332790 Longitude: -121.902140

Affiliation:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 525 W SANTA CLARA ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95113-1507 Affiliation Phone: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAP CENTER (Continued) S113124581

Affiliation Type Desc: Legal Owner SAN JOSE ARENA **Entity Name:** Entity Title: Not reported

Affiliation Address: 525 W SANTA CLARA ST

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 95113-1507 Affiliation Phone: (408) 999-6850

Affiliation Type Desc: Operator Eric Gold Entity Name: Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 999-5848

Affiliation Type Desc: Parent Corporation Entity Name: SAP Center at San Jose

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Entity Name: Eric Gold Entity Title: Not reported

Affiliation Address: 525 W Santa Clara St

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95113-1507 (408) 999-5848 Affiliation Phone:

SAN JOSE ARENA S101303999 LUST

ssw **555 SAINT JOHN** < 1/8 SAN JOSE, CA 95110

0.054 mi.

B16

284 ft. Site 5 of 5 in cluster B

LUST REG 2: Relative: Higher Region:

Facility Id: 43-2271 Actual:

Facility Status: Preliminary site assessment workplan submitted 87 ft.

2

Case Number: 07S1E07K04 How Discovered: Tank Closure UNK Leak Cause: Leak Source: UNK Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: 10/17/1998

N/A

HIST CORTESE

SAN JOSE HAZMAT

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA (Continued) S101303999

Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-2271

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 405614

Misc. Complex firms and labs Class:

Region: SAN JOSE File Num: 600352

Auto Wrecking/Misc Simple Facility Class:

PLATFORM 16 CPS-SLIC S123102639 E17 440 W JULIAN ST NNE **CERS** N/A

< 1/8 SAN JOSE, CA 95110

0.062 mi.

326 ft. Site 1 of 6 in cluster E

CPS-SLIC: Relative: Lower STATE Region: **Facility Status:** Open - Active Actual: Status Date: 10/09/2018 83 ft.

> T10000012200 Global Id:

SANTA CLARA COUNTY LOP Lead Agency:

Lead Agency Case Number: 2018-28s Latitude: 37.33639 Longitude: -121.90166

Case Type: Cleanup Program Site

Case Worker: GOR

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database Potential Media Affected: Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern: Not reported

Historically the site was used for industrial purposes (fruit Site History:

cannery). Because redevelopment construction will include soil excavation to depths of 38 to 48 feet over much of the project, the RP seeks SCCDEH review and approval of a Site Management and

Contingency Plan.

Click here to access the California GeoTracker records for this facility:

CERS TANKS:

444114 Site ID: CERS ID: T10000012200 CERS Description: Cleanup Program Site

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

PLATFORM 16 (Continued) S123102639

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: Gerald O'Regan - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 BERGER DRIVE STE 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

C18 SAN JOSE ARENA (JULIAN ST.) LUST S105512905

West 565 W JULIAN HIST LUST N/A

< 1/8 SAN JOSE, CA

0.062 mi.

329 ft. Site 3 of 8 in cluster C

Relative: LUST SANTA CLARA:

 Higher
 Region:
 SANTA CLARA

 Actual:
 SCVWD ID:
 07S1E07K05F

 86 ft.
 Date Closed:
 04/09/1997

 EDR Link ID:
 07S1E07K05F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07K05 Oversite Agency: SFRWQCB

Date Listed: 1997-12-02 00:00:00 Closed Date: 1997-04-09 00:00:00

C19 SAN JOSE ARENA JULIAN PARCEL LUST S103473041
West 565 JULIAN HIST CORTESE N/A

< 1/8 SAN JOSE, CA 95110

0.062 mi.

329 ft. Site 4 of 8 in cluster C

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

86 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501163

Global Id: T0608501163
Latitude: 37.34619
Longitude: -121.881931

Status: Completed - Case Closed

Status Date: 04/10/1997
Case Worker: Not reported
RB Case Number: 43-1174
Local Agency: Not reported
File Location: Not reported
Local Case Number: Not reported
Potential Media Affect: Not reported
Potential Contaminants of Concern: Diesel

Site History: Not reported

CERS

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA JULIAN PARCEL (Continued)

S103473041

LUST:

T0608501163 Global Id: **ENFORCEMENT** Action Type: Date: 01/17/1997

Action: Staff Letter - #43-1174

T0608501163 Global Id: Action Type: Other Date: 09/14/1989 Action: Leak Reported

Global Id: T0608501163 Action Type: Other 09/14/1989 Date: Action: Leak Discovery

Global Id: T0608501163 Action Type: Other 09/14/1989 Date: Action: Leak Stopped

LUST:

Global Id: T0608501163

Completed - Case Closed Status:

Status Date: 04/10/1997

Global Id: T0608501163

Status: Open - Case Begin Date

09/14/1989 Status Date:

HIST CORTESE:

CORTESE Region: Facility County Code: 43 LTNKA Reg By: 43-2213 Reg Id:

CERS TANKS:

211479 Site ID: T0608501163 CERS ID:

CERS Description: Leaking Underground Storage Tank Cleanup Site

E20 **ACME SAW SALES & SERVICE** CERS HAZ WASTE \$103661326

North **475 W JULIAN ST** < 1/8 SAN JOSE, CA 95110

CUPA Listings SAN JOSE HAZMAT

0.067 mi.

353 ft. Site 2 of 6 in cluster E

Relative: CERS HAZ WASTE:

2920 Lower Site ID: CERS ID: 10353250 Actual:

CERS Description: Hazardous Waste Generator 83 ft.

Coordinates:

Site ID: 2920

Facility Name: ACME SAW SALES & SERVICE N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

ACME SAW SALES & SERVICE (Continued)

S103661326

EDR ID Number

Env Int Type Code: HWG
Program ID: 10353250
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336580 Longitude: -121.902430

Affiliation:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country:

Affiliation Zip:

Affiliation Zip:

Affiliation Phone:

Not reported
95112-2716
(408) 918-3400

Affiliation Type Desc: Parent Corporation

Entity Name: ACME SAW SALES & SERVICE

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 475 W JULIAN ST
Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Legal Owner

OLIVET, DOM

Not reported

475 W JULIAN ST

Affiliation City: SAN JOSE

Affiliation State: CA
Affiliation Country: United States

Affiliation Country: United State Affiliation Zip: 95110

Affiliation Phone: (408) 293-1969

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2240

Program Description: GENERATES < 10 GAL/YR

 Latitude:
 37.336387

 Longitude:
 -121.902384

 Record ID:
 PR0380176

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ACME SAW SALES & SERVICE (Continued)

S103661326

1001195465 CAR000020446

FINDS

ECHO

Facility ID: FA0259474

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 405431

Auto Wrecking/Misc Simple Facility Class:

RCRA-SQG

E21 **ACME SAW SALES AND SERVICE** North **475 W JULIAN ST**

SAN JOSE, CA 95110 < 1/8

0.067 mi.

353 ft. Site 3 of 6 in cluster E

Relative: RCRA-SQG:

Date form received by agency: 06/13/1997 Lower

Facility name: ACME SAW SALES AND SERVICE Actual:

Facility address: 475 W JULIAN ST 83 ft.

SAN JOSE, CA 95110

EPA ID: CAR000020446

Mailing address: W JULIAN ST

SAN JOSE, CA 95110

KEN OLIVET Contact: Contact address: 475 W JULIAN ST

SAN JOSE, CA 95110

Contact country: US

Contact telephone: 408-293-1969 Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

KEN AND DOM OLIVET Owner/operator name: Owner/operator address: 475 W JULIAN ST

SAN JOSE, CA 95110

Owner/operator country: Not reported Owner/operator telephone: 408-293-1969 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: Nο

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ACME SAW SALES AND SERVICE (Continued)

1001195465

On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002917826

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001195465 Registry ID: 110002917826

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002917826

E22 **R & L BROSAMER INC CUPA Listings** S121472762 N/A

406 W JULIAN NNE **SAN JOSE, CA 95110** < 1/8

0.070 mi.

367 ft. Site 4 of 6 in cluster E

83 ft.

CUPA SANTA CLARA: Relative: Lower Region: SANTA CLARA

Facility ID:

PE#: 2201 Actual:

Program Description: GENERATES WASTE OIL ONLY Latitude: 37.336558 Longitude: -121.901676 Record ID: PR0373601

FA0255824

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

C23 **SOUTHBAY DRIVELINE CUPA Listings** S121473175 West N/A

573 W JULIAN ST

SAN JOSE, CA 95110 < 1/8 0.083 mi.

438 ft. Site 5 of 8 in cluster C Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 86 ft.

Latitude: 37.335158 Longitude: -121.904122 Record ID: PR0377596 Facility ID: FA0257979

SILICON VALLEY IRON WORK INC C24 **CUPA Listings** S121474654

West **573 W JULIAN ST** < 1/8 **SAN JOSE, CA 95110**

0.083 mi.

Site 6 of 8 in cluster C 438 ft. CUPA SANTA CLARA: Relative:

Higher SANTA CLARA Region: PE#: Not reported Actual:

Program Description: HMBP FACILITY, 1-3 CHEMICALS 86 ft.

37.335108 Latitude: Longitude: -121.903957 PR0409708 Record ID: Facility ID: FA0271356

C25 **ROCK STAR TRUX CUPA Listings** S121472683

West **573 W JULIAN ST** SAN JOSE, CA 95110 < 1/8

0.083 mi.

438 ft.

438 ft. Site 7 of 8 in cluster C

Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

PE#: 2201 Actual:

Program Description: GENERATES WASTE OIL ONLY 86 ft.

37.335158 Latitude: Longitude: -121.904122 Record ID: PR0372717 Facility ID: FA0255251

C26 **SOUTH BAY DRIVELINE INC** RCRA-SQG 1001815636 West **573 W JULIAN ST FINDS** CAR000058321

SAN JOSE, CA 95110 ECHO < 1/8 0.083 mi. **HAZNET** Site 8 of 8 in cluster C **SAN JOSE HAZMAT**

Relative: RCRA-SQG:

Higher Date form received by agency: 10/25/1999

Facility name: SOUTH BAY DRIVELINE INC Actual:

Facility address: 573 W JULIAN ST 86 ft.

SAN JOSE, CA 95110

EPA ID: CAR000058321 **CERS**

N/A

N/A

Direction Distance Elevation

ance EDR ID Number ation Site Database(s) EPA ID Number

SOUTH BAY DRIVELINE INC (Continued)

1001815636

Contact: STEVE JOHNSON
Contact address: 573 W JULIAN ST

SAN JOSE, CA 95110

Contact country: US

Contact telephone: 408-995-6000 Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: SOUTH BAY DRIVELINE INC

Owner/operator address: 573 W JULIAN ST

SAN JOSE, CA 95110

Owner/operator country: Not reported Owner/operator telephone: 408-995-6000 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: Nο Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Waste code: D039

. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110002930669

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

Direction Distance

Elevation Site Database(s) **EPA ID Number**

SOUTH BAY DRIVELINE INC (Continued)

1001815636

EDR ID Number

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001815636 Registry ID: 110002930669

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002930669

HAZNET:

1001815636 envid: Year: 2003

GEPAID: CAR000058321

SOUTH BAY DRIVELINE INC Contact:

Telephone:

Mailing Name: Not reported Mailing Address: 573 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Not reported TSD EPA ID: CA0000084517 TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: **Transfer Station**

0.25 Tons:

Not reported Cat Decode: Method Decode: Not reported Facility County: Santa Clara

1001815636 envid: Year: 2002

GEPAID: CAR000058321

Contact: SOUTH BAY DRIVELINE INC

Telephone:

Not reported Mailing Name: Mailing Address: 573 W JULIAN ST

SAN JOSE, CA 951100000 Mailing City, St, Zip:

Gen County: Not reported TSD EPA ID: CA0000084517 TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: **Transfer Station**

Tons: 1.04 Cat Decode:

Not reported Not reported Method Decode: Santa Clara Facility County:

1001815636 envid: Year: 2001

GEPAID: CAR000058321

SOUTH BAY DRIVELINE INC Contact:

Telephone:

Direction Distance

Elevation Site Database(s) EPA ID Number

SOUTH BAY DRIVELINE INC (Continued)

1001815636

EDR ID Number

Mailing Name: Not reported
Mailing Address: 573 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: Transfer Station

Tons: 0.25

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1001815636 Year: 2001

GEPAID: CAR000058321

Contact: SOUTH BAY DRIVELINE INC

Telephone: --

Mailing Name: Not reported
Mailing Address: 573 W JULIAN ST

Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: Transfer Station

Tons: 1.04

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1001815636 Year: 2000

GEPAID: CAR000058321

Contact: SOUTH BAY DRIVELINE INC

Telephone: --

Mailing Name: Not reported
Mailing Address: 573 W JULIAN ST

Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: Treatment, Tank

Tons: 0.75

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

<u>Click this hyperlink</u> while viewing on your computer to access 2 additional CA_HAZNET: record(s) in the EDR Site Report.

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 401357

Class: Auto Wrecking/Misc Simple Facility

Direction Distance

Elevation Site Database(s) EPA ID Number

E27 FERRERAS AUTOMOTIVE RCRA-SQG 1000857860
NNE 445 W JULIAN ST FINDS CAD983673104

< 1/8 SAN JOSE, CA 95110

0.085 mi.

449 ft. Site 5 of 6 in cluster E

Relative: RCRA-SQG:

Lower Date form received by agency: 08/06/1993

Actual: Facility name: FERRERAS AUTOMOTIVE

83 ft. Facility address: 445 W JULIAN ST SAN JOSE, CA 95110

EPA ID: CAD983673104

Mailing address: W JULIAN ST

SAN JOSE, CA 95110
Contact: MICHAEL BRENNER
Contact address: 445 W JULIAN ST

SAN JOSE, CA 95110

Contact country: US

Contact telephone: 408-297-1627 Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: JOHN FERRERA
Owner/operator address: 445 W JULIAN ST

SAN JOSE, CA 95110

Not reported Owner/operator country: Owner/operator telephone: 408-297-1627 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No **EDR ID Number**

ECHO

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FERRERAS AUTOMOTIVE (Continued)

1000857860

S101309114

Violation Status: No violations found

FINDS:

Registry ID: 110002902761

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

1000857860 Envid: Registry ID: 110002902761

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002902761

F28 **MILLIGAN NEWS** LUST

East 150 N AUTUMN ST **HIST LUST** N/A < 1/8 SAN JOSE, CA 95110 **SWEEPS UST**

0.087 mi.

HIST CORTESE 459 ft. Site 1 of 3 in cluster F **CERS**

LUST: Relative:

Lower Lead Agency: SANTA CLARA COUNTY LOP

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500904 79 ft.

Global Id: T0608500904 Latitude: 37.3346272215183 -121.900820732117 Longitude: Status: Completed - Case Closed

01/24/1997 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500904

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608500904

Direction Distance

Elevation Site Database(s) EPA ID Number

MILLIGAN NEWS (Continued)

S101309114

EDR ID Number

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP

Address: SANTA CLARA COUNTY LOF

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500904

 Action Type:
 Other

 Date:
 10/28/1988

 Action:
 Leak Reported

 Global Id:
 T0608500904

 Action Type:
 ENFORCEMENT

 Date:
 10/04/1989

Action: Notice of Responsibility - #39945

 Global Id:
 T0608500904

 Action Type:
 ENFORCEMENT

 Date:
 01/24/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608500904

 Action Type:
 RESPONSE

 Date:
 01/24/1997

Action: Other Report / Document

LUST:

Global Id: T0608500904

Status: Completed - Case Closed

Status Date: 01/24/1997

Global Id: T0608500904

Status: Open - Case Begin Date

Status Date: 10/28/1988

Global Id: T0608500904

Status: Open - Site Assessment

Status Date: 05/04/1989

LUST REG 2:

Region: 2

Facility Id: Not reported
Facility Status: Case Closed
Case Number: 07S1E07K03f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 5/4/1989
Pollution Characterization Began: 5/4/1989

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MILLIGAN NEWS (Continued)

S101309114

Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E07K03F Date Closed: 01/24/1997 EDR Link ID: 07S1E07K03F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07K03 Oversite Agency: SCVWD

1989-01-01 00:00:00 Date Listed: 1997-01-24 00:00:00 Closed Date:

SWEEPS UST:

Status: Not reported 401454 Comp Number: Number: Not reported Board Of Equalization: Not reported Not reported Referral Date: Action Date: Not reported Not reported Created Date: Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-401454-000001

Not reported Tank Status: 10000 Capacity: Active Date: Not reported M.V. FUEL Tank Use: STG: **PRODUCT REG UNLEADED** Content:

Number Of Tanks:

Status: Not reported Comp Number: 401454 Not reported Number: Board Of Equalization: Not reported Referral Date: Not reported Action Date: Not reported Created Date: Not reported Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-401454-000002

Tank Status: Not reported 10000 Capacity: Not reported Active Date: M.V. FUEL Tank Use: STG: **PRODUCT** Content: **LEADED** Number Of Tanks: Not reported

HIST CORTESE:

Region: CORTESE

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

MILLIGAN NEWS (Continued)

S101309114

Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0896

CERS TANKS:

 Site ID:
 227862

 CERS ID:
 T0608500904

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA
Affiliation Country: Not reporte

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

E29 BRUNO S AUTOMOTIVE SERVICE EDR Hist Auto 1009000391

NNE 435 W JULIAN ST < 1/8 SAN JOSE, CA

0.091 mi.

478 ft. Site 6 of 6 in cluster E

Relative: EDR Hist Auto

Lower

Actual: Year: Name: Type:

83 ft. 1966 BRUNO S AUTOMOTIVE SERVICE AUTOMOBILE REPAIRING
1970 BRUNO S AUTOMOTIVE SERVICE AUTOMOBILE REPAIRING
1971 YOUNG WILLIAM H General Automotive Repair Shops
1972 YOUNG WILLIAM H General Automotive Repair Shops

1973 YOUNG WILLIAM H General Automotive Repair Shops 1974 YOUNGS AUTOMOTIVE General Automotive Repair Shops 1975 YOUNG S AUTOMOTIVE SERVICE **AUTOMOBILE REPAIRING** 1975 YOUNGS AUTOMOTIVE General Automotive Repair Shops 1976 YOUNGS BILL AUTO SERVICE General Automotive Repair Shops 1977 YOUNGS BILL AUTO SERVICE General Automotive Repair Shops

1978YOUNGS BILL AUTO SERVICEGeneral Automotive Repair Shops1978BALLAS REPAIRSAuto And Home Supply Stores1979BALLAS REPAIRSGeneral Automotive Repair Shops1979YOUNGS BILL AUTO SERVICEGeneral Automotive Repair Shops

1979 YOUNGS BILL AUTO SERVICE General Automotive Repair Snops
1980 YOUNGS BILL AUTO SERVICE General Automotive Repair Shops
1980 BALLAS REPAIRS General Automotive Repair Shops
1980 BALLAS REPAIRS General Automotive Repair Shops

1982 YOUNGS BILL AUTO SERVICE General Automotive Repair Shops
 1982 BALLAS REPAIRS General Automotive Repair Shops

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

BRUNO S AUTOMOTIVE SERVICE (Continued)

1009000391

EDR ID Number

1983 **BALLAS REPAIRS** General Automotive Repair Shops 1983 YOUNGS BILL AUTO SERVICE General Automotive Repair Shops 1985 **BALLAS REPAIRS** General Automotive Repair Shops 1985 ALL AMERICAN TOWING SV CTR General Automotive Repair Shops 1986 **BALLAS REPAIRS** General Automotive Repair Shops General Automotive Repair Shops 1987 **BALLAS REPAIRS**

G30 C & M DIVERSIFIED CUPA Listings S121474715

N/A

S102416180

N/A

SWEEPS UST

SAN JOSE HAZMAT

NW 330 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.092 mi.

486 ft. Site 1 of 20 in cluster G

Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

Actual: PE#: 2240

84 ft. Program Description: GENERATES < 10 GAL/YR

 Latitude:
 37.335947

 Longitude:
 -121.903929

 Record ID:
 PR0410635

 Facility ID:
 FA0271695

G31 C & M DIVERSIFIED CO
NW 330 N MONTGOMERY ST 1
< 1/8 SAN JOSE, CA 95110

0.092 mi.

486 ft. Site 2 of 20 in cluster G

Relative: SWEEPS UST: Higher Status:

Higher Status: Not reported

Actual: Comp Number: 400336

84 ft. Number: Not reported

Board Of Equalization: Not reported

Referral Date: Not reported

Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-400336-000001

Tank Status: Not reported Capacity: Not reported Active Date: Not reported Tank Use: CHEMICAL STG: PRODUCT Content: Not reported

Number Of Tanks: 1

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 400336

Class: Auto Wrecking/Misc Simple Facility

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

G32 **ADVANCE AUTO DETAIL EDR Hist Auto** 1009000809 WNW 333 N MONTGOMERY ST N/A

< 1/8 SAN JOSE, CA

0.093 mi.

492 ft. Site 3 of 20 in cluster G

Relative: Higher

EDR Hist Auto

Actual: 84 ft.

Year: Name: Type: 1966 **FAY S SPEEDOMETER SERVICE** AUTOMOBILE REPAIRING **AUTOMOBILE REPAIRING** 1966 **FOLLOSCO S RAY TRANSMISSIONS** 1966 PAUL S AUTO ELECTRIC **AUTOMOBILE REPAIRING** 1969 PAULS AUTO ELECTRIC Automotive Repair Shops, NEC Automotive Repair Shops, NEC 1969 FOLLOSCO RAY AUTMTC TRANSM SV **AUTOMOBILE REPAIRING** 1970 PAUL S AUTO ELECTRIC **FOLLOSCO S RAY TRANSMISSIONS AUTOMOBILE REPAIRING** 1970 1971 PAULS AUTO ELECTRIC Automotive Repair Shops, NEC 1971 FOLLOSCO RAY AUTMTC TRANSM SV Automotive Repair Shops, NEC 1971 Automotive Repair Shops, NEC JIMS AUTO TRIM 1972 FOLLOSCO RAY AUTMTC TRANSM SV Automotive Repair Shops, NEC 1972 JIMS AUTO TRIM Automotive Repair Shops, NEC 1972 PAULS AUTO ELECTRIC Automotive Repair Shops, NEC 1973 FOLLOSCO RAY AUTMTC TRANSM SV Automotive Repair Shops, NEC 1973 PAULS AUTO ELECTRIC Automotive Repair Shops, NEC Automotive Repair Shops, NEC 1973 JIMS AUTO TRIM 1974 A & B AUTO CLEAN Gasoline Service Stations 1974 FOLLOSCO RAY AUTMTC TRANSM SV Automotive Repair Shops, NEC 1974 PAULS AUTO ELECTRIC Automotive Repair Shops, NEC 1974 JIMS AUTO TRIM Automotive Repair Shops, NEC 1975 **FOLLOSCO S RAY TRANSMISSIONS AUTOMOBILE REPAIRING** 1975 ADVANCE AUTO DETAIL **AUTOMOBILE REPAIRING** PAUL S AUTO ELECTRIC **AUTOMOBILE REPAIRING** 1975 1975 FOLLOSIOS AUTOMATIC TRANSM SV Automotive Repair Shops, NEC 1975 FOLLOSCO RAY AUTMTC TRANSM SV Automotive Repair Shops, NEC PAULS AUTO ELECTRIC Automotive Repair Shops, NEC 1975 1976 PAULS AUTO ELECTRIC Automotive Repair Shops, NEC 1976 JIMS AUTO TRIM Automotive Repair Shops, NEC FOLLOSCOS AUTOMATIC TRANSM SV Automotive Repair Shops, NEC 1976 1977 FOLLOSCOS AUTMTC TRNSMSN SRVC Automotive Repair Shops, NEC 1978 FOLLOSCOS AUTMTC TRNSMSN SRVC Automotive Repair Shops, NEC 1979 FOLLOSCOS AUTMTC TMN SVC Automotive Repair Shops, NEC 1989 **R&M BODY & REPAIR** General Automotive Repair Shops 1989 PEREZ AUTO SERVICE General Automotive Repair Shops 1990 PEREZ AUTO SERVICE General Automotive Repair Shops 1991 **R&M BODY & REPAIR** General Automotive Repair Shops 1991 Automotive Transmission Repair Shops J S TRANNY WORK J S TRANNY WORK Automotive Transmission Repair Shops 1992 1992 **R&M BODY & REPAIR** General Automotive Repair Shops SANCHEZ AUTO REPAIR & TRA General Automotive Repair Shops 1992 1993 SANCHEZ AUTO REPAIR & TRA General Automotive Repair Shops 1993 R&M BODY & REPAIR General Automotive Repair Shops 1993 J S TRANNY WORK Automotive Transmission Repair Shops 1994 SANCHEZ AUTO REPAIR & TRA General Automotive Repair Shops 1994 J S TRANNY WORK Automotive Transmission Repair Shops 1995 SANCHEZ AUTO REPAIR & TRA General Automotive Repair Shops 1996 SANCHEZ AUTO REPAIR & TRA General Automotive Repair Shops

Direction Distance

Distance EDR ID Number
Database(s) EPA ID Number

G33 ANTUZZI, J A CONCRETE CO, SAN JOSE HAZMAT S109429349

N/A

N/A

WNW 333 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.093 mi.

492 ft. Site 4 of 20 in cluster G Relative: SAN JOSE HAZMAT:

HigherRegion:SAN JOSEActual:File Num:401073

84 ft. Class: Auto Wrecking/Misc Simple Facility

G34 ANTUZZI CONCRETE CO CUPA Listings S121472687

WNW 333 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.093 mi.

492 ft. Site 5 of 20 in cluster G Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

Actual: PE#: 2201

84 ft. Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.335848

 Longitude:
 -121.904052

 Record ID:
 PR0372851

 Facility ID:
 FA0255338

 H35
 S J FOUNDRY
 SWEEPS UST
 \$102416684

 SE
 525 W ST JOHN ST
 N/A

SE 525 W ST JOHN ST < 1/8 SAN JOSE, CA

0.097 mi.

511 ft. Site 1 of 14 in cluster H

Relative: SWEEPS UST:

HigherStatus:Not reportedActual:Comp Number:40015585 ft.Number:Not reportedBoard Of Equalization:Not reported

Referral Date:
Action Date:
Created Date:
Owner Tank Id:
Not reported
Not reported
Not reported
Not reported
Not reported

SWRCB Tank Id: 43-060-400155-000001

Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: UNKNOWN
STG: PRODUCT
Content: Not reported

Number Of Tanks: 1

Direction Distance

Elevation Site Database(s) EPA ID Number

 H36
 SAN JOSE FOUNDRY
 LUST
 \$103880999

 SE
 525 W SAINT JOHN ST
 HIST LUST
 N/A

SE 525 W SAINT JOHN ST < 1/8 SAN JOSE, CA 95110

0.097 mi.

511 ft. Site 2 of 14 in cluster H

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

85 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501177

 Global Id:
 T0608501177

 Latitude:
 37.3339447725193

 Longitude:
 -121.901314258575

 Status:
 Completed - Case Closed

 Status Date:
 07/21/2015

 Case Worker:
 GOR

 RB Case Number:
 10-079

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E07Q01f

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline

Site History:

The site is located in a commercial and industrial area of San Jose on the northern corner of North Montgomery and West Saint John Streets. The property (APN 259-29-001), presently vacant, was occupied by the San Jose Foundry until 2008. A combined warehouse and office building is located along the eastern, southern, and western property boundaries. The central and northern areas of the site are paved. Prior to this phase of work, a network of three groundwater monitoring wells were installed at the site (Figure 3, Table 1). The San Jose Arena is located south and west of the site, and commercial parcels are located north and east of the site. The confluence of the Guadalupe River and the Los Gatos Creek is approximately 750 feet east of the site. Evidence of gasoline leakage into soils at the site was discovered when an underground gasoline storage tank (UST) was excavated in March 1987. The former UST location is illustrated in Figure 3. Analytical results for soil samples collected during a 1987 phase of investigation indicated that soils in the immediate vicinity of the former UST contained up to 2,200 parts per million (ppm) of total petroleum hydrocarbons as gasoline (TPHg). Four exploratory soil borings, SB-1 through SB-4 were drilled in the vicinity of the former UST in 1987 (Figure 3). The results for the analysis of two soil samples from Boring SB-4 located approximately 24 feet east of the tank excavation area ranged from 50 to 110 ppm of TPHq (Table 2). Two groundwater monitoring Wells, LF-1 and LF-2 were installed at the site in 1991. A third groundwater monitoring well, LF-3, was installed in 1992. A soil sample collected at a depth of 14 feet from the boring for well LF-1 contained 3,500 ppm of TPHg. Concentrations of gasoline compounds in groundwater samples collected from Well LF-1 have remained at levels above regulatory concern since the well was installed in 1991. Groundwater testing data collected from Wells LF-2 and LF-3 have not indicated any significant gasoline-impact above laboratory reporting levels for TPHg, BTEX, and MTBE during the six sampling events for these wells. The historic groundwater flow direction has been toward the northeast. Cores recovered during previous drilling operations revealed that the upper 10 to 13 feet of sediments beneath the site are composed generally of silty and clayey sediments. Thin sandy units interbedded with silts and clavs have been logged in sediments beneath 13 feet bgs to the total depths

EDR ID Number

HAZNET

CERS

Direction Distance Elevation

vation Site Database(s) EPA ID Number

SAN JOSE FOUNDRY (Continued)

S103880999

EDR ID Number

explored (28 feet bgs). Soil samples collected from the boring from well LF-1, drilled near the former UST, indicate that the vertical extent of the petroleum hydrocarbon release attenuates with depth. In various phases WELLTEST has advanced a total of 11 direct-push exploratory borings and collected continuous soil-core and grab-groundwater samples from these borings. Groundwater was firstencountered approximately 16 feet bgs in the borings. Based upon the historical groundwater monitoring data and the results of the grab groundwater samples collected, the plume appears to be migrating toward the northeast. The lateral extent of the plume has been defined to the north, east and west, and has been define to moderate concentrations to the south.

LUST:

Global Id: T0608501177

Contact Type: Local Agency Caseworker

Contact Name: Gerald O'Regan

Organization Name: SANTA CLARA COUNTY LOP Address: SANTA CLARA COUNTY LOP 1555 BERGER DRIVE STE 300

City: SAN JOSE

Email: gerald.o'regan@deh.sccgov.org

Phone Number: Not reported

Global Id: T0608501177

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

LUST:

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 07/31/2013

Action: Monitoring Report - Semi-Annually

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 01/31/2013

Action: CAP/RAP - Other Report

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 01/31/2013

Action: Monitoring Report - Semi-Annually - Regulator Responded

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 07/12/2013

Action: Soil and Water Investigation Workplan - Regulator Responded

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 07/12/2012

Action: Request for Closure - Regulator Responded

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE FOUNDRY (Continued)

S103880999

Global Id: T0608501177 **ENFORCEMENT** Action Type: Date: 09/21/2015

Action: Closure/No Further Action Letter

Global Id: T0608501177 **RESPONSE** Action Type: Date: 06/13/2014

Action: Site Assessment Report - Regulator Responded

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 04/11/2008 Action: Staff Letter

Global Id: T0608501177 **ENFORCEMENT** Action Type: Date: 04/10/2009 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 05/15/2012

Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0608501177 Action Type: Other Date: 03/16/1987 Action: Leak Reported

Global Id: T0608501177 Action Type: **RESPONSE** Date: 01/31/2014

Action: Monitoring Report - Semi-Annually

Global Id: T0608501177 Action Type: **RESPONSE** Date: 03/04/2013 Action: Request for Closure

T0608501177 Global Id: Action Type: **RESPONSE** Date: 01/17/2014

Action: Site Assessment Report

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 08/11/2009 Action: Staff Letter

T0608501177 Global Id: Action Type: **RESPONSE** Date: 06/02/2008

Action: Soil and Water Investigation Workplan

Global Id: T0608501177 Action Type: **RESPONSE**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE FOUNDRY (Continued)

S103880999

Date: 07/31/1999

Monitoring Report - Quarterly Action:

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 10/14/2014

Notification - Public Notice of Case Closure Action:

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 03/10/2011

Action: Site Visit / Inspection / Sampling

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 06/23/2011 Action: Staff Letter

Global Id: T0608501177 **ENFORCEMENT** Action Type: Date: 12/20/2011 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 01/08/2013 Action: Staff Letter

T0608501177 Global Id: Action Type: **ENFORCEMENT** Date: 09/09/2013 Action: Staff Letter

Global Id: T0608501177 **ENFORCEMENT** Action Type: Date: 05/18/2012 Action: Staff Letter

T0608501177 Global Id: Action Type: **ENFORCEMENT** Date: 05/07/2013 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 10/10/2012 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** 06/18/2013 Date: Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 06/12/2012 Action: Staff Letter

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE FOUNDRY (Continued)

S103880999

Global Id: T0608501177 RESPONSE Action Type: Date: 07/31/2010

Action: Monitoring Report - Semi-Annually

Global Id: T0608501177 **RESPONSE** Action Type: Date: 07/21/2015

Action: Well Destruction Report

Global Id: T0608501177 Action Type: **ENFORCEMENT** 05/03/2013 Date: Action: Staff Letter

Global Id: T0608501177 **ENFORCEMENT** Action Type: Date: 09/18/2015

Action: Closure/No Further Action Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 03/20/2014 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 03/21/2014 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 09/26/2014

Action: State Water Board Closure Order

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 10/14/2014

Notification - Public Notice of Case Closure Action:

T0608501177 Global Id: Action Type: **ENFORCEMENT** Date: 06/06/2014 Action: Staff Letter

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 09/26/2014

Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

T0608501177 Global Id: Action Type: **RESPONSE** Date: 01/31/2010

Action: Monitoring Report - Semi-Annually

Global Id: T0608501177 Action Type: **RESPONSE**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE FOUNDRY (Continued)

S103880999

Date: 07/15/2009

Action: Site Assessment Report

Global Id: T0608501177 Action Type: **RESPONSE** 08/22/2014 Date:

Action: Other Report / Document

Global Id: T0608501177 Action Type: Other Date: 03/09/1987 Leak Discovery Action:

Global Id: T0608501177 Action Type: **RESPONSE** Date: 03/20/2014

Action: Other Report / Document

Global Id: T0608501177 **RESPONSE** Action Type: Date: 03/27/2009 Action: Proposed Plan

Global Id: T0608501177 Action Type: **RESPONSE** 05/11/2009 Date:

Action: Clean Up Fund - 5-Year Review Summary

T0608501177 Global Id: Action Type: **RESPONSE** 06/22/2011 Date:

Action: Remedial Progress Report

Global Id: T0608501177 RESPONSE Action Type: 03/16/1987 Date:

Action: Unauthorized Release Form

Global Id: T0608501177 RESPONSE Action Type: Date: 11/12/2004

Action: **Verbal Communication**

Global Id: T0608501177 Action Type: **RESPONSE** Date: 08/12/2015

Action: **Email Correspondence**

Global Id: T0608501177 Action Type: **RESPONSE** Date: 07/11/2012

Action: Other Report / Document

Global Id: T0608501177 Action Type: **ENFORCEMENT** Date: 12/04/1990

Action: Notice of Violation - #39955

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE FOUNDRY (Continued)

S103880999

EDR ID Number

 Global Id:
 T0608501177

 Action Type:
 ENFORCEMENT

 Date:
 05/09/1999

 Action:
 Staff Letter - #26845

Global Id: T0608501177
Action Type: ENFORCEMENT
Date: 01/21/2015

Action: State Water Board Closure Order

 Global Id:
 T0608501177

 Action Type:
 ENFORCEMENT

 Date:
 01/28/2015

 Action:
 Staff Letter

 Global Id:
 T0608501177

 Action Type:
 ENFORCEMENT

 Date:
 02/20/2014

Action: Email Correspondence

 Global Id:
 T0608501177

 Action Type:
 ENFORCEMENT

 Date:
 04/11/2014

 Action:
 Staff Letter

Global Id: T0608501177
Action Type: RESPONSE
Date: 01/31/2011

Action: Monitoring Report - Semi-Annually

Global Id: T0608501177
Action Type: RESPONSE
Date: 07/31/2011

Action: Monitoring Report - Semi-Annually

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 01/31/2012

Action: Monitoring Report - Semi-Annually

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 05/21/2011

Action: Well Installation Report

Global Id: T0608501177
Action Type: RESPONSE
Date: 01/17/1992

Action: Soil and Water Investigation Workplan

Global Id: T0608501177
Action Type: RESPONSE
Date: 03/05/1987

Action: Other Report / Document

Global Id: T0608501177
Action Type: RESPONSE

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE FOUNDRY (Continued)

S103880999

Date: 08/08/1994 Proposed Plan Action:

Global Id: T0608501177 Action Type: **RESPONSE** 05/10/2004 Date: Action: Other Workplan

Global Id: T0608501177 Action Type: Other Date: 03/18/1987 Action: Leak Stopped

T0608501177 Global Id: Action Type: **RESPONSE** Date: 01/29/2014

Action: Monitoring Report - Quarterly

Global Id: T0608501177 RESPONSE Action Type: Date: 03/22/1991 Action: Other Workplan

Global Id: T0608501177 **RESPONSE** Action Type: Date: 12/30/1993 Action: Other Workplan

T0608501177 Global Id: Action Type: **RESPONSE** 09/29/2000 Date:

Action: Soil Vapor Intrusion Investigation Workplan

Global Id: T0608501177 **RESPONSE** Action Type: 07/10/2013 Date: Action: Other Workplan

Global Id: T0608501177 **RESPONSE** Action Type: Date: 05/20/2002

Action: Other Report / Document

Global Id: T0608501177 Action Type: **RESPONSE** Date: 03/20/2014 Action: Correspondence

Global Id: T0608501177 Action Type: **RESPONSE** Date: 12/27/2013

Action: Soil and Water Investigation Report

Global Id: T0608501177 Action Type: RESPONSE Date: 06/12/2012 Action: Correspondence

Direction Distance Flevation

Elevation Site Database(s) EPA ID Number

SAN JOSE FOUNDRY (Continued)

S103880999

EDR ID Number

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 06/29/2012

Action: Other Report / Document

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 05/20/2002

Action: Other Report / Document

 Global Id:
 T0608501177

 Action Type:
 RESPONSE

 Date:
 03/20/2005

 Action:
 Other Workplan

Global Id: T0608501177
Action Type: RESPONSE
Date: 05/23/2011

Action: Clean Up Fund - 5-Year Review Summary - Regulator Responded

LUST:

Global Id: T0608501177

Status: Completed - Case Closed

Status Date: 07/21/2015

Global Id: T0608501177

Status: Open - Case Begin Date

Status Date: 03/05/1987

Global Id: T0608501177

Status: Open - Site Assessment

Status Date: 03/05/1987

LUST REG 2:

Region: 2

Facility Id: Not reported

Facility Status: Pollution Characterization

Case Number: 07S1E07Q01f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E07Q01F Date Closed: Not reported EDR Link ID: 07S1E07Q01F

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE FOUNDRY (Continued)

S103880999

EDR ID Number

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07Q01 Oversite Agency: SCCDEH

Date Listed: 1988-01-01 00:00:00
Closed Date: Not reported

HAZNET:

envid: \$103880999 Year: 2016

GEPAID: CAC002860636
Contact: MIKE MCGEE
Telephone: 2096783165
Mailing Name: Not reported
Mailing Address: PO BOX 3700
Mailing City,St,Zip: Gen County: Santa Clara

TSD EPA ID: CAD008252405 TSD County: Los Angeles

Waste Category: Unspecified organic liquid mixture

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

Tons: 0.153

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

CERS TANKS:

Site ID: 189502 CERS ID: T0608501177

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: Gerald O'Regan - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 BERGER DRIVE STE 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

H37 SAN JOSE FOUNDRY UST U004271405 SE **525 W. SAINT JOHN STREET** N/A

Claim No. 1674

< 1/8 **SAN JOSE, CA 95113**

0.097 mi.

511 ft. Site 3 of 14 in cluster H

Relative: UST CLOSURE: Higher Claim Number:

Type: Closure Denials and Approved Orders

Actual: Deadline Date: 2014-12-24 00:00:00 85 ft.

> Documents: Notice, Draft Order, Review Summary

Comments: Not reported Comments URL: Not reported Response: Not reported Response URL: Not reported Comments2: Not reported Comments2 URL: Not reported Response2: Not reported Response2 URL: Not reported

Closure: WQO 2015-0001-UST (01/25/2015)

Closure URL: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents

/8999758660/wqo_2015_0001_ust.pdf

Uniform Closure Letter (09/12/2017) Uniform:

Uniform URL: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents

/7125655233/1674 Uniform Closure Letter %28T.S.%29.pdf

G38 LLOYD S AUTO & TRUCK SERVICE **EDR Hist Auto** 1009003523

NW 338 N MONTGOMERY ST < 1/8 SAN JOSE, CA

0.102 mi.

Site 6 of 20 in cluster G 536 ft.

Relative: **EDR Hist Auto**

Lower

Year: Name: Type: Actual:

1969 **ESLINGER LLOYD** General Automotive Repair Shops 83 ft. 1970 LLOYD S AUTO & TRUCK SERVICE AUTOMOBILE REPAIRING

1970 **ESLINGER LLOYD** General Automotive Repair Shops 1971 **ESLINGER LLOYD** General Automotive Repair Shops

1987 MERCEDES AUTO BODY Not reported 1988 MERCEDES AUTO BODY Not reported

1989 ARENA BODY SHOP General Automotive Repair Shops 1991 ARENA BODY SHOP General Automotive Repair Shops 1992 ARENA BODY SHOP General Automotive Repair Shops 1992 **DNT AUTOMOTIVE** General Automotive Repair Shops ARENA BODY SHOP 1993 General Automotive Repair Shops 1993 **DNT AUTOMOTIVE** General Automotive Repair Shops

1994 **DNT AUTOMOTIVE** General Automotive Repair Shops 1994 ARENA BODY SHOP General Automotive Repair Shops 1995 **GONZALES EDGAR** General Automotive Repair Shops 1995 ARENA BODY SHOP General Automotive Repair Shops 1996 **GONZALES EDGAR** General Automotive Repair Shops 1997 **GONZALES EDGAR** General Automotive Repair Shops 1998 **GONZALES EDGAR** General Automotive Repair Shops 1999 **GONZALES EDGAR** General Automotive Repair Shops 2000 **GONZALES EDGAR** General Automotive Repair Shops

2001 **GONZALES EDGAR** General Automotive Repair Shops 2002 **GONZALES EDGAR** General Automotive Repair Shops 2003 **GONZALES EDGAR** General Automotive Repair Shops 2004 **GONZALES EDGAR** General Automotive Repair Shops

N/A

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

LLOYD S AUTO & TRUCK SERVICE (Continued)

1009003523

SAN JOSE HAZMAT

CERS

2005 **GONZALES EDGAR** General Automotive Repair Shops 2006 **GONZALES EDGAR** General Automotive Repair Shops 2007 **GONZALES EDGAR** General Automotive Repair Shops General Automotive Repair Shops 2008 **GONZALES EDGAR** 2009 **GONZALES EDGAR** General Automotive Repair Shops 2010 **GONZALES EDGAR** General Automotive Repair Shops 2011 **GONZALES EDGAR** General Automotive Repair Shops 2012 **GONZALES EDGAR** General Automotive Repair Shops 2013 **GONZALES EDGAR** General Automotive Repair Shops 2014 **GONZALES EDGAR** General Automotive Repair Shops

G39 DNT AUTOMOTIVE CERS HAZ WASTE S112345675
NW 338 N MONTGOMERY ST B CUPA Listings N/A

< 1/8 SAN JOSE, CA 95110 0.102 mi.

536 ft. Site 7 of 20 in cluster G

Relative: CERS HAZ WASTE:

 Lower
 Site ID:
 23629

 Actual:
 CERS ID:
 10351960

83 ft. CERS Description: Hazardous Waste Generator

Violations:

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Notes: The used oil filter container did not have the correct accumulation

start date marked. Ensure the container is marked with the date the

first filter is added.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and

portable tanks with the following requirements: "Hazardous Waste",

name and address of the generator, physical and chemical

characteristics of the Hazardous Waste, and starting accumulation

date.

Violation Notes: The used oil drums did not have the proper marking. Ensure all

hazardous waste containers have the proper marking as detailed below.

Provided hazardous waste labels with one filled out as an example.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter

6.95, Section(s) 25508.1(a)-(f)

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

DNT AUTOMOTIVE (Continued)

S112345675

Violation Description: Failure to electronically update business plan within 30 days of any

one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that

requires modification to any portion of the business plan.

Violation Notes: The chemical inventory submitted 9/9/2016 lists oxygen, but the oxygen

cylinder is no longer stored at the facility. Update the inventory in FrontCounter (http://FrontCounter.sccgov.org). Contact me for assistance accessing or modifying your information on FrontCounter.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter

1, Section(s) 265.173

Violation Description: Failure to meet the following container management requirements: (a) A

container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to

leak.

Violation Notes: 1 of the 3 used oil drums was not closed. Keep container closed when

not adding or removing waste.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5,

Section(s) 25250.22

Violation Description: Failure to properly manage used oil and/or fuel filters in accordance

with the requirements.

Violation Notes: Drained used oil filters accumulated for longer than one year. Ensure

used oil filters are not accumulated for more than one year.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: HSC 6.5 25123.3(h)(1)(c) - California Health and Safety Code, Chapter

6.5, Section(s) 25123.3(h)(1)(c)

Violation Description: Failure to send hazardous waste offsite for treatment, storage, or

disposal of acute/extremely hazardous waste after the first 1-kilogram

threshold amount was accumulated within a 90 day period.

Violation Notes: Facility accumulated hazardous waste for longer than 180 days once

they passed the 100 kg mark. Ensure that once 100 kg of hazardous $\,$

waste is accumulated, the waste is picked up within 180 days.

Violation Division: Santa Clara County Environmental Health

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DNT AUTOMOTIVE (Continued)

S112345675

Violation Program: HW **CERS** Violation Source:

Evaluation:

Eval Division:

Compliance Evaluation Inspection Eval General Type:

12-01-2016 Eval Date:

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Automotive repair facility. Currently generating ~13 gallons of used

> oil a month and drained used oil filters. Emergency equipment available and emergency information posted in the office. Due to the volume of waste being generated you may take advantage of the County's Business Small Generator program. Go to HHW.org and scroll down for information on the Business Small Generator program. Corrected Minor:

G002: Inactive EPA ID Number- Completed and submitted a DTSC Form 1358

during the inspection. eMail: dntracer@yahoo.com

Santa Clara County Environmental Health

Eval Program: HW Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 12-01-2016 Violations Found:

Eval Type: Routine done by local agency

Eval Notes: Automotive repair facility. Submittal to FrontCounter on 9/9/2016 is

> accurate as observed except as noted above. Currently storing used oil (3x 55 gallons) in HMBP quantities. New oil, various automotive fluids and aerosol cans stored in less than HMBP quantities. Emergency equipment available. NOTE: If you decide to reduce your used oil storage to less than 55 gallons total, please contact me for a follow up inspection to verify their removal and close out of the HMBP

permit.

Eval Division: Santa Clara County Environmental Health

HMRRP Eval Program: Eval Source: **CERS**

Coordinates:

Site ID: 23629

D N T AUTOMOTIVE Facility Name:

Env Int Type Code: HWG Program ID: 10351960 Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336330 -121.903940 Longitude:

Affiliation:

Affiliation Type Desc: Operator

GONZALEZ, EDGAR **Entity Name:**

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported (408) 891-8330 Affiliation Phone:

Direction Distance

Elevation Site Database(s) **EPA ID Number**

DNT AUTOMOTIVE (Continued)

S112345675

EDR ID Number

Affiliation Type Desc: **Document Preparer** EDGAR GONZALEZ **Entity Name:**

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact** Entity Name: **EDGAR GONZALEZ** Entity Title: Not reported

Affiliation Address: 338 N MONTGOMERY

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 891-8330

Affiliation Type Desc: Facility Mailing Address Entity Name: Mailing Address Entity Title: Not reported

338 N MONTGOMERY ST Affiliation Address:

Affiliation City: SAN JOSE Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: 95110 Affiliation Phone: Not reported

Legal Owner Affiliation Type Desc: Entity Name: GONZALEZ, EDGAR

Entity Title: Not reported

338 N MONTGOMERY ST Affiliation Address:

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 95110 (408) 280-5444 Affiliation Phone:

Affiliation Type Desc: Identification Signer Entity Name: **EDGAR GONZALEZ**

Entity Title: OWNER Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

CUPA District Affiliation Type Desc:

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

DNT AUTOMOTIVE (Continued)

S112345675

EDR ID Number

Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation
Entity Name: D N T AUTOMOTIVE

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Affiliation Type Desc: Property Owner
Entity Name: EDGAR GONZALEZ

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: United States
Affiliation Zip: Not reported
Affiliation Phone: (408) 280-5444

CUPA SANTA CLARA:

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.336095

 Longitude:
 -121.903876

 Record ID:
 PR0396713

 Facility ID:
 FA0251077

Region: SANTA CLARA

PE#: 2201

Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.336095

 Longitude:
 -121.903876

 Record ID:
 PR0364342

 Facility ID:
 FA0251077

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 404835

Class: Auto Body and Paint

CERS TANKS:

Site ID: 23629 CERS ID: 10351960

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Map ID MAP FINDINGS
Direction

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DNT AUTOMOTIVE (Continued)

S112345675

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Notes: The used oil filter container did not have the correct accumulation start date marked. Ensure the container is marked with the date the

first filter is added.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and

portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical

characteristics of the Hazardous Waste, and starting accumulation

date.

Violation Notes: The used oil drums did not have the proper marking. Ensure all

hazardous waste containers have the proper marking as detailed below. Provided hazardous waste labels with one filled out as an example.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter

6.95, Section(s) 25508.1(a)-(f)

Violation Description: Failure to electronically update business plan within 30 days of any

one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that

requires modification to any portion of the business plan.

Violation Notes: The chemical inventory submitted 9/9/2016 lists oxygen, but the oxygen

cylinder is no longer stored at the facility. Update the inventory in FrontCounter (http://FrontCounter.sccgov.org). Contact me for assistance accessing or modifying your information on FrontCounter.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter

1, Section(s) 265.173

Violation Description: Failure to meet the following container management requirements: (a) A

container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to

leak.

Map ID MAP FINDINGS Direction

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

DNT AUTOMOTIVE (Continued)

S112345675

Violation Notes: 1 of the 3 used oil drums was not closed. Keep container closed when

not adding or removing waste. Santa Clara County Environmental Health

Violation Division: Violation Program: HW Violation Source: **CERS**

Site ID: 23629

D N T AUTOMOTIVE Site Name:

12-01-2016 Violation Date:

Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5,

Section(s) 25250.22

Failure to properly manage used oil and/or fuel filters in accordance Violation Description:

with the requirements.

Violation Notes: Drained used oil filters accumulated for longer than one year. Ensure

used oil filters are not accumulated for more than one year.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 23629

Site Name: D N T AUTOMOTIVE

Violation Date: 12-01-2016

HSC 6.5 25123.3(h)(1)(c) - California Health and Safety Code, Chapter Citation:

6.5, Section(s) 25123.3(h)(1)(c)

Violation Description: Failure to send hazardous waste offsite for treatment, storage, or

disposal of acute/extremely hazardous waste after the first 1-kilogram

threshold amount was accumulated within a 90 day period.

Violation Notes: Facility accumulated hazardous waste for longer than 180 days once

they passed the 100 kg mark. Ensure that once 100 kg of hazardous

waste is accumulated, the waste is picked up within 180 days.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 12-01-2016

Violations Found: Yes

Eval Type: Routine done by local agency

Automotive repair facility. Currently generating ~13 gallons of used **Eval Notes:**

oil a month and drained used oil filters. Emergency equipment available and emergency information posted in the office. Due to the volume of waste being generated you may take advantage of the County's Business Small Generator program. Go to HHW.org and scroll down for information on the Business Small Generator program. Corrected Minor: G002: Inactive EPA ID Number- Completed and submitted a DTSC Form 1358

during the inspection. eMail: dntracer@yahoo.com

Santa Clara County Environmental Health **Eval Division:**

HW Eval Program: **Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

12-01-2016 Eval Date: Yes Violations Found:

Eval Type: Routine done by local agency

Eval Notes: Automotive repair facility. Submittal to FrontCounter on 9/9/2016 is

accurate as observed except as noted above. Currently storing used oil

Map ID MAP FINDINGS
Direction

Distance
Elevation Site

EDR ID Number
Database(s) EPA ID Number

DNT AUTOMOTIVE (Continued)

S112345675

(3x 55 gallons) in HMBP quantities. New oil, various automotive fluids and aerosol cans stored in less than HMBP quantities. Emergency equipment available. NOTE: If you decide to reduce your used oil storage to less than 55 gallons total, please contact me for a follow up inspection to verify their removal and close out of the HMBP

permit.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 23629

Facility Name: D N T AUTOMOTIVE

Env Int Type Code: HWG
Program ID: 10351960
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336330 Longitude: -121.903940

Affiliation:

Affiliation Type Desc: Operator

Entity Name: GONZALEZ, EDGAR

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 891-8330

Affiliation Type Desc: Document Preparer Entity Name: EDGAR GONZALEZ

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact Entity Name: EDGAR GONZALEZ

Entity Title: Not reported

Affiliation Address: 338 N MONTGOMERY

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: (408) 891-8330

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 338 N MONTGOMERY ST

Affiliation City: SAN JOSE

Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

DNT AUTOMOTIVE (Continued)

S112345675

EDR ID Number

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Legal Owner

GONZALEZ, EDGAR

Not reported

Affiliation Address: 338 N MONTGOMERY ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110
Affiliation Phone: (408) 280-5444

Affiliation Type Desc: Identification Signer Entity Name: EDGAR GONZALEZ

Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Net report

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation
Entity Name: D N T AUTOMOTIVE

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: EDGAR GONZALEZ

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

United States

Not reported

(408) 280-5444

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

I40BRENNER'S AUTOMOTIVECUPA Listings\$121469926North330 N AUTUMN STSAN JOSE HAZMATN/A

< 1/8 SAN JOSE, CA 95110

0.102 mi.

537 ft. Site 1 of 8 in cluster I

Relative: CUPA SANTA CLARA:

Lower Region: SANTA CLARA

Actual: PE#: 2201

83 ft. Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.336697

 Longitude:
 -121.902962

 Record ID:
 PR0313589

 Facility ID:
 FA0209512

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 405315

Class: Auto Body and Paint

Region: SAN JOSE File Num: 410978

Class: Auto Body and Paint

141 OUT OF BUSINESS SAN JOSE HAZMAT S115780484

North 330 N AUTUMN ST SUITE A < 1/8 SAN JOSE, CA 95110

0.102 mi.

537 ft. Site 2 of 8 in cluster I

Relative: SAN JOSE HAZMAT:

 Lower
 Date of Data:
 AS OF 02/07/2014

 Actual:
 Region:
 SAN JOSE

 83 ft.
 File Num:
 405315

Class: Auto Body and Paint

I42 IA 102813 SALAZAR AUTO BODY CUPA Listings

North 330 AUTUMN ST B < 1/8 SAN JOSE, CA 95112

0.102 mi.

537 ft. Site 3 of 8 in cluster I

Relative: CUPA SANTA CLARA:

Lower Region: SANTA CLARA

Actual: PE#: 2240

83 ft. Program Description: GENERATES < 10 GAL/YR

 Latitude:
 37.348347

 Longitude:
 -121.886516

 Record ID:
 PR0381269

 Facility ID:
 FA0260153

N/A

S121473700

N/A

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

I43 OUT OF BUSINESS SAN JOSE HAZMAT S115780612

330 AUTUMN ST SUITE B N/A

< 1/8 0.102 mi.

North

537 ft. Site 4 of 8 in cluster I

Relative: SAN JOSE HAZMAT:

 Lower
 Date of Data:
 AS OF 02/07/2014

 Actual:
 Region:
 SAN JOSE

 83 ft.
 File Num:
 410978

SAN JOSE, CA 95110

Class: Auto Body and Paint

144 ARCHITECTURAL FACADES UNLIMITE CERS HAZ WASTE \$106826128

North 490 HOWARD STREET CUPA Listings N/A

< 1/8 SAN JOSE, CA 95110 EMI

0.105 mi. SAN JOSE HAZMAT
552 ft. Site 5 of 8 in cluster I CERS

Relative: CERS HAZ WASTE:

 Lower
 Site ID:
 7042

 Actual:
 CERS ID:
 10353346

83 ft. CERS Description: Hazardous Waste Generator

Violations:

Site ID: 7042

Site Name: ARTURO AUTO REPAIR

Violation Date: 06-25-2015

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: _____ Facility

last submitted and HMBP in 2012. Submit a complete HMBP on FrontCounter or CERS. Ensure all three HMBP sections (Facility

Information, Hazardous Materials Inventory, and Emergency Response and

Training Plans) are submitted annually to re-certify the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 7042

Site Name: ARTURO AUTO REPAIR

Violation Date: 06-25-2015

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain and/or maintain an Active EPA ID.

Violation Notes: Facility s

EPA ID number (CAL000377056) is currently inactive. Maintain an active EPA ID number while generating any hazardous waste. A copy of DTSC

Form 1358 was left onsite during the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-25-2015 Violations Found: Yes

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

Eval Type: Routine done by local agency

Auto repair facility. Currently storing used oil (3x 55 gallons) in **Eval Notes:**

HMBP quantities. Under HMBP quantities of new motor oil (quart size) and various aerosol cans. NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents retained for 3 years. Contact me for more information. A sample training log attached

with this report.

Eval Division: Santa Clara County Environmental Health

HMRRP Eval Program: Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-25-2015 Violations Found:

Eval Type: Routine done by local agency

Eval Notes: Automotive repair facility. Currently generating used oil and oil

> filters. Reviewed pickup receipts. Emergency equipment available and properly maintained. Corrected minors: -Emergency Information Posted -Marking: 1 rolling cart and 1 55 gallon used oil drum -Container

Open: 1 55 gallon used oil drum -Container Requirements: Used Oil/Fuel

Filters: 1 55 gallon drum of oil filters eMail:

arturoautorepair4@gmail.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: **CERS**

Enforcement Action:

Site ID: 7042

Site Name: ARTURO AUTO REPAIR Site Address: 490 HOWARD ST Site City: SAN JOSE Site Zip: 95110 Enf Action Date: 06-25-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: **HMRRP CERS** Enf Action Source:

Site ID: 7042

Site Name: ARTURO AUTO REPAIR Site Address: 490 HOWARD ST Site City: SAN JOSE 95110 Site Zip: Enf Action Date: 06-25-2015

Enf Action Type: Notice of Violation (Unified Program)

Notice of Violation Issued by the Inspector at the Time of Inspection Enf Action Description:

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

HW Enf Action Program: Enf Action Source: **CERS**

Coordinates:

7042 Site ID:

Facility Name: ARTURO AUTO REPAIR Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

EDR ID Number

Env Int Type Code: HWG
Program ID: 10353346
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336950 Longitude: -121.903010

Affiliation:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Property Owner

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation
Entity Name: ARTURO AUTO REPAIR

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name: Mike Akataffer Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: United States Affiliation Zip: Not reported (408) 907-3432 Affiliation Phone:

Affiliation Type Desc: Operator Entity Name: Arturo Sanchez Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported (408) 890-9749 Affiliation Phone:

Affiliation Type Desc: Document Preparer
Entity Name: ARTURO SANCHEZ JR

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

EDR ID Number

Environmental Contact Affiliation Type Desc: **Entity Name:** Arturo Sanchez Entity Title: Not reported Affiliation Address: 490 Howard St Affiliation City: San Jose Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 287-7743

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 490 HOWARD ST
Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: ARTURO AUTO REPAIR

Entity Title: Not reported
Affiliation Address: 490 HOWARD ST
Affiliation City: SAN JOSE

Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95110
Affiliation Phone: (408) 890-9749

Affiliation Type Desc: Identification Signer
Entity Name: ARTURO SANCHEZ JR

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.336977

 Longitude:
 -121.903392

 Record ID:
 PR0410091

 Facility ID:
 FA0271502

Region: SANTA CLARA

PE#: 2201

Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.336977

 Longitude:
 -121.903392

 Record ID:
 PR0410094

 Facility ID:
 FA0271502

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

EMI:

1993 Year: County Code: 43 Air Basin: SF Facility ID: 8258 Air District Name: BA SIC Code: 3272

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0 Reactive Organic Gases Tons/Yr: 0 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: n Part. Matter 10 Micrometers and Smllr Tons/Yr:0

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 601660 Auto Repair Class:

CERS TANKS:

Site ID: 7042 CERS ID: 10353346

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 7042

Site Name: ARTURO AUTO REPAIR

Violation Date: 06-25-2015

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Facility

> last submitted and HMBP in 2012. Submit a complete HMBP on FrontCounter or CERS. Ensure all three HMBP sections (Facility

Information, Hazardous Materials Inventory, and Emergency Response and

Training Plans) are submitted annually to re-certify the HMBP.

Santa Clara County Environmental Health Violation Division:

HMRRP Violation Program: **CERS** Violation Source:

Site ID: 7042

Site Name: ARTURO AUTO REPAIR

Violation Date: 06-25-2015

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain and/or maintain an Active EPA ID.

Violation Notes: Facility s

EPA ID number (CAL000377056) is currently inactive. Maintain an active EPA ID number while generating any hazardous waste. A copy of DTSC

Form 1358 was left onsite during the inspection.

Direction Distance

Elevation Site Database(s) EPA ID Number

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

EDR ID Number

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-25-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility. Currently storing used oil (3x 55 gallons) in

HMBP quantities. Under HMBP quantities of new motor oil (quart size) and various aerosol cans. NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents retained for 3 years. Contact me for more information. A sample training log attached

with this report.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-25-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Automotive repair facility. Currently generating used oil and oil

filters. Reviewed pickup receipts. Emergency equipment available and properly maintained. Corrected minors: -Emergency Information Posted -Marking: 1 rolling cart and 1 55 gallon used oil drum -Container

Open: 1 55 gallon used oil drum -Container Requirements: Used Oil/Fuel

Filters: 1 55 gallon drum of oil filters eMail:

arturoautorepair4@gmail.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Enforcement Action:

Site ID: 7042

Site Name: ARTURO AUTO REPAIR
Site Address: 490 HOWARD ST
Site City: SAN JOSE
Site Zip: 95110

 Site Zip:
 95110

 Enf Action Date:
 06-25-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP
Enf Action Source: CERS

Site ID: 7042

Site Name: ARTURO AUTO REPAIR
Site Address: 490 HOWARD ST
Site City: SAN JOSE
Site Zip: 95110
Enf Action Date: 06-25-2015

Enf Action Type: Notice of Violation (Unified Program)

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: HW Enf Action Source: **CERS**

Coordinates:

Site ID: 7042

Facility Name: ARTURO AUTO REPAIR

Env Int Type Code: **HWG** Program ID: 10353346 Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336950 Longitude: -121.903010

Affiliation:

Affiliation Type Desc: **CUPA District**

Santa Clara County Environmental Health **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA Affiliation Country: Not reported 95112-2716 Affiliation Zip: Affiliation Phone: (408) 918-3400

Parent Corporation Affiliation Type Desc: ARTURO AUTO REPAIR **Entity Name:**

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner Mike Akataffer Entity Name: Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: United States Affiliation Zip: Not reported Affiliation Phone: (408) 907-3432

Affiliation Type Desc: Operator **Entity Name:** Arturo Sanchez Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 890-9749 Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

ARCHITECTURAL FACADES UNLIMITE (Continued)

S106826128

EDR ID Number

Affiliation Type Desc: Document Preparer
Entity Name: ARTURO SANCHEZ JR

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc:
Entity Name:
Entity Title:
Affiliation Address:
Affiliation City:
Affiliation State:

Affiliation State:

Affiliation Country:

Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affiliation Country:
Affil

Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 287-7743

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 490 HOWARD ST
Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: ARTURO AUTO REPAIR

Entity Title: Not reported
Affiliation Address: 490 HOWARD ST
Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 890-9749

Affiliation Type Desc: Identification Signer
Entity Name: ARTURO SANCHEZ JR

Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

H45 PG&E- SAN JOSE GAS SERVICE CENTER RCRA-SQG 1000199514
SSE 105 N MONTGOMERY ST FINDS CAD981159403

< 1/8 SAN JOSE, CA 95110

0.106 mi.

558 ft. Site 4 of 14 in cluster H

Relative: RCRA-SQG:

Higher Date form received by agency: 09/01/1996

Actual: Facility name: PG&E- SAN JOSE GAS SERVICE CENTER

86 ft. Facility address: 105 N MONTGOMERY ST

SAN JOSE, CA 95110

EPA ID: CAD981159403
Mailing address: N MONTGOMERY ST

SAN JOSE, CA 95110

Contact: Not reported Contact address: Not reported

Not reported

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

ECHO

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: PG&E

Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E- SAN JOSE GAS SERVICE CENTER (Continued)

1000199514

Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: Nο User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 04/16/1990 Site name: PG&E-SAN JOSE Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110002677522

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

1000199514 Envid: Registry ID: 110002677522

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002677522

H46 MANADA TILE LUST S101303936 **517 W SAINT JOHN ST HIST LUST** SE N/A

< 1/8 SAN JOSE, CA 95110 **CERS**

0.107 mi.

Site 5 of 14 in cluster H 566 ft.

Relative: LUST:

SANTA CLARA COUNTY LOP Lower Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500864 83 ft.

Global Id: T0608500864 37.3339703644687 Latitude: Longitude: -121.900777816772 Status: Completed - Case Closed

05/30/1996 Status Date:

Direction Distance

Elevation Site Database(s) EPA ID Number

MANADA TILE (Continued) S101303936

Case Worker: UST

RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500864

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500864

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP

Address: SANTA CLARA COUNTY LOP

1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500864

 Action Type:
 Other

 Date:
 01/01/1990

 Action:
 Leak Reported

 Global Id:
 T0608500864

 Action Type:
 RESPONSE

 Date:
 05/30/1996

Action: Other Report / Document

Global Id: T0608500864
Action Type: ENFORCEMENT
Date: 05/30/1996

Action: Closure/No Further Action Letter

LUST:

Global Id: T0608500864

Status: Completed - Case Closed

Status Date: 05/30/1996

Global Id: T0608500864

Status: Open - Case Begin Date

Status Date: 01/01/1990

LUST REG 2:

Region: 2

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

MANADA TILE (Continued)

S101303936

EDR ID Number

Facility Id: Not reported Case Closed Facility Status: 07S1E07Q10f Case Number: How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Not reported Date Leak Confirmed: Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07Q10F

 Date Closed:
 05/30/1996

 EDR Link ID:
 07S1E07Q10F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07Q10 Oversite Agency: SCVWD

Date Listed: 1991-01-03 00:00:00 Closed Date: 1996-05-30 00:00:00

CERS TANKS:

 Site ID:
 220843

 CERS ID:
 T0608500864

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

 H47
 MANADA TILE CO, INC
 SWEEPS UST
 \$106929030

 SE
 517 W ST JOHN ST
 N/A

< 1/8 SAN JOSE, CA

0.107 mi.

566 ft. Site 6 of 14 in cluster H

Relative: SWEEPS UST: Lower Status:

LowerStatus:ActiveActual:Comp Number:40690483 ft.Number:9

Board Of Equalization: Not reported Referral Date: 09-30-92 Action Date: 09-08-92 Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank ld: 43-060-406904-000001

Tank Status: A
Capacity: 2000
Active Date: Not reported
Tank Use: M.V. FUEL

STG: F

Content: REG UNLEADED

Number Of Tanks: 2

Status: Active
Comp Number: 406904
Number: 9
Roard Of Equalization: Not repo

Board Of Equalization: Not reported Referral Date: 09-30-92 Action Date: 09-08-92 Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-406904-000002

Tank Status: A
Capacity: 2000
Active Date: Not reported
Tank Use: M.V. FUEL

STG: P

Content: REG UNLEADED Number Of Tanks: Not reported

 H48
 PG&E- SAN JOSE GAS LOAD CENTER
 RCRA-SQG
 1000199515

 SSE
 65 N MONTGOMERY ST
 FINDS
 CAD981159411

< 1/8 SAN JOSE, CA 95110

0.108 mi.

569 ft. Site 7 of 14 in cluster H

Relative: RCRA-SQG:

Higher Date form received by agency: 09/01/1996

Actual: Facility name: PG&E- SAN JOSE GAS LOAD CENTER

86 ft. Facility address: 65 N MONTGOMERY ST SAN JOSE, CA 95110

EPA ID: CAD981159411
Mailing address: N MONTGOMERY ST
SAN JOSE, CA 95110

Contact: Not reported Contact address: Not reported

nntact address: Not reported
Not reported

Contact country: US

Contact telephone: Not reported

ECHO

Direction Distance Elevation

evation Site Database(s) EPA ID Number

PG&E- SAN JOSE GAS LOAD CENTER (Continued)

1000199515

EDR ID Number

Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: PG&E

Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: Nο Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E- SAN JOSE GAS LOAD CENTER (Continued)

1000199515

1009122970

N/A

Registry ID: 110002677531

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

1000199515 Envid: Registry ID: 110002677531

http://echo.epa.gov/detailed-facility-report?fid=110002677531 DFR URL:

H49 **ECONO-LINE EDR Hist Auto**

SSE 33 N MONTGOMERY ST

< 1/8 SAN JOSE, CA

0.110 mi.

579 ft. Site 8 of 14 in cluster H

Relative: Higher

EDR Hist Auto

Year: Name: Type: Actual:

1966 **ECONO-LINE AUTOMOBILE REPAIRING** 86 ft. 1972 CITY GLASS SERVICE Automotive Repair Shops, NEC 1973 CITY GLASS SERVICE Automotive Repair Shops, NEC 1974 CITY GLASS SERVICE Automotive Repair Shops, NEC CITY GLASS SERVICE Automotive Repair Shops, NEC 1975 1976 CITY GLASS SERVICE Automotive Repair Shops, NEC CITY GLASS SERVICE Automotive Repair Shops, NEC 1977 1978 CITY GLASS SERVICE Automotive Repair Shops, NEC Automotive Repair Shops, NEC 1979 MORALES LARRY

1980 MORALES LARRY Automotive Repair Shops, NEC 1982 **MORALES LARRY** Automotive Repair Shops, NEC **MORALES LARRY** Automotive Repair Shops, NEC 1983 1985 MORALES LARRY Automotive Repair Shops, NEC 1986 MORALES LARRY Automotive Repair Shops, NEC Automotive Repair Shops, NEC 1987 **MORALES LARRY** 1988 **MORALES LARRY** Automotive Repair Shops, NEC

MORALES LARRY Powertrain Components Repair Services 1989 1990 MORALES LARRY Powertrain Components Repair Services

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

J50 GARDEN CITY GAS WORKS EDR MGP 1008407764

SSE W. ST JOHN AND MONTGOMERY STREETS

< 1/8 SAN JOSE, CA 95110

0.112 mi.

590 ft. Site 1 of 2 in cluster JRelative: Manufactured Gas Plants:

Higher Alternate Name: PACIFIC GAS AND ELECTRIC CO. No additional information available

Actual: 89 ft.

G51 FLEET BODYWORX CUPA Listings S118585172
NW 341 N MONTGOMERY ST N/A

NW 341 N MONTGOMERY S
< 1/8 SAN JOSE, CA 95110</p>

0.112 mi.

591 ft. Site 8 of 20 in cluster G
Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

Actual: PE#: 2205

84 ft. Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.33598

 Longitude:
 -121.904202

 Record ID:
 PR0364348

 Facility ID:
 FA0251081

Region: SANTA CLARA

PE#: 2225

Program Description: ONSITE HAZ WASTE RECYCLER > 100 KG/MO

 Latitude:
 37.33598

 Longitude:
 -121.904202

 Record ID:
 PR0400476

 Facility ID:
 FA0251081

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 4-6 CHEMICALS

 Latitude:
 37.33598

 Longitude:
 -121.904202

 Record ID:
 PR0397670

 Facility ID:
 FA0251081

G52 VINCENT ELECTRIC MOTOR CO

NW 341 N MONTGOMERY ST

CUPA Listings S121469822

N/A

NW 341 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.112 mi.

591 ft. Site 9 of 20 in cluster G
Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

Actual: PE#: 2205

84 ft. Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.335953

 Longitude:
 -121.904129

 Record ID:
 PR0317770

 Facility ID:
 FA0208923

N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number**

G53 A J WASTE RCRA NonGen / NLR 1000136072

NW 345 MONTGOMERY ST **FINDS** CAD980735419

SAN JOSE, CA 95110 **ECHO** < 1/8

0.112 mi.

591 ft. Site 10 of 20 in cluster G Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 06/01/1982 Facility name: A J WASTE Actual:

Facility address: 345 MONTGOMERY ST 84 ft.

SAN JOSE, CA 95110

EPA ID: CAD980735419

Mailing address: 1425 BROADWAY SUITE 12

BURLINGAME, CA 94010

Contact: ENVIRONMENTAL MANAGER

Contact address: 345 MONTGOMERY ST

SAN JOSE, CA 95110

Contact country: US

415-343-3679 Contact telephone: Contact email: Not reported

EPA Region: 09

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

NOT REQUIRED Owner/operator name: Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private

Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: FERRANO ATILIO J Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported 415-555-1212 Owner/operator telephone: Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Private Legal status: Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: Yes Treater, storer or disposer of HW: No Underground injection activity: No

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

A J WASTE (Continued) 1000136072

On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002671010

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

1000136072 Envid: Registry ID: 110002671010

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002671010

G54 **VINCENT ELECTRIC MOTOR COMPANY** LUST S103880994 NW **341 N MONTGOMERY ST HIST LUST** N/A

< 1/8 0.112 mi.

Site 11 of 20 in cluster G 591 ft.

SAN JOSE, CA 95150

LUST REG 2: Relative: Higher Region:

Actual: 84 ft.

Facility Id: Not reported Case Closed Facility Status: Case Number: 07S1E07L04f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 11/29/1993 Pollution Characterization Began: 11/29/1993 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

EMI

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VINCENT ELECTRIC MOTOR COMPANY (Continued)

S103880994

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07L04 Oversite Agency: SCVWD

Date Listed: 1994-05-31 00:00:00 2001-06-21 00:00:00 Closed Date:

EMI:

Year: 1995 County Code: 43 SF Air Basin: Facility ID: 6423 Air District Name: BA SIC Code: 7694

Air District Name: **BAY AREA AQMD** Not reported Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 2 Reactive Organic Gases Tons/Yr: 1 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 1 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1996 County Code: 43 Air Basin: SF Facility ID: 6423 Air District Name: BA SIC Code: 7694

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 2 Reactive Organic Gases Tons/Yr: 1 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 1 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1997 County Code: 43 Air Basin: SF Facility ID: 6423 Air District Name: ВА SIC Code: 7694

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 1 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 1 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0

Direction Distance Elevation

Site Database(s) EPA ID Number

VINCENT ELECTRIC MOTOR COMPANY (Continued)

S103880994

EDR ID Number

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1998

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6423

 Air District Name:
 BA

 SIC Code:
 7694

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 1
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1999

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6423

 Air District Name:
 BA

 SIC Code:
 7694

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 1
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2000

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6423

 Air District Name:
 BA

 SIC Code:
 7694

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 1
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Direction Distance

Elevation Site Database(s) EPA ID Number

G55 FLEET BODYWORK CERS HAZ WASTE S121740009
NW 341 N MONTGOMERY ST CERS N/A

NW 341 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.112 mi.

591 ft. Site 12 of 20 in cluster G

Relative: CERS HAZ WASTE:

 Higher
 Site ID:
 116840

 Actual:
 CERS ID:
 10351981

84 ft. CERS Description: Hazardous Waste Generator

Violations:

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: 22 CCR 23 66273.31(a) - California Code of Regulations, Title 22,

Chapter 23, Section(s) 66273.31(a)

Violation Description: Failure of the universal waste handler to transfer universal waste to

the appropriate designation facility.

Violation Notes: Returned to compliance on 04/26/2016. Noted several broken fluorescent

light bulbs in an outdoor trashcan. Mr. Smith directed an employee to

contain the bulbs during the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes: Returned to compliance on 04/26/2016. Facility does not currently

record volumes of recycled solvent per month.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain and/or maintain an Active EPA ID.

Violation Notes: Returned to compliance on 04/26/2016. EPA ID number CAL000332714 is

currently inactive. Mr. Blair was given DTSC form 1358 at the time of

inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: Returned to compliance on 06/13/2016. Facility stores materials in

EDR ID Number

Map ID MAP FINDINGS Direction

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

FLEET BODYWORK (Continued)

S121740009

Hazardous Materials Business Plan Quantities but has not submitted an HMBP to CERS. Submit a complete HMBP to CERS or Santa Clara County's

FrontCounter (frontcounter.sccgov.org). Ensure the HMBP is certified

for accuracy annually.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HMRRP** Violation Source: **CERS**

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

22 CCR 12 66262.40(c) - California Code of Regulations, Title 22, Citation:

Chapter 12, Section(s) 66262.40(c)

Violation Description: Failure to determine if the waste generated is a hazardous waste and

to maintain analysis results for three years.

Violation Notes: Returned to compliance on 04/26/2016. The following containers were

> unmarked and had unknown contents. Determine if the following containers hold hazardous waste and manage accordingly: 1x5 gallon metal bucket next to paint booth (outside) 2x5 gallon plastic buckets in back corner of frame shop near roll-up door 1x5 gallon metal container (labeled thinner) in storage closet of painting area Any

container of hazardous waste must be closed and marked.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Citation:

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers with

> the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous

Waste, and starting accumulation date.

Returned to compliance on 04/26/2016. Observed 2x5 gallon containers Violation Notes:

of used antifreeze in corner of framing garage with no labels. Observed several containers of paint gun cleaning waste, awaiting

recycling in a distiller, with no labels.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Evaluation:

Eval General Type: Compliance Evaluation Inspection

03-10-2016 Eval Date:

Violations Found: No

Eval Type: Routine done by local agency

See Hazardous Waste Generator report for details. **Eval Notes:**

Eval Division: Santa Clara County Environmental Health

Eval Program: **HWRecycler Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2016 Violations Found:

Eval Type: Routine done by local agency

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

FLEET BODYWORK (Continued)

S121740009

Eval Notes: Inspection conducted by Matt Burge. Large fleet auto body facility.

Facility stores oxygen (251 cuft x 6), acetylene (140 cuft x 4), Argon/CO2 (280 cuft x 5), propane (8 gallons x 9 cylinders) and 55 gallons of water bourne paint. Facility also stores Argon, CO2, various paints, solvents, greases in less than HMBP quantities. Contact me (matthew.burge@deh.sccgov.org, 408-918-3458) for information and assistance with SCC's FrontCounter website.

Eval Division: Santa Clara County Environmental Health

HMRRP Eval Program: Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

03-10-2016 Eval Date: Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Inspection conducted with Matt Burge. Facility does body work for

large fleet vehicles and recently moved to the current location. Consolidated manifests for solvent recycling machine service and solid paint waste pickups were reviewed at the time of inspection. Uniforms are commercially laundered and fire extinguishers were serviced in April of 2015. Spill equipment was noted on-site. The following violations were corrected at the time of inspection: 1.) Emergency posting did not have a map of emergency response equipment locations. Mr. Smith added equipment to the facility map and posted it next to emergency contact numbers at the time of inspection. 2.) An empty drum of hazardous waste over 5 gallons had no label or date. Mr. Smith labeled the drum at the time of inspection and was advised to manage it within one year. NOTES: 1.) No manifests were available for the disposal of paint booth filters. Mr. Smith (General Manager) stated

that filters are every [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW **Eval Source: CERS**

Coordinates:

Site ID: 116840

FLEET BODYWORK Facility Name:

Env Int Type Code: HWG Program ID: 10351981 Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.335960 Longitude: -121.904610

Affiliation:

Affiliation Type Desc: Facility Mailing Address Entity Name: Mailing Address Entity Title: Not reported

Affiliation Address: 341 N MONTGOMERY ST

Affiliation City: SAN JOSE Affiliation State: Affiliation Country: Not reported Affiliation Zip: 95110 Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Distance

Elevation Site Database(s) EPA ID Number

FLEET BODYWORK (Continued)

S121740009

EDR ID Number

Entity Name: FLEET BODYWORK INC

Entity Title: Not reported

Affiliation Address: 345 N MONTGOMERY ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 291-0676

Affiliation Type Desc: Parent Corporation
Entity Name: FLEET BODYWORK

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Document Preparer Affiliation Type Desc: Entity Name: Ronald Zamudio **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: Ronald Zamudio
Entity Title: Not reported

Affiliation Address: 341 N. Montgomery St Affiliation City: San Jose

Affiliation City: San C Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: (408) 291-0676

Affiliation Type Desc: Identification Signer Entity Name: Ronald Zamudio **Entity Title:** Vice President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

FLEET BODYWORK (Continued)

S121740009

EDR ID Number

Affiliation Phone: Not reported

Affiliation Type Desc: Operator Entity Name: Ronald Zamudio **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 291-0676

CERS TANKS:

Site ID: 116840 CERS ID: 10351981

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: 22 CCR 23 66273.31(a) - California Code of Regulations, Title 22,

Chapter 23, Section(s) 66273.31(a)

Violation Description: Failure of the universal waste handler to transfer universal waste to

the appropriate designation facility.

Violation Notes: Returned to compliance on 04/26/2016. Noted several broken fluorescent

light bulbs in an outdoor trashcan. Mr. Smith directed an employee to

contain the bulbs during the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes: Returned to compliance on 04/26/2016. Facility does not currently

record volumes of recycled solvent per month.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain and/or maintain an Active EPA ID.

Violation Notes: Returned to compliance on 04/26/2016. EPA ID number CAL000332714 is

currently inactive. Mr. Blair was given DTSC form 1358 at the time of

inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Map ID MAP FINDINGS
Direction

Distance EDR ID Number
Elevation Site EPA ID Number

FLEET BODYWORK (Continued)

S121740009

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: Returned to compliance on 06/13/2016. Facility stores materials in

Hazardous Materials Business Plan Quantities but has not submitted an HMBP to CERS. Submit a complete HMBP to CERS or Santa Clara County's FrontCounter (frontcounter.sccgov.org). Ensure the HMBP is certified

for accuracy annually.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: 22 CCR 12 66262.40(c) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.40(c)

Violation Description: Failure to determine if the waste generated is a hazardous waste and

to maintain analysis results for three years.

Violation Notes: Returned to compliance on 04/26/2016. The following containers were

unmarked and had unknown contents. Determine if the following containers hold hazardous waste and manage accordingly: 1x5 gallon metal bucket next to paint booth (outside) 2x5 gallon plastic buckets in back corner of frame shop near roll-up door 1x5 gallon metal container (labeled thinner) in storage closet of painting area Any container of hazardous waste must be closed and marked.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 116840

Site Name: FLEET BODYWORK

Violation Date: 03-10-2016

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers with

the following requirements: "Hazardous Waste", name and address of the

generator, physical and chemical characteristics of the Hazardous

Waste, and starting accumulation date.

Violation Notes: Returned to compliance on 04/26/2016. Observed 2x5 gallon containers

of used antifreeze in corner of framing garage with no labels. Observed several containers of paint gun cleaning waste, awaiting

recycling in a distiller, with no labels.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2016

Violations Found: No

Eval Type: Routine done by local agency

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FLEET BODYWORK (Continued)

S121740009

Eval Notes: See Hazardous Waste Generator report for details.

Santa Clara County Environmental Health Eval Division: Eval Program: **HWRecycler**

Eval Source: **CERS**

Compliance Evaluation Inspection Eval General Type:

03-10-2016 Eval Date: Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Inspection conducted by Matt Burge. Large fleet auto body facility.

> Facility stores oxygen (251 cuft x 6), acetylene (140 cuft x 4), Argon/CO2 (280 cuft x 5), propane (8 gallons x 9 cylinders) and 55 gallons of water bourne paint. Facility also stores Argon, CO2, various paints, solvents, greases in less than HMBP quantities. Contact me (matthew.burge@deh.sccgov.org, 408-918-3458) for information and assistance with SCC's FrontCounter website.

Eval Division: Santa Clara County Environmental Health

Eval Program: **HMRRP** Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2016

Violations Found:

Eval Type: Routine done by local agency

Eval Notes: Inspection conducted with Matt Burge. Facility does body work for

large fleet vehicles and recently moved to the current location. Consolidated manifests for solvent recycling machine service and solid paint waste pickups were reviewed at the time of inspection. Uniforms are commercially laundered and fire extinguishers were serviced in April of 2015. Spill equipment was noted on-site. The following violations were corrected at the time of inspection: 1.) Emergency posting did not have a map of emergency response equipment locations.

Mr. Smith added equipment to the facility map and posted it next to emergency contact numbers at the time of inspection. 2.) An empty drum of hazardous waste over 5 gallons had no label or date. Mr. Smith labeled the drum at the time of inspection and was advised to manage it within one year. NOTES: 1.) No manifests were available for the disposal of paint booth filters. Mr. Smith (General Manager) stated

that filters are every [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: **CERS**

Coordinates:

Site ID: 116840

FLEET BODYWORK Facility Name:

Env Int Type Code: **HWG** Program ID: 10351981 Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.335960 Longitude: -121.904610

Affiliation:

Affiliation Type Desc: Facility Mailing Address Entity Name: Mailing Address

Direction Distance

Elevation Site Database(s) EPA ID Number

FLEET BODYWORK (Continued)

S121740009

EDR ID Number

Entity Title: Not reported

Affiliation Address: 341 N MONTGOMERY ST

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: FLEET BODYWORK INC

Entity Title: Not reported

Affiliation Address: 345 N MONTGOMERY ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 291-0676

Affiliation Type Desc: Parent Corporation
Entity Name: FLEET BODYWORK

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: **Document Preparer** Ronald Zamudio Entity Name: Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact Entity Name: Ronald Zamudio Not reported

Affiliation Address: 341 N. Montgomery St

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110

Affiliation Phone: (408) 291-0676

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FLEET BODYWORK (Continued)

S121740009

Affiliation Type Desc: Identification Signer Ronald Zamudio **Entity Name:** Entity Title: Vice President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Operator Entity Name: Ronald Zamudio Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 291-0676

G56 EBJ PARTNERS, LP LUST S100943412

NW **341 N MONTGOMERY ST HAZNET** N/A

< 1/8 SAN JOSE, CA 95110 **SAN JOSE HAZMAT** 0.112 mi. **CERS**

591 ft. Site 13 of 20 in cluster G

Relative: LUST:

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: **LUST Cleanup Site** Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501412 84 ft.

T0608501412 Global Id: 37.3364 Latitude: Longitude: -121.90364

Completed - Case Closed Status:

Status Date: 06/21/2001 Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608501412 Global Id:

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

OAKLAND City: Email: Not reported Phone Number: Not reported

Global Id: T0608501412

Contact Type: Local Agency Caseworker UST CASE WORKER Contact Name:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

EBJ PARTNERS, LP (Continued)

S100943412

SANTA CLARA COUNTY LOP Organization Name: 1555 Berger Drive, Suite 300 Address:

City: SAN JOSE Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608501412 Action Type: Other Date: 01/21/1994 Action: Leak Reported

Global Id: T0608501412 Action Type: **ENFORCEMENT** Date: 06/21/2001

Closure/No Further Action Letter Action:

Global Id: T0608501412 Action Type: **ENFORCEMENT** Date: 11/19/1996

Action: Notice of Responsibility - #39949

Global Id: T0608501412 **ENFORCEMENT** Action Type: Date: 03/01/1999 Action: Staff Letter - #27014

Global Id: T0608501412 Action Type: **ENFORCEMENT** 12/03/1999 Date:

Action: Staff Letter - #27016

Global Id: T0608501412 Action Type: **ENFORCEMENT** Date: 05/10/2000

Action: Staff Letter - #27018

Global Id: T0608501412 Action Type: **ENFORCEMENT** 04/10/1995 Date: Action: Staff Letter - #27012

Global Id: T0608501412 Action Type: REMEDIATION Date: 11/29/1993 Action: Excavation

Global Id: T0608501412 **RESPONSE** Action Type: Date: 11/20/2000

Action: Tank Removal Report / UST Sampling Report

Global Id: T0608501412 Action Type: **RESPONSE** Date: 06/20/2000 Action: Other Workplan

Direction Distance

Elevation Site Database(s) EPA ID Number

EBJ PARTNERS, LP (Continued)

S100943412

EDR ID Number

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 11/09/2000

Action: Verbal Communication

Global Id: T0608501412
Action Type: RESPONSE
Date: 01/25/1994

Action: Unauthorized Release Form

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 06/21/2001

 Action:
 Correspondence

Global Id: T0608501412
Action Type: RESPONSE
Date: 11/29/1993

Action: Tank Removal Report / UST Sampling Report

Global Id: T0608501412
Action Type: RESPONSE
Date: 02/26/1980

Action: Other Report / Document

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 04/19/1995

Action: Preliminary Site Assessment Report

Global Id: T0608501412
Action Type: RESPONSE
Date: 08/01/2000

Action: Soil and Water Investigation Report

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 01/21/1999

 Action:
 Correspondence

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 07/30/1999

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 01/17/2000

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608501412

 Action Type:
 RESPONSE

 Date:
 08/08/2000

Action: Soil and Water Investigation Report

Global Id: T0608501412 Action Type: RESPONSE

Direction Distance

Elevation Site Database(s) EPA ID Number

EBJ PARTNERS, LP (Continued)

S100943412

EDR ID Number

Date: 04/10/1995

Action: Preliminary Site Assessment Report

LUST:

Global Id: T0608501412

Status: Completed - Case Closed

Status Date: 06/21/2001

Global Id: T0608501412

Status: Open - Case Begin Date

Status Date: 11/29/1993

Global Id: T0608501412

Status: Open - Site Assessment

Status Date: 11/29/1993

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07L04F

 Date Closed:
 06/21/2001

 EDR Link ID:
 07S1E07L04F

HAZNET:

envid: \$100943412 Year: 2016

GEPAID: CAC002875768
Contact: TONY GONZALEZ
Telephone: 4083181869
Mailing Name: Not reported

Mailing Address: 1855 HAMILTON AVE STE 200
Mailing City,St,Zip: SAN JOSE, CA 951255672

Gen County: Santa Clara
TSD EPA ID: CAD981382732

TSD County: Alameda

Waste Category: Asbestos containing waste

Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To

Include On-Site Treatment And/Or Stabilization)

Tons: 1.15

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 401902

Class: Auto Body and Paint

CERS TANKS:

 Site ID:
 195151

 CERS ID:
 T0608501412

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

EBJ PARTNERS, LP (Continued)

S100943412

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Not reported Entity Title:

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND

Affiliation State: CA Affiliation Country:

Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State:

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

G57 FLEET BODY WORX CPS-SLIC S113060266 NW 345 N MONTGOMERY **HAZNET** N/A SAN JOSE, CA 95110 **CERS**

< 1/8 0.112 mi.

591 ft. Site 14 of 20 in cluster G

Relative: CPS-SLIC: Higher Region:

Facility Status: Open - Inactive Actual: Status Date: 12/01/2015 84 ft. Global Id: T10000008060

> SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency:

STATE

Lead Agency Case Number: Not reported 37.3362 Latitude: Longitude: -121.90462

Case Type: Cleanup Program Site

Case Worker: Not reported Local Agency: Not reported RB Case Number: 43S0607

File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media Affected:

Potential Contaminants of Concern: Polychlorinated biphenyls (PCBs), Arsenic, Chromium, Copper, Lead

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HAZNET:

Mailing Name:

S113060266 envid: Year: 2016 GEPAID: CAL000100853 **RON ZAMUDIO** Contact: Telephone: 4082910676

Mailing Address: 341 N MONTGOMERY ST Mailing City, St, Zip: SAN JOSE, CA 951102326

Not reported

Gen County: Santa Clara TSD EPA ID: UTD981552177

Direction Distance

Elevation Site Database(s) EPA ID Number

FLEET BODY WORX (Continued)

S113060266

EDR ID Number

TSD County: 99

Waste Category: Other organic solids

Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel

Tons: 0.05

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113060266 Year: 2016

GEPAID: CAL000100853
Contact: RON ZAMUDIO
Telephone: 4082910676
Mailing Name: Not reported

Mailing Address: 341 N MONTGOMERY ST Mailing City,St,Zip: SAN JOSE, CA 951102326

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara

Waste Category: Off-specification, aged or surplus organics

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.15

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: \$113060266 Year: 2016

GEPAID: CAL000100853
Contact: RON ZAMUDIO
Telephone: 4082910676
Mailing Name: Not reported

Mailing Address: 341 N MONTGOMERY ST Mailing City,St,Zip: SAN JOSE, CA 951102326

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara

Waste Category: Off-specification, aged or surplus organics

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.15
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$113060266 Year: 2016

GEPAID: CAL000100853
Contact: RON ZAMUDIO
Telephone: 4082910676
Mailing Name: Not reported

Mailing Address: 341 N MONTGOMERY ST Mailing City,St,Zip: SAN JOSE, CA 951102326

Gen County: Santa Clara
TSD EPA ID: NED981723513

TSD County: 99

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FLEET BODY WORX (Continued)

S113060266

Other still bottom waste Waste Category:

Incineration--Thermal Destruction Other Than Use As A Fuel Disposal Method:

Tons: 0.2

Cat Decode: Not reported Method Decode: Not reported Santa Clara Facility County:

envid: S113060266 Year: 2016

CAL000100853 GEPAID: **RON ZAMUDIO** Contact: Telephone: 4082910676 Mailing Name: Not reported

Mailing Address: 341 N MONTGOMERY ST Mailing City, St, Zip: SAN JOSE, CA 951102326

Gen County: Santa Clara TSD EPA ID: NED981723513

TSD County: 99

Waste Category: Other still bottom waste

Incineration--Thermal Destruction Other Than Use As A Fuel Disposal Method:

Tons: 0.2

Not reported Cat Decode: Method Decode: Not reported Facility County: Santa Clara

> Click this hyperlink while viewing on your computer to access 145 additional CA HAZNET: record(s) in the EDR Site Report.

CERS TANKS:

361310 Site ID: T10000008060 CERS ID: CERS Description: Cleanup Program Site

MONTGOMERY ST PROPERTY G58 RCRA-SQG 1000985143 **341 MONTGOMERY ST** CAR000002543 **FINDS**

NW < 1/8 SAN JOSE, CA 95110

0.112 mi. **HAZNET HIST CORTESE** Site 15 of 20 in cluster G 591 ft.

Relative: RCRA-SQG:

Higher Date form received by agency: 09/01/1996

Facility name: MONTGOMERY ST PROPERTY Actual: Facility address: 341 MONTGOMERY ST 84 ft.

> SAN JOSE, CA 95110 CAR000002543

EPA ID: Mailing address: MONTEREY HWY SAN JOSE, CA 95112

Not reported Contact: Contact address: Not reported Not reported

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region:

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of

ECHO

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

MONTGOMERY ST PROPERTY (Continued)

1000985143

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: EBJ ENTERPRISES INC
Owner/operator address: 1800 MONTEREY HWY
SAN JOSE, CA 95112

Owner/operator country: Not reported Owner/operator telephone: 408-295-8222 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110010461927

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS AIR POLLUTANT MAJOR

STATE MASTER

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Direction Distance

Elevation Site Database(s) EPA ID Number

MONTGOMERY ST PROPERTY (Continued)

1000985143

EDR ID Number

ECHO:

Envid: 1000985143 Registry ID: 110010461927

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110010461927

HAZNET:

envid: 1000985143 Year: 1995

GEPAID: CAR000002543

Contact: EBJ ENTERPRISES INC

Telephone: 4153243025 Mailing Name: Not reported

Mailing Address: 550 HAMILTON AVE STE 329
Mailing City,St,Zip: PALO ALTO, CA 943012031

Gen County: Not reported
TSD EPA ID: CAT080010101
TSD County: Not reported

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

Disposal Method: Transfer Station

Tons: .0011

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000985143 Year: 1995

GEPAID: CAR000002543

Contact: EBJ ENTERPRISES INC

Telephone: 4153243025 Mailing Name: Not reported

Mailing Address: 550 HAMILTON AVE STE 329
Mailing City,St,Zip: PALO ALTO, CA 943012031

Gen County: Not reported
TSD EPA ID: CAT080010101
TSD County: Not reported

Waste Category: Other inorganic solid waste

Disposal Method: Transfer Station

Tons: .0185
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: 1000985143

Year: 1995

GEPAID: CAR000002543

Contact: EBJ ENTERPRISES INC

Telephone: 4153243025 Mailing Name: Not reported

Mailing Address: 550 HAMILTON AVE STE 329
Mailing City,St,Zip: PALO ALTO, CA 943012031

Gen County: Not reported
TSD EPA ID: CAT080010101
TSD County: Not reported

Waste Category: Unspecified organic liquid mixture

Disposal Method: Transfer Station

Tons: .0011

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MONTGOMERY ST PROPERTY (Continued)

1000985143

Cat Decode: Not reported Method Decode: Not reported Santa Clara Facility County:

HIST CORTESE:

CORTESE Region: Facility County Code: 43 LTNKA Reg By: Reg Id: 43-1441

VALLEY AUTOMOTIVE SERVICE EDR Hist Auto 1009003538 F59

ESE 125 N AUTUMN ST N/A

SAN JOSE, CA < 1/8

0.113 mi.

599 ft. Site 2 of 3 in cluster F

Relative: **EDR Hist Auto**

Lower

Year: Name: Actual:

VALLEY AUTOMOTIVE SERVICE 1970 **AUTOMOBILE REPAIRING** 80 ft.

VALLEY AUTOMOTIVE General Automotive Repair Shops 1971 1972 VALLEY AUTOMOTIVE General Automotive Repair Shops 1973 VALLEY AUTOMOTIVE General Automotive Repair Shops **VALLEY AUTOMOTIVE** General Automotive Repair Shops 1974 1976 VALLEY AUTOMOTIVE General Automotive Repair Shops

F60 **VALAYA AUTO** CERS HAZ WASTE S107030411 **ESE** 447 W ST JOHN ST **CUPA Listings** N/A **SAN JOSE HAZMAT**

< 1/8 SAN JOSE, CA 95110

0.113 mi.

Site 3 of 3 in cluster F 599 ft.

CERS HAZ WASTE: Relative: Lower Site ID:

79673 CERS ID: 10352992 Actual:

CERS Description: Hazardous Waste Generator 80 ft.

Violations:

Site ID: 79673

Site Name: VALAYA AUTO Violation Date: 02-20-2015

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain and/or maintain an Active EPA ID.

Violation Notes:

Facility does not have an EPA ID number due to a change in ownership. Apply for and maintain an active EPA ID number. A copy of DTSC Form

1358 and assistance filling it out was given during the inspection.

Santa Clara County Environmental Health Violation Division:

Violation Program: HW Violation Source: **CERS**

Site ID: 79673

Site Name: VALAYA AUTO Violation Date: 01-21-2016

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

VALAYA AUTO (Continued) S107030411

Citation: HSC 6.11 25404.1 - California Health and Safety Code, Chapter 6.11,

Section(s) 25404.1

Violation Description: Failure to obtain and/or maintain an active hazardous waste generator

permit.

Violation Notes: On-site to conduct a Hazardous Waste Generator permit investigation.

This facility is currently operating without a valid Hazardous Waste Generator Permit due to unpaid permit fees. Immediately pay the permit fees. The facility was provided with a copy of the invoices. Upon receipt of full payment, a Hazardous Waste Generator permit will be

issued and mailed to the facility.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 79673

Site Name: VALAYA AUTO Violation Date: 02-20-2015

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 11/07/2016.

Facility last certified its HMBP in 2012. Submit a complete HMBP online in CERS. Ensure all three HMBP sections (Facility Information, Hazardous Materials Inventory, and Emergency Response and Training

Plans) are submitted annually to re-certify the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 02-20-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility. Used oil and waste coolant in HMBP quantities. Facility stated they will be looking into obtaining smaller collection

drums. Contact me for a reinspection if smaller containers are obtained. Contact me for information on accessing the online California Environmental Reporting System (CERS) to submit your Hazardous Materials Business Plan (HMBP) information. NOTE: Beginning

January 1, 2015 all annual HBMP training must be documented and the documents retained for 3 years. Contact me for more information.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 01-21-2016

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site to conduct a permit investigation per phone call from the

facility stating that they had reduced the sizes of their drums from 55 gallons to 35 gallons. Consent to conduct a facility walk-through was granted by owner Ted May, and it was verified that they are no

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VALAYA AUTO (Continued) S107030411

longer subject to the Hazardous Materials Business Plan permit. Based

on this observation, starting today, the BP01 permit will be

inactivated with our office.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 02-20-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility generating used oil, waste antifreeze, and

drained used oil filters.

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: **CERS**

Other/Unknown Eval General Type: Eval Date: 01-21-2016

Violations Found: Yes

Eval Type: Other, not routine, done by local agency

Eval Notes: Note: A check for \$81.00 was received during this inspection (Check

Eval Division: Santa Clara County Environmental Health

Eval Program: HWEval Source: **CERS**

Enforcement Action:

Site ID: 79673

VALAYA AUTO Site Name: Site Address: 447 W ST JOHN ST

Site City: SAN JOSE Site Zip: 95110 Enf Action Date: 02-20-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: **HMRRP** Enf Action Source: **CERS**

Site ID: 79673

Site Name: VALAYA AUTO 447 W ST JOHN ST Site Address:

Site City: SAN JOSE Site Zip: 95110 Enf Action Date: 02-20-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: HW Enf Action Source: **CERS**

Coordinates:

Site ID: 79673

Direction Distance

Elevation Site Database(s) EPA ID Number

VALAYA AUTO (Continued)

S107030411

EDR ID Number

Facility Name: VALAYA AUTO

Env Int Type Code: HWG
Program ID: 10352992
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.334480 Longitude: -121.900260

Affiliation:

Affiliation Type Desc:
Entity Name:
Entity Title:
Affiliation Address:
Legal Owner
MAY, TED
Not reported
447 W ST JOHN ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 297-1990

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not report

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 447 W ST JOHN ST

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc:
Entity Name:
VALAYA AUTO
Entity Title:
Not reported
Affiliation Address:
Not reported
Affiliation City:
Not reported
Affiliation State:
Not reported
Not reported
Not reported
Not reported
Not reported

Affiliation Zip: Not reported
Affiliation Phone: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.334273 Longitude: -121.900159

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VALAYA AUTO (Continued) S107030411

Record ID: PR0402070 FA0270106 Facility ID:

SANTA CLARA Region:

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

Latitude: 37.334273 Longitude: -121.900159 Record ID: PR0402071 Facility ID: FA0270106

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 410517 Auto Repair Class:

H61 **CUSTOM PAD & PATTERN LA FIESTA** LUST S105032418

555 ST JOHN ST W SE < 1/8 **SAN JOSE, CA 95110**

0.115 mi.

606 ft. Site 9 of 14 in cluster H

LUST: Relative:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: **LUST Cleanup Site** Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500483 84 ft.

T0608500483 Global Id: Latitude: 37.333653 -121.900756 Longitude:

Status: Completed - Case Closed

Status Date: 04/09/1997 Case Worker: UUU 43-0433 RB Case Number:

SANTA CLARA COUNTY LOP Local Agency:

Not reported File Location: Local Case Number: Not reported

Other Groundwater (uses other than drinking water) Potential Media Affect:

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500483

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

OAKLAND City: Not reported Email: Phone Number: Not reported

Global Id: T0608500483

Contact Type: Local Agency Caseworker Contact Name: UST CASE WORKER

SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Not reported Email: Phone Number: 4089183400 **CERS**

N/A

Direction Distance Elevation

evation Site Database(s) EPA ID Number

CUSTOM PAD & PATTERN LA FIESTA (Continued)

S105032418

EDR ID Number

LUST:

 Global Id:
 T0608500483

 Action Type:
 ENFORCEMENT

 Date:
 05/26/1995

Action: Clean Up Fund - Letter to RP - #43-0433

 Global Id:
 T0608500483

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Reported

 Global Id:
 T0608500483

Global Id: T0608500483
Action Type: ENFORCEMENT
Date: 04/09/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608500483

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Discovery

 Global Id:
 T0608500483

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Stopped

LUST:

Global Id: T0608500483

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608500483

Status: Open - Case Begin Date

Status Date: 03/28/1989

LUST REG 2:

Region: 2
Facility Id: 43-0433
Facility Status: Case Closed
Case Number: 07S1E07Q08
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Not reported
Pollution Remediation Plan Submitted:
Not reported
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: Not reported

CERS TANKS:

Site ID: 204733

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CUSTOM PAD & PATTERN LA FIESTA (Continued)

S105032418

CERS ID: T0608500483

CERS Description: Leaking Underground Storage Tank Cleanup Site

4089183400

Affiliation:

Affiliation Phone:

Local Agency Caseworker Affiliation Type Desc:

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA Affiliation Country: Not reported Not reported Affiliation Zip:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002D21F.pdf

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

CUSTOM PAD AND PARTITION CO INC

HIST UST S118409055

N/A

< 1/8

SAN JOSE, CA 95110

0.115 mi.

H62

SE

606 ft. Site 10 of 14 in cluster H

URL:

555 WEST ST JOHN STREET

Relative: Higher

HIST UST: File Number: 0002D21F

Actual: 84 ft.

Not reported Region: Facility ID: Not reported Facility Type: Not reported Other Type: Not reported Contact Name: Not reported Not reported Telephone: Owner Name: Not reported Owner Address: Not reported Not reported Owner City, St, Zip: Not reported Total Tanks:

Tank Num: Not reported Container Num: Not reported Year Installed: Not reported Tank Capacity: Not reported Tank Used for: Not reported Type of Fuel: Not reported Container Construction Thickness: Not reported Leak Detection: Not reported

Click here for Geo Tracker PDF:

Direction Distance

Elevation Site Database(s) EPA ID Number

 H63
 CUSTOM PAD & PARTITION CO. INC
 LUST
 U001602472

 SE
 555 W SAINT JOHN ST
 HIST UST
 N/A

SE 555 W SAINT JOHN ST < 1/8 SAN JOSE, CA 95110

0.115 mi.

606 ft. Site 11 of 14 in cluster H

Relative: LUST SANTA CLARA:

 Higher
 Region:
 SANTA CLARA

 Actual:
 SCVWD ID:
 07S1E07Q08F

 84 ft.
 Date Closed:
 04/09/1997

 EDR Link ID:
 07S1E07Q08F

HIST UST:

File Number: Not reported URL: Not reported Region: STATE 00000001008

Facility Type: Other

Other Type: MFG. CORRUGATED BXS.

Contact Name: JAMES L. JONES Telephone: 4082922114

Owner Name: CUSTOM PAD & PARITION CO. INC. Owner Address: 555 WEST ST. JOHN STREET

Owner City,St,Zip: SAN JOSE, CA 95110

Total Tanks: 0001

Tank Num: 001 Container Num: 1

Year Installed:
Tank Capacity:
O0000500
Tank Used for:
Type of Fuel:
Container Construction Thickness:
Leak Detection:
Not reported
REGULAR
Not reported
Stock Inventor

H64 CUSTOMPAD&PATTERN/LAFIESTAFOOD

SE 555 W SAINT JOHN ST

< 1/8 SAN JOSE, CA

0.115 mi.

606 ft. Site 12 of 14 in cluster H

Relative: HIST LUST SANTA CLARA:

Higher Region: SANTA CLARA

Actual: Region Code: 2

84 ft. SCVWD ID: 07S1E07Q08

Oversite Agency: SFRWQCB

Date Listed: 1995-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00

TC05569778.2r Page 131

HIST LUST

S105512872

N/A

EDR ID Number

Map ID MAP FINDINGS Direction

EDR ID Number Distance Elevation Site **EPA ID Number** Database(s)

H65 **SAN JOSE FOUNDRY** HIST CORTESE \$101303937

525 JOHN ST N/A

SSE SAN JOSE, CA 95113 < 1/8

0.116 mi.

614 ft. Site 13 of 14 in cluster H

Relative: HIST CORTESE:

Higher CORTESE Region: Facility County Code: 43 Actual: Reg By: **LTNKA** 86 ft. 43-1189 Reg Id:

BERRYMAN PRODUCTS CERS HAZ WASTE **G66** S113115619

NW 350 N MONTGOMERY ST **HAZNET** N/A < 1/8 SAN JOSE, CA 95110 **CERS**

0.120 mi.

Site 16 of 20 in cluster G 632 ft.

Relative: **CERS HAZ WASTE:**

Lower Site ID: 4304 CERS ID: 10352086 Actual:

Hazardous Waste Generator **CERS** Description: 83 ft.

Evaluation:

Eval General Type: Compliance Evaluation Inspection

03-10-2017 Eval Date:

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility. Currently generating used oil, waste coolant and used oil filters. Waste pickups approximately every 6 months. Reviewed

consolidated manifests. Be sure to inform your waste hauler to update their forms to your current EPA ID number (CAL000348315). G002: Inactive EPA ID Number (DTSC 1358 submitted) G020: Marking of Hazardous Waste (waste coolant) G412: Marking of Used Oil Filters

eMail: afacinc@gmail.com

Eval Division: Santa Clara County Environmental Health

HW Eval Program: Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

03-10-2017 Eval Date: Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility currently storing used oil (55 gallons) and waste

antifreeze (55 gallons) in HMBP quantities. Smaller quantities of new automotive fluids also stored. FrontCounter submittal on 12/23/2016 is

accurate and accepted.

Eval Division: Santa Clara County Environmental Health

Eval Program: **HMRRP CERS Eval Source:**

Coordinates:

Site ID:

Facility Name: ALL FOREIGN AUTO CENTER INC

Env Int Type Code: **HWG** Program ID: 10352086 Coord Name: Not reported

Center of a facility or station. Ref Point Type Desc:

Latitude: 37.336560 Longitude: -121.904120

Direction Distance

Elevation Site Database(s) EPA ID Number

BERRYMAN PRODUCTS (Continued)

S113115619

EDR ID Number

Affiliation:

Affiliation Type Desc: Identification Signer
Entity Name: RODOLFO CORRALES

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

OWNER

Not reported

Not reported

Not reported

Not reported

Affiliation Type Desc: Property Owner

Entity Name: RODOLFO CORRALES

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: United States
Affiliation Zip: Not reported
Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Environmental Contact Entity Name: EnVironmental Contact RODOLFO CORRALES

Entity Title: Not reported

Affiliation Address: 350 N MONTGOMERY ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Legal Owner

Entity Name: ALL FOREIGN AUTO CENTER INC

Entity Title: Not reported

Affiliation Address: 350 N MONTGOMERY ST

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Operator
Entity Name: RODOLFO CORRALES

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation City:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

(408) 286-5404

Affiliation Type Desc: Parent Corporation

Entity Name: ALL FOREIGN AUTO CENTER INC

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

BERRYMAN PRODUCTS (Continued)

S113115619

EDR ID Number

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Document Preparer
Entity Name: RODOLFO CORRALES

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 350 N MONTGOMERY ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95110
Affiliation Phone: Not reported

HAZNET:

envid: \$113115619 Year: 2016

GEPAID: CAL000348315

Contact: RODOLFO CORRALES

Telephone: 4082865404 Mailing Name: Not reported

Mailing Address: 350 N MONTGOMERY ST Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara

Waste Category: Off-specification, aged or surplus organics

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.05

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: S113115619

Year: 2003

Direction Distance

Elevation Site Database(s) EPA ID Number

BERRYMAN PRODUCTS (Continued)

S113115619

EDR ID Number

GEPAID: CAL000233951

Contact: TRUMAN BLANKENSHIP

Telephone: 8004331704 Mailing Name: Not reported

Mailing Address: 3800 E RANDALL MILL RD Mailing City, St, Zip: ARLINGTON, TX 760110000

Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported

Waste Category: Unspecified organic liquid mixture

Disposal Method: Transfer Station

Tons: 1.83
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$113115619

Year: 2001

GEPAID: CAL000233951

Contact: TRUMAN BLANKENSHIP

Telephone: 8004331704 Mailing Name: Not reported

Mailing Address: 3800 E RANDALL MILL RD Mailing City,St,Zip: ARLINGTON, TX 760110000

Gen County: Not reported
TSD EPA ID: AZD980892731
TSD County: Not reported

Waste Category: Unspecified aqueous solution

Disposal Method: Recycler Tons: 1.6

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

CERS TANKS:

 Site ID:
 4304

 CERS ID:
 10352086

CERS Description: Chemical Storage Facilities

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2017 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility. Currently generating used oil, waste coolant and

used oil filters. Waste pickups approximately every 6 months. Reviewed consolidated manifests. Be sure to inform your waste hauler to update their forms to your current EPA ID number (CAL000348315). G002: Inactive EPA ID Number (DTSC 1358 submitted) G020: Marking of Hazardous Waste (waste coolant) G412: Marking of Used Oil Filters

eMail: afacinc@gmail.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2017

Direction Distance Elevation

Elevation Site Database(s) EPA ID Number

BERRYMAN PRODUCTS (Continued)

S113115619

EDR ID Number

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Auto repair facility currently storing used oil (55 gallons) and waste antifreeze (55 gallons) in HMBP quantities. Smaller quantities of new

antifreeze (55 gallons) in HMBP quantities. Smaller quantities of new automotive fluids also stored. FrontCounter submittal on 12/23/2016 is

accurate and accepted.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 4304

Facility Name: ALL FOREIGN AUTO CENTER INC

Env Int Type Code: HWG
Program ID: 10352086
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336560 Longitude: -121.904120

Affiliation:

Affiliation Type Desc: Identification Signer
Entity Name: RODOLFO CORRALES

Entity Title: OWNER

Affiliation Address: Not reported

Affiliation City: Not reported

Affiliation State: Not reported

Affiliation Country: Not reported

Affiliation Zip: Not reported

Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner

Entity Name: RODOLFO CORRALES

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: United States
Affiliation Zip: Not reported
Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Environmental Contact Entity Name: RODOLFO CORRALES

Entity Title: Not reported

Affiliation Address: 350 N MONTGOMERY ST

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Legal Owner

Entity Name: ALL FOREIGN AUTO CENTER INC

Entity Title: Not reported

Affiliation Address: 350 N MONTGOMERY ST

Affiliation City: SAN JOSE

Direction Distance Elevation

vation Site Database(s) EPA ID Number

BERRYMAN PRODUCTS (Continued)

S113115619

EDR ID Number

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110
Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Operator

Entity Name: RODOLFO CORRALES

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 286-5404

Affiliation Type Desc: Parent Corporation

Entity Name: ALL FOREIGN AUTO CENTER INC

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Document Preparer Entity Name: RODOLFO CORRALES

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

San Jose

CA

Not reported

95112-2716

(408) 918-3400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 350 N MONTGOMERY ST

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

G67 AC LABEL CO/BERRYMAN PRODUCTS CPS-SLIC S106235104

N/A

S105512850

N/A

HIST LUST

EMI

350 NORTH MONTGOMERY ST SAN JOSE, CA < 1/8

0.120 mi.

NW

Site 17 of 20 in cluster G 632 ft.

Relative: SLIC REG 2: Lower Region:

Facility ID: SL18217597 Actual:

Facility Status: Post remedial action monitoring 83 ft.

Date Closed: Not reported Local Case #: Not reported How Discovered: RPR Leak Cause: Not reported Leak Source: Not reported Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: Not reported Date Preliminary Site Assessment Began: Not reported Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

G68 USA TOUCH-UP SERVICE NW 350 N MONTGOMERY ST < 1/8 SAN JOSE, CA 95110

0.120 mi.

632 ft. Site 18 of 20 in cluster G

Relative: HIST LUST SANTA CLARA:

Lower SANTA CLARA Region:

Air District Name:

Region Code: 2 Actual:

SCVWD ID: 07S1E07K01 83 ft.

Oversite Agency: SFRWQCB

1988-01-01 00:00:00 Date Listed: Closed Date: Not reported

EMI:

2006 Year: County Code: 43 Air Basin: SF Facility ID: 16053 Air District Name: ВА SIC Code: 7532

BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 1.503 Reactive Organic Gases Tons/Yr: 1.27895

Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2007 Year: County Code: 43 Air Basin: SF Facility ID: 16053

MAP FINDINGS Map ID Direction

Distance Elevation Site

Database(s) **EPA ID Number**

USA TOUCH-UP SERVICE (Continued)

S105512850

EDR ID Number

Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 1.503 Reactive Organic Gases Tons/Yr: 1.27895 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2008 Year: County Code: 43 Air Basin: SF Facility ID: 16053 Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 1.936 Reactive Organic Gases Tons/Yr: 1.6542562

Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2009 Year: County Code: 43 Air Basin: SF Facility ID: 16053 Air District Name: BA 7532 SIC Code:

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 1.167

1.077789799999999 Reactive Organic Gases Tons/Yr:

Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: O Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2010 County Code: 43 Air Basin: SF Facility ID: 16053 Air District Name: ВА 7532 SIC Code:

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 1.167

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

USA TOUCH-UP SERVICE (Continued)

S105512850

Reactive Organic Gases Tons/Yr: 1.0777897999999999900
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2011

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 16053

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:
Reactive Organic Gases Tons/Yr:
Carbon Monoxide Emissions Tons/Yr:

BAY AREA AQMD
Not reported
Not reported
1.167
1.0777898
0

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2012

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 16053

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:

Not reported
Not reported
1.167
1.0777898

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2013

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 16053

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:

Not reported
Not reported
1.167
Reactive Organic Gases Tons/Yr:
1.0777898

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Direction Distance

Elevation Site Database(s) EPA ID Number

G69 SCR-A C LABEL/BERRYMAN PR CPS-SLIC S105026266

NW 350 MONTGOMERY DEED N/A < 1/8 SAN JOSE, CA 95110 Cortese

< 1/8 SAN JOSE, CA 95110 0.120 mi.

0.120 mi.
632 ft. Site 19 of 20 in cluster G HIST CORTESE
CIWQS

Relative: Lower

Actual: CPS-SLIC: 83 ft. Region: STATE

Facility Status: Completed - Case Closed

 Status Date:
 07/01/2002

 Global Id:
 SL18217597

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported
Latitude: 37.3364596268248
Longitude: -121.904273246696
Case Type: Cleanup Program Site

Case Worker: MBR
Local Agency: Not reported
RB Case Number: 43S0201
File Location: Regional Board

Potential Media Affected: Aquifer used for drinking water supply, Soil, Soil Vapor

Potential Contaminants of Concern: Other Acid or Corrosive, 1,1,1-Trichloroethane (TCA), Acetone,

Benzene, Other Chlorinated Hydrocarbons, Other Solvent or Non-Petroleum Hydrocarbon, Tetrachloroethylene (PCE), Toluene, Trichloroethylene (TCE), Xylene, Other Petroleum, Waste Oil / Motor /

Hydraulic / Lubricating

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

DEED:

Envirostor ID: SL18217597
Area: Not reported
Sub Area: Not reported

Site Type: SLIC

Status: COMPLETED - CASE CLOSED

Agency: SWRCB
Covenant Uploaded: Y
Deed Date(s): 11/18/2013

File Name: Geotracker Land Use/Deed Restrictions

CORTESE:

CORTESE Region: Envirostor Id: Not reported Site/Facility Type: Not reported Cleanup Status: Not reported Status Date: Not reported Site Code: Not reported Latitude: Not reported Longitude: Not reported Owner: Not reported Not reported Enf Type: Swat R: Not reported Flag: CORTESE Order No: Not reported Waste Discharge System No: Not reported **EDR ID Number**

CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

EDR ID Number

Effective Date: Not reported Region 2: 2
WID Id: 2 438235N01
Solid Waste Id No: Not reported

Waste Management Uit Name: Not reported
File Name: Cease Desist Orders & Cleanup Abatement Orders

ENF:

Region: 2 Facility Id: 203980

Agency Name: AC Label Company

Place Type: Facility

Place Subtype: Groundwater Cleanup Site

Facility Type: Industrial

Agency Type: Privately-Owned Business

Of Agencies:

 Place Latitude:
 37.336269

 Place Longitude:
 -121.904327

 SIC Code 1:
 2752

SIC Desc 1: Commercial Printing, Lithographic

SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Not reported Complexity: Not reported Pretreatment: Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported UNREGS Program: Program Category1: **UNREGS** Program Category2: **UNREGS**

Of Programs: 1
WDID: 2 438235N01
Reg Measure Id: 162328
Reg Measure Type: Unregulated

Region: 2

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Reclamation: Not reported Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported Status: Never Active

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported Not reported WDR Review - No Action Required: WDR Review - Pending: Not reported WDR Review - Planned: Not reported

Status Enrollee: Ν Individual/General:

Fee Code: Not reported Direction/Voice: Passive 222947 Enforcement Id(EID): Region: Order / Resolution Number: 95-111

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 05/24/1995 Adoption/Issuance Date: Not reported Achieve Date: Not reported Termination Date: Not reported ACL Issuance Date: Not reported **EPL Issuance Date:** Not reported Status: Active

Title: Enforcement - 2 438235N01

Description: SCR-Program: **UNREGS** Latest Milestone Completion Date: Not reported

Of Programs1: Total Assessment Amount: 0 Initial Assessed Amount: 0 Liability \$ Amount: 0 Project \$ Amount: 0 Liability \$ Paid: 0 Project \$ Completed: n Total \$ Paid/Completed Amount: 0

Region: 2 Facility Id: 203980

Agency Name: **AC Label Company**

Place Type: Facility

Place Subtype: Groundwater Cleanup Site

Facility Type: Industrial

Agency Type: **Privately-Owned Business**

Of Agencies:

Place Latitude: 37.336269 Place Longitude: -121.904327

SIC Code 1: 2752

SIC Desc 1: Commercial Printing, Lithographic

SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Complexity: Not reported Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported UNREGS Program: Program Category1: **UNREGS** Program Category2: **UNREGS** # Of Programs:

WDID: 2 438235N01 Reg Measure Id: 162328 Unregulated Reg Measure Type:

Region:

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Not reported Npdes Type: Reclamation: Not reported Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported Status: **Never Active** Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported Not reported WDR Review - Amend: WDR Review - Revise/Renew: Not reported Not reported WDR Review - Rescind: WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported Not reported WDR Review - Planned:

Status Enrollee: Ν Individual/General:

Fee Code: Not reported Direction/Voice: **Passive** 220078 Enforcement Id(EID): Region: Order / Resolution Number: 87-118

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 08/25/1987 Adoption/Issuance Date: Not reported Achieve Date: Not reported Termination Date: Not reported Not reported ACL Issuance Date: **EPL Issuance Date:** Not reported Status: Historical

Title: Enforcement - 2 438235N01

Description: **REQUIRES SITE INVESTIGATION & CLEANUP**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

Program: **UNREGS** Latest Milestone Completion Date: Not reported

Of Programs1: **Total Assessment Amount:** 0 Initial Assessed Amount: 0 Liability \$ Amount: 0 Project \$ Amount: 0 Liability \$ Paid: 0 Project \$ Completed: 0 Total \$ Paid/Completed Amount: 0

2 Region: Facility Id: 203980

Agency Name: AC Label Company

Place Type: Facility

Place Subtype: Groundwater Cleanup Site

Facility Type: Industrial

Agency Type: **Privately-Owned Business**

Of Agencies:

37.336269 Place Latitude: Place Longitude: -121.904327 SIC Code 1: 2752

SIC Desc 1: Commercial Printing, Lithographic

SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported Not reported NAICS Desc 2: NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Not reported Design Flow: Threat To Water Quality: Not reported Complexity: Not reported Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported **UNREGS** Program: Program Category1: **UNREGS** Program Category2: **UNREGS**

Of Programs:

Reclamation:

Dredge Fill Fee:

WDID: 2 438235N01 Reg Measure Id: 162328 Reg Measure Type: Unregulated Region: Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported

Not reported

Not reported

TC05569778.2r Page 145

Direction Distance

Elevation Site Database(s) EPA ID Number

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

EDR ID Number

301H: Not reported Application Fee Amt Received: Not reported Status: **Never Active** Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Not reported Termination Date: Not reported WDR Review - Amend: WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned:

Status Enrollee: N Individual/General: I

Fee Code:

Direction/Voice:

Enforcement Id(EID):

Region:

Order / Resolution Number:

Not reported
Passive
219971
29701
89-089

Enforcement Action Type: Admin Civil Liability

Effective Date: 09/20/1989

Adoption/Issuance Date: Not reported

Achieve Date: 1989-10-20

Termination Date: Not reported

ACL Issuance Date: Not reported

EPL Issuance Date: Not reported

Status: Historical

Title: Enforcement - 2 438235N01

Description: REFERRED TO ATT GEN - FAILURE TO SUBMIT REPORTS ON INTERIM

REMEDIAL ACTIONS. VIOLATED CAO 87-118

Program: UNREGS Latest Milestone Completion Date: 1989-10-20

Of Programs1:

Total Assessment Amount:

Initial Assessed Amount:

Liability \$ Amount:

Project \$ Amount:

Liability \$ Paid:

Project \$ Completed:

Total \$ Paid/Completed Amount:

80000

80000

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: WBC&D
Reg Id: 2 438235N01

CIWQS:

Agency: AC Label Company

Agency Address: 47690 Westinghouse Drive, Fremont, CA 94539

Place/Project Type: Groundwater Cleanup Site

SIC/NAICS: 2752 Region: 2

Program: NPDNONMUNIPRCS

Regulatory Measure Status: Historical

Direction Distance

Elevation Site Database(s) EPA ID Number

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

EDR ID Number

Regulatory Measure Type: NPDES Permit Order Number: 97-00801 WDID: 2 438235002 NPDES Number: CAG912003 Adoption Date: 01/15/1997 Effective Date: 01/15/1997 Termination Date: Not reported Expiration/Review Date: Not reported Design Flow: 0.001 Major/Minor: Major, Minor

Complexity: B
TTWQ: 2
Enforcement Actions within 5 years: 0
Violations within 5 years: 0

Latitude: 37.336269 Longitude: -121.904327

CERS TANKS:

 Site ID:
 244817

 CERS ID:
 SL18217597

CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: MICHAEL ROCHETTE - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY STREET, SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Site ID: 348528 CERS ID: 203980

CERS Description: NPDES Wastewater and Stormwater

Enforcement Action:

Site ID: 348528

Site Name: A C Label/Berryman PRD Site Address: 350 MONTGOMERY

 Site City:
 SAN JOSE

 Site Zip:
 95110

 Enf Action Date:
 05-24-1995

Enf Action Type: Clean-up and Abatement Order Enf Action Description: Clean-up and Abatement Order

Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 348528

Site Name: A C Label/Berryman PRD Site Address: 350 MONTGOMERY

 Site City:
 SAN JOSE

 Site Zip:
 95110

 Enf Action Date:
 08-25-1987

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCR-A C LABEL/BERRYMAN PR (Continued)

S105026266

HIST UST

Enf Action Type: Clean-up and Abatement Order Enf Action Description: Clean-up and Abatement Order

Enf Action Notes: Not reported Enf Action Division: Water Boards **UNSPEC** Enf Action Program: **CIWQS** Enf Action Source:

Site ID: 348528

Site Name: A C Label/Berryman PRD Site Address: 350 MONTGOMERY

Site City: SAN JOSE Site Zip: 95110 Enf Action Date: 09-20-1989

Enf Action Type: Administrative Enforcement with Penality

Enf Action Description: Administrative Enforcement with Civil Liability (Penality)

Enf Action Notes: Not reported Enf Action Division: Water Boards **UNSPEC** Enf Action Program: Enf Action Source: **CIWQS**

G70 **AC LABEL CO SEMS-ARCHIVE** 1000275747 **350 NO MONTGOMERY** NW LUST CAD981693492

< 1/8 SAN JOSE, CA 95110

0.120 mi. RCRA NonGen / NLR 632 ft. Site 20 of 20 in cluster G **FINDS ECHO**

Relative: **CUPA Listings** Lower EMI

Actual: **HAZNET**

83 ft. **SAN JOSE HAZMAT**

SEMS Archive:

0902512 Site ID: EPA ID: CAD981693492

Cong District: 10 FIPS Code: 06085 FF: Ν

NPL: Not on the NPL

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Latitude: 37.331667 Longitude: -121.878333

SEMS Archive Detail:

Region: 09

Site ID: 0902512 EPA ID: CAD981693492 Site Name: AC LABEL CO

NPL: Ν FF: Ν OU: 00 Action Code: VS Action Name: ARCH SITE

SEQ:

Start Date: Not reported Finish Date: 1991-10-11 04:00:00 Qual: Not reported Current Action Lead: EPA Perf In-Hse

Region:

Site ID:

EPA ID:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

09

AC LABEL CO (Continued)

0902512 CAD981693492 1000275747

Site Name: AC LABEL CO NPL: Ν FF: Ν OU: 00 Action Code: РΑ Action Name: PΑ SEQ:

Start Date: 1987-02-01 05:00:00 Finish Date: 1987-02-01 05:00:00

Qual:

Current Action Lead: EPA Perf

09 Region: Site ID: 0902512 EPA ID: CAD981693492 Site Name: AC LABEL CO

NPL: Ν FF: Ν OU: 00 Action Code: SI Action Name: SI SEQ:

Not reported Start Date: Finish Date: 1987-07-01 04:00:00

Qual: **Current Action Lead: EPA Perf**

Region: 09 Site ID: 0902512 EPA ID: CAD981693492 Site Name: AC LABEL CO

NPL: FF: Ν OU: 00 Action Code: SI Action Name: SI SEQ: 2

Start Date: Not reported Finish Date: 1991-10-11 04:00:00

Qual: Ν

Current Action Lead: **EPA Perf**

Region: 09 Site ID: 0902512 EPA ID: CAD981693492 AC LABEL CO Site Name:

NPL: Ν FF: Ν OU: 00 Action Code: DS **DISCVRY** Action Name: SEQ:

Start Date: 1987-01-01 05:00:00 Finish Date: 1987-01-01 05:00:00

Direction Distance

Elevation Site Database(s) EPA ID Number

AC LABEL CO (Continued) 1000275747

Qual: Not reported Current Action Lead: Other

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07\$1E07K01F Date Closed: Not reported EDR Link ID: 07\$1E07K01F

HIST UST:

File Number: Not reported URL: Not reported Region: STATE Facility ID: 00000000987

Facility Type: Other

Other Type: LABEL COMPANY
Contact Name: Not reported
Telephone: 4089984848

Owner Name: LEWIS & JAMES DIBONA & RICHARD

Owner Address: 350 NO MONTGOMERY ST.
Owner City,St,Zip: SAN JOSE, CA 95110

Total Tanks: 0002

Tank Num: 001 Container Num: 350-1 Year Installed: Not reported 00006000 Tank Capacity: Tank Used for: Not reported Type of Fuel: Not reported Not reported Container Construction Thickness: Leak Detection: None

Tank Num: 002 Container Num: 350-2 Year Installed: Not reported 00006000 Tank Capacity: Not reported Tank Used for: Type of Fuel: Not reported Container Construction Thickness: Not reported Leak Detection: None

RCRA NonGen / NLR:

Date form received by agency: 12/29/1981 Facility name: AC LABEL CO

Facility address: 350 NO MONTGOMERY

SAN JOSE, CA 95110

EPA ID: CAD981693492

Mailing address: 350 NO MONTGOMERY ST

SAN JOSE, CA 95110

Contact: ENVIRONMENTAL MANAGER
Contact address: 350 NO MONTGOMERY

SAN JOSE, CA 95110

Contact country: US

Contact telephone: 408-998-4848 Contact email: Not reported **EDR ID Number**

Distance Elevation

Site Database(s) EPA ID Number

AC LABEL CO (Continued)

1000275747

EDR ID Number

EPA Region: 09

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: LEWIS DI BONA
Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No No Furnace exemption: Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110001197204

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

Direction Distance

Elevation Site Database(s) EPA ID Number

AC LABEL CO (Continued) 1000275747

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000275747 Registry ID: 110001197204

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110001197204

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.336226

 Longitude:
 -121.904026

 Record ID:
 PR0364341

 Facility ID:
 FA0251076

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.336226

 Longitude:
 -121.904026

 Record ID:
 PR0396712

 Facility ID:
 FA0251076

EMI:

 Year:
 1990

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5418

 Air District Name:
 BA

 SIC Code:
 4953

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

HAZNET:

envid: 1000275747 Year: 1996

GEPAID: CAD981693492
Contact: Not reported
Telephone: 0000000000

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AC LABEL CO (Continued)

1000275747

Mailing Name: Not reported

350 NO MONTGOMERY ST Mailing Address: SAN JOSE, CA 951100000 Mailing City, St, Zip:

Gen County: Not reported TSD EPA ID: WAD980978142 TSD County: Not reported

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

Disposal Method: Recycler 3.6487 Tons: Cat Decode: Not reported Method Decode: Not reported Santa Clara Facility County:

envid: 1000275747 Year: 1995

GEPAID: CAD981693492 Contact: Not reported Telephone: 000000000 Mailing Name: Not reported

350 NO MONTGOMERY ST Mailing Address: Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Not reported TSD EPA ID: WAD980978142 TSD County: Not reported

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

Disposal Method: Recycler Tons: 1.5220 Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000275747 Year: 1995

GEPAID: CAD981693492 Not reported Contact: 000000000 Telephone: Not reported Mailing Name:

Mailing Address: 350 NO MONTGOMERY ST Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Not reported TSD EPA ID: WAD980978142 TSD County: Not reported

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

Disposal Method: Not reported Tons: 1.1467 Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

1000275747 envid: Year: 1994 GEPAID: CAD981693492 Contact: Not reported Telephone: 000000000 Mailing Name: Not reported

Mailing Address: 350 NO MONTGOMERY ST Mailing City, St, Zip: SAN JOSE, CA 951100000

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AC LABEL CO (Continued)

1000275747

Gen County: Not reported CAD059494310 TSD EPA ID: Not reported TSD County:

Waste Category: Unspecified organic liquid mixture

Disposal Method: Disposal, Other

.2293 Tons:

Cat Decode: Not reported Not reported Method Decode: Santa Clara Facility County:

1000275747 envid: Year: 1993

CAD981693492 GEPAID: Contact: Not reported 000000000 Telephone: Mailing Name: Not reported

Mailing Address: 350 NO MONTGOMERY ST Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Not reported CAD009452657 TSD EPA ID: TSD County: Not reported

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

Disposal Method: Recycler Tons: 0.2293 Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

> Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 401905 Class: Auto Repair

171 LINCOLN PROPERTY S103473037 LUST NNW **469 HOWARD HIST LUST** N/A SAN JOSE, CA 95112 < 1/8 **HIST CORTESE** 0.121 mi. **CERS**

638 ft. Site 6 of 8 in cluster I

LUST: Relative:

Lower SANTA CLARA COUNTY LOP Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501646 83 ft.

T0608501646 Global Id: Latitude: 37.3378925047634 -121.903288364411 Longitude:

Status: Completed - Case Closed 02/26/1993 Status Date: Case Worker: UST RB Case Number: Not reported

SANTA CLARA COUNTY LOP Local Agency:

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Direction
Distance

Elevation Site Database(s) EPA ID Number

LINCOLN PROPERTY (Continued)

S103473037

EDR ID Number

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608501646

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501646

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608501646

 Action Type:
 Other

 Date:
 12/02/1986

 Action:
 Leak Reported

Global Id: T0608501646
Action Type: ENFORCEMENT
Date: 10/26/1993

Action: Closure/No Further Action Letter

 Global Id:
 T0608501646

 Action Type:
 ENFORCEMENT

 Date:
 02/26/1987

Action: Notice of Responsibility - #39944

Global Id: T0608501646
Action Type: RESPONSE
Date: 10/21/1993

Action: Other Report / Document

Global Id: T0608501646
Action Type: ENFORCEMENT
Date: 11/08/1993

Action: Closure/No Further Action Letter - #43-1769

LUST:

Global Id: T0608501646

Status: Completed - Case Closed

Status Date: 02/26/1993

Global Id: T0608501646

Status: Open - Case Begin Date

Status Date: 12/02/1986

Direction
Distance

Elevation Site Database(s) EPA ID Number

LINCOLN PROPERTY (Continued)

S103473037

EDR ID Number

Global Id: T0608501646

Status: Open - Site Assessment

Status Date: 12/02/1986

Global Id: T0608501646

Status: Open - Verification Monitoring

Status Date: 01/22/1987

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed 07S1E07K02f Case Number: How Discovered: Not reported Not reported Leak Cause: Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 12/2/1986
Pollution Characterization Began: 12/2/1986
Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: 1/22/1987

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07K02F

 Date Closed:
 02/26/1993

 EDR Link ID:
 07S1E07K02F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07K02 Oversite Agency: SCVWD

Date Listed: 1987-01-01 00:00:00 Closed Date: 1993-02-26 00:00:00

HIST CORTESE:

Region: CORTESE Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1705

CERS TANKS:

Site ID: 196470 CERS ID: T0608501646

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

LINCOLN PROPERTY (Continued)

S103473037

S113137414

N/A

HAZNET

SAN JOSE HAZMAT

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: **OAKLAND** Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

172 **USA TOUCH-UP AUTO BODY**

NNW 351 N AUTUMN ST < 1/8 SAN JOSE, CA 95110

0.124 mi.

655 ft. Site 7 of 8 in cluster I

Relative: HAZNET:

Lower S113137414 envid: Year: 2013

Actual: GEPAID: CAL000294572 83 ft.

NAM TRAN OWNER Contact:

Telephone: 4082920808 Mailing Name: Not reported Mailing Address: 351 N AUTUMN ST

Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara TSD EPA ID: CAD008252405 TSD County: Los Angeles Waste Category: Not reported

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

0.2502 Tons: Cat Decode: Not reported Method Decode: Not reported Facility County: Not reported

envid: S113137414 Year: 2013

GEPAID: CAL000294572 NAM TRAN OWNER Contact:

Telephone: 4082920808 Mailing Name: Not reported Mailing Address: 351 N AUTUMN ST Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara TSD EPA ID: CAD008252405 TSD County: Los Angeles Waste Category: Not reported

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

Tons: 0.108 Cat Decode: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

USA TOUCH-UP AUTO BODY (Continued)

S113137414

EDR ID Number

Method Decode: Not reported Facility County: Not reported

envid: \$113137414 Year: 2012

GEPAID: CAL000294572
Contact: NAM TRAN OWNER
Telephone: 4082920808
Mailing Name: Not reported
Mailing Address: 351 N AUTUMN ST

Mailing Address: 351 N AUTUMN ST
Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD008252405
TSD County: Los Angeles
Waste Category: Not reported

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

Tons: 0.2502
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$113137414

Year: 2012

GEPAID: CAL000294572 Contact: NAM TRAN OWNER

Telephone: 4082920808
Mailing Name: Not reported
Mailing Address: 351 N AUTUMN ST

Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD008252405
TSD County: Los Angeles
Waste Category: Not reported
Disposal Method: Solvents Recovery

Tons: 0.1404
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: S113137414 Year: 2011

GEPAID: CAL000294572 Contact: NAM TRAN OWNER

Telephone: 4082920808
Mailing Name: Not reported
Mailing Address: 351 N AUTUM

Mailing Address: 351 N AUTUMN ST Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Not reported
TSD EPA ID: CAD008252405
TSD County: Not reported

Waste Category: Unspecified solvent mixture

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

Tons: 0.09

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

USA TOUCH-UP AUTO BODY (Continued)

S113137414

Click this hyperlink while viewing on your computer to access 15 additional CA_HAZNET: record(s) in the EDR Site Report.

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 410095

Class: Auto Body and Paint

173 IA 062613 USA TOUCH-UP AUTO BODY INC **CUPA Listings** S121473281

N/A

NNW 351 N AUTUMN ST SAN JOSE, CA 95110 < 1/8

0.124 mi.

655 ft. Site 8 of 8 in cluster I CUPA SANTA CLARA: Relative:

Lower Region: SANTA CLARA

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 83 ft.

> Latitude: 37.336927 Longitude: -121.903604 Record ID: PR0378297 Facility ID: FA0258377

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.336927 Longitude: -121.903604 Record ID: PR0397016 Facility ID: FA0258377

H74 HIST CORTESE S105026258 **MANADA TILE**

SE **517 JOHN ST**

< 1/8 SAN JOSE, CA 95110

0.124 mi.

657 ft. Site 14 of 14 in cluster H

HIST CORTESE: Relative:

Lower Region: CORTESE Facility County Code: Actual: Reg By: **LTNKA** 83 ft. 43-0853 Reg Id:

J75 SAN JOSE ARENA GEISLER PARCEL LUST S103473075 **CERS** N/A

SSE **80 MONTGOMERY ST N**

1/8-1/4 **SAN JOSE, CA 95113**

0.139 mi.

735 ft. Site 2 of 2 in cluster J

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501982 87 ft.

Global Id: T0608501982 N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA GEISLER PARCEL (Continued)

S103473075

Latitude: 37.3319488 Longitude: -121.9012454

Status: Completed - Case Closed

Status Date: 04/09/1997 Case Worker: UUU RB Case Number: 43-2158

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608501982 Global Id:

Regional Board Caseworker Contact Type: Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND Email: Not reported Phone Number: Not reported

Global Id: T0608501982

Local Agency Caseworker Contact Type: Contact Name: UST CASE WORKER SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608501982 Action Type: Other 04/10/1997 Date: Action: Leak Reported

T0608501982 Global Id: **RESPONSE** Action Type: Date: 01/01/1989

Action: Other Report / Document

Global Id: T0608501982 **RESPONSE** Action Type: Date: 01/01/1989

Action: Other Report / Document

Global Id: T0608501982 Action Type: Other Date: 04/10/1997 Action: Leak Discovery

Global Id: T0608501982 Action Type: **ENFORCEMENT** Date: 04/09/1997

Action: Closure/No Further Action Letter

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA GEISLER PARCEL (Continued)

S103473075

EDR ID Number

 Global Id:
 T0608501982

 Action Type:
 Other

 Date:
 04/10/1997

 Action:
 Leak Stopped

LUST:

Global Id: T0608501982

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608501982

Status: Open - Case Begin Date

Status Date: 04/09/1997

LUST REG 2:

Region: 2

Facility Id: 43-2158
Facility Status: Case Closed
Case Number: 07S1E07Q14
How Discovered: Tank Closure
Leak Cause: UNK
Leak Source: UNK

Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

CERS TANKS:

 Site ID:
 217410

 CERS ID:
 T0608501982

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

SAN JOSE ARENA GEISLER PARCEL (Continued)

Affiliation Phone: Not reported

K76 CERULEAN GLOBAL SERVICES AST A100418652

SW 250 STOCKTON AVE N/A

1/8-1/4 SAN JOSE, CA 95126

0.140 mi.

741 ft. Site 1 of 5 in cluster K

Relative: AST:

HigherCertified Unified Program Agencies:Not reportedActual:Owner:Robert Taylor94 ft.Total Gallons:Not reportedCERSID:10636273Facility ID:Not reported

Business Name: Cerulean Global Services

Phone: 6506192992
Fax: Not reported
Mailing Address: 250 Stockton Ave

Mailing Address City:

Mailing Address State:

CA

Mailing Address Zip Code:

Operator Name:

Operator Phone:

Owner Phone:

Owner Mail Address:

San Jose

CA

Men Choi

6506192992

2135421812

Owner Mail Address:

250 Stockton AVe

Owner State:
Owner Zip Code:
Owner Country:
Property Owner Name:
Property Owner Phone:
Property Owner Mailing Address:
Property Owner City:
CA
95126
United States
Robert Taylor
2135421812
250 Stockton Ave
San Jose

Property Owner Stat : CA
Property Owner Zip Code: 95126
Property Owner Country: United States
EPAID: Not reported

SAN JOSE UNIFIED SCHOOL DISTRICT LUST \$101304085

SW 250 STOCKTON AVE CPS-SLIC N/A

1/8-1/4 SAN JOSE, CA 95126 ENF 0.140 mi. HIST CORTESE

741 ft. Site 2 of 5 in cluster K CERS

Relative: LUST:

K77

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

94 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501192

 Global Id:
 T0608501192

 Latitude:
 37.333625

 Longitude:
 -121.9045

Status: Completed - Case Closed

Status Date: 12/08/1998
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

S103473075

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE UNIFIED SCHOOL DISTRICT (Continued)

S101304085

File Location: All Files are on GeoTracker or in the Local Agency Database

Not reported Local Case Number:

Other Groundwater (uses other than drinking water) Potential Media Affect: Potential Contaminants of Concern: Stoddard solvent / Mineral Spriits / Distillates

Site History: Not reported

LUST:

Global Id: T0608501192

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND Email: Not reported Phone Number: Not reported

Global Id: T0608501192

Contact Type: Local Agency Caseworker UST CASE WORKER Contact Name: SANTA CLARA COUNTY LOP Organization Name: 1555 Berger Drive, Suite 300 Address:

SAN JOSE City: Email: Not reported Phone Number: 4089183400

LUST:

Global Id: T0608501192 Action Type: Other 01/01/1990 Date: Action: Leak Reported

Global Id: T0608501192 Action Type: **RESPONSE** Date: 12/08/1998

Other Report / Document Action:

Global Id: T0608501192 Action Type: REMEDIATION Date: 02/04/1997 Action: Excavation

Global Id: T0608501192 Action Type: **ENFORCEMENT** Date: 05/27/1997

Action: Staff Letter - #26836

Global Id: T0608501192 Action Type: **ENFORCEMENT** 12/08/1998 Date:

Action: Closure/No Further Action Letter

Global Id: T0608501192 **RESPONSE** Action Type: 07/15/1997 Date:

Action: Monitoring Report - Quarterly

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE UNIFIED SCHOOL DISTRICT (Continued)

S101304085

LUST:

T0608501192 Global Id:

Completed - Case Closed Status:

Status Date: 12/08/1998

T0608501192 Global Id:

Status: Open - Case Begin Date

01/01/1990 Status Date:

Global Id: T0608501192

Status: Open - Site Assessment

Status Date: 02/04/1994

LUST SANTA CLARA:

SANTA CLARA Region: SCVWD ID: 07S1E07P01F Date Closed: 12/08/1998 07S1E07P01F EDR Link ID:

CPS-SLIC:

Region: STATE

Facility Status: Completed - Case Closed

Status Date: 12/09/2014 Global Id: T10000005262

SANTA CLARA COUNTY LOP Lead Agency:

Lead Agency Case Number: 07S1E07P04s Latitude: 37.333584 Longitude: -121.904686

Case Type: Cleanup Program Site

Case Worker: Not reported Local Agency: Not reported RB Case Number: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database Potential Media Affected: Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern: Diesel

Site History: Spill of 100 gallons of diesel while filling tank for emergency

generator in 2000. Report of release not provided. Some soil was excavated, but no further assessment was conducted. 2014 - soil and groundwater sampling conducted to confirm results of soil excavation

work and possible impact to groundwater at the site.

Click here to access the California GeoTracker records for this facility:

ENF:

Region: Facility Id: 271080 Agency Name: Verio Place Type: Facility Place Subtype: Not reported Facility Type: All other facilities

Agency Type: **Privately-Owned Business**

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported

Direction Distance Elevation

EDR ID Number Site Database(s) **EPA ID Number**

SAN JOSE UNIFIED SCHOOL DISTRICT (Continued)

S101304085

SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Not reported Complexity: Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported Program: AGT Program Category1: **TANKS** Program Category2: **TANKS** # Of Programs:

WDID: 2 43AGT253U Reg Measure Id: 169359 Reg Measure Type: Unregulated

Region:

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Not reported Reclamation: Not reported Dredge Fill Fee: 301H: Not reported Application Fee Amt Received: Not reported Status: **Never Active** Status Date: 02/20/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned: Not reported Status Enrollee: Ν

Individual/General:

Fee Code: Not reported Direction/Voice: **Passive** Enforcement Id(EID): 238117 Region:

Order / Resolution Number: UNKNOWN Enforcement Action Type: 13267 Letter

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE UNIFIED SCHOOL DISTRICT (Continued)

S101304085

Effective Date: 01/30/2001 Adoption/Issuance Date: Not reported Achieve Date: Not reported Termination Date: Not reported ACL Issuance Date: Not reported Not reported **EPL Issuance Date:** Active Status:

Title: Enforcement - 2 43AGT253U

Description: NOV for failure to register AGT as required by APSA

Program: **AGT**

Latest Milestone Completion Date: Not reported

Of Programs1: **Total Assessment Amount:** 0 Initial Assessed Amount: 0 Liability \$ Amount: 0 Project \$ Amount: 0 Liability \$ Paid: 0 Project \$ Completed: 0 Total \$ Paid/Completed Amount:

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-1206

CERS TANKS:

Site ID: 202315 CERS ID: T0608501192

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Local Agency Caseworker Affiliation Type Desc:

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Site ID: 218647 CERS ID: T10000005262 **CERS** Description: Cleanup Program Site

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE UNIFIED SCHOOL DISTRICT (Continued)

S101304085

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

1515 CLAY ST SUITE 1400 Affiliation Address:

OAKLAND Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

K78 SAN JOSE UNIFIED SCHOOL DISTRI

LUST S104571602 **HIST LUST 250 STOCKTON AVE** N/A

SW 1/8-1/4 **SAN JOSE, CA 95126 SWEEPS UST**

0.140 mi.

741 ft. Site 3 of 5 in cluster K

Relative: LUST REG 2:

Higher Region: 2

Facility Id: Not reported Actual: Facility Status: Case Closed 94 ft. 07S1E07P01f Case Number: How Discovered: Not reported

Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 2/4/1994 Pollution Characterization Began: 2/4/1994 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07P01 Oversite Agency: SCVWD

Date Listed: 1991-03-21 00:00:00 Closed Date: 1998-12-08 00:00:00

SWEEPS UST:

Status: Active Comp Number: 400616

Number: 9

Board Of Equalization: Not reported Referral Date: 09-30-92 09-08-92 Action Date: Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-400616-000001

Tank Status: Capacity: 5000 Active Date: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE UNIFIED SCHOOL DISTRI (Continued)

S104571602

Tank Use: M.V. FUEL

STG:

Content: **REG UNLEADED**

Number Of Tanks:

Active Comp Number: 400616 Number:

Board Of Equalization: Not reported Referral Date: 09-30-92 09-08-92 Action Date: Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-400616-000002

Tank Status: Capacity: 1000 Active Date: Not reported **PETROLEUM** Tank Use:

STG:

Not reported Content: Number Of Tanks: Not reported

K79 **CERULEAN GLOBAL SERVICES CERS TANKS** S121765045 **CERS** N/A

SW 250 STOCKTON AVE 1/8-1/4 SAN JOSE, CA 95126

0.140 mi.

741 ft. Site 4 of 5 in cluster K

CERS TANKS: Relative:

Higher Site ID: 354674 CERS ID: 10636273 Actual:

CERS Description: Aboveground Petroleum Storage 94 ft.

Violations:

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Facility failed to submit an accurate hazardous materials inventory

including the Uniterruptible Power Supply (UPS) batteries, 275 gallon diesel generator day tank and FM-200 fire suppression material. Update

the inventory and resubmit.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HMRRP** Violation Source: **CERS**

Site ID: 354674

Cerulean Global Services Site Name:

Violation Date: 06-13-2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95. Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit the Business Activities

Page and/or Business Owner Operator Identification Page.

The environmental contact listed in the submittal on 11/2/2017 no Violation Notes:

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

longer works for the company. Update the Business Owner/Operator

Identification page with current information and resubmit.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to conduct spill prevention briefing for oil-handling

personnel at least once a year to assure adequate understanding of the

SPCC Plan.

Violation Notes: Facility did not perform the annual SPCC briefing for employees.

Ensure the briefing is done annually and is documented and the

documentation retained for at least three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25505.1 - California Health and Safety Code, Chapter 6.95,

Section(s) 25505.1

Violation Description: Failure to provide a copy of the business plan to the owner or the

owner's agent within five working days after receiving a request for a

copy from the owner or the owner's agent.

Violation Notes: Facility failed to notify the property owner in writing that they are

subject to and in compliance with HMBP requirements. A sample owner

notifications letter is provided with this report.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to include in the SPCC Plan an adequate facility diagram, or

no facility diagram included. The facility diagram is not required on

a Tier I qualified facility SPCC Plan.

Violation Notes: Facility did not include a map in their SPCC plan. Provide a map that

includes all the required elements.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.6(a)(1), 25270.6(a)(2) - California Health and Safety

Code, Chapter 6.67, Section(s) 25270.6(a)(1), 25270.6(a)(2)

Violation Description: Failure to submit a tank facility statement on or before January 1

annually unless a current Business Plan has been submitted.

Direction Distance

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

Violation Notes: The facility did not list the 275 gallon diesel day tank that feeds

the three in service emergency generators in their HMBP. Update the HMBP Chemical Inventory to list the 275 gallon diesel day tank. Ensure all petroleum containers over 55 gallons are listed in the HMBP or

annual tank statement.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to adequately describe in the SPCC Plan, overfill prevention

methods, including a description of the systems or procedures used to

prevent overfills for each container.

Violation Notes: The SPCC Plan references a written procedure for filling the tanks but

the facility could not provide the procedure. Submit the written procedure and include it in the SPCC plan as an appendix.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA
Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to implement the SPCC Plan.

Violation Notes: Facility is not fully implementing the SPCC plan including

inspections, employee training, Spill Briefings, monitoring,

maintenance and record keeping. Ensure the SPCC plan is implemented as

described.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to provide the following training to all oil-handling

personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations.

5. Contents of the SPCC Plan.

Violation Notes: Facility failed to train oil handling employees on the SPCC plan as

required. Have the personnel trained and refresh the training at least annually. Retain training documentation for at least three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Map ID MAP FINDINGS
Direction

Distance Flevation Site

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to regularly test liquid level sensing devices to ensure

proper operation.

Violation Notes: Facility failed to test and maintain the electronic monitoring system

for the 4000 gallon diesel AST and 275 gallon diesel day tank feeding three in service emergency generators. Have the monitoring system

repaired to functional status and ensure it is tested per

manufacturer's requirements. Submit a compliance plan with expected

dates of completion.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Facility failed to provide and document initial and annual training to

all employees in emergency response and safety procedures. These training records must be maintained for a minimum of three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 05-31-2016

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: Returned to compliance on 08/18/2016. A complete Hazardous Materials

Business Plan has not yet been submitted electronically through the California Environmental Reporting System (CERS) or the local portal,

FrontCounter.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to address in the SPCC Plan the type of oil and storage

capacity for each fixed container, and either the type of oil and storage capacity for each mobile or portable container, or an estimate of the potential number of mobile or portable containers, the types of

oil, and anticipated storage capacities.

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

Violation Notes: The SPCC plan did not include the 275 gallon diesel day tank that

feeds the three in service emergency generators. Update the SPCC to

include the 275 gallon tank.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5 (a)

Violation Description: Failure to comply with one or more of the following requirements: 1.

Have record of inspections and integrity tests signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and integrity tests for at least three years.

3. Keep comparison records.

Violation Notes: Facility did not maintain records for inspections of the petroleum

storage areas as detailed in their SPCC plan. Ensure all inspection and testing records are maintained for a minimum of three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA
Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all

required content.

Violation Notes: Facility failed to prepare an adequate site map that showed locations

of several Uninterruptible Power Supply (UPS) units containing batteries in the basement and first floor, 275 gallon diesel emergency day tank in the side yard as well as FM 200 fire suppression material in the basement. Submit detailed site maps that show the locations of all hazardous materials and other required elements noted below.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-13-2018 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Inspection was conducted with Ken Choi and Tiffany Shon of Cerulean

Global Services. Ruben Williams, Senior Hazardous Materials Specialist, HMCD was also present. Facility is a communications and server co-location operation. Observed diesel, Uniterruptible Power Supply (UPS) batteries, and FM-200 fire suppression material in HMBP quantities. The FM-200 is disconnected from the fire suppression system and is therefore in storage. Facility stated they will attempt to remove the FM-200 as soon as practicable. CERS submittal on 11/2/2017 was generally complete and accurate except as noted in the

violations above. Observed one 55 gallon drum labeled as

"Non-Hazardous Waste". Determine the contents and properly manage it

Direction Distance

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

if it is determined to be a hazardous material. Please contact HMCD to

gain access to CERS or FrontCounter.

Eval Division: Santa Clara County Environmental Health Eval Program: HMRRP

Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 05-31-2016
Violations Found: Yes

Eval Type: Other, not routine, done by local agency

Eval Notes: On-site to perform Hazardous Materials Business Plan (HMBP)

inspection. A facility walk-through was conducted with Director Jack Huh. Facility is a 24-hour data center. Mr. Huh stated that they have 2 x 2000 gal diesel generators. This was observed in the outdoor/ back area. Owner: Cerulean Global Services Facility name: Cerulean Global Services Mailing Address:250 Stockton Av, San Jose, CA95126 A Hazardous Materials Business Plan permit will be issued by our office

and mailed to the facility address.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-13-2018

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Inspection was conducted with Ken Choi and Tiffany Shon of Cerulean

Global Services. Ruben Williams, Senior Hazardous Materials Specialist, HMCD was also present. Facility uses diesel for emergency generators. Two 4000 gallon tanks and one 275 gallon day tank qualify for the APSA program as a Tier I facility Tier I Template SPCC plan dated 6/9/2018 was reviewed. See above for missing, incomplete or

inaccurate information.

Eval Division: Santa Clara County Environmental Health

Eval Program: APSA Eval Source: CERS

Coordinates:

Site ID: 354674

Facility Name: Cerulean Global Services

Env Int Type Code: HMBP
Program ID: 10636273
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.333580 Longitude: -121.904690

Affiliation:

Affiliation Type Desc:

Entity Name:
Entity Title:
Entity Title:
Affiliation Address:

Legal Owner
ROBERT TAYLOR
Not reported
250 Stockton AVe

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Distance

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

Affiliation Phone: (213) 542-1812

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Affiliation City:

Property Owner

Robert Taylor

Not reported

250 Stockton Ave

San Jose

Affiliation City: San Jos Affiliation State: CA

Affiliation Country: United States Affiliation Zip: 95126

Affiliation Phone: (213) 542-1812

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Environmental Contact

Entity Name: Jack Huh
Entity Title: Not reported
Affiliation Address: 250 Stockton Ave

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95126

Affiliation Phone: (408) 636-3326

Affiliation Type Desc: Identification Signer

Entity Name: Jack Huh Entity Title: Director Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Document Preparer

Entity Name: Jack Huh Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 250 Stockton Ave
Affiliation City: San Jose

Direction Distance

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: Not reported

Affiliation Type Desc: Operator Entity Name: Ken Choi Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: (650) 619-2992

Affiliation Type Desc: Parent Corporation
Entity Name: Cerulean Global Services

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

CERS TANKS:

Site ID: 354674 CERS ID: 10636273

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Facility failed to submit an accurate hazardous materials inventory

including the Uniterruptible Power Supply (UPS) batteries, 275 gallon diesel generator day tank and FM-200 fire suppression material. Update

the inventory and resubmit.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit the Business Activities

Page and/or Business Owner Operator Identification Page.

Violation Notes: The environmental contact listed in the submittal on 11/2/2017 no

longer works for the company. Update the Business Owner/Operator

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

Identification page with current information and resubmit.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to conduct spill prevention briefing for oil-handling

personnel at least once a year to assure adequate understanding of the

SPCC Plan.

Violation Notes: Facility did not perform the annual SPCC briefing for employees.

Ensure the briefing is done annually and is documented and the

documentation retained for at least three years. Santa Clara County Environmental Health

Violation Division: Santa Clara County Environmen

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.95 25505.1 - California Health and Safety Code, Chapter 6.95,

Section(s) 25505.1

Violation Description: Failure to provide a copy of the business plan to the owner or the

owner's agent within five working days after receiving a request for a

copy from the owner or the owner's agent.

Violation Notes: Facility failed to notify the property owner in writing that they are

subject to and in compliance with HMBP requirements. A sample owner

notifications letter is provided with this report.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to include in the SPCC Plan an adequate facility diagram, or

no facility diagram included. The facility diagram is not required on

a Tier I qualified facility SPCC Plan.

Violation Notes: Facility did not include a map in their SPCC plan. Provide a map that

includes all the required elements.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.6(a)(1), 25270.6(a)(2) - California Health and Safety

Code, Chapter 6.67, Section(s) 25270.6(a)(1), 25270.6(a)(2)

Violation Description: Failure to submit a tank facility statement on or before January 1

annually unless a current Business Plan has been submitted.

Violation Notes: The facility did not list the 275 gallon diesel day tank that feeds

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

the three in service emergency generators in their HMBP. Update the HMBP Chemical Inventory to list the 275 gallon diesel day tank. Ensure all petroleum containers over 55 gallons are listed in the HMBP or

annual tank statement.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to adequately describe in the SPCC Plan, overfill prevention

methods, including a description of the systems or procedures used to

prevent overfills for each container.

Violation Notes: The SPCC Plan references a written procedure for filling the tanks but

the facility could not provide the procedure. Submit the written procedure and include it in the SPCC plan as an appendix.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to implement the SPCC Plan.

Violation Notes: Facility is not fully implementing the SPCC plan including

inspections, employee training, Spill Briefings, monitoring,

maintenance and record keeping. Ensure the SPCC plan is implemented as

described.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to provide the following training to all oil-handling

personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations.

5. Contents of the SPCC Plan.

Violation Notes: Facility failed to train oil handling employees on the SPCC plan as

required. Have the personnel trained and refresh the training at least annually. Retain training documentation for at least three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: APSA Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Distance Elevation Site Database(s)

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

EPA ID Number

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to regularly test liquid level sensing devices to ensure

proper operation.

Violation Notes: Facility failed to test and maintain the electronic monitoring system

> for the 4000 gallon diesel AST and 275 gallon diesel day tank feeding three in service emergency generators. Have the monitoring system

repaired to functional status and ensure it is tested per

manufacturer's requirements. Submit a compliance plan with expected

dates of completion.

Violation Division: Santa Clara County Environmental Health

APSA Violation Program: Violation Source: **CERS**

Site ID: 354674

Cerulean Global Services Site Name:

Violation Date: 06-13-2018

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

> safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Facility failed to provide and document initial and annual training to

all employees in emergency response and safety procedures. These training records must be maintained for a minimum of three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HMRRP** Violation Source: CERS

Site ID: 354674

Site Name: Cerulean Global Services

05-31-2016 Violation Date:

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Failure to complete and/or electronically submit a business plan when Violation Description:

storing/handling a hazardous material at or above reportable

Returned to compliance on 08/18/2016. A complete Hazardous Materials Violation Notes:

> Business Plan has not yet been submitted electronically through the California Environmental Reporting System (CERS) or the local portal,

FrontCounter.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HMRRP** Violation Source: **CERS**

Site ID: 354674

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter Citation:

6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to address in the SPCC Plan the type of oil and storage

> capacity for each fixed container, and either the type of oil and storage capacity for each mobile or portable container, or an estimate of the potential number of mobile or portable containers, the types of

oil, and anticipated storage capacities.

Violation Notes: The SPCC plan did not include the 275 gallon diesel day tank that

Elevation

Distance

EPA ID Number Site Database(s)

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

feeds the three in service emergency generators. Update the SPCC to

include the 275 gallon tank.

Violation Division: Santa Clara County Environmental Health

Violation Program: **APSA** Violation Source: **CERS**

354674 Site ID:

Site Name: Cerulean Global Services

Violation Date: 06-13-2018

Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter

6.67, Section(s) 25270.4.5 (a)

Failure to comply with one or more of the following requirements: 1. Violation Description:

> Have record of inspections and integrity tests signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and integrity tests for at least three years.

3. Keep comparison records.

Violation Notes: Facility did not maintain records for inspections of the petroleum

> storage areas as detailed in their SPCC plan. Ensure all inspection and testing records are maintained for a minimum of three years.

Violation Division: Santa Clara County Environmental Health

APSA Violation Program: Violation Source: **CERS**

Site ID: 354674

Cerulean Global Services Site Name:

Violation Date: 06-13-2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all

required content.

Violation Notes: Facility failed to prepare an adequate site map that showed locations

of several Uninterruptible Power Supply (UPS) units containing batteries in the basement and first floor, 275 gallon diesel emergency day tank in the side yard as well as FM 200 fire suppression material in the basement. Submit detailed site maps that show the locations of all hazardous materials and other required elements noted below.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HMRRP** Violation Source: **CERS**

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-13-2018 Violations Found: Yes

Eval Type: Routine done by local agency

Inspection was conducted with Ken Choi and Tiffany Shon of Cerulean **Eval Notes:**

> Global Services. Ruben Williams, Senior Hazardous Materials Specialist, HMCD was also present. Facility is a communications and server co-location operation. Observed diesel, Uniterruptible Power Supply (UPS) batteries, and FM-200 fire suppression material in HMBP quantities. The FM-200 is disconnected from the fire suppression system and is therefore in storage. Facility stated they will attempt to remove the FM-200 as soon as practicable. CERS submittal on 11/2/2017 was generally complete and accurate except as noted in the

violations above. Observed one 55 gallon drum labeled as

"Non-Hazardous Waste". Determine the contents and properly manage it if it is determined to be a hazardous material. Please contact HMCD to

Direction Distance

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

gain access to CERS or FrontCounter.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 05-31-2016
Violations Found: Yes

Eval Type: Other, not routine, done by local agency

Eval Notes: On-site to perform Hazardous Materials Business Plan (HMBP)

inspection. A facility walk-through was conducted with Director Jack Huh. Facility is a 24-hour data center. Mr. Huh stated that they have 2 x 2000 gal diesel generators. This was observed in the outdoor/ back area. Owner: Cerulean Global Services Facility name: Cerulean Global Services Mailing Address:250 Stockton Av, San Jose, CA95126 A Hazardous Materials Business Plan permit will be issued by our office

and mailed to the facility address.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-13-2018

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Inspection was conducted with Ken Choi and Tiffany Shon of Cerulean

Global Services. Ruben Williams, Senior Hazardous Materials Specialist, HMCD was also present. Facility uses diesel for emergency generators. Two 4000 gallon tanks and one 275 gallon day tank qualify for the APSA program as a Tier I facility Tier I Template SPCC plan dated 6/9/2018 was reviewed. See above for missing, incomplete or

inaccurate information.

Eval Division: Santa Clara County Environmental Health

Eval Program: APSA Eval Source: CERS

Coordinates:

Site ID: 354674

Facility Name: Cerulean Global Services

Env Int Type Code: HMBP
Program ID: 10636273
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.333580 Longitude: -121.904690

Affiliation:

Affiliation Type Desc:

Entity Name:
Entity Title:
Affiliation Address:

Legal Owner
ROBERT TAYLOR
Not reported
250 Stockton AVe

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (213) 542-1812

Direction Distance

Elevation Site Database(s) EPA ID Number

CERULEAN GLOBAL SERVICES (Continued)

S121765045

EDR ID Number

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Affiliation City:

Property Owner

Robert Taylor

Not reported

250 Stockton Ave

San Jose

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (213) 542-1812

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported

Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Environmental Contact

Entity Name: Jack Huh
Entity Title: Not reported
Affiliation Address: 250 Stockton Ave

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: (408) 636-3326

Affiliation Type Desc: Identification Signer

Entity Name: Jack Huh **Entity Title:** Director Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Document Preparer

Entity Name: Jack Huh **Entity Title:** Not reported Not reported Affiliation Address: Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 250 Stockton Ave

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CERULEAN GLOBAL SERVICES (Continued)

S121765045

Affiliation Zip: 95126 Affiliation Phone: Not reported

Affiliation Type Desc: Operator **Entity Name:** Ken Choi Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: (650) 619-2992

Parent Corporation Affiliation Type Desc: Cerulean Global Services Entity Name:

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

CERULEAN GLOBAL SERVICES CUPA Listings S118585051 **SAN JOSE HAZMAT** N/A

SW 250 STOCKTON AV 1/8-1/4 SAN JOSE, CA 95126

0.140 mi.

K80

741 ft. Site 5 of 5 in cluster K

Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA PE#: Not reported Actual:

Program Description: HMBP FACILITY, 1-3 CHEMICALS 94 ft.

Latitude: 37.333408 Longitude: -121.905449 Record ID: PR0424037 Facility ID: FA0700855

SANTA CLARA Region:

PE#:

Program Description: APSA FACILITY-SPCC TEMPLATE (<10,000 GAL CAP)

Latitude: 37.333408 Longitude: -121.905449 PR0424038 Record ID: Facility ID: FA0700855

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 408338

Auto Wrecking/Misc Simple Facility Class:

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

L81 **GRUTHFIELD PROPERTY** LUST S103473074 NW N/A

370 N MONTGOMERY HIST LUST

CERS HAZ WASTE 1/8-1/4 SAN JOSE, CA 95110

0.152 mi. **CUPA Listings** HIST CORTESE 800 ft. Site 1 of 6 in cluster L **SAN JOSE HAZMAT**

Relative: **CERS**

Lower

LUST: Actual:

SANTA CLARA COUNTY LOP Lead Agency: 83 ft.

Case Type: **LUST Cleanup Site**

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608502082 T0608502082 Global Id:

37.337107 Latitude: -121.904987 Longitude:

Status: Completed - Case Closed

Status Date: 04/27/2000 Case Worker: UST RB Case Number: Not reported

SANTA CLARA COUNTY LOP Local Agency:

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608502082 Global Id:

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

OAKLAND City: Not reported Email: Phone Number: Not reported

Global Id: T0608502082

Contact Type: Local Agency Caseworker Contact Name: UST CASE WORKER Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

SAN JOSE City: Email: Not reported Phone Number: 4089183400

LUST:

T0608502082 Global Id: Action Type: Other Date: 05/31/1994 Action: Leak Reported

Global Id: T0608502082 Action Type: **ENFORCEMENT** Date: 01/08/1999 Staff Letter - #27020 Action:

Global Id: T0608502082 Action Type: **ENFORCEMENT** Date: 10/05/1999

Direction Distance Elevation

vation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Action: Staff Letter - #27030

 Global Id:
 T0608502082

 Action Type:
 ENFORCEMENT

 Date:
 02/24/1999

 Action:
 Staff Letter - #27023

 Global Id:
 T0608502082

 Action Type:
 ENFORCEMENT

 Date:
 06/02/1999

 Action:
 Staff Letter - #27026

 Global Id:
 T0608502082

 Action Type:
 REMEDIATION

 Date:
 05/31/1994

 Action:
 Excavation

 Global Id:
 T0608502082

 Action Type:
 RESPONSE

 Date:
 04/25/2000

Action: Other Report / Document

 Global Id:
 T0608502082

 Action Type:
 ENFORCEMENT

 Date:
 04/27/2000

Action: Closure/No Further Action Letter

 Global Id:
 T0608502082

 Action Type:
 RESPONSE

 Date:
 02/22/1999

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608502082

 Action Type:
 RESPONSE

 Date:
 04/15/2000

Action: Monitoring Report - Quarterly

 Global Id:
 T0608502082

 Action Type:
 RESPONSE

 Date:
 04/05/1999

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608502082

 Action Type:
 RESPONSE

 Date:
 07/20/1999

Action: Soil and Water Investigation Report

LUST:

Global Id: T0608502082

Status: Completed - Case Closed

Status Date: 04/27/2000

Global Id: T0608502082

Status: Open - Case Begin Date

Status Date: 11/25/1986

Global Id: T0608502082

Direction Distance

Elevation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Status: Open - Site Assessment

Status Date: 11/25/1986

Global Id: T0608502082

Status: Open - Site Assessment

Status Date: 06/02/1999

Global Id: T0608502082

Status: Open - Verification Monitoring

Status Date: 10/04/1999

LUST REG 2:

Region: 2

Facility Id: Not reported Case Closed Facility Status: 07S1E07L05f Case Number: How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Not reported Date Leak Confirmed: Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: 10/4/1999

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07\$1E07L05F

 Date Closed:
 04/27/2000

 EDR Link ID:
 07\$1E07L05F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07L05 Oversite Agency: SCVWD

Date Listed: 1995-01-01 00:00:00 Closed Date: 2000-04-27 00:00:00

CERS HAZ WASTE:

 Site ID:
 73081

 CERS ID:
 10352293

CERS Description: Hazardous Waste Generator

Violations:

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

Direction Distance

Elevation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

hazardous waste.

Violation Notes: Facility does not have an EPA ID number. Obtain an EPA ID number and

keep it active while generating hazardous waste. Assisted with $\ensuremath{\mathsf{DTSC}}$

form 1358 completion during the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: 40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter

1, Section(s) 265.31

Violation Description: Failure to maintain and operate the facility to minimize the

possibility of a fire, explosion, or any unplanned sudden or

non-sudden release of hazardous waste or hazardous waste constituents

to air, soil, or surface water which could threaten human health or

the environment.

Violation Notes: The secondary containment of the used oil drum was filled with empty

new oil containers. Remove the containers and keep the secondary containment clean and available to accept any potential spills or

leaks.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: Facility could not produce used oil pickup receipts. Locate and submit

the last pickup receipt with the response to this report. Ensure 3

years worth of receipts are available for review.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: Facility did not correct or submit a response to the 11/7/2012

inspection report.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2017

Violations Found: No

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

Eval Type: Routine done by local agency

Eval Notes: Facility is a produce warehousing and distribution business. Current

FrontCounter submittal on 1/9/2017 has been accepted. Currently only

storing used oil (55 gallons) in HMBP quantities.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2017 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is a produce warehousing and distribution business. Used oil

generated from vehicle maintenance. Currently generating one 55 gallon

drum of used oil and operating under point of generation rules. Corrected Minors: G020: Marking of Hazardous Waste G023: Open

Container eMail: joey_614@yahoo.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Coordinates:

Site ID: 73081

Facility Name: T & S PRODUCE CO INC

Env Int Type Code: HWG
Program ID: 10352293
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336920 Longitude: -121.904520

Affiliation:

Affiliation Type Desc: Operator Entity Name: LIEN, DU Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 204-0388

Affiliation Type Desc: Environmental Contact

Entity Name: Du Lien
Entity Title: Not reported

Affiliation Address: 370 North Montgomery Street

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: (408) 204-0388

Affiliation Type Desc:

Entity Name:

Entity Title:

Legal Owner

LIEN, DU

Not reported

Affiliation Address: 370 N MONTGOMERY ST

Direction Distance Elevation

vation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95110
Affiliation Phone: (408) 204-0388

Affiliation Type Desc: Document Preparer

Entity Name: Du Lien Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer

Entity Name: Du Lien Entity Title: Owner Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Property Owner Entity Name:** Sen Troung Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: **United States** Affiliation Zip: Not reported Affiliation Phone: (408) 226-2332

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 370 N MONTGOMERY ST

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation

Direction Distance

Elevation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Entity Name: T & S PRODUCE CO INC

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.336445

 Longitude:
 -121.904276

 Record ID:
 PR0390051

 Facility ID:
 FA0255830

Region: SANTA CLARA

PE#: 2201

Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.336445

 Longitude:
 -121.904276

 Record ID:
 PR0373607

 Facility ID:
 FA0255830

HIST CORTESE:

Region: CORTESE Facility County Code: 43 Reg By: LTNKA Reg Id: 43-2267

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 409883

Class: Auto Wrecking/Misc Simple Facility

CERS TANKS:

 Site ID:
 189198

 CERS ID:
 T0608502082

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

OAKLAND

CA

Not reported

Not reported

Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Direction Distance Elevation

evation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

 Site ID:
 73081

 CERS ID:
 10352293

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

hazardous waste.

Violation Notes: Facility does not have an EPA ID number. Obtain an EPA ID number and

keep it active while generating hazardous waste. Assisted with DTSC

form 1358 completion during the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: 40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter

1, Section(s) 265.31

Violation Description: Failure to maintain and operate the facility to minimize the

possibility of a fire, explosion, or any unplanned sudden or

non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or

the environment.

Violation Notes: The secondary containment of the used oil drum was filled with empty

new oil containers. Remove the containers and keep the secondary containment clean and available to accept any potential spills or

leaks.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: Facility could not produce used oil pickup receipts. Locate and submit

the last pickup receipt with the response to this report. Ensure $\boldsymbol{3}$

years worth of receipts are available for review.

Violation Division: Santa Clara County Environmental Health

Direction Distance

Elevation Site Database(s) EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Violation Program: HW
Violation Source: CERS

Site ID: 73081

Site Name: T & S PRODUCE CO INC

Violation Date: 03-10-2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: Facility did not correct or submit a response to the 11/7/2012

inspection report.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2017

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Facility is a produce warehousing and distribution business. Current

FrontCounter submittal on 1/9/2017 has been accepted. Currently only

storing used oil (55 gallons) in HMBP quantities.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 03-10-2017

Violations Found: Yes

Eval Type: Routine done by local agency
Eval Notes: Facility is a produce warehous

otes: Facility is a produce warehousing and distribution business. Used oil

generated from vehicle maintenance. Currently generating one 55 gallon

drum of used oil and operating under point of generation rules. Corrected Minors: G020: Marking of Hazardous Waste G023: Open

Container eMail: joey_614@yahoo.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: CERS

Coordinates:

Site ID: 73081

Facility Name: T & S PRODUCE CO INC

Env Int Type Code: HWG
Program ID: 10352293
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.336920 Longitude: -121.904520

Affiliation:

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Operator

LIEN, DU

Not reported

Not reported

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

GRUTHFIELD PROPERTY (Continued)

S103473074

EDR ID Number

Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported (408) 204-0388 Affiliation Phone:

Environmental Contact Affiliation Type Desc:

Entity Name: Du Lien Entity Title: Not reported

Affiliation Address: 370 North Montgomery Street

Affiliation City: San Jose Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: 95110 (408) 204-0388 Affiliation Phone:

Legal Owner Affiliation Type Desc: LIEN, DU **Entity Name:** Entity Title: Not reported

370 N MONTGOMERY ST Affiliation Address:

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 95110 Affiliation Phone: (408) 204-0388

Affiliation Type Desc: **Document Preparer**

Entity Name: Du Lien Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer

Entity Name: Du Lien **Entity Title:** Owner Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner Entity Name: Sen Troung Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: **United States** Affiliation Zip: Not reported Affiliation Phone: (408) 226-2332

Affiliation Type Desc: **CUPA District**

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

GRUTHFIELD PROPERTY (Continued)

S103473074

S105088986

N/A

CERS

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

Affiliation Address: 370 N MONTGOMERY ST

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: T & S PRODUCE CO INC

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

32 PUCCIO MACHINE & WELDING SAN JOSE HAZMAT

L82 PUCCIO MACHINE & WELDING
NW 357 N MONTGOMERY ST
1/8-1/4 SAN JOSE, CA 95110

0.153 mi.

810 ft. Site 2 of 6 in cluster L

Relative: SAN JOSE HAZMAT:

Lower Region: SAN JOSE
Actual: File Num: 401458

83 ft. Class: Auto Wrecking/Misc Simple Facility

 M83
 VASPAIO AT DIRADON
 CPS-SLIC
 S119777531

 SSW
 138 STOCKTON AVENUE
 NPDES
 N/A

1/8-1/4 SAN JOSE, CA 95126

0.158 mi.

835 ft. Site 1 of 7 in cluster M

Relative: CPS-SLIC: Higher Region:

 Higher
 Region:
 STATE

 Actual:
 Facility Status:
 Open - Eligible for Closure

95 ft. Status Date: 10/29/2018 Global ld: T10000010091

Lead Agency: SANTA CLARA COUNTY LOP

Lead Agency Case Number: 2017-03s Latitude: 37.33285 Longitude: -121.90443

Direction Distance

Elevation Site Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

EDR ID Number

Case Type: Cleanup Program Site

Case Worker: AC

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media Affected: Soi

Potential Contaminants of Concern: Copper, Lead, Nickel

Site History: The Site is bound by Stockton Avenue to the southwest, an office

building/warehouse to the northwest, Caltrain railroad tracks to the northeast and an automotive shop to the southeast. Development plans

are to construct a seven-story mixed use of commercial and residential structure at-grade. Shallow soils are contaminated with hazardous levels of the heavy metals copper, lead, and nickel at select areas of the site. These soils will be excavated to a maximum depth of 9 feet below current grade, and stockpiled on-site while rough grading activities are completed. The contaminated soils will then be placed in a consolidated layer between 6 and 9 feet below grade and capped by the concrete foundation of the new building.

Click here to access the California GeoTracker records for this facility:

NPDES:

Facility Status: Active
NPDES Number: CAS000002

Region: Agency Number: O Regulatory Measure ID: 484744 Place ID: Not reported 2009-0009-DWQ Order Number: WDID: 2 43C379350 Regulatory Measure Type: Enrollee Program Type: Construction Adoption Date Of Regulatory Measure: Not reported

Effective Date Of Regulatory Measure: 04/03/2017
Termination Date Of Regulatory Measure: Not reported
Expiration Date Of Regulatory Measure: Not reported
Discharge Address: 1510 South B

Discharge Address: 1510 South Bascom Avenue Suite 7

Discharge Name: Vespaio LLC Discharge City: Campbell Discharge State: California Discharge Zip: 95008 Status: Not reported Status Date: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported

NPDES as of 03/2018:

 NPDES Number:
 CAS000002

 Status:
 Active

 Agency Number:
 0

 Region:
 2

 Regulatory Measure ID:
 484744

Order Number: 2009-0009-DWQ

Regulatory Measure Type: Enrollee

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

Place ID: Not reported 2 43C379350 WDID: Program Type: Construction Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: 04/03/2017 Expiration Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Discharge Name: Vespaio LLC

Discharge Address: 1510 South Bascom Avenue Suite 7

Discharge City: Campbell Discharge State: California Discharge Zip: 95008 Received Date: Not reported Processed Date: Not reported Status: Not reported Status Date: Not reported Not reported Place Size: Place Size Unit: Not reported Contact: Not reported Contact Title: Not reported Contact Phone: Not reported Contact Phone Ext: Not reported Contact Email: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported **Operator Contact:** Not reported Operator Contact Title: Not reported **Operator Contact Phone:** Not reported Operator Contact Phone Ext: Not reported Operator Contact Email: Not reported Operator Type: Not reported Not reported Developer: Developer Address: Not reported Developer City: Not reported Developer State: Not reported Developer Zip: Not reported **Developer Contact:** Not reported **Developer Contact Title:** Not reported Constype Linear Utility Ind: Not reported **Emergency Phone:** Not reported Emergency Phone Ext: Not reported Constype Above Ground Ind: Not reported Constype Below Ground Ind: Not reported Constype Cable Line Ind: Not reported Constype Comm Line Ind: Not reported Constype Commertial Ind: Not reported Not reported Constype Electrical Line Ind: Constype Gas Line Ind: Not reported Constype Industrial Ind: Not reported Constype Other Description: Not reported Constype Other Ind: Not reported Constype Recons Ind: Not reported Constype Residential Ind: Not reported

Not reported

Constype Transport Ind:

Distance Elevation Site

Site Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

EDR ID Number

Constype Utility Description: Not reported Not reported Constype Utility Ind: Constype Water Sewer Ind: Not reported Dir Discharge Uswater Ind: Not reported Receiving Water Name: Not reported Not reported Certifier: Certifier Title: Not reported Certification Date: Not reported Primary Sic: Not reported Secondary Sic: Not reported **Tertiary Sic:** Not reported

NPDES Number: Not reported Status: Not reported Agency Number: Not reported Not reported

Region: Regulatory Measure ID: 484744 Order Number: Not reported Regulatory Measure Type: Construction Place ID: Not reported WDID: 2 43C379350 Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Discharge Name: Not reported Discharge Address: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported 03/27/2017 Received Date: Processed Date: 04/03/2017 Status: Active 04/03/2017 Status Date: Place Size: 1.72

Place Size Unit:

Contact:

Contact Title:

Contact Phone:

Contact Phone Ext:

Acres

Marc Mastriani

Superintendent

408-410-0005

Not reported

Contact Email: marcm@echelcon.com

Operator Name: Vespaio LLC

Operator Address: 1510 South Bascom Avenue Suite 7

Operator City:
Campbell
Operator State:
California
Operator Zip:
Operator Contact:
Operator Contact:
Operator Contact Title:
Operator Contact Phone:
Operator Contact Phone Ext:
Not reported

Operator Contact Email: MJones@hudcorp.net
Operator Type: Private Business
Developer: Vespaio LLC

Developer Address: 1510 South Bascom Avenue Suite 7

Developer City: Campbell Developer State: California

Distance Elevation

Site Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

EDR ID Number

Developer Zip: 95008

Developer Contact: Dan Hudson

Developer Contact Title: Not reported

Constype Linear Utility Ind:

Emergency Phone: Not reported Emergency Phone Ext: Not reported

Constype Above Ground Ind: Ν Constype Below Ground Ind: Ν Constype Cable Line Ind: Ν Constype Comm Line Ind: Ν Constype Commertial Ind: Ν Constype Electrical Line Ind: Ν Constype Gas Line Ind: Ν Constype Industrial Ind: Ν

Constype Other Description: Mixed Use

Constype Other Ind: N
Constype Recons Ind: N
Constype Residential Ind: N
Constype Transport Ind: N

Constype Utility Description: Not reported

Constype Utility Ind: N
Constype Water Sewer Ind: N
Dir Discharge Uswater Ind: N

Receiving Water Name:

Certifier:

Dan Hudson
Certifier Title:

Certification Date:

Primary Sic:

Secondary Sic:

Tertiary Sic:

Not reported
Not reported
Not reported
Not reported
Not reported

Facility Status: Not reported NPDES Number: Not reported Not reported Region: Not reported Agency Number: Not reported Regulatory Measure ID: Place ID: Not reported Order Number: Not reported WDID: 2 43C379350 Regulatory Measure Type: Construction Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Discharge Address: Not reported Discharge Name: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Status: Active Status Date: 04/03/2017 Operator Name: Vespaio LLC

Operator Address: 1510 South Bascom Avenue Suite 7

Operator City: Campbell Operator State: California

Distance Elevation Site

e Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

EDR ID Number

Operator Zip: 95008

NPDES as of 03/2018:

 NPDES Number:
 CAS000002

 Status:
 Active

 Agency Number:
 0

 Region:
 2

 Regulatory Measure ID:
 484744

Regulatory Measure ID: 484744
Order Number: 2009-0009-DWQ

Regulatory Measure Type: Enrollee Place ID: Not reported WDID: 2 43C379350 Program Type: Construction Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: 04/03/2017 Expiration Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Discharge Name: Vespaio LLC

Discharge Address: 1510 South Bascom Avenue Suite 7

Discharge City: Campbell Discharge State: California Discharge Zip: 95008 Received Date: Not reported Processed Date: Not reported Status: Not reported Status Date: Not reported Place Size: Not reported Place Size Unit: Not reported Contact: Not reported Contact Title: Not reported Contact Phone: Not reported Contact Phone Ext: Not reported Contact Email: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported **Operator Contact:** Not reported

Operator Contact Title: Not reported Not reported **Operator Contact Phone:** Not reported Operator Contact Phone Ext: Operator Contact Email: Not reported Operator Type: Not reported Developer: Not reported Developer Address: Not reported Developer City: Not reported Developer State: Not reported Developer Zip: Not reported **Developer Contact:** Not reported **Developer Contact Title:** Not reported Constype Linear Utility Ind: Not reported **Emergency Phone:** Not reported Emergency Phone Ext: Not reported Constype Above Ground Ind: Not reported

Not reported

Not reported

Not reported

Constype Below Ground Ind:

Constype Cable Line Ind:

Constype Comm Line Ind:

Distance Elevation

Site Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

EDR ID Number

Constype Commertial Ind: Not reported Not reported Constype Electrical Line Ind: Constype Gas Line Ind: Not reported Constype Industrial Ind: Not reported Constype Other Description: Not reported Constype Other Ind: Not reported Not reported Constype Recons Ind: Constype Residential Ind: Not reported Constype Transport Ind: Not reported Constype Utility Description: Not reported Constype Utility Ind: Not reported Constype Water Sewer Ind: Not reported Dir Discharge Uswater Ind: Not reported Receiving Water Name: Not reported Certifier: Not reported Certifier Title: Not reported Certification Date: Not reported Primary Sic: Not reported Secondary Sic: Not reported **Tertiary Sic:** Not reported

NPDES Number: Not reported Not reported Status: Agency Number: Not reported Region: Regulatory Measure ID: 484744 Order Number: Not reported Regulatory Measure Type: Construction Place ID: Not reported WDID: 2 43C379350 Not reported Program Type: Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Discharge Name: Not reported Discharge Address: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Received Date: 03/27/2017 Processed Date: 04/03/2017 Status: Active 04/03/2017 Status Date: Place Size: 1.72 Place Size Unit: Acres

Contact: Marc Mastriani
Contact Title: Superintendent
Contact Phone: 408-410-0005
Contact Phone Ext: Not reported

Contact Email: marcm@echelcon.com

Operator Name: Vespaio LLC

Operator Address: 1510 South Bascom Avenue Suite 7

Operator City: Campbell
Operator State: California
Operator Zip: 95008
Operator Contact: Dan Hudson

Direction Distance

Elevation Site Database(s) EPA ID Number

VASPAIO AT DIRADON (Continued)

S119777531

EDR ID Number

Operator Contact Title: Not reported
Operator Contact Phone: 408-963-6712
Operator Contact Phone Ext: Not reported

Operator Contact Email: MJones@hudcorp.net
Operator Type: Private Business
Developer: Vespaio LLC

Developer Address: 1510 South Bascom Avenue Suite 7

Developer City:CampbellDeveloper State:CaliforniaDeveloper Zip:95008Developer Contact:Dan HudsonDeveloper Contact Title:Not reported

Constype Linear Utility Ind: N

Emergency Phone: Not reported Emergency Phone Ext: Not reported

Constype Above Ground Ind:

Constype Below Ground Ind:

N
Constype Cable Line Ind:

Constype Comm Line Ind:

N
Constype Commertial Ind:

N
Constype Electrical Line Ind:

N
Constype Gas Line Ind:

N
Constype Industrial Ind:

N

Constype Other Description: Mixed Use

Constype Other Ind: N
Constype Recons Ind: N
Constype Residential Ind: N
Constype Transport Ind: N

Constype Utility Description: Not reported

Constype Utility Ind: N
Constype Water Sewer Ind: N
Dir Discharge Uswater Ind: N

Receiving Water Name:

Certifier:

Dan Hudson
Certifier Title:

Certification Date:

Primary Sic:

Secondary Sic:

Tertiary Sic:

Not reported
Not reported
Not reported
Not reported
Not reported

CERS TANKS:

 Site ID:
 417165

 CERS ID:
 T10000010091

 CERS Description:
 Cleanup Program Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: AARON COSTA - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089181954

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

L84 **CS AUTOWORKS CUPA Listings** S114555354 NNW 383 N AUTUMN ST N/A

SAN JOSE, CA 95110 1/8-1/4

0.159 mi.

837 ft. Site 3 of 6 in cluster L

Relative: CUPA SANTA CLARA: Lower

Region: SANTA CLARA PE#: 2205 Actual:

GENERATES 100 KG YR TO <5 TONS/YR Program Description: 83 ft.

Latitude: 37.3372559 Longitude: -121.904225 Record ID: PR0413884 Facility ID: FA0273715

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.3372559 Longitude: -121.904225 Record ID: PR0413883 Facility ID: FA0273715

S121472928 L85 **CAR CARE CLINIC CUPA Listings** NNW 383 N AUTUM ST

N/A

N/A

1/8-1/4 SAN JOSE, CA 95110

0.159 mi. Site 4 of 6 in cluster L

837 ft.

Relative: CUPA SANTA CLARA:

Lower SANTA CLARA Region:

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 83 ft.

Latitude: 37.337024 Longitude: -121.90379 Record ID: PR0365493 Facility ID: FA0256655

L86 **BOSNAK AUTO CONCEPTS & SMOG** S117349038 **CUPA Listings**

NNW 383 N AUTUMN ST UNIT 7 1/8-1/4 SAN JOSE, CA 95110

0.159 mi.

837 ft. Site 5 of 6 in cluster L CUPA SANTA CLARA: Relative:

Lower Region: SANTA CLARA

PE#: 2205 Actual:

83 ft. Program Description: GENERATES 100 KG YR TO <5 TONS/YR

Latitude: 37.3372559 -121.904225 Longitude: Record ID: PR0417168 Facility ID: FA0276009

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.3372559 Longitude: -121.904225

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BOSNAK AUTO CONCEPTS & SMOG (Continued)

S117349038

Record ID: PR0417167 Facility ID: FA0276009

L87 **JOAQUIN MEDIA** CUPA Listings S121473829 NNW 385 N AUTUMN ST N/A

1/8-1/4 SAN JOSE, CA 95110

0.159 mi.

Relative:

839 ft. Site 6 of 6 in cluster L CUPA SANTA CLARA:

Lower Region: SANTA CLARA PE#: Not reported Actual:

83 ft. Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.337033 Longitude: -121.903799 Record ID: PR0397703 Facility ID: FA0260629

Region: SANTA CLARA

PE#: 2201

Program Description: GENERATES WASTE OIL ONLY

Latitude: 37.337033 -121.903799 Longitude: Record ID: PR0382023 Facility ID: FA0260629

N88 HIST UST U001602502 **SCU / PARAMEDICAL SERVICES** SE 98 NORTH AUTUMN STREET N/A

1/8-1/4 SAN JOSE, CA 95110

0.161 mi.

850 ft. Site 1 of 2 in cluster N

HIST UST: Relative: Lower File Number: 0002088C

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002088C.pdf Actual:

Not reported

STATE 83 ft. Region: Facility ID: 00000010372 Facility Type: Gas Station

Other Type: PARAMEDICAL OPERATIO

Contact Name: **BRUCE WAGNER** Telephone: 4082951555

Owner Name: SCU/PARAMEDICAL SERVICES Owner Address: 98 NORTH AUTUMN STREET

Owner City, St, Zip: SAN JOSE, CA 95110 Total Tanks: 0002

Tank Num: 001 Container Num: #001 Year Installed: Not reported 00001000 Tank Capacity: Tank Used for: **PRODUCT** Type of Fuel: **REGULAR**

Leak Detection: Visual, Stock Inventor, 10

Tank Num: 002

Container Construction Thickness:

Direction Distance

Elevation Site Database(s) EPA ID Number

SCU / PARAMEDICAL SERVICES (Continued)

U001602502

EDR ID Number

Container Num: #002
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported

Leak Detection: Visual, Stock Inventor, 10

Click here for Geo Tracker PDF:

O89 FMC CORP SAN JOSE ORDNANCE PLANT CPS-SLIC S103393863

NE 333 JULIAN ST N/A

1/8-1/4 SAN JOSE, CA 95122

0.164 mi.

866 ft. Site 1 of 5 in cluster O

Relative: SLIC REG 2:

LowerRegion:2Actual:Facility ID:43-1965

Facility Status: Remediation Plan
Date Closed: Not reported
Local Case #: 431964
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: 1/30/1991
Date Preliminary Site Assessment Began: Not reported
Date Pollution Characterization Began: Not reported
Date Remediation Plan Submitted: 1/31/1991
Date Remedial Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

090 FMC CORP SAN JOSE ORDNANCE PLT ENVIROSTOR \$106235203

 NE
 333 WEST JULIAN STREET
 CPS-SLIC

 1/8-1/4
 SAN JOSE, CA 95110
 DEED

 0.168 mi.
 CERS

887 ft. Site 2 of 5 in cluster O

Relative: ENVIROSTOR:

 Lower
 Facility ID:
 43370005

 Actual:
 Status:
 Refer: RWQCB

 76 ft.
 Status Date:
 01/14/1991

 Site Code:
 200225

Site Code: 200225
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 9.2
NPL: NO

Regulatory Agencies: HWMP, RWQCB 2 - San Francisco Bay

Lead Agency: RWQCB 2 - San Francisco Bay

Program Manager: Not reported

Supervisor: Referred - Not Assigned Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: * Site Char & Assess Grant (CERCLA 104)

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

FMC CORP SAN JOSE ORDNANCE PLT (Continued)

S106235203

EDR ID Number

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Not reported Latitude: 37.33717 Longitude: -121.8998

APN: 259-24-024, 259-24-025, 259-24-035, 259-30-091

Past Use: AEROSPACE MANUFACTURING/MAINTENANCE, LABORATORIES- UNSPECIFIED,

MANUFACTURING - INDUSTRIAL MACHINERY, RESEARCH - AEROSPACE, RESEARCH

- WEAPONS

Potential COC: Asbestos Containing Materials (ACM Lead Tetrachloroethylene (PCE

TPH-diesel TPH-MOTOR OIL 1,1,1-Trichloroethane (TCA Trichloroethylene

(TCE Vinyl chloride Copper and compounds 1,1-Dichloroethane 1,2-Dichloroethane (EDC 1,1-Dichloroethylene 1,2-Dichloroethylene

(cis 1,2-Dichloroethylene (trans 1,1,2-Trichloroethane

Confirmed COC: Asbestos Containing Materials (ACM 1,1,2-Trichloroethane

Tetrachloroethylene (PCE TPH-diesel 1,1,1-Trichloroethane (TCA Trichloroethylene (TCE Vinyl chloride Copper and compounds 1,1-Dichloroethane 1,2-Dichloroethane (EDC 1,1-Dichloroethylene 1,2-Dichloroethylene (cis 1,2-Dichloroethylene (trans Lead TPH-MOTOR

OIL

Potential Description: OTH, SOIL

Alias Name: SOBRATO DEVELOPMENT COMPANY

Alias Type: Alternate Name Alias Name: 259-24-024 Alias Type: APN Alias Name: 259-24-025 Alias Type: APN Alias Name: 259-24-035 Alias Type: APN Alias Name: 259-30-091 Alias Type: APN

Alias Name: CAD009146952

Alias Type: EPA Identification Number

Alias Name: 200225

Alias Type: Project Code (Site Code)

Alias Name: 43370005

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 10/12/1983

Comments: FACILITY IDENTIFIED ID FROM ERRIS

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 01/08/2002

Comments: This site is actively monitored by the RWQCB. There are environmental

deed restrictions on the property for soil and groundwater concerns.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 12/31/1997

Comments: Under oversight of RWQCB

Elevation Site

EDR ID Number Database(s) EPA ID Number

FMC CORP SAN JOSE ORDNANCE PLT (Continued)

S106235203

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Assessment Report

Completed Date: 04/24/2014
Comments: Not reported

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Schedule Area Name: Not reported Not reported Schedule Sub Area Name: Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

CPS-SLIC:

Distance

Region: STATE

Facility Status: Open - Eligible for Closure

 Status Date:
 09/24/2015

 Global Id:
 SL20214832

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number:
Latitude:
Solution 2012
Not reported
37.3365380457309
Longitude:
-121.899254322052
Case Type:
Cleanup Program Site

Case Worker: REG
Local Agency: Not reported
RB Case Number: 43S0253

File Location: All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected: Aquifer used for drinking water supply, Sediments, Soil, Soil Vapor,

Surface water

Potential Contaminants of Concern: 1,1,1-Trichloroethane (TCA), Other Chlorinated Hydrocarbons,

Trichloroethylene (TCE), Vinyl chloride, Other Petroleum

Site History: The area of the Site is approximately 13 acres, centered on Old West

Julian Street, bounded on the west by the Guadalupe River, on the east by the Guadalupe Parkway (Route 87), on the north by the Union Pacific Railroad, and on the south by West Julian Street. The Site is under development by Sobrato Development Companies (SDC), the current owner. Two buildings and a parking structure have been completed. Construction on a third building was iscontinued prior to completion due to economic reasons. FMC and predecessor companies occupied the Site from the early 1900s through 1986. Manufacturing operations, including production of agricultural machinery, food-processing equipment, and military tracked vehicles, occurred at the Site beginning in the early 1900s. Manufacturing operations at the Site ceased in 1986 and the facility was leased for warehousing and other storage purposes. In June 1998, FMC sold the property to SDC.FMC initiated environmental investigations at the Site in 1986. Soil sampling in former manufacturing and product storage areas revealed the presence of petroleum hydrocarbons, volatile organic compounds (VOCs), and metals. Further investigations included the installation of groundwater monitoring wells that detected VOC constituents in two

shallow water-bearing zones beneath the Site. Quarterly groundwater monitoring was conducted from the third quarter of 1989 through the first quarter of 2001. Semi-annual groundwater monitoring and reporting began in April 2001. On June 21, 1989, the State of

Distance Elevation Site

Site

Database(s)

EDR ID Number EPA ID Number

FMC CORP SAN JOSE ORDNANCE PLT (Continued)

S106235203

California Regional Water Quality Control Board, San Francisco Bay Region (RWQCB) adopted Order Number 89-107, Site Cleanup Requirements for FMC Corporation-Ground Systems Division, 333 West Julian Street, San Jose, Santa Clara County (RWQCB, 1989). On August 15, 1990, Order Number 90-122 (RWQCB, 1990) was adopted by the RWQCB, amending Order Number 89-107 with respect to the adoption of final Site cleanup levels. On January 21, 1998, Order Number 98-006 was adopted (RWQCB, 1998) for the Site, amending Orders 89-107 and 90-122 with respect to revising soil cleanup standards and adding additional tasks to protect groundwater and address risks associated with exposure to residual soil contamination. On March 21, 2001, Order No. 01-031, Final Site Cleanup Requirements and Rescission of Orders Nos. 89-107, 90-122, and 98-006 for FMC Corporation, for the property located at 333 West Julian Street, San Jose, Santa Clara County (RWQCB, 2001) was adopted by the RWQCB. This annual compliance report is being submitted to the RWQCB as required by Order No. 01-031, Provision D.5. FMC implemented VOC source removal using a Soil Vapor Extraction system in the southwest portion of the Site from 1991 through March 1994. In addition, a groundwater extraction and treatment system for the A-level aquifer operated at the Site from March 1992 through January 1997, when it was discontinued due to changed groundwater flow directions, limited mass removal over time, and completion of effective source removal. Authorization to discontinue operation of the groundwater extraction and treatment systemwas given by the RWQCB in their letter to FMC, dated January 2, 1997 (RWQCB, 1997). The RWQCB documented the achievement of meeting the Site soil cleanup goals forchlorinated solvents in prior Order No. 98-006. FMC performed a natural attenuation evaluation in 2000 (HSI GeoTrans, 2000) to consider methods of remediating the residual VOCs present in Site groundwater. The evaluation concluded that VOC degradation could be accelerated through the introduction of an electron donor that would enhance the biodegradation. Cheese whey was selected as the electron donor material, and, in accordance with Task C.2. of Order Number 01-031 and the Work Plan for In-Situ Bioremediation Using Cheese Whey Injection (Work Plan) dated May 30, 2001 (GeoTrans, 2001), cheese whey injection was conducted at ten Site monitoring wells and piezometers in July2001 to enhance biodegradation of VOCs in groundwater. Additional cheese whey was injected at nine monitoring wells and piezometers in May 2003 to increase the in-situ reactive zone and further promote an environment for biodegradation. Groundwater sampling was conducted to evaluate the effectiveness of enhanced biodegradation on a monthly basis from September through December 2001, and on a semi-annual basis from March 2002 to March 2005. Discharger was urged to evaluate the site for case closure under the low threat closure criteria in February 2015.

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region: 2

Facility ID: SL20214832

Facility Status: Post remedial action monitoring

Date Closed: Not reported Local Case #: Not reported How Discovered: RPR

Leak Cause: Not reported Leak Source: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FMC CORP SAN JOSE ORDNANCE PLT (Continued)

S106235203

Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: Not reported Date Preliminary Site Assessment Began: Not reported Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

DEED:

Envirostor ID: SL20214832 Area: Not reported Not reported Sub Area:

Site Type: SLIC

OPEN - ELIGIBLE FOR CLOSURE Status:

SWRCB Agency: Covenant Uploaded: 09/08/1998 Deed Date(s):

File Name: Geotracker Land Use/Deed Restrictions

CERS TANKS:

Site ID: 233907 CERS ID: SL20214832

CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: RON GOLOUBOW - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 Clay Street Suite 1400

OAKLAND Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 5106222442 Affiliation Phone:

FMC CORP SEMS-ARCHIVE 1015730622 333 JULIAN ST RCRA-SQG CAD009146952

ΝE 1/8-1/4 **SAN JOSE, CA 95110**

0.168 mi.

O91

887 ft. Site 3 of 5 in cluster O

SEMS Archive: Relative:

Lower Site ID: 0901166 EPA ID: CAD009146952 Actual: Cong District: 10 76 ft.

FIPS Code: 06085 FF: Ν

NPL: Not on the NPL

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

37.344444 Latitude: Longitude: -121.887500

SEMS Archive Detail:

Region: 09 Site ID: 0901166 EPA ID: CAD009146952

Site Name: FMC CORP SAN JOSE ORDNANCE PLT

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FMC CORP (Continued) 1015730622

NPL: Ν FF: Ν OU: 00 Action Code: PΑ Action Name: PΑ SEQ:

Start Date: 1988-05-01 04:00:00 Finish Date: 1988-05-01 04:00:00

Qual: **Current Action Lead: EPA Perf**

09 Region: Site ID: 0901166 EPA ID: CAD009146952

FMC CORP SAN JOSE ORDNANCE PLT Site Name:

NPL: FF: Ν OU: 00 Action Code: 00

SITE REASS Action Name:

SEQ:

Start Date: 2013-07-01 05:00:00 Finish Date: 2014-04-24 04:00:00

Qual:

Current Action Lead: **EPA Perf**

Region: 09 Site ID: 0901166 EPA ID: CAD009146952

FMC CORP SAN JOSE ORDNANCE PLT Site Name:

NPL: FF: Ν OU: 00 Action Code: SI Action Name: SI SEQ:

Start Date: 1990-03-30 05:00:00 Finish Date: 1990-03-30 05:00:00

Qual:

Current Action Lead: **EPA Perf**

Region: 09 Site ID: 0901166 EPA ID: CAD009146952

FMC CORP SAN JOSE ORDNANCE PLT Site Name:

NPL: Ν FF: Ν OU: 00 Action Code: DS **DISCVRY** Action Name:

SEQ:

1980-08-01 04:00:00 Start Date: 1980-08-01 04:00:00 Finish Date: Qual: Not reported Current Action Lead: **EPA** Perf

Region: 09

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FMC CORP (Continued) 1015730622

Site ID: 0901166 CAD009146952 EPA ID:

FMC CORP SAN JOSE ORDNANCE PLT Site Name:

NPL: FF: Ν OU: 00 Action Code: PΑ Action Name: PΑ SEQ:

Start Date: 1986-03-01 05:00:00 Finish Date: 1986-03-01 05:00:00

Qual: St Perf **Current Action Lead:**

RCRA-SQG:

Date form received by agency: 09/01/1996 Facility name: **FMC CORP** Facility address: 333 JULIAN ST

SAN JOSE, CA 95110

CAD009146952 EPA ID: Mailing address: PO BOX 367

SAN JOSE, CA 95103

Contact: Not reported Not reported Contact address:

Not reported

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

NOT REQUIRED Owner/operator name: Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

NOT REQUIRED Owner/operator name: Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FMC CORP (Continued) 1015730622

Owner/operator email: Not reported Not reported Owner/operator fax: Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: Nο Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 04/09/1990

FMC CORP (GROUND SYSTEMS DIV) Site name:

Classification: Large Quantity Generator

Date form received by agency: 08/15/1980 **FMC CORP** Site name:

Classification: Large Quantity Generator

Violation Status: No violations found

O92 COUNTY OF SANTA CLARA FAF SOCIAL SERVICES AGENCY J

333 JULIAN ST SAN JOSE, CA 95131 1/8-1/4

HIST UST:

0.168 mi.

ΝE

Site 4 of 5 in cluster O

887 ft.

Relative: Lower File Number: Not reported URL: Not reported Actual: Region: STATE 76 ft. Facility ID: 0000001362

Facility Type: Other

Other Type: **MANUFACTURING**

Contact Name: P.C. WOGLOM, OPERATIONS MANAGE

Telephone: 4082894285

FMC CORPORATION Owner Name: Owner Address: 200 RANDOLPH DRIVE Owner City, St, Zip: CHICAGO, IL 60601

Total Tanks: 0001

Tank Num: 001 Container Num: 001

U001602489

N/A

HIST UST

CUPA Listings

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COUNTY OF SANTA CLARA FAF SOCIAL SERVICES AGENCY JULIAN FACI (Continued)

U001602489

Year Installed: 1982 00000150 Tank Capacity: Tank Used for: WASTE Type of Fuel: WASTE OIL

Container Construction Thickness: 14 Leak Detection: Visual

CUPA SANTA CLARA:

Region: SANTA CLARA PE#: Not reported

Program Description: HAZMAT STORAGE & HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.3439484 -121.8866992 Longitude: Record ID: PR0390262 Facility ID: FA0264598

Region: SANTA CLARA

PE#: 2502

Program Description: HAZMAT STORAGE FACILITY-MINIMAL STORAGE SITE

Latitude: 37.336197 Longitude: -121.899104 Record ID: PR0390499 Facility ID: FA0264733

O93 FMC CORPORATION Cortese S102429620 N/A

NE 333 JULIAN **ENF HIST CORTESE** 1/8-1/4 SAN JOSE, CA 95103 **CIWQS**

0.168 mi. 887 ft. Site 5 of 5 in cluster O

Relative:

CORTESE:

Lower Region: CORTESE Not reported Envirostor Id: Actual: Site/Facility Type: Not reported 76 ft. Cleanup Status: Not reported

Waste Management Uit Name:

Status Date: Not reported Site Code: Not reported Latitude: Not reported Longitude: Not reported Owner: Not reported Enf Type: Not reported Not reported Swat R: CORTESE Flag: Order No: Not reported Waste Discharge System No: Not reported Effective Date: Not reported Region 2: Not reported WID Id: Not reported Solid Waste Id No: Not reported

Not reported Cease Desist Orders & Cleanup Abatement Orders File Name:

Region: **CORTESE** Envirostor Id: Not reported Site/Facility Type: Not reported Cleanup Status: Not reported Status Date: Not reported

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

FMC CORPORATION (Continued)

S102429620

Site Code: Not reported Not reported Latitude: Not reported Longitude: Owner: Not reported Enf Type: Not reported Not reported Swat R: CORTESE Flag: Order No: Not reported Waste Discharge System No: Not reported Effective Date: Not reported

Region 2: 2

WID Id: 2 438311N01
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported

File Name: Cease Desist Orders & Cleanup Abatement Orders

CORTESE Region: Envirostor Id: Not reported Site/Facility Type: Not reported Cleanup Status: Not reported Status Date: Not reported Site Code: Not reported Latitude: Not reported Longitude: Not reported Owner: Not reported Not reported Enf Type: Swat R: Not reported Flag: CORTESE Order No: Not reported Waste Discharge System No: Not reported Effective Date: Not reported

Region 2: 2
WID Id: 2 438311N01
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported

File Name: Cease Desist Orders & Cleanup Abatement Orders

Region: **CORTESE** Envirostor Id: Not reported Site/Facility Type: Not reported Cleanup Status: Not reported Status Date: Not reported Site Code: Not reported Not reported Latitude: Not reported Longitude: Owner: Not reported Enf Type: Not reported Swat R: Not reported Flag: CORTESE Order No: Not reported Waste Discharge System No: Not reported

Effective Date: Not reported Region 2: 2

WID Id: 2 438311N01
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported

File Name: Cease Desist Orders & Cleanup Abatement Orders

MAP FINDINGS Map ID Direction

Distance

Elevation Site Database(s) **EPA ID Number**

FMC CORPORATION (Continued)

S102429620

EDR ID Number

ENF:

Region: 2 Facility Id: 224709

Agency Name: FMC Corporation Philadelphia

Place Type: Facility Place Subtype: Not reported Facility Type: Industrial

Agency Type: Privately-Owned Business

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Complexity: Not reported Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported Program: **UNREGS** Program Category1: **UNREGS** Program Category2: **UNREGS**

Of Programs:

WDID: 2 438311N01 162396 Reg Measure Id: Unregulated Reg Measure Type: Region:

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Not reported Reclamation: Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported Status: **Never Active** Status Date: 02/21/2013 Effective Date: Not reported Not reported Expiration/Review Date: Not reported Termination Date: WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported

MAP FINDINGS Map ID Direction

Distance Elevation Site

Database(s) **EPA ID Number**

FMC CORPORATION (Continued)

S102429620

EDR ID Number

WDR Review - No Action Required: Not reported Not reported WDR Review - Pending: WDR Review - Planned: Not reported

Status Enrollee: Ν Individual/General:

Fee Code: Not reported Direction/Voice: **Passive** Enforcement Id(EID): 222608 Region: Order / Resolution Number: 89-107

Enforcement Action Type: Clean-up and Abatement Order

06/21/1989 Effective Date: Adoption/Issuance Date: Not reported Achieve Date: Not reported Termination Date: Not reported ACL Issuance Date: Not reported EPL Issuance Date: Not reported Status: Active

Enforcement - 2 438311N01 Title:

Description: **ENF ORDER** Program: **UNREGS** Latest Milestone Completion Date: Not reported

Of Programs1: **Total Assessment Amount:** 0 Initial Assessed Amount: 0 Liability \$ Amount: 0 Project \$ Amount: 0 Liability \$ Paid: 0 Project \$ Completed: 0 Total \$ Paid/Completed Amount: 0

Region: 2 Facility Id: 224709

Agency Name: FMC Corporation Philadelphia

Place Type: Facility Place Subtype: Not reported Facility Type: Industrial

Agency Type: **Privately-Owned Business**

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

FMC CORPORATION (Continued)

S102429620

EDR ID Number

Complexity: Not reported Not reported Pretreatment: Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported UNREGS Program: Program Category1: **UNREGS** Program Category2: **UNREGS** # Of Programs:

WDID: 2 438311N01 Reg Measure Id: 162396 Reg Measure Type: Unregulated

Region: 2

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Reclamation: Not reported Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported **Never Active** Status: Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned: Not reported

Status Enrollee: N Individual/General: I

Fee Code:
Direction/Voice:
Enforcement Id(EID):
Region:
Order / Resolution Number:
Not reported
Passive
222607
290-122

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 08/15/1990
Adoption/Issuance Date: Not reported
Achieve Date: Not reported
Termination Date: Not reported
ACL Issuance Date: Not reported
EPL Issuance Date: Not reported
Status: Active

Title: Enforcement - 2 438311N01

Description: ENF ORDER
Program: UNREGS
Latest Milestone Completion Date: Not reported

Of Programs1: 1
Total Assessment Amount: 0
Initial Assessed Amount: 0
Liability \$ Amount: 0
Project \$ Amount: 0

Distance Elevation

ion Site Database(s) EPA ID Number

FMC CORPORATION (Continued)

S102429620

EDR ID Number

Liability \$ Paid: 0
Project \$ Completed: 0
Total \$ Paid/Completed Amount: 0

Region: 2 Facility Id: 224709

Agency Name: FMC Corporation Philadelphia

Place Type: Facility
Place Subtype: Not reported
Facility Type: Industrial

Agency Type: Privately-Owned Business

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places: Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Not reported Complexity: Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported Program: UNREGS Program Category1: **UNREGS**

Of Programs:

Program Category2:

 WDID:
 2 438311N01

 Reg Measure Id:
 162396

 Reg Measure Type:
 Unregulated

UNREGS

Region: 2

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Reclamation: Not reported Dredge Fill Fee: Not reported Not reported 301H: Application Fee Amt Received: Not reported Never Active Status: Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

FMC CORPORATION (Continued)

S102429620

EDR ID Number

WDR Review - Amend:
WDR Review - Revise/Renew:
WDR Review - Rescind:
WDR Review - Rescind:
WDR Review - No Action Required:
WDR Review - Pending:
WDR Review - Planned:
Not reported
Not reported
Not reported

Status Enrollee: N Individual/General: I

Fee Code:
Direction/Voice:
Enforcement Id(EID):
Region:

Not reported
Passive
222043
222043

Order / Resolution Number: R2-1998-0006

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 01/21/1998
Adoption/Issuance Date: Not reported
Achieve Date: Not reported
Termination Date: Not reported
ACL Issuance Date: Not reported
EPL Issuance Date: Not reported
Status: Active

Title: Enforcement - 2 438311N01

Description: SCR-CHANGED SOIL CLEANUP STANDARDS AND REQUIRED ADDITIONAL

TASKS

Program: UNREGS
Latest Milestone Completion Date: Not reported

Of Programs1: 1
Total Assessment Amount: 0
Initial Assessed Amount: 0
Liability \$ Amount: 0
Project \$ Amount: 0
Liability \$ Paid: 0
Project \$ Completed: 0
Total \$ Paid/Completed Amount: 0

2 Region: Facility Id: 224708 Agency Name: Not reported Facility Place Type: Place Subtype: Not reported Facility Type: Industrial Agency Type: Not reported # Of Agencies: Not reported Not reported Place Latitude: Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported Not reported SIC Desc 3: NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Distance

Elevation Site Database(s) EPA ID Number

FMC CORPORATION (Continued)

S102429620

EDR ID Number

Of Places: Enf Action Source Of Facility: Not reported Design Flow: Threat To Water Quality: Not reported Complexity: Not reported Pretreatment: Not reported Not reported Facility Waste Type: Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported Program: Not reported Not reported Program Category1: **NPDESWW** Program Category2: # Of Programs: Not reported WDID: Not reported Reg Measure Id: Not reported Reg Measure Type: Not reported Region: Not reported Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Reclamation: Not reported Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported Status: Not reported Status Date: Not reported Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported Not reported WDR Review - Pending: WDR Review - Planned: Not reported Status Enrollee: Not reported Individual/General: Not reported Fee Code: Not reported Direction/Voice: Not reported Enforcement Id(EID): 236038

Region: 2

Order / Resolution Number: R2-2001-0031

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 03/21/2001
Adoption/Issuance Date: Not reported
Achieve Date: Not reported
Termination Date: Not reported
ACL Issuance Date: Not reported
EPL Issuance Date: Not reported
Status: Active

Title: Enforcement - 2 438311002

Description: Final site cleanup requirements (CAO)

Program: NPDESWW
Latest Milestone Completion Date: Not reported

Of Programs1:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FMC CORPORATION (Continued)

S102429620

Total Assessment Amount: 0 0 Initial Assessed Amount: Liability \$ Amount: 0 Project \$ Amount: 0 Liability \$ Paid: 0 Project \$ Completed: 0 Total \$ Paid/Completed Amount: 0

HIST CORTESE:

Region: CORTESE Facility County Code: 43 WBC&D Reg By: 2 438311N01 Reg Id:

CIWQS:

FMC Corporation Philadelphia Agency:

Agency Address: Not reported Place/Project Type: Other SIC/NAICS: Not reported

Region:

NPDESWW Program: Regulatory Measure Status: Historical Regulatory Measure Type: **WDR** 97-00805 Order Number: WDID: 2 438311002 NPDES Number: Not reported Adoption Date: 01/15/1997 Effective Date: 01/15/1997 Not reported Termination Date: Expiration/Review Date: Not reported Design Flow: 0.015

Major/Minor: Not reported

Complexity: В TTWQ: 2 Enforcement Actions within 5 years: 0 Violations within 5 years: 0

Latitude: Not reported Longitude: Not reported

M94 SAN JOSE AUTO BODY & SERV CNTR

SSW **60 STOCKTON AV** 1/8-1/4 SAN JOSE, CA 95126

0.168 mi.

888 ft. Site 2 of 7 in cluster M Relative: CUPA SANTA CLARA:

Higher SANTA CLARA Region:

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 97 ft.

Latitude: 37.332406 Longitude: -121.904153 Record ID: PR0313021 Facility ID: FA0210240

S121470043

N/A

CUPA Listings

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

M95 **CENTURY COLLISION & SERVICE CENTER CUPA Listings** S121471731 N/A

SSW **60 STOCKTON AV**

1/8-1/4 SAN JOSE, CA 95126

0.168 mi.

888 ft. Site 3 of 7 in cluster M Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

PE#: 2205 Actual:

GENERATES 100 KG YR TO <5 TONS/YR Program Description: 97 ft.

Latitude: 37.332406 Longitude: -121.904153 Record ID: PR0364173 Facility ID: FA0250928

DHT COLLISION & SERVICE CENTER M96 **CUPA Listings** S121473542

SSW **60 STOCKTON AV** 1/8-1/4 **SAN JOSE, CA 95126**

0.168 mi.

Site 4 of 7 in cluster M 888 ft. CUPA SANTA CLARA: Relative:

Higher Region: SANTA CLARA

PE#: Actual:

GENERATES 100 KG YR TO <5 TONS/YR Program Description: 97 ft.

> Latitude: 37.332406 Longitude: -121.904153 Record ID: PR0380102 Facility ID: FA0259415

SANTA CLARA Region: PE#: Not reported

Program Description: HMBP FACILITY, 4-6 CHEMICALS

Latitude: 37.332406 Longitude: -121.904153 Record ID: PR0397060 Facility ID: FA0259415

M97 **SAN JOSE AUTO BODY** RCRA-SQG 1000121099 SSW **60 STOCKTON AVENUE CERS HAZ WASTE** CAD981572985

1/8-1/4 SAN JOSE, CA 95126 0.168 mi.

888 ft. Site 5 of 7 in cluster M **CUPA Listings EMI**

Relative: **SAN JOSE HAZMAT** Higher **CERS**

Actual:

97 ft. RCRA-SQG:

Date form received by agency: 09/01/1996

SAN JOSE AUTO BODY Facility name: Facility address: **60 STOCKTON AVENUE**

SAN JOSE, CA 95126 EPA ID: CAD981572985

Contact: Not reported Contact address: Not reported Not reported

Contact country: US

Contact telephone: Not reported **FINDS**

ECHO

N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE AUTO BODY (Continued)

1000121099

Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

> waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: KEITH BERGEY Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

NOT REQUIRED Owner/operator name: **NOT REQUIRED** Owner/operator address:

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Not reported Owner/operator extension: Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: Nο Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 09/26/1986

SAN JOSE AUTO BODY Site name:

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

SAN JOSE AUTO BODY (Continued)

1000121099

Classification: Large Quantity Generator

Violation Status: No violations found

CERS HAZ WASTE:

Site ID: 111355 CERS ID: 10354396

Hazardous Waste Generator CERS Description:

Violations:

Site ID: 111355

Site Name: **DLT COLLISION & SERVICE CENTER**

06-26-2015 Violation Date:

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: Violation Source: **CERS**

Site ID: 111355

Site Name: **DLT COLLISION & SERVICE CENTER**

Violation Date: 06-26-2015

22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Citation:

Chapter 12, Section(s) 66262.40(a)

Violation Description: Failure to maintain uniform hazardous waste manifest, consolidated

manifest, or bills of lading copies for three years.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Abandonment/Illegal

Disposal/Unauthorized Treatment - General

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes: Violation Division:

Santa Clara County Environmental Health

Map ID MAP FINDINGS
Direction

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Violation Program: HW
Violation Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Violation Date: 06-26-2015

Citation: 49 CFR 1 172.201(e) - U.S. Code of Federal Regulations, Title 49,

Chapter 1, Section(s) 172.201(e)

Violation Description: Failure of the universal waste handler to properly package, label,

mark, placard, or prepare and retain shipping papers for all universal waste being shipped to another universal waste handler, destination

facility, or foreign facility.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Violation Date: 06-26-2015

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: ______ Facility

last submitted an HMBP in 2012. Submit a complete HMBP on FrontCounter or CERS. Ensure all three HMBP sections (Facility Information,

Hazardous Materials Inventory, and Emergency Response and Training

Plans) are submitted annually to re-certify the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Violation Date: 06-26-2015

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers with

the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous

Waste, and starting accumulation date.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Violation Date: 06-26-2015

Citation: HSC 6.5 25189.5(a) - California Health and Safety Code, Chapter 6.5,

Section(s) 25189.5(a)

Violation Description: Failure to properly dispose of hazardous waste at an authorized

location.

Map ID MAP FINDINGS
Direction

Distance EDR ID Number
Elevation Site EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Violation Date: 06-26-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Violation Date: 06-26-2015

Citation: 40 CFR 1 262.34(d)(5)(ii) - U.S. Code of Federal Regulations, Title

40, Chapter 1, Section(s) 262.34(d)(5)(ii)

Violation Description: Failure to post, next to the telephone, Emergency Information (SQG)

containing the location of emergency equipment, contact names and

numbers.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-26-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair and body facility. Currently generating used oil, used oil filters, paint solvent waste, debris contaminated with paint and

solvent, and universal waste fluorescent tubes. Spray booth filters are exchanged by service company. EPA ID# CAL000379665 is active.

eMail: dltauto888@yahoo.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-26-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair and body work facility. Currently storing used oil (3x 55

gallons), acetylene (2x 150 cuft), oxygen (1x 251 and 2x 150 cuft), and 75% Argon/25% carbon dioxide (1x 250 and 3x 141 cuft) in HMBP

quantities. Also storing various paint tints, solvents, aerosols in smaller quantities. NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents retained for 3 years. Contact me for more information. A sample training log attached with

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

this report.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 03-01-2018

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On-site to conduct a permit investigation at DLT Collision & Service

Center with Manager Justin Phan. This facility is an auto body shop that provides welding services. I observed the following Hazardous Materials at or above HMBP quantities: - 2 x 55 gal Used Oil - 2 x 150 cubic ft Acetylene - 2 x 150 cubic ft + 251 cubic ft Oxygen New Oil was also observed but it is stored at quantities under the HMBP thresholds (1 x 55 gal). Based on my permit investigation, the permit should be adjusted to BP01. NOTES: - Contact name: Justin Phan - Contact number: (408) 288-8856 - Contact e-mail: dltauto888@yahoo.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Enforcement Action:

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Site Address: 60 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 06-26-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP Enf Action Source: CERS

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Site Address: 60 STOCKTON AV Site City: SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 06-26-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW
Enf Action Source: CERS

Affiliation:

Affiliation Type Desc: Environmental Contact

Entity Name: Justin Phan Entity Title: Not reported

Affiliation Address: 60 STOCKTON AVE

Affiliation City: SAN JOSE Affiliation State: CA

Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: (408) 288-8856

Parent Corporation Affiliation Type Desc: DLT COLLISION **Entity Name:** Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 60 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95126
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Legal Owner

NGUYEN, LINDA

Not reported

60 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 288-8856

Affiliation Type Desc: Operator Entity Name: LINDA NGUYEN **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: (408) 288-8856

Affiliation Type Desc: Property Owner

Entity Name: Linda Nguyen and David Phan

Entity Title: Not reported

Direction Distance Elevation

ation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

United States

Not reported

(408) 316-4645

Affiliation Type Desc: **Document Preparer** Entity Name: Justin Phan **Entity Title:** Not reported Not reported Affiliation Address: Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: Justin Phan Entity Title: Manager Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

FINDS:

Registry ID: 110010462436

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000121099 Registry ID: 110010462436

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110010462436

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.332615

 Longitude:
 -121.904624

 Record ID:
 PR0411436

Direction
Distance
Elevation

tion Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Facility ID: FA0272069

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.332615

 Longitude:
 -121.904624

 Record ID:
 PR0411435

 Facility ID:
 FA0272069

EMI:

 Year:
 1996

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:

BAY AREA AQMD
Not reported
Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1997

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1998

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0

Direction Distance Elevation

nce EDR ID Number tion Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1999

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2000

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:

BAY AREA AQMD
Not reported
Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2001

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1

Reactive Organic Gases Tons/Yr: 1
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2002

Direction Distance Elevation

n Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2003

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2004

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:

Not reported
Not reported
0.552
Reactive Organic Gases Tons/Yr:
0.5117294

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2005

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD

Direction Distance Elevation

Site Database(s) EPA ID Number

BAY AREA AQMD

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: .552 Reactive Organic Gases Tons/Yr: .5117294 Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2006

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: .552 .5117294 Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2007

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: .552 Reactive Organic Gases Tons/Yr: .5117294 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2008

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 8417

 Air District Name:
 BA

 SIC Code:
 7532

NOX - Oxides of Nitrogen Tons/Yr:

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

Total Organic Hydrocarbon Gases Tons/Yr:

Reactive Organic Gases Tons/Yr:

Carbon Monoxide Emissions Tons/Yr:

BAY AREA AQMD

Not reported

552

5117294

0

0

Direction Distance

Elevation Site Database(s) **EPA ID Number**

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2009 County Code: 43 Air Basin: SF Facility ID: 8417 Air District Name: BA SIC Code: 7532

Air District Name: **BAY AREA AQMD** Not reported Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0.55200000000000005

Reactive Organic Gases Tons/Yr: 0.5117294

Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 403223 Class: Auto Repair

CERS TANKS:

Site ID: 111355 CERS ID: 10354396

CERS Description: Chemical Storage Facilities

Violations:

Site ID:

Site Name: **DLT COLLISION & SERVICE CENTER**

Violation Date: 06-26-2015

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: Violation Source: **CERS**

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Citation:

Chapter 12, Section(s) 66262.40(a)

Violation Description: Failure to maintain uniform hazardous waste manifest, consolidated

manifest, or bills of lading copies for three years.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWViolation Source: **CERS**

Violation Notes:

Map ID MAP FINDINGS Direction

Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

SAN JOSE AUTO BODY (Continued)

1000121099

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter Citation:

6.5, Section(s) Multiple Sections

Haz Waste Generator Program - Abandonment/Illegal Violation Description:

Disposal/Unauthorized Treatment - General

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 111355

Site Name: **DLT COLLISION & SERVICE CENTER**

Violation Date: 06-26-2015

HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Citation:

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes:

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 111355

Site Name: **DLT COLLISION & SERVICE CENTER**

Violation Date: 06-26-2015

Citation: 49 CFR 1 172.201(e) - U.S. Code of Federal Regulations, Title 49,

Chapter 1, Section(s) 172.201(e)

Violation Description: Failure of the universal waste handler to properly package, label,

mark, placard, or prepare and retain shipping papers for all universal waste being shipped to another universal waste handler, destination

facility, or foreign facility.

Santa Clara County Environmental Health Violation Division:

Violation Program: HW **CERS** Violation Source:

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Citation:

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Facility last submitted an HMBP in 2012. Submit a complete HMBP on FrontCounter

or CERS. Ensure all three HMBP sections (Facility Information,

Hazardous Materials Inventory, and Emergency Response and Training Plans) are submitted annually to re-certify the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HMRRP** Violation Source: **CERS**

Map ID MAP FINDINGS Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE AUTO BODY (Continued)

1000121099

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Citation:

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers with

> the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous

Waste, and starting accumulation date.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

Citation: HSC 6.5 25189.5(a) - California Health and Safety Code, Chapter 6.5,

Section(s) 25189.5(a)

Violation Description: Failure to properly dispose of hazardous waste at an authorized

location.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes:

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: HW **CERS** Violation Source:

Site ID: 111355

DLT COLLISION & SERVICE CENTER Site Name:

Violation Date: 06-26-2015

40 CFR 1 262.34(d)(5)(ii) - U.S. Code of Federal Regulations, Title Citation:

40, Chapter 1, Section(s) 262.34(d)(5)(ii)

Violation Description: Failure to post, next to the telephone, Emergency Information (SQG)

containing the location of emergency equipment, contact names and

numbers.

Violation Notes:

Violation Division: Santa Clara County Environmental Health

Violation Program: **CERS** Violation Source:

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-26-2015

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair and body facility. Currently generating used oil, used oil

filters, paint solvent waste, debris contaminated with paint and solvent, and universal waste fluorescent tubes. Spray booth filters are exchanged by service company. EPA ID# CAL000379665 is active.

eMail: dltauto888@yahoo.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-26-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Auto repair and body work facility. Currently storing used oil (3x 55

gallons), acetylene (2x 150 cuft), oxygen (1x 251 and 2x 150 cuft), and 75% Argon/25% carbon dioxide (1x 250 and 3x 141 cuft) in HMBP

quantities. Also storing various paint tints, solvents, aerosols in smaller quantities. NOTE: Beginning January 1, 2015 all annual HBMP training must be decumented and the decuments retained for 2 years.

training must be documented and the documents retained for 3 years. Contact me for more information. A sample training log attached with

this report.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 03-01-2018

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On-site to conduct a permit investigation at DLT Collision & Service

Center with Manager Justin Phan. This facility is an auto body shop that provides welding services. I observed the following Hazardous Materials at or above HMBP quantities: - 2 x 55 gal Used Oil - 2 x 150 cubic ft Acetylene - 2 x 150 cubic ft + 251 cubic ft Oxygen New Oil was also observed but it is stored at quantities under the HMBP thresholds (1 x 55 gal). Based on my permit investigation, the permit should be adjusted to BP01. NOTES: - Contact name: Justin Phan - Contact number: (408) 288-8856 - Contact e-mail: dltauto888@yahoo.com

Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Enforcement Action:

Eval Division:

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Site Address: 60 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 06-26-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP Enf Action Source: CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Site ID: 111355

Site Name: DLT COLLISION & SERVICE CENTER

Site Address: 60 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 06-26-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW
Enf Action Source: CERS

Affiliation:

Affiliation Type Desc: Environmental Contact

Entity Name: Justin Phan Entity Title: Not reported

Affiliation Address: 60 STOCKTON AVE

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95126

Affiliation Phone: (408) 288-8856

Parent Corporation Affiliation Type Desc: DLT COLLISION Entity Name: Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 60 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Legal Owner

NGUYEN, LINDA

Not reported

Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO BODY (Continued)

1000121099

EDR ID Number

Affiliation Address: 60 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 288-8856

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Not reported

Not reported

Not reported

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 288-8856

Affiliation Type Desc: Property Owner

Entity Name: Linda Nguyen and David Phan

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Value States

Not reported

Value States

Not reported

Value States

Va

Affiliation Type Desc: Document Preparer

Entity Name: Justin Phan Entity Title: Not reported Affiliation Address: Not reported Not reported Affiliation City: Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer

Entity Name: Justin Phan Entity Title: Manager Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Not reported Affiliation Phone:

Direction Distance

Elevation Site Database(s) EPA ID Number

98 RIVER STREET PROJECT LUST S105086170
ENE 350 W JULIAN ST HIST LUST N/A

350 W JULIAN ST HIST LUST N/A SAN JOSE, CA 95112 CERS

1/8-1/4 0.171 mi. 904 ft.

Relative: LUST:

Lower Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

82 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608589591

Global Id: T0608589591 Latitude: 37.336177 Longitude: -121.899509

Status: Completed - Case Closed

Status Date: 07/23/2001
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608589591

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608589591

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 05/01/2001

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608589591

 Action Type:
 Other

 Date:
 09/22/2000

 Action:
 Leak Reported

 Global Id:
 T0608589591

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

EDR ID Number

Direction Distance Elevation

vation Site Database(s) EPA ID Number

RIVER STREET PROJECT (Continued)

S105086170

EDR ID Number

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 01/01/2000

 Action:
 Correspondence

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 04/03/2001

Action: Preliminary Site Assessment Report

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 05/09/2001

Action: Soil and Water Investigation Report

Global Id: T0608589591
Action Type: RESPONSE
Date: 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 09/21/2000

Action: Unauthorized Release Form

 Global Id:
 T0608589591

 Action Type:
 ENFORCEMENT

 Date:
 05/09/2001

Action: Staff Letter - #27138

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 06/18/2001

 Action:
 Request for Closure

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 03/29/2001

 Action:
 Other Workplan

 Global Id:
 T0608589591

 Action Type:
 RESPONSE

 Date:
 05/17/2001

Action: Soil and Water Investigation Report

LUST:

Global Id: T0608589591

Status: Completed - Case Closed

Status Date: 07/23/2001

Global Id: T0608589591

Status: Open - Case Begin Date

Direction Distance

Elevation Site Database(s) EPA ID Number

RIVER STREET PROJECT (Continued)

S105086170

EDR ID Number

Status Date: 08/30/2000

Global Id: T0608589591

Status: Open - Site Assessment

Status Date: 08/30/2000

LUST REG 2:

Region: 2

Facility Id: Not reported Case Closed Facility Status: Case Number: 07S1E07J01f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 8/30/2000 Pollution Characterization Began: 8/30/2000 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07J01F

 Date Closed:
 07/23/2001

 EDR Link ID:
 07S1E07J01F

HIST LUST SANTA CLARA:

Region: SANTA CLARA
Region Code: 2
SCVWD ID: 07S1E07J01
Oversite Agency: SCVWD

Date Listed: 2000-10-16 00:00:00 Closed Date: 2001-07-23 00:00:00

CERS TANKS:

 Site ID:
 195977

 CERS ID:
 T0608589591

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RIVER STREET PROJECT (Continued)

S105086170

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

N99 SAN JOSE ARENA RITCHEY PARCEL LUST S105194819 **60 MONTGOTMERY ST N** SE **CERS** N/A

1/8-1/4 **SAN JOSE, CA 95110**

0.174 mi.

919 ft. Site 2 of 2 in cluster N

LUST: Relative:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: LUST Cleanup Site Actual:

Geo Track: 87 ft.

http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501981

Global Id: T0608501981 Latitude: 37.3319732 Longitude: -121.9012464

Completed - Case Closed Status:

04/09/1997 Status Date: Case Worker: UUU RB Case Number: 43-2157

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608501981

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

1515 CLAY ST SUITE 1400 Address:

City: OAKLAND Not reported Email: Phone Number: Not reported

Global Id: T0608501981

Local Agency Caseworker Contact Type: Contact Name: UST CASE WORKER SANTA CLARA COUNTY LOP Organization Name: 1555 Berger Drive, Suite 300 Address:

SAN JOSE City: Email: Not reported Phone Number: 4089183400

LUST:

T0608501981 Global Id: Action Type: Other 04/21/1997 Date: Leak Reported Action:

Direction Distance

Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA RITCHEY PARCEL (Continued)

S105194819

EDR ID Number

Global Id: T0608501981 **RESPONSE** Action Type: 01/01/1997 Date:

Action: Other Report / Document

Global Id: T0608501981 Action Type: **ENFORCEMENT** Date: 04/09/1997

Action: Closure/No Further Action Letter

Global Id: T0608501981 Action Type: Other 04/21/1997 Date: Action: Leak Discovery

Global Id: T0608501981 Other Action Type: 04/21/1997 Date: Action: Leak Stopped

LUST:

T0608501981 Global Id:

Status: Completed - Case Closed

04/09/1997 Status Date:

Global Id: T0608501981

Open - Case Begin Date Status:

Status Date: 04/09/1997

LUST REG 2:

Region: 2 43-2157 Facility Id: Case Closed Facility Status: Case Number: 07S1E07Q13 How Discovered: Tank Closure Leak Cause: UNK Leak Source: UNK

Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

CERS TANKS:

Site ID: 203022 CERS ID: T0608501981

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA RITCHEY PARCEL (Continued)

S105194819

1555 Berger Drive, Suite 300 Affiliation Address:

SAN JOSE Affiliation City: Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

P100 **PG&E: CINNABAR SERVICE CENTER** AST A100423348 N/A

WSW 308 STOCKTON AV SAN JOSE, CA 95126 1/8-1/4

0.190 mi.

1001 ft. Site 1 of 15 in cluster P

Relative: AST:

Higher Certified Unified Program Agencies: Not reported

Pacific Gas & Electric Company Actual:

Total Gallons: Not reported 92 ft. CERSID: 10146769 Facility ID: FA0208679 **Business Name:**

PG&E Phone: (408) 299-1179 (408) 299-1006 Fax: Mailing Address: PO Box 7640 San Francisco Mailing Address City:

Mailing Address State: CA Mailing Address Zip Code: 94120

Operator Name: Pacific Gas & Electric Company

Operator Phone: (408) 202-8186 (415) 973-7000 Owner Phone:

Owner Mail Address: c/o Environmental Services, 3401 Crow Canyon Road

Owner State: 94583 Owner Zip Code: Owner Country: **United States**

Property Owner Name: Pacific Gas & Electric Company

Property Owner Phone: (415) 973-7000

Property Owner Mailing Address: c/o Environmental Services, 3401 Crow Canyon Road

Property Owner City: San Ramon Property Owner Stat: CA Property Owner Zip Code: 94583 Property Owner Country: **United States** EPAID: CAD981409725

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

P101 **PG&E CINNABAR SERVICE CTR** LUST S106610927

N/A

N/A

WSW 308 STOCKTON AVE 1/8-1/4 SAN JOSE, CA 95126

0.190 mi.

1001 ft. Site 2 of 15 in cluster P

Relative: LUST REG 2: Higher Region:

Facility Id: Not reported Actual:

Facility Status: Case Closed 92 ft. Case Number: 07S1E07L07f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported

> Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported 8/21/2000 Preliminary Site Assesment Began: Pollution Characterization Began: 1/21/2002 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

SWEEPS UST \$106930410

P102 **PACIFIC GAS & ELECTRIC CO** wsw **308 STOCKTON AVENUE VECH** SAN JOSE, CA 95126

1/8-1/4

0.190 mi. 1001 ft. Site 3 of 15 in cluster P

Relative: SWEEPS UST:

Higher Active Status: Comp Number: 405875 Actual: Number: 92 ft.

> Board Of Equalization: Not reported Referral Date: 09-30-92 Action Date: 09-08-92 Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-405875-000001

Tank Status: 10000 Capacity: Active Date: Not reported Tank Use: M.V. FUEL

STG:

REG UNLEADED Content:

Number Of Tanks:

Status: Active 405875 Comp Number: Number: 9

Board Of Equalization: Not reported Referral Date: 09-30-92 Action Date: 09-08-92 Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-405875-000002

Tank Status: 10000 Capacity: Active Date: Not reported Tank Use: M.V. FUEL

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PACIFIC GAS & ELECTRIC CO (Continued)

S106930410

STG: Ρ DIESEL Content: Number Of Tanks: Not reported

Status: Active 405875 Comp Number: Number:

Board Of Equalization: Not reported Referral Date: 09-30-92 Action Date: 09-08-92 02-29-88 Created Date: Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-405875-000003

Tank Status: Capacity: 15000 Active Date: Not reported Tank Use: M.V. FUEL

STG:

REG UNLEADED Content: Number Of Tanks: Not reported

Status: Active Comp Number: 405875 Number: Board Of Equalization: Not reported

Referral Date: 09-30-92 09-08-92 Action Date: Created Date: 02-29-88 Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-405875-000004

Tank Status: Capacity: 1000 Active Date: Not reported

Tank Use: OIL STG: W

Content: Not reported Number Of Tanks: Not reported

P103 **CINNABAR SERVICE CENTER**

wsw 308 STOCKTON AVE. 1/8-1/4 SAN JOSE, CA

0.190 mi.

1001 ft. Site 4 of 15 in cluster P

Relative: AST:

Higher Certified Unified Program Agencies: Santa Clara County

PG&E Owner: Actual: Total Gallons: 92 ft. 1,770

CERSID: Not reported Facility ID: Not reported Business Name: Not reported Phone: Not reported Not reported Fax: Mailing Address: Not reported Mailing Address City: Not reported Mailing Address State: Not reported Mailing Address Zip Code: Not reported Operator Name: Not reported AST

A100323425

N/A

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

CINNABAR SERVICE CENTER (Continued)

A100323425

S121775003

N/A

Operator Phone: Not reported Not reported Owner Phone: Not reported Owner Mail Address: Not reported Owner State: Owner Zip Code: Not reported Owner Country: Not reported Not reported Property Owner Name: Property Owner Phone: Not reported Property Owner Mailing Address: Not reported Property Owner City: Not reported Property Owner Stat: Not reported Property Owner Zip Code: Not reported Property Owner Country: Not reported EPAID: Not reported

P104 PG&E: CINNABAR SERVICE CENTER

WSW 308 STOCKTON AV 1/8-1/4 SAN JOSE, CA 95126

0.190 mi.

1001 ft. Site 5 of 15 in cluster P

Relative: CERS HAZ WASTE:

 Higher
 Site ID:
 399422

 Actual:
 CERS ID:
 10146769

92 ft. CERS Description: Hazardous Waste Generator

Violations:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter

16, Section(s) 2641(a)

Violation Description: Failure of sensor to be located in the proper position/location.

Violation Notes: SENSOR TESTING, L-1, L-2, L-3, DISPENSER SENSORS, ALL THREE FAIL.

NOTE: PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE. REPAIR OR REPLACE THE DISPENSER

CERS HAZ WASTE

CERS TANKS

CERS

SENSORS WITHIN THE NEXT 30 DAYS. .

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16,

Section(s) 2665

Violation Description: Failure to comply with one or more of the following: failure to

install a spill bucket, have a functional drain valve or other method

for the removal of liquid from the spill bucket/spill container,

and/or be resistant to galvanic corrosion.

Violation Notes: THE SPILL BUCKET ON THE TANK #3 FAILED THE WATER TEST AND COULD NOT BE

SERVICED AT THE TIME OF TESTING. tHIS BUCKET IS NOT IN COMPLIANCE AND SHALL BE SERVICED, REPAIRED, OR REPLACED. PROVIDE A PLAN OF ACTION, TO THIS OFFICE. THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE.

REPAIR OR REPLACE THE SPILL BUCKET WITHIN THE NEXT 30 DAYS.

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-02-2018

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: I am on site for the 2018 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2019 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK

Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1:

UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular, NOTE: This annular space was found to have a small bit of water in it. A Vacuum drew about a quart of water from the annular space. L-1, L-2, L-3, dispenser UDC sensors, [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-04-2016 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2016 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email InI5@pge.com UST Operating Permit to be issued by this office. SB-989 Testing to be conducted in May 2016. To be scheduled. Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Monitoring System Certification. ICC # 8017001 Serv Tech Expires 6/9/2017 VR B-36532- Expires, 6/28/2017 3754183706 12/23/2016 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown, Audio and Visual Alarm, Print, OK L-4, L-5, L-6, Used

Oil AST sensors, Audio and Visual Alarm, Print, OK L-7, L-8, L-9, L-10,L-11, L-12, UST [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 06-10-2016

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: ON-SITE TO OVERSEE SENSOR FUNCTIONALITY (MONITORING COLD-START)

INSPECTION. TESTING WAS CONDUCTED BY GARRETT WARREN WITH TAIT ENVIRONMENTAL. MR WARREN HAS THE FOLLOWING CERTIFICATIONS; ICC#00206654 EXP., 10/2/17; VR#B42126 EXP., 1/8/17. PRIOR TO TESTING

OF THE SENSORS THERE WERE NO ACTIVE ALARMS AT THE VEEDER ROOT PANEL. THE FOLLOWING SENSORS WERE TESTED AND PASSED DURING THIS INSPECTION; -3 STP SUMPS SENSORS -3 ANNULAR SENSORS -3 UDC SENSORS -3 ATG PROBES

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

FOR OVERFILL ALARM WERE TESTED ** ALL SENSORS ABOVE PROVIDED AND AUDIBLE AND VISUAL ALARM AT THE VEEDER ROOT ADDITIONALLY THE FOLLOWING SENSORS WERE TESTED BY THE TECHNICIAN FOR THE ABOVE GROUND USED OIL TANK, AS THESE SENSORS ARE CONNECTED TO THE VEEDER ROOT PANEL. - 1 ANNULAR SENSOR (L5) - 1 OUTER ANNULAR SPACE SENSOR (L6) - 1 SECONDARY PIPING SUMP (L7) NOTES: THIS INSPECTION REPORT CLOSES OUT PERMIT

SR0850423 WITH OUR DEPARTMENT.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-03-2017 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2017 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com The record of Inspection and Monitoring System Certification for SR0850423 was copied from on site records. Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2017 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1: UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: ON SITE IN PART TO REVIEW THE HAZARDOUS MATERIALS BUSINESS PLAN (HMBP)

AND INVENTORY IN THE CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM (CERS) SYSTEM WITH WHAT IS STORED ON SITE IN THE UNDERGROUND STORAGE TANK (UST) SYSTEMS (3). DAVE WILCOX, SHOP MANAGER, PG&E, ON SITE TO PROVIDE ACCESS, RECORDS, AND INFORMATION. THERE ARE 3 UST s, 2 PETROLEUM DIESEL, 1 UNLEADED 87 GASOLINE. THE RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE FROM HENNER TANK LINES, INC.

PO BOX 867 WINTERS, CA RECEIPTS FROM 10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). DAVE WILCOX SHARED THE FOLLOWING INFORMATION: IN THE PAST, ABOUT 4 YEARS AGO, DIESEL B-20 HAD REPLACED PETROLEUM DIESEL

IN THE TWO DIESEL TANKS. FILTRATION CAPACITY AND CLOGGING WAS A

PROBLEM. [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Eval General Type: Other/Unknown Eval Date: 04-16-2015

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site to confirm spill bucket test after replacing the swivel

connection. Lin Leung, Env. Compliance Manager, PG&E, on site to

facilitate access. Garrett Warren, UST Service Tech, TAIT

ENVIRONMENTAL, on site to conduct service and testing. ICC 8185019 exp. 10/4/2015, Incon/Franklin Cert. Level 4, #3754183706 Exp. 2/2/2017 Tank #2, Spill bucket, direct bury, tested with water and Incon accelerated tester. Tested two times, both pass, ok NOTE: Include this testing and results in the 2015 UST Monitoring System

Certification Report.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: ON SITE FOR THE 2014 UNDERGROUND STORAGE TANK (UST) MONITORING SYSTEM

CERTIFICATION. LIN LEUNG, PG&E, ON SITE TO PROVIDE ACCESS TO THE FACILITY AN RECORDS, LIN LEUNG, PG&E, IS THE DESIGNATED UST OPERATOR

(DUSTO). ICC#8013042-UC, EXP. 1/30/2015. PATTRIC BANBURY, TAIT ENVIRONMENTAL SERVICES, UST SERVICE TECH, ICC# 5254955, EXP. 1/26/2015, VEEDER-ROOT #A20465, LEVEL 4, EXP. 1/7/2015, FRANKLIN FUEL/INCON LEVEL 4, CERT#8613043701, EXP. 7/26/2015 TANK-1, 15,000 GASOLINE TANK-2, 10,000 DIESEL-1 TANK-3, 10,000 DIESEL-2 NOTE: THE

RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE

FROM HENNER TANK LINES, INC. PO BOX 867 WINTERS, CA RECEIPTS FROM

10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993,

DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). SYSTEM SETUP

AND ALARM HISTORY [Truncated]
Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval Division:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-06-2015

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: On site, 308 Stockton Ave. San Jose, for the 2015 UST Monitoring

System Certification. Lin Leung, Environmental Compliance Specialist, PG&E, On site to provide facility accessm and records review. will send inspection report to InI5@pge.com John Cascio, UST Service TAIT ENVIRONMENTAL, ICC 5252163 Exp. 7/5/2015, Veeder-Root B35337 Exp. 2/5/2017 INCON, 6929323704-Lvl. 4 Exp. 11/5/2016 System Set-up and

Alarm History provided DUSTO reports reviewed, OK Financial Responsibility, OK CERS Review, OK, Approved. Spill Buckets (3) tested with INCON accelerated test in water, several failures due to nearby passing trains. Diesel #2 Spill Bucket showed visible drop, serviced, re-test. FAIL, Service and Re-schedule testing. Diesel #1 and

gasoline, Pass, OK All sensors tested, Dispensers (3), Pump shutdown, Audio and Visual Alarm, Print, OK Piping Sumps (3), Audio and Visual

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Alarm, Print, OK Annular Space (3), Audio and Visual Alarm, Print,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST **Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 05-10-2016 Violations Found: No

Eval Type: Routine done by local agency

Onsite today for routine aboveground petroleum storage act inspection, **Eval Notes:**

noted the following: -CUPA/Santa Clara County contact number and information updated in plan under Additional Numbers today by Lin. -The SPCC is stored onsite. -The SPCC is certified by a PE. -The SPCC has management approval, it occurred on 5-10-16. -Inspections are being performed monthly and annually and records are maintained; records were reviewed today, including any electronic monitoring equipment certification documents. -Tank and container areas are free of leaks and provided with adequate secondary containment. No

violations were noted today, thank you. Santa Clara County Environmental Health

Eval Program: **APSA Eval Source: CERS**

Eval Division:

Eval General Type: Other/Unknown 05-16-2016 **Eval Date:**

Violations Found:

Eval Type: Other, not routine, done by local agency

Eval Notes: On site, 308 Stockton Ave., PG&E-Cinabar, for the 2016 UST Secondary

Containment Testing. Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Secondary Containment Testing. ICC # 8017001 Serv Tech Expires 6/9/2017 Franklin Fueling #3754183706 (Incon Level 4) 12/23/2016 One UST test (2 of 3 UST's are hydrostatic secondary), vacuum of 10 in Hg, 60 minutes, no drop, OK 3 STP sumps tested, Incon Accelerated test. Each sump passed 2 consecutive tests OK 3 piping runs tested, 5 psi air, 60 minutes, no drop in pressure observed. OK 3 UDCs being tested, Incon accelerated test, Each UDC to pass 2

consecutive tests. (PG&E standard) NOTE: Submit the 2016 UST Secondary

Containment testing report to this office within 30 days.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST **Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-30-2016

Violations Found:

Eval Type: Routine done by local agency

I was on site, 308 Stockton, for the 2016 Hazardous Waste Generator **Eval Notes:**

> permit inspection. Lin Leung, Environmental Field Specialist, was on site to provide facility access and records review. The 4/8/2014 Notice of Inspection (NOI) Return to Compliance (RTC) was received for the record. Facility inspection; The 350 gallon generator has a

spill/accumulation of oily debris below it that shall be cleaned from the concrete pad below the generator tank. The system shall be confirmed to be product tight. If this unit is to be closed, then

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

identify the time line for fuel removal and closure and the current remaining fuel in the system. A 5 gallon orange "Homer" bucket was observed containing a small oil filled vessel. This was from a service truck as is to be managed properly. Any usable parts are to be identified, removed, prior to discarding as waste. All hazardous waste containers observed were closed, labeled, and in good order. Records

review; I reviewed [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: **CERS**

Enforcement Action:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Site Address: 308 STOCKTON AV

Site City: SAN JOSE Site Zip: 95126 Enf Action Date: 04-08-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: UST **CERS** Enf Action Source:

Affiliation:

Affiliation Type Desc: **Document Preparer Entity Name:** Liza Marfori, Parsons

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Entity Name: Lin Leung Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address Entity Title: Not reported Affiliation Address: PO Box 7640 Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 94120 Affiliation Phone: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Affiliation Type Desc: Operator

Pacific Gas & Electric Company **Entity Name:**

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 726-1128

Affiliation Type Desc: **UST Permit Applicant**

Entity Name: Lin Leung

Entity Title: **Environmental Field Specialist**

Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Identification Signer Entity Name: **Daniel Sanchez**

Entity Title: Hazardous Materials & Water Quality Manager

Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Legal Owner Affiliation Type Desc:

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon

Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 94583 (415) 973-7000 Affiliation Phone:

Affiliation Type Desc: Property Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 94583

Affiliation Phone: (415) 973-7000

UST Tank Operator Affiliation Type Desc: Entity Name: PG&E - Attn: Lin Leung

Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: **United States**

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: UST Tank Owner

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94105
Affiliation Phone: (415) 973-7204

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation

PG&E Entity Name: Not reported Entity Title: Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: UST Property Owner Name

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

Site ID: 399422 CERS ID: 10146769

CERS Description: RCRA LQ HW Generator

Violations:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter

16, Section(s) 2641(a)

Violation Description: Failure of sensor to be located in the proper position/location.

Violation Notes: SENSOR TESTING, L-1, L-2, L-3, DISPENSER SENSORS, ALL THREE FAIL.

NOTE: PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE, REPAIR OR REPLACE THE DISPENSER

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

SENSORS WITHIN THE NEXT 30 DAYS. .

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16,

Section(s) 2665

Violation Description: Failure to comply with one or more of the following: failure to

install a spill bucket, have a functional drain valve or other method

for the removal of liquid from the spill bucket/spill container,

and/or be resistant to galvanic corrosion.

Violation Notes: THE SPILL BUCKET ON THE TANK #3 FAILED THE WATER TEST AND COULD NOT BE

SERVICED AT THE TIME OF TESTING. tHIS BUCKET IS NOT IN COMPLIANCE AND SHALL BE SERVICED, REPAIRED, OR REPLACED. PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE,

REPAIR OR REPLACE THE SPILL BUCKET WITHIN THE NEXT 30 DAYS.

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-02-2018 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: I am on site for the 2018 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO,
Environmental Field Specialist, PG&E, on site to allow access and
records review. email InI5@pge.com Warren Garrett, Tait Environmental
Services, Inc. 588098, on site to conduct UST Monitoring System
Certification. ICC# 206654 Serv Tech Expires 10/1/2019 VR B42126 Exp
1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System
Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK

Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1:

UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular, NOTE: This annular space was found to have a small bit of water in it. A Vacuum drew about a quart of water from the annular space. L-1, L-2, L-3, dispenser UDC sensors, [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-04-2016 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2016 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email InI5@pge.com UST Operating Permit to be issued by this office. SB-989 Testing to be conducted in May 2016. To be scheduled. Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Monitoring System Certification.

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

ICC # 8017001 Serv Tech Expires 6/9/2017 VR B-36532- Expires, 6/28/2017 3754183706 12/23/2016 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown, Audio and Visual Alarm, Print, OK L-4, L-5, L-6, Used Oil AST sensors, Audio and Visual Alarm, Print, OK L-7, L-8, L-9,

L-10,L-11, L-12, UST [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 06-10-2016

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: ON-SITE TO OVERSEE SENSOR FUNCTIONALITY (MONITORING COLD-START)

INSPECTION. TESTING WAS CONDUCTED BY GARRETT WARREN WITH TAIT ENVIRONMENTAL. MR WARREN HAS THE FOLLOWING CERTIFICATIONS; ICC#00206654 EXP., 10/2/17; VR#B42126 EXP., 1/8/17. PRIOR TO TESTING

OF THE SENSORS THERE WERE NO ACTIVE ALARMS AT THE VEEDER ROOT PANEL. THE FOLLOWING SENSORS WERE TESTED AND PASSED DURING THIS INSPECTION; -3 STP SUMPS SENSORS -3 ANNULAR SENSORS -3 UDC SENSORS -3 ATG PROBES FOR OVERFILL ALARM WERE TESTED ** ALL SENSORS ABOVE PROVIDED AND AUDIBLE AND VISUAL ALARM AT THE VEEDER ROOT ADDITIONALLY THE FOLLOWING SENSORS WERE TESTED BY THE TECHNICIAN FOR THE ABOVE GROUND USED OIL TANK, AS THESE SENSORS ARE CONNECTED TO THE VEEDER ROOT PANEL. - 1 ANNULAR SENSOR (L5) - 1 OUTER ANNULAR SPACE SENSOR (L6) - 1 SECONDARY

PIPING SUMP (L7) NOTES: THIS INSPECTION REPORT CLOSES OUT PERMIT SR0850423 WITH OUR DEPARTMENT.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-03-2017 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2017 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com The record of Inspection and Monitoring System Certification for SR0850423 was copied from on site records. Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2017 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1: UNLEADED - Wet annular

Approved submittal, OK 3 USTs, Tank ID # T1: UNLEADED - Wet annula Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: ON SITE IN PART TO REVIEW THE HAZARDOUS MATERIALS BUSINESS PLAN (HMBP)

AND INVENTORY IN THE CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM (CERS) SYSTEM WITH WHAT IS STORED ON SITE IN THE UNDERGROUND STORAGE TANK (UST) SYSTEMS (3). DAVE WILCOX, SHOP MANAGER, PG&E, ON SITE TO PROVIDE ACCESS, RECORDS, AND INFORMATION. THERE ARE 3 UST s, 2 PETROLEUM DIESEL, 1 UNLEADED 87 GASOLINE. THE RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE FROM HENNER TANK LINES, INC.

PO BOX 867 WINTERS, CA RECEIPTS FROM 10/10/2013, 11/3/2013, AND

1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). DAVE WILCOX SHARED THE FOLLOWING INFORMATION: IN THE PAST, ABOUT 4 YEARS AGO, DIESEL B-20 HAD REPLACED PETROLEUM DIESEL

IN THE TWO DIESEL TANKS. FILTRATION CAPACITY AND CLOGGING WAS A

PROBLEM. [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 04-16-2015

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site to confirm spill bucket test after replacing the swivel

connection. Lin Leung, Env. Compliance Manager, PG&E, on site to

facilitate access. Garrett Warren, UST Service Tech, TAIT

ENVIRONMENTAL, on site to conduct service and testing. ICC 8185019 exp. 10/4/2015, Incon/Franklin Cert. Level 4, #3754183706 Exp. 2/2/2017 Tank #2, Spill bucket, direct bury, tested with water and Incon accelerated tester. Tested two times, both pass, ok NOTE: Include this testing and results in the 2015 UST Monitoring System

Certification Report.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: ON SITE FOR THE 2014 UNDERGROUND STORAGE TANK (UST) MONITORING SYSTEM

CERTIFICATION. LIN LEUNG, PG&E, ON SITE TO PROVIDE ACCESS TO THE FACILITY AN RECORDS, LIN LEUNG, PG&E, IS THE DESIGNATED UST OPERATOR

(DUSTO). ICC#8013042-UC, EXP. 1/30/2015. PATTRIC BANBURY, TAIT ENVIRONMENTAL SERVICES, UST SERVICE TECH, ICC# 5254955, EXP. 1/26/2015, VEEDER-ROOT #A20465, LEVEL 4, EXP. 1/7/2015, FRANKLIN FUEL/INCON LEVEL 4, CERT#8613043701, EXP. 7/26/2015 TANK-1, 15,000 GASOLINE TANK-2, 10,000 DIESEL-1 TANK-3, 10,000 DIESEL-2 NOTE: THE

RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE

FROM HENNER TANK LINES, INC. PO BOX 867 WINTERS, CA RECEIPTS FROM

10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993,

DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). SYSTEM SETUP

AND ALARM HISTORY [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST **Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-06-2015 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: On site, 308 Stockton Ave. San Jose, for the 2015 UST Monitoring

> System Certification. Lin Leung, Environmental Compliance Specialist, PG&E, On site to provide facility accessm and records review. will send inspection report to InI5@pge.com John Cascio, UST Service TAIT ENVIRONMENTAL, ICC 5252163 Exp. 7/5/2015, Veeder-Root B35337 Exp. 2/5/2017 INCON, 6929323704-Lvl. 4 Exp. 11/5/2016 System Set-up and

Alarm History provided DUSTO reports reviewed, OK Financial

Responsibility, OK CERS Review, OK, Approved. Spill Buckets (3) tested with INCON accelerated test in water, several failures due to nearby passing trains. Diesel #2 Spill Bucket showed visible drop, serviced, re-test. FAIL, Service and Re-schedule testing. Diesel #1 and

gasoline, Pass, OK All sensors tested, Dispensers (3), Pump shutdown, Audio and Visual Alarm, Print, OK Piping Sumps (3), Audio and Visual Alarm, Print, OK Annular Space (3), Audio and Visual Alarm, Print,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST **Eval Source: CERS**

Compliance Evaluation Inspection **Eval General Type:**

05-10-2016 Eval Date:

Violations Found: No

Routine done by local agency Eval Type:

Eval Notes: Onsite today for routine aboveground petroleum storage act inspection,

> noted the following: -CUPA/Santa Clara County contact number and information updated in plan under Additional Numbers today by Lin. -The SPCC is stored onsite. -The SPCC is certified by a PE. -The SPCC has management approval, it occurred on 5-10-16. -Inspections are being performed monthly and annually and records are maintained; records were reviewed today, including any electronic monitoring equipment certification documents. -Tank and container areas are free of leaks and provided with adequate secondary containment. No

violations were noted today, thank you.

Eval Division: Santa Clara County Environmental Health

Eval Program: **APSA CERS** Eval Source:

Eval General Type: Other/Unknown Eval Date: 05-16-2016

Violations Found: Nο

Eval Type: Other, not routine, done by local agency

Eval Notes: On site, 308 Stockton Ave., PG&E-Cinabar, for the 2016 UST Secondary

> Containment Testing. Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Secondary Containment Testing, ICC # 8017001 Serv Tech Expires 6/9/2017 Franklin Fueling #3754183706 (Incon Level

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

4) 12/23/2016 One UST test (2 of 3 UST's are hydrostatic secondary), vacuum of 10 in Hg, 60 minutes, no drop, OK 3 STP sumps tested, Incon Accelerated test. Each sump passed 2 consecutive tests OK 3 piping runs tested, 5 psi air, 60 minutes, no drop in pressure observed. OK 3 UDCs being tested, Incon accelerated test, Each UDC to pass 2

consecutive tests. (PG&E standard) NOTE: Submit the 2016 UST Secondary

Containment testing report to this office within 30 days.

Eval Division: Santa Clara County Environmental Health

UST Eval Program: Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-30-2016

Violations Found: Nο

Eval Type: Routine done by local agency

Eval Notes: I was on site, 308 Stockton, for the 2016 Hazardous Waste Generator

permit inspection. Lin Leung, Environmental Field Specialist, was on site to provide facility access and records review. The 4/8/2014

Notice of Inspection (NOI) Return to Compliance (RTC) was received for

the record. Facility inspection; The 350 gallon generator has a spill/accumulation of oily debris below it that shall be cleaned from the concrete pad below the generator tank. The system shall be confirmed to be product tight. If this unit is to be closed, then identify the time line for fuel removal and closure and the current remaining fuel in the system. A 5 gallon orange "Homer" bucket was observed containing a small oil filled vessel. This was from a service truck as is to be managed properly. Any usable parts are to be identified, removed, prior to discarding as waste. All hazardous waste containers observed were closed, labeled, and in good order. Records

review; I reviewed [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW **Eval Source: CERS**

Enforcement Action:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Site Address: 308 STOCKTON AV

SAN JOSE Site City: Site Zip: 95126 Enf Action Date: 04-08-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: UST Enf Action Source: **CERS**

Affiliation:

Affiliation Type Desc: **Document Preparer** Entity Name: Liza Marfori, Parsons

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact

Entity Name: Lin Leung
Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: PO Box 7640
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 94120
Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 726-1128

Affiliation Type Desc: UST Permit Applicant

Entity Name: Lin Leung

Entity Title: Environmental Field Specialist

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Not reported

Affiliation Phone:

Not reported

Not reported

Affiliation Type Desc: Identification Signer Entity Name: Daniel Sanchez

Entity Title: Hazardous Materials & Water Quality Manager

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Affiliation Type Desc: Legal Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation City: San Ramon
Affiliation State: CA
Affiliation Country: United States

Affiliation Zip: 94583 Affiliation Phone: (415) 973-7000

Affiliation Type Desc: Property Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94583

Affiliation Phone: (415) 973-7000

Affiliation Type Desc: UST Tank Operator Entity Name: PG&E - Attn: Lin Leung

Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: UST Tank Owner

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94105
Affiliation Phone: (415) 973-7204

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation

Entity Name: PG&E **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: UST Property Owner Name

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

CERS TANKS:

Site ID: 399422 CERS ID: 10146769

CERS Description: Underground Storage Tank

Violations:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter

16, Section(s) 2641(a)

Violation Description: Failure of sensor to be located in the proper position/location.

Violation Notes: SENSOR TESTING, L-1, L-2, L-3, DISPENSER SENSORS, ALL THREE FAIL.

NOTE: PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE, REPAIR OR REPLACE THE DISPENSER

SENSORS WITHIN THE NEXT 30 DAYS. .

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16,

Section(s) 2665

Violation Description: Failure to comply with one or more of the following: failure to

install a spill bucket, have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container,

and/or be resistant to galvanic corrosion.

Violation Notes: THE SPILL BUCKET ON THE TANK #3 FAILED THE WATER TEST AND COULD NOT BE

SERVICED AT THE TIME OF TESTING. tHIS BUCKET IS NOT IN COMPLIANCE AND SHALL BE SERVICED, REPAIRED, OR REPLACED. PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE,

REPAIR OR REPLACE THE SPILL BUCKET WITHIN THE NEXT 30 DAYS.

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-02-2018 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: I am on site for the 2018 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email InI5@pge.com Warren Garrett, Tait Environmental

Direction Distance Elevation

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Services, Inc. 588098, on site to conduct UST Monitoring System
Certification. ICC# 206654 Serv Tech Expires 10/1/2019 VR B42126 Exp
1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System
Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK

Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1:

UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular, NOTE: This annular space was found to have a small bit of water in it. A Vacuum drew about a quart of water from the annular space. L-1, L-2, L-3, dispenser UDC sensors, [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-04-2016

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2016 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO,

Environmental Field Specialist, PG&E, on site to allow access and records review. email InI5@pge.com UST Operating Permit to be issued by this office. SB-989 Testing to be conducted in May 2016. To be scheduled. Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Monitoring System Certification. ICC # 8017001 Serv Tech Expires 6/9/2017 VR B-36532- Expires, 6/28/2017 3754183706 12/23/2016 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown, Audio and Visual Alarm, Print, OK L-4, L-5, L-6, Used Oil AST sensors, Audio and Visual Alarm, Print, OK L-7, L-8, L-9.

L-10,L-11, L-12, UST [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 06-10-2016
Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: ON-SITE TO OVERSEE SENSOR FUNCTIONALITY (MONITORING COLD-START)

INSPECTION. TESTING WAS CONDUCTED BY GARRETT WARREN WITH TAIT ENVIRONMENTAL. MR WARREN HAS THE FOLLOWING CERTIFICATIONS; ICC#00206654 EXP., 10/2/17; VR#B42126 EXP., 1/8/17. PRIOR TO TESTING

OF THE SENSORS THERE WERE NO ACTIVE ALARMS AT THE VEEDER ROOT PANEL. THE FOLLOWING SENSORS WERE TESTED AND PASSED DURING THIS INSPECTION; -3 STP SUMPS SENSORS -3 ANNULAR SENSORS -3 UDC SENSORS -3 ATG PROBES FOR OVERFILL ALARM WERE TESTED ** ALL SENSORS ABOVE PROVIDED AND AUDIBLE AND VISUAL ALARM AT THE VEEDER ROOT ADDITIONALLY THE FOLLOWING SENSORS WERE TESTED BY THE TECHNICIAN FOR THE ABOVE GROUND USED OIL TANK, AS THESE SENSORS ARE CONNECTED TO THE VEEDER ROOT PANEL. - 1 ANNULAR SENSOR (L5) - 1 OUTER ANNULAR SPACE SENSOR (L6) - 1 SECONDARY

PIPING SUMP (L7) NOTES: THIS INSPECTION REPORT CLOSES OUT PERMIT SR0850423 WITH OUR DEPARTMENT.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-03-2017 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2017 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com The record of Inspection and Monitoring System Certification for SR0850423 was copied from on site records. Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2017 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review: UST Permit Information. OK Financial Responsibility. OK

Approved submittal, OK 3 USTs, Tank ID # T1: UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: ON SITE IN PART TO REVIEW THE HAZARDOUS MATERIALS BUSINESS PLAN (HMBP)

AND INVENTORY IN THE CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM (CERS) SYSTEM WITH WHAT IS STORED ON SITE IN THE UNDERGROUND STORAGE TANK (UST) SYSTEMS (3). DAVE WILCOX, SHOP MANAGER, PG&E, ON SITE TO PROVIDE ACCESS, RECORDS, AND INFORMATION. THERE ARE 3 UST s, 2 PETROLEUM DIESEL, 1 UNLEADED 87 GASOLINE. THE RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE FROM HENNER TANK LINES, INC.

PO BOX 867 WINTERS, CA RECEIPTS FROM 10/10/2013, 11/3/2013, AND

1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). DAVE WILCOX SHARED THE FOLLOWING INFORMATION: IN THE PAST, ABOUT 4 YEARS AGO, DIESEL B-20 HAD REPLACED PETROLEUM DIESEL

IN THE TWO DIESEL TANKS. FILTRATION CAPACITY AND CLOGGING WAS A

PROBLEM. [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 04-16-2015

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site to confirm spill bucket test after replacing the swivel

connection. Lin Leung, Env. Compliance Manager, PG&E, on site to

facilitate access. Garrett Warren, UST Service Tech, TAIT

ENVIRONMENTAL, on site to conduct service and testing. ICC 8185019 exp. 10/4/2015, Incon/Franklin Cert. Level 4, #3754183706 Exp.

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

2/2/2017 Tank #2, Spill bucket, direct bury, tested with water and Incon accelerated tester. Tested two times, both pass, ok NOTE: Include this testing and results in the 2015 UST Monitoring System

Certification Report.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: ON SITE FOR THE 2014 UNDERGROUND STORAGE TANK (UST) MONITORING SYSTEM

CERTIFICATION. LIN LEUNG, PG&E, ON SITE TO PROVIDE ACCESS TO THE FACILITY AN RECORDS, LIN LEUNG, PG&E, IS THE DESIGNATED UST OPERATOR

(DUSTO). ICC#8013042-UC, EXP. 1/30/2015. PATTRIC BANBURY, TAIT ENVIRONMENTAL SERVICES, UST SERVICE TECH, ICC# 5254955, EXP. 1/26/2015, VEEDER-ROOT #A20465, LEVEL 4, EXP. 1/7/2015, FRANKLIN FUEL/INCON LEVEL 4, CERT#8613043701, EXP. 7/26/2015 TANK-1, 15,000 GASOLINE TANK-2, 10,000 DIESEL-1 TANK-3, 10,000 DIESEL-2 NOTE: THE

RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE

FROM HENNER TANK LINES, INC. PO BOX 867 WINTERS, CA RECEIPTS FROM 10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). SYSTEM SETUP

AND ALARM HISTORY [Truncated]
Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval Division:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-06-2015 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: On site, 308 Stockton Ave. San Jose, for the 2015 UST Monitoring

System Certification. Lin Leung, Environmental Compliance Specialist, PG&E, On site to provide facility accessm and records review. will send inspection report to InI5@pge.com John Cascio, UST Service TAIT ENVIRONMENTAL, ICC 5252163 Exp. 7/5/2015, Veeder-Root B35337 Exp. 2/5/2017 INCON, 6929323704-Lvl. 4 Exp. 11/5/2016 System Set-up and

Alarm History provided DUSTO reports reviewed, OK Financial

Responsibility, OK CERS Review, OK, Approved. Spill Buckets (3) tested with INCON accelerated test in water, several failures due to nearby passing trains. Diesel #2 Spill Bucket showed visible drop, serviced, re-test. FAIL, Service and Re-schedule testing. Diesel #1 and

gasoline, Pass, OK All sensors tested, Dispensers (3), Pump shutdown, Audio and Visual Alarm, Print, OK Piping Sumps (3), Audio and Visual Alarm, Print, OK Annular Space (3), Audio and Visual Alarm, Print,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 05-10-2016

Violations Found: No

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Eval Type: Routine done by local agency

Eval Notes: Onsite today for routine aboveground petroleum storage act inspection,

noted the following: -CUPA/Santa Clara County contact number and information updated in plan under Additional Numbers today by Lin. -The SPCC is stored onsite. -The SPCC is certified by a PE. -The SPCC has management approval, it occurred on 5-10-16. -Inspections are being performed monthly and annually and records are maintained; records were reviewed today, including any electronic monitoring equipment certification documents. -Tank and container areas are free of leaks and provided with adequate secondary containment. No

violations were noted today, thank you. Santa Clara County Environmental Health

Eval Division: Santa Clara Cou Eval Program: APSA Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 05-16-2016
Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site, 308 Stockton Ave., PG&E-Cinabar, for the 2016 UST Secondary

Containment Testing. Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Secondary Containment Testing. ICC # 8017001 Serv Tech Expires 6/9/2017 Franklin Fueling #3754183706 (Incon Level 4) 12/23/2016 One UST test (2 of 3 UST's are hydrostatic secondary), vacuum of 10 in Hg, 60 minutes, no drop, OK 3 STP sumps tested, Incon Accelerated test. Each sump passed 2 consecutive tests OK 3 piping runs tested, 5 psi air, 60 minutes, no drop in pressure observed. OK 3 UDCs being tested, Incon accelerated test, Each UDC to pass 2

consecutive tests. (PG&E standard) NOTE: Submit the 2016 UST Secondary

Containment testing report to this office within 30 days.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-30-2016 Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: I was on site, 308 Stockton, for the 2016 Hazardous Waste Generator

permit inspection. Lin Leung, Environmental Field Specialist, was on site to provide facility access and records review. The 4/8/2014

Notice of Inspection (NOI) Return to Compliance (RTC) was received for the record. Facility inspection; The 350 gallon generator has a

the record. Facility inspection; The 350 gallon generator has a spill/accumulation of oily debris below it that shall be cleaned from the concrete pad below the generator tank. The system shall be confirmed to be product tight. If this unit is to be closed, then identify the time line for fuel removal and closure and the current remaining fuel in the system. A 5 gallon orange "Homer" bucket was observed containing a small oil filled vessel. This was from a service truck as is to be managed properly. Any usable parts are to be identified, removed, prior to discarding as waste. All hazardous waste containers observed were closed, labeled, and in good order. Records

review; I reviewed [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

CERS Eval Source:

Enforcement Action:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

308 STOCKTON AV Site Address:

SAN JOSE Site City: Site Zip: 95126 Enf Action Date: 04-08-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: UST Enf Action Source: **CERS**

Affiliation:

Affiliation Type Desc: **Document Preparer** Liza Marfori, Parsons **Entity Name:**

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Entity Name: Lin Leung Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose Affiliation State:

Not reported Affiliation Country: Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address Not reported Entity Title: Affiliation Address: PO Box 7640 Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: Not reported 94120 Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 726-1128

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation Type Desc: **UST Permit Applicant**

Entity Name: Lin Leung

Entity Title: **Environmental Field Specialist**

Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Identification Signer Entity Name: Daniel Sanchez

Entity Title: Hazardous Materials & Water Quality Manager

Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon Affiliation State: CA Affiliation Country: **United States** Affiliation Zip: 94583 (415) 973-7000 Affiliation Phone:

Property Owner Affiliation Type Desc:

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon

Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 94583

(415) 973-7000 Affiliation Phone:

UST Tank Operator Affiliation Type Desc: Entity Name: PG&E - Attn: Lin Leung

Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 95113 Affiliation Phone: (415) 310-7968

Affiliation Type Desc: **UST Tank Owner**

Entity Name: PG&E - Environmental Management

Entity Title: Not reported Affiliation Address: 77 Beale Street Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: **United States**

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation

Entity Name: PG&E Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: UST Property Owner Name

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

 Site ID:
 399422

 CERS ID:
 10146769

CERS Description: Aboveground Petroleum Storage

Violations:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter

16, Section(s) 2641(a)

Violation Description: Failure of sensor to be located in the proper position/location.

Violation Notes: SENSOR TESTING, L-1, L-2, L-3, DISPENSER SENSORS, ALL THREE FAIL.

NOTE: PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE, REPAIR OR REPLACE THE DISPENSER

SENSORS WITHIN THE NEXT 30 DAYS. .

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16,

Section(s) 2665

Map ID MAP FINDINGS Direction

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Violation Description: Failure to comply with one or more of the following: failure to

> install a spill bucket, have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container,

and/or be resistant to galvanic corrosion.

Violation Notes: THE SPILL BUCKET ON THE TANK #3 FAILED THE WATER TEST AND COULD NOT BE

> SERVICED AT THE TIME OF TESTING. tHIS BUCKET IS NOT IN COMPLIANCE AND SHALL BE SERVICED, REPAIRED, OR REPLACED. PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE,

REPAIR OR REPLACE THE SPILL BUCKET WITHIN THE NEXT 30 DAYS.

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: **CERS**

Evaluation:

Eval General Type: Compliance Evaluation Inspection

04-02-2018 **Eval Date:**

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: I am on site for the 2018 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2019 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK

Training, OK CERS Review: UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1:

UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular, NOTE: This annular space was found to have a small bit of water in it. A Vacuum drew about a quart of water from the annular space. L-1, L-2, L-3, dispenser UDC sensors, [Truncated]

Eval Division: Santa Clara County Environmental Health

UST **Eval Program: CERS** Eval Source:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-04-2016

Violations Found: No

Eval Type: Routine done by local agency

Im on site for the 2016 UST Operating Permit Inspection and records **Eval Notes:**

review. Monitoring System Certification Lin Leung, DUSTO,

Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com UST Operating Permit to be issued by this office. SB-989 Testing to be conducted in May 2016. To be scheduled. Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Monitoring System Certification. ICC # 8017001 Serv Tech Expires 6/9/2017 VR B-36532- Expires, 6/28/2017 3754183706 12/23/2016 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK L-1, L-2, L-3, dispenser UDC sensors, Suction

Pump shutdown, Audio and Visual Alarm, Print, OK L-4, L-5, L-6, Used Oil AST sensors, Audio and Visual Alarm, Print, OK L-7, L-8, L-9,

L-10,L-11, L-12, UST [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 06-10-2016

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: ON-SITE TO OVERSEE SENSOR FUNCTIONALITY (MONITORING COLD-START) INSPECTION. TESTING WAS CONDUCTED BY GARRETT WARREN WITH TAIT

ENVIRONMENTAL. MR WARREN HAS THE FOLLOWING CERTIFICATIONS; ICC#00206654 EXP., 10/2/17; VR#B42126 EXP., 1/8/17. PRIOR TO TESTING

OF THE SENSORS THERE WERE NO ACTIVE ALARMS AT THE VEEDER ROOT PANEL. THE FOLLOWING SENSORS WERE TESTED AND PASSED DURING THIS INSPECTION; -3 STP SUMPS SENSORS -3 ANNULAR SENSORS -3 UDC SENSORS -3 ATG PROBES FOR OVERFILL ALARM WERE TESTED ** ALL SENSORS ABOVE PROVIDED AND AUDIBLE AND VISUAL ALARM AT THE VEEDER ROOT ADDITIONALLY THE FOLLOWING SENSORS WERE TESTED BY THE TECHNICIAN FOR THE ABOVE GROUND USED OIL TANK, AS THESE SENSORS ARE CONNECTED TO THE VEEDER ROOT PANEL. - 1 ANNULAR SENSOR (L5) - 1 OUTER ANNULAR SPACE SENSOR (L6) - 1 SECONDARY PIPING SUMP (L7) NOTES: THIS INSPECTION REPORT CLOSES OUT PERMIT

SR0850423 WITH OUR DEPARTMENT.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-03-2017

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2017 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email InI5@pge.com The record of Inspection and Monitoring System Certification for SR0850423 was copied from on site records. Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2017 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK

Approved submittal, OK 3 USTs, Tank ID # T1: UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: ON SITE IN PART TO REVIEW THE HAZARDOUS MATERIALS BUSINESS PLAN (HMBP)

AND INVENTORY IN THE CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM (CERS) SYSTEM WITH WHAT IS STORED ON SITE IN THE UNDERGROUND STORAGE TANK (UST) SYSTEMS (3). DAVE WILCOX, SHOP MANAGER, PG&E, ON SITE TO PROVIDE ACCESS, RECORDS, AND INFORMATION. THERE ARE 3 UST s, 2 PETROLEUM DIESEL, 1 UNLEADED 87 GASOLINE. THE RECENT DIESEL PURCHASE RECORDS

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE FROM HENNER TANK LINES, INC.

PO BOX 867 WINTERS, CA RECEIPTS FROM 10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED

ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). DAVE WILCOX SHARED THE FOLLOWING INFORMATION: IN THE PAST, ABOUT 4 YEARS AGO, DIESEL B-20 HAD REPLACED PETROLEUM DIESEL

IN THE TWO DIESEL TANKS. FILTRATION CAPACITY AND CLOGGING WAS A

PROBLEM. [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 04-16-2015

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site to confirm spill bucket test after replacing the swivel

connection. Lin Leung, Env. Compliance Manager, PG&E, on site to

facilitate access. Garrett Warren, UST Service Tech, TAIT

ENVIRONMENTAL, on site to conduct service and testing. ICC 8185019 exp. 10/4/2015, Incon/Franklin Cert. Level 4, #3754183706 Exp.

2/2/2017 Tank #2, Spill bucket, direct bury, tested with water and Incon accelerated tester. Tested two times, both pass, ok NOTE: Include this testing and results in the 2015 UST Monitoring System

Certification Report.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: ON SITE FOR THE 2014 UNDERGROUND STORAGE TANK (UST) MONITORING SYSTEM

CERTIFICATION. LIN LEUNG, PG&E, ON SITE TO PROVIDE ACCESS TO THE FACILITY AN RECORDS, LIN LEUNG, PG&E, IS THE DESIGNATED UST OPERATOR

(DUSTO). ICC#8013042-UC, EXP. 1/30/2015. PATTRIC BANBURY, TAIT ENVIRONMENTAL SERVICES, UST SERVICE TECH, ICC# 5254955, EXP. 1/26/2015, VEEDER-ROOT #A20465, LEVEL 4, EXP. 1/7/2015, FRANKLIN FUEL/INCON LEVEL 4, CERT#8613043701, EXP. 7/26/2015 TANK-1, 15,000 GASOLINE TANK-2, 10,000 DIESEL-1 TANK-3, 10,000 DIESEL-2 NOTE: THE

RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE

FROM HENNER TANK LINES, INC. PO BOX 867 WINTERS, CA RECEIPTS FROM

10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993,

DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). SYSTEM SETUP

AND ALARM HISTORY [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-06-2015

Violations Found: No

Eval Type: Routine done by local agency

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Eval Notes: On site, 308 Stockton Ave. San Jose, for the 2015 UST Monitoring

> System Certification. Lin Leung, Environmental Compliance Specialist, PG&E, On site to provide facility accessm and records review. will send inspection report to InI5@pge.com John Cascio, UST Service TAIT ENVIRONMENTAL, ICC 5252163 Exp. 7/5/2015, Veeder-Root B35337 Exp. 2/5/2017 INCON, 6929323704-Lvl. 4 Exp. 11/5/2016 System Set-up and

Alarm History provided DUSTO reports reviewed, OK Financial

Responsibility, OK CERS Review, OK, Approved. Spill Buckets (3) tested with INCON accelerated test in water, several failures due to nearby passing trains. Diesel #2 Spill Bucket showed visible drop, serviced, re-test. FAIL, Service and Re-schedule testing. Diesel #1 and

gasoline, Pass, OK All sensors tested, Dispensers (3), Pump shutdown, Audio and Visual Alarm, Print, OK Piping Sumps (3), Audio and Visual Alarm, Print, OK Annular Space (3), Audio and Visual Alarm, Print,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST **Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 05-10-2016

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Onsite today for routine aboveground petroleum storage act inspection,

noted the following: -CUPA/Santa Clara County contact number and information updated in plan under Additional Numbers today by Lin. -The SPCC is stored onsite. -The SPCC is certified by a PE. -The SPCC has management approval, it occurred on 5-10-16. -Inspections are being performed monthly and annually and records are maintained; records were reviewed today, including any electronic monitoring equipment certification documents. -Tank and container areas are free

of leaks and provided with adequate secondary containment. No violations were noted today, thank you.

Eval Division: Santa Clara County Environmental Health

Eval Program: **APSA Eval Source: CERS**

Eval General Type: Other/Unknown Eval Date: 05-16-2016 Violations Found: No

Other, not routine, done by local agency Eval Type:

On site, 308 Stockton Ave., PG&E-Cinabar, for the 2016 UST Secondary **Eval Notes:**

> Containment Testing. Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Secondary Containment Testing. ICC # 8017001 Serv Tech Expires 6/9/2017 Franklin Fueling #3754183706 (Incon Level 4) 12/23/2016 One UST test (2 of 3 UST's are hydrostatic secondary), vacuum of 10 in Hg, 60 minutes, no drop, OK 3 STP sumps tested, Incon Accelerated test. Each sump passed 2 consecutive tests OK 3 piping runs tested, 5 psi air, 60 minutes, no drop in pressure observed. OK 3 UDCs being tested, Incon accelerated test, Each UDC to pass 2

consecutive tests. (PG&E standard) NOTE: Submit the 2016 UST Secondary

Containment testing report to this office within 30 days.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST **Eval Source: CERS**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Eval General Type: Compliance Evaluation Inspection

11-30-2016 Eval Date:

Violations Found: Nο

Routine done by local agency Eval Type:

Eval Notes: I was on site, 308 Stockton, for the 2016 Hazardous Waste Generator

permit inspection. Lin Leung, Environmental Field Specialist, was on site to provide facility access and records review. The 4/8/2014 Notice of Inspection (NOI) Return to Compliance (RTC) was received for

the record. Facility inspection; The 350 gallon generator has a spill/accumulation of oily debris below it that shall be cleaned from the concrete pad below the generator tank. The system shall be confirmed to be product tight. If this unit is to be closed, then identify the time line for fuel removal and closure and the current remaining fuel in the system. A 5 gallon orange "Homer" bucket was observed containing a small oil filled vessel. This was from a service truck as is to be managed properly. Any usable parts are to be identified, removed, prior to discarding as waste. All hazardous waste

containers observed were closed, labeled, and in good order. Records

review; I reviewed [Truncated]

Santa Clara County Environmental Health Eval Division:

Eval Program: HW **Eval Source: CERS**

Enforcement Action:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Site Address: 308 STOCKTON AV

Site City: SAN JOSE Site Zip: 95126 04-08-2014 Enf Action Date:

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

UST Enf Action Program: Enf Action Source: **CERS**

Affiliation:

Affiliation Type Desc: **Document Preparer** Entity Name: Liza Marfori, Parsons

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Lin Leung **Entity Name: Entity Title:** Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95113

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: PO Box 7640
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 94120
Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 726-1128

Affiliation Type Desc: UST Permit Applicant

Entity Name: Lin Leung

Entity Title: Environmental Field Specialist

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Not reported

Not reported

Affiliation Phone:

(415) 310-7968

Affiliation Type Desc: Identification Signer Entity Name: Daniel Sanchez

Entity Title: Hazardous Materials & Water Quality Manager

Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94583
Affiliation Phone: (415) 973-7000

Affiliation Type Desc: Property Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94583
Affiliation Phone: (415) 973-7000

Affiliation Type Desc: UST Tank Operator Entity Name: PG&E - Attn: Lin Leung

Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: UST Tank Owner

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported

Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation

Entity Name: PG&E **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Not reported Affiliation Phone:

Affiliation Type Desc: UST Property Owner Name

Entity Name: PG&E - Environmental Management

Entity Title: Not reported
Affiliation Address: 77 Beale Street
Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

EDR ID Number

S121775003

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

CERS TANKS:

Site ID: 399422 CERS ID: 10146769

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter

16, Section(s) 2641(a)

Violation Description: Failure of sensor to be located in the proper position/location.

Violation Notes: SENSOR TESTING, L-1, L-2, L-3, DISPENSER SENSORS, ALL THREE FAIL.

NOTE: PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE, REPAIR OR REPLACE THE DISPENSER

SENSORS WITHIN THE NEXT 30 DAYS. .

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Violation Date: 04-08-2014

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16,

Section(s) 2665

Violation Description: Failure to comply with one or more of the following: failure to

install a spill bucket, have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container.

and/or be resistant to galvanic corrosion.

Violation Notes: THE SPILL BUCKET ON THE TANK #3 FAILED THE WATER TEST AND COULD NOT BE

SERVICED AT THE TIME OF TESTING. tHIS BUCKET IS NOT IN COMPLIANCE AND SHALL BE SERVICED, REPAIRED, OR REPLACED. PROVIDE A PLAN OF ACTION, TO THIS OFFICE, THAT WILL ADDRESS IN DETAIL STEPS TO BE TAKEN TO SERVICE.

REPAIR OR REPLACE THE SPILL BUCKET WITHIN THE NEXT 30 DAYS.

Violation Division: Santa Clara County Environmental Health

Violation Program: UST Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-02-2018

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: I am on site for the 2018 UST Operating Permit Inspection and records

review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2019 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK

Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1:

UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular, NOTE: This annular space was found to have a small bit of water in it. A Vacuum drew about a quart of water from the annular space. L-1, L-2, L-3, dispenser UDC sensors, [Truncated]

Direction Distance

Elevation **EPA ID Number** Site Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

04-04-2016 **Eval Date:** No

Violations Found:

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2016 UST Operating Permit Inspection and records

> review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com UST Operating Permit to be issued by this office. SB-989 Testing to be conducted in May 2016. To be scheduled. Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Monitoring System Certification. ICC # 8017001 Serv Tech Expires 6/9/2017 VR B-36532- Expires, 6/28/2017 3754183706 12/23/2016 Monitoring System Set-up and Alarm History provided, DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK

Approved submittal, OK L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown, Audio and Visual Alarm, Print, OK L-4, L-5, L-6, Used Oil AST sensors, Audio and Visual Alarm, Print, OK L-7, L-8, L-9,

L-10.L-11, L-12, UST [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: **CERS**

Eval General Type: Other/Unknown Eval Date: 06-10-2016

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: ON-SITE TO OVERSEE SENSOR FUNCTIONALITY (MONITORING COLD-START)

INSPECTION. TESTING WAS CONDUCTED BY GARRETT WARREN WITH TAIT ENVIRONMENTAL. MR WARREN HAS THE FOLLOWING CERTIFICATIONS; ICC#00206654 EXP., 10/2/17; VR#B42126 EXP., 1/8/17. PRIOR TO TESTING

OF THE SENSORS THERE WERE NO ACTIVE ALARMS AT THE VEEDER ROOT PANEL. THE FOLLOWING SENSORS WERE TESTED AND PASSED DURING THIS INSPECTION: -3 STP SUMPS SENSORS -3 ANNULAR SENSORS -3 UDC SENSORS -3 ATG PROBES FOR OVERFILL ALARM WERE TESTED ** ALL SENSORS ABOVE PROVIDED AND AUDIBLE AND VISUAL ALARM AT THE VEEDER ROOT ADDITIONALLY THE FOLLOWING SENSORS WERE TESTED BY THE TECHNICIAN FOR THE ABOVE GROUND USED OIL TANK, AS THESE SENSORS ARE CONNECTED TO THE VEEDER ROOT PANEL. - 1 ANNULAR SENSOR (L5) - 1 OUTER ANNULAR SPACE SENSOR (L6) - 1 SECONDARY

PIPING SUMP (L7) NOTES: THIS INSPECTION REPORT CLOSES OUT PERMIT

SR0850423 WITH OUR DEPARTMENT. **Eval Division:** Santa Clara County Environmental Health

Eval Program: UST Eval Source: **CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-03-2017

Violations Found:

Eval Type: Routine done by local agency

Eval Notes: Im on site for the 2017 UST Operating Permit Inspection and records

> review. Monitoring System Certification Lin Leung, DUSTO, Environmental Field Specialist, PG&E, on site to allow access and records review. email Inl5@pge.com The record of Inspection and

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Monitoring System Certification for SR0850423 was copied from on site records. Warren Garrett, Tait Environmental Services, Inc. 588098, on site to conduct UST Monitoring System Certification. ICC# 206654 Serv Tech Expires 10/1/2017 VR B42126 Exp 1/23/2019 Incon/ Level 4, 3754183706 exp. 1/6/2019 Monitoring System Set-up and Alarm History provided. DUSTO, OK Monthly DUSTO Reports, OK Training, OK CERS Review; UST Permit Information, OK Financial Responsibility, OK Approved submittal, OK 3 USTs, Tank ID # T1: UNLEADED - Wet annular Tank ID # T3: DIESEL 2 - Wet annular Tank ID # T2: DIESEL 1 - Dry annular L-1, L-2, L-3, dispenser UDC sensors, Suction Pump shutdown,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: ON SITE IN PART TO REVIEW THE HAZARDOUS MATERIALS BUSINESS PLAN (HMBP)

AND INVENTORY IN THE CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM (CERS) SYSTEM WITH WHAT IS STORED ON SITE IN THE UNDERGROUND STORAGE TANK (UST) SYSTEMS (3). DAVE WILCOX, SHOP MANAGER, PG&E, ON SITE TO PROVIDE ACCESS, RECORDS, AND INFORMATION. THERE ARE 3 UST s, 2 PETROLEUM DIESEL, 1 UNLEADED 87 GASOLINE. THE RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE FROM HENNER TANK LINES, INC.

PO BOX 867 WINTERS, CA RECEIPTS FROM 10/10/2013, 11/3/2013, AND

1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). DAVE WILCOX SHARED THE FOLLOWING INFORMATION: IN THE PAST, ABOUT 4 YEARS AGO, DIESEL B-20 HAD REPLACED PETROLEUM DIESEL

IN THE TWO DIESEL TANKS. FILTRATION CAPACITY AND CLOGGING WAS A

PROBLEM. [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 04-16-2015

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site to confirm spill bucket test after replacing the swivel

connection. Lin Leung, Env. Compliance Manager, PG&E, on site to

facilitate access. Garrett Warren, UST Service Tech, TAIT

ENVIRONMENTAL, on site to conduct service and testing. ICC 8185019

exp. 10/4/2015, Incon/Franklin Cert. Level 4, #3754183706 Exp. 2/2/2017 Tank #2, Spill bucket, direct bury, tested with water and Incon accelerated tester. Tested two times, both pass, ok NOTE: Include this testing and results in the 2015 UST Monitoring System

Certification Report.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-08-2014

Map ID MAP FINDINGS
Direction

Distance
Elevation Site Database(s)

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

EPA ID Number

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: ON SITE FOR THE 2014 UNDERGROUND STORAGE TANK (UST) MONITORING SYSTEM

CERTIFICATION. LIN LEUNG, PG&E, ON SITE TO PROVIDE ACCESS TO THE FACILITY AN RECORDS, LIN LEUNG, PG&E, IS THE DESIGNATED UST OPERATOR

(DUSTO). ICC#8013042-UC, EXP. 1/30/2015. PATTRIC BANBURY, TAIT ENVIRONMENTAL SERVICES, UST SERVICE TECH, ICC# 5254955, EXP. 1/26/2015, VEEDER-ROOT #A20465, LEVEL 4, EXP. 1/7/2015, FRANKLIN FUEL/INCON LEVEL 4, CERT#8613043701, EXP. 7/26/2015 TANK-1, 15,000 GASOLINE TANK-2, 10,000 DIESEL-1 TANK-3, 10,000 DIESEL-2 NOTE: THE

RECENT DIESEL PURCHASE RECORDS WERE REVIEWED TO DETERMINE THE TYPE OF DIESEL PURCHASED AND STORED WITHIN THE UST SYSTEM. ALL PURCHASES WERE

FROM HENNER TANK LINES, INC. PO BOX 867 WINTERS, CA RECEIPTS FROM

10/10/2013, 11/3/2013, AND 1/14/2014, ALL - CLEAR ULSD, NA 1993, DIESEL FUEL, 15PPM SULFUR UNDYED ULTRA-LOW SULFUR DIESEL, EPA REGISTRATION #-4294. SHIPPER - TESORO REFINING (6081-41). SYSTEM SETUP

AND ALARM HISTORY [Truncated]
Santa Clara County Environmental Health

Eval Division: Santa (
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-06-2015

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: On site, 308 Stockton Ave. San Jose, for the 2015 UST Monitoring

System Certification. Lin Leung, Environmental Compliance Specialist, PG&E, On site to provide facility accessm and records review. will send inspection report to InI5@pge.com John Cascio, UST Service TAIT ENVIRONMENTAL, ICC 5252163 Exp. 7/5/2015, Veeder-Root B35337 Exp. 2/5/2017 INCON, 6929323704-Lvl. 4 Exp. 11/5/2016 System Set-up and

Alarm History provided DUSTO reports reviewed, OK Financial

Responsibility, OK CERS Review, OK, Approved. Spill Buckets (3) tested with INCON accelerated test in water, several failures due to nearby passing trains. Diesel #2 Spill Bucket showed visible drop, serviced, re-test. FAIL, Service and Re-schedule testing. Diesel #1 and

gasoline, Pass, OK All sensors tested, Dispensers (3), Pump shutdown, Audio and Visual Alarm, Print, OK Piping Sumps (3), Audio and Visual Alarm, Print, OK Annular Space (3), Audio and Visual Alarm, Print,

[Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 05-10-2016

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Onsite today for routine aboveground petroleum storage act inspection,

noted the following: -CUPA/Santa Clara County contact number and information updated in plan under Additional Numbers today by Lin.
-The SPCC is stored onsite. -The SPCC is certified by a PE. -The SPCC has management approval, it occurred on 5-10-16. -Inspections are being performed monthly and annually and records are maintained; records were reviewed today, including any electronic monitoring equipment certification documents. -Tank and container areas are free of leaks and provided with adequate secondary containment. No

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E: CINNABAR SERVICE CENTER (Continued)

Eval Division:

S121775003

EDR ID Number

violations were noted today, thank you. Santa Clara County Environmental Health

Eval Program: APSA Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 05-16-2016

Violations Found: No

Eval Type: Other, not routine, done by local agency

Eval Notes: On site, 308 Stockton Ave., PG&E-Cinabar, for the 2016 UST Secondary Containment Testing. Lin Leung, DUSTO, Environmental Field Specialist,

PG&E, on site to allow access and records review. email InI5@pge.com Victor Guerrero, UST Service Tech, Tait Environmental Services, Inc. on site to conduct UST Secondary Containment Testing. ICC # 8017001 Serv Tech Expires 6/9/2017 Franklin Fueling #3754183706 (Incon Level 4) 12/23/2016 One UST test (2 of 3 UST's are hydrostatic secondary), vacuum of 10 in Hg, 60 minutes, no drop, OK 3 STP sumps tested, Incon Accelerated test. Each sump passed 2 consecutive tests OK 3 piping runs tested, 5 psi air, 60 minutes, no drop in pressure observed. OK 3 UDCs being tested, Incon accelerated test, Each UDC to pass 2

consecutive tests. (PG&E standard) NOTE: Submit the 2016 UST Secondary

Containment testing report to this office within 30 days.

Eval Division: Santa Clara County Environmental Health

Eval Program: UST Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-30-2016

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes:

I was on site, 308 Stockton, for the 2016 Hazardous Waste Generator permit inspection. Lin Leung, Environmental Field Specialist, was on

permit inspection. Lin Leung, Environmental Field Specialist, was on site to provide facility access and records review. The 4/8/2014 Notice of Inspection (NOI) Return to Compliance (RTC) was received for

the record. Facility inspection; The 350 gallon generator has a spill/accumulation of oily debris below it that shall be cleaned from the concrete pad below the generator tank. The system shall be confirmed to be product tight. If this unit is to be closed, then identify the time line for fuel removal and closure and the current remaining fuel in the system. A 5 gallon orange "Homer" bucket was observed containing a small oil filled vessel. This was from a service truck as is to be managed properly. Any usable parts are to be identified, removed, prior to discarding as waste. All hazardous waste containers observed were closed, labeled, and in good order. Records

review; I reviewed [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Enforcement Action:

Site ID: 399422

Site Name: PG&E: Cinnabar Service Center

Site Address: 308 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 04-08-2014

Enf Action Type: Notice of Violation (Unified Program)

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: UST Enf Action Source: **CERS**

Affiliation:

Affiliation Type Desc: **Document Preparer Entity Name:** Liza Marfori, Parsons

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Entity Name: Lin Leung Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95113

Affiliation Phone: (415) 310-7968

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address Not reported Entity Title: Affiliation Address: PO Box 7640 Affiliation City: San Francisco

Affiliation State: CA

Affiliation Country: Not reported 94120 Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 726-1128

Affiliation Type Desc: **UST Permit Applicant**

Entity Name: Lin Leung

Entity Title: **Environmental Field Specialist**

Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (415) 310-7968

Direction Distance

Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

EDR ID Number

Affiliation Type Desc: Identification Signer **Entity Name: Daniel Sanchez**

Entity Title: Hazardous Materials & Water Quality Manager

Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon

Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 94583

Affiliation Phone: (415) 973-7000

Affiliation Type Desc: **Property Owner**

Entity Name: Pacific Gas & Electric Company

Entity Title: Not reported

Affiliation Address: c/o Environmental Services, 3401 Crow Canyon Road

Affiliation City: San Ramon Affiliation State: CA Affiliation Country: **United States** Affiliation Zip: 94583 (415) 973-7000 Affiliation Phone:

UST Tank Operator Affiliation Type Desc: **Entity Name:** PG&E - Attn: Lin Leung

Entity Title: Not reported

Affiliation Address: 111 Almaden Boulevard

San Jose Affiliation City: Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 95113 (415) 310-7968 Affiliation Phone:

Affiliation Type Desc: **UST Tank Owner**

Entity Name: PG&E - Environmental Management

Entity Title: Not reported Affiliation Address: 77 Beale Street Affiliation City: San Francisco Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

Affiliation Type Desc: **CUPA District**

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E: CINNABAR SERVICE CENTER (Continued)

S121775003

U003941030

N/A

Affiliation Zip: 95112-2716 Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation

Entity Name: PG&E Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **UST Property Owner Name**

PG&E - Environmental Management Entity Name:

Entity Title: Not reported Affiliation Address: 77 Beale Street Affiliation City: San Francisco

Affiliation State: CA

United States Affiliation Country: Affiliation Zip: 94105

Affiliation Phone: (415) 973-7204

PACIFIC GAS & ELECTRIC COMPANY WSW 308 STOCKTON AVE 1/8-1/4 SAN JOSE, CA 95126

0.190 mi.

P105

1001 ft. Site 6 of 15 in cluster P

Relative: UST:

Higher Facility ID: 405875

SAN JOSE, CITY OF Permitting Agency: Actual:

Latitude: 37.33391 92 ft. Longitude: -121.90603

> Facility ID: FA0208679

Permitting Agency: Santa Clara County Environmental Health

Latitude: 37.334 -121.90607 Longitude:

P106 **PG&E CINNABAR SERVICE CTR** LUST S105882239

wsw **308 STOCKTON AVE CHMIRS** N/A **CUPA Listings** 1/8-1/4 SAN JOSE, CA 95126 0.190 mi. **SAN JOSE HAZMAT** 1001 ft. Site 7 of 15 in cluster P **CERS**

Relative: LUST:

SANTA CLARA COUNTY LOP Higher Lead Agency:

Case Type: LUST Cleanup Site Actual:

http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608517440 Geo Track: 92 ft.

Global Id: T0608517440 Latitude: 37.333904 Longitude: -121.906046

Completed - Case Closed Status:

12/19/2003 Status Date:

Direction Distance

Elevation Site Database(s) EPA ID Number

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

Case Worker: UST

RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Diesel Site History: Not reported

LUST:

Global Id: T0608517440

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608517440

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP

Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608517440

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608517440

 Action Type:
 Other

 Date:
 07/13/2001

 Action:
 Leak Reported

 Global Id:
 T0608517440

 Action Type:
 RESPONSE

 Date:
 06/28/2001

Action: Unauthorized Release Form

 Global Id:
 T0608517440

 Action Type:
 RESPONSE

 Date:
 10/22/2001

 Action:
 Other Workplan

 Global Id:
 T0608517440

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

Global Id: T0608517440
Action Type: RESPONSE
Date: 09/04/2001

Direction Distance

Elevation Site Database(s) **EPA ID Number**

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

Action: Tank Removal Report / UST Sampling Report

Global Id: T0608517440 Action Type: **RESPONSE** Date: 01/01/2001 Action: Correspondence

Global Id: T0608517440 Action Type: **RESPONSE** Date: 08/20/2002

Action: Monitoring Report - Quarterly

T0608517440 Global Id: Action Type: **RESPONSE** Date: 01/31/2002

Action: Preliminary Site Assessment Report

T0608517440 Global Id: Action Type: **RESPONSE** 05/06/2002 Date:

Action: Well Installation Report

Global Id: T0608517440 Action Type: **RESPONSE** Date: 12/08/2003

Action: Well Destruction Report

Global Id: T0608517440 Action Type: **ENFORCEMENT** Date: 09/04/2001 Staff Letter - #27039 Action:

Global Id: T0608517440 Action Type: **ENFORCEMENT** Date: 10/22/2001

Staff Letter - #27041 Action:

Global Id: T0608517440 **ENFORCEMENT** Action Type: Date: 01/31/2002 Staff Letter - #27043 Action:

Global Id: T0608517440 Action Type: **RESPONSE** Date: 06/03/2005

Other Report / Document Action:

Global Id: T0608517440 Action Type: **RESPONSE** 09/05/2001 Date:

Action: Other Report / Document

Global Id: T0608517440 Action Type: **RESPONSE** Date: 09/09/2002

Action: Monitoring Report - Quarterly

Direction Distance Flevation

Elevation Site Database(s) EPA ID Number

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

 Global Id:
 T0608517440

 Action Type:
 RESPONSE

 Date:
 10/24/2001

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608517440

 Action Type:
 RESPONSE

 Date:
 02/01/2002

Action: Preliminary Site Assessment Report

 Global Id:
 T0608517440

 Action Type:
 ENFORCEMENT

 Date:
 05/20/2002

 Action:
 Staff Letter - #37777

LUST:

Global Id: T0608517440

Status: Completed - Case Closed

Status Date: 12/19/2003

Global Id: T0608517440

Status: Open - Case Begin Date

Status Date: 08/21/2000

Global Id: T0608517440

Status: Open - Site Assessment

Status Date: 08/21/2000

Global Id: T0608517440

Status: Open - Site Assessment

Status Date: 01/21/2002

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07L07F

 Date Closed:
 12/19/2003

 EDR Link ID:
 07S1E07L07F

CHMIRS:

OES Incident Number: 2-0330 OES notification: 01/17/2002 OES Date: Not reported Not reported OES Time: **Date Completed:** Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Not reported Time Completed: Surrounding Area: Not reported Not reported Estimated Temperature: Not reported Property Management: More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported

Distance

Elevation Site Database(s) EPA ID Number

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

Responding Agency Personel # Of Fatalities: Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Not reported Vehicle License Number: Not reported Vehicle State: Vehicle Id Number: Not reported CA DOT PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Facility Telephone: Not reported Waterway Involved: Yes Waterway: Storm drain. Spill Site: Not reported Cleanup By: Responsible Party Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002

Incident Date: 1/17/200212:00:00 AM

Admin Agency: Santa Clara County Health Department

NRC

Amount: Not reported
Contained: Yes
Site Type: Road
E Date: Not reported
Substance: Mineral Oil

Gallons: 7 Unknown: 0

Agency:

Substance #2: Not reported Substance #3: Not reported

Evacuations: 0
Number of Injuries: 0
Number of Fatalities: 0
#1 Pipeline: Not reported

#2 Pipeline: Not reported #3 Pipeline: Not reported #1 Vessel >= 300 Tons: Not reported #2 Vessel >= 300 Tons: Not reported #3 Vessel >= 300 Tons: Not reported Evacs: Not reported Injuries: Not reported Fatals: Not reported Comments: Not reported

Description: Per the NRC report, due to equipment failure, a

pole mounted transformer spilled transformer oil onto an asphalt surface and into a storm drain. 3 gallons of the 7 went into the storm drain. Absorbents were applied and material contained.

OES Incident Number: 10-4432 OES notification: 07/23/2010

Direction Distance Elevation

vation Site Database(s) EPA ID Number

Not reported

PG&E CINNABAR SERVICE CTR (Continued)

OES Date:

S105882239

EDR ID Number

Not reported **OES Time: Date Completed:** Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Not reported Time Notified: Time Completed: Not reported Surrounding Area: Not reported **Estimated Temperature:** Not reported Property Management: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities: Not reported Others Number Of Decontaminated: Not reported Not reported Others Number Of Injuries: Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported Not reported CA DOT PUC/ICC Number: Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Facility Telephone: Not reported Waterway Involved: Yes Waterway: Storm drain Spill Site: Merchant/Business Cleanup By: Contractor Containment: Not reported What Happened: Not reported Type: Not reported Measure: Gal(s) Not reported Other: Date/Time: 330 Year: 2010 Agency: PG&E Incident Date: 7/23/2010

Admin Agency: Santa Clara County Health Department

Amount: Not reported Contained: Yes Site Type: Storm drain E Date: Not reported

Substance: Insulating oil (mineral oil)

Quantity Released: 150

Unknown: Not reported Substance #2: Not reported Substance #3: Not reported Evacuations: Not reported Number of Injuries: Not reported Number of Fatalities: Not reported #1 Pipeline: Not reported #2 Pipeline: Not reported #3 Pipeline: Not reported #1 Vessel >= 300 Tons: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

#2 Vessel >= 300 Tons:

#3 Vessel >= 300 Tons:

Not reported
Evacs:

Not reported
Injuries:

Not reported

Description:

A transformer was in the process of being moved when it fell from a truck causing the product to spill onto asphalt and approximately 5-10 gallons went into a storm drain. A clean up crew is on

went into a storm drain. A clean up crew is on scene and in the process of vacuming it out of the drain. A sample will be obtained for lab

purposes.

Not reported

OES Incident Number: 16-4984 OES notification: 08/16/2016 OES Date: Not reported **OES Time:** Not reported **Date Completed:** Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Not reported Time Notified: Time Completed: Not reported Surrounding Area: Not reported Not reported **Estimated Temperature: Property Management:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities: Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA DOT PUC/ICC Number: Not reported Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported

Waterway Involved: Yes

Facility Telephone:

Storm Drain Waterway: Spill Site: Other Cleanup By: Contractor Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported **PETROLEUM** Type: Measure: Gal(s) Other: Not reported

 Date/Time:
 100

 Year:
 2016

Distance
Elevation Site

EDR ID Number
Database(s) EPA ID Number

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

Agency: PG&E Incident Date: 08/16/2016

Admin Agency: Santa Clara County Department of Environmental Health

Amount: Not reported

Contained: No

Site Type: Storm Drain E Date: Not reported

Substance: Non-PCB Transformer Oil

Quantity Released: 500

Unknown:

Substance #2:

Substance #3:

Evacuations:

Not reported

#1 Pipeline: No #2 Pipeline: No #3 Pipeline: No #1 Vessel >= 300 Tons: No #2 Vessel >= 300 Tons: No #3 Vessel >= 300 Tons: No Evacs: No Injuries: No Fatals: No

Comments: Not reported

Description:

RP states, During the off-loading of a transformer from the back of the truck, the forklift could not handle the weight and fell over. This caused the release of approx 500

Not reported

gallons of non-pcb transformer oil. The transformer is no longer releasing and is

OES Incident Number: 12-1510 03/15/2012 OES notification: OES Date: Not reported **OES Time:** Not reported **Date Completed:** Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Not reported Time Notified: Time Completed: Not reported Surrounding Area: Not reported **Estimated Temperature:** Not reported **Property Management:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities: Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported

CA DOT PUC/ICC Number:

Direction Distance Elevation

evation Site Database(s) EPA ID Number

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Facility Telephone: Not reported Waterway Involved: Yes Waterway: Storm drain Spill Site: Other Cleanup By: Contractor Containment: Not reported What Happened: Not reported Type: Not reported Measure: Gal(s) Other: Not reported Date/Time: 745 2012 Year: Agency: PG&E Incident Date: 3/15/2012

Admin Agency: Santa Clara County Health Department

Amount: Not reported

Contained: Yes

Site Type: Storm drain E Date: Not reported Substance: Gasoline Quantity Released: 6-May Unknown: Not reported Substance #2: Not reported Substance #3: Not reported Evacuations: Not reported Number of Injuries: Not reported Number of Fatalities: Not reported #1 Pipeline: Not reported #2 Pipeline: Not reported #3 Pipeline: Not reported #1 Vessel >= 300 Tons: Not reported #2 Vessel >= 300 Tons: Not reported #3 Vessel >= 300 Tons: Not reported Evacs: Not reported Injuries: Not reported

Description: Caller states a personal vehicle had a hole in

the gas tank resulting in a release of

approximately two gallons being released to a storm drain. Caller states clean-up is in

progress.

Not reported

Not reported

CUPA SANTA CLARA:

Fatals:

Comments:

Region: SANTA CLARA

PE#: 2208

Program Description: GENERATES 50 TO <250 TONS/YR

 Latitude:
 37.334128

 Longitude:
 -121.906064

 Record ID:
 PR0312804

 Facility ID:
 FA0208679

Region: SANTA CLARA

PE#: 2399

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

UNDERGROUND STORAGE TANK PROGRAM RECORD Program Description:

Latitude: 37.334128 Longitude: -121.906064 Record ID: PR0396276 Facility ID: FA0208679

SANTA CLARA Region: PE#: Not reported

Program Description: HMBP FACILITY, 22+ CHEMICALS

Latitude: 37.334128 -121.906064 Longitude: Record ID: PR0396277 Facility ID: FA0208679

Region: SANTA CLARA

PE#: 2011

Program Description: APSA FACILITY-SPCC TEMPLATE (<10,000 GAL CAP)

Latitude: 37.334128 Longitude: -121.906064 Record ID: PR0399623 Facility ID: FA0208679

Region: SANTA CLARA PE#: Not reported

HMBP FAC, \$152 FOR EACH ADDITIONAL 6 CHEMS Program Description:

Latitude: 37.334128 Longitude: -121.906064 Record ID: PR0396278 Facility ID: FA0208679

SANTA CLARA Region: PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.33409 -121.906186 Longitude: Record ID: PR0399265 Facility ID: FA0268764

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 405875

Class: **Chemical Warehouse**

SAN JOSE Region: File Num: 600005

Class: Misc. Complex firms and labs

CERS TANKS:

Site ID: 203297 CERS ID: T0608517440

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Local Agency Caseworker Affiliation Type Desc:

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Direction Distance

Elevation Site Database(s) **EPA ID Number**

PG&E CINNABAR SERVICE CTR (Continued)

S105882239

EDR ID Number

SAN JOSE Affiliation City: Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

OAKLAND Affiliation City: Affiliation State: CA Affiliation Country: Not reported

Affiliation Zip: Not reported Affiliation Phone: Not reported

M107 **MASCO SWEEPERS CUPA Listings** S121471743 SSW

120 STOCKTON AV N/A

SAN JOSE, CA 95127 1/8-1/4

0.193 mi.

1020 ft. Site 6 of 7 in cluster M CUPA SANTA CLARA: Relative:

Higher Region: SANTA CLARA

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 94 ft.

> Latitude: 37.332683 Longitude: -121.904473 Record ID: PR0364244 Facility ID: FA0250976

Q108 **GRIFFEL FURNITURE SHOP CUPA Listings** S121469417

1/8-1/4 SAN JOSE, CA 95126

165 STOCKTON AV

0.193 mi.

SW

1021 ft. Site 1 of 2 in cluster Q Relative: CUPA SANTA CLARA:

Higher Region: SANTA CLARA

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 94 ft.

Latitude: 37.332707 Longitude: -121.90496 Record ID: PR0313128 Facility ID: FA0206694

N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number**

R109 INTERIOR PLANT DESIGN LUST S101309292 South

589 SANTA CLARA ST W HIST LUST N/A

1/8-1/4 SAN JOSE, CA 95113 **HIST CORTESE** 0.196 mi. **CERS**

1037 ft. Site 1 of 6 in cluster R

LUST: Relative:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500754 91 ft.

Global Id: T0608500754 Latitude: 37.332119 -121.900945 Longitude:

Completed - Case Closed Status:

07/25/1997 Status Date: Case Worker: UUU RB Case Number: 43-0727

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608500754 Global Id:

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608500754

Local Agency Caseworker Contact Type: **UST CASE WORKER** Contact Name: Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

SAN JOSE City: Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608500754 Action Type: Other Date: 03/28/1989 Action: Leak Reported

T0608500754 Global Id: Action Type: **ENFORCEMENT** 04/09/1997 Date:

Action: Closure/No Further Action Letter

Global Id: T0608500754 Action Type: Other 03/28/1989 Date: Action: Leak Discovery **EDR ID Number**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

INTERIOR PLANT DESIGN (Continued)

S101309292

T0608500754 Global Id: Action Type: Other 03/28/1989 Date: Action: Leak Stopped

LUST:

Global Id: T0608500754

Status: Completed - Case Closed

Status Date: 07/25/1997

T0608500754 Global Id:

Status: Open - Case Begin Date

03/28/1989 Status Date:

LUST REG 2:

Region: 2

Facility Id: 43-0727 Facility Status: Case Closed Case Number: 07S1E07Q09 How Discovered: Tank Closure Leak Cause: Structure Failure Leak Source: Tank Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

SANTA CLARA Region: SCVWD ID: 07S1E07Q09F Date Closed: 04/09/1997 EDR Link ID: 07S1E07Q09F

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E07Q09 Oversite Agency: SFRWQCB

1996-01-01 00:00:00 Date Listed: Closed Date: 1997-04-09 00:00:00

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-0727

CERS TANKS:

Site ID: 212708

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

INTERIOR PLANT DESIGN (Continued)

S101309292

CERS ID: T0608500754

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported

Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

 R110
 SAN JOSE ARENA FOLLOSCO PARCEL
 LUST S103177350

 South
 575 SANTA CLARA ST W
 HIST CORTESE N/A

 1/8-1/4
 SAN JOSE, CA 95113
 CERS

0.197 mi.

1038 ft. Site 2 of 6 in cluster R

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

91 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500632

 Global Id:
 T0608500632

 Latitude:
 37.332132

 Longitude:
 -121.900765

Status: Completed - Case Closed

Status Date: 04/10/1997 Case Worker: UUU RB Case Number: 43-0596

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Soil

Potential Contaminants of Concern: Stoddard solvent / Mineral Spriits / Distillates

Site History: Not reported

LUST:

Global Id: T0608500632

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Direction
Distance
Flevation

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA FOLLOSCO PARCEL (Continued)

S103177350

EDR ID Number

Global Id: T0608500632

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500632

 Action Type:
 ENFORCEMENT

 Date:
 04/09/1997

Action: Closure/No Further Action Letter - #43-0596

 Global Id:
 T0608500632

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Reported

 Global Id:
 T0608500632

 Action Type:
 RESPONSE

 Date:
 01/01/1997

Action: Other Report / Document

 Global Id:
 T0608500632

 Action Type:
 RESPONSE

 Date:
 01/01/1989

Action: Other Report / Document

 Global Id:
 T0608500632

 Action Type:
 RESPONSE

 Date:
 01/01/1997

Action: Other Report / Document

Global Id: T0608500632
Action Type: RESPONSE
Date: 01/01/1990

Action: Other Report / Document

 Global Id:
 T0608500632

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Discovery

 Global Id:
 T0608500632

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Stopped

LUST:

Global Id: T0608500632

Status: Completed - Case Closed

Status Date: 04/10/1997

Global Id: T0608500632

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA FOLLOSCO PARCEL (Continued)

S103177350

EDR ID Number

Status: Open - Case Begin Date

Status Date: 03/28/1989

LUST REG 2:

Region: 2

Facility Id: 43-0596 Facility Status: Case Closed Case Number: 43-0596 How Discovered: Tank Closure Leak Cause: Structure Failure Leak Source: Tank Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Not reported
Not reported
Not reported
Not reported
Post Remediation Action Underway:
Not reported
Not reported
Not reported
Not reported

HIST CORTESE:

Region: CORTESE Facility County Code: 43 Reg By: LTNKA Reg Id: 43-0596

CERS TANKS:

Site ID: 249703 CERS ID: T0608500632

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

R111 FOLLOSCO TRANSMISSION REPAIR LUST S103881001
South 575 W SANTA CLARA ST HIST LUST N/A

South 575 W SANTA CLARA ST 1/8-1/4 SAN JOSE, CA

1/8-1/4 0.197 mi.

1038 ft. Site 3 of 6 in cluster R

Relative: LUST SANTA CLARA:

 Higher
 Region:
 SANTA CLARA

 Actual:
 SCVWD ID:
 07S1E07Q05F

 91 ft.
 Date Closed:
 04/09/1997

 EDR Link ID:
 07S1E07Q05F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07Q05 Oversite Agency: SFRWQCB

Date Listed: 1992-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00

 R112
 KOSICH CONSTRUCTION COMPANY
 LUST
 \$103473098

 South
 555-561 SANTA CLARA ST W
 CERS
 N/A

1/8-1/4 SAN JOSE, CA 95113

0.197 mi.

1038 ft. Site 4 of 6 in cluster R

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

91 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500229

Global Id: T0608500229
Latitude: 37.332152
Longitude: -121.900495

Status: Completed - Case Closed

 Status Date:
 04/09/1997

 Case Worker:
 UUU

 RB Case Number:
 43-0163

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500229

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500229

Contact Type: Local Agency Caseworker Contact Name: UST CASE WORKER

Organization Name: SANTA CLARA COUNTY LOP Address: SANTA CLARA COUNTY LOP 1555 Berger Drive, Suite 300

City: SAN JOSE

Direction Distance

Elevation Site Database(s) EPA ID Number

KOSICH CONSTRUCTION COMPANY (Continued)

S103473098

EDR ID Number

Email: Not reported Phone Number: 4089183400

LUST:

 Global Id:
 T0608500229

 Action Type:
 ENFORCEMENT

 Date:
 05/26/1995

Action: Clean Up Fund - Letter to RP - #43-0163

 Global Id:
 T0608500229

 Action Type:
 ENFORCEMENT

 Date:
 08/05/1993

Action: Staff Letter - #43-0163

 Global Id:
 T0608500229

 Action Type:
 Other

 Date:
 07/21/1989

 Action:
 Leak Reported

Global Id: T0608500229
Action Type: ENFORCEMENT
Date: 04/09/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608500229

 Action Type:
 RESPONSE

 Date:
 01/01/1989

Action: Other Report / Document

Global Id: T0608500229
Action Type: RESPONSE
Date: 01/01/1997

Action: Other Report / Document

Global Id: T0608500229
Action Type: RESPONSE
Date: 01/01/1997

Action: Other Report / Document

 Global Id:
 T0608500229

 Action Type:
 RESPONSE

 Date:
 01/01/1989

Action: Other Report / Document

Global Id: T0608500229
Action Type: RESPONSE
Date: 01/01/1989

Action: Other Report / Document

 Global Id:
 T0608500229

 Action Type:
 RESPONSE

 Date:
 01/01/2004

Action: Other Report / Document

 Global Id:
 T0608500229

 Action Type:
 RESPONSE

 Date:
 01/01/1989

Direction Distance

Elevation Site Database(s) EPA ID Number

KOSICH CONSTRUCTION COMPANY (Continued)

S103473098

EDR ID Number

Action: Other Report / Document

 Global Id:
 T0608500229

 Action Type:
 Other

 Date:
 07/21/1989

 Action:
 Leak Discovery

 Global Id:
 T0608500229

 Action Type:
 Other

 Date:
 07/21/1989

 Action:
 Leak Stopped

LUST:

Global Id: T0608500229

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608500229

Status: Open - Case Begin Date

Status Date: 07/21/1989

LUST REG 2:

Region: 2
Facility Id: 43-0163
Facility Status: Case Closed
Case Number: 07S1E07Q03
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Not reported
Not reported
Not reported
Not reported
Not reported

CERS TANKS:

 Site ID:
 252112

 CERS ID:
 T0608500229

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

KOSICH CONSTRUCTION COMPANY (Continued)

S103473098

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Not reported Affiliation Zip: 4089183400 Affiliation Phone:

SAN JOSE AUTO STEAM CLEANERS M113

RCRA-SQG 1000121094 SSW CAD981452808

32 STOCKTON AVE **CERS HAZ WASTE** 1/8-1/4 SAN JOSE, CA 95126

FINDS ECHO

Site 7 of 7 in cluster M 1043 ft. **CUPA Listings HAZNET** Relative:

SAN JOSE HAZMAT **CERS**

Higher Actual:

0.198 mi.

RCRA-SQG: 91 ft.

Date form received by agency: 09/01/1996

Facility name: SAN JOSE AUTO STEAM CLEANERS

Facility address: 32 STOCKTON AVE

SAN JOSE, CA 95126

EPA ID: CAD981452808

STOCKTON AVE Mailing address:

SAN JOSE, CA 95126

Contact: Not reported Contact address: Not reported

Not reported

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: DAVID M GREWER Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED NOT REQUIRED Owner/operator address:

Distance Elevation Site

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

NOT REQUIRED, ME 99999

Owner/operator country: Not reported 415-555-1212 Owner/operator telephone: Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: Nο Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

CERS HAZ WASTE:

Site ID: 64604 CERS ID: 10351732

CERS Description: Hazardous Waste Generator

Violations:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: 22 CCR 15 66265.195(a) - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.195(a)

Violation Description: Failure of the owner or operator to conduct inspections and maintain

inspection records at the facility of the following tank equipment: 1)
Overfill/spill control equipment (e.g., waste-feed cutoff systems, bypass systems, and drainage systems) to ensure that it is in good working order; 2) The aboveground portions of the tank system, if any, to detect corrosion or releases of waste; 3) Data gathered from

monitoring equipment and leak-detection equipment, (e.g., pressure and

temperature gauges, monitoring wells) to ensure that the tank system is being operated according to its design; 4) The construction

materials and the area immediately surrounding the externally accessible portion of the tank system including secondary containment

structures (e.g., dikes) to detect erosion or signs of releases of hazardous waste (e.g., wet spots, dead vegetation); and 5) For uncovered tanks, the level of waste in the tank, to ensure compliance

with section 66265.194(b)(3).

Violation Notes: Returned to compliance on 10/10/2014.

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

Facility observes the tank multiple times daily but is not logging the inspections. Update your inspection records to include the items noted

below and log the inspection details at least once daily.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 10/10/2014.

Facility did not submit an annual update to CERS to cover the 1500 gallon hazardous waste treatment tank, the 55 gallon drum of Hi-Chem HMP (corrosive) and the 2x 55gallon waste sludge drums. Submit a

complete HMBP on CERS.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure of the generator to prepare and maintain onsite, for a period

of five years, the following: (1) compliance records of all

pretreatment and discharge records to the POTW; (2) records of the dates, concentrations, amounts, and types of waste treated; and (3) operating instructions that include: A) How to operate the treatment unit and carry out waste treatment; B) How to recognize potential and actual process upsets and respond to them; C) When to implement the contingency plan; D) How to determine if the treatment has been efficacious; and E) How to address the residuals of waste treatment.

Deturned to compliance on 10/10/2014

Violation Notes: Returned to compliance on 10/10/2014.

facility could not produce the current POTW (waste water discharge permit). An application from 2012 was observed. Obtain a copy of the

permit and ensure it is on site for review during inspections.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure of the generator to prepare and maintain onsite, for a period

of five years, the following: (1) compliance records of all

The

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

pretreatment and discharge records to the POTW; (2) records of the dates, concentrations, amounts, and types of waste treated; and (3) operating instructions that include: A) How to operate the treatment unit and carry out waste treatment; B) How to recognize potential and actual process upsets and respond to them; C) When to implement the contingency plan; D) How to determine if the treatment has been efficacious; and E) How to address the residuals of waste treatment.

Violation Notes: Returned to compliance on 10/10/2014.

Facility did not have operating instructions on site. A file copy is no longer valid as their processes have changed slightly. Prepare an updated operating instructions and begin logging the volumes of waste

treated on the daily log.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 09/05/2014.

_____One

of two waste water sludge drums had the drum ring removed. Ensure all hazardous waste containers are properly closed when not adding or removing waste. Drum ring was replaced during the inspection. No

further corrective actions required.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure to prepare and maintain onsite for five years, a treatment

system inspection program and the log of inspections conducted.

Violation Notes: Returned to compliance on 10/10/2014.

Facility observes the treatment system multiple times during the operating day, but does not have a written inspection schedule and a minimal log. Prepare a written inspection schedule and update the log

to provide details of the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014 Violations Found: Yes

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

Eval Type: Routine done by local agency

Eval Notes: Light automotive engine steam cleaning operations. Facility has a 1500

gallon hazardous waste treatment tank, 1x 55 gallon Hi-Chem HMP

(corrosive) and 2 55 gallon drums of waste sludge.

Eval Division: Santa Clara County Environmental Health

Eval Program: **HMRRP** Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility treats waste water from automobile engine steam cleaning.

> Facility stated that their operations have changed from more heavy-duty equipment to light-duty passenger vehicles. Facility also stated that the POTW may not require a permit in the future due to the low levels and infrequent high readings. It is recommended that a representative sample of the waste generated be collected and sent for testing (CAM-17 hazardous waste metals). Collect the sample of waste prior to it reaching the first sump. Contact the inspector with any

questions.

Eval Division: Santa Clara County Environmental Health

Eval Program: CA **Eval Source: CERS**

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014

Violations Found: Yes

Eval Type: Routine done by local agency

EPA ID# CAD981452808 is active. Facility generates waste water and **Eval Notes:**

waste water treatment sludge from automotive engine steam cleaning

operations.

Eval Division: Santa Clara County Environmental Health

Eval Program: HW **CERS Eval Source:**

Enforcement Action:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

32 STOCKTON AV Site Address:

SAN JOSE Site City: Site Zip: 95125 Enf Action Date: 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: CA **CERS** Enf Action Source:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Site Address: 32 STOCKTON AV

Site City: SAN JOSE Site Zip: 95125 Enf Action Date: 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: **HMRRP** Enf Action Source: **CERS**

Site ID: 64604

SAN JOSE AUTO STEAM CLEANING Site Name:

Site Address: 32 STOCKTON AV

Site City: SAN JOSE Site Zip: 95125 Enf Action Date: 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW **CERS** Enf Action Source:

Affiliation:

Affiliation Type Desc: **Environmental Contact**

Entity Name: James Grewer Entity Title: Not reported Affiliation Address: 32 Stockton Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95126

(408) 288-7440 Affiliation Phone:

Affiliation Type Desc: **Document Preparer Entity Name:** James Grewer **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Facility Mailing Address Affiliation Type Desc: Entity Name: Mailing Address

Entity Title: Not reported 32 STOCKTON AV Affiliation Address:

SAN JOSE Affiliation City:

Affiliation State: CA

Affiliation Country: Not reported 95125 Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: James Grewer Entity Title: Vice Pres. Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: SAN JOSE AUTO STEAM CLEANING

Entity Title: Not reported
Affiliation Address: 32 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95125

Affiliation Phone: (408) 288-7440

Affiliation Type Desc: Operator

Entity Name: San Jose Auto Steam Cleaning Inc.

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 288-7440

Affiliation Type Desc: Parent Corporation

Entity Name: SAN JOSE AUTO STEAM CLEANING

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: James Grewer Entity Title: Vice President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Site ID: 64604 CERS ID: 10351732

CERS Description: Hazardous Waste Onsite Treatment

Elevation Site

Distance

Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Violations:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: 22 CCR 15 66265.195(a) - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.195(a)

Violation Description: Failure of the owner or operator to conduct inspections and maintain

inspection records at the facility of the following tank equipment: 1) Overfill/spill control equipment (e.g., waste-feed cutoff systems, bypass systems, and drainage systems) to ensure that it is in good working order; 2) The aboveground portions of the tank system, if any, to detect corrosion or releases of waste; 3) Data gathered from

monitoring equipment and leak-detection equipment, (e.g., pressure and temperature gauges, monitoring wells) to ensure that the tank system is being operated according to its design; 4) The construction

accessible portion of the tank system including secondary containment structures (e.g., dikes) to detect erosion or signs of releases of hazardous waste (e.g., wet spots, dead vegetation); and 5) For uncovered tanks, the level of waste in the tank, to ensure compliance

materials and the area immediately surrounding the externally

with section 66265.194(b)(3).

Violation Notes: Returned to compliance on 10/10/2014.

Facility observes the tank multiple times daily but is not logging the inspections. Update your inspection records to include the items noted

below and log the inspection details at least once daily.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 10/10/2014.

Facility did not submit an annual update to CERS to cover the 1500 gallon hazardous waste treatment tank, the 55 gallon drum of Hi-Chem HMP (corrosive) and the 2x 55gallon waste sludge drums. Submit a

complete HMBP on CERS.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure of the generator to prepare and maintain onsite, for a period

of five years, the following: (1) compliance records of all

pretreatment and discharge records to the POTW; (2) records of the

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

dates, concentrations, amounts, and types of waste treated; and (3) operating instructions that include: A) How to operate the treatment unit and carry out waste treatment; B) How to recognize potential and actual process upsets and respond to them; C) When to implement the contingency plan; D) How to determine if the treatment has been efficacious; and E) How to address the residuals of waste treatment.

Violation Notes: Returned to compliance on 10/10/2014.

The

facility could not produce the current POTW (waste water discharge permit). An application from 2012 was observed. Obtain a copy of the permit and ensure it is on site for review during inspections.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure of the generator to prepare and maintain onsite, for a period

of five years, the following: (1) compliance records of all pretreatment and discharge records to the POTW; (2) records of the dates, concentrations, amounts, and types of waste treated; and (3) operating instructions that include: A) How to operate the treatment unit and carry out waste treatment: B) How to recognize potential and

operating instructions that include: A) How to operate the treatment unit and carry out waste treatment; B) How to recognize potential and actual process upsets and respond to them; C) When to implement the contingency plan; D) How to determine if the treatment has been efficacious; and E) How to address the residuals of waste treatment.

Violation Notes: Returned to compliance on 10/10/2014.

Facility did not have operating instructions on site. A file copy is no longer valid as their processes have changed slightly. Prepare an updated operating instructions and begin logging the volumes of waste

treated on the daily log.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 09/05/2014.

One

of two waste water sludge drums had the drum ring removed. Ensure all hazardous waste containers are properly closed when not adding or removing waste. Drum ring was replaced during the inspection. No

further corrective actions required.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure to prepare and maintain onsite for five years, a treatment

system inspection program and the log of inspections conducted.

Violation Notes: Returned to compliance on 10/10/2014.

Facility observes the treatment system multiple times during the operating day, but does not have a written inspection schedule and a minimal log. Prepare a written inspection schedule and update the log

to provide details of the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Light automotive engine steam cleaning operations. Facility has a 1500

gallon hazardous waste treatment tank, 1x 55 gallon Hi-Chem HMP

(corrosive) and 2 55 gallon drums of waste sludge.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility treats waste water from automobile engine steam cleaning.

Facility stated that their operations have changed from more heavy-duty equipment to light-duty passenger vehicles. Facility also stated that the POTW may not require a permit in the future due to the low levels and infrequent high readings. It is recommended that a representative sample of the waste generated be collected and sent for testing (CAM-17 hazardous waste metals). Collect the sample of waste

prior to it reaching the first sump. Contact the inspector with any questions.

Eval Division: Santa Clara County Environmental Health

Eval Program: CA Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: EPA ID# CAD981452808 is active. Facility generates waste water and

waste water treatment sludge from automotive engine steam cleaning

operations.

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Enforcement Action:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Site Address: 32 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95125

 Enf Action Date:
 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: CA
Enf Action Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Site Address: 32 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95125

 Enf Action Date:
 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP Enf Action Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Site Address: 32 STOCKTON AV

 Site City:
 SAN JOSE

 Site Zip:
 95125

 Enf Action Date:
 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW
Enf Action Source: CERS

Affiliation:

Affiliation Type Desc: Environmental Contact

Entity Name: James Grewer Entity Title: Not reported Affiliation Address: 32 Stockton Affiliation City: San Jose Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: 95126 Affiliation Phone: (408) 288-7440

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Affiliation City:

Document Preparer

James Grewer

Not reported

Not reported

Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 32 STOCKTON AV
Affiliation City: SAN JOSE

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95125

Affiliation Zip: 95125
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: James Grewer Entity Title: Vice Pres. Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: SAN JOSE AUTO STEAM CLEANING

Entity Title: Not reported
Affiliation Address: 32 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95125

Affiliation Phone: (408) 288-7440

Affiliation Type Desc: Operator

Entity Name: San Jose Auto Steam Cleaning Inc.

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Not reported

(408) 288-7440

Affiliation Type Desc: Parent Corporation

Entity Name: SAN JOSE AUTO STEAM CLEANING

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: James Grewer Entity Title: Vice President Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

FINDS:

Registry ID: 110002712146

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

STATE MASTER

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000121094 Registry ID: 110002712146

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002712146

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.332277

 Longitude:
 -121.904004

 Record ID:
 PR0313208

 Facility ID:
 FA0208794

Region: SANTA CLARA

PE#: 2262

Program Description: CONDITIONALLY AUTHORIZED (CA)

Latitude: 37.332277 Longitude: -121.904004

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Record ID: PR0369361 Facility ID: FA0208794

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.332277

 Longitude:
 -121.904004

 Record ID:
 PR0397745

 Facility ID:
 FA0208794

HAZNET:

envid: 1000121094 Year: 2017

GEPAID: CAD981452808
Contact: JIM GREWER
Telephone: 4082887440
Mailing Name: Not reported
Mailing Address: 32 STOCKTON AVE
Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Other organic solids

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.9

Cat Decode: Other organic solids

Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Facility County: Santa Clara

envid: 1000121094
Year: 2016
GEPAID: CAD981452808
Contact: JIM GREWER
Telephone: 4082887440
Mailing Name: Not reported
Mailing Address: 32 STOCKTON AVE

Mailing Address: 32 STOCKTON AVE
Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Other organic solids

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 2.25

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000121094 Year: 2015

GEPAID: CAD981452808
Contact: JIM GREWER
Telephone: 4082887440
Mailing Name: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Mailing Address: 32 STOCKTON AVE
Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Other organic solids

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 3.45
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: 1000121094 Year: 2014

GEPAID: CAD981452808
Contact: JIM GREWER
Telephone: 4082887440
Mailing Name: Not reported

Mailing Address: 32 STOCKTON AVE
Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Other organic solids

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.7

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000121094 Year: 2013

GEPAID: CAD981452808
Contact: JIM GREWER
Telephone: 4082887440
Mailing Name: Not reported
Mailing Address: 32 STOCKTON AVE

Mailing City,St,Zip: SAN JOSE, CA 951260000
Gen County: Santa Clara
TSD EPA ID: CAD059494310
TSD County: Santa Clara

Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135) Tons: 0.6

Cat Decode: Not reported Method Decode: Not reported Facility County: Not reported

Click this hyperlink while viewing on your computer to access 18 additional CA_HAZNET: record(s) in the EDR Site Report.

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 483638

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

Class: Auto Wrecking/Misc Simple Facility

CERS TANKS:

Site ID: 64604 CERS ID: 10351732

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

22 CCR 15 66265.195(a) - California Code of Regulations, Title 22, Citation:

Chapter 15, Section(s) 66265.195(a)

Violation Description: Failure of the owner or operator to conduct inspections and maintain

> inspection records at the facility of the following tank equipment: 1) Overfill/spill control equipment (e.g., waste-feed cutoff systems, bypass systems, and drainage systems) to ensure that it is in good working order; 2) The aboveground portions of the tank system, if any, to detect corrosion or releases of waste; 3) Data gathered from

monitoring equipment and leak-detection equipment, (e.g., pressure and temperature gauges, monitoring wells) to ensure that the tank system is being operated according to its design; 4) The construction materials and the area immediately surrounding the externally accessible portion of the tank system including secondary containment structures (e.g., dikes) to detect erosion or signs of releases of hazardous waste (e.g., wet spots, dead vegetation); and 5) For

uncovered tanks, the level of waste in the tank, to ensure compliance with section 66265.194(b)(3).

Violation Notes: Returned to compliance on 10/10/2014.

> Facility observes the tank multiple times daily but is not logging the inspections. Update your inspection records to include the items noted

below and log the inspection details at least once daily.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA Violation Source: **CERS**

64604 Site ID:

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 10/10/2014.

> Facility did not submit an annual update to CERS to cover the 1500 gallon hazardous waste treatment tank, the 55 gallon drum of Hi-Chem HMP (corrosive) and the 2x 55gallon waste sludge drums. Submit a

complete HMBP on CERS.

Santa Clara County Environmental Health Violation Division:

Violation Program: **HMRRP** Violation Source: **CERS**

Site ID: 64604 Map ID MAP FINDINGS Direction

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure of the generator to prepare and maintain onsite, for a period

of five years, the following: (1) compliance records of all

pretreatment and discharge records to the POTW; (2) records of the dates, concentrations, amounts, and types of waste treated; and (3) operating instructions that include: A) How to operate the treatment unit and carry out waste treatment; B) How to recognize potential and actual process upsets and respond to them; C) When to implement the contingency plan; D) How to determine if the treatment has been efficacious; and E) How to address the residuals of waste treatment.

Violation Notes: Returned to compliance on 10/10/2014.

The

facility could not produce the current POTW (waste water discharge permit). An application from 2012 was observed. Obtain a copy of the

permit and ensure it is on site for review during inspections.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA **CERS** Violation Source:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure of the generator to prepare and maintain onsite, for a period

of five years, the following: (1) compliance records of all

pretreatment and discharge records to the POTW; (2) records of the dates, concentrations, amounts, and types of waste treated; and (3) operating instructions that include: A) How to operate the treatment unit and carry out waste treatment; B) How to recognize potential and actual process upsets and respond to them; C) When to implement the contingency plan; D) How to determine if the treatment has been efficacious; and E) How to address the residuals of waste treatment.

Returned to compliance on 10/10/2014.

Facility did not have operating instructions on site. A file copy is

no longer valid as their processes have changed slightly. Prepare an updated operating instructions and begin logging the volumes of waste

treated on the daily log.

Santa Clara County Environmental Health

Violation Division: Violation Program: CA Violation Source: **CERS**

Site ID: 64604

Violation Notes:

SAN JOSE AUTO STEAM CLEANING Site Name:

Violation Date: 09-05-2014

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 09/05/2014.

One

of two waste water sludge drums had the drum ring removed. Ensure all

Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

hazardous waste containers are properly closed when not adding or removing waste. Drum ring was replaced during the inspection. No

further corrective actions required.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Violation Date: 09-05-2014

Citation: HSC 6.5 25200.3(c)(7) - California Health and Safety Code, Chapter

6.5, Section(s) 25200.3(c)(7)

Violation Description: Failure to prepare and maintain onsite for five years, a treatment

system inspection program and the log of inspections conducted.

Violation Notes: Returned to compliance on 10/10/2014.

Facility observes the treatment system multiple times during the operating day, but does not have a written inspection schedule and a minimal log. Prepare a written inspection schedule and update the log

to provide details of the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: CA
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Light automotive engine steam cleaning operations. Facility has a 1500

gallon hazardous waste treatment tank, 1x 55 gallon Hi-Chem HMP

(corrosive) and 2 55 gallon drums of waste sludge.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility treats waste water from automobile engine steam cleaning.

Facility stated that their operations have changed from more heavy-duty equipment to light-duty passenger vehicles. Facility also stated that the POTW may not require a permit in the future due to the low levels and infrequent high readings. It is recommended that a representative sample of the waste generated be collected and sent for testing (CAM-17 hazardous waste metals). Collect the sample of waste prior to it reaching the first sump. Contact the inspector with any

questions.

Eval Division: Santa Clara County Environmental Health

Eval Program: CA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-05-2014

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: EPA ID# CAD981452808 is active. Facility generates waste water and

waste water treatment sludge from automotive engine steam cleaning

operations.

Eval Division: Santa Clara County Environmental Health

Eval Program: HW Eval Source: **CERS**

Enforcement Action:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

32 STOCKTON AV Site Address:

Site City: SAN JOSE Site Zip: 95125 Enf Action Date: 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: CA Enf Action Source: **CERS**

Site ID: 64604

SAN JOSE AUTO STEAM CLEANING Site Name:

Site Address: 32 STOCKTON AV

SAN JOSE Site City: Site Zip: 95125 Enf Action Date: 09-05-2014

Notice of Violation (Unified Program) Enf Action Type:

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: **HMRRP CERS** Enf Action Source:

Site ID: 64604

Site Name: SAN JOSE AUTO STEAM CLEANING

Site Address: 32 STOCKTON AV Site City: SAN JOSE

Site Zip: 95125 Enf Action Date: 09-05-2014

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW **CERS** Enf Action Source:

Affiliation:

Affiliation Type Desc: **Environmental Contact Entity Name:** James Grewer Entity Title: Not reported

Affiliation Address: 32 Stockton Affiliation City: San Jose Affiliation State: CA

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: (408) 288-7440

Affiliation Type Desc: **Document Preparer** Entity Name: James Grewer Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 32 STOCKTON AV
Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95125
Affiliation Phone: Not reported

Identification Signer Affiliation Type Desc: Entity Name: James Grewer Entity Title: Vice Pres. Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: SAN JOSE AUTO STEAM CLEANING

Entity Title: Not reported
Affiliation Address: 32 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95125

Affiliation Phone: (408) 288-7440

Affiliation Type Desc: Operator

Entity Name: San Jose Auto Steam Cleaning Inc.

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation City:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

(408) 288-7440

Affiliation Type Desc: Parent Corporation

Entity Name: SAN JOSE AUTO STEAM CLEANING

Entity Title: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE AUTO STEAM CLEANERS (Continued)

1000121094

EDR ID Number

Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: James Grewer Entity Title: Vice President Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

P114 CINNABAR SERVICE CENTER

WSW 309 STOCKTON AVE 1/8-1/4 SAN JOSE, CA 95126

0.198 mi.

1045 ft. Site 8 of 15 in cluster P

Relative: RCRA-LQG:

Higher Date form received by agency: 04/01/2010

Actual: Facility name: CINNABAR SERVICE CENTER

92 ft. Facility address: 309 STOCKTON AVE

SAN JOSE, CA 95126 EPA ID: CAD981409725

Mailing address: SALEM STREET
CHICO, CA 95928
Contact: DAVE MISSALL
Contact address: SALEM STREET

CHICO, CA 95928

Contact country: US

Contact telephone: 530-896-4281 Contact email: DAM9@PGE.COM

EPA Region: 09 Land type: Private

Classification: Large Quantity Generator

Description: Handler: generates 1,000 kg or more of hazardous waste during any

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1

RCRA-LQG

1007199295

CAD981409725

Direction Distance Elevation

Site Database(s) **EPA ID Number**

CINNABAR SERVICE CENTER (Continued)

1007199295

EDR ID Number

kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

PACIFIC GAS AND ELECTRIC Owner/operator name:

Owner/operator address: Not reported Not reported Owner/operator country: Not reported Owner/operator telephone: Not reported Owner/operator email: Not reported Owner/operator fax: Not reported Not reported Owner/operator extension: Legal status: Private Owner/Operator Type: Operator

Owner/Op start date: 01/01/1952 Owner/Op end date: Not reported

PACIFIC GAS AND ELECTRIC Owner/operator name:

Owner/operator address: P.O. BOX 77000

SAN FRANCISCO, CA 94105

Owner/operator country: Not reported Owner/operator telephone: 530-896-4281 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner 01/01/1952

Owner/Op start date: Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: Nο On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Waste code:

Waste name: Other inorganic solid waste

Waste code: 223

Waste name: Unspecified oil-containing waste Map ID MAP FINDINGS
Direction

Distance Elevation

Site Database(s) EPA ID Number

CINNABAR SERVICE CENTER (Continued)

1007199295

EDR ID Number

. Waste code: 272

. Waste name: Polymeric resin waste

. Waste code: 281 . Waste name: Adhesives

Waste code: 343

Waste name: Unspecified organic liquid mixture

Waste code: 792

. Waste name: Liquids with pH < 2 with metals

Waste code: D001

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D009
. Waste name: MERCURY

Waste code: D018
Waste name: BENZENE

Waste code: F003

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT
MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT
NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS
CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED
SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR
MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL
BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT

MIXTURES.

Historical Generators:

Date form received by agency: 10/12/2000

Site name: CINNABAR SERVICE CENTER
Classification: Large Quantity Generator

Date form received by agency: 04/16/1990

Site name: PG&E-CINNABAR SERVICE CENTER

Classification: Large Quantity Generator

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CINNABAR SERVICE CENTER (Continued)

1007199295

Facility Has Received Notices of Violations:

Regulation violated: Not reported Area of violation: Generators - General

Date violation determined: 10/19/2007 Date achieved compliance: 11/29/2007 Violation lead agency: State

WRITTEN INFORMAL Enforcement action:

Enforcement action date: 10/19/2007 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/19/2007

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 11/29/2007 Evaluation lead agency: State

OUT OF BUSINESS (J LOHR WINERY) S115 **CUPA Listings** S121474997

566 CINNABAR ST WNW SAN JOSE HAZMAT N/A

1/8-1/4 SAN JOSE, CA 95110

0.204 mi.

1079 ft. Site 1 of 2 in cluster S

CUPA SANTA CLARA: Relative: Lower SANTA CLARA Region: PE#: Not reported

Actual: Program Description: HMBP FACILITY, 4-6 CHEMICALS 83 ft.

37.336993 Latitude: Longitude: -121.905354 Record ID: PR0397416 Facility ID: FA0700421

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 403147

Class: Auto Wrecking/Misc Simple Facility

P116 **HANOVER 715 W JULIAN MIXED USE** CPS-SLIC S123185290

WSW 715 W JULIAN ST 1/8-1/4 SAN JOSE, CA 95126

0.207 mi.

1093 ft. Site 9 of 15 in cluster P

Relative: CPS-SLIC:

Higher STATE Region: **Facility Status:** Open - Active Actual: Status Date: 12/04/2018 92 ft. Global Id: T10000012367

> SANTA CLARA COUNTY LOP Lead Agency:

Lead Agency Case Number: 2018-32s 37.33388 Latitude:

N/A

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

HANOVER 715 W JULIAN MIXED USE (Continued)

S123185290

Longitude: -121.90648

Case Type: Cleanup Program Site

Case Worker: AC

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database Potential Media Affected: Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern: Not reported Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Q117 WHOLE FOODS MARKET - THE ALAMEDA CERS HAZ WASTE S117892489

SW 777 THE ALAMEDA CUPA Listings N/A
1/8-1/4 SAN JOSE, CA 95126 SAN JOSE HAZMAT
0.211 mi. CERS

1115 ft. Site 2 of 2 in cluster Q

Relative: CERS HAZ WASTE:

 Higher
 Site ID:
 85974

 Actual:
 CERS ID:
 10601911

94 ft. CERS Description: Hazardous Waste Generator

Coordinates:

Site ID: 85974

Facility Name: Whole Foods Market - The Alameda

Env Int Type Code: HWG
Program ID: 10601911
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.331850 Longitude: -121.905200

Affiliation:

Affiliation Type Desc: Environmental Contact
Entity Name: Debora Sanches
Entity Title: Not reported

Affiliation Address: 5980 Horton Street, Suite 200

Affiliation City: Emeryville
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94608
Affiliation Phone: (510) 428-7400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: P.O. Box 684786

Affiliation City: Austin
Affiliation State: TX
Affiliation Country: Not rep

Affiliation Country: Not reported Affiliation Zip: 78768
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: Whole Foods Market California, Inc.

Entity Title: Not reported

Affiliation Address: 5980 Horton Street, Suite 200

Direction Distance

Elevation Site Database(s) EPA ID Number

WHOLE FOODS MARKET - THE ALAMEDA (Continued)

S117892489

EDR ID Number

Affiliation City: Emeryville
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94608
Affiliation Phone: (510) 428-7400

Affiliation Type Desc: Operator

Entity Name: Whole Foods Market California, Inc.

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 207-1120

Affiliation Type Desc: **Document Preparer** Hartman King PC **Entity Name:** Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner

Entity Name: Alameda Stockton LLC; Eugene Hudson

Entity Title: Not reported

Affiliation Address: 1885 The Alameda, Suite 100-E

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 247-4570

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer
Entity Name: Debora Sanches
Entity Title: Environmental Specialist

Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation

Direction Distance

Elevation Site Database(s) **EPA ID Number**

WHOLE FOODS MARKET - THE ALAMEDA (Continued)

S117892489

EDR ID Number

Entity Name: Whole Foods Market California, Inc.

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

CUPA SANTA CLARA:

SANTA CLARA Region: PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.33185 Longitude: -121.9052 PR0420198 Record ID: Facility ID: FA0278077

Region: SANTA CLARA

PE#: 2205

GENERATES 100 KG YR TO <5 TONS/YR Program Description:

Latitude: 37.33185 Longitude: -121.9052 PR0420197 Record ID: Facility ID: FA0278077

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 602247

Class: Auto Wrecking/Misc Simple Facility

CERS TANKS:

Site ID: 85974 CERS ID: 10601911

CERS Description: Chemical Storage Facilities

Coordinates:

Site ID: 85974

Whole Foods Market - The Alameda Facility Name:

Env Int Type Code: **HWG** Program ID: 10601911 Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.331850 Longitude: -121.905200

Affiliation:

Affiliation Type Desc: **Environmental Contact Entity Name:** Debora Sanches Entity Title: Not reported

Affiliation Address: 5980 Horton Street, Suite 200

Affiliation City: Emeryville

Affiliation State: CA

Affiliation Country: Not reported 94608 Affiliation Zip:

Direction Distance Elevation

ation Site Database(s) EPA ID Number

WHOLE FOODS MARKET - THE ALAMEDA (Continued)

S117892489

EDR ID Number

Affiliation Phone: (510) 428-7400

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: P.O. Box 684786

Affiliation City: Austin
Affiliation State: TX

Affiliation Country: Not reported Affiliation Zip: 78768
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: Whole Foods Market California, Inc.

Entity Title: Not reported

Affiliation Address: 5980 Horton Street, Suite 200

Affiliation City: Emeryville
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 94608

Affiliation Phone: (510) 428-7400

Affiliation Type Desc: Operator

Entity Name: Whole Foods Market California, Inc.

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 207-1120

Affiliation Type Desc: **Document Preparer Entity Name:** Hartman King PC Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner

Entity Name: Alameda Stockton LLC; Eugene Hudson

Entity Title: Not reported

Affiliation Address: 1885 The Alameda, Suite 100-E

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95126
Affiliation Phone: (408) 247-4570

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WHOLE FOODS MARKET - THE ALAMEDA (Continued)

S117892489

Affiliation State: CA

Not reported Affiliation Country: 95112-2716 Affiliation Zip: Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer Entity Name: **Debora Sanches** Entity Title: **Environmental Specialist**

Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation

Entity Name: Whole Foods Market California, Inc.

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: Not reported

T118 **TIERNAN BODY SHOP INC** RCRA-SQG 1000365233 **FINDS 60 N AUTUMN** CAD029310208 SE 1/8-1/4 **SAN JOSE, CA 95110 ECHO**

0.218 mi.

1149 ft. Site 1 of 14 in cluster T

Relative: RCRA-SQG:

Higher Date form received by agency: 09/01/1996

TIERNAN BODY SHOP INC Facility name: Actual:

60 N AUTUMN Facility address: 87 ft.

SAN JOSE, CA 95110 EPA ID: CAD029310208 N AUTUMN Mailing address:

SAN JOSE, CA 95110

Contact: Not reported Contact address: Not reported Not reported

US Contact country:

Contact telephone: Not reported Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

TIERNAN BODY SHOP INC Owner/operator name:

Owner/operator address: **NOT REQUIRED**

Distance Elevation Site

Site Database(s) EPA ID Number

TIERNAN BODY SHOP INC (Continued)

1000365233

EDR ID Number

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002641972

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

TIERNAN BODY SHOP INC (Continued)

1000365233

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

1000365233 Envid: Registry ID: 110002641972

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002641972

S119 **XEROX ENGINEERING SYSTEMS** RCRA-SQG 1000985073 NW CAR000001834 **567 CINNABAR** ICIS

1/8-1/4 SAN JOSE, CA 95110 **FINDS**

ECHO 0.218 mi.

1151 ft. Site 2 of 2 in cluster S Relative: RCRA-SQG:

Lower Date form received by agency: 09/01/1996

XEROX ENGINEERING SYSTEMS Facility name: Actual:

Facility address: 567 CINNABAR 83 ft.

SAN JOSE, CA 95110

CAR000001834 EPA ID: Mailing address: **RUE FERRARI** SAN JOSE, CA 95110

Contact: Not reported Contact address: Not reported Not reported

Contact country: US

Not reported Contact telephone: Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

SAN JOSE DITRIBUTION SVC Owner/operator name:

Owner/operator address: 567 CINNABAR ST SAN JOSE, CA 95151

Owner/operator country: Not reported Owner/operator telephone: 408-292-9100 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner

Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No

Direction Distance

Elevation Site Database(s) EPA ID Number

XEROX ENGINEERING SYSTEMS (Continued)

1000985073

EDR ID Number

Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: Nο Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

ICIS:

Enforcement Action ID: 09-2013-4104 FRS ID: 110055109127

Action Name: FIFRA FY13 Pittsburg Wholesale Grocers, Inc. (dba Pitco Foods)
Facility Name: PITTSBURG WHOLESALE GROCERS, INC. (DBA PITCO FOODS)

Facility Address: 567 CINNABAR ST. SAN JOSE, CA 95110

Enforcement Action Type: FIFRA 14A Action For Penalty

Facility County: SANTA CLARA

Program System Acronym: ICIS

Enforcement Action Forum Desc: Administrative - Formal

EA Type Code: 14A

Facility SIC Code: Not reported Federal Facility ID: Not reported Latitude in Decimal Degrees: 37.336996 Longitude in Decimal Degrees: -121.905649 Permit Type Desc: Not reported Program System Acronym: 3400012900 Facility NAICS Code: Not reported Tribal Land Code: Not reported

Facility Name: PITTSBURG WHOLESALE GROCERS, INC. (DBA PITCO FOODS)

Address: 567 CINNABAR ST.

Tribal Indicator: N

Fed Facility: Not reported NAIC Code: Not reported SIC Code: Not reported

FINDS:

Registry ID: 110055109127

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

XEROX ENGINEERING SYSTEMS (Continued)

1000985073

Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

110002905385 Registry ID:

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000985073 Registry ID: 110055109127

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055109127

Envid: 1000985073 Registry ID: 110002905385

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002905385

T120 SCV PARAMEDICS/SAN JOSE AMBULA

SE **58 N AUTUMN ST** 1/8-1/4 SAN JOSE, CA

0.218 mi.

1153 ft. Site 2 of 14 in cluster T

Relative: LUST SANTA CLARA:

Higher Region: SANTA CLARA SCVWD ID: 07S1E07Q02F Actual: Date Closed: 04/09/1997 87 ft. 07S1E07Q02F EDR Link ID:

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code: 2

SCVWD ID: 07S1E07Q02 Oversite Agency: SFRWQCB

Date Listed: 1989-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00 LUST

HIST LUST

S103881000

N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

U121 **KOSICH CONSTRUCTION COMPA** HIST CORTESE S105026288 SSE N/A

561 SANTA CLARA

1/8-1/4 SAN JOSE, CA

0.220 mi.

Site 1 of 2 in cluster U 1162 ft. HIST CORTESE: Relative:

Higher **CORTESE** Region:

Facility County Code: 43 Actual: LTNKA Reg By: 90 ft. 43-0163 Reg Id:

DISTRICT PROPERTY S103881006 122 LUST **ESE 361 W SANTA CLARA ST HIST LUST** N/A

1/8-1/4 SAN JOSE, CA

0.223 mi. 1176 ft.

Relative: LUST SANTA CLARA:

Lower Region: SANTA CLARA SCVWD ID: 07S1E07R02F Actual: Date Closed: Not reported 77 ft.

07S1E07R02F EDR Link ID:

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07R02 Oversite Agency: SFRWQCB

Date Listed: 1991-02-05 00:00:00 Closed Date: Not reported

T123 **KOSICH CONSTRUCTION COMPANY** LUST S107996179 N/A

SSE 555-561 W SANTA CLARA ST

1/8-1/4 SAN JOSE, CA

0.223 mi.

Site 3 of 14 in cluster T 1179 ft. LUST SANTA CLARA: Relative:

Higher SANTA CLARA Region: SCVWD ID: 07S1E07Q03F Actual: 90 ft.

Date Closed: 04/09/1997 EDR Link ID: 07S1E07Q03F

R124 **PACIFIC BELL (FUEL UNIT)** UST U003782580 N/A

SSE 1 S MONTGOMERY ST 1/8-1/4 SAN JOSE, CA 95110

0.229 mi.

1211 ft. Site 5 of 6 in cluster R

UST: Relative:

Higher Facility ID: 402619

Permitting Agency: SAN JOSE, CITY OF Actual:

Latitude: 37.33186 90 ft. Longitude: -121.90122

Direction Distance

Elevation Site Database(s) EPA ID Number

V125 PHILIP SAN PHILIPPO PROPERTIES LUST \$102859853

SSW 735 THE ALAMEDA HIST LUST N/A

1/8-1/4 SAN JOSE, CA 95126 HIST CORTESE 0.235 mi. CERS

1240 ft. Site 1 of 2 in cluster V

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

93 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608502012

Global Id: T0608502012 Latitude: 37.3318837 Longitude: -121.9046631

Status: Completed - Case Closed

Status Date: 09/17/1997
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Diesel Site History: Not reported

LUST:

Global Id: T0608502012

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608502012

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608502012

 Action Type:
 Other

 Date:
 07/15/1997

 Action:
 Leak Reported

 Global Id:
 T0608502012

 Action Type:
 ENFORCEMENT

 Date:
 09/17/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608502012

 Action Type:
 RESPONSE

 Date:
 09/17/1997

Action: Other Report / Document

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

PHILIP SAN PHILIPPO PROPERTIES (Continued)

S102859853

EDR ID Number

LUST:

Global Id: T0608502012

Status: Completed - Case Closed

Status Date: 09/17/1997

Global Id: T0608502012

Status: Open - Case Begin Date

Status Date: 01/30/1997

Global Id: T0608502012

Status: Open - Site Assessment

Status Date: 01/30/1997

Global Id: T0608502012

Status: Open - Site Assessment

Status Date: 02/06/1997

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed 07S1E07P02f Case Number: How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07P02F

 Date Closed:
 09/17/1997

 EDR Link ID:
 07S1E07P02F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07P02 Oversite Agency: SCVWD

Date Listed: 1997-07-22 00:00:00 Closed Date: 1997-09-17 00:00:00

HIST CORTESE:

Region: CORTESE Facility County Code: 43 Reg By: LTNKA Reg Id: 43-2190

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PHILIP SAN PHILIPPO PROPERTIES (Continued)

S102859853

CERS TANKS:

Site ID: 235500 T0608502012 CERS ID:

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

OAKLAND Affiliation City: Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Local Agency Caseworker Affiliation Type Desc:

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

AV MACHINE SHOP CERS HAZ WASTE \$111216950 P126 **CUPA Listings** wsw 710 W JULIAN ST **SAN JOSE, CA 95126 HAZNET**

1/8-1/4 0.235 mi.

Relative:

1241 ft. Site 10 of 15 in cluster P

CERS HAZ WASTE:

Higher 10120 Site ID: CERS ID: 10355362 Actual:

94 ft. CERS Description: Hazardous Waste Generator

Coordinates:

Site ID: 10120

Facility Name: AV MACHINE SHOP

Env Int Type Code: **HWG** Program ID: 10355362 Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.333370 Longitude: -121.906610

Affiliation:

Affiliation Type Desc: **Property Owner** Mario Villafuerte Entity Name: Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported **United States** Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: (408) 288-7040

N/A

SAN JOSE HAZMAT

CERS

Distance

Elevation Site Database(s) EPA ID Number

AV MACHINE SHOP (Continued)

S111216950

EDR ID Number

Affiliation Type Desc: Operator

Entity Name: VILLAFUERTE, MARIO ALBERTO

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 288-7040

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc:
Entity Name:
Entity Title:
Not reported
Affiliation Address:
Affiliation City:
San Jose

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95126

Affiliation Phone: (408) 828-2480

Identification Signer Affiliation Type Desc: Entity Name: Mario Villafuerte **Entity Title:** CO OWNER Affiliation Address: Not reported Not reported Affiliation City: Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: VILLAFUERTE, MARIO ALBERTO

Entity Title: Not reported
Affiliation Address: 710 W JULIAN ST
Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 288-7040

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Not reported

Not reported

Not reported

Not reported

Not reported

Direction Distance Elevation

Elevation Site Database(s) EPA ID Number

AV MACHINE SHOP (Continued)

S111216950

EDR ID Number

Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 710 W JULIAN ST

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: AV MACHINE SHOP

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.33355

 Longitude:
 -121.90599

 Record ID:
 PR0377491

 Facility ID:
 FA0257911

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.33355

 Longitude:
 -121.90599

 Record ID:
 PR0397600

 Facility ID:
 FA0257911

HAZNET:

envid: \$111216950

Year: 2017

GEPAID: CAL000384060

Contact: ALBERTO VILLAFUERTE

Telephone: 4082887040
Mailing Name: Not reported
Mailing Address: 710 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951260000

Gen County: Santa Clara
TSD EPA ID: AZR000515924

TSD County: 99

Waste Category: Off-specification, aged or surplus organics

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Direction Distance

Elevation Site Database(s) EPA ID Number

AV MACHINE SHOP (Continued)

S111216950

EDR ID Number

Tons: 0.25

Cat Decode: Off-specification, aged or surplus organics

Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Facility County: Santa Clara

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 402480 Class: Auto Repair

CERS TANKS:

Site ID: 10120 CERS ID: 10355362

CERS Description: Chemical Storage Facilities

Coordinates:

Site ID: 10120

Facility Name: AV MACHINE SHOP

Env Int Type Code: HWG
Program ID: 10355362
Coord Name: Not reported

Ref Point Type Desc: Center of a facility or station.

Latitude: 37.333370 Longitude: -121.906610

Affiliation:

Property Owner Affiliation Type Desc: Entity Name: Mario Villafuerte Entity Title: Not reported Not reported Affiliation Address: Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: **United States** Affiliation Zip: Not reported Affiliation Phone: (408) 288-7040

Affiliation Type Desc: Operator

Entity Name: VILLAFUERTE, MARIO ALBERTO

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 288-7040

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not report.

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Direction Distance Elevation

ation Site Database(s) EPA ID Number

AV MACHINE SHOP (Continued)

S111216950

EDR ID Number

Affiliation Type Desc:
Entity Name:
Entity Title:
Affiliation Address:
Affiliation City:
Affiliation State:

Environmental Contact
Nelda Villafuerte
Not reported
710 W. Julian St.
San Jose
CA

Affiliation Country: Not reported Affiliation Zip: 95126

Affiliation Phone: (408) 828-2480

Affiliation Type Desc: Identification Signer Entity Name: Mario Villafuerte Entity Title: CO OWNER Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: VILLAFUERTE, MARIO ALBERTO

Entity Title: Not reported
Affiliation Address: 710 W JULIAN ST
Affiliation City: SAN JOSE

Affiliation City.

Affiliation State:

Affiliation Country:

Affiliation Zip:

United States

95126

Affiliation Phone: (408) 288-7040

Document Preparer Affiliation Type Desc: Entity Name: Mario Villafuerte Entity Title: Not reported Affiliation Address: Not reported Not reported Affiliation City: Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 710 W JULIAN ST
Affiliation City: SAN JOSE

Affiliation City: SAN JO: Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: AV MACHINE SHOP

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

AV MACHINE SHOP (Continued) S111216950

Affiliation Zip: Not reported Affiliation Phone: Not reported

P127 A.A. ENGINE CO. HIST UST U001602883
WSW 710-W- JULIAN ST N/A

1/8-1/4 SAN JOSE, CA 95126

0.235 mi.

1241 ft. Site 11 of 15 in cluster P

Relative: HIST UST: Higher File Num

 Higher
 File Number:
 Not reported

 Actual:
 URL:
 Not reported

 94 ft.
 Region:
 STATE

 Facility ID:
 00000054620

Facility Type: Other

Other Type: AUTO MACHINE SHOP
Contact Name: GEORGIA RUDASILL

Telephone: 4082933046

Owner Name: CARL & CHRISTINE HAAS
Owner Address: 773 CLINTON PLACE
Owner City,St,Zip: SAN JOSE, CA 95126

Total Tanks: 0001

Tank Num: 001 Container Num: 1

Year Installed:
Tank Capacity:
O0000000
Tank Used for:
WASTE
Type of Fuel:
Container Construction Thickness:
Leak Detection:
Not reported
None

P128 CANCILLA PROPERTY LUST S113038597 WSW 708 W JULIAN ST. LUST S113038597

1/8-1/4 0.235 mi.

1241 ft. Site 12 of 15 in cluster P

SAN JOSE, CA 95126

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

94 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T10000007704

Global Id: T10000007704
Latitude: 37.33355
Longitude: -121.90659

Status: Completed - Case Closed

Status Date: 02/16/2018
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E07P04f

Potential Media Affect: Aquifer used for drinking water supply, Soil, Soil Vapor

Potential Contaminants of Concern: Total Petroleum Hydrocarbons (TPH), Waste Oil / Motor / Hydraulic / Lubricating

Site History: Small UST was located on property historically. Phase II

CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

CANCILLA PROPERTY (Continued)

S113038597

EDR ID Number

investigation reported groundwater contamination beneath the site. Oil/Water separator was also used on the site historically.

LUST:

 Global Id:
 T1000007704

 Action Type:
 ENFORCEMENT

 Date:
 11/15/2016

 Action:
 Staff Letter

 Global Id:
 T10000007704

 Action Type:
 ENFORCEMENT

 Date:
 02/08/2016

 Action:
 Staff Letter

 Global Id:
 T10000007704

 Action Type:
 ENFORCEMENT

 Date:
 02/23/2017

 Action:
 Staff Letter

 Global Id:
 T10000007704

 Action Type:
 ENFORCEMENT

 Date:
 10/13/2015

Action: Notice of Responsibility

 Global Id:
 T10000007704

 Action Type:
 ENFORCEMENT

 Date:
 05/08/2017

 Action:
 Staff Letter

 Global Id:
 T10000007704

 Action Type:
 Other

 Date:
 06/30/1967

 Action:
 Leak Stopped

Global Id: T10000007704
Action Type: RESPONSE
Date: 03/30/2017

Action: Other Report / Document

 Global Id:
 T10000007704

 Action Type:
 ENFORCEMENT

 Date:
 10/13/2015

Action: Notice of Responsibility

Global Id: T10000007704
Action Type: ENFORCEMENT
Date: 09/11/2015

Action: Unauthorized Release Form

 Global Id:
 T10000007704

 Action Type:
 Other

 Date:
 09/11/2015

 Action:
 Leak Reported

Global Id: T1000007704
Action Type: RESPONSE
Date: 01/31/2017

Action: Preliminary Site Assessment Workplan - Regulator Responded

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CANCILLA PROPERTY (Continued)

S113038597

Global Id: T10000007704 **RESPONSE** Action Type: 03/30/2017 Date:

Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T10000007704 **ENFORCEMENT** Action Type: 01/27/2016 Date:

Action: Notice of Responsibility

T10000007704 Global Id: **RESPONSE** Action Type: Date: 09/08/2017

Action: Soil and Water Investigation Report

Global Id: T10000007704 **ENFORCEMENT** Action Type: Date: 12/11/2017

Action: Notification - Public Notice of Case Closure

Global Id: T10000007704 **ENFORCEMENT** Action Type: Date: 08/30/2017

Action: **Email Correspondence**

Global Id: T10000007704 Action Type: **ENFORCEMENT** Date: 02/16/2018

Action: Closure/No Further Action Letter

Global Id: T10000007704 Action Type: Other Date: 06/30/1967 Action: Leak Began

Global Id: T10000007704 Action Type: Other Date: 07/30/2015 Action: Leak Discovery

T10000007704 Global Id: Action Type: **RESPONSE** Date: 01/28/2016

Action: **Email Correspondence**

Global Id: T10000007704 Action Type: **RESPONSE** Date: 10/22/2015 Action: Correspondence

T10000007704 Global Id: Action Type: **RESPONSE** 10/22/2015 Date: Action: Correspondence

Global Id: T10000007704 Action Type: **RESPONSE**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CANCILLA PROPERTY (Continued)

S113038597

Date: 07/30/2015

Action: Preliminary Site Assessment Report

LUST:

Global Id: T10000007704

Completed - Case Closed Status:

02/16/2018 Status Date:

Global Id: T10000007704

Status: Open - Case Begin Date

Status Date: 07/30/2015

Global Id: T10000007704

Status: Open - Site Assessment

09/24/2015 Status Date:

HAZNET:

S113038597 envid: Year: 1997

GEPAID: CAL000042415 Contact: ROBERT CANCILLA

Telephone: 4082877161 Mailing Name: Not reported 708 W JULIAN ST Mailing Address:

Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Not reported TSD EPA ID: CAD042345884 TSD County: Not reported

Unspecified organic liquid mixture Waste Category:

Disposal Method: **Transfer Station**

Tons: .4587 Cat Decode: Not reported Not reported Method Decode: Santa Clara Facility County:

envid: S113038597 Year: 1997

GEPAID: CAL000042415 Contact: **ROBERT CANCILLA**

Telephone: 4082877161 Mailing Name: Not reported Mailing Address: 708 W JULIAN ST

Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Not reported TSD EPA ID: CAD042345884 TSD County: Not reported

Waste Category: Unspecified solvent mixture

Santa Clara

Disposal Method: **Transfer Station**

Tons: .4586 Cat Decode: Not reported Not reported Method Decode:

envid: S113038597 Year: 1997

Facility County:

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

CANCILLA PROPERTY (Continued)

S113038597

GEPAID: CAL000042415 Contact: ROBERT CANCILLA

Telephone: 4082877161
Mailing Name: Not reported
Mailing Address: 708 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951260000

Gen County: Not reported
TSD EPA ID: CAD042345884
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Not reported

Tons: .0000
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$113038597

Year: 1997

GEPAID: CAL000042415 Contact: ROBERT CANCILLA

Telephone: 4082877161
Mailing Name: Not reported
Mailing Address: 708 W JULIAN ST

Mailing City,St,Zip: SAN JOSE, CA 951260000

Gen County: Not reported
TSD EPA ID: CAD042345884
TSD County: Not reported

Waste Category: Organic liquids with metals (Alkaline solution (pH \geq 12.5) with

metals)

Disposal Method: Not reported 70ns: .0000
Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

CERS TANKS:

 Site ID:
 358262

 CERS ID:
 T10000007704

CERS Description: Leaking Underground Storage Tank Cleanup Site

P129 AA ENGINE CO HIST UST S118407204
WSW 710 W-JULIAN ST N/A

1/8-1/4 SAN JOSE, CA 95126

0.235 mi.

1241 ft. Site 13 of 15 in cluster P

Relative: HIST UST: Higher File Number: 0002CF89

Actual: URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002CF89.pdf

94 ft. Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported

Contact Name: Not reported Telephone: Not reported Owner Name: Not reported Owner Address: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AA ENGINE CO (Continued) S118407204

Owner City, St, Zip: Not reported Total Tanks: Not reported

Tank Num: Not reported Container Num: Not reported Not reported Year Installed: Not reported Tank Capacity: Tank Used for: Not reported Type of Fuel: Not reported Container Construction Thickness: Not reported Leak Detection: Not reported

Click here for Geo Tracker PDF:

T130 **SAN JOSE ARENA** CPS-SLIC S106162013 N/A

SSE **UNKNOWN UKNOWN** 1/8-1/4 SAN JOSE, CA 95113

0.236 mi.

1247 ft. Site 4 of 14 in cluster T

Relative: SLIC REG 2:

Higher Region: Facility ID: 43S0538 Actual: Facility Status: Case Closed 88 ft.

Date Closed: 3/21/1997 Local Case #: Not reported How Discovered: Tank Closure Leak Cause: UNK UNK Leak Source: Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: Not reported Date Preliminary Site Assessment Began: Not reported Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

R131 CITY OF SJ-CAHILL PUMP STATION **CUPA Listings** S123102584 **CERS** N/A

South **4 CAHILL ST** 1/8-1/4 SAN JOSE, CA 95110

0.237 mi.

1249 ft. Site 6 of 6 in cluster R

Relative: CUPA SANTA CLARA: Higher SANTA CLARA Region: PE#: Not reported

Actual: Program Description: HMBP FACILITY, 1-3 CHEMICALS 91 ft.

> Latitude: 37.3315165 Longitude: -121.9021511 Record ID: PR0432706 Facility ID: FA0288579

CERS TANKS:

443962 Site ID: CERS ID: 10774132

CERS Description: Chemical Storage Facilities

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CITY OF SJ-CAHILL PUMP STATION (Continued)

S123102584

Coordinates:

Site ID: 443962

CITY OF SJ-CAHILL PUMP STATION Facility Name:

Env Int Type Code: **HMBP** Program ID: 10774132 Coord Name: Not reported

Ref Point Type Desc: Entrance point of a facility or station

Latitude: 37.331517 Longitude: -121.902150

Affiliation:

Affiliation Type Desc: Parent Corporation

Entity Name: CITY OF SJ-CAHILL PUMP STATION

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **CUPA District**

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

1555 Berger Drive, Suite 300 Affiliation Address:

Affiliation City: San Jose Affiliation State: CA Not reported Affiliation Country: Affiliation Zip: 95112-2716 Affiliation Phone: (408) 918-3400

T132 **DOWNTOWN TRUCK & TRAILER** LUST S101309289

SE **405 SANTA CLARA ST W HIST LUST** N/A 1/8-1/4 SAN JOSE, CA 95113 **HIST CORTESE** 0.237 mi. **CERS**

Site 5 of 14 in cluster T 1252 ft.

LUST: Relative:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

LUST Cleanup Site Case Type: Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500530 85 ft.

> Global Id: T0608500530 37.332835 Latitude: Longitude: -121.896941

Completed - Case Closed Status:

04/09/1997 Status Date: Case Worker: UUU RB Case Number: 43-0484

SANTA CLARA COUNTY LOP Local Agency:

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water) Potential Contaminants of Concern: Stoddard solvent / Mineral Spriits / Distillates

Site History: Not reported

LUST:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DOWNTOWN TRUCK & TRAILER (Continued)

S101309289

Global Id: T0608500530

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608500530

Local Agency Caseworker Contact Type: Contact Name: UST CASE WORKER Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

SAN JOSE City: Email: Not reported Phone Number: 4089183400

LUST:

T0608500530 Global Id: Action Type: Other Date: 03/28/1989 Action: Leak Reported

T0608500530 Global Id: Action Type: **RESPONSE** Date: 01/01/1989

Action: Other Report / Document

T0608500530 Global Id: Action Type: **RESPONSE** Date: 01/01/1997

Other Report / Document Action:

Global Id: T0608500530 Action Type: RESPONSE Date: 01/01/1996

Action: Other Report / Document

T0608500530 Global Id: Action Type: Other Date: 03/28/1989 Action: Leak Discovery

Global Id: T0608500530 **ENFORCEMENT** Action Type: Date: 04/09/1997

Closure/No Further Action Letter Action:

T0608500530 Global Id: Action Type: Other Date: 03/28/1989 Action: Leak Stopped

LUST:

Global Id: T0608500530

Direction Distance

Elevation Site Database(s) EPA ID Number

DOWNTOWN TRUCK & TRAILER (Continued)

S101309289

EDR ID Number

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608500530

Status: Open - Case Begin Date

Status Date: 03/28/1989

LUST REG 2:

Region:

Facility Id: 43-0484
Facility Status: Case Closed
Case Number: 07S1E07Q04
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07Q04F

 Date Closed:
 04/09/1997

 EDR Link ID:
 07S1E07Q04F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07Q04 Oversite Agency: SFRWQCB

Date Listed: 1991-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0484

CERS TANKS:

 Site ID:
 254778

 CERS ID:
 T0608500530

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DOWNTOWN TRUCK & TRAILER (Continued)

S101309289

Affiliation City: SAN JOSE Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) Entity Name:

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

OAKLAND Affiliation City: Affiliation State: CA Affiliation Country: Not reported

Affiliation Zip: Not reported Affiliation Phone: Not reported

P133 **SAN JOSE BLUE CUPA Listings** S121470202 835 W JULIAN ST **WSW** N/A

1/8-1/4 SAN JOSE, CA 95126

0.238 mi.

1255 ft. Site 14 of 15 in cluster P CUPA SANTA CLARA: Relative:

Higher Region: SANTA CLARA

PE#: 2205 Actual:

Program Description: GENERATES 100 KG YR TO <5 TONS/YR 92 ft.

> Latitude: 37.333767 Longitude: -121.907084 Record ID: PR0315323 Facility ID: FA0211001

SAN JOSE BLUEPRINT SERVICE RCRA-SQG 1000686067 P134 CAD983631862 **WSW** 835 W JULIAN ST **FINDS**

1/8-1/4 SAN JOSE, CA 95126 0.238 mi.

1255 ft. Site 15 of 15 in cluster P

Relative: RCRA-SQG: Higher Date form received by agency: 06/15/1992

Facility name: SAN JOSE BLUEPRINT SERVICE Actual:

Facility address: 835 W JULIAN ST 92 ft. SAN JOSE, CA 95126

EPA ID: CAD983631862 Contact: RICHARD LAVALLEY Contact address: 835 W JULIAN ST

SAN JOSE, CA 95126

Contact country: US

Contact telephone: 408-295-5770 Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

> waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

ECHO HAZNET

Direction Distance Elevation

Site Database(s) EPA ID Number

SAN JOSE BLUEPRINT SERVICE (Continued)

1000686067

EDR ID Number

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: RANDALL DEAN COWHERD

Owner/operator address: 835 W JULIAN ST

SAN JOSE, CA 95126

Owner/operator country: Not reported 408-295-5770 Owner/operator telephone: Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Private Legal status: Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: Nο Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002873944

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000686067 Registry ID: 110002873944

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002873944

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE BLUEPRINT SERVICE (Continued)

1000686067

HAZNET:

1000686067 envid: Year: 1995

GEPAID: CAD983631862

Contact: SAN JOSE BLUEPRINT COMPANY

Telephone: 4082955770 Mailing Name: Not reported Mailing Address: 835 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951262716

Gen County: Not reported TSD EPA ID: CAL000027741 TSD County: Not reported

Asbestos containing waste Waste Category:

Disposal Method: Disposal, Land Fill

.0000 Tons: Cat Decode: Not reported Not reported Method Decode: Facility County: Santa Clara

1000686067 envid: Year: 1995

CAD983631862 GEPAID:

Contact: SAN JOSE BLUEPRINT COMPANY

Telephone: 4082955770 Mailing Name: Not reported Mailing Address: 835 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951262716

Gen County: Not reported TSD EPA ID: CAD983667783 TSD County: Not reported

Waste Category: Photochemicals/photoprocessing waste

Disposal Method: Not reported

Tons: .2502

Cat Decode: Not reported Method Decode: Not reported Santa Clara Facility County:

envid: 1000686067 1995 Year:

GEPAID: CAD983631862

SAN JOSE BLUEPRINT COMPANY Contact:

Telephone: 4082955770 Mailing Name: Not reported 835 W JULIAN ST Mailing Address:

Mailing City, St, Zip: SAN JOSE, CA 951262716

Gen County: Not reported TSD EPA ID: CAD981382732 Not reported TSD County: Not reported Waste Category: Disposal Method: Not reported Tons: .8428 Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000686067 Year: 1995

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE BLUEPRINT SERVICE (Continued)

GEPAID:

CAD983631862

SAN JOSE BLUEPRINT COMPANY Contact:

Telephone: 4082955770 Mailing Name: Not reported Mailing Address: 835 W JULIAN ST

Mailing City, St, Zip: SAN JOSE, CA 951262716

Gen County: Not reported TSD EPA ID: CAD981382732 TSD County: Not reported

Waste Category: Asbestos containing waste

Disposal Method: Disposal, Land Fill

2.5284 Tons: Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

135 **SMITH & MCKAY PRINTING CO, INC CUPA Listings** S121472907

East 96 N ALMADEN BL 1/8-1/4 SAN JOSE, CA 95110

0.239 mi. 1264 ft.

CUPA SANTA CLARA: Relative:

Lower SANTA CLARA Region:

PE#: 2202 Actual:

Program Description: GENERATES < 100 KG/YR 83 ft.

Latitude: 37.335612 Longitude: -121.894372 Record ID: PR0374733 Facility ID: FA0256617

T136 **BANK OF AMERICA/WELLS FARGO** LUST S103473096 **521 W SANTA CLARA ST HIST LUST** N/A

SE

1/8-1/4 SAN JOSE, CA

0.241 mi.

1274 ft. Site 6 of 14 in cluster T LUST SANTA CLARA: Relative:

Higher SANTA CLARA Region: SCVWD ID: 07S1E07Q06F Actual: Date Closed: 04/09/1997 85 ft. EDR Link ID: 07S1E07Q06F

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code: 2

SCVWD ID: 07S1E07Q06 Oversite Agency: SFRWQCB

Date Listed: 1993-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00 1000686067

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

T137 DOWNTOWN DATSUN LUST 1000322716
SE 443 W SANTA CLARA ST LUST N/A

1/8-1/4 SAN JOSE, CA 95113 0.241 mi.

1274 ft. Site 7 of 14 in cluster T

Relative: LUST SANTA CLARA:

 Higher
 Region:
 SANTA CLARA

 Actual:
 SCVWD ID:
 07S1E07Q07F

 85 ft.
 Date Closed:
 04/09/1997

 EDR Link ID:
 07S1E07Q07F

HIST UST:

File Number: 0002D2BA

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002D2BA.pdf

Region: STATE
Facility ID: 00000038844
Facility Type: Other
Other Type: CAR DEALER
Contact Name: MICHAEL GIAN

Contact Name: MICHAEL GIANAKIS
Telephone: 4082877411

Owner Name: DOWNTOWN DATSUN
Owner Address: 443 S. SANTA CLARA ST.
Owner City,St,Zip: SAN JOSE, CA 95113

Total Tanks: 0003

Tank Num: 001 Container Num: 1

Year Installed:

Tank Capacity:

O0002000

Tank Used for:

Type of Fuel:

Container Construction Thickness:

Leak Detection:

Not reported

UNLEADED

Not reported

None

Tank Num: 002 Container Num: 2

Year Installed:

Tank Capacity:

Tank Used for:

Type of Fuel:

Container Construction Thickness:

Not reported

WASTE

WASTE OIL

Not reported

Leak Detection: None

Tank Num: 003 Container Num: 3

Year Installed:

Tank Capacity:

O0000000

Tank Used for:

Type of Fuel:

Container Construction Thickness:

Leak Detection:

Not reported

WASTE

WASTE OIL

Not reported

None

Click here for Geo Tracker PDF:

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

T138 PREMIER NISSAN RCRA NonGen / NLR 1000299626
SE 443 W SANTA CLARA ST FINDS CAD98201869

SE 443 W SANTA CLARA ST FINDS CAD982018699
1/8-1/4 SAN JOSE, CA 95113 ECHO

0.241 mi.

1274 ft. Site 8 of 14 in cluster T

Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 07/30/1987

Actual:Facility name:PREMIER NISSAN85 ft.Facility address:443 W SANTA CLARA ST

SAN JOSE, CA 95113 EPA ID: CAD982018699

Mailing address: W SANTA CLARA ST

SAN JOSE, CA 95113

Contact: ENVIRONMENTAL MANAGER
Contact address: 443 W SANTA CLARA ST

SAN JOSE, CA 95113

Contact country: US

Contact telephone: 408-287-7411 Contact email: Not reported

EPA Region: 09

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/Op end date:

Owner/operator name: CERRITO MANAGEMENT CO

Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Not reported

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Private Legal status: Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No

EDR ID Number

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PREMIER NISSAN (Continued)

1000299626

On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002777629

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000299626 Registry ID: 110002777629

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002777629

T139 UNKNOWN HIST LUST S103881002 SE 443 W SANTA CLARA ST N/A

1/8-1/4 SAN JOSE, CA

0.241 mi.

1274 ft. Site 9 of 14 in cluster T

Relative: HIST LUST SANTA CLARA: Higher Region: SANTA CLARA

Region Code: Actual:

SCVWD ID: 07S1E07Q07 85 ft.

Oversite Agency: SFRWQCB Date Listed:

1994-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00

Direction Distance

Elevation Site Database(s) EPA ID Number

T140 BANK OF AMERICA WELLS FARGO LUST S103723225

SE 521 SANTA CLARA ST W HIST CORTESE N/A

1/8-1/4 SAN JOSE, CA 95113 CERS

0.241 mi.

1274 ft. Site 10 of 14 in cluster T

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

85 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500211

Global Id: T0608500211
Latitude: 37.332186
Longitude: -121.899746

Status: Completed - Case Closed

 Status Date:
 04/09/1997

 Case Worker:
 UUU

 RB Case Number:
 43-0145

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500211

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500211

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500211

 Action Type:
 ENFORCEMENT

 Date:
 05/26/1995

Action: Clean Up Fund - Letter to RP - #43-0145

Global Id: T0608500211
Action Type: Other
Date: 03/28/1989
Action: Leak Reported

Global Id: T0608500211
Action Type: ENFORCEMENT
Date: 04/09/1997

Action: Closure/No Further Action Letter

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BANK OF AMERICA WELLS FARGO (Continued)

S103723225

Global Id: T0608500211 RESPONSE Action Type: 04/09/1997 Date:

Action: Other Report / Document

Global Id: T0608500211 Action Type: Other 03/28/1989 Date: Action: Leak Discovery

T0608500211 Global Id: Action Type: Other 03/28/1989 Date: Action: Leak Stopped

LUST:

T0608500211 Global Id:

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608500211

Status: Open - Case Begin Date

Status Date: 03/28/1989

LUST REG 2:

Region: Facility Id:

43-0145 Case Closed Facility Status: 07S1E07Q06 Case Number: How Discovered: Tank Closure Leak Cause: Structure Failure

Leak Source: Tank Date Leak Confirmed: Not reported LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** 43-0145 Reg Id:

CERS TANKS:

Site ID: 230968 CERS ID: T0608500211

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) **Entity Name:**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BANK OF AMERICA WELLS FARGO (Continued)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Not reported Affiliation Zip: 4089183400 Affiliation Phone:

BRADFORD MANUFACTURING U141 HIST CORTESE \$101304001 N/A

SSE **8 MONTGOMERY** 1/8-1/4 SAN JOSE, CA 95110

0.244 mi.

1286 ft. Site 2 of 2 in cluster U

Relative: HIST CORTESE:

Higher Region: **CORTESE** Facility County Code: 43 Actual: **LTNKA** Reg By: 90 ft.

Reg Id: 43-0198

W142 **NATIONAL AUTO BODY REPAIR CUPA Listings** S121469851 N/A

355 STOCKTON AV West 1/8-1/4 SAN JOSE, CA 95126

0.244 mi.

1289 ft. Site 1 of 9 in cluster W CUPA SANTA CLARA: Relative:

Higher SANTA CLARA Region:

PE#: 2202 Actual:

Program Description: GENERATES < 100 KG/YR 90 ft.

Latitude: 37.334591 Longitude: -121.907028 Record ID: PR0316354 Facility ID: FA0209027

S103723225

Direction Distance

Elevation Site Database(s) EPA ID Number

W143 AIR SYSTEMS INC LUST U001602886

West 381 STOCKTON AVE HIST UST N/A

1/8-1/4 SAN JOSE, CA 95126 HIST CORTESE 0.244 mi. CERS

1289 ft. Site 2 of 9 in cluster W

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

90 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500108

Global Id: T0608500108
Latitude: 37.33495
Longitude: -121.906334

Status: Completed - Case Closed

Status Date: 10/22/1997
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500108

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500108

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500108

 Action Type:
 Other

 Date:
 02/19/1991

 Action:
 Leak Reported

 Global Id:
 T0608500108

 Action Type:
 REMEDIATION

 Date:
 09/13/1991

 Action:
 Excavation

 Global Id:
 T0608500108

 Action Type:
 ENFORCEMENT

 Date:
 02/25/1992

Action: Notice of Responsibility - #39948

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

AIR SYSTEMS INC (Continued)

U001602886

EDR ID Number

 Global Id:
 T0608500108

 Action Type:
 ENFORCEMENT

 Date:
 01/02/1996

 Action:
 Staff Letter - #26999

 Global Id:
 T0608500108

 Action Type:
 ENFORCEMENT

 Date:
 11/06/1996

 Action:
 Staff Letter - #27004

 Global Id:
 T0608500108

 Action Type:
 ENFORCEMENT

 Date:
 06/09/1997

 Action:
 Staff Letter - #27009

 Global Id:
 T0608500108

 Action Type:
 ENFORCEMENT

 Date:
 08/16/1996

 Action:
 Staff Letter - #27002

Global Id: T0608500108
Action Type: RESPONSE

Action: Other Report / Document

Global Id: T0608500108
Action Type: ENFORCEMENT
Date: 10/22/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608500108

 Action Type:
 RESPONSE

 Date:
 04/01/1996

Action: Soil and Water Investigation Report

 Global Id:
 T0608500108

 Action Type:
 RESPONSE

 Date:
 01/31/1997

Action: Corrective Action Plan / Remedial Action Plan

11/06/1997

 Global Id:
 T0608500108

 Action Type:
 RESPONSE

 Date:
 07/30/1997

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500108

 Action Type:
 RESPONSE

 Date:
 10/25/1996

Action: Soil and Water Investigation Report

LUST:

Date:

Global Id: T0608500108

Status: Completed - Case Closed

Status Date: 10/22/1997

Global Id: T0608500108

Status: Open - Case Begin Date

Direction Distance

Elevation Site Database(s) **EPA ID Number**

AIR SYSTEMS INC (Continued)

U001602886

EDR ID Number

Status Date: 07/13/1989

Global Id: T0608500108 Status: Open - Remediation

09/13/1991 Status Date:

Global Id: T0608500108

Status: Open - Site Assessment

Status Date: 07/13/1989

HIST UST:

Not reported File Number: URL: Not reported Region: STATE Facility ID: 00000058288 Facility Type: Other Other Type: **PLUMBING** Contact Name: Not reported 4082801666 Telephone: Owner Name: JOHN W DAVIS 710 MARGARET WAY Owner Address: Owner City, St, Zip: SAN JOSE, CA 95112

Total Tanks: 0002

Tank Num: 001 Container Num:

Year Installed: Not reported 0008000 Tank Capacity: **PRODUCT** Tank Used for: Type of Fuel: UNLEADED Container Construction Thickness: Not reported Leak Detection: None

Tank Num: 002 Container Num: 2

Year Installed: Not reported Tank Capacity: 00001000 **PRODUCT** Tank Used for: Type of Fuel: **REGULAR** Container Construction Thickness: Not reported

Leak Detection: None

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-0038

CERS TANKS:

Site ID: 202733 CERS ID: T0608500108

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AIR SYSTEMS INC (Continued) U001602886

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State:

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

W144 DON BOCCI MOBILE AUTO SERVICE HIST UST U001602899 N/A

West **395 STOCKTON AVE** 1/8-1/4 SAN JOSE, CA 95126

0.244 mi.

1289 ft. Site 3 of 9 in cluster W

Relative: HIST UST: Higher File Number: 0002D29C

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002D29C.pdf Actual:

STATE Region: 90 ft. Facility ID: 00000014644 Facility Type: Gas Station Other Type: Not reported Not reported Contact Name:

Telephone: 4082299933 Owner Name: DON BOCCI MOBILE AUTO SERVICE

395 STOCKTON AVE. Owner Address: SAN JOSE, CA 95126 Owner City, St, Zip:

Total Tanks: 0003

Tank Num: 001 Container Num:

Year Installed: Not reported Tank Capacity: 00000500 **PRODUCT** Tank Used for: Type of Fuel: **PREMIUM** Container Construction Thickness: Not reported Leak Detection: None

Tank Num: 002 Container Num:

Year Installed: Not reported Tank Capacity: 00000500 **PRODUCT** Tank Used for: Type of Fuel: **PREMIUM** Container Construction Thickness: Not reported Leak Detection: None

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DON BOCCI MOBILE AUTO SERVICE (Continued)

U001602899

Tank Num: 003 Container Num: 3

Year Installed: Not reported Tank Capacity: 00002000 Tank Used for: **PRODUCT UNLEADED** Type of Fuel: Container Construction Thickness: Not reported Leak Detection: None

Click here for Geo Tracker PDF:

W145 **AIR SYSTEMS** LUST S105035954 West **381 STOCKTON AVE HIST LUST** N/A

1/8-1/4 SAN JOSE, CA 95126

0.244 mi.

Site 4 of 9 in cluster W 1289 ft.

Relative: LUST REG 2: Higher Region:

Facility Id: Not reported Actual: Case Closed Facility Status: 90 ft.

Case Number: 07S1E07L03f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 7/13/1989 Pollution Characterization Began: 7/13/1989 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: 9/13/1991 Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07L03 Oversite Agency: SCVWD

Date Listed: 1992-02-20 00:00:00 Closed Date: 1997-10-22 00:00:00

W146 **TIM'S AUTO TRIM** LUST S105086736 West **369 STOCKTON AVE HIST LUST** N/A

1/8-1/4 0.244 mi.

1289 ft. Site 5 of 9 in cluster W

SAN JOSE, CA 95112

Relative: LUST:

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: **LUST Cleanup Site** Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608591864 90 ft.

Global Id: T0608591864 Latitude: 37.334461 Longitude: -121.907137

Status: Completed - Case Closed

Direction Distance

Elevation Site Database(s) EPA ID Number

TIM'S AUTO TRIM (Continued)

S105086736

EDR ID Number

Status Date: 08/24/2001
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608591864

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608591864

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608591864

 Action Type:
 Other

 Date:
 04/25/2000

 Action:
 Leak Reported

 Global Id:
 T0608591864

 Action Type:
 ENFORCEMENT

 Date:
 08/24/2001

Action: Closure/No Further Action Letter

 Global Id:
 T0608591864

 Action Type:
 ENFORCEMENT

 Date:
 01/15/2001

 Action:
 Stoff Letter, #3700

Action: Staff Letter - #27033

 Global Id:
 T0608591864

 Action Type:
 ENFORCEMENT

 Date:
 03/17/2001

Action: Staff Letter - #27035

Global Id: T0608591864
Action Type: RESPONSE
Date: 11/15/2000

Action: Unauthorized Release Form

Global Id: T0608591864 Action Type: RESPONSE

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

TIM'S AUTO TRIM (Continued)

S105086736

Date: 08/15/2001 Action: Correspondence

Global Id: T0608591864 Action Type: **RESPONSE** 12/08/2000 Date:

Tank Removal Report / UST Sampling Report Action:

Global Id: T0608591864 Action Type: **RESPONSE** Date: 03/01/2001

Soil and Water Investigation Workplan Action:

Global Id: T0608591864 Action Type: **RESPONSE** Date: 06/15/2001

Action: Preliminary Site Assessment Report

Global Id: T0608591864 **RESPONSE** Action Type: Date: 07/16/2001

Action: Preliminary Site Assessment Report

Global Id: T0608591864 Action Type: **RESPONSE** 12/11/2001 Date: Action: Correspondence

T0608591864 Global Id: Action Type: **RESPONSE** 04/23/2001 Date: Action: Other Workplan

Global Id: T0608591864 **RESPONSE** Action Type: 04/24/2000 Date:

Action: Other Report / Document

T0608591864 Global Id: **RESPONSE** Action Type: Date: 10/25/2000

Tank Removal Report / UST Sampling Report Action:

LUST:

T0608591864 Global Id:

Completed - Case Closed Status:

Status Date: 08/24/2001

Global Id: T0608591864

Open - Case Begin Date Status:

Status Date: 04/25/2000

Global Id: T0608591864

Open - Site Assessment Status:

04/30/2001 Status Date:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

TIM'S AUTO TRIM (Continued)

S105086736

LUST REG 2:

Region:

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E07L06f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 4/30/2001 Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

SANTA CLARA Region: SCVWD ID: 07S1E07L06F Date Closed: 08/24/2001 EDR Link ID: 07S1E07L06F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07L06 Oversite Agency: SCVWD

2000-12-26 00:00:00 Date Listed: Closed Date: 2001-08-24 00:00:00

W147 **AIR SYSTEMS INC**

West **381 STOCKTON AVENUE 1-3** 1/8-1/4 SAN JOSE, CA 95126

0.244 mi.

1289 ft. Site 6 of 9 in cluster W

SWEEPS UST: Relative: Higher Status:

Comp Number: 403131 Actual: Not reported Number: 90 ft. Board Of Equalization: Not reported Referral Date: Not reported Action Date:

Not reported Created Date: Not reported Owner Tank Id: Not reported SWRCB Tank Id:

43-060-403131-000001

Not reported

Tank Status: Not reported Capacity: 10000 Active Date: Not reported Tank Use: M.V. FUEL STG: **PRODUCT** Content: **REG UNLEADED**

Number Of Tanks:

Not reported Status:

SWEEPS UST \$106922468

N/A

Distance Elevation

Site Database(s) EPA ID Number

AIR SYSTEMS INC (Continued)

S106922468

EDR ID Number

Comp Number: 403131
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported

SWRCB Tank ld: 43-060-403131-000002

Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Not reported Status: Comp Number: 403131 Number: Not reported Board Of Equalization: Not reported Referral Date: Not reported Action Date: Not reported Created Date: Not reported Owner Tank Id: Not reported

SWRCB Tank ld: 43-060-403131-000003

Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Status: Not reported Comp Number: 403131 Number: Not reported Board Of Equalization: Not reported Referral Date: Not reported Action Date: Not reported Created Date: Not reported Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-403131-000004

Tank Status:

Capacity:

Active Date:

Tank Use:

STG:

Content:

Not reported

Not reported

M.V. FUEL

PRODUCT

DIESEL

Number Of Tanks:

Not reported

Status: Not reported
Comp Number: 403131
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AIR SYSTEMS INC (Continued)

S106922468

Owner Tank Id: Not reported

43-060-403131-000005 SWRCB Tank Id:

Tank Status: Not reported 10000 Capacity: Active Date: Not reported M.V. FUEL Tank Use: **PRODUCT** STG: Content: **DIESEL** Number Of Tanks: Not reported

Not reported Status: 403131 Comp Number: Not reported Number: Board Of Equalization: Not reported Referral Date: Not reported Action Date: Not reported Not reported Created Date: Owner Tank Id: Not reported

SWRCB Tank Id: 43-060-403131-000006

Tank Status: Not reported Capacity: 10000 Active Date: Not reported Tank Use: M.V. FUEL STG: **PRODUCT** Content: **DIESEL** Number Of Tanks: Not reported

W148 **MIX INTERNATIONAL AUTO BODY CUPA Listings** S121471162

West **355 STOCKTON AV**

1/8-1/4 **SAN JOSE, CA 95126**

0.244 mi.

1289 ft. Site 7 of 9 in cluster W Relative: CUPA SANTA CLARA:

Higher SANTA CLARA Region:

PE#: Actual:

90 ft. Program Description: GENERATES 100 KG YR TO <5 TONS/YR

Latitude: 37.334591 Longitude: -121.907028 Record ID: PR0330085 Facility ID: FA0230078

W149 **SUPERIOR AUTO BODY** RCRA-SQG 1000215824

CAD053888806 West **355 STOCKTON AVE FINDS ECHO** 1/8-1/4 SAN JOSE, CA 95126

0.244 mi.

Site 8 of 9 in cluster W 1289 ft.

Relative: RCRA-SQG:

Higher Date form received by agency: 05/06/1986

Facility name: SUPERIOR AUTO BODY Actual: Facility address: 355 STOCKTON AVE 90 ft. SAN JOSE, CA 95126

> EPA ID: CAD053888806 Mailing address: STOCKTON AVE

SAN JOSE, CA 95126

N/A

Direction Distance Elevation

vation Site Database(s) EPA ID Number

SUPERIOR AUTO BODY (Continued)

1000215824

EDR ID Number

Contact: ENVIRONMENTAL MANAGER

Contact address: 355 STOCKTON AVE

SAN JOSE, CA 95126

Contact country: US

Contact telephone: 408-292-9838 Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: FRANK LAURICELLA Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Not reported Owner/operator email: Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Not reported Owner/Op end date:

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SUPERIOR AUTO BODY (Continued)

1000215824

Used oil transporter: No

Violation Status: No violations found

FINDS:

110002649590 Registry ID:

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access

additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000215824 Registry ID: 110002649590

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002649590

W150 **MORRISON PARK** LUST S104162882

395 STOCKTON AVENUE West **CPS-SLIC** N/A 1/8-1/4 SAN JOSE, CA 95126 **HIST LUST**

0.244 mi. **BROWNFIELDS** 1289 ft. Site 9 of 9 in cluster W **HIST CORTESE**

Relative:

Higher LUST:

SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency: Actual:

Case Type: LUST Cleanup Site 90 ft.

http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500525 Geo Track:

T0608500525 Global Id: 37.33512 Latitude: -121.906524 Longitude:

Completed - Case Closed Status:

Status Date: 04/06/2009 Case Worker: UUU RB Case Number: 07S1E07L01f Not reported Local Agency:

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E07L01f

Other Groundwater (uses other than drinking water) Potential Media Affect:

Potential Contaminants of Concern: Gasoline

Site History: Site is part of the Morrison Park redevelopment - see Water Board

files for Morrison Park.

LUST:

Global Id: T0608500525

Regional Board Caseworker Contact Type: Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

OAKLAND City:

CERS

Distance

Elevation Site Database(s) EPA ID Number

MORRISON PARK (Continued)

S104162882

EDR ID Number

Email: Not reported Phone Number: Not reported

LUST:

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 12/04/2000

Action: Interim Remedial Action Plan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 11/10/1997

Action: Corrective Action Plan / Remedial Action Plan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 10/16/2006

Action: Other Report / Document

Global Id: T0608500525
Action Type: RESPONSE
Date: 07/30/2004

Action: Corrective Action Plan / Remedial Action Plan

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 05/02/2006

 Action:
 Staff Letter - #6025

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 09/18/2006

Action: Well Installation Report

Global Id: T0608500525
Action Type: ENFORCEMENT
Date: 04/03/2009

Action: Closure/No Further Action Letter

 Global Id:
 T0608500525

 Action Type:
 Other

 Date:
 08/14/1985

 Action:
 Leak Reported

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 03/10/1997

 Action:
 Other Workplan

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 04/03/2009

Action: Closure/No Further Action Letter

 Global Id:
 T0608500525

 Action Type:
 REMEDIATION

 Date:
 01/01/2002

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MORRISON PARK (Continued)

S104162882

Action: Soil Vapor Extraction (SVE)

T0608500525 Global Id: Action Type: REMEDIATION Date: 01/01/2002

Pump & Treat (P&T) Groundwater Action:

Global Id: T0608500525 Action Type: **RESPONSE** Date: 02/18/2009

Action: CAP/RAP - Other Report

Global Id: T0608500525 Action Type: **RESPONSE** Date: 02/18/2009

CAP/RAP - Other Report Action:

T0608500525 Global Id: Action Type: **RESPONSE** 03/02/2007 Date:

Action: Remedial Progress Report

Global Id: T0608500525 Action Type: REMEDIATION Date: 07/31/2005 Action: Excavation

Global Id: T0608500525 Action Type: **RESPONSE** Date: 04/20/2000

Action: Well Installation Report

Global Id: T0608500525 RESPONSE Action Type: Date: 10/13/2000

CAP/RAP - Feasibility Study Report Action:

Global Id: T0608500525 **ENFORCEMENT** Action Type: Date: 07/18/2005 Action: Warning Letter

Global Id: T0608500525 Action Type: **ENFORCEMENT** Date: 11/16/2001

Staff Letter - #26989 Action:

Global Id: T0608500525 Action Type: **ENFORCEMENT** 08/05/2003 Date: Action: Staff Letter - #41862

Global Id: T0608500525 Action Type: **ENFORCEMENT** Date: 04/29/2004

Action: Notice of Responsibility - #43722

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

MORRISON PARK (Continued)

S104162882

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 04/29/2004

 Action:
 Staff Letter - #43729

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 12/08/2004

 Action:
 Staff Letter

Global Id: T0608500525
Action Type: ENFORCEMENT
Date: 11/03/2006

Action: Staff Letter - #603011

Global Id: T0608500525
Action Type: ENFORCEMENT
Date: 10/27/1989

Action: Notice of Responsibility - #39946

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 09/05/1995

Action: Staff Letter - #27143

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 11/03/1997

Action: Staff Letter - #27148

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 06/01/1999

Action: Staff Letter - #27156

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 06/06/2000

Action: Staff Letter - #27159

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 10/24/2000

Action: Staff Letter - #27163

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 05/03/2001

Action: Staff Letter - #26983

 Global Id:
 T0608500525

 Action Type:
 ENFORCEMENT

 Date:
 11/15/2001

 Action:
 Staff Letter - #26987

2.

Global Id: T0608500525 Action Type: RESPONSE

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MORRISON PARK (Continued)

S104162882

Date: 07/16/2003

Interim Remedial Action Report Action:

Global Id: T0608500525 Action Type: **RESPONSE** 12/27/1991 Date: Action: Correspondence

Global Id: T0608500525 Action Type: **RESPONSE** Date: 08/06/1995 Action: Other Workplan

Global Id: T0608500525 Action Type: **RESPONSE** Date: 10/31/2002

Action: Other Report / Document

Global Id: T0608500525 **RESPONSE** Action Type: Date: 05/02/2006 Action: Correspondence

Global Id: T0608500525 Action Type: **RESPONSE** Date: 07/27/2004

Action: CAP/RAP - Other Report

Global Id: T0608500525 Action Type: **RESPONSE** 11/03/1993 Date: Action: Other Workplan

Global Id: T0608500525 **RESPONSE** Action Type: 07/15/2004 Date:

Action: Monitoring Report - Semi-Annually

T0608500525 Global Id: **RESPONSE** Action Type: Date: 10/14/1997

Action: Other Report / Document

Global Id: T0608500525 Action Type: **ENFORCEMENT** Date: 09/27/2006

Action: Staff Letter - #607290

Global Id: T0608500525 Action Type: **ENFORCEMENT** Date: 08/08/2006

Action: Staff Letter - #608080

Global Id: T0608500525 Action Type: **ENFORCEMENT** Date: 03/06/2008 Action: Staff Letter

Direction Distance Elevation

evation Site Database(s) EPA ID Number

MORRISON PARK (Continued)

S104162882

EDR ID Number

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 07/16/1999

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 07/30/2008

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 07/10/2000

Action: Soil and Water Investigation Workplan

Global Id: T0608500525
Action Type: RESPONSE
Date: 04/30/2008

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 08/09/2000

 Action:
 Other Workplan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 12/28/1990

Action: Preliminary Site Assessment Report

Global Id: T0608500525
Action Type: RESPONSE
Date: 10/17/2006

Action: Other Report / Document

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 10/23/2008

 Action:
 Correspondence

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 10/31/2002

Action: Other Report / Document

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 04/29/2004

 Action:
 Correspondence

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 01/30/2003

Action: Remedial Progress Report

Global Id: T0608500525 Action Type: RESPONSE

Direction Distance Elevation

levation Site Database(s) EPA ID Number

MORRISON PARK (Continued)

S104162882

EDR ID Number

Date: 02/11/2005

Action: Verbal Communication

Global Id: T0608500525
Action Type: RESPONSE
Date: 02/14/2008

Action: NPDES / WDR Reports

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 08/11/2008

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 04/20/2001

Action: Interim Remedial Action Plan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 05/26/1999

Action: Well Installation Workplan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 11/12/1998

 Action:
 Other Workplan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 08/14/1985

Action: Unauthorized Release Form

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 10/23/2006

Action: Other Report / Document

Global Id: T0608500525
Action Type: RESPONSE
Date: 01/15/1996

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 07/15/2001

Action: Soil and Water Investigation Report

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 10/13/2003

Action: Remedial Progress Report

 Global Id:
 T0608500525

 Action Type:
 RESPONSE

 Date:
 12/24/2001

Action: Monitoring Report - Quarterly

Direction Distance

Elevation Site Database(s) **EPA ID Number**

MORRISON PARK (Continued)

S104162882

EDR ID Number

Global Id: T0608500525 RESPONSE Action Type: 12/24/2001 Date:

Action: Monitoring Report - Quarterly

Global Id: T0608500525 **RESPONSE** Action Type: Date: 07/17/2006

Action: Soil and Water Investigation Report

Global Id: T0608500525 **RESPONSE** Action Type: Date: 03/26/1998

Action: Well Installation Workplan

Global Id: T0608500525 **RESPONSE** Action Type: Date: 08/29/2006

Action: Other Report / Document

Global Id: T0608500525 **RESPONSE** Action Type: Date: 10/17/2006

Action: Other Report / Document

Global Id: T0608500525 Action Type: **RESPONSE** Date: 11/28/1990

Action: Preliminary Site Assessment Workplan

LUST:

Global Id: T0608500525

Completed - Case Closed Status:

04/06/2009 Status Date:

Global Id: T0608500525

Status: Open - Case Begin Date

Status Date: 01/09/1985

T0608500525 Global Id: Open - Remediation Status: Status Date: 10/23/2003

T0608500525 Global Id: Status: Open - Remediation

07/29/2004 Status Date:

Global Id: T0608500525 Open - Remediation Status:

12/08/2004 Status Date:

T0608500525 Global Id:

Open - Site Assessment Status:

01/09/1985 Status Date:

Global Id: T0608500525

Status: Open - Site Assessment

Direction Distance

Elevation Site Database(s) EPA ID Number

MORRISON PARK (Continued)

S104162882

EDR ID Number

Status Date: 08/09/2000

LUST REG 2:

Region: 2

Facility Id: Not reported

Facility Status: Pollution Characterization

Case Number: 07S1E07L01f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 7/9/1985
Pollution Characterization Began: 7/9/1985
Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07L01F

 Date Closed:
 04/03/2009

 EDR Link ID:
 07S1E07L01F

CPS-SLIC:

Region: STATE

Facility Status: Completed - Case Closed

 Status Date:
 03/19/2009

 Global Id:
 T0608573680

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: 07S1E07L01f Latitude: 37.335252 Longitude: -121.907848

Case Type: Cleanup Program Site

Case Worker: UUU
Local Agency: Not reported
RB Case Number: 43S1090
File Location: Regional Board

Potential Media Affected: Aquifer used for drinking water supply

Potential Contaminants of Concern: Gasoline, Benzene, Diesel

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07L01 Oversite Agency: SCCDEH

Date Listed: 1986-01-01 00:00:00
Closed Date: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MORRISON PARK (Continued)

S104162882

BROWNFIELDS:

T0608573680 Global ID: Latitude: 37.335252 Longitude: -121.907848

Project Type: Cleanup Program Site Completed - Case Closed Status:

03/19/2009 Status Date:

SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency:

Last Correspondence Date: 03/19/2009

Release Type: Federally Regulated Underground Storage Tank System - UST

Contaminant(s) of Concern: Gasoline, Benzene, Diesel

Media of Concern: Aquifer used for drinking water supply

Past Use(s) that Caused Contamination: Not reported Human Health Exposure Controlled: Not reported Human Health Exposure Controlled Date: Not reported **Groundwater Migration Controlled:** Not reported Groundwater Migration Controlled Date: Not reported

Primary Caseworker Name: Regional Water Board

Primary Caseworker Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Primary Caseworker Phone Number: 510-622-3277

Primary Caseworker Address: 1515 CLAY ST SUITE 1400

Primary Caseworker Address: OAKLAND Primary Caseworker Address: CA

Primary Caseworker Email: Not reported

HIST CORTESE:

Region: **CORTESE** Facility County Code: 43 **LTNKA** Reg By: 43-0479 Reg Id:

CERS TANKS:

204581 Site ID: CERS ID: T0608500525

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) Entity Name:

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Site ID: 244249 CERS ID: T0608573680 **CERS** Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

1515 CLAY ST SUITE 1400 Affiliation Address:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MORRISON PARK (Continued) S104162882

Affiliation City: **OAKLAND** Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

V151 **DIRIDON STATION ACE HARDWARE CUPA Listings** S122495131

SW 785 THE ALAMEDA STE 40

SAN JOSE, CA 95126 1/8-1/4

0.246 mi.

1300 ft. Site 2 of 2 in cluster V Relative: CUPA SANTA CLARA:

Higher SANTA CLARA Region:

PE#: 2240 Actual:

Program Description: GENERATES < 10 GAL/YR 94 ft.

> Latitude: 37.3320896 -121.9053965 Longitude: Record ID: PR0432529 Facility ID: FA0288473

X152 JAMES LICK HIGH SCHOOL HIST CORTESE S100937669

SSW 57 WHITE

1/8-1/4 SAN JOSE, CA 95127

0.248 mi.

Site 1 of 5 in cluster X 1312 ft. Relative: HIST CORTESE:

Higher Region: **CORTESE** Facility County Code: 43 Actual:

Reg By: **LTNKA** 95 ft. 43-0726 Reg Id:

RCRA NonGen / NLR 1000251594 153 **PACIFIC BELL FINDS** CAT080024946

SW **817 THE ALAMEDA** 1/8-1/4 SAN JOSE, CA 95126 0.249 mi.

1317 ft. Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 09/02/1997 Facility name: PACIFIC BELL Actual: Facility address: 95 ft. 817 THE ALAMEDA

SAN JOSE, CA 95126 EPA ID: CAT080024946

Mailing address: 2 NORTH SECOND ST ROOM 1125

SAN JOSE, CA 95113

Contact: ENVIRONMENTAL MANAGER

Contact address: 817 THE ALAMEDA SAN JOSE, CA 95126

Contact country: US

Contact telephone: 408-491-6029 Contact email: Not reported

EPA Region: 09 N/A

N/A

ECHO

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PACIFIC BELL (Continued) 1000251594

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: THE PACIFIC TELEPHONE AND TELEGRAPH CO

NOT REQUIRED Owner/operator address:

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: THE PACIFIC TELEPHONE AND TELEGRAPH CO

Owner/operator address: NOT REQUIRED

SAN JOSE, CA 95126

Owner/operator country: Not reported Owner/operator telephone: 408-491-6029 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 09/01/1996 PACIFIC BELL Site name:

Classification: Small Quantity Generator

Date form received by agency: 01/26/1981 Site name: PACIFIC BELL

Classification: Large Quantity Generator

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

PACIFIC BELL (Continued) 1000251594

Violation Status: No violations found

FINDS:

Registry ID: 110002952252

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000251594 Registry ID: 110002952252

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002952252

T154 SAN JOSE ARENA BLOCK 5A LUST S121753229
SSE 522 W SANTA CLARA ST. DEED N/A
1/4-1/2 SAN JOSE, CA 95113 CERS

0.252 mi.

1331 ft. Site 11 of 14 in cluster T

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

88 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500220

 Global Id:
 T0608500220

 Latitude:
 37.3316369311374

 Longitude:
 -121.900710419643

 Status:
 Completed - Case Closed

Status Date: 02/13/2009
Case Worker: AC
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E07Q12f

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500220

Contact Type: Local Agency Caseworker

Contact Name: AARON COSTA

Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

City: SAN JOSE

Email: aaron.costa@cep.sccgov.org

Phone Number: 4089181954

Global Id: T0608500220

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA BLOCK 5A (Continued)

S121753229

EDR ID Number

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

LUST:

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 08/01/2008

Action: Deed Restriction / Land Use Restriction / Covenant

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 08/17/2001

Action: Other Report / Document

Global Id: T0608500220
Action Type: RESPONSE
Date: 06/03/2005

Action: Other Report / Document

Global Id: T0608500220
Action Type: ENFORCEMENT
Date: 02/13/2009

Action: Closure/No Further Action Letter

 Global Id:
 T0608500220

 Action Type:
 Other

 Date:
 01/01/1992

 Action:
 Leak Reported

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 01/01/1990

 Action:
 Correspondence

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

Global Id: T0608500220
Action Type: RESPONSE
Date: 01/09/1991

Action: Other Report / Document

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 09/01/1993

Action: Soil and Water Investigation Report

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 09/13/1990

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA BLOCK 5A (Continued)

S121753229

EDR ID Number

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 10/10/1990

Action: Unauthorized Release Form

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 09/25/2018

Action: Soil and Water Investigation Workplan - Regulator Responded

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 12/13/2014

Action: Other Report / Document

Global Id: T0608500220
Action Type: RESPONSE
Date: 11/24/1999

Action: Other Report / Document

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 10/26/1988

Action: Preliminary Site Assessment Report

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 04/05/2018

Action: Preliminary Site Assessment Workplan - Regulator Responded

 Global Id:
 T0608500220

 Action Type:
 REMEDIATION

 Date:
 12/01/1995

Action: In Situ Physical/Chemical Treatment (other than SVE)

 Global Id:
 T0608500220

 Action Type:
 REMEDIATION

 Date:
 12/01/1995

Action: Soil Vapor Extraction (SVE)

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 07/24/2008

 Action:
 Notice to Comply

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 08/31/1999

Action: Risk Assessment Report

Direction
Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA BLOCK 5A (Continued)

S121753229

EDR ID Number

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 02/09/2009

Action: Well Destruction Report

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 10/02/2018

 Action:
 Staff Letter

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 04/09/2018

 Action:
 Staff Letter

Global Id: T0608500220
Action Type: ENFORCEMENT
Date: 02/13/2009

Action: Closure/No Further Action Letter

Global Id: T0608500220
Action Type: RESPONSE
Date: 07/01/1996

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 04/24/1995

Action: NPDES / WDR Reports

Global Id: T0608500220
Action Type: RESPONSE
Date: 05/07/1993

Action: Other Report / Document

 Global Id:
 T0608500220

 Action Type:
 RESPONSE

 Date:
 02/24/1997

 Action:
 Other Workplan

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 11/17/1998

 Action:
 Staff Letter - #26854

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 12/18/1998

 Action:
 Staff Letter - #26857

 Global Id:
 T0608500220

 Action Type:
 ENFORCEMENT

 Date:
 10/31/1995

Action: Notice of Responsibility - #39956

LUST:

Global Id: T0608500220

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA BLOCK 5A (Continued)

S121753229

Status: Completed - Case Closed

02/13/2009 Status Date:

Global Id: T0608500220

Status: Open - Case Begin Date

09/01/1988 Status Date:

T0608500220 Global Id: Status: Open - Inactive Status Date: 11/13/2008

T0608500220 Global Id: Status: Open - Remediation

Status Date: 12/01/1995

Global Id: T0608500220

Open - Site Assessment Status:

09/01/1988 Status Date:

Global Id: T0608500220

Status: Open - Site Assessment

10/01/1988 Status Date:

Global Id: T0608500220

Open - Verification Monitoring Status:

Status Date: 11/27/1996

DEED:

T0608500220 **Envirostor ID:** Not reported Area: Sub Area: Not reported

Site Type: **LUFT**

COMPLETED - CASE CLOSED Status:

SWRCB Agency: Covenant Uploaded: Deed Date(s): 08/01/2008

File Name: Geotracker Land Use/Deed Restrictions

CERS TANKS:

Site ID: 226383 CERS ID: T0608500220

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported

Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

AARON COSTA - SANTA CLARA COUNTY LOP **Entity Name:**

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA BLOCK 5A (Continued)

S121753229

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089181954

T155 **SAN JOSE ARENA BLOCK 5A** LUST S103473097

522 SANTA CLARA SSE **HIST LUST** N/A

1/4-1/2 **SAN JOSE, CA 95110 HIST CORTESE**

0.252 mi.

1331 ft. Site 12 of 14 in cluster T

Relative: LUST REG 2: Higher Region:

Facility Id: Not reported Actual:

Facility Status: 88 ft. Post remedial action monitoring

Case Number: 07S1E07Q12f How Discovered: Not reported Leak Cause: Not reported Not reported Leak Source: Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 9/1/1988 Pollution Characterization Began: 10/1/1988 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: 12/1/1995 Date Post Remedial Action Monitoring Began: 11/27/1996

LUST SANTA CLARA:

SANTA CLARA Region: SCVWD ID: 07S1E07Q12F Date Closed: 02/13/2009 EDR Link ID: 07S1E07Q12F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

07S1E07Q12 SCVWD ID: Oversite Agency: SCVWD

1993-05-20 00:00:00 Date Listed: Closed Date: Not reported

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-0154

Direction Distance

Elevation Site Database(s) EPA ID Number

T156 SAN JOSE ARENA HOLEMAN PARCEL LUST S103177353

SE 443 SANTA CLARA ST W HIST CORTESE N/A

1/4-1/2 SAN JOSE, CA 95113 CERS

0.261 mi.

1378 ft. Site 13 of 14 in cluster T

Relative: LUST:

Lower Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

83 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500733

Global Id: T0608500733

Latitude: 37.3321703761059

Longitude: -121.899468898773

Status: Completed - Case Closed

 Status Date:
 04/10/1997

 Case Worker:
 UUU

 RB Case Number:
 43-0704

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Stoddard solvent / Mineral Spriits / Distillates

Site History: Not reported

LUST:

Global Id: T0608500733

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500733

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500733

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Reported

 Global Id:
 T0608500733

 Action Type:
 RESPONSE

 Date:
 01/01/1997

Action: Other Report / Document

Global Id: T0608500733
Action Type: RESPONSE
Date: 01/01/1997

Action: Other Report / Document

EDR ID Number

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA HOLEMAN PARCEL (Continued)

S103177353

Global Id: T0608500733 RESPONSE Action Type: 01/01/1989 Date:

Action: Other Report / Document

Global Id: T0608500733 **RESPONSE** Action Type: Date: 01/01/1989

Action: Other Report / Document

Global Id: T0608500733 Action Type: **ENFORCEMENT** Date: 04/09/1997

Action: Closure/No Further Action Letter

Global Id: T0608500733 Other Action Type: 03/28/1989 Date: Action: Leak Discovery

Global Id: T0608500733 Action Type: Other 03/28/1989 Date: Action: Leak Stopped

LUST:

Global Id: T0608500733

Status: Completed - Case Closed

Status Date: 04/10/1997

Global Id: T0608500733

Status: Open - Case Begin Date

03/28/1989 Status Date:

Global Id: T0608500733

Open - Site Assessment Status:

Status Date: 01/31/1996

LUST REG 2:

Region:

Facility Id: 43-0704 Facility Status: Case Closed Case Number: 07S1E07Q07 How Discovered: Tank Closure Leak Cause: Structure Failure Leak Source: Tank

Date Leak Confirmed: 1/31/1996 LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

SAN JOSE ARENA HOLEMAN PARCEL (Continued)

S103177353

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0704

CERS TANKS:

Site ID: 189812 CERS ID: 70608500733

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

T157 S & W LAND COMPANY LUST S105512901
SE 454 W SANTA CLARA ST LUST N/A

1/4-1/2 SAN JOSE, CA 95128 0.262 mi.

1381 ft. Site 14 of 14 in cluster T

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

85 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608502143

 Global Id:
 T0608502143

 Latitude:
 37.3317347807548

 Longitude:
 -121.899832359

 Status:
 Completed - Case Closed

Status Date: 04/09/1999
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil

Potential Contaminants of Concern: Heating Oil / Fuel Oil Site History: Not reported

CERS

Direction Distance Elevation

vation Site Database(s) EPA ID Number

S & W LAND COMPANY (Continued)

S105512901

EDR ID Number

LUST:

Global Id: T0608502143

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608502143

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608502143

 Action Type:
 Other

 Date:
 01/01/1991

 Action:
 Leak Reported

 Global Id:
 T0608502143

 Action Type:
 RESPONSE

 Date:
 04/09/1999

Action: Other Report / Document

 Global Id:
 T0608502143

 Action Type:
 ENFORCEMENT

 Date:
 04/09/1999

Action: Closure/No Further Action Letter

LUST:

Global Id: T0608502143

Status: Completed - Case Closed

Status Date: 04/09/1999

Global Id: T0608502143

Status: Open - Case Begin Date

Status Date: 01/01/1991

Global Id: T0608502143

Status: Open - Site Assessment

Status Date: 04/01/1999

LUST REG 2:

Region: 2

Facility Id: Not reported
Facility Status: Case Closed
Case Number: 07S1E07Q15f
How Discovered: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

S & W LAND COMPANY (Continued)

S105512901

EDR ID Number

Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Not reported
Not reported
Not reported
Not reported
Not reported
Polte Remediation Action Underway:
Not reported
Not reported
Not reported
Not reported
Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07Q15F

 Date Closed:
 04/09/1999

 EDR Link ID:
 07S1E07Q15F

HIST LUST SANTA CLARA:

Region: SANTA CLARA Region Code: 2

SCVWD ID: 07S1E07Q15 Oversite Agency: SCVWD

Date Listed: 1992-01-01 00:00:00 Closed Date: 1999-04-09 00:00:00

CERS TANKS:

 Site ID:
 255990

 CERS ID:
 T0608502143

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Distance EDR ID Number EDevation Site EDR ID Number Database(s) EPA ID Number

X158 EAGLE GAS AND MINI MART HIST CORTESE \$102429051

SSW 95 WHITE

1/4-1/2 SAN JOSE, CA 95127

0.264 mi.

1396 ft. Site 2 of 5 in cluster X
Relative: HIST CORTESE:

HigherRegion:CORTESEActual:Facility County Code:43

96 ft. Reg By: LTNKA Reg Id: 43-2073

Y159 MILITARY FAMILY HOUSING, HIST CORTESE \$105026287

SE 400 SANTA CLARA

1/4-1/2 SAN JOSE, CA

0.279 mi.

1475 ft. Site 1 of 2 in cluster Y
Relative: HIST CORTESE:

 Lower
 Region:
 CORTESE

 Actual:
 Facility County Code:
 43

 79 ft.
 Reg By:
 LTNKA

 Reg Id:
 2738

Z160 UNKNOWN Notify 65 S100178940

ESE 35 NORTH RIVER STREET N/A

1/4-1/2 SAN JOSE, CA 93212

0.280 mi.

1477 ft. Site 1 of 3 in cluster Z

Relative: NOTIFY 65:

LowerDate Reported:Not reportedActual:Staff Initials:Not reported80 ft.Board File Number:Not reported

Board File Number: Not reported Facility Type: Not reported Discharge Date: Not reported Incident Description: Not reported Not reported Not reported

X161 DEL MONTE PLANT 51 CPS-SLIC S105194855

SSW 50 BUSH

1/4-1/2 SAN JOSE, CA 95113

0.285 mi.

1507 ft. Site 3 of 5 in cluster X

Relative: SLIC REG 2: Higher Region:

Higher Region: 2
Actual: Facility ID: 43S0956

95 ft. Facility Status: Preliminary site assessment workplan submitted

Date Closed: Not reported
Local Case #: Not reported
How Discovered: Tank Closure
Leak Cause: UNK
Leak Source: UNK
Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: 11/2/2000
Date Preliminary Site Assessment Began: Not reported

TC05569778.2r Page 396

N/A

N/A

N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DEL MONTE PLANT 51 (Continued) S105194855

Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

DEL MONTE PLANT 51 X162 LUST S101303874 **HIST LUST** N/A

ssw **50 BUSH ST**

1/4-1/2 SAN JOSE, CA 95103

0.285 mi.

1507 ft. Site 4 of 5 in cluster X

LUST REG 2: Relative: Higher Region:

Facility Id: Not reported Actual:

Case Closed Facility Status: 95 ft. 07S1E18C02f Case Number: How Discovered: Not reported

Leak Cause: Not reported Leak Source: Not reported Not reported Date Leak Confirmed: Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 7/26/1989 Pollution Characterization Began: 3/12/1990 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E18C02 Oversite Agency: SCVWD

1990-01-01 00:00:00 Date Listed: 1995-09-06 00:00:00 Closed Date:

S103881056 X163 **DEL MONTE PLANT 51** LUST

SSW **50 BUSH ST** CPS-SLIC N/A

1/4-1/2 SAN JOSE, CA 95103 **HIST CORTESE**

0.285 mi. CERS

1507 ft. Site 5 of 5 in cluster X

Relative: LUST:

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500504 95 ft.

Global Id: T0608500504 37.330669524292 Latitude: Longitude: -121.904219916672 Completed - Case Closed Status:

09/06/1995 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

All Files are on GeoTracker or in the Local Agency Database File Location:

Local Case Number: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

DEL MONTE PLANT 51 (Continued)

S103881056

EDR ID Number

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Heating Oil / Fuel Oil

Site History: Not reported

LUST:

Global Id: T0608500504

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500504

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500504

 Action Type:
 RESPONSE

 Date:
 12/21/1993

Action: Other Report / Document

 Global Id:
 T0608500504

 Action Type:
 Other

 Date:
 07/27/1989

 Action:
 Leak Reported

Global Id: T0608500504
Action Type: ENFORCEMENT
Date: 05/18/1993

Action: Notice of Violation - #39849

 Global Id:
 T0608500504

 Action Type:
 ENFORCEMENT

 Date:
 09/06/1995

Action: Closure/No Further Action Letter

 Global Id:
 T0608500504

 Action Type:
 REMEDIATION

 Date:
 12/20/1988

 Action:
 Excavation

LUST:

Global Id: T0608500504

Status: Completed - Case Closed

Status Date: 09/06/1995

Global Id: T0608500504

Status: Open - Case Begin Date

Status Date: 07/26/1989

Direction Distance

Elevation Site Database(s) EPA ID Number

DEL MONTE PLANT 51 (Continued)

S103881056

EDR ID Number

Global Id: T0608500504

Status: Open - Site Assessment

Status Date: 07/26/1989

Global Id: T0608500504

Status: Open - Site Assessment

Status Date: 03/12/1990

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E18C02F

 Date Closed:
 09/06/1995

 EDR Link ID:
 07S1E18C02F

CPS-SLIC:

Region: STATE

 Facility Status:
 Open - Inactive

 Status Date:
 09/15/2015

 Global Id:
 T0608591714

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported 37.330359
Longitude: -121.90444

Case Type: Cleanup Program Site

Case Worker: DIB
Local Agency: Not reported
RB Case Number: 43S0956
File Location: Regional Board

Potential Media Affected: Soil

Potential Contaminants of Concern: * Solvents, Arsenic, Diesel, Other Petroleum

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0457

CERS TANKS:

Site ID: 244635
CERS ID: T0608591714
CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: David Barr - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST., STE. 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

DEL MONTE PLANT 51 (Continued)

S103881056

 Site ID:
 215869

 CERS ID:
 T0608500504

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

BOCARDO PROPERTY LUST S106112776 849 THE ALAMEDA HIST LUST N/A /2 SAN JOSE, CA 95101 CERS

1/4-1/2 0.301 mi. 1588 ft.

164

SW

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

96 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608548658

 Global Id:
 T0608548658

 Latitude:
 37.332091

 Longitude:
 -121.906926

Status: Completed - Case Closed

Status Date: 09/02/2003
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608548658

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Direction Distance Elevation

Database(s) EPA ID Number

Database(s) EPA ID Number

BOCARDO PROPERTY (Continued)

S106112776

Global Id: T0608548658

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608548658

 Action Type:
 Other

 Date:
 06/13/2003

 Action:
 Leak Reported

Global Id: T0608548658
Action Type: RESPONSE
Date: 06/13/2003

Action: Unauthorized Release Form

 Global Id:
 T0608548658

 Action Type:
 ENFORCEMENT

 Date:
 08/26/2003

Action: Closure/No Further Action Letter

 Global Id:
 T0608548658

 Action Type:
 RESPONSE

 Date:
 06/01/2003

Action: Preliminary Site Assessment Report

Global Id: T0608548658
Action Type: RESPONSE
Date: 03/12/1991

Action: Other Report / Document

LUST:

Global Id: T0608548658

Status: Completed - Case Closed

Status Date: 09/02/2003

Global Id: T0608548658

Status: Open - Case Begin Date

Status Date: 04/17/2003

Global Id: T0608548658

Status: Open - Site Assessment

Status Date: 04/17/2003

LUST REG 2:

Region: 2

Facility Id: Not reported
Facility Status: Case Closed
Case Number: 07S1E07P03f
How Discovered: Not reported
Leak Cause: Unknown

Direction Distance

Elevation Site Database(s) EPA ID Number

BOCARDO PROPERTY (Continued)

S106112776

EDR ID Number

Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 4/17/2003
Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07P03F

 Date Closed:
 08/26/2003

 EDR Link ID:
 07S1E07P03F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07P03 Oversite Agency: SCVWD

Date Listed: 2003-09-02 00:00:00 Closed Date: 2003-09-02 00:00:00

CERS TANKS:

 Site ID:
 240706

 CERS ID:
 T0608548658

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

Z165 MANNING PROPERTY LUST \$101304186

ESE 35 RIVER ST N HIST LUST N/A

1/4-1/2 SAN JOSE, CA 95110 HIST CORTESE 0.303 mi. CERS

1602 ft. Site 2 of 3 in cluster Z

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

84 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500865

Global Id: T0608500865
Latitude: 37.333559
Longitude: -121.896959

Status: Completed - Case Closed

Status Date: 03/03/1997
Case Worker: UUU
RB Case Number: 43-0854

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Diesel Site History: Not reported

LUST:

Global Id: T0608500865

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500865

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500865

 Action Type:
 ENFORCEMENT

 Date:
 03/23/1995

Action: Staff Letter - #43-0854

 Global Id:
 T0608500865

 Action Type:
 RESPONSE

 Date:
 01/01/1989

 Action:
 Correspondence

Global Id: T0608500865
Action Type: ENFORCEMENT
Date: 03/03/1997

Action: Closure/No Further Action Letter - #43-0854

EDR ID Number

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

MANNING PROPERTY (Continued)

S101304186

 Global Id:
 T0608500865

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Reported

Global Id: T0608500865
Action Type: RESPONSE
Date: 08/31/1994

Action: Well Installation Report

Global Id: T0608500865
Action Type: RESPONSE
Date: 09/26/1987

Action: Other Report / Document

Global Id: T0608500865
Action Type: RESPONSE
Date: 05/05/1989

Action: Preliminary Site Assessment Report

Global Id: T0608500865
Action Type: RESPONSE
Date: 09/25/1989

Action: Soil and Water Investigation Report

 Global Id:
 T0608500865

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

Global Id: T0608500865
Action Type: RESPONSE
Date: 12/10/1990

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500865

 Action Type:
 RESPONSE

 Date:
 02/14/1989

Action: Unauthorized Release Form

 Global Id:
 T0608500865

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608500865

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608500865

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Discovery

Global Id: T0608500865

Action Type: Other

Direction Distance Elevation

vation Site Database(s) EPA ID Number

MANNING PROPERTY (Continued)

S101304186

EDR ID Number

Date: 03/28/1989 Action: Leak Stopped

LUST:

Global Id: T0608500865

Status: Completed - Case Closed

Status Date: 03/03/1997

Global Id: T0608500865

Status: Open - Case Begin Date

Status Date: 03/28/1989

Global Id: T0608500865

Status: Open - Site Assessment

Status Date: 09/13/1989

Global Id: T0608500865

Status: Open - Site Assessment

Status Date: 04/05/1991

LUST REG 2:

Region:

Facility Id: 43-0854
Facility Status: Case Closed
Case Number: 43-0854
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07R01 Oversite Agency: SFRWQCB

Date Listed: 1989-03-01 00:00:00
Closed Date: Not reported

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0854

CERS TANKS:

 Site ID:
 233724

 CERS ID:
 T0608500865

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

MANNING PROPERTY (Continued)

S101304186

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Z166 SAN JOSE SIDEWALK CITY OF HIST CORTESE \$103473095

N/A

ESE 333 SANTA CLARA 1/4-1/2 SAN JOSE, CA 95112

0.304 mi.

1607 ft. Site 3 of 3 in cluster Z

Relative: HIST CORTESE:

 Lower
 Region:
 CORTESE

 Actual:
 Facility County Code:
 43

 80 ft.
 Reg By:
 LTNKA

 Reg Id:
 43-2174

 167
 CINNABAR COMMONS
 CPS-SLIC
 \$118154681

 West
 875 CINNABAR STREET
 CERS
 N/A

1/4-1/2 0.311 mi. 1641 ft.

Relative: CPS-SLIC:
Higher Region: STATE

SAN JOSE, CA 95126

Actual: Facility Status: Completed - Case Closed

89 ft. Status Date: 02/06/2004 Global Id: SL0608552906

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported 121:404: 37.335392 121.908308

Case Type: Cleanup Program Site

Case Worker: DIB

Local Agency:

RB Case Number:

File Location:

Not reported

Regional Board

Potential Media Affected: Other Groundwater (uses other than drinking water), Soil

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CINNABAR COMMONS (Continued)

S118154681

Potential Contaminants of Concern: * Petroleum - Automotive gasolines, * Petroleum - Diesel fuels, *

Metals/Heavy Metals

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

CERS TANKS:

Site ID: 222809 CERS ID: SL0608552906 **CERS** Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: David Barr - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST., STE. 1400

OAKLAND Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Y168 **DIRIDON STATION JV** CPS-SLIC S118822761 W SANTA CLARA ST AND DELMAS AVE SE **CERS** N/A

1/4-1/2 SAN JOSE, CA 95113

0.314 mi.

1658 ft. Site 2 of 2 in cluster Y

CPS-SLIC: Relative: Higher Region:

STATE **Facility Status:** Open - Assessment & Interim Remedial Action Actual:

09/08/2016 Status Date: 86 ft.

T10000009352 Global Id:

SANTA CLARA COUNTY LOP Lead Agency:

2016-33s Lead Agency Case Number: Latitude: 37.33183 -121.89845 Longitude:

Case Type: Cleanup Program Site

Case Worker:

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported File Location: Not reported Potential Media Affected: Soil

Potential Contaminants of Concern: Not reported Site History: Not reported

Click here to access the California GeoTracker records for this facility:

CERS TANKS:

Site ID: 408151 CERS ID: T10000009352 **CERS** Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

AARON COSTA - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

DIRIDON STATION JV (Continued)

S118822761

S101304000

N/A

CERS

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089181954

AA169 PERRUCCI PROPERTIES CPS-SLIC

SSE 53 MONTGOMERY S 1/4-1/2 SAN JOSE, CA 95110

0.322 mi.

1700 ft. Site 1 of 5 in cluster AA

Relative: CPS-SLIC:
Higher Region: STATE

Actual: Facility Status: Completed - Case Closed

92 ft. Status Date: 01/09/2018 Global ld: T0608591654

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number:Not reportedLatitude:37.3296200147992Longitude:-121.901796704368Case Type:Cleanup Program Site

Case Worker: UUU
Local Agency: Not reported
RB Case Number: 43S0528
File Location: Regional Board

Potential Media Affected: Soil Potential Contaminants of Concern: Gasoline

Site History: This proposed site closure is based on the July 1992 Report of

Findings - Excavation of Contaminated Soils (Report) Environmental Solutions. The Report documented the excavation of contaminated petroleum hydrocarbons around the oil-water separator pit and the associated sump. Based on available information, the excavation removed total petroleum hydrocarbons as diesel, gasoline and benzene/toluene/ethylbenzene/xylenes to non-detectable levels.

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region: 2

Facility ID: 43S0528

Facility Status: Preliminary site assessment workplan submitted

Date Closed: Not reported
Local Case #: Not reported
How Discovered: Tank Closure
Leak Cause: UNK
Leak Source: UNK
Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: 3/15/1993

Date Preliminary Site Assessment Began: Not reported
Date Pollution Characterization Began: Not reported
Date Remediation Plan Submitted: Not reported
Date Remedial Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PERRUCCI PROPERTIES (Continued)

S101304000

CERS

N/A

CERS TANKS:

Site ID: 206986 T0608591654 CERS ID: CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

1515 CLAY ST SUITE 1400 Affiliation Address:

Affiliation City: OAKLAND Affiliation State: CA Affiliation Country: Not reported

Affiliation Zip: Not reported Affiliation Phone: Not reported

SERPA PROPERTY LUST S103982503

WNW 435 STOCKTON ST SAN JOSE, CA 95126 1/4-1/2

0.324 mi.

AB170

1711 ft. Site 1 of 2 in cluster AB

LUST: Relative:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Case Type: **LUST Cleanup Site** Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile report.asp?global id=T0608502421 87 ft.

T0608502421 Global Id: 37.3364054523797 Latitude: Longitude: -121.909134627012 Status: Completed - Case Closed

Status Date: 05/22/2002 Case Worker: UST RB Case Number: Not reported

SANTA CLARA COUNTY LOP Local Agency:

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608502421

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND Not reported Email: Phone Number: Not reported

T0608502421 Global Id:

Contact Type: Local Agency Caseworker Contact Name: UST CASE WORKER Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Not reported Email:

Direction Distance

Elevation Site Database(s) EPA ID Number

SERPA PROPERTY (Continued)

S103982503

EDR ID Number

Phone Number: 4089183400

LUST:

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 01/09/2004

Action: Interim Remedial Action Report

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 08/01/1997

Action: Other Report / Document

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 02/17/2004

Action: Site Assessment Report

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 01/06/2004

Action: Well Destruction Report

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 02/29/2000

 Action:
 Other Workplan

 Global Id:
 T0608502421

 Action Type:
 Other

 Date:
 07/30/1999

 Action:
 Leak Reported

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 09/03/1999

Action: Soil and Water Investigation Report

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 04/08/2002

Action: Other Report / Document

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 09/17/1998

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608502421

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 05/15/2000

Action: Other Report / Document

Direction Distance Elevation

evation Site Database(s) EPA ID Number

SERPA PROPERTY (Continued)

S103982503

EDR ID Number

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608502421

 Action Type:
 ENFORCEMENT

 Date:
 05/24/2000

 Action:
 Staff Letter - #26813

 Global Id:
 T0608502421

 Action Type:
 ENFORCEMENT

 Date:
 12/31/2001

 Action:
 Staff Letter - #26820

 Global Id:
 T0608502421

 Action Type:
 ENFORCEMENT

 Date:
 12/15/1999

Action: Staff Letter - #27109

Global Id: T0608502421
Action Type: ENFORCEMENT
Date: 07/03/2001

Action: Staff Letter - #26818

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 01/16/2004

Action: Remedial Progress Report

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 01/01/1999

 Action:
 Correspondence

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 10/12/2001

Action: Monitoring Report - Quarterly

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 08/28/2000

Action: Unauthorized Release Form

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 07/24/2000

Action: Soil and Water Investigation Report

Global Id: T0608502421 Action Type: RESPONSE

Direction Distance

Elevation Site Database(s) EPA ID Number

SERPA PROPERTY (Continued)

S103982503

EDR ID Number

Date: 01/11/2002

Action: Monitoring Report - Quarterly

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 02/28/2000

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608502421

 Action Type:
 RESPONSE

 Date:
 10/15/2001

Action: Monitoring Report - Quarterly

LUST:

Global Id: T0608502421

Status: Completed - Case Closed

Status Date: 05/22/2002

Global Id: T0608502421

Status: Open - Case Begin Date

Status Date: 07/30/1999

Global Id: T0608502421

Status: Open - Site Assessment

Status Date: 07/30/1999

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07M04F

 Date Closed:
 05/22/2002

 EDR Link ID:
 07S1E07M04F

CERS TANKS:

 Site ID:
 239438

 CERS ID:
 T0608502421

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SERPA PROPERTY (Continued) S103982503

Affiliation Zip: Not reported 4089183400 Affiliation Phone:

2

SERPA PROPERTY LUST S105512908 **AB171** WNW **HIST LUST** 435 STOCKTON ST N/A

1/4-1/2 **SAN JOSE, CA 95126**

0.324 mi.

1711 ft. Site 2 of 2 in cluster AB

Relative: LUST REG 2: Higher Region:

Facility Id: Not reported Actual: Facility Status: Case Closed 87 ft. 07S1E07M04f Case Number:

How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 7/30/1999 Pollution Characterization Began: 7/30/1999 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E07M04 Oversite Agency: SCVWD

1999-09-07 00:00:00 Date Listed: 2002-05-22 00:00:00 Closed Date:

LUST S103881007 **COMERICA BANK BUILDING**

East 333 W SANTA CLARA ST **HIST LUST** N/A 1/4-1/2 **SAN JOSE, CA 95113 CUPA Listings** 0.325 mi. SAN JOSE HAZMAT

1718 ft. **CERS**

LUST: Relative:

172

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501998 86 ft.

T0608501998 Global Id: 37.333116 Latitude: Longitude: -121.897243

Status: Completed - Case Closed

Status Date: 09/01/2011 Case Worker: Not reported RB Case Number: 14-396 Local Agency: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E07R03f Potential Media Affect: **Under Investigation**

Direction Distance Elevation

EDR ID Number
tion Site Database(s) EPA ID Number

COMERICA BANK BUILDING (Continued)

S103881007

Potential Contaminants of Concern: Gasoline

Site History: 1993 - June: Three UST's discovered under the sidewalk during the

planting of palm trees were removed. The highest level of 840 ppm TPHg was recorded in samples. No BTEX was detected. 1997 - San Jose Redevelopment Agency (SJRA) named responsible party by SCVWD. 1998 - SJRA notified to submit tests for fuel oxygenates and additives. 1998 - 2010 Numerous correspondence sent to SJRA and City of San Jose for

the submittal of a Workplan to Perform a Soil and Groundwater Investigation of the release. 2011 March - Site visit conducted with the City of San Jose and their Consultant. May - Workplan for SWI submitted and approved. Due date for report in August 2011. July - SWI submitted. Stop work pending closure review letter issued.

LUST:

Global Id: T0608501998

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

LUST:

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 05/03/2006

 Action:
 Notice of Violation

 Global Id:
 T0608501998

 Action Type:
 Other

 Date:
 07/01/1993

 Action:
 Leak Reported

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 02/25/1999

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 01/30/2005

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 06/25/1997

 Action:
 Unknown

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 01/01/1989

Direction Distance

Elevation Site Database(s) EPA ID Number

COMERICA BANK BUILDING (Continued)

S103881007

EDR ID Number

Action: Correspondence

Global Id: T0608501998
Action Type: RESPONSE
Date: 05/01/1986

Action: Other Report / Document

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 07/27/2011

 Action:
 Staff Letter

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 09/01/2011

Action: Closure/No Further Action Letter

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 10/27/2010

 Action:
 Staff Letter

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 03/25/2011

Action: Site Visit / Inspection / Sampling

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 05/16/2011

 Action:
 Staff Letter

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 07/01/2009

 Action:
 Staff Letter

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 07/25/2011

Action: Soil and Water Investigation Report

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 03/17/1989

Action: Unauthorized Release Form

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 05/10/2011

 Action:
 Other Workplan

Direction Distance

Elevation Site Database(s) EPA ID Number

COMERICA BANK BUILDING (Continued)

S103881007

EDR ID Number

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 07/03/2006

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608501998

 Action Type:
 Other

 Date:
 06/30/1993

 Action:
 Leak Discovery

Global Id: T0608501998
Action Type: RESPONSE
Date: 07/01/2009

Action: Soil and Water Investigation Workplan

Global Id: T0608501998
Action Type: ENFORCEMENT
Date: 06/25/1997

Action: Notice of Responsibility - #7991526

Global Id: T0608501998
Action Type: RESPONSE
Date: 08/20/2011

Action: Soil and Water Investigation Report

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 10/21/2004

Action: Staff Letter - #46242

 Global Id:
 T0608501998

 Action Type:
 Other

 Date:
 06/30/1993

 Action:
 Leak Stopped

 Global Id:
 T0608501998

 Action Type:
 RESPONSE

 Date:
 10/27/2010

Action: Soil and Water Investigation Workplan - Regulator Responded

 Global Id:
 T0608501998

 Action Type:
 ENFORCEMENT

 Date:
 12/18/1998

Action: Staff Letter - #26859

LUST:

Global Id: T0608501998

Status: Completed - Case Closed

Status Date: 09/01/2011

Global Id: T0608501998

Status: Open - Case Begin Date

Direction Distance

Elevation Site Database(s) EPA ID Number

COMERICA BANK BUILDING (Continued)

S103881007

EDR ID Number

Status Date: 06/30/1993

Global Id: T0608501998

Status: Open - Site Assessment

Status Date: 06/30/1993

LUST REG 2:

Region: 2

Facility Id: Not reported

Facility Status: Preliminary site assessment underway

Case Number: 07S1E07R03f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 6/30/1993
Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07R03F

 Date Closed:
 09/01/2011

 EDR Link ID:
 07S1E07R03F

HIST LUST SANTA CLARA:

Region: SANTA CLARA
Region Code: 2
SCVWD ID: 07S1E07R03
Oversite Agency: SCCDEH

Date Listed: 1997-05-30 00:00:00

Closed Date: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.333985

 Longitude:
 -121.895933

 Record ID:
 PR0397466

 Facility ID:
 FA0700792

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 600793

Class: Auto Wrecking/Misc Simple Facility

CERS TANKS:

Site ID: 237846

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COMERICA BANK BUILDING (Continued)

S103881007

CERS ID: T0608501998

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

AA173 LUST S104541892 **SAN JOSE ARENA (RITCHEY)** SSE **60 N MONTGOMERY ST HIST LUST** N/A

1/4-1/2 SAN JOSE, CA

0.334 mi.

1764 ft. Site 2 of 5 in cluster AA Relative: LUST SANTA CLARA:

Higher Region: SANTA CLARA SCVWD ID: 07S1E07Q13F Actual: Date Closed: 04/09/1997 92 ft. EDR Link ID: 07S1E07Q13F

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E07Q13 Oversite Agency: SFRWQCB

1990-01-01 00:00:00 Date Listed: 1997-04-09 00:00:00 Closed Date:

174 **CALTRAIN SOUTH TERMINAL IMPROVEMENTS** CPS-SLIC S112847304

South **65 CAHILL ST BROWNFIELDS** N/A 1/4-1/2 SAN JOSE, CA 95110 **CHMIRS**

0.334 mi. **EMI** 1766 ft. **HAZNET CIWQS** Relative: **CERS**

Higher

CPS-SLIC: Actual: Region: STATE 96 ft.

Facility Status: **Open - Verification Monitoring**

Status Date: 06/11/2018 Global Id: SL0608582748

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported Latitude: 37.3303788756706 Longitude: -121.9020652771 Case Type: Cleanup Program Site

Case Worker: СН

Local Agency: Not reported **RB Case Number:** 43S1111

Map ID MAP FINDINGS Direction

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

Regional Board

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

File Location:

Potential Media Affected: Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating, Diesel

Site History:

Other Groundwater (uses other than drinking water)

The Peninsula Corridor Joint Powers Board, owner and operator of the

Caltrain commuter rail system, plans to make improvements to the existing Diridon Station located at 65 Cahill Street in San Jose. The site is currently used for commercial purposes and is located within a commercial/industrial area of San Jose. The site use will remain the Diridon Station. The project includes demolition of the maintenance facilities and constructing two new platforms at the station immediately to the west and outside of the historic platforms, along with new tracks, platform canopies, and station amenities. The site is currently a passenger train depot and maintenance yard. There are currently seven tracks used for storage and maintenance activities. According to site personnel and historical reviews, railroad operations at the site have remained generally constant since approximately the 1880's. However, the onsite maintenance facilities, including the inspection pits, the train shed, and the water collection and treatment systems were not constructed until the mid 1990's. Soil analytical results indicate TPH diesel-range detections above the ESL of 100 mg/kg in five of 36 samples analyzed at concentrations ranging from 850 to 14,000 mg/kg and TPH motor oil-range detections above the ESL of 500 mg/kg in 12 samples of 36 analyzed at concentrations ranging from 950 to 12,000 mg/kg. Arsenic was detected at levels above the ESL of 0.38 mg/kg in 22 samples ranging from 1.3 to 48 mg/kg; however, 21 of the 22 detections were at concentrations between 1.3 to 7.9 mg/kg, which are similar to documented regional arsenic background concentrations and below the arsenic action level of 8 mg/kg established in the SMP. Ground water analytical results indicate TPH diesel-range detections in 2 samples above the ESL of 100 a%g/L ranging from 18,000 to 170,000 a%g/L and one TPH motor oil-range detection of 17,000 a%g/L above the ESL of 100 a%g/L. MTBE was detected at 6.9 a%g/L in one sample, above the ESL of 2.3 a%g/L. The Phase I ESA identified a number of leaking underground storage tank sites potentially upgradient of the Diridon Station and the MTBE detection is most likely related to one of these adjacent sites. Dissolved lead was detected at a concentration of 21 a%g/L in one sample which is above the MCL of 2.5 a%g/L. The site is located approximately 0.15 mile west of Los Gatos Creek and 0.3 mile west of Guadalupe River. The site is not within the 100-year flood plain and wetlands are not present on the site.

Click here to access the California GeoTracker records for this facility:

BROWNFIELDS:

Global ID: SL0608582748 37.330378876 Latitude: Longitude: -121.90206528 Project Type: Cleanup Program Site Open - Verification Monitoring Status:

Status Date: 06/11/2018

SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency:

07/05/2018 Last Correspondence Date:

Release Type: Other Type of Release

Contaminant(s) of Concern: Waste Oil / Motor / Hydraulic / Lubricating, Diesel Media of Concern: Other Groundwater (uses other than drinking water) Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

EDR ID Number

Past Use(s) that Caused Contamination: FUEL - VEHICLE STORAGE/ REFUELING, RAIL ROAD MAINTENANCE SHOP

Human Health Exposure Controlled: YES
Human Health Exposure Controlled Date: 05/14/2009
Groundwater Migration Controlled: YES
Groundwater Migration Controlled Date: 05/14/2009

Primary Caseworker Name: CELINA HERNANDEZ

Primary Caseworker Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Primary Caseworker Phone Number: 510-622-2447

Primary Caseworker Address: 1515 CLAY STREET, SUITE 1400

Primary Caseworker Address: OAKLAND Primary Caseworker Address: CA

Primary Caseworker Email: celina.hernandez@waterboards.ca.gov

CHMIRS:

OES Incident Number: 18-1946 OES notification: 03/24/2018 OES Date: Not reported **OES Time:** Not reported **Date Completed:** Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported **Estimated Temperature:** Not reported **Property Management:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities: Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA DOT PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Facility Telephone: Not reported Waterway Involved: Yes Storm Drain Waterway: Spill Site: Other Cleanup By: Contractor Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported **PETROLEUM** Type: Measure: Qt.(s) Not reported Other: Date/Time: 1424 Year: 2018

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

Agency: Santa Clara Valley Transportation Authority

Incident Date: 03/24/2018

Admin Agency: Santa Clara County Department of Environmental Health

Amount: Not reported Contained: Yes Site Type: Storm Drain Not reported E Date: Diesel Substance: Quantity Released:

Unknown: Not reported Substance #2: Not reported Not reported Substance #3: Not reported Evacuations: Number of Injuries: Not reported Number of Fatalities: Not reported

#1 Pipeline: No #2 Pipeline: No #3 Pipeline: No #1 Vessel >= 300 Tons: No #2 Vessel >= 300 Tons: No #3 Vessel >= 300 Tons: No Evacs: No Injuries: No Fatals: No

Comments: Not reported

Description: A break in the fuel oil line on a bus caused the

release.

EMI:

2012 Year: County Code: 43 Air Basin: SF 21319 Facility ID: Air District Name: BA SIC Code: 4111

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0 Reactive Organic Gases Tons/Yr: 0 Carbon Monoxide Emissions Tons/Yr: 0.002 NOX - Oxides of Nitrogen Tons/Yr: 0.026 SOX - Oxides of Sulphur Tons/Yr:

Particulate Matter Tons/Yr: 0.0020491803279

Part. Matter 10 Micrometers and Smllr Tons/Yr:0.002

Year: 2013 County Code: 43 SF Air Basin: Facility ID: 21319 Air District Name: BA SIC Code: 4111

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 0 Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

EDR ID Number

Carbon Monoxide Emissions Tons/Yr: 0.002
NOX - Oxides of Nitrogen Tons/Yr: 0.026
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:0.002

 Year:
 2014

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 21319

 Air District Name:
 BA

 SIC Code:
 4111

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

Total Organic Hydrocarbon Gases Tons/Yr:

BAY AREA AQMD

Not reported

Not reported

4.9644e-005

Reactive Organic Gases Tons/Yr: 0

Carbon Monoxide Emissions Tons/Yr: 0.000175484

NOX - Oxides of Nitrogen Tons/Yr: 0.004384579

SOX - Oxides of Sulphur Tons/Yr: 8.156e-006

Particulate Matter Tons/Yr: 0.000194166

Part. Matter 10 Micrometers and Smllr Tons/Yr:0.0001864

 Year:
 2015

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 21319

 Air District Name:
 BA

 SIC Code:
 4111

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 4.9644e-005 Reactive Organic Gases Tons/Yr: 3.2918e-005 Carbon Monoxide Emissions Tons/Yr: 0.000175484 NOX - Oxides of Nitrogen Tons/Yr: 0.004384579 SOX - Oxides of Sulphur Tons/Yr: 8.156e-006 Particulate Matter Tons/Yr: 0.000194166 Part. Matter 10 Micrometers and Smllr Tons/Yr:0.0001864

 Year:
 2016

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 21319

 Air District Name:
 BA

 SIC Code:
 4111

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 5.2953e-005 Reactive Organic Gases Tons/Yr: 4.65192105e-005 Carbon Monoxide Emissions Tons/Yr: 0.000187182 NOX - Oxides of Nitrogen Tons/Yr: 0.004676883 SOX - Oxides of Sulphur Tons/Yr: 8.7e-006 Particulate Matter Tons/Yr: 0.000207111 Part. Matter 10 Micrometers and Smllr Tons/Yr:0.000198827

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

HAZNET:

envid: S112847304 Year: 2013

GEPAID: CAC002753877 Contact: JEFFREY WHITE Telephone: 5108736151 Mailing Name: Not reported Mailing Address: 530 WATER ST

Mailing City, St, Zip: OAKLAND, CA 946073524

Gen County: Santa Clara TSD EPA ID: CAD982042475 TSD County: Solano Waste Category: Not reported

Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill (To

Include On-Site Treatment And/Or Stabilization)

Tons:

Cat Decode: Not reported Method Decode: Not reported Facility County: Not reported

S112847304 envid: Year: 2013

GEPAID: CAC002753877 JEFFREY WHITE Contact: Telephone: 5108736151 Mailing Name: Not reported Mailing Address: 530 WATER ST

Mailing City, St, Zip: OAKLAND, CA 946073524

Gen County: Santa Clara CAT080013352 TSD EPA ID: TSD County: Los Angeles Waste Category: Not reported

Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration,

Organics Recovery Ect

6.05484 Tons: Not reported Cat Decode: Not reported Method Decode: Facility County: Not reported

S112847304 envid: Year: 1993

GEPAID: CAC000840208 Contact: **CAL-TRANS** Telephone: 000000000 Mailing Name: Not reported Mailing Address: PO BOX 23660

Mailing City, St, Zip: OAKLAND, CA 946230660

Gen County: Not reported CAD982042475 TSD EPA ID: TSD County: Not reported

Waste Category: Asbestos containing waste Disposal Method: Disposal, Land Fill

42.1400000000 Tons: Cat Decode: Not reported Method Decode: Not reported

Facility County:

Direction Distance

Elevation Site Database(s) EPA ID Number

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

EDR ID Number

envid: \$112847304 Year: 1993

GEPAID: CAC000840208
Contact: CAL-TRANS
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: PO BOX 23660

Mailing City, St, Zip: OAKLAND, CA 946230660

Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported

Waste Category: Asbestos containing waste

Disposal Method: Not reported
Tons: 0.2107
Cat Decode: Not reported
Method Decode: Not reported

Facility County: 99

envid: S112847304

Year: 1993

GEPAID: CAC000840208
Contact: CAL-TRANS
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: PO BOX 23660

Mailing City, St, Zip: OAKLAND, CA 946230660

Gen County: Not reported
TSD EPA ID: CAD982040865
TSD County: Not reported

Waste Category: Asbestos containing waste

Disposal Method: Not reported
Tons: 5.0568
Cat Decode: Not reported
Method Decode: Not reported

Facility County: 99

Click this hyperlink while viewing on your computer to access 1 additional CA_HAZNET: record(s) in the EDR Site Report.

CIWQS:

Agency: Peninsula Corridor Joint Powers Board
Agency Address: 4000 Campbell Ave, Menlo Park, CA 94070

Place/Project Type: Construction - Transportation

SIC/NAICS: Not reported

Region: 2 Program: CO

Program: CONSTW
Regulatory Measure Status: Terminated

Regulatory Measure Type: Storm water construction

Order Number: 2009-0009-DWQ WDID: 2 43C357840 NPDES Number: CAS000002 Adoption Date: Not reported Effective Date: 04/08/2010 Termination Date: 08/24/2012 Expiration/Review Date: Not reported Design Flow: Not reported Major/Minor: Not reported

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

CALTRAIN SOUTH TERMINAL IMPROVEMENTS (Continued)

S112847304

Complexity: Not reported TTWQ: Not reported

Enforcement Actions within 5 years: 0
Violations within 5 years: 0
Latitude: 37.33
Longitude: -121.902778

CERS TANKS:

 Site ID:
 212247

 CERS ID:
 SL0608582748

 CERS Description:
 Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: CELINA HERNANDEZ - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 Clay Street, suite 1400

Affiliation City: OAKLAND

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 5106222447

AC175 VITALE AUTO BODY LUST S102440967 SSE 52 AUTUMN HIST CORTESE N/A

SSE 52 AUTUMN HIST CORTESE N/A
1/4-1/2 SAN JOSE, CA 95110 CERS

0.334 mi.

1766 ft. Site 1 of 4 in cluster AC

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

93 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501566

Global Id: T0608501566
Latitude: 37.329914
Longitude: -121.899085

Status: Completed - Case Closed

 Status Date:
 07/19/1991

 Case Worker:
 UUU

 RB Case Number:
 43-1611

Local Agency: SANTA CLARA COUNTY LOP

File Location:

Local Case Number:

Potential Media Affect:

Not reported

Not reported

Under Investigation

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608501566

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VITALE AUTO BODY (Continued)

S102440967

Global Id: T0608501566

Local Agency Caseworker Contact Type: Contact Name: UST CASE WORKER Organization Name: SANTA CLARA COUNTY LOP 1555 Berger Drive, Suite 300 Address:

City: SAN JOSE Email: Not reported Phone Number: 4089183400

LUST:

Global Id: T0608501566 Action Type: Other Date: 07/09/1990 Action: Leak Reported

Global Id: T0608501566 Action Type: Other Date: 07/09/1990 Action: Leak Discovery

Global Id: T0608501566 Action Type: Other Date: 07/09/1990 Action: Leak Stopped

LUST:

Global Id: T0608501566

Status: Completed - Case Closed

07/19/1991 Status Date:

Global Id: T0608501566

Status: Open - Case Begin Date

Status Date: 07/09/1990

LUST REG 2:

Region: Facility Id: 43-1611 Facility Status: Case Closed Case Number: 43-1611 How Discovered: Tank Closure Leak Cause: Structure Failure

Leak Source: Tank Date Leak Confirmed: Not reported LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:

Region: CORTESE Facility County Code: 43

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VITALE AUTO BODY (Continued)

S102440967

Reg By: **LTNKA** 43-1611 Reg Id:

CERS TANKS:

Site ID: 220684 CERS ID: T0608501566

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State:

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

AC176 **VITALE BODY SHOP** SSE **52 S AUTUMN ST SAN JOSE, CA 95110** 1/4-1/2

LUST **HIST LUST** N/A

S103881054

0.334 mi.

1766 ft. Site 2 of 4 in cluster AC

LUST REG 2: Relative: Higher

Region: 2 Facility Id: Actual:

Not reported Facility Status: Case Closed 93 ft. Case Number: 07S1E18B02f How Discovered: Not reported Leak Cause: Not reported

Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 4/17/1990 Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E18B02

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

VITALE BODY SHOP (Continued) S103881054

Oversite Agency: SCVWD

Date Listed: 1990-08-06 00:00:00 Closed Date: 1991-07-26 00:00:00

AC177 VITALE BODY SHOP LUST S103950858
SSE 52 S AUTUMN ST CERS N/A

1/4-1/2 SAN JOSE, CA 95110

0.334 mi.

1766 ft. Site 3 of 4 in cluster AC

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

93 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608595685

 Global Id:
 T0608595685

 Latitude:
 37.3306262758922

 Longitude:
 -121.899763941765

 Status:
 Completed - Case Closed

Status Date: 07/26/1991
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608595685

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608595685

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER

Organization Name: SANTA CLARA COUNTY LOP Address: SANTA CLARA COUNTY LOP 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608595685

 Action Type:
 Other

 Date:
 07/09/1990

 Action:
 Leak Reported

 Global Id:
 T0608595685

 Action Type:
 REMEDIATION

 Date:
 07/09/1990

 Action:
 Excavation

Direction Distance

Elevation Site Database(s) EPA ID Number

VITALE BODY SHOP (Continued)

S103950858

EDR ID Number

 Global Id:
 T0608595685

 Action Type:
 REMEDIATION

 Date:
 07/09/1990

 Action:
 Excavation

 Global Id:
 T0608595685

 Action Type:
 ENFORCEMENT

 Date:
 07/26/1991

Action: Closure/No Further Action Letter

Global Id: T0608595685
Action Type: ENFORCEMENT
Date: 06/27/1991

Action: Notice of Responsibility - #39845

 Global Id:
 T0608595685

 Action Type:
 RESPONSE

 Date:
 07/09/1990

Action: Other Report / Document

LUST:

Global Id: T0608595685

Status: Completed - Case Closed

Status Date: 07/26/1991

Global Id: T0608595685

Status: Open - Case Begin Date

Status Date: 04/17/1990

Global Id: T0608595685

Status: Open - Site Assessment

Status Date: 04/17/1990

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E18B02F

 Date Closed:
 07/26/1991

 EDR Link ID:
 07S1E18B02F

CERS TANKS:

Site ID: 226485 CERS ID: T0608595685

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VITALE BODY SHOP (Continued) S103950858

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

OAKLAND Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

AA178 MARIAN JOHNSON CPS-SLIC S101641791

SSE 59 SUTUM ST S N/A

1/4-1/2 SAN JOSE, CA 95113

0.346 mi.

Site 3 of 5 in cluster AA 1826 ft.

Relative: SLIC REG 2: Higher Region:

Facility ID: 43S0447 Actual:

Facility Status: Leak being confirmed 91 ft.

Date Closed: Not reported Local Case #: Not reported How Discovered: Tank Closure Leak Cause: UNK UNK Leak Source:

Date Confirmed: 3/27/1995

Date Prelim Site Assmnt Workplan Submitted: Not reported Not reported Date Preliminary Site Assessment Began: Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

179 **CARLYSLE DEVELOPMENT** CPS-SLIC S103671546 **East**

76 NOTRE DAME DEED N/A

1/4-1/2 SAN JOSE, CA 95113 **EMI** 0.347 mi. **CERS**

1833 ft.

Relative: CPS-SLIC: Higher STATE Region:

Facility Status: **Completed - Case Closed** Actual:

Status Date: 08/28/2014 87 ft.

Global Id: T10000003326

Lead Agency: SANTA CLARA COUNTY LOP

Lead Agency Case Number: 07S1E07J02s Latitude: 37.335639 Longitude: -121.895093

Case Type: Cleanup Program Site

Case Worker: **GOR**

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database Potential Media Affected: Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern: Lead, Gasoline

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

CARLYSLE DEVELOPMENT (Continued)

S103671546

Site History: Subsurface investigations conducted prior to site redevelopment found

elevated concentrations of lead and petroleum hydrocarbons in soil and groundwater at the site. Proposed to excavate and remove impacted

soil. The project encompasses the entire city block.

Click here to access the California GeoTracker records for this facility:

DEED:

Status:

Envirostor ID: T10000003326
Area: Not reported
Sub Area: Not reported

Site Type: SLIC

COMPLETED - CASE CLOSED

Agency: SWRCB
Covenant Uploaded: Y
Deed Date(s): 07/18/2014

File Name: Geotracker Land Use/Deed Restrictions

EMI:

 Year:
 1990

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 7
Reactive Organic Gases Tons/Yr: 7
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1996

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1997 County Code: 43 Air Basin: SF

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CARLYSLE DEVELOPMENT (Continued)

S103671546

Facility ID: 6079 Air District Name: BA SIC Code: 2759

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 0 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1998 County Code: 43 Air Basin: SF Facility ID: 6079 Air District Name: ВА SIC Code: 2759

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 0 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1999 County Code: 43 Air Basin: SF 6079 Facility ID: Air District Name: BA SIC Code: 2759

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 2 Reactive Organic Gases Tons/Yr: 2 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2000 County Code: 43 Air Basin: SF Facility ID: 6079 Air District Name: BA SIC Code: 2759

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Direction
Distance
Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

CARLYSLE DEVELOPMENT (Continued)

S103671546

Total Organic Hydrocarbon Gases Tons/Yr: 2
Reactive Organic Gases Tons/Yr: 2
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2001

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 7
Reactive Organic Gases Tons/Yr: 7
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2002

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:

BAY AREA AQMD
Not reported
Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 32
Reactive Organic Gases Tons/Yr: 32
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2003

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 3
Reactive Organic Gases Tons/Yr: 3
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0

Direction Distance Elevation

Site Database(s) EPA ID Number

CARLYSLE DEVELOPMENT (Continued)

S103671546

EDR ID Number

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2004

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:

BAY AREA AQMD
Not reported
Not reported
5.22

Total Organic Hydrocarbon Gases Tons/Yr: 5.22
Reactive Organic Gases Tons/Yr: 5.22
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2005

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 3.424 Reactive Organic Gases Tons/Yr: 3.424 Carbon Monoxide Emissions Tons/Yr: n NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2006

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 3.424 Reactive Organic Gases Tons/Yr: 3.424 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2007

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

Direction Distance

Elevation Site Database(s) EPA ID Number

CARLYSLE DEVELOPMENT (Continued)

S103671546

EDR ID Number

Air District Name: BA SIC Code: 2759

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 3.872 Reactive Organic Gases Tons/Yr: 3.872 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2008

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 6079

 Air District Name:
 BA

 SIC Code:
 2759

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 3.872 Reactive Organic Gases Tons/Yr: 3.872 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

CERS TANKS:

 Site ID:
 226638

 CERS ID:
 T10000003326

 CERS Description:
 Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: Gerald O'Regan - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 BERGER DRIVE STE 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

AD180 LORENTZ & SONS SEMS-ARCHIVE 1003879372
NE 201 W JULIAN ST CAD982400004

1/4-1/2 SAN JOSE, CA 95110

0.349 mi.

1843 ft. Site 1 of 5 in cluster AD

Relative: SEMS Archive:

 Lower
 Site ID:
 0903348

 Actual:
 EPA ID:
 CAD982400004

 83 ft.
 Cong District:
 10

FIPS Code: 06085 FF: N

NPL: Not on the NPL

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Latitude: 37.331667 Longitude: -121.878333

SEMS Archive Detail:

 Region:
 09

 Site ID:
 0903348

 EPA ID:
 CAD982400004

 Site Name:
 LORENTZ & SONS

 NPL:
 N

 FF:
 N

 OU:
 00

 Action Code:
 VS

Action Name: ARCH SITE

SEQ: 1

Start Date:

Finish Date:

Qual:

Current Action Lead:

Not reported

Not reported

EPA Perf In-Hse

 Region:
 09

 Site ID:
 0903348

 EPA ID:
 CAD982400004

 Site Name:
 LORENTZ & SONS

 NPL:
 N

 FF:
 N

 OU:
 00

 Action Code:
 PA

 Action Name:
 PA

 SEQ:
 1

 Start Date:
 Not reported

 Finish Date:
 1988-09-01 04:00:00

Qual: N
Current Action Lead: St Perf

 Region:
 09

 Site ID:
 0903348

 EPA ID:
 CAD982400004

 Site Name:
 LORENTZ & SONS

 NPL:
 N

 FF:
 N

 OU:
 00

 Action Code:
 DS

 Action Name:
 DISCVRY

SEQ: 1

Start Date: 1988-03-01 05:00:00 Finish Date: 1988-03-01 05:00:00 **EDR ID Number**

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

LORENTZ & SONS (Continued) 1003879372

Qual: Not reported Current Action Lead: St Perf

STATE

 181
 NORTH SAN PEDRO APARTMENTS
 CPS-SLIC
 \$121647155

 NE
 201 BASSETT ST
 CIWQS
 N/A

1/4-1/2 SAN JOSE, CA 95110

0.349 mi. 1845 ft.

Relative: CPS-SLIC: Lower Region:

 Actual:
 Facility Status:
 Open - Active

 82 ft.
 Status Date:
 07/30/2018

 Global Id:
 T10000011850

Lead Agency: SANTA CLARA COUNTY LOP

Lead Agency Case Number: 2018-21s

 Latitude:
 37.3400353397908

 Longitude:
 -121.898242127647

 Case Type:
 Cleanup Program Site

Case Worker: AC

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media Affected: Not reported Potential Contaminants of Concern: Not reported Site History: Not reported

Click here to access the California GeoTracker records for this facility:

CIWQS:

Agency: Jefferson Smurfit Corp

Agency Address: 8182 Maryland Ave, Clayton, MO 63105
Place/Project Type: Industrial - Scrap and Waste Materials

SIC/NAICS: 5093
Region: 2
Program: INDSTW
Regulatory Measure Status: Terminated
Regulatory Measure Type: Storm water industrial

Order Number: 2014-0057-DWQ WDID: 2 431006634 NPDES Number: CAS000001 Adoption Date: Not reported Effective Date: 04/30/1992 Termination Date: 01/26/2001 Expiration/Review Date: Not reported Design Flow: Not reported Major/Minor: Not reported Complexity: Not reported TTWQ: Not reported

Enforcement Actions within 5 years: 0
Violations within 5 years: 0
Latitude: 37.34
Longitude: -121.898

Direction Distance

Elevation Site Database(s) **EPA ID Number**

182 **SCVWD PROPERTY** LUST S102436623 **ESE**

HIST CORTESE 361 SANTA CLARA ST W N/A

1/4-1/2 SAN JOSE, CA 95113 **CERS**

0.352 mi. 1857 ft.

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501653 86 ft.

Global Id: T0608501653 Latitude: 37.332856 -121.896431 Longitude:

Completed - Case Closed Status:

03/03/1997 Status Date: Case Worker: UUU RB Case Number: 43-1712

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported Potential Media Affect: **Under Investigation**

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating

Site History: Not reported

LUST:

Global Id: T0608501653

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608501653

Local Agency Caseworker Contact Type: Contact Name: **UST CASE WORKER** Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

SAN JOSE City: Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608501653 Action Type: **RESPONSE** Date: 01/21/1993

Action: Unauthorized Release Form

Global Id: T0608501653 Action Type: Other 05/11/1993 Date: Action: Leak Reported

Global Id: T0608501653 Action Type: **ENFORCEMENT** Date: 01/01/1989 Action: Other Report

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCVWD PROPERTY (Continued)

S102436623

Global Id: T0608501653 RESPONSE Action Type: Date: 01/01/1989 Action: Correspondence

Global Id: T0608501653 Action Type: **RESPONSE** Date: 08/28/1989

Action: Other Report / Document

T0608501653 Global Id: **RESPONSE** Action Type: 08/07/1989 Date:

Action: Other Report / Document

Global Id: T0608501653 **RESPONSE** Action Type: 06/03/2005 Date:

Action: Other Report / Document

Global Id: T0608501653 Action Type: Other Date: 05/11/1993 Action: Leak Discovery

Global Id: T0608501653 Action Type: **RESPONSE** Date: 09/25/1989

Action: Soil and Water Investigation Report

Global Id: T0608501653 Action Type: **RESPONSE** Date: 10/24/1989

Action: Tank Removal Report / UST Sampling Report

Global Id: T0608501653 Action Type: Other 05/11/1993 Date: Action: Leak Stopped

LUST:

Global Id: T0608501653

Status: Completed - Case Closed

03/03/1997 Status Date:

Global Id: T0608501653

Open - Case Begin Date Status:

Status Date: 05/11/1993

T0608501653 Global Id:

Status: Open - Site Assessment

Status Date: 01/31/1996

LUST REG 2:

Region: 2

Direction Distance

Elevation Site Database(s) EPA ID Number

SCVWD PROPERTY (Continued)

S102436623

EDR ID Number

Facility Id: 43-1712
Facility Status: Case Closed
Case Number: 43-1712
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: 1/31/1996
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1712

CERS TANKS:

 Site ID:
 231827

 CERS ID:
 T0608501653

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Distance EDR ID Number
Elevation Site EPA ID Number

AC183 SCV PARAMEDICS SJ AMBULANCE LUST S103472992

SSE 58 AUTUMN ST N HIST CORTESE N/A

1/4-1/2 SAN JOSE, CA 95110 CERS

0.356 mi.

1880 ft. Site 4 of 4 in cluster AC

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

92 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500140

 Global Id:
 T0608500140

 Latitude:
 37.3304129998875

 Longitude:
 -121.900005340576

 Status:
 Completed - Case Closed

 Status Date:
 04/09/1997

 Case Worker:
 UUU

 RB Case Number:
 43-0072

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Stoddard solvent / Mineral Spriits / Distillates

Site History: Not reported

LUST:

Global Id: T0608500140

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500140

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500140

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Reported

 Global Id:
 T0608500140

 Action Type:
 RESPONSE

 Date:
 01/01/1989

Action: Other Report / Document

Global Id: T0608500140
Action Type: RESPONSE
Date: 01/01/1985

Action: Other Report / Document

Direction Distance

Elevation Site Database(s) EPA ID Number

SCV PARAMEDICS SJ AMBULANCE (Continued)

S103472992

EDR ID Number

 Global Id:
 T0608500140

 Action Type:
 RESPONSE

 Date:
 01/01/1984

Action: Other Report / Document

 Global Id:
 T0608500140

 Action Type:
 ENFORCEMENT

 Date:
 04/09/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608500140

 Action Type:
 RESPONSE

 Date:
 01/01/1997

Action: Other Report / Document

 Global Id:
 T0608500140

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Discovery

 Global Id:
 T0608500140

 Action Type:
 Other

 Date:
 03/28/1989

 Action:
 Leak Stopped

LUST:

Global Id: T0608500140

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608500140

Status: Open - Case Begin Date

Status Date: 03/28/1989

Global Id: T0608500140

Status: Open - Site Assessment

Status Date: 02/07/1990

Global Id: T0608500140

Status: Open - Site Assessment

Status Date: 04/19/1995

LUST REG 2:

Region: 2

Facility Id: 43-0072
Facility Status: Case Closed
Case Number: 07S1E07Q02
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: 2/7/1990
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 4/19/1995
Pollution Characterization Began: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCV PARAMEDICS SJ AMBULANCE (Continued)

S103472992

Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:

CORTESE Region: Facility County Code: 43 LTNKA Reg By: Reg Id: 43-0072

CERS TANKS:

Site ID: 252595 CERS ID: T0608500140

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA Affiliation Country: Not reported

Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300 Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

PG&E SAN JOSE SEMS-ARCHIVE 1003879008 **AE184** WNW **650 LENZEN AVE** CAD981671886

1/4-1/2 **SAN JOSE, CA 95126**

0.359 mi.

1898 ft. Site 1 of 5 in cluster AE

SEMS Archive: Relative:

Higher Site ID: 0902491 EPA ID: CAD981671886 Actual:

86 ft. Cong District: 10 FIPS Code:

06085 FF:

NPL: Not on the NPL

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Latitude: 37.328333 Longitude: -121.911667

SEMS Archive Detail:

Region: 09 Site ID: 0902491 EPA ID: CAD981671886

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E SAN JOSE (Continued)

Site Name: **PG&E SAN JOSE**

NPL: Ν FF: Ν OU: 00 Action Code: ٧S

ARCH SITE Action Name:

SEQ:

Start Date: Not reported Finish Date: 1987-02-01 05:00:00 Qual: Not reported Current Action Lead: EPA Perf In-Hse

Region: 09 Site ID: 0902491 CAD981671886 EPA ID: Site Name: **PG&E SAN JOSE**

NPL: Ν FF: Ν OU: 00 Action Code: PΑ РΑ Action Name: SEQ:

Start Date: 1987-02-01 05:00:00

Finish Date: 1987-02-01 05:00:00

Qual: Ν

Current Action Lead: **EPA Perf**

Region: 09 Site ID: 0902491 CAD981671886 EPA ID: Site Name: PG&E SAN JOSE

NPL: Ν FF: Ν OU: 00 Action Code: DS Action Name: **DISCVRY**

SEQ:

Start Date: 1987-01-01 05:00:00 1987-01-01 05:00:00 Finish Date: Qual: Not reported

Current Action Lead: Other

AA185 SAN JOSE ARENA JULIAN ST LUST S106163380 70-90 MONTGOMERY N **CERS** N/A

SSE 1/4-1/2 SAN JOSE, CA 95110

0.362 mi.

1910 ft. Site 4 of 5 in cluster AA

Relative: LUST:

Higher SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608502031 93 ft.

Global Id: T0608502031 Latitude: 37.3319366 -121.9012449 Longitude:

Status: Completed - Case Closed

Status Date: 04/09/1997 1003879008

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE ARENA JULIAN ST (Continued)

S106163380

EDR ID Number

Case Worker: UUU RB Case Number: 43-2213

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:

Global Id: T0608502031

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608502031

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP

Address: SANTA CLARA COUNTY LOP

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608502031

 Action Type:
 Other

 Date:
 02/02/1998

 Action:
 Leak Reported

Global Id: T0608502031
Action Type: RESPONSE
Date: 01/01/1993

Action: Other Report / Document

 Global Id:
 T0608502031

 Action Type:
 ENFORCEMENT

 Date:
 04/09/1997

Action: Closure/No Further Action Letter

 Global Id:
 T0608502031

 Action Type:
 RESPONSE

 Date:
 01/01/1989

 Action:
 Correspondence

 Global Id:
 T0608502031

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

 Global Id:
 T0608502031

 Action Type:
 RESPONSE

 Date:
 03/16/1993

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

SAN JOSE ARENA JULIAN ST (Continued)

S106163380

Action: Other Report / Document

 Global Id:
 T0608502031

 Action Type:
 Other

 Date:
 02/02/1996

 Action:
 Leak Discovery

 Global Id:
 T0608502031

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608502031

 Action Type:
 RESPONSE

 Date:
 09/22/1989

Action: Unauthorized Release Form

 Global Id:
 T0608502031

 Action Type:
 Other

 Date:
 02/02/1996

 Action:
 Leak Stopped

LUST:

Global Id: T0608502031

Status: Completed - Case Closed

Status Date: 04/09/1997

Global Id: T0608502031

Status: Open - Case Begin Date

Status Date: 02/02/1996

LUST REG 2:

Region: 2
Facility Id: 43-2213
Facility Status: Case Closed
Case Number: 07S1E07K05
How Discovered: Tank Closure
Leak Cause: UNK
Leak Source: UNK

Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Not reported
Not reported
Not reported
Post Remedial Action Monitoring Began:
Not reported

CERS TANKS:

Site ID: 198788 CERS ID: T0608502031

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA JULIAN ST (Continued)

S106163380

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State:

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

AA186 AUTOMATIC CAR WASH LUST U001602464 South 77 S MONTGOMERY ST **HIST LUST** N/A **HIST UST** 1/4-1/2 SAN JOSE, CA 95110

0.362 mi.

HIST CORTESE CERS 1913 ft. Site 5 of 5 in cluster AA

Relative: LUST:

SANTA CLARA COUNTY LOP Higher Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500198 93 ft.

Global Id: T0608500198 37.3296556557036 Latitude: Longitude: -121.901523320446 Completed - Case Closed Status:

11/02/1995 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500198

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

1515 CLAY ST SUITE 1400 Address:

City: OAKLAND Email: Not reported Phone Number: Not reported

Global Id: T0608500198

Contact Type: Local Agency Caseworker UST CASE WORKER Contact Name: Organization Name: SANTA CLARA COUNTY LOP

Direction Distance

Elevation Site Database(s) EPA ID Number

AUTOMATIC CAR WASH (Continued)

U001602464

EDR ID Number

Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500198

 Action Type:
 RESPONSE

 Date:
 01/05/1995

Action: Other Report / Document

 Global Id:
 T0608500198

 Action Type:
 Other

 Date:
 11/01/1989

 Action:
 Leak Reported

 Global Id:
 T0608500198

 Action Type:
 ENFORCEMENT

 Date:
 03/23/1992

Action: Notice of Responsibility - #39846

Global Id: T0608500198
Action Type: ENFORCEMENT
Date: 11/02/1995

Action: Closure/No Further Action Letter

 Global Id:
 T0608500198

 Action Type:
 REMEDIATION

 Date:
 11/15/1991

 Action:
 Excavation

LUST:

Global Id: T0608500198

Status: Completed - Case Closed

Status Date: 11/02/1995

Global Id: T0608500198

Status: Open - Case Begin Date

Status Date: 11/01/1989

Global Id: T0608500198

Status: Open - Site Assessment

Status Date: 04/25/1990

Global Id: T0608500198

Status: Open - Site Assessment

Status Date: 02/24/1994

LUST REG 2:

Region: 2

Facility Id: Not reported
Facility Status: Case Closed
Case Number: 07S1E18B03f
How Discovered: Not reported
Leak Cause: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

AUTOMATIC CAR WASH (Continued)

U001602464

EDR ID Number

Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 4/25/1990 Pollution Characterization Began: 2/24/1994 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E18B03F

 Date Closed:
 11/02/1995

 EDR Link ID:
 07S1E18B03F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E18B03 Oversite Agency: SCVWD

Date Listed: 1990-10-26 00:00:00 Closed Date: 1995-11-02 00:00:00

HIST UST:

File Number: 000206ED

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000206ED.pdf

Region: STATE
Facility ID: 00000028560
Facility Type: Gas Station
Other Type: Not reported

Contact Name: WILLIAM PALAZZOLA

Telephone: 4082937685

Owner Name: PAULINE GUGLIELMETTI
Owner Address: 812 SO. MONROE ST.
Owner City, St, Zip: SAN JOSE, CA 95008

Total Tanks: 0006

Tank Num: 001 #005 Container Num: Year Installed: 1950 Tank Capacity: 00000000 Tank Used for: WASTE Not reported Type of Fuel: Container Construction Thickness: Not reported Leak Detection: Visual

Tank Num: 002
Container Num: #001
Year Installed: 1980
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported

Leak Detection: Visual, Stock Inventor

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

AUTOMATIC CAR WASH (Continued)

U001602464

Tank Num: 003 Container Num: #002 Year Installed: 1980 Tank Capacity: 00010000 Tank Used for: **PRODUCT** Type of Fuel: **UNLEADED** Container Construction Thickness: Not reported

Visual, Stock Inventor Leak Detection:

Tank Num: 004 Container Num: #003 Year Installed: 1950 Tank Capacity: 00002000 Tank Used for: **PRODUCT** Type of Fuel: **REGULAR** Container Construction Thickness: Not reported Leak Detection: None

Tank Num: 005 #004 Container Num: Year Installed: 1950 Tank Capacity: 00002000 Tank Used for: **PRODUCT** Type of Fuel: PREMIUM Container Construction Thickness: Not reported

Leak Detection: None

Tank Num: 006 Container Num: #006 Year Installed: 1950 Tank Capacity: 00002000 Tank Used for: **PRODUCT** Type of Fuel:

Container Construction Thickness: Not reported Leak Detection: None

Click here for Geo Tracker PDF:

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-0131

CERS TANKS:

Site ID: 208973 CERS ID: T0608500198

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) Entity Name:

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

AUTOMATIC CAR WASH (Continued)

U001602464

Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

AF187 1-2-3 POOL SERVICE LUST \$102423372

1913 ft. Site 1 of 2 in cluster AF

Relative: LUST:

Lower Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

74 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501855

Global Id: T0608501855
Latitude: 37.340942
Longitude: -121.902423

Status: Completed - Case Closed

Status Date: 03/02/1995 Case Worker: UST

RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Not reported Site History: Not reported

LUST:

Global Id: T0608501855

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501855

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

Direction Distance Elevation

nce EDR ID Number ttion Site Database(s) EPA ID Number

1-2-3 POOL SERVICE (Continued)

S102423372

LUST:

Global Id: T0608501855
Action Type: RESPONSE
Date: 01/01/1987

Action: Other Report / Document

 Global Id:
 T0608501855

 Action Type:
 RESPONSE

 Date:
 01/01/1987

Action: Other Report / Document

 Global Id:
 T0608501855

 Action Type:
 RESPONSE

 Date:
 01/01/1987

Action: Other Report / Document

Global Id: T0608501855
Action Type: RESPONSE
Date: 01/01/1987

Action: Other Report / Document

 Global Id:
 T0608501855

 Action Type:
 RESPONSE

 Date:
 01/01/1987

Action: Other Report / Document

Global Id: T0608501855
Action Type: RESPONSE
Date: 01/01/1987

Action: Other Report / Document

Global Id: T0608501855
Action Type: RESPONSE
Date: 01/01/1987

Action: Other Report / Document

Global Id: T0608501855
Action Type: RESPONSE
Date: 01/01/1987

Action: Other Report / Document

Global Id: T0608501855
Action Type: RESPONSE
Date: 01/01/1987

Action: Other Report / Document

 Global Id:
 T0608501855

 Action Type:
 RESPONSE

 Date:
 01/01/1987

Action: Other Report / Document

 Global Id:
 T0608501855

 Action Type:
 RESPONSE

 Date:
 01/01/1987

Action: Other Report / Document

Global Id: T0608501855

Direction Distance Elevation

evation Site Database(s) EPA ID Number

1-2-3 POOL SERVICE (Continued)

S102423372

EDR ID Number

Action Type: Other
Date: 01/01/1993
Action: Leak Reported

 Global Id:
 T0608501855

 Action Type:
 ENFORCEMENT

 Date:
 03/02/1995

Action: Closure/No Further Action Letter

LUST:

Global Id: T0608501855

Status: Completed - Case Closed

Status Date: 03/02/1995

Global Id: T0608501855

Status: Open - Case Begin Date

Status Date: 01/01/1993

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed 07S1E07G02f Case Number: Not reported How Discovered: Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07\$1E07G02F

 Date Closed:
 03/02/1995

 EDR Link ID:
 07\$1E07G02F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2 SCVWD ID: 07

SCVWD ID: 07S1E07G02 Oversite Agency: SCVWD

Date Listed: 1994-07-21 00:00:00 Closed Date: 1995-03-02 00:00:00

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-2013

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

1-2-3 POOL SERVICE (Continued)

S102423372

S103473049

LUST

CERS TANKS:

Site ID: 230115 T0608501855 CERS ID:

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) Entity Name:

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

SOUTHERN PACIFIC TRANS. **AE188** WNW

595 LENZEN AVE HIST LUST N/A **SAN JOSE, CA 95126**

1/4-1/2 0.363 mi.

1916 ft. Site 2 of 5 in cluster AE

LUST REG 2: Relative:

Higher Region: 2

Facility Id: Not reported Actual: 85 ft. Facility Status: Case Closed Case Number: 07S1E07F03f How Discovered: Not reported Not reported Leak Cause: Leak Source: Not reported

Date Leak Confirmed:

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 9/20/1990 Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07F03 Oversite Agency: SCVWD

Date Listed: 1990-01-01 00:00:00 1992-02-11 00:00:00 Closed Date:

Direction Distance

Elevation Site Database(s) **EPA ID Number**

AE189 SOUTHERN PACIFIC TRANS CO LUST S102437868

WNW **595 LENZEN HAZNET** N/A

1/4-1/2 SAN JOSE, CA 95126 **HIST CORTESE** 0.363 mi. **CERS**

1916 ft. Site 3 of 5 in cluster AE

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501340 85 ft.

Global Id: T0608501340 Latitude: 37.338551182941 -121.908910274506 Longitude: Completed - Case Closed Status:

02/11/1992 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608501340

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608501340

Local Agency Caseworker Contact Type: Contact Name: **UST CASE WORKER** Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608501340 Action Type: Other Date: 04/18/1989 Action: Leak Reported

Global Id: T0608501340 Action Type: **ENFORCEMENT** 02/11/1992 Date:

Action: Closure/No Further Action Letter

Global Id: T0608501340 Action Type: **ENFORCEMENT** Date: 04/04/1990

Action: Notice of Responsibility - #39940 **EDR ID Number**

Direction Distance

Elevation Site Database(s) EPA ID Number

SOUTHERN PACIFIC TRANS CO (Continued)

S102437868

EDR ID Number

 Global Id:
 T0608501340

 Action Type:
 REMEDIATION

 Date:
 04/18/1989

 Action:
 Excavation

 Global Id:
 T0608501340

 Action Type:
 RESPONSE

 Date:
 07/29/1992

Action: Other Report / Document

LUST:

Global Id: T0608501340

Status: Completed - Case Closed

Status Date: 02/11/1992

Global Id: T0608501340

Status: Open - Case Begin Date

Status Date: 04/18/1989

Global Id: T0608501340

Status: Open - Site Assessment

Status Date: 09/20/1990

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07F03F

 Date Closed:
 02/11/1992

 EDR Link ID:
 07S1E07F03F

HAZNET:

envid: \$102437868 Year: 2016 GEPAID: CAC002857772 Contact: LAUREN MANCUSO

Telephone: 5102683025 Mailing Name: Not reported

Mailing Address: 2401 E, SEPULVEDA BLVD.
Mailing City,St,Zip: LONG BEACH, CA 90810

Gen County: Santa Clara
TSD EPA ID: CAT080013352
TSD County: Los Angeles

Waste Category: Unspecified oil-containing waste

Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration,

Organics Recovery Ect

Tons: 0.10425
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$102437868 Year: 2015

GEPAID: CAC002827162 Contact: LAUREN MANCUSO

Telephone: 9167895184 Mailing Name: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SOUTHERN PACIFIC TRANS CO (Continued)

S102437868

EDR ID Number

Mailing Address: 2401 E, SEPULVEDA BLVD.
Mailing City, St, Zip: LONG BEACH, CA 90810

Gen County: Santa Clara
TSD EPA ID: CAT080013352
TSD County: Los Angeles

Waste Category: Waste oil and mixed oil

Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration,

Organics Recovery Ect

Tons: 0.019
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$102437868 Year: 2015

GEPAID: CAC002841814
Contact: ANNE THERIAULT
Telephone: 5624907013
Mailing Name: Not reported

Mailing Address: 2401 E, SEPULVEDA BLVD.
Mailing City,St,Zip: LONG BEACH, CA 90810

Gen County: Santa Clara
TSD EPA ID: CAT080013352
TSD County: Los Angeles

Waste Category: Unspecified oil-containing waste

Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration,

Organics Recovery Ect

Tons: 0.10425
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1364

CERS TANKS:

Site ID: 193334 CERS ID: T0608501340

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SOUTHERN PACIFIC TRANS CO (Continued)

S102437868

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Not reported Affiliation Phone:

CPS-SLIC S106235055 AG190 **COLLEGE PARK YARD - UP** N/A

NNW **483 COLEMAN AVE SAN JOSE, CA 95110** 1/4-1/2

0.366 mi.

1931 ft. Site 1 of 2 in cluster AG

Relative: SLIC REG 2: Lower Region:

Facility ID: 43S0936

Actual:

Facility Status: Post remedial action monitoring 78 ft.

Date Closed: Not reported Local Case #: Not reported How Discovered: DVA

Leak Cause: Not reported Leak Source: Not reported Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: Not reported Date Preliminary Site Assessment Began: Not reported Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

AG191 **MR AIR SWEEPERS** RCRA-SQG 1000455752 NNW **483 COLEMAN AVE** LUST CAD982494650

1/4-1/2 SAN JOSE, CA 95110 0.366 mi.

1931 ft. Site 2 of 2 in cluster AG

SWEEPS UST Relative: Lower Actual: 78 ft.

HAZNET HIST CORTESE CERS

RCRA-SQG:

Date form received by agency: 08/02/1990

MR AIR SWEEPERS Facility name: Facility address: 483 COLEMAN AVE SAN JOSE, CA 95110

EPA ID: CAD982494650 Mailing address: P O BOX 6312

SAN JOSE, CA 95150

Contact: **ENVIRONMENTAL MANAGER**

Contact address: 483 COLEMAN AVE

SAN JOSE, CA 95110

Contact country: US

Contact telephone: 408-275-1246 **CPS-SLIC**

HIST LUST

DEED

FINDS

ECHO

Direction Distance Elevation

Site Database(s) EPA ID Number

MR AIR SWEEPERS (Continued)

1000455752

EDR ID Number

Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: LARRY DYCK
Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: Nο Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

LUST:

Lead Agency: SANTA CLARA COUNTY LOP

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MR AIR SWEEPERS (Continued)

1000455752

Case Type: LUST Cleanup Site

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501012

Global Id: T0608501012 Latitude: 37.340819 Longitude: -121.90312

Completed - Case Closed Status:

10/31/1995 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Soil

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating

Not reported Site History:

LUST:

Global Id: T0608501012

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608501012

Contact Type: Local Agency Caseworker **UST CASE WORKER** Contact Name: SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE

Email: Not reported Phone Number: 4089183400

LUST:

Global Id: T0608501012 Action Type: **RESPONSE** Date: 09/25/1990

Other Report / Document Action:

Global Id: T0608501012 Action Type: Other 01/01/1990 Date: Action: Leak Reported

Global Id: T0608501012 Action Type: **ENFORCEMENT** Date: 10/31/1995

Action: Closure/No Further Action Letter

LUST:

Global Id: T0608501012

Status: Completed - Case Closed

10/31/1995 Status Date:

Global Id: T0608501012

Direction Distance

Elevation Site Database(s) **EPA ID Number**

MR AIR SWEEPERS (Continued)

1000455752

EDR ID Number

Status: Open - Case Begin Date

01/01/1990 Status Date:

LUST REG 2:

2 Region:

Facility Id: Not reported Case Closed Facility Status: Case Number: 07S1E07D04f How Discovered: Not reported Leak Cause: Not reported Not reported Leak Source: Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Not reported Preliminary Site Assesment Began: Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E07D04F Date Closed: 10/31/1995 EDR Link ID: 07S1E07D04F

CPS-SLIC:

STATE Region:

Facility Status: Open - Verification Monitoring

Status Date: 01/01/2014 Global Id: SL18381801

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported Latitude: 37.3384147007674 Longitude: -121.907644271851 Case Type: Cleanup Program Site

Case Worker: **RWP** Local Agency: Not reported 43S0936 RB Case Number: File Location: Regional Board

Potential Media Affected: Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern: Diesel, * Petroleum, Lead

Site includes two properties: - Former Lenzen Yard: 13 acres with PHC Site History:

plume within the property boundary. - College Park Yard - Parcel 2: 8 acres with no groundwater impact. Contaminated soil from use as an old railyard now being redeveloped for a variety of uses including residential and a Caltrain (JPB) maintenance center. Extraction-well maintenance of an open excavation removed thousands of gallons of groundwater heavily contaminated with petroleum hydrocarbons (PHCs). GAC treatment of the PHC-contaminated water removed hundreds of

pounds of PHCs from the subsurface.

Click here to access the California GeoTracker records for this facility:

Direction Distance Elevation

Site Database(s) EPA ID Number

MR AIR SWEEPERS (Continued)

1000455752

EDR ID Number

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07D04 Oversite Agency: SCVWD

Date Listed: 1991-01-01 00:00:00 Closed Date: 1995-10-31 00:00:00

SWEEPS UST:

Not reported Status: 401794 Comp Number: Not reported Number: Board Of Equalization: Not reported Not reported Referral Date: Not reported Action Date: Created Date: Not reported Not reported Owner Tank Id:

SWRCB Tank ld: 43-060-401794-000001

Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: Not reported

Number Of Tanks: 2

Status: Not reported 401794 Comp Number: Number: Not reported Board Of Equalization: Not reported Referral Date: Not reported Action Date: Not reported Created Date: Not reported Not reported Owner Tank Id:

SWRCB Tank Id: 43-060-401794-000002

Tank Status: Not reported

Capacity: 75

Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: Not reported
Number Of Tanks: Not reported

DEED:

Envirostor ID: SL18381801
Area: Not reported
Sub Area: Not reported
Site Type: SLIC

Status: OPEN - VERIFICATION MONITORING

Agency: SWRCB
Covenant Uploaded: Y
Deed Date(s): 07/30/2007

File Name: Geotracker Land Use/Deed Restrictions

FINDS:

Direction Distance

Elevation Site Database(s) EPA ID Number

MR AIR SWEEPERS (Continued)

1000455752

EDR ID Number

Registry ID: 110002830937

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000455752 Registry ID: 110002830937

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002830937

HAZNET:

envid: 1000455752 Year: 2001

GEPAID: CAD982494650
Contact: NOT REQUIRED
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: PO BOX 5993

Mailing City, St, Zip: SAN JOSE, CA 951505993

Gen County: Not reported TSD EPA ID: CA0000084517 TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: Transfer Station

Tons: 0.41

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000455752 Year: 2000

GEPAID: CAD982494650
Contact: NOT REQUIRED
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: PO BOX 5993

Mailing City, St, Zip: SAN JOSE, CA 951505993

Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported

Waste Category: Aqueous solution with total organic residues less than 10 percent

Disposal Method: Transfer Station

Tons: 0.08

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MR AIR SWEEPERS (Continued)

1000455752

envid: 1000455752 Year: 1996

CAD982494650 GEPAID: Contact: LARRY DYCK Telephone: 4082751246 Mailing Name: Not reported Mailing Address: PO BOX 5993

Mailing City,St,Zip: SAN JOSE, CA 951505993

Gen County: Not reported TSD EPA ID: CAD009452657 TSD County: Not reported

Unspecified solvent mixture Waste Category:

Disposal Method: Recycler Tons: .1500 Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000455752

Year: 1995

GEPAID: CAD982494650 Contact: LARRY DYCK Telephone: 4082751246 Mailing Name: Not reported Mailing Address: PO BOX 5993

Mailing City, St, Zip: SAN JOSE, CA 951505993

Gen County: Not reported TSD EPA ID: CAD009452657 TSD County: Not reported

Waste Category: Unspecified solvent mixture

Disposal Method: Recycler Tons: .1834 Cat Decode: Not reported Method Decode: Not reported Santa Clara Facility County:

1000455752 envid: Year: 1994

CAD982494650 GEPAID: Contact: LARRY DYCK Telephone: 4082751246 Mailing Name: Not reported Mailing Address: PO BOX 5993

Mailing City, St, Zip: SAN JOSE, CA 951505993

Gen County: Not reported TSD EPA ID: CAD009452657 TSD County: Not reported

Waste Category: Unspecified solvent mixture

Disposal Method: Recycler .8880 Tons: Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

> Click this hyperlink while viewing on your computer to access 3 additional CA_HAZNET: record(s) in the EDR Site Report.

Direction Distance

Elevation Site Database(s) EPA ID Number

MR AIR SWEEPERS (Continued)

1000455752

EDR ID Number

HIST CORTESE:

Region: CORTESE Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1017

CERS TANKS:

 Site ID:
 256583

 CERS ID:
 T0608501012

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Site ID: 191486 CERS ID: SL18381801

CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Roger Papler - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY STREET, SUITE 1500

Affiliation City: OAKLAND

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

AD192 235 WEST JULIAN STREET CPS-SLIC S108992047
NE 235 WEST JULIAN STREET BROWNFIELDS N/A

SAN JOSE, CA 95110 CERS

1/4-1/2 0.368 mi.

1945 ft. Site 2 of 5 in cluster AD

Relative: CPS-SLIC:
Higher Region: STATE

 Actual:
 Facility Status:
 Open - Inactive

 84 ft.
 Status Date:
 07/03/2018

 Global Id:
 SL0608515396

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number:
Latitude:
Solution 27.3389995038696
Longitude:
Case Type:
Not reported
37.3389995038696
-121.897766876335
Cleanup Program Site

Case Worker: MBR
Local Agency: Not reported
RB Case Number: 43S1105
File Location: Regional Board
Potential Media Affected: Under Investigation
Potential Contaminants of Concern: * Metals, Diesel

Site History: The approximately 0.65-acre Site is located at 235 West Julian Street

near the intersection of Terraine Street and West Julian Street in San Jos, California in a commercial/light industrial area. The Site was occupied by Ropers Fruit Packing Depot in 1891; Bean Spray and Pump Company (with on-Site spray mixing, spray storage and machine shop activities) in 1915; a U.S. Government Warehouse in 1950; and foundry and lithograph businesses in 1969. A 2005 SECOR environmental investigation (Phase I and II) revealed elevated metal concentrations (arsenic, chromium, copper, lead, nickel and zinc in the upper 2 feet of soil. Diesel ranged petroleum hydrocarbons also were at depths ranging from 15 to 20 feet. Secor also reported elevated diesel ranged petroleum hydrocarbons in ground water (SB-8 @ 12,000 ppm). The results of the human health risk assessment indicated that potential on-Site construction workers and potential future residents will not incur significant carcinogenic or noncarcinogenic health effects via indoor and outdoor inhalation of the Chemicals of Concern

in soil, soil vapor and ground water. The Site is zoned for commercial/industrial use but will be rezoned to high density residential use. The proposed Site use is for a 10 to 16 story residential tower. Construction is planned to commence in 2014 but could be as early as 2011. The discharger is proposing capping the Site with the development effectively limiting exposure to future

residents.

Click here to access the California GeoTracker records for this facility:

BROWNFIELDS:

 Global ID:
 \$1,0608515396

 Latitude:
 37,338999504

 Longitude:
 -121.89776688

 Project Type:
 Cleanup Program Site

 Status:
 Open - Inactive

 Status Date:
 07/03/2018

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Last Correspondence Date: 09/13/2017

Release Type: Surface Discharge, Federally Regulated Underground Storage Tank System

- UST, Unknown

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

235 WEST JULIAN STREET (Continued)

S108992047

Contaminant(s) of Concern: * Metals, Diesel Media of Concern: **Under Investigation**

Past Use(s) that Caused Contamination: MANUFACTURING - OTHER, RAILROAD RIGHT OF WAY

Human Health Exposure Controlled: YES Human Health Exposure Controlled Date: 06/06/2016 Groundwater Migration Controlled: YES Groundwater Migration Controlled Date: 06/06/2016

Primary Caseworker Name: MICHAEL ROCHETTE

Primary Caseworker Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Primary Caseworker Phone Number: 510-622-2411

Primary Caseworker Address: 1515 CLAY STREET, SUITE 1400

Primary Caseworker Address: OAKLAND Primary Caseworker Address: CA

Primary Caseworker Email: mrochette@waterboards.ca.gov

CERS TANKS:

190352 Site ID: CERS ID: SL0608515396 **CERS** Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: MICHAEL ROCHETTE - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY STREET, SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

AE193 PG&E LUST S102435161

WNW **655 LENZEN AVE HIST LUST** N/A

1/4-1/2 **SAN JOSE, CA 95126 HIST CORTESE** 0.369 mi. **CERS**

Site 4 of 5 in cluster AE 1950 ft.

LUST: Relative:

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501053 86 ft.

Global Id: T0608501053 Latitude: 37.337544 -121.907473 Longitude:

Status: Completed - Case Closed

02/05/1999 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608501053 Global Id:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E (Continued) S102435161

Contact Type: Regional Board Caseworker Regional Water Board Contact Name:

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608501053

Contact Type: Local Agency Caseworker UST CASE WORKER Contact Name: SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Email: Not reported Phone Number: 4089183400

LUST:

T0608501053 Global Id: Action Type: Other 01/21/1985 Date: Action: Leak Reported

Global Id: T0608501053 Action Type: REMEDIATION Date: 07/01/1988 Action: Excavation

Global Id: T0608501053 **ENFORCEMENT** Action Type: Date: 06/08/1988

Action: Notice of Responsibility - #39947

Global Id: T0608501053 **ENFORCEMENT** Action Type: Date: 08/19/1997 Action: Staff Letter - #26996

T0608501053 Global Id: **ENFORCEMENT** Action Type: 02/05/1999 Date:

Action: Closure/No Further Action Letter

Global Id: T0608501053 Action Type: **RESPONSE** 02/05/1999 Date:

Other Report / Document Action:

Global Id: T0608501053 **RESPONSE** Action Type: Date: 08/26/1997

Action: Monitoring Report - Quarterly

LUST:

Global Id: T0608501053

Status: Completed - Case Closed

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E (Continued) S102435161

Status Date: 02/05/1999

T0608501053 Global Id:

Status: Open - Case Begin Date

Status Date: 12/01/1984

Global Id: T0608501053

Status: Open - Site Assessment

Status Date: 12/01/1984

T0608501053 Global Id:

Open - Site Assessment Status:

01/12/1988 Status Date:

LUST REG 2:

Region:

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E07L02f How Discovered: Not reported Not reported Leak Cause: Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 12/1/1984 Pollution Characterization Began: 1/12/1988 Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

SANTA CLARA Region: SCVWD ID: 07S1E07L02F Date Closed: 02/05/1999 EDR Link ID: 07S1E07L02F

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E07L02 Oversite Agency: SCVWD

Date Listed: 1901-01-01 00:00:00 Closed Date: 1999-02-05 00:00:00

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** 43-1059 Reg Id:

CERS TANKS:

Site ID: 250587 T0608501053 CERS ID:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG&E (Continued) S102435161

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: 4089183400

AD194 **BRANDENBURG PROPERTIES** LUST U001602467

ΝE 330 TERRAINE ST CDL 1/4-1/2 SAN JOSE, CA 94113 **HIST UST CERS**

0.374 mi.

1975 ft. Site 3 of 5 in cluster AD

Relative: LUST:

Lower Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: **LUST Cleanup Site** Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608571841 83 ft.

Global Id: T0608571841 37.3393825 Latitude: Longitude: -121.8974861

Completed - Case Closed Status:

Status Date: 03/27/2002 Case Worker: Not reported RB Case Number: 43-2418

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Not reported Local Case Number: Potential Media Affect: **Under Investigation**

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating

Site History: Not reported

LUST:

Global Id: T0608571841

Contact Type: Local Agency Caseworker **UST CASE WORKER** Contact Name: SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

SAN JOSE City: Email: Not reported 4089183400 Phone Number:

N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number**

BRANDENBURG PROPERTIES (Continued)

U001602467

EDR ID Number

LUST:

T0608571841 Global Id: **ENFORCEMENT** Action Type: Date: 04/30/2002

Action: Closure/No Further Action Letter

Global Id: T0608571841 Other Action Type: Date: 08/01/2001 Action: Leak Reported

Global Id: T0608571841 Action Type: Other 03/09/2000 Date: Action: Leak Discovery

Global Id: T0608571841 Action Type: **ENFORCEMENT** Date: 03/27/2002

Action: Closure/No Further Action Letter

Global Id: T0608571841 Action Type: Other 03/09/2000 Date: Leak Stopped Action:

LUST:

T0608571841 Global Id:

Completed - Case Closed Status:

03/27/2002 Status Date:

Global Id: T0608571841

2

Status: Open - Case Begin Date

03/09/2000 Status Date:

LUST REG 2:

Region: Facility Id: 43-2418 Facility Status: Case Closed Case Number: Not reported How Discovered: Tank Closure UNK Leak Cause:

UNK Leak Source: Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Not reported Pollution Characterization Began: Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

CDL:

Facility ID: 2003-02-013

Direction Distance

Elevation Site Database(s) EPA ID Number

BRANDENBURG PROPERTIES (Continued)

U001602467

EDR ID Number

Date: 02/03/2003 Labtype: Mobile Lab

Lab Type: Mobile Lab (M) - location where illegal drug lab equipment and materials were found in a vehicle or other mode of transport.

HIST UST:

File Number: 0002CEFB

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002CEFB.pdf

Region: STATE
Facility ID: 0000042676

Facility Type: Other

Other Type: STEEL SERVICE CENTER
Contact Name: JAMES L. MURPHY

Telephone: 4082956257

Owner Name: BRANDENBERG_BUTTERS

Owner Address: 333 W. SANTA CLARA ST.STE 1212

Owner City, St, Zip: SAN JOSE, CA 95113

Total Tanks: 0000

001 Tank Num: Container Num: 1 Year Installed: 1973 Tank Capacity: 00001000 Tank Used for: **PRODUCT** Type of Fuel: **REGULAR** Container Construction Thickness: Not reported Leak Detection: Stock Inventor

Tank Num: 002 Container Num: 2 Year Installed: 1973 Tank Capacity: 00003000 Tank Used for: **PRODUCT** Type of Fuel: DIESEL Container Construction Thickness: Not reported Leak Detection: Stock Inventor

Click here for Geo Tracker PDF:

CERS TANKS:

 Site ID:
 213299

 CERS ID:
 T0608571841

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Direction Distance

Elevation Site Database(s) EPA ID Number

AD195 BRANDENBURG PROPERTIES LUST S105481886
NE 185 JULIAN W CERS N/A

NE 185 JULIAN W 1/4-1/2 SAN JOSE, CA 95113

0.379 mi.

2001 ft. Site 4 of 5 in cluster AD

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

84 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608503496

 Global Id:
 T0608503496

 Latitude:
 37.339286

 Longitude:
 -121.897017

Status: Completed - Case Closed

Status Date: 03/27/2002
Case Worker: Not reported
RB Case Number: 43-2416

Local Agency: SANTA CLARA COUNTY LOP

File Location:

Local Case Number:

Potential Media Affect:

Not reported

Not reported

Under Investigation

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating, Heating Oil / Fuel Oil

Site History: Not reported

LUST:

Global Id: T0608503496

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE

Email: Not reported Phone Number: 4089183400

LUST:

 Global Id:
 T0608503496

 Action Type:
 ENFORCEMENT

 Date:
 03/27/2002

Action: Closure/No Further Action Letter

 Global Id:
 T0608503496

 Action Type:
 Other

 Date:
 08/01/2000

 Action:
 Leak Reported

 Global Id:
 T0608503496

 Action Type:
 ENFORCEMENT

 Date:
 11/14/2001

 Action:
 Staff Letter

 Global Id:
 T0608503496

 Action Type:
 Other

 Date:
 03/09/2000

 Action:
 Leak Discovery

Global Id: T0608503496
Action Type: ENFORCEMENT
Date: 03/27/2002

Action: Closure/No Further Action Letter

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

BRANDENBURG PROPERTIES (Continued)

S105481886

EDR ID Number

 Global Id:
 T0608503496

 Action Type:
 Other

 Date:
 03/09/2000

 Action:
 Leak Stopped

LUST:

Global Id: T0608503496

Status: Completed - Case Closed

Status Date: 03/27/2002

Global Id: T0608503496

Status: Open - Case Begin Date

Status Date: 03/09/2000

LUST REG 2:

Region: 2

Facility Id: 43-2416
Facility Status: Case Closed
Case Number: Not reported
How Discovered: Tank Closure
Leak Cause: UNK
Leak Source: UNK

Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

CERS TANKS:

 Site ID:
 241794

 CERS ID:
 T0608503496

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Direction Distance

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

AH196 SAN JOSE ARENA (GIESLER) LUST S103881005 SSE 80 N MONTGOMERY HIST LUST N/A

SSE 80 N MONTGOMERY 1/4-1/2 SAN JOSE, CA

0.383 mi.

2024 ft. Site 1 of 4 in cluster AH Relative: LUST SANTA CLARA:

 Higher
 Region:
 SANTA CLARA

 Actual:
 SCVWD ID:
 07S1E07Q14F

 93 ft.
 Date Closed:
 04/09/1997

EDR Link ID: 07S1E07Q14F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07Q14 Oversite Agency: SFRWQCB

Date Listed: 1991-01-01 00:00:00 Closed Date: 1997-04-09 00:00:00

 AI197
 CHEVRON #9-0882
 LUST
 U001602879

 SW
 955 THE ALAMEDA
 HIST UST
 N/A

1/4-1/2 SAN JOSE, CA 95118

0.388 mi.

2048 ft. Site 1 of 5 in cluster AI

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

97 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500403

 Global Id:
 T0608500403

 Latitude:
 37.3320168205997

 Longitude:
 -121.908674240112

 Status:
 Completed - Case Closed

Status Date: 04/11/1991
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:

Global Id: T0608500403

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500403

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER

Organization Name: SANTA CLARA COUNTY LOP Address: SANTA CLARA COUNTY LOP 1555 Berger Drive, Suite 300

City: SAN JOSE

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CHEVRON #9-0882 (Continued)

U001602879

Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608500403 Action Type: Other 12/04/1990 Date: Leak Reported Action:

Global Id: T0608500403 Action Type: **ENFORCEMENT** Date: 04/11/1991

Action: Closure/No Further Action Letter

Global Id: T0608500403 REMEDIATION Action Type: Date: 12/04/1990 Action: Excavation

T0608500403 Global Id: Action Type: **ENFORCEMENT** Date: 02/06/1991

Action: Notice of Responsibility - #39954

LUST:

Global Id: T0608500403

Status: Completed - Case Closed

04/11/1991 Status Date:

Global Id: T0608500403

Open - Case Begin Date Status:

Status Date: 11/06/1989

T0608500403 Global Id:

Open - Site Assessment Status:

Status Date: 11/06/1989

HIST UST:

File Number: 0002CFE6

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002CFE6.pdf

Region: STATE Facility ID: 00000061928 Facility Type: Gas Station Other Type: Not reported Contact Name: SEPTON, LARRY Telephone: 4082952363

Owner Name: CHEVRON U.S.A. INC.

Owner Address: 575 MARKET

Owner City, St, Zip: SAN FRANCISCO, CA 94105

Total Tanks: 0004

Tank Num: 001 Container Num: 1 Year Installed: 1969 00010000 Tank Capacity:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CHEVRON #9-0882 (Continued) U001602879

Tank Used for: **PRODUCT** Not reported Type of Fuel: Container Construction Thickness: 0000250 Leak Detection: Stock Inventor

002 Tank Num: Container Num: 2 1969 Year Installed: Tank Capacity: 00005000 Tank Used for: **PRODUCT** Type of Fuel: Not reported Container Construction Thickness: 0000250 Leak Detection: Stock Inventor

Tank Num: 003 Container Num: 3 Year Installed: 1969 00010000 Tank Capacity: Tank Used for: **PRODUCT** Not reported Type of Fuel: Container Construction Thickness: 0000250 Leak Detection: Stock Inventor

Tank Num: 004 Container Num: 4 Year Installed: 1969 Tank Capacity: 00001000 Tank Used for: WASTE Type of Fuel: Not reported Container Construction Thickness: 0000130 Leak Detection: Stock Inventor

Click here for Geo Tracker PDF:

AI198 **CHEVRON** HIST CORTESE S110060613 SW

955 THE ALAMEDA N/A

SAN JOSE, CA 1/4-1/2

0.388 mi.

2048 ft. Site 2 of 5 in cluster Al Relative: HIST CORTESE:

Higher Region:

CORTESE Facility County Code: 43 Actual: Reg By: **LTNKA** 97 ft. 43-0347 Reg Id:

AI199 CHEVRON #9-0882 S105030651 LUST SW 955 THE ALAMEDA **HIST LUST** N/A

1/4-1/2 SAN JOSE, CA 95118

0.388 mi.

2048 ft. Site 3 of 5 in cluster Al

Relative: LUST REG 2:

Higher Region:

Facility Id: Not reported Actual: Case Closed Facility Status: 97 ft.

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CHEVRON #9-0882 (Continued)

S105030651

Case Number: 07S1E07N02f How Discovered: Not reported Not reported Leak Cause: Leak Source: Not reported Date Leak Confirmed: Not reported LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 11/6/1989 Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E07N02 Oversite Agency: SCVWD

Date Listed: 1991-02-04 00:00:00 1991-04-11 00:00:00 Closed Date:

AI200 CHEVRON #9-0882 LUST S108743188 955 THE ALAMEDA **CERS** N/A

SW 1/4-1/2 SAN JOSE, CA 95118

0.388 mi.

2048 ft. Site 4 of 5 in cluster Al Relative: LUST SANTA CLARA:

SANTA CLARA Higher Region: SCVWD ID: 07S1E07N02F Actual: Date Closed: 04/11/1991 97 ft. EDR Link ID: 07S1E07N02F

CERS TANKS:

Site ID: 219021 CERS ID: T0608500403

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) **Entity Name:**

Entity Title: Not reported

1515 CLAY ST SUITE 1400 Affiliation Address:

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

CHEVRON #9-0882 (Continued) \$108743188

Affiliation Phone: Not reported

DERBY FOOD SERVICE LUST \$103473110

 201
 DERBY FOOD SERVICE
 LUST
 \$1034

 SW
 55 SUNOL ST
 HIST LUST
 N/A

1/4-1/2 SAN JOSE, CA 95126 HIST CORTESE 0.388 mi. CERS

2050 ft.

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

97 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500508

 Global Id:
 T0608500508

 Latitude:
 37.3298158238535

 Longitude:
 -121.906324625015

 Status:
 Completed - Case Closed

Status Date: 01/02/1991
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500508

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500508

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500508

 Action Type:
 Other

 Date:
 12/09/1987

 Action:
 Leak Reported

 Global Id:
 T0608500508

 Action Type:
 ENFORCEMENT

 Date:
 12/29/1989

Action: Notice of Responsibility - #39848

Global Id: T0608500508

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DERBY FOOD SERVICE (Continued)

S103473110

Action Type: **ENFORCEMENT** Date: 01/31/1991

Action: Closure/No Further Action Letter

Global Id: T0608500508 **RESPONSE** Action Type: Date: 10/02/1987

Action: Other Report / Document

LUST:

T0608500508 Global Id:

Status: Completed - Case Closed

Status Date: 01/02/1991

Global Id: T0608500508

Open - Case Begin Date Status:

12/09/1987 Status Date:

Global Id: T0608500508

Status: Open - Site Assessment

12/14/1990 Status Date:

LUST REG 2:

Region:

Facility Id: Not reported Facility Status: Case Closed 07S1E18C01f Case Number: How Discovered: Not reported Not reported Leak Cause: Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 12/14/1990 Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E18C01F Date Closed: 01/02/1991 07S1E18C01F EDR Link ID:

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E18C01 Oversite Agency: SCVWD

Date Listed: 1988-01-01 00:00:00 Closed Date: 1991-01-02 00:00:00

Direction Distance

Elevation Site Database(s) EPA ID Number

DERBY FOOD SERVICE (Continued)

S103473110

EDR ID Number

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0461

CERS TANKS:

 Site ID:
 229360

 CERS ID:
 T0608500508

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

 AI202
 CAMPISI TRUST
 LUST
 \$108240972

 WSW
 975 THE ALAMEDA
 CERS
 N/A

1/4-1/2 SAN JOSE, CA 95126

0.389 mi.

2055 ft. Site 5 of 5 in cluster AI

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

97 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608527783

 Global Id:
 T0608527783

 Latitude:
 37.331862711

 Longitude:
 -121.908616833

Status: Completed - Case Closed

Status Date: 07/25/2012
Case Worker: Not reported
RB Case Number: 14-772
Local Agency: Not reported

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E07N05f

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline

Site History: 2006 In July, 5 underground storage tanks (2-4,000 gallon gasoline,

1-1,000 gallon waste oil, and 2-1,000 gallon gasoline) were removed

Map ID Direction Distance Elevation

Site

MAP FINDINGS

Dat

Database(s)

EDR ID Number EPA ID Number

CAMPISI TRUST (Continued)

S108240972

from the site. Pitting and holes were noted in at least one of the USTs. Soil samples collected beneath the gasoline USTs were analyzed for Total Petroleum Hydrocarbons as Gasoline, Benzene, Toluene, Ethylbenzene, Xylenes (BTEX), fuel oxygenates and Ethylene Dibromide (EDB). None of these constituents were reported to be present above the laboratory reporting limits. 2 soil samples (T5-North-9 and T5-South-10) were collected from beneath the waste oil UST. These samples were analyzed for the same constituents as above, plus TPH as Diesel (TPHd), semi-volatile organic compounds by EPA Method No. 8270, and Polycholorinated Biphenyls (PCBs). The only constituent reported present above the laboratory reporting limit was Tetrachloroethene (PCE) at 0.0065 parts per million (ppm). During removal, a 6th tank was encountered and was 1,000-gallons in capacity and is believed to have held gasoline. 2 soil samples were collected from beneath the UST and were reported to have up to 0.45 ppm TPHg, 0.013 Benzene, 0.079 ppm Toluene, 0.014 ppm Ethylbenzene, and 0.063 ppm Xylenes. Fuel oxygenates were not reported to be present above the laboratory reporting limits. During tank removal, the eastern end of the tank was breached causing the release of approximately 5 gallons of fuel-water mixture into the excavation. Approximately 30 cubic yards of soil were removed from the eastern portion of the excavation. Additional soil samples were collected from 9.5 and 12 feet below the ground surface (ft bgs) in the excavated area. The sample collected at 12 ft bgs was reported to have 150 ppm TPHg and 1.9 ppm Xylenes. All other constituents were not reported to be present above the laboratory reporting limits. In November, 3 Geoprobe borings (GP-1 through GP-3) were drilled onsite to a depth of 30 ft bgs. Soil samples collected from boring GP-3 were not reported to have detectable concentrations of constituents of concern. Soil samples collected from boring GP-1 were only reported to have very low concentrations of TPHg present above the laboratory reporting limits. The highest concentrations were reported for the sample collected from 20 ft bgs in boring GP-2 located adjacent to the 6th UST, with 10,000 ppm TPHg and 30 ppm Ethylbenzene. Grab groundwater samples were collected from the 3 borings and were reported to have a maximum concentration of 5,100 parts per billion TPHq, 6.6 ppb Benzene, 5.1 ppb Toluene, 200 ppb Ethylbenzene, 240 ppb Xylenes, and 6.5 ppb 1,2-Dichloroethane (DCA). The sample collected from GP-2 was also reported to have 3,200 ppb hydrocarbons in the C8-C18 range with no diesel pattern present. 2007 In August, 4 monitoring wells (MW1 through MW4) were installed on and off-site to approximately 29 ft bgs and one geoprobe boring (GP4) was advanced onsite to approximately 24 ft bgs. 15 soil samples were collected and reported to have low to non-detectable concentrations of the Constituents of Concern (COCs). A grab groundwater sample was collected from GP4 and was reported to contain 62 ppb TPHg, 1.9 ppb Benzene, and 0.64 ppb Xylenes. In October, well MW5 was installed onsite to approximately 30 ft bgs to the south of UST T1. 4 soil samples were collected and reported to contain maximum concentrations of 390 ppm TPHg at 16 ft bgs and 0.018 ppm cis-1,2,-dichloroethene (cis-1,2-DCE) at 12 ft bgs. All other constituents were not reported to be present above the laboratory reporting limits. Following installation, all the monitoring wells were sampled and reported to contain maximum concentrations of 180 ppb TPHg, 280 ppb cis-1,2-DCE, 3.8 ppb 1,2-Dichloroethane (1,2-DCA), 19 ppb PCE, 8.2 ppb Trichloroethylene (TCE), 3.3 ppb trans-1.2-Dichloroethene, and 1.1 ppb Vinyl Chloride (VC). 2011 In December, the final groundwater

Direction Distance Elevation

ation Site Database(s) EPA ID Number

CAMPISI TRUST (Continued)

S108240972

EDR ID Number

monitoring event was conducted. It is reported that there is a groundwater mound in the vicinity of well MW2, which is located near the sanitary sewer system along North Morrison Street. It is reported that the groundwater elevations suggest that leakage from the sanitary sewer system may have created the groundwater mound. The groundwater mound was not present in each monitoring event. During this sampling event, maximum concentrations were reported of 290 ppb TPHg, 5.4 ppb Benzene, 0.54 ppb Ethylbenzene, 2.5 ppb 1,2-DCA, 200 ppb cis-1,2-DCE, 140 ppb PCE, 74 ppb TCE, 3.9 ppb trans-1,2-Dichloroethene, and 1.8 ppb VC. A higher TPHg concentration (320 ppb) was reported for well MW1, but the laboratory reported the TPHg was entirely due to the presence of chlorinated solvents (discrete peaks) and does not represent actual petroleum hydrocarbons. Not reported

LUST:

Global Id: T0608527783

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

LUST:

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 11/26/2008

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 05/28/2008

Action: Staff Letter - #80825

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 08/29/2007

Action: Other Report / Document

Global Id: T0608527783
Action Type: RESPONSE
Date: 05/12/2009

Action: Other Report / Document

Global Id: T0608527783
Action Type: RESPONSE
Date: 12/05/2007

Action: Monitoring Report - Quarterly

Global Id: T0608527783
Action Type: RESPONSE
Date: 06/29/2007

Action: Other Report / Document

Global Id: T0608527783

Distance Elevation Site

Site Database(s) EPA ID Number

CAMPISI TRUST (Continued)

S108240972

EDR ID Number

Action Type: RESPONSE Date: 01/30/2012

Action: Request for Closure

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 12/18/2006

Action: Unauthorized Release Form

Global Id: T0608527783
Action Type: RESPONSE
Date: 07/13/2012

Action: Well Destruction Report

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 02/24/2009

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 01/21/2009

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 06/12/2009

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 05/27/2009

 Action:
 Warning Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 06/01/2009

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 Other

 Date:
 12/19/2006

 Action:
 Leak Reported

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 06/13/2008

Action: Other Report / Document

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 01/30/2009

Action: Monitoring Report - Quarterly

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 11/17/2007

Distance

Elevation Site Database(s) EPA ID Number

CAMPISI TRUST (Continued)

S108240972

EDR ID Number

Action: Other Report / Document

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 07/30/2009

Action: Monitoring Report - Quarterly

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 03/12/2009

Action: Soil and Water Investigation Workplan - Addendum

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 01/15/2009

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 08/29/2007

Action: Soil and Water Investigation Report

Global Id: T0608527783
Action Type: RESPONSE
Date: 03/28/2008

Action: Other Report / Document

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 10/26/2007

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 01/30/2008

Action: Monitoring Report - Quarterly

Global Id: T0608527783
Action Type: RESPONSE
Date: 07/30/2008

Action: Monitoring Report - Quarterly

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 10/30/2008

Action: Monitoring Report - Quarterly

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 01/07/2008

Action: Soil and Water Investigation Report

Global Id: T0608527783
Action Type: RESPONSE
Date: 12/18/2007

Action: Soil and Water Investigation Report

Direction Distance Elevation

ance EDR ID Number vation Site Database(s) EPA ID Number

CAMPISI TRUST (Continued)

S108240972

 Global Id:
 T0608527783

 Action Type:
 REMEDIATION

 Date:
 07/25/2006

 Action:
 Excavation

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 03/16/2010

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 07/27/2011

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 05/31/2011

 Action:
 Staff Letter

Global Id: T0608527783
Action Type: ENFORCEMENT
Date: 06/16/2011

Action: Notice of Responsibility

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 08/31/2010

 Action:
 Warning Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 02/27/2012

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 02/14/2012

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 07/25/2012

Action: Closure/No Further Action Letter

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 05/22/2012

 Action:
 Staff Letter

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 04/30/2009

Action: Monitoring Report - Quarterly

Global Id: T0608527783
Action Type: RESPONSE

Direction
Distance
Flevation

Elevation Site Database(s) EPA ID Number

CAMPISI TRUST (Continued)

S108240972

EDR ID Number

Date: 07/30/2010

Action: Monitoring Report - Semi-Annually

Global Id: T0608527783
Action Type: RESPONSE
Date: 01/30/2010

Action: Monitoring Report - Semi-Annually

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 01/30/2011

Action: Monitoring Report - Semi-Annually

Global Id: T0608527783
Action Type: RESPONSE
Date: 06/23/2009

Action: Monitoring Report - Quarterly

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 03/26/2007

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 04/30/2008

Action: Monitoring Report - Quarterly

Global Id: T0608527783
Action Type: RESPONSE
Date: 04/28/2010

Action: Monitoring Report - Quarterly

Global Id: T0608527783
Action Type: RESPONSE
Date: 06/30/2010

Action: Soil and Water Investigation Report

Global Id: T0608527783
Action Type: RESPONSE
Date: 01/26/2007

Action: Other Report / Document

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 12/26/2006

 Action:
 Other Report

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 07/01/2009

Action: Soil and Water Investigation Workplan - Addendum

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 10/05/2009

Action: Soil and Water Investigation Report

Distance

Elevation Site Database(s) EPA ID Number

CAMPISI TRUST (Continued)

S108240972

EDR ID Number

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 01/29/2007

 Action:
 Other Workplan

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 12/11/2007

Action: Staff Letter - #71121

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 03/04/2008

 Action:
 Staff Letter - #80403

Global Id: T0608527783
Action Type: RESPONSE
Date: 12/06/2010

Action: Site Assessment Report

Global Id: T0608527783
Action Type: RESPONSE
Date: 10/15/2010

Action: Monitoring Report - Semi-Annually

Global Id: T0608527783
Action Type: RESPONSE
Date: 10/08/2013

Action: Other Report / Document

Global Id: T0608527783

Action Type: ENFORCEMENT

Date: 09/05/2007

Action: Staff Letter - #70509

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 10/04/2007

 Action:
 Staff Letter - #70401

 Global Id:
 T0608527783

 Action Type:
 ENFORCEMENT

 Date:
 07/19/2007

Action: Staff Letter - #70917

 Global Id:
 T0608527783

 Action Type:
 Other

 Date:
 07/25/2006

 Action:
 Leak Discovery

 Global Id:
 T0608527783

 Action Type:
 RESPONSE

 Date:
 07/31/2011

Action: Monitoring Report - Quarterly

Global Id: T0608527783
Action Type: RESPONSE

Direction Distance Elevation

EDR ID Number Site Database(s) **EPA ID Number**

CAMPISI TRUST (Continued)

S108240972

Date: 10/31/2011

Monitoring Report - Quarterly Action:

Global Id: T0608527783 Action Type: **RESPONSE** 06/20/2011 Date: Action: Correspondence

Global Id: T0608527783 Action Type: **RESPONSE** 01/01/2007 Date: Action: Correspondence

Global Id: T0608527783 Action Type: **RESPONSE** Date: 12/07/2006

Action: Tank Removal Report / UST Sampling Report

Global Id: T0608527783 **ENFORCEMENT** Action Type: Date: 01/04/2007

Action: Staff Letter - #7041

Global Id: T0608527783 Action Type: **ENFORCEMENT** Date: 12/27/2006

Action: Notice of Responsibility - #607221

Global Id: T0608527783 Action Type: **ENFORCEMENT** Date: 03/28/2007

Action: Staff Letter - #708230

Global Id: T0608527783 Action Type: **ENFORCEMENT** Date: 07/11/2007

Action: Staff Letter - #701170

T0608527783 Global Id: Action Type: Other 07/25/2006 Date: Action: Leak Stopped

Global Id: T0608527783 **RESPONSE** Action Type: Date: 07/15/2012

Action: Well Destruction Report

Global Id: T0608527783 Action Type: **RESPONSE** Date: 01/31/2012

Action: Monitoring Report - Quarterly - Regulator Responded

LUST:

Global Id: T0608527783

Status: Completed - Case Closed

07/25/2012 Status Date:

Direction Distance

Elevation Site Database(s) EPA ID Number

CAMPISI TRUST (Continued) S108240972

Global Id: T0608527783

Status: Open - Case Begin Date

Status Date: 07/25/2006

Global Id: T0608527783

Status: Open - Site Assessment

Status Date: 07/25/2006

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07N05F

 Date Closed:
 07/25/2012

 EDR Link ID:
 07S1E07N05F

CERS TANKS:

Site ID: 234631 CERS ID: T0608527783

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

AH203 SAN JOSE ARENA PG & E PARCEL LUST S105194820 SSE 90 MONTGOMERY ST N CERS N/A

1/4-1/2 SAN JOSE, CA 95150

0.392 mi.

2072 ft. Site 2 of 4 in cluster AH

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

93 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501983

 Global Id:
 T0608501983

 Latitude:
 37.329425

 Longitude:
 -121.900926

Status: Completed - Case Closed

 Status Date:
 10/01/1997

 Case Worker:
 UUU

 RB Case Number:
 43-2159

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:

Global Id: T0608501983

EDR ID Number

Direction Distance Elevation

levation Site Database(s) EPA ID Number

SAN JOSE ARENA PG & E PARCEL (Continued)

S105194820

EDR ID Number

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501983

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608501983

 Action Type:
 Other

 Date:
 04/10/1997

 Action:
 Leak Reported

 Global Id:
 T0608501983

 Action Type:
 Other

 Date:
 04/10/1997

 Action:
 Leak Discovery

 Global Id:
 T0608501983

 Action Type:
 Other

 Date:
 04/10/1997

 Action:
 Leak Stopped

LUST:

Global Id: T0608501983

Status: Completed - Case Closed

Status Date: 10/01/1997

Global Id: T0608501983

Status: Open - Case Begin Date

Status Date: 04/10/1997

LUST REG 2:

Region: 2 43-2159 Facility Id: Facility Status: Case Closed Case Number: 43-2159 Tank Closure How Discovered: Leak Cause: UNK Leak Source: UNK Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE ARENA PG & E PARCEL (Continued)

S105194820

Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

CERS TANKS:

Site ID: 236043 CERS ID: T0608501983

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

AH204 **SAN JOSE ARENA JULIAN PAR** HIST CORTESE S110060846

SSE **70 90 MONTGOMERY**

1/4-1/2 SAN JOSE, CA 95110

0.392 mi.

2072 ft. Site 3 of 4 in cluster AH HIST CORTESE:

Relative: Higher CORTESE Region: Facility County Code: 43 Actual: Reg By: LTNKA 93 ft.

Reg Id: 43-1174

AE205 STOCKTON AUTOMOTIVE **CERS HAZ WASTE** S101441079

WNW **465 STOCKTON AV SWEEPS UST** N/A SAN JOSE, CA 95126 1/4-1/2 **CUPA Listings**

0.395 mi. **HIST CORTESE** 2085 ft. Site 5 of 5 in cluster AE **SAN JOSE HAZMAT CERS**

Relative:

Higher CERS HAZ WASTE:

Site ID: 157368 Actual: CERS ID: 10353181 86 ft.

CERS Description: Hazardous Waste Generator

Affiliation:

Affiliation Type Desc: Identification Signer N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

STOCKTON AUTOMOTIVE (Continued)

S101441079

EDR ID Number

Entity Name: HUMBERTO NANEZ

Entity Title: OWNER

Affiliation Address: Not reported

Affiliation City: Not reported

Affiliation State: Not reported

Affiliation Country: Not reported

Affiliation Zip: Not reported

Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not report

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Document Preparer Entity Name: HUMBERTO NANEZ

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact Entity Name: HUMBERTO NANEZ

Entity Title: Not reported

Affiliation Address: 465 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: (408) 279-3732

Affiliation Type Desc: Operator

Entity Name: NANEZ, HUMBERTO

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 279-3732

Affiliation Type Desc: Parent Corporation

Entity Name: STOCKTON AUTOMOTIVE

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

STOCKTON AUTOMOTIVE (Continued)

S101441079

EDR ID Number

Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: NANEZ, HUMBERTO

Entity Title: Not reported

Affiliation Address: 465 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 279-3732

Affiliation Type Desc: Property Owner **Entity Name: BILL WASH** Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: **United States** Affiliation Zip: Not reported Affiliation Phone: (408) 274-9807

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 465 STOCKTON AV

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country:
Affiliation Zip:
Affiliation Phone:

Not reported
95126
Not reported

SWEEPS UST:

Not reported Status: 401485 Comp Number: Number: Not reported Board Of Equalization: Not reported Not reported Referral Date: Action Date: Not reported Created Date: Not reported Owner Tank Id: Not reported

SWRCB Tank ld: 43-060-401485-000001

Tank Status: Not reported

Capacity: 125

Active Date: Not reported Tank Use: OIL STG: WASTE Content: Not reported

Number Of Tanks: 1

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

Latitude: 37.337033

Direction Distance

Elevation Site Database(s) EPA ID Number

STOCKTON AUTOMOTIVE (Continued)

S101441079

EDR ID Number

 Longitude:
 -121.909679

 Record ID:
 PR0315890

 Facility ID:
 FA0209602

Region: SANTA CLARA

PE#: 2201

Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.337033

 Longitude:
 -121.909679

 Record ID:
 PR0369530

 Facility ID:
 FA0253729

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.337033

 Longitude:
 -121.909679

 Record ID:
 PR0412661

 Facility ID:
 FA0253729

HIST CORTESE:

Region: CORTESE Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1858

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 401485 Class: Auto Repair

CERS TANKS:

Site ID: 157368 CERS ID: 10353181

CERS Description: Chemical Storage Facilities

Affiliation:

Affiliation Type Desc: Identification Signer Entity Name: HUMBERTO NANEZ

Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported

Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Distance

Elevation Site Database(s) EPA ID Number

STOCKTON AUTOMOTIVE (Continued)

S101441079

EDR ID Number

Affiliation Type Desc: Document Preparer Entity Name: HUMBERTO NANEZ

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: HUMBERTO NANEZ

Entity Title: Not reported

Affiliation Address: 465 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95126

Affiliation Phone: (408) 279-3732

Affiliation Type Desc: Operator

Entity Name: NANEZ, HUMBERTO

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 279-3732

Affiliation Type Desc: Parent Corporation

Entity Name: STOCKTON AUTOMOTIVE

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner

Entity Name: NANEZ, HUMBERTO

Entity Title: Not reported

Affiliation Address: 465 STOCKTON AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 279-3732

Affiliation Type Desc:
Entity Name:
Entity Title:
Affiliation Address:
Affiliation City:
Affiliation State:
Affiliation Country:
United States

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

STOCKTON AUTOMOTIVE (Continued)

S101441079

Affiliation Zip: Not reported
Affiliation Phone: (408) 274-9807

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 465 STOCKTON AV

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: Not reported

AF206 WELLS FARGO ALARM SERVICES LUST \$102441133

2109 ft. Site 2 of 2 in cluster AF

Relative: LUST:

Lower Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

77 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501580

Global Id: T0608501580
Latitude: 37.341498
Longitude: -121.902394

Status: Completed - Case Closed

Status Date: 02/19/1991 Case Worker: UST

RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608501580

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501580

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

WELLS FARGO ALARM SERVICES (Continued)

S102441133

LUST:

 Global Id:
 T0608501580

 Action Type:
 Other

 Date:
 01/31/1990

 Action:
 Leak Reported

 Global Id:
 T0608501580

 Action Type:
 ENFORCEMENT

 Date:
 02/19/1991

Action: Closure/No Further Action Letter

 Global Id:
 T0608501580

 Action Type:
 ENFORCEMENT

 Date:
 01/10/1991

Action: Notice of Responsibility - #39941

 Global Id:
 T0608501580

 Action Type:
 REMEDIATION

 Date:
 01/31/1990

 Action:
 Excavation

Global Id: T0608501580
Action Type: RESPONSE
Date: 01/10/1991

Action: Other Report / Document

LUST:

Global Id: T0608501580

Status: Completed - Case Closed

Status Date: 02/19/1991

Global Id: T0608501580

Status: Open - Case Begin Date

Status Date: 01/31/1990

Global Id: T0608501580

Status: Open - Site Assessment

Status Date: 12/11/1990

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E07G01f How Discovered: Not reported Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Not reported
Pollution Remediation Plan Submitted:
Not reported
Date Remediation Action Underway:
Not reported
Not reported
Not reported
Not reported
Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

WELLS FARGO ALARM SERVICES (Continued)

S102441133

EDR ID Number

LUST SANTA CLARA:

SANTA CLARA Region: SCVWD ID: 07S1E07G01F Date Closed: 02/19/1991 EDR Link ID: 07S1E07G01F

HIST LUST SANTA CLARA:

SANTA CLARA Region:

Region Code:

SCVWD ID: 07S1E07G01 Oversite Agency: SCVWD

Date Listed: 1991-01-01 00:00:00 Closed Date: 1991-02-19 00:00:00

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** 43-1628 Reg Id:

CERS TANKS:

Site ID: 188342 CERS ID: T0608501580

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND

Affiliation State:

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

AJ207 BRANDENBURG PROPERTIES LUST S105481887 N/A

NE 160 JULIAN W **CERS**

1/4-1/2 SAN JOSE, CA 95113

0.400 mi.

2111 ft. Site 1 of 5 in cluster AJ

LUST: Relative:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608595937 85 ft.

Global Id: T0608595937 Latitude: 37.339096 -121.896311 Longitude:

Completed - Case Closed Status:

06/11/2003 Status Date: Case Worker: Not reported RB Case Number: 43-2417

SANTA CLARA COUNTY LOP Local Agency:

File Location: Not reported Local Case Number: Not reported Potential Media Affect: **Under Investigation**

Potential Contaminants of Concern: Gasoline, Waste Oil / Motor / Hydraulic / Lubricating

Site History: Not reported

LUST:

Global Id: T0608595937

Local Agency Caseworker Contact Type: Contact Name: UST CASE WORKER Organization Name: SANTA CLARA COUNTY LOP Address: 1555 Berger Drive, Suite 300

City: SAN JOSE

Email: Not reported 4089183400 Phone Number:

LUST:

Global Id: T0608595937 **RESPONSE** Action Type: 06/03/2005 Date:

Action: Other Report / Document

T0608595937 Global Id: **RESPONSE** Action Type: Date: 01/01/2001 Action: Correspondence

Global Id: T0608595937 **RESPONSE** Action Type: Date: 05/26/2000

Action: Tank Removal Report / UST Sampling Report

Global Id: T0608595937 Action Type: **RESPONSE** Date: 05/10/2000

Action: Soil and Water Investigation Report

Global Id: T0608595937 Action Type: Other 08/01/2001 Date: Action: Leak Reported **EDR ID Number**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BRANDENBURG PROPERTIES (Continued)

S105481887

T0608595937 Global Id: RESPONSE Action Type: Date: 01/02/2002

Action: Monitoring Report - Other

Global Id: T0608595937 **ENFORCEMENT** Action Type: Date: 06/03/2005 Action: Other Report

T0608595937 Global Id: Action Type: **ENFORCEMENT** 11/14/2001 Date: Action: Staff Letter

Global Id: T0608595937 **ENFORCEMENT** Action Type: Date: 03/27/2002

Action: Closure/No Further Action Letter

Global Id: T0608595937 **RESPONSE** Action Type: Date: 11/07/2001

Action: **Email Correspondence**

Global Id: T0608595937 Action Type: Other Date: 03/09/2000 Action: Leak Discovery

Global Id: T0608595937 Action Type: **ENFORCEMENT** Date: 06/11/2003

Action: Closure/No Further Action Letter

Global Id: T0608595937 Action Type: Other 03/09/2000 Date: Action: Leak Stopped

LUST:

Global Id: T0608595937

Status: Completed - Case Closed

Status Date: 06/11/2003

Global Id: T0608595937

Status: Open - Case Begin Date

03/09/2000 Status Date:

LUST REG 2:

Region: 43-2417 Facility Id: Facility Status: Case Closed Case Number: Not reported

How Discovered: Tank Closure

Direction Distance

Elevation Site Database(s) EPA ID Number

BRANDENBURG PROPERTIES (Continued)

S105481887

EDR ID Number

Leak Cause: UNK
Leak Source: UNK
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

CERS TANKS:

Site ID: 187453 CERS ID: 70608595937

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported

Affiliation Zip: Not reported Affiliation Phone: 4089183400

NORTH SAN PEDRO SQUARE RESIDENCES CPS-SLIC S122853939

NE BOUNDED BY W. JULIAN, TERRAINE, BASSETT, AND N. SAN PEDRO ST BROWNFIELDS N/A

1/4-1/2 SAN JOSE, CA 95110

0.400 mi.

AD208

2114 ft. Site 5 of 5 in cluster AD

Relative: CPS-SLIC:
Higher Region: STATE

Actual: Facility Status: Open - Assessment & Interim Remedial Action

84 ft. Status Date: 07/17/2018 Global ld: T10000011811

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported Latitude: 37.33974 Longitude: -121.89702

Case Type: Cleanup Program Site

Case Worker: MBR
Local Agency: Not reported
RB Case Number: 43S1223

File Location: All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected: Indoor Air, Other Groundwater (uses other than drinking water), Soil,

Soil Vapor

Potential Contaminants of Concern: Not reported

Site History: August 2018 Block BF LLC is planning to construct a 5-story

podium-style apartment building with one full level of ventilated, subterranean parking. Prior commercial operations at the site date back to 1884 and have included underground storage tanks, oil water separators, associated piping, a railroad spur(s), and manufacturing of specialty bicycle parts. The Regional Water Board has issued several no further action letters for parcels within the site when

Direction Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

NORTH SAN PEDRO SQUARE RESIDENCES (Continued)

S122853939

the site was zoned for commercial use. Block BF LLC has submitted a vapor intrusion mitigation system (VIMS) VIMS Design Report that includes the following elements: Excavation of soil at the entire site to approximately10 feet below ground surface (bgs) to allow for the subterranean parking Excavation of soil at the elevator pit locations to approximately 15 feet bgs Vapor barrier under the entire building footprint Vapor collection system installed beneath the vapor barrier with 50 spacing Ventilation risers to the roof fitted with active fans on the rooftop Implementation of a construction quality assurance plan under the oversight of VIMS design engineer Subslab sampling layer and four subslab sampling points Two rounds of indoor air and subslab sampling at four locations Submittal of a VIMS completion report and O&M plan

Click here to access the California GeoTracker records for this facility:

BROWNFIELDS:

Global ID: T10000011811 Latitude: 37.33974 -121.89702 Longitude:

Project Type: Cleanup Program Site

Status: Open - Assessment & Interim Remedial Action

Status Date: 07/17/2018

SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency:

Last Correspondence Date: 08/30/2018

Release Type: Other Type of Release

Contaminant(s) of Concern: Not reported

Media of Concern: Indoor Air, Other Groundwater (uses other than drinking water), Soil,

Soil Vapor

MACHINE SHOP, MAINTENANCE / CLEANING, MANUFACTURING - OTHER, OIL/WATER SEPARATORS, PESTICIDE/INSECTIDE/RODENTICIDE STORAGE

Human Health Exposure Controlled: YES Human Health Exposure Controlled Date: 07/17/2018 Groundwater Migration Controlled: YES 07/17/2018

Groundwater Migration Controlled Date:

Past Use(s) that Caused Contamination:

Primary Caseworker Name: MICHAEL ROCHETTE

Primary Caseworker Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Primary Caseworker Phone Number: 510-622-2411

1515 CLAY STREET, SUITE 1400 Primary Caseworker Address:

Primary Caseworker Address: OAKLAND

Primary Caseworker Address: CA

Primary Caseworker Email: mrochette@waterboards.ca.gov

COMMON GROUND LANDSCAPE MGMT 209 LUST S100274371

WNW 725 LENZEN AV **HIST LUST** N/A **CERS HAZ WASTE** 1/4-1/2 SAN JOSE, CA 95126 0.401 mi. **CUPA Listings** 2115 ft. **HIST CORTESE**

SAN JOSE HAZMAT Relative: **CERS** Higher

LUST: Actual:

Lead Agency: SANTA CLARA COUNTY LOP 87 ft.

Case Type: **LUST Cleanup Site**

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500684

T0608500684 Global Id: 37.336295 Latitude:

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Longitude: -121.909253

Status: Completed - Case Closed

Status Date: 10/07/2003
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500684

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500684

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 10/07/2003

Action: Closure/No Further Action Letter

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 10/30/1990

Action: Soil and Water Investigation Workplan

Global Id: T0608500684
Action Type: RESPONSE
Date: 03/11/1994

Action: Other Report / Document

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 06/19/1995

Action: Other Report / Document

Global Id: T0608500684
Action Type: RESPONSE
Date: 12/01/2000

Action: Soil and Water Investigation Report

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

Global Id: T0608500684 Action Type: Other 05/01/1989 Date: Action: Leak Reported

Global Id: T0608500684 REMEDIATION Action Type: Date: 02/06/1996

Action: Pump & Treat (P&T) Groundwater

Global Id: T0608500684 Action Type: REMEDIATION 02/06/1996 Date:

Action: Soil Vapor Extraction (SVE)

Global Id: T0608500684 **RESPONSE** Action Type: 09/28/1994 Date:

Action: Interim Remedial Action Plan

Global Id: T0608500684 Action Type: **ENFORCEMENT** Date: 03/03/1994

Action: Staff Letter - #27055

Global Id: T0608500684 Action Type: **ENFORCEMENT** Date: 07/14/1994

Action: Staff Letter - #27061

Global Id: T0608500684 Action Type: **ENFORCEMENT** Date: 06/15/1998

Action: Staff Letter - #27080

Global Id: T0608500684 Action Type: **ENFORCEMENT** Date: 04/29/1997

Staff Letter - #27075 Action:

Global Id: T0608500684 Action Type: **ENFORCEMENT** Date: 02/14/1997

Action: Staff Letter - #27073

Global Id: T0608500684 Action Type: **ENFORCEMENT** Date: 11/15/1996

Action: Staff Letter - #27071

T0608500684 Global Id: Action Type: **ENFORCEMENT** Date: 01/29/1997 Action: Staff Letter - #27069

Global Id: T0608500684 Action Type: **ENFORCEMENT**

Direction Distance Flevation

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Date: 06/18/1996

Action: Staff Letter - #27067

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 12/12/1995

Action: Staff Letter - #27065

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 06/15/1995

Action: Staff Letter - #27063

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 11/17/2000

Action: Staff Letter - #27086

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 07/07/1994

Action: Staff Letter - #27059

Global Id: T0608500684
Action Type: ENFORCEMENT
Date: 09/27/1990

Action: Staff Letter - #27048

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 06/07/1994

Action: Staff Letter - #27057

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 10/13/1993

 Action:
 Staff Letter - #27051

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 09/25/1990

 Action:
 Staff Letter - #27046

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 03/07/2003

Action: Soil and Water Investigation Report

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 07/27/1998

Action: Interim Remedial Action Plan

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 07/24/2003

Action: Verbal Communication

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 12/10/2002

Action: Other Report / Document

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 04/20/1994

Action: CAP/RAP - Feasibility Study Report

Global Id: T0608500684
Action Type: RESPONSE
Date: 12/12/1995

Action: CAP/RAP - Other Report

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 05/01/1989

Action: Unauthorized Release Form

Global Id: T0608500684
Action Type: RESPONSE
Date: 02/25/1997

Action: Other Report / Document

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 06/08/1999

Action: Other Report / Document

Global Id: T0608500684
Action Type: RESPONSE
Date: 03/05/1998

Action: Interim Remedial Action Report

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 12/27/2002

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 09/28/2001

Action: Soil and Water Investigation Workplan

Global Id: T0608500684
Action Type: RESPONSE
Date: 07/07/1994

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 03/01/2002

Action: Other Report / Document

Global Id: T0608500684
Action Type: RESPONSE

Direction Distance

Date:

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

04/30/1997

Action: Monitoring Report - Quarterly

Global Id: T0608500684
Action Type: RESPONSE
Date: 02/13/1997

Action: Soil and Water Investigation Report

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 01/30/1997

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 04/30/1997

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 06/25/1996

Action: Other Report / Document

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 12/15/1995

Action: Interim Remedial Action Plan

Global Id: T0608500684
Action Type: RESPONSE
Date: 08/25/1994

Action: Other Report / Document

Global Id: T0608500684
Action Type: RESPONSE
Date: 12/09/1998

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 07/31/1998

Action: Soil and Water Investigation Workplan

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 06/13/1997

Action: Other Report / Document

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 10/13/1993

Action: Other Report / Document

 Global Id:
 T0608500684

 Action Type:
 RESPONSE

 Date:
 12/13/2002

 Action:
 Correspondence

EDR ID Number

S100274371

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

Global Id: T0608500684 RESPONSE Action Type: 05/03/1994 Date:

Action: Other Report / Document

Global Id: T0608500684 RESPONSE Action Type: Date: 01/06/1995

Action: Soil and Water Investigation Report

Global Id: T0608500684 **RESPONSE** Action Type: Date: 11/02/1993

Action: Soil and Water Investigation Report

Global Id: T0608500684 **RESPONSE** Action Type: 10/30/1990 Date:

Action: Soil and Water Investigation Report

Global Id: T0608500684 RESPONSE Action Type: Date: 03/22/2004 Action: Correspondence

Global Id: T0608500684 Action Type: **RESPONSE** Date: 09/25/2003 Action: Correspondence

Global Id: T0608500684 Action Type: **RESPONSE** Date: 10/28/1997 Action: Other Workplan

Global Id: T0608500684 Action Type: **RESPONSE** Date: 11/27/1992

Tank Removal Workplan Action:

T0608500684 Global Id: Action Type: **RESPONSE** Date: 09/27/1990

Soil and Water Investigation Workplan Action:

Global Id: T0608500684 Action Type: **RESPONSE** Date: 09/01/1993 Action: Correspondence

T0608500684 Global Id: Action Type: **RESPONSE** Date: 11/17/2000

Action: Remedial Progress Report

Global Id: T0608500684 Action Type: **RESPONSE**

Direction Distance Elevation

ation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Date: 10/26/1989

Action: Other Report / Document

Global Id: T0608500684
Action Type: RESPONSE
Date: 05/01/2003

Action: Monitoring Report - Quarterly

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 02/22/1994

 Action:
 Staff Letter - #27053

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 08/15/1990

Action: Notice of Responsibility - #39950

 Global Id:
 T0608500684

 Action Type:
 ENFORCEMENT

 Date:
 10/25/1998

Action: Staff Letter - #27082

LUST:

Global Id: T0608500684

Status: Completed - Case Closed

Status Date: 10/07/2003

Global Id: T0608500684

Status: Open - Case Begin Date

Status Date: 03/16/1989

Global Id: T0608500684

Status: Open - Site Assessment

Status Date: 03/16/1989

Global Id: T0608500684

Status: Open - Site Assessment

Status Date: 06/01/1990

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E07M01f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 3/16/1989
Pollution Characterization Began: 6/1/1990
Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported

Direction Distance Elevation

vation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07M01F

 Date Closed:
 10/07/2003

 EDR Link ID:
 07S1E07M01F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07M01 Oversite Agency: SCVWD

Date Listed: 1990-01-01 00:00:00 Closed Date: 2003-10-07 00:00:00

CERS HAZ WASTE:

Site ID: 21118 CERS ID: 10355404

CERS Description: Hazardous Waste Generator

Violations:

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 11/03/2015.

___ Funnels

were in use but there was still oil spilled on the top of the drums.

There was also absorbent in the secondary containment and some outside secondary containment. Store used/contaminated absorbent in a container with a lid and if determined to be hazardous waste, properly label the container. Respond to spills as they happen. Clean up the hazardous waste area and maintain it in a way to minimize the

potential for releases to the environment.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes: Returned to compliance on 11/03/2015.

_ The used

oil filter container did not have an accumulation start date.

Determine the start date and properly mark the date on the label.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

Violation Source: **CERS**

Site ID: 21118

COMMON GROUND LANDSCAPE MGMT Site Name:

Violation Date: 09-29-2015

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 11/03/2015.

Facility

last submitted an HMBP in 2012. Submit a complete HMBP on FrontCounter or CERS (CERS ID# 10355404). Ensure all three HMBP sections (Facility Information, Hazardous Materials Inventory, and Emergency Response and

Training Plans) are submitted annually to re-certify the HMBP.

Santa Clara County Environmental Health Violation Division:

Violation Program: **HMRRP** Violation Source: **CERS**

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers with

the following requirements: "Hazardous Waste", name and address of the

generator, physical and chemical characteristics of the Hazardous

Waste, and starting accumulation date.

Violation Notes: Returned to compliance on 11/03/2015.

The used

oil containers had illegible labels. Ensure all hazardous waste is properly marked with the required information. Hazardous waste labels

provided during the inspection.

Santa Clara County Environmental Health Violation Division:

Violation Program: Violation Source: **CERS**

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date:

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 11/03/2015.

The used

oil containers were open during the inspection. One had filters and containers actively draining into it, the other did not. Ensure all hazardous waste containers are kept closed except when adding or

removing hazardous waste and at the close of business.

Santa Clara County Environmental Health Violation Division:

Violation Program: Violation Source: **CERS**

Site ID: 21118

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes: Returned to compliance on 11/03/2015.

The used

oil filter drum was open during the inspection. The container should

only be opened when adding or removing filters.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-29-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscape company, hazardous waste generated from maintenance of

equipment. EPA ID# CAL000274496 is active. Emergency equipment present

and maintained, emergency actions form posted near phone. eMail:

mail@commongroundlandscapeinc.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-29-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscaping business. Storing motor oil, used oil, and various

fertilizers in HMBP quantities. Smaller quantities of two-stroke engine oil, paint, surfactants etc. also stored. Contact me once your CERS account is set up, I will connect you to the facility already created for your business. eMail: mail@commongroundlandscapeinc.com NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents retained for 3 years. Contact me for more

information. A sample training log attached with this report.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Enforcement Action:

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

 Site Address:
 725 LENZEN AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 09-29-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Enf Action Source: CERS

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

 Site Address:
 725 LENZEN AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 09-29-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW
Enf Action Source: CERS

Affiliation:

Affiliation Type Desc:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Operator

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716

 Affiliation Zip:
 95112-2716

 Affiliation Phone:
 (408) 918-3400

Entity Name: William Jauch **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Not reported Affiliation Zip: Affiliation Phone: (408) 592-9048

Affiliation Type Desc: Parent Corporation

Entity Name: COMMON GROUND LANDSCAPE MGMT

Not reported

Entity Title:
Affiliation Address:
Affiliation City:
Affiliation State:
Affiliation Country:
Affiliation Country:
Affiliation Zip:
Affiliation Phone:
Not reported
Not reported
Not reported
Not reported

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 725 LENZEN AV
Affiliation City: SAN JOSE

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95126

Affiliation Phone:

Affiliation Type Desc: Identification Signer

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Entity Name: William Jauch Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: William Jauch
Entity Title: Not reported
Affiliation Address: 1127 Mockingbird Ct.

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95120

Affiliation Phone: (408) 268-5829

Affiliation Type Desc: **Document Preparer Entity Name:** William Jauch Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact

Entity Name: William Jauch
Entity Title: Not reported
Affiliation Address: 725 Lenzen Ave.
Affiliation City: San Jose

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95126
Affiliation Phone: (408) 278-9807

Affiliation Type Desc: Legal Owner

Entity Name: COMMON GROUND LANDSCAPE MGMT

Entity Title: Not reported
Affiliation Address: 725 LENZEN AV
Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95126

Affiliation Phone: (408) 278-9807

CUPA SANTA CLARA:

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 4-6 CHEMICALS

 Latitude:
 37.336464

 Longitude:
 -121.909754

 Record ID:
 PR0410100

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Facility ID: FA0271505

Region: SANTA CLARA

PE#: 2201

Program Description: GENERATES WASTE OIL ONLY

 Latitude:
 37.336464

 Longitude:
 -121.909754

 Record ID:
 PR0410101

 Facility ID:
 FA0271505

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-0651

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 601564

Class: Auto Wrecking/Misc Simple Facility

CERS TANKS:

 Site ID:
 230363

 CERS ID:
 T0608500684

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Site ID: 21118 CERS ID: 10355404

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 11/03/2015.

Funnels

were in use but there was still oil spilled on the top of the drums.

hazardous waste area and maintain it in a way to minimize the

There was also absorbent in the secondary containment and some outside secondary containment. Store used/contaminated absorbent in a container with a lid and if determined to be hazardous waste, properly label the container. Respond to spills as they happen. Clean up the

potential for releases to the environment.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22,

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes: Returned to compliance on 11/03/2015.

_ The used

oil filter container did not have an accumulation start date.

Determine the start date and properly mark the date on the label.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete, accurate, and up-to-date.

Violation Notes: Returned to compliance on 11/03/2015.

Facility

last submitted an HMBP in 2012. Submit a complete HMBP on FrontCounter or CERS (CERS ID# 10355404). Ensure all three HMBP sections (Facility Information, Hazardous Materials Inventory, and Emergency Response and

Training Plans) are submitted annually to re-certify the HMBP.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers with

the following requirements: "Hazardous Waste", name and address of the

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

generator, physical and chemical characteristics of the Hazardous

Waste, and starting accumulation date.

Violation Notes: Returned to compliance on 11/03/2015.

The used

oil containers had illegible labels. Ensure all hazardous waste is properly marked with the required information. Hazardous waste labels

provided during the inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW **CERS** Violation Source:

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

Violation Date: 09-29-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Returned to compliance on 11/03/2015.

The used

oil containers were open during the inspection. One had filters and containers actively draining into it, the other did not. Ensure all hazardous waste containers are kept closed except when adding or

removing hazardous waste and at the close of business.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 21118

COMMON GROUND LANDSCAPE MGMT Site Name:

Violation Date: 09-29-2015

22 CCR 16 66266.130 - California Code of Regulations, Title 22, Citation:

Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and

fuel filters.

Violation Notes: Returned to compliance on 11/03/2015.

The used

oil filter drum was open during the inspection. The container should

only be opened when adding or removing filters.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Evaluation:

Eval General Type: Compliance Evaluation Inspection

09-29-2015 Eval Date: Violations Found: Yes

Eval Type: Routine done by local agency

Landscape company, hazardous waste generated from maintenance of **Eval Notes:**

equipment. EPA ID# CAL000274496 is active. Emergency equipment present

and maintained, emergency actions form posted near phone. eMail:

mail@commongroundlandscapeinc.com

Eval Division: Santa Clara County Environmental Health

Eval Program: HW **Eval Source: CERS**

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Eval General Type: Compliance Evaluation Inspection

Eval Date: 09-29-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Landscaping business. Storing motor oil, used oil, and various

fertilizers in HMBP quantities. Smaller quantities of two-stroke engine oil, paint, surfactants etc. also stored. Contact me once your CERS account is set up, I will connect you to the facility already

created for your business. eMail: mail@commongroundlandscapeinc.com NOTE: Beginning January 1, 2015 all annual HBMP training must be documented and the documents retained for 3 years. Contact me for more

information. A sample training log attached with this report.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Enforcement Action:

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

 Site Address:
 725 LENZEN AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 09-29-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP Enf Action Source: CERS

Site ID: 21118

Site Name: COMMON GROUND LANDSCAPE MGMT

 Site Address:
 725 LENZEN AV

 Site City:
 SAN JOSE

 Site Zip:
 95126

 Enf Action Date:
 09-29-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW
Enf Action Source: CERS

Affiliation:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Operator
Entity Name: William Jauch

Direction Distance

Elevation Site Database(s) EPA ID Number

COMMON GROUND LANDSCAPE MGMT (Continued)

S100274371

EDR ID Number

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 592-9048

Affiliation Type Desc: Parent Corporation

Entity Name: COMMON GROUND LANDSCAPE MGMT

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address

Mailing Address **Entity Name:** Entity Title: Not reported Affiliation Address: 725 LENZEN AV Affiliation City: SAN JOSE Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: 95126 Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: William Jauch
Entity Title: President
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: William Jauch
Entity Title: Not reported
Affiliation Address: 1127 Mockingbird Ct.

Affiliation City: San Jose

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95120

Affiliation Phone: (408) 268-5829

Affiliation Type Desc: **Document Preparer Entity Name:** William Jauch Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COMMON GROUND LANDSCAPE MGMT (Continued)

Affiliation Type Desc: **Environmental Contact**

Entity Name: William Jauch Entity Title: Not reported Affiliation Address: 725 Lenzen Ave. Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95126 Affiliation Phone: (408) 278-9807

Affiliation Type Desc: Legal Owner

Entity Name: COMMON GROUND LANDSCAPE MGMT

Entity Title: Not reported Affiliation Address: 725 LENZEN AV Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: **United States** Affiliation Zip: 95126

Affiliation Phone: (408) 278-9807

AJ210 **BRANDENBERG, STAEDLER & MOORE** SEMS-ARCHIVE 1000310663 153 W JULIAN ST CPS-SLIC NE CAD981671647

1/4-1/2 SAN JOSE, CA 95110

0.402 mi.

2122 ft. Site 2 of 5 in cluster AJ

Relative: SEMS Archive:

Higher 0902488 Site ID: EPA ID: CAD981671647 Actual:

86 ft. Cong District: 10 FIPS Code: 06085

FF: Ν

NPL: Not on the NPL

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Latitude: 37.331667 Longitude: -121.878333

SEMS Archive Detail:

09 Region: Site ID: 0902488 CAD981671647 EPA ID:

BRANDENBERG, STAEDLER & MOORE Site Name:

NPL: FF: Ν OU: 00 Action Code: SI Action Name: SI SEQ:

1987-06-01 04:00:00 Start Date: Finish Date: 1987-06-01 04:00:00

Qual: Current Action Lead: **EPA Perf**

Region: 09 Site ID: 0902488 EPA ID: CAD981671647

BRANDENBERG, STAEDLER & MOORE Site Name:

S100274371

WDS

CERS

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BRANDENBERG, STAEDLER & MOORE (Continued)

1000310663

NPL: Ν FF: Ν OU: 00 Action Code: 00

Action Name: SITE REASS

SEQ:

Start Date: 2013-07-01 05:00:00 Finish Date: 2014-04-14 04:00:00

Qual: **Current Action Lead: EPA Perf**

Region: 09 Site ID: 0902488 EPA ID: CAD981671647

BRANDENBERG, STAEDLER & MOORE Site Name:

NPL: FF: Ν OU: 00 Action Code: PΑ Action Name: PΑ SEQ:

Start Date: 1987-02-01 05:00:00 Finish Date: 1987-06-01 04:00:00

Qual:

EPA Perf Current Action Lead:

Region: 09 Site ID: 0902488 EPA ID: CAD981671647

Site Name: BRANDENBERG, STAEDLER & MOORE

NPL: FF: Ν OU: 00 Action Code: DS Action Name: DISCVRY

SEQ:

Start Date: 1987-01-01 05:00:00 Finish Date: 1987-01-01 05:00:00 Qual: Not reported

Current Action Lead: Other

CPS-SLIC:

Region: STATE

Facility Status: **Completed - Case Closed**

Status Date: 06/30/2003 Global Id: SL18218598

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported 37.339457 Latitude: Longitude: -121.896624

Cleanup Program Site Case Type: Case Worker: MBR

Local Agency: Not reported RB Case Number: 43S0172 File Location: Regional Board

Potential Media Affected: Indoor Air, Other Groundwater (uses other than drinking water), Soil,

Direction Distance

Elevation Site Database(s) EPA ID Number

BRANDENBERG, STAEDLER & MOORE (Continued)

1000310663

EDR ID Number

Soil Vapor

Potential Contaminants of Concern: 1,1,1-Trichloroethane (TCA)

Site History: TCA release from machine shop, since cleaned up, post-cleanup

monitoring in effect

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region: 2

Facility ID: SL18218598

Facility Status: Remedial action (cleanup) Underway

Date Closed: Not reported
Local Case #: Not reported
How Discovered: RPR
Leak Cause: Not reported
Leak Source: Not reported
Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: Not reported Date Preliminary Site Assessment Began: Not reported Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

WDS:

Facility ID: San Francisco Bay 438194002

Facility Type: Industrial - Facility that treats and/or disposes of liquid or

semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water

pumping.

Facility Status: Active - Any facility with a continuous or seasonal discharge that is

under Waste Discharge Requirements.

NPDES Number: CAG912003 The 1st 2 characters designate the state. The remaining 7

are assigned by the Regional Board

Subregion: 2

Facility Telephone: 4082795200 Facility Contact: BILL BARON

Agency Name: BRANDENBURG FAMILY ASSOCIATES

Agency Address: 1122 Willow Street Suite 200

Agency City,St,Zip: SAN JOSE 95125
Agency Contact: BILL BARON
Agency Telephone: 4082795200
Agency Type: Private
SIC Code: 7399
SIC Code 2: Not reported

Primary Waste Type: Hazardous/Influent or Solid Wastes that contain toxic, corrosive,

ignitable or reactive substances and must be managed according to

applicable DOHS standards.

Primary Waste: CNWTRS Waste Type2: Not reported

Waste2: Contaminated Ground Water

Primary Waste Type: Hazardous/Influent or Solid Wastes that contain toxic, corrosive,

ignitable or reactive substances and must be managed according to

applicable DOHS standards.

Direction Distance

Elevation Site Database(s) EPA ID Number

BRANDENBERG, STAEDLER & MOORE (Continued)

1000310663

EDR ID Number

Secondary Waste: Not reported Secondary Waste Type: Not reported

Design Flow: 0
Baseline Flow: 0

Reclamation: No reclamation requirements associated with this facility.

POTW: The facility is not a POTW.

Treat To Water: Moderate Threat to Water Quality. A violation could have a major

adverse impact on receiving biota, can cause aesthetic impairment to a significant human population, or render unusable a potential domestic or municipal water supply. Awsthetic impairment would include nuisance

from a waste treatment facility.

Complexity: Category B - Any facility having a physical, chemical, or biological

waste treatment system (except for septic systems with subsurface disposal), or any Class II or III disposal site, or facilities without treatment systems that are complex, such as marinas with petroleum

products, solid wastes, and sewage pump out facilities.

CERS TANKS:

 Site ID:
 236213

 CERS ID:
 SL18218598

CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: MICHAEL ROCHETTE - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY STREET, SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

AJ211 BRANDENBURG FAMILY ASSOC Cortese \$105026260

NE 153 JULIAN ENF N/A

1/4-1/2 SAN JOSE, CA 95110 HIST CORTESE

0.402 mi.

2122 ft. Site 3 of 5 in cluster AJ

Relative: CORTESE: Higher Region:

 Higher
 Region:
 CORTESE

 Actual:
 Envirostor Id:
 Not reported

 86 ft.
 Site/Facility Type:
 Not reported

Cleanup Status: Not reported Status Date: Not reported Site Code: Not reported Not reported Latitude: Not reported Longitude: Not reported Owner: Enf Type: Not reported Not reported Swat R: CORTESE Flag: Order No: Not reported

Waste Discharge System No: Not reported Effective Date: Not reported

Region 2: 2

WID ld: 2 438194N01

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

Solid Waste Id No: Not reported Waste Management Uit Name: Not reported

File Name: Cease Desist Orders & Cleanup Abatement Orders

Region: CORTESE Envirostor Id: Not reported Not reported Site/Facility Type: Cleanup Status: Not reported Status Date: Not reported Site Code: Not reported Latitude: Not reported Longitude: Not reported Owner: Not reported Enf Type: Not reported Swat R: Not reported CORTESE Flag: Order No: Not reported Waste Discharge System No: Not reported Effective Date: Not reported Region 2: 2 WID Id: 2 438194N01 Solid Waste Id No: Not reported

Waste Management Uit Name: Not reported

File Name: Cease Desist Orders & Cleanup Abatement Orders

Region: **CORTESE** Envirostor Id: Not reported Site/Facility Type: Not reported Cleanup Status: Not reported Status Date: Not reported Site Code: Not reported Latitude: Not reported Longitude: Not reported Owner: Not reported Enf Type: Not reported Swat R: Not reported Flag: CORTESE Order No: Not reported Waste Discharge System No: Not reported Effective Date: Not reported

Region 2: 2

WID Id: 2 438194N01 Solid Waste Id No: Not reported Waste Management Uit Name: Not reported

File Name: Cease Desist Orders & Cleanup Abatement Orders

ENF:

2 Region: Facility Id: 210235

Agency Name: Brandenburg Family Associates

Place Type: Facility Place Subtype: Not reported Facility Type: Industrial

Agency Type: Privately-Owned Business

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported

Direction Distance Elevation

EDR ID Number Site Database(s) **EPA ID Number**

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Not reported Complexity: Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported **UNREGS** Program: Program Category1: **UNREGS** Program Category2: **UNREGS**

Of Programs:

WDID: 2 438194N01 Reg Measure Id: 162018 Reg Measure Type: Unregulated

Region:

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Not reported Reclamation: Not reported Dredge Fill Fee: 301H: Not reported Application Fee Amt Received: Not reported Status: **Never Active** Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported Not reported WDR Review - Amend: WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned: Not reported

Status Enrollee: Ν Individual/General:

Fee Code: Not reported Direction/Voice: **Passive** Enforcement Id(EID): 234694 Region:

Order / Resolution Number: R2-1999-0088

Enforcement Action Type: Clean-up and Abatement Order

Direction Distance Elevation

nce EDR ID Number ation Site Database(s) EPA ID Number

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

Effective Date: 10/20/1999
Adoption/Issuance Date: Not reported
Achieve Date: Not reported
Termination Date: Not reported
ACL Issuance Date: Not reported
EPL Issuance Date: Not reported
Status: Active

Title: Enforcement - 2 438194N01

Description: Not reported Program: UNREGS Latest Milestone Completion Date: Not reported

Of Programs1: 1
Total Assessment Amount: 0
Initial Assessed Amount: 0
Liability \$ Amount: 0
Project \$ Amount: 0
Liability \$ Paid: 0
Project \$ Completed: 0
Total \$ Paid/Completed Amount: 0

Region: 2 Facility Id: 256023

Agency Name: Brandenburg Family Associates

Place Type: Facility
Place Subtype: Not reported
Facility Type: Not reported

Agency Type: Privately-Owned Business

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places: Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Complexity: Not reported Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported Program: **UNREGS** Program Category1: **UNREGS** Program Category2: **UNREGS**

Of Programs: 1

WDID: 2 438194N01

Direction Distance

Elevation Site Database(s) EPA ID Number

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

EDR ID Number

Reg Measure Id: 166487 Unregulated Reg Measure Type: Region: 2 Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Not reported Npdes Type: Not reported Reclamation: Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported **Never Active** Status: 02/21/2013 Status Date: Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned: Not reported Status Enrollee: Ν

Status Enrollee: N Individual/General: I

Fee Code:

Direction/Voice:

Enforcement Id(EID):

Region:

Order / Resolution Number:

Not reported
Passive
226711
299-088

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 10/20/1999
Adoption/Issuance Date: Not reported
Achieve Date: Not reported
Termination Date: Not reported
ACL Issuance Date: Not reported
EPL Issuance Date: Not reported
Status: Active

Title: Enforcement - 2 438194N01
Description: Amendment of SCR 94-027

Program: UNREGS
Latest Milestone Completion Date: Not reported

Of Programs1: 1
Total Assessment Amount: 0
Initial Assessed Amount: 0
Liability \$ Amount: 0
Project \$ Amount: 0
Liability \$ Paid: 0
Project \$ Completed: 0
Total \$ Paid/Completed Amount: 0

Region: 2 Facility Id: 210235

Agency Name: Brandenburg Family Associates

Place Type: Facility
Place Subtype: Not reported
Facility Type: Industrial

Agency Type: Privately-Owned Business

Distance Elevation Site

Site Database(s) EPA ID Number

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

EDR ID Number

Of Agencies: Not reported Place Latitude: Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places: 1

Reg Meas Source Of Facility: Design Flow: Not reported Threat To Water Quality: Not reported Complexity: Not reported Pretreatment: Not reported Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported UNREGS Program: Program Category1: **UNREGS** Program Category2: **UNREGS**

Of Programs:

 WDID:
 2 438194N01

 Reg Measure Id:
 162018

 Reg Measure Type:
 Unregulated

Region: 2

Order #: Not reported Npdes# CA#: Not reported Not reported Major-Minor: Not reported Npdes Type: Reclamation: Not reported Dredge Fill Fee: Not reported 301H: Not reported Application Fee Amt Received: Not reported **Never Active** Status: Status Date: 02/21/2013 Not reported Effective Date: Not reported Expiration/Review Date: Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned: Not reported

Status Enrollee: N Individual/General: I

Fee Code: Not reported Direction/Voice: Passive Enforcement Id(EID): 223285

Direction Distance Elevation

n Site Database(s) EPA ID Number

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

EDR ID Number

Region: 2 Order / Resolution Number: 94-027

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 02/16/1994
Adoption/Issuance Date: Not reported
Achieve Date: Not reported
Termination Date: Not reported
ACL Issuance Date: Not reported
EPL Issuance Date: Not reported
Status: Active

Title: Enforcement - 2 438194N01

Description: SCR-FINAL SCR.
Program: UNREGS
Latest Milestone Completion Date: Not reported

Of Programs1: 1
Total Assessment Amount: 0
Initial Assessed Amount: 0
Liability \$ Amount: 0
Project \$ Amount: 0
Liability \$ Paid: 0
Project \$ Completed: 0
Total \$ Paid/Completed Amount: 0

Region: 2 Facility Id: 210235

Agency Name: Brandenburg Family Associates

Place Type: Facility
Place Subtype: Not reported
Facility Type: Industrial

Agency Type: Privately-Owned Business

Of Agencies:

Place Latitude: Not reported Place Longitude: Not reported SIC Code 1: Not reported SIC Desc 1: Not reported SIC Code 2: Not reported SIC Desc 2: Not reported SIC Code 3: Not reported SIC Desc 3: Not reported NAICS Code 1: Not reported NAICS Desc 1: Not reported NAICS Code 2: Not reported NAICS Desc 2: Not reported NAICS Code 3: Not reported NAICS Desc 3: Not reported

Of Places:

Source Of Facility: Reg Meas Design Flow: Not reported Threat To Water Quality: Not reported Complexity: Not reported Not reported Pretreatment: Facility Waste Type: Not reported Facility Waste Type 2: Not reported Facility Waste Type 3: Not reported Facility Waste Type 4: Not reported Program: **UNREGS** Program Category1: **UNREGS**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BRANDENBURG FAMILY ASSOC (Continued)

S105026260

Program Category2: **UNREGS**

Of Programs:

WDID: 2 438194N01 Reg Measure Id: 162018 Reg Measure Type: Unregulated

Region:

Order #: Not reported Npdes# CA#: Not reported Major-Minor: Not reported Npdes Type: Not reported Reclamation: Not reported Not reported Dredge Fill Fee: Not reported 301H: Application Fee Amt Received: Not reported **Never Active** Status: Status Date: 02/21/2013 Effective Date: Not reported Expiration/Review Date: Not reported Termination Date: Not reported WDR Review - Amend: Not reported WDR Review - Revise/Renew: Not reported WDR Review - Rescind: Not reported WDR Review - No Action Required: Not reported WDR Review - Pending: Not reported WDR Review - Planned: Not reported

Status Enrollee: Ν Individual/General:

Fee Code: Not reported Direction/Voice: **Passive** 222983 Enforcement Id(EID): Region: Order / Resolution Number: 88-062

Enforcement Action Type: Clean-up and Abatement Order

Effective Date: 04/20/1988 Not reported Adoption/Issuance Date: Achieve Date: Not reported Termination Date: Not reported ACL Issuance Date: Not reported **EPL Issuance Date:** Not reported Status: Historical

Title: Enforcement - 2 438194N01

Description: SCR - ESTABLISHES A COMPLIANCE SCHEDULE FOR SOIL & GW

REMEDIATION

Program: **UNREGS** Latest Milestone Completion Date: Not reported

Of Programs1: **Total Assessment Amount:** 0 Initial Assessed Amount: 0 Liability \$ Amount: n Project \$ Amount: 0 Liability \$ Paid: 0 Project \$ Completed: 0 Total \$ Paid/Completed Amount: 0

HIST CORTESE:

Region: CORTESE Facility County Code: 43

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BRANDENBURG FAMILY ASSOC (Continued) S105026260

Reg By: WBC&D Reg Id: 2 438194N01

AJ212 **BRANDENBURG PROPERTIES** LUST S102795416

N/A

160 W JULIAN ST ΝE 1/4-1/2 SAN JOSE, CA

0.402 mi.

2123 ft. Site 4 of 5 in cluster AJ Relative: LUST SANTA CLARA:

Higher SANTA CLARA Region: SCVWD ID: 07S1E07H04F Actual: 85 ft. Date Closed: 03/27/2002 EDR Link ID: 07S1E07H04F

AJ213 BRANDENBURG PROPERTIES HIST LUST S105512865

160 W JULIAN ST ΝE N/A

1/4-1/2 SAN JOSE, CA

0.402 mi.

2123 ft. Site 5 of 5 in cluster AJ

Relative: HIST LUST SANTA CLARA: Higher Region: SANTA CLARA

Region Code: Actual:

SCVWD ID: 07S1E07H04 85 ft. Oversite Agency: SFRWQCB

> 2001-09-07 00:00:00 Date Listed: 2002-03-27 00:00:00 Closed Date:

214 **THOMAS FALLON HOUSE** LUST S102438919 **ENE** 175 W SAINT JOHN ST **HIST LUST** N/A

1/4-1/2 **SAN JOSE, CA 95112**

0.406 mi. 2145 ft.

LUST: Relative:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608524383 88 ft.

Global Id: T0608524383 Latitude: 37.336978 -121.894893 Longitude:

Status: Completed - Case Closed

10/03/1994 Status Date: Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil

Potential Contaminants of Concern: Not reported Site History: Not reported

LUST:

T0608524383 Global Id:

CERS

Direction Distance Elevation

levation Site Database(s) EPA ID Number

THOMAS FALLON HOUSE (Continued)

S102438919

EDR ID Number

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608524383

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608524383

 Action Type:
 RESPONSE

 Date:
 05/06/1993

Action: Other Report / Document

 Global Id:
 T0608524383

 Action Type:
 Other

 Date:
 01/01/1991

 Action:
 Leak Reported

Global Id: T0608524383
Action Type: ENFORCEMENT
Date: 10/03/1994

Action: Closure/No Further Action Letter

LUST:

Global Id: T0608524383

Status: Completed - Case Closed

Status Date: 10/03/1994

Global Id: T0608524383

Status: Open - Case Begin Date

Status Date: 01/01/1991

LUST REG 2:

Region: 2 Facility Id: Not reported

Facility Status: Case Closed
Case Number: 07S1E08M02f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

THOMAS FALLON HOUSE (Continued)

S102438919

Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E08M02F 10/03/1994 Date Closed: EDR Link ID: 07S1E08M02F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E08M02 Oversite Agency: SCVWD

1992-05-20 00:00:00 Date Listed: Closed Date: 1994-10-03 00:00:00

CERS TANKS:

Site ID: 189899 CERS ID: T0608524383

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

1515 CLAY ST SUITE 1400 Affiliation Address:

OAKLAND Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

U-HAUL MOVING & STORAGE AT THE ALAMEDA **AK215** LUST S102439368

WSW 1027 THE ALAMEDA HIST LUST N/A

SAN JOSE, CA 95126 1/4-1/2 **CUPA Listings**

HIST CORTESE

2185 ft. Site 1 of 2 in cluster AK **CERS**

Relative: LUST REG 2:

0.414 mi.

Higher Region:

Facility Id: Not reported Actual: Facility Status: Case Closed 98 ft.

07S1E07N03f Case Number: How Discovered: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

U-HAUL MOVING & STORAGE AT THE ALAMEDA (Continued)

S102439368

EDR ID Number

Leak Cause: Not reported Leak Source: Not reported Not reported Date Leak Confirmed: LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07N03 Oversite Agency: SCVWD

Date Listed: 1992-07-30 00:00:00 Closed Date: 1993-08-16 00:00:00

CUPA SANTA CLARA:

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

Latitude: 37.3317 Longitude: -121.9097 Record ID: PR0397477 Facility ID: FA0700887

HIST CORTESE:

CORTESE Region: Facility County Code: 43 Reg By: **LTNKA** Reg Id: 43-1103

CERS TANKS:

Site ID: 404584 10343998 CERS ID:

CERS Description: Chemical Storage Facilities

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 07-21-2016 Violations Found: No

Eval Type: Routine done by local agency

A HAZARDOUS MATERIALS BUSINESS PLAN WAS CONDUCTED WITH MR. RAHUL **Eval Notes:**

> NAIDU- U-HAUL GENERAL MANAGER ON JULY 20, 2016 AND THE NOTICE OF INSPECTION REPORT WAS ISSUED ON JULY 21, 2016. A FACILITY WALK THROUGH WAS CONDUCTED TO VERIFY CHEMICAL QUANTITIES AND MAP STORAGE LOCATIONS. ALL CHEMICAL QUANTITIES AND MAP STORAGE LOCATIONS WERE CURRENT. THE FACILITY HAD A CURRENT HAZARDOUS MATERIAL BUSINESS PLAN PERMIT. ALL INFORMATIONS ENTERED ELECTRONICALLY IN THE CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM. (CERS) SUBMITTED IN 2016 WAS CURRENT. NO VIOLATIONS

WERE NOTED DURING THE FACILITY WALK THROUGH.

Eval Division: Santa Clara County Environmental Health

Eval Program: **HMRRP Eval Source: CERS**

Direction Distance

Elevation Site Database(s) EPA ID Number

U-HAUL MOVING & STORAGE AT THE ALAMEDA (Continued)

S102439368

EDR ID Number

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-17-2015

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: Facility walkthrough conducted with inspector Matt Burge and

facility's general manager, Ray Naidu. Facility stores various automotive maintenance materials in small quantities for vehicle maintenance as well as a 1,150 gallon propane tank for refilling 5 gallon cylinders for retail. The last HMBP submittal on CERS was from 02/20/2015 and verified during this inspection. Note: As of January 1, 2015, HMBP training is required to be documented and retained for three years. Attached with this report is a copy of our training log template which you may use for the required documentation.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-01-2018

Violations Found: No

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous materials business plan (HMBP)

inspection. Facility handles Propane (1 x 1165 gallon aboveground tank) at HMBP-reporting thresholds. No violations were observed.

NOTES: -A HMBP was submitted to CERS on 12/29/17 and was reviewed as

complete. -Training documentation is retained electronically. -Small quantities of hazardous materials are used on-site but according to personnel only to perform hitch installations or wiring repairs (it appears small quantities of motor oil and coolant may be handled on-site for "topping off" rental vehicles). As a reminder, ensure any hazardous materials containers are used until completely empty (no liquid contents will pour out of them) before disposing of them into the trash. -A hard-copy HMBP is provided to the facility by U-haul

corporate.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Coordinates:

Site ID: 404584

Facility Name: U-Haul Moving & Storage at The Alameda

Env Int Type Code: HMBP
Program ID: 10343998
Coord Name: Not reported
Ref Point Type Desc: Unknown
Latitude: 37.332111
Longitude: -121.909454

Affiliation:

Affiliation Type Desc: Legal Owner

Entity Name: U-Haul Co. of California

Entity Title: Not reported

Affiliation Address: c/o U-Haul Co. of South Bay, 44511 Grimmer Blvd, Bldg A

Affiliation City: Fremont Affiliation State: CA

Affiliation Country: United States

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

U-HAUL MOVING & STORAGE AT THE ALAMEDA (Continued)

S102439368

Affiliation Zip: 94538

Affiliation Phone: (510) 656-6200 Affiliation Type Desc: **CUPA** District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95112-2716 Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Operator

Entity Name: U-Haul Moving & Storage at The Alameda

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (510) 656-6200

Affiliation Type Desc: Facility Mailing Address Entity Name: Mailing Address Entity Title: Not reported

Affiliation Address: 44511 Grimmer Blvd, Bldg A

Affiliation City: Fremont Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 94538 Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: Kamalveer Barn

Entity Title: Marketing Company President

Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Parent Corporation Affiliation Type Desc: Entity Name: U-Haul Co. of South Bay

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner

Entity Name: Amerco Real Estate Company

Entity Title: Not reported Affiliation Address: 2727 N Central Ave

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

U-HAUL MOVING & STORAGE AT THE ALAMEDA (Continued)

S102439368

Affiliation City: Phoenix
Affiliation State: AZ
Affiliation Country: United States
Affiliation Zip: 85004
Affiliation Phone: (602) 263-6555

Affiliation Type Desc: **Document Preparer Entity Name:** Yanira Valdez Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: Kamalveer Barn
Entity Title: Not reported

Affiliation Address: 44511 Grimmer Blvd, Bldg A

Affiliation City: Fremont Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 94538

Affiliation Phone: (510) 656-6200

AK216 DOWNTOWN MC LUST U001603882 WSW 1027 THE ALAMEDA HIST UST N/A

1/4-1/2 SAN JOSE, CA 95220

0.414 mi.

2185 ft. Site 2 of 2 in cluster AK

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

98 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608570600

Global Id: T0608570600
Latitude: 37.332236
Longitude: -121.909415

Status: Completed - Case Closed

Status Date: 08/16/1993
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Not reported Site History: Not reported

LUST:

Global Id: T0608570600

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND

CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

DOWNTOWN MC (Continued)

U001603882

EDR ID Number

Email: Not reported Phone Number: Not reported

Global Id: T0608570600

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608570600

 Action Type:
 Other

 Date:
 01/01/1991

 Action:
 Leak Reported

Global Id: T0608570600
Action Type: ENFORCEMENT
Date: 08/16/1993

Action: Closure/No Further Action Letter

Global Id: T0608570600
Action Type: RESPONSE
Date: 09/08/1992

Action: Other Report / Document

LUST:

Global Id: T0608570600

Status: Completed - Case Closed

Status Date: 08/16/1993

Global Id: T0608570600

Status: Open - Case Begin Date

Status Date: 01/01/1991

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07\$1E07N03F

 Date Closed:
 08/16/1993

 EDR Link ID:
 07\$1E07N03F

HIST UST:

Telephone:

File Number: 000209DD

URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000209DD.pdf

4082994884

Region: STATE
Facility ID: 00000021743
Facility Type: Other
Other Type: RENTAL YARD
Contact Name: CHUCK CULLI

Owner Name: U HAUL CO OF EAST BAY
Owner Address: 44511 GRIMMER BLVD.

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DOWNTOWN MC (Continued) U001603882

Owner City, St, Zip: FREMONT, CA 945538

Total Tanks: 0002

Tank Num: 001 Container Num: 1 1979 Year Installed: 00010000 Tank Capacity: Tank Used for: **PRODUCT** Type of Fuel: **REGULAR** Container Construction Thickness: Not reported

Leak Detection: Visual, Stock Inventor

Tank Num: 002 Container Num:

Year Installed: Not reported Tank Capacity: 00000000 Tank Used for: Not reported Type of Fuel: Not reported Container Construction Thickness: Not reported Not reported Leak Detection:

Click here for Geo Tracker PDF:

CERS TANKS:

Site ID: 226907 CERS ID: T0608570600

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) Entity Name:

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

OAKLAND Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

AH217 NATIONAL RAILROAD PASSENGER CO RCRA-SQG 1000819563

SSE 510 W SAN FERNANDO ST LUST CAD983655549
1/4-1/2 SAN JOSE, CA 95110 HIST LUST

0.425 mi.
2243 ft. Site 4 of 4 in cluster AH ECHO
CERS

Relative:

Higher RCRA-SQG:

Actual: Date form received by agency: 09/01/1996

91 ft. Facility name: NATIONAL RAILROAD PASSENGER CO

Facility address: 510 W SAN FERNANDO ST

SAN JOSE, CA 95110 EPA ID: CAD983655549

Mailing address: W SAN FERNANDO ST

SAN JOSE, CA 95110

Contact: Not reported Contact address: Not reported

Not reported

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: J P B SAMTRANS
Owner/operator address: 1250 SAN CARLOS AVE
SAN CARLOS, CA 94070

Owner/operator country:

Owner/operator telephone:

Owner/operator email:

Owner/operator fax:

Not reported

Not reported

Not reported

Owner/operator extension:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No **EDR ID Number**

Direction Distance

Elevation Site Database(s) EPA ID Number

NATIONAL RAILROAD PASSENGER CO (Continued)

1000819563

EDR ID Number

Used oil transporter: No

Violation Status: No violations found

LUST:

Lead Agency: SANTA CLARA COUNTY LOP

Case Type: LUST Cleanup Site

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500278

 Global Id:
 T0608500278

 Latitude:
 37.3289285821236

 Longitude:
 -121.900691986084

 Status:
 Completed - Case Closed

Status Date: 03/30/1992
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

Global Id: T0608500278

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500278

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE

Email: Not reported Phone Number: 4089183400

LUST:

 Global Id:
 T0608500278

 Action Type:
 Other

 Date:
 11/17/1989

 Action:
 Leak Reported

 Global Id:
 T0608500278

 Action Type:
 REMEDIATION

 Date:
 11/17/1989

 Action:
 Excavation

Global Id: T0608500278
Action Type: ENFORCEMENT
Date: 03/30/1992

Action: Closure/No Further Action Letter

Global Id: T0608500278

Direction Distance

Elevation Site Database(s) EPA ID Number

NATIONAL RAILROAD PASSENGER CO (Continued)

EDR ID Number

1000819563

Action Type: ENFORCEMENT Date: 02/07/1991

Action: Notice of Responsibility - #39844

 Global Id:
 T0608500278

 Action Type:
 RESPONSE

 Date:
 06/19/1989

Action: Other Report / Document

LUST:

Global Id: T0608500278

Status: Completed - Case Closed

Status Date: 03/30/1992

Global Id: T0608500278

Status: Open - Case Begin Date

Status Date: 11/17/1989

Global Id: T0608500278

Status: Open - Site Assessment

Status Date: 11/17/1989

Global Id: T0608500278

Status: Open - Verification Monitoring

Status Date: 03/07/1991

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E18B01f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: 3/7/1991

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E18B01F

 Date Closed:
 03/30/1992

 EDR Link ID:
 07S1E18B01F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E18B01 Oversite Agency: SCVWD

Direction Distance

Elevation Site Database(s) EPA ID Number

NATIONAL RAILROAD PASSENGER CO (Continued)

1000819563

EDR ID Number

Date Listed: 1990-01-01 00:00:00 Closed Date: 1992-03-30 00:00:00

FINDS:

Registry ID: 110002889679

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000819563 Registry ID: 110002889679

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002889679

CERS TANKS:

Site ID: 199353 CERS ID: T0608500278

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

AL218 VERIZON BUSINESS: SNTFCA LUST S110060945 WNW

500 STOCKTON AV AST N/A **CUPA Listings**

0.427 mi. HIST CORTESE SAN JOSE HAZMAT 2257 ft. Site 1 of 2 in cluster AL

Relative:

1/4-1/2

Higher LUST:

SAN JOSE, CA 95113

Lead Agency: SANTA CLARA COUNTY LOP Actual:

Case Type: **LUST Cleanup Site** 85 ft.

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501530

Global Id: T0608501530 Latitude: 37.337926 -121.90931 Longitude:

Status: Completed - Case Closed

Status Date: 02/19/1998 Case Worker: UST RB Case Number: Not reported

SANTA CLARA COUNTY LOP Local Agency:

Stored on Microfiche File Location:

Local Case Number: Not reported

Other Groundwater (uses other than drinking water) Potential Media Affect:

Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608501530 Global Id:

Regional Board Caseworker Contact Type: Regional Water Board Contact Name:

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND Not reported Email: Phone Number: Not reported

Global Id: T0608501530

Contact Type: Local Agency Caseworker Contact Name: UST CASE WORKER SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Email: Not reported Phone Number: 4089183400

LUST:

Global Id: T0608501530 Action Type: Other 07/21/1989 Date: Action: Leak Reported

Global Id: T0608501530 Action Type: **RESPONSE** Date: 10/13/1995

Action: Other Report / Document

Global Id: T0608501530 Action Type: RESPONSE 02/19/1998 Date:

Action: Other Report / Document **EDR ID Number**

CERS

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VERIZON BUSINESS: SNTFCA (Continued)

S110060945

Global Id: T0608501530 **ENFORCEMENT** Action Type: Date: 09/25/1995

Action: Notice of Responsibility - #39951

Global Id: T0608501530 Action Type: **ENFORCEMENT** Date: 08/31/1996 Action: Staff Letter - #27096

Global Id: T0608501530 **ENFORCEMENT** Action Type: Date: 05/31/1996 Action: Staff Letter - #27094

Global Id: T0608501530 REMEDIATION Action Type: 01/01/1989 Date: Action: Excavation

Global Id: T0608501530 Action Type: **ENFORCEMENT** Date: 02/19/1998

Action: Closure/No Further Action Letter

Global Id: T0608501530 Action Type: **RESPONSE** Date: 10/15/1996

Action: Monitoring Report - Quarterly

Global Id: T0608501530 Action Type: **RESPONSE** Date: 01/15/1997

Action: Monitoring Report - Quarterly

Global Id: T0608501530 Action Type: **RESPONSE** Date: 04/15/1997

Monitoring Report - Quarterly Action:

Global Id: T0608501530 Action Type: **RESPONSE** Date: 07/15/1997

Monitoring Report - Quarterly Action:

Global Id: T0608501530 Action Type: **RESPONSE** Date: 10/15/1997

Action: Monitoring Report - Quarterly

T0608501530 Global Id: Action Type: **RESPONSE** Date: 07/15/1996

Remedial Progress Report Action:

LUST:

T0608501530 Global Id:

Direction Distance

Elevation Site Database(s) EPA ID Number

VERIZON BUSINESS: SNTFCA (Continued)

S110060945

EDR ID Number

Status: Completed - Case Closed

Status Date: 02/19/1998

Global Id: T0608501530

Status: Open - Case Begin Date

Status Date: 08/28/1987

Global Id: T0608501530

Status: Open - Site Assessment

Status Date: 08/28/1987

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07M02F

 Date Closed:
 02/19/1998

 EDR Link ID:
 07S1E07M02F

AST:

Certified Unified Program Agencies: Not reported

Owner: MCI dba Verizon Business

Total Gallons: Not reported CERSID: 10096255 Facility ID: FA0263708

Business Name: MCI, dba Verizon Business

 Phone:
 408-273-7087

 Fax:
 909-629-3471

 Mailing Address:
 280 S. Locust St.

 Mailing Address City:
 Pomona

Mailing Address State: CA
Mailing Address Zip Code: 91766

Operator Name: Verizon Business
Operator Phone: 909-620-5962
Owner Phone: 909-620-5962
Owner Mail Address: 280 S. Locust St

Owner State: CA Owner Zip Code: 91766 **United States** Owner Country: Property Owner Name: Not reported Property Owner Phone: Not reported Property Owner Mailing Address: Not reported Property Owner City: Not reported Property Owner Stat: Not reported Property Owner Zip Code: Not reported Property Owner Country: Not reported EPAID: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2011

Program Description: APSA FACILITY-SPCC TEMPLATE (<10,000 GAL CAP)

 Latitude:
 37.337429

 Longitude:
 -121.909666

 Record ID:
 PR0399664

 Facility ID:
 FA0263708

Direction Distance

Elevation Site Database(s) EPA ID Number

VERIZON BUSINESS: SNTFCA (Continued)

S110060945

EDR ID Number

Region: SANTA CLARA

PE#: 2240

Program Description: GENERATES < 10 GAL/YR

 Latitude:
 37.337429

 Longitude:
 -121.909666

 Record ID:
 PR0388596

 Facility ID:
 FA0263708

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.337429

 Longitude:
 -121.909666

 Record ID:
 PR0397168

 Facility ID:
 FA0263708

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1570

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 408274

Class: Misc. Complex firms and labs

CERS TANKS:

Site ID: 216065 CERS ID: 70608501530

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

AL219 UNOCAL #0688 S105194601 WNW **500 STOCKTON AVE HIST LUST** N/A

1/4-1/2 SAN JOSE, CA 95126

0.427 mi.

2257 ft. Site 2 of 2 in cluster AL

Relative: LUST REG 2: Higher Region:

Facility Id: Not reported Actual: Facility Status: Case Closed 85 ft. Case Number: 07S1E07M02f

How Discovered: Not reported Leak Cause: Not reported Not reported Leak Source: Not reported Date Leak Confirmed: Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 8/28/1987 Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07M02 Oversite Agency: SCVWD

1990-01-01 00:00:00 Date Listed: Closed Date: 1998-02-19 00:00:00

AM220 **BRANDENBURG PROPERTIES**

NE 355 N SAN PEDRO 1/4-1/2 SAN JOSE, CA

0.431 mi.

2277 ft. Site 1 of 2 in cluster AM

Relative: LUST SANTA CLARA:

Higher Region: SANTA CLARA SCVWD ID: 07S1E07H02F Actual: Date Closed: 03/27/2002 86 ft. 07S1E07H02F EDR Link ID:

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07H02 Oversite Agency: SFRWQCB

2001-09-07 00:00:00 Date Listed: 2002-03-27 00:00:00 Closed Date:

TC05569778.2r Page 549

LUST

HIST LUST

S105512864

N/A

EDR ID Number

Direction Distance

Distance EDR ID Number

Elevation Site EDA ID Number

 AN221
 PG&E SUBSTATION A
 LUST
 \$103473079

 South
 17 OTTERSON ST
 HIST LUST
 N/A

1/4-1/2 SAN JOSE, CA 95110

0.434 mi.

2291 ft. Site 1 of 2 in cluster AN

Relative: LUST REG 2: Higher Region:

HigherRegion:2Actual:Facility Id:Not reported

98 ft. Facility Status: Case Closed
Case Number: 07S1E18B05f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported

Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 3/1/1989
Pollution Characterization Began: 3/1/1989
Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E18B05 Oversite Agency: SCVWD

Date Listed: 1992-06-04 00:00:00 Closed Date: 2001-07-31 00:00:00

AO222 COLLEGE PARK LUST S107142608
NNE 190 RYLAND STREET CERS N/A

1/4-1/2 SAN JOSE, CA 95110 0.434 mi.

2292 ft. Site 1 of 2 in cluster AO

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

91 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608502142

 Global Id:
 T0608502142

 Latitude:
 37.341264

 Longitude:
 -121.898804

Status: Completed - Case Closed

Status Date: 06/28/2005
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Diesel
Site History: Not reported

LUST:

Global Id: T0608502142

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Direction
Distance

Elevation Site Database(s) EPA ID Number

COLLEGE PARK (Continued)

Address:

1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608502142

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608502142

 Action Type:
 Other

 Date:
 11/05/2003

 Action:
 Leak Reported

 Global Id:
 T0608502142

 Action Type:
 RESPONSE

 Date:
 05/30/2002

Action: Unauthorized Release Form

 Global Id:
 T0608502142

 Action Type:
 REMEDIATION

 Date:
 07/15/2003

 Action:
 Not reported

Global Id: T0608502142
Action Type: ENFORCEMENT
Date: 06/28/2005

Action: Closure/No Further Action Letter

Global Id: T0608502142
Action Type: RESPONSE
Date: 10/28/2003

Action: Unauthorized Release Form

 Global Id:
 T0608502142

 Action Type:
 Other

 Date:
 07/15/2003

 Action:
 Leak Discovery

LUST:

Global Id: T0608502142

Status: Completed - Case Closed

Status Date: 06/28/2005

Global Id: T0608502142

Status: Open - Case Begin Date

Status Date: 07/15/2003

Global Id: T0608502142

Status: Open - Site Assessment

EDR ID Number

S107142608

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

COLLEGE PARK (Continued) S107142608

Status Date: 06/27/2005

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E07H07F Date Closed: 06/28/2005 EDR Link ID: 07S1E07H07F

CERS TANKS:

246790 Site ID: CERS ID: T0608502142

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City:

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

1515 CLAY ST SUITE 1400 Affiliation Address:

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

HIST CORTESE \$104397021 **SAN JOSE MERCURY NEWS**

AP223 211 SANTA CLARA East N/A

1/4-1/2 **SAN JOSE, CA 95113**

0.436 mi.

2301 ft. Site 1 of 2 in cluster AP

HIST CORTESE: Relative:

Higher CORTESE Region:

Facility County Code: 43 Actual: Reg By: **LTNKA** 89 ft.

Reg Id: 43-2227

Direction Distance

Elevation Site Database(s) EPA ID Number

AM224 BRANDENBURG PROPERTIES LUST \$105481885

NE 345 SAN PEDRO N CERS N/A

NE 345 SAN PEDRO N 1/4-1/2 SAN JOSE, CA 95113

0.440 mi.

2324 ft. Site 2 of 2 in cluster AM

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

90 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608568823

Global Id: T0608568823 Latitude: 37.339877 Longitude: -121.896756

Status: Completed - Case Closed

Status Date: 03/27/2002
Case Worker: Not reported
RB Case Number: 43-2415

Local Agency: SANTA CLARA COUNTY LOP

File Location:

Local Case Number:

Potential Media Affect:

Not reported

Not reported

Under Investigation

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating

Site History: Not reported

LUST:

Global Id: T0608568823

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE

Email: Not reported Phone Number: 4089183400

LUST:

Global Id: T0608568823
Action Type: RESPONSE
Date: 05/26/2000

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608568823

 Action Type:
 Other

 Date:
 08/01/2001

 Action:
 Leak Reported

 Global Id:
 T0608568823

 Action Type:
 RESPONSE

 Date:
 08/01/2001

Action: Unauthorized Release Form

 Global Id:
 T0608568823

 Action Type:
 RESPONSE

 Date:
 05/22/2003

Action: Other Report / Document

 Global Id:
 T0608568823

 Action Type:
 RESPONSE

 Date:
 01/01/2001

 Action:
 Correspondence

EDR ID Number

Direction
Distance

Elevation Site Database(s) EPA ID Number

BRANDENBURG PROPERTIES (Continued)

S105481885

EDR ID Number

Global Id: T0608568823
Action Type: RESPONSE
Date: 05/10/2000

Action: Soil and Water Investigation Report

 Global Id:
 T0608568823

 Action Type:
 ENFORCEMENT

 Date:
 03/27/2002

Action: Closure/No Further Action Letter

 Global Id:
 T0608568823

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

Global Id: T0608568823
Action Type: ENFORCEMENT
Date: 03/27/2002

Action: Staff Letter - #43/2415

 Global Id:
 T0608568823

 Action Type:
 ENFORCEMENT

 Date:
 11/14/2001

 Action:
 Staff Letter

Global Id: T0608568823
Action Type: ENFORCEMENT
Date: 03/27/2002

Action: Closure/No Further Action Letter

Global Id: T0608568823
Action Type: RESPONSE
Date: 11/27/2001

Action: CAP/RAP - Other Report

 Global Id:
 T0608568823

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608568823

 Action Type:
 Other

 Date:
 03/09/2000

 Action:
 Leak Discovery

Global Id: T0608568823
Action Type: ENFORCEMENT
Date: 03/27/2002

Action: Closure/No Further Action Letter

 Global Id:
 T0608568823

 Action Type:
 Other

 Date:
 03/09/2000

 Action:
 Leak Stopped

LUST:

Global Id: T0608568823

Direction Distance

Elevation Site Database(s) **EPA ID Number**

BRANDENBURG PROPERTIES (Continued)

S105481885

EDR ID Number

Status: Completed - Case Closed

Status Date: 03/27/2002

Global Id: T0608568823

Status: Open - Case Begin Date

03/09/2000 Status Date:

LUST REG 2:

Region:

43-2415 Facility Id: Facility Status: Case Closed Case Number: Not reported How Discovered: Tank Closure

Leak Cause: UNK UNK Leak Source: Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

CERS TANKS:

Site ID: 259115 CERS ID: T0608568823

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP **Entity Name:**

Entity Title: Not reported

1555 Berger Drive, Suite 300 Affiliation Address:

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

S103473094 **AP225** SAN JOSE MERCURY NEWS LUST 211 W. SANTA CLARA ST. **HIST LUST** East N/A **CERS**

1/4-1/2 SAN JOSE, CA 95113

0.441 mi.

Site 2 of 2 in cluster AP 2328 ft.

Relative: LUST:

SANTA CLARA COUNTY LOP Higher Lead Agency:

LUST Cleanup Site Case Type: Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608502045 89 ft.

Global Id: T0608502045 Latitude: 37.3352926033228 Longitude: -121.894973516464

Status: Open - Verification Monitoring

02/01/2018 Status Date:

Map ID MAP FINDINGS
Direction

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

SAN JOSE MERCURY NEWS (Continued)

S103473094

Case Worker: TLF RB Case Number: 14-444

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: 07S1E08M03f

Potential Media Affect: Aquifer used for drinking water supply, Soil

Potential Contaminants of Concern: Benzene, Toluene, Trichloroethylene (TCE), Xylene, Gasoline, Waste Oil / Motor / Hydraulic / Lubric

Site History:

In 1997 a Phase I Environmental Site Assessment (ESA) was performed and a potential UST was noted near the northern site boundary. In January 1998, a Phase II ESA was performed and discovered the presence of petroleum hydrocarbons and related constituents in soil and groundwater beneath the site. In May 1998 two USTs were removed from the site. On May 10, 1998 a UST (Tank 1) with an estimated volume of 8,000 gallons was removed and was suspected to have contained leaded gasoline. On May 19, 1998 a second UST (Tank 2) with an estimated volume of was removed and was suspected to have also contained leaded gasoline. The UST removal included overexcavation of the impacted soils. However, excavation of visibly impacted soils to the north was stopped due to concerns regarding the integrity of Carlysle Street. The maximum level of TPH-g detected below the tank were was 3,300 ppm. At that time 460 tons of soil was removed to Kirby Canyon landfill in Morgan Hill. In September 1999 additional soil sampling was performed. The maximum level of contamination in soil was 280 ppm TPH-g, 2 ppm benzene, 9 ppm toluene, 8.5 ppm ethylbenzene and 38 ppm xylenes. Groundwater contamination was up to 2,400 ppb TPH-g, 11 ppb benzene, 44 ppb toluene, 28 ppb ethylbenzene and 170 ppb xylenes. MTBE was not detected. On December 9, 1999 additional soil was excavated from the area around the former USTs. Approximately 344 tons of soil was removed and disposed of at the Forward Landfill in Manteca on December 17, 1999. Eight soil samples were collected in and around the excavated area. The maximum detected soil concentrations were 14 ppm lead, 19 ppm TPG-g and 0.22 ppm benzene. On December 29, 1999 approximately 93 tons of soil was excavated from the area near the former USTs (between shoring columns 10 and 14) and eventually disposed of at the Forward Landfill in Manteca. Confirmation soil samples detected TPH-g and benzene up to 250 and 1.6 ppm, respectively in sample location E-1-19'). On December 30, 1999 302 tons of soil was excavated and transported to Forward Landfill. Confirmation soil samples collected from sample location E-13 identified an area of concern. Consequently, on December 31, 1999 further excavation was performed between columns 17 and 19 and confirmation samples E-14 through E-16 were collected for chemical analyses. It was determined that the area of concern had been removed. Approximately 302 tons of soil was removed to the Forward Landfill. On February 10, 2000 approximately 20 tons of soil was excavated and disposed at Forward Landfill. Confirmation soil samples taken from the excavation indicated that all constituents were below the affected zone criteria. Prior to March 13, 2000 13 soil samples were collected from the base of the northern portion of the site excavation area. A sample collected between columns 13 and 14 at a depth of 23.5 feet contained 0.83 ppm benzene. Approximately 5 cubic yards (7 tons) of soil was excavated at this location and disposed of off-site. Two additional soil samples collected at this location on January 10, and February 18, 2000. The soils samples were below the affected zone criteria. Groundwater extraction was used to dewater the site to allow for construction activities beginning on October 11, 1999. Extraction rates varied between 5 and 30 gallons

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE MERCURY NEWS (Continued)

S103473094

EDR ID Number

per minute (gpm) from the eleven extraction wells. The permit to discharge water was terminated on March 9, 2000. Approximately 7,176,000 gallons of impacted water was discharged to the sanitary sewer during site development activities.

LUST:

Global Id: T0608502045

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608502045

Contact Type: Local Agency Caseworker Contact Name: TRAVIS L. FLORA

Organization Name: SANTA CLARA COUNTY LOP

Address: 1555 Berger Dr. City: SAN JOSE

Email: travis.flora@cep.sccgov.org

Phone Number: 4089183486

LUST:

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 01/01/2006

 Action:
 Correspondence

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 06/27/2018

 Action:
 Correspondence

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 05/23/2014

Action: Soil and Water Investigation Workplan - Regulator Responded

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 07/15/2015

Action: Site Assessment Report - Regulator Responded

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 03/08/2016

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 Other

 Date:
 03/09/2006

 Action:
 Leak Reported

Global Id: T0608502045 Action Type: RESPONSE

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE MERCURY NEWS (Continued)

S103473094

Date: 01/22/1998

Other Report / Document Action:

Global Id: T0608502045 Action Type: **RESPONSE** Date: 07/30/2018

Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0608502045 Action Type: **ENFORCEMENT** Date: 08/16/2000

Closure/No Further Action Letter Action:

Global Id: T0608502045 Action Type: **RESPONSE** Date: 07/17/2006

Action: Preliminary Site Assessment Workplan

Global Id: T0608502045 **RESPONSE** Action Type: Date: 01/09/2000

Other Report / Document Action:

Global Id: T0608502045 Action Type: **RESPONSE** Date: 08/09/1999

Action: Soil and Water Investigation Report

T0608502045 Global Id: **RESPONSE** Action Type: 01/10/2014 Date:

Action: Soil and Water Investigation Workplan - Addendum

Global Id: T0608502045 **RESPONSE** Action Type: 01/10/2014 Date:

Action: Other Report / Document

T0608502045 Global Id: **RESPONSE** Action Type: Date: 02/19/2014

Action: Other Report / Document

Global Id: T0608502045 **RESPONSE** Action Type: Date: 05/15/2018

Action: Clean Up Fund - 5-Year Review Summary

Global Id: T0608502045 Action Type: REMEDIATION Date: 05/01/1998 Action: Excavation

Global Id: T0608502045 Action Type: **ENFORCEMENT** 09/14/2010 Date:

Action: Staff Letter - #0102419

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

SAN JOSE MERCURY NEWS (Continued)

S103473094

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 07/19/2012

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 11/01/2013

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 11/21/2017

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 01/30/2018

Action: Monitoring Report - Semi-Annually

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 12/20/2013

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 01/21/2014

 Action:
 Meeting

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 01/28/2015

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 01/12/2015

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 04/07/2014

 Action:
 Staff Letter

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 01/29/2014

Action: Email Correspondence

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 05/29/2018

 Action:
 Staff Letter

Global Id: T0608502045
Action Type: RESPONSE

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE MERCURY NEWS (Continued)

S103473094

EDR ID Number

Date: 07/09/1998

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608502045

 Action Type:
 REMEDIATION

 Date:
 10/23/1999

Action: Other (Use Description Field)

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 08/03/2006

Action: Other Report / Document

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 12/03/2010

Action: Preliminary Site Assessment Workplan

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 11/17/1997

Action: Other Report / Document

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 06/21/2006

Action: Notice of Responsibility - #6002126

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 06/25/2014

 Action:
 Staff Letter

Global Id: T0608502045
Action Type: RESPONSE
Date: 03/16/2016

Action: Verbal Communication

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 01/28/2016

Action: Email Correspondence

 Global Id:
 T0608502045

 Action Type:
 RESPONSE

 Date:
 01/30/2019

Action: Monitoring Report - Semi-Annually

 Global Id:
 T0608502045

 Action Type:
 ENFORCEMENT

 Date:
 06/05/2006

Action: Notice of Responsibility - #6056

Global Id: T0608502045
Action Type: ENFORCEMENT
Date: 08/16/2000

Action: Closure/No Further Action Letter - #00618

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE MERCURY NEWS (Continued)

S103473094

T0608502045 Global Id: **ENFORCEMENT** Action Type: 11/15/1999 Date: Action: Staff Letter - #26708

Global Id: T0608502045 Action Type: **ENFORCEMENT** Date: 06/15/1999 Action: Staff Letter - #26706

Global Id: T0608502045 **RESPONSE** Action Type: 01/03/2017 Date:

Action: **Email Correspondence**

Global Id: T0608502045 **ENFORCEMENT** Action Type: Date: 06/05/2006

Action: Staff Letter - #605060

LUST:

T0608502045 Global Id:

Status: Completed - Case Closed

08/16/2000 Status Date:

Global Id: T0608502045

Status: Open - Assessment & Interim Remedial Action

Status Date: 09/09/2010

T0608502045 Global Id:

Status: Open - Case Begin Date

Status Date: 12/29/1997

Global Id: T0608502045 Open - Reopen Case Status:

06/05/2006 Status Date:

Global Id: T0608502045

Status: Open - Site Assessment

12/29/1997 Status Date:

Global Id: T0608502045

Status: Open - Site Assessment

07/06/1998 Status Date:

Global Id: T0608502045

Status: Open - Site Assessment

Status Date: 09/28/2016

T0608502045 Global Id:

Status: Open - Verification Monitoring

Status Date: 02/01/2018

LUST REG 2:

Region: 2

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE MERCURY NEWS (Continued)

S103473094

EDR ID Number

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E08M03f How Discovered: Not reported Leak Cause: Not reported Not reported Leak Source: Not reported Date Leak Confirmed: Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported
Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E08M03F Date Closed: Not reported EDR Link ID: 07S1E08M03F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E08M03 Oversite Agency: SCVWD

Date Listed: 1998-06-11 00:00:00 Closed Date: 2000-08-16 00:00:00

CERS TANKS:

Affiliation Phone:

Site ID: 196509 CERS ID: 70608502045

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker

Entity Name: TRAVIS L. FLORA - SANTA CLARA COUNTY LOP

4089183486

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

Not reported

Not reported

Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

226 ADOBE NORTH TOWER CPS-SLIC S123102236
ESE 333 WEST SAN FERNANDO STREET NPDES N/A

333 WEST SAN FERNANDO STREET NPDES N/A SAN JOSE, CA 95113 CERS

1/4-1/2 SAN JOSE, CA 95113 0.451 mi.

0.451 mi. 2382 ft.

Relative: CPS-SLIC:
Higher Region: STATE

Actual: Facility Status: Open - Assessment & Interim Remedial Action

86 ft. Status Date: 10/05/2018 Global Id: T10000012042

Lead Agency: SANTA CLARA COUNTY LOP

Lead Agency Case Number: 2018-27s Latitude: 37.332 Longitude: -121.89529

Case Type: Cleanup Program Site

Case Worker: TLF

Local Agency: SANTA CLARA COUNTY LOP

RB Case Number: Not reported

File Location:

Potential Media Affected:

All Files are on GeoTracker or in the Local Agency Database
Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern: Not reported Site History: Not reported

Click here to access the California GeoTracker records for this facility:

NPDES:

Facility Status: Active
NPDES Number: CAS000002

Region: 2 Agency Number: 0 502880 Regulatory Measure ID: Place ID: Not reported Order Number: 2009-0009-DWQ WDID: 2 43C385030 Regulatory Measure Type: Enrollee Program Type: Construction

Adoption Date Of Regulatory Measure: Not reported
Effective Date Of Regulatory Measure: 10/25/2018
Termination Date Of Regulatory Measure: Not reported
Expiration Date Of Regulatory Measure: Not reported
Discharge Address: 345 Park Avenue

Discharge Name: Adobe Systems Incorporated

Discharge City: San Jose Discharge State: California Discharge Zip: 95110 Status: Not reported Status Date: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported

Facility Status:

Not reported
NPDES Number:

Region:

Agency Number:

Not reported
Agency Number:

Not reported
Regulatory Measure ID:

Not reported

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ADOBE NORTH TOWER (Continued)

S123102236

Place ID: Not reported Not reported Order Number: 2 43C385030 WDID: Regulatory Measure Type: Construction Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Discharge Address: Not reported Discharge Name: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Status: Active 10/25/2018 Status Date:

Adobe Systems Incorporated Operator Name:

Operator Address: 345 Park Avenue Operator City: San Jose Operator State: California 95110 Operator Zip:

CERS TANKS:

443153 Site ID: CERS ID: T10000012042 **CERS** Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: TRAVIS L. FLORA - SANTA CLARA COUNTY LOP

Entity Title: Not reported Affiliation Address: 1555 Berger Dr. Affiliation City: SAN JOSE Affiliation State:

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183486

227 **DIOCESE OF SAN JOSE** S102428828 LUST

West 855 LENZEN **HIST LUST** N/A 1/4-1/2 SAN JOSE, CA 94022 **HIST CORTESE** 0.451 mi. **CERS**

2382 ft.

LUST: Relative:

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501831 89 ft.

Global Id: T0608501831 Latitude: 37.335467 Longitude: -121.910334

Completed - Case Closed Status:

Status Date: 01/08/1996 Case Worker: UST

RB Case Number: Not reported

SANTA CLARA COUNTY LOP Local Agency:

File Location: All Files are on GeoTracker or in the Local Agency Database

Direction Distance

Elevation Site Database(s) EPA ID Number

DIOCESE OF SAN JOSE (Continued)

S102428828

EDR ID Number

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Heating Oil / Fuel Oil Site History: Not reported

LUST:

Global Id: T0608501831

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501831

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608501831

 Action Type:
 Other

 Date:
 01/01/1993

 Action:
 Leak Reported

 Global Id:
 T0608501831

 Action Type:
 REMEDIATION

 Date:
 02/24/1994

 Action:
 Excavation

 Global Id:
 T0608501831

 Action Type:
 ENFORCEMENT

 Date:
 10/16/1995

Action: Notice of Responsibility - #39952

Global Id: T0608501831
Action Type: ENFORCEMENT
Date: 01/08/1996

Action: Closure/No Further Action Letter

 Global Id:
 T0608501831

 Action Type:
 RESPONSE

 Date:
 01/08/1996

Action: Other Report / Document

LUST:

Global Id: T0608501831

Status: Completed - Case Closed

Status Date: 01/08/1996

Global Id: T0608501831

Status: Open - Case Begin Date

Direction Distance

Elevation Site Database(s) EPA ID Number

DIOCESE OF SAN JOSE (Continued)

S102428828

EDR ID Number

Status Date: 01/01/1993

Global Id: T0608501831

Status: Open - Site Assessment

Status Date: 02/24/1994

Global Id: T0608501831

Status: Open - Verification Monitoring

Status Date: 04/25/1994

LUST REG 2:

Region: 2

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E07M03f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 2/24/1994
Pollution Characterization Began: 2/24/1994
Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: 4/25/1994

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07M03F

 Date Closed:
 01/08/1996

 EDR Link ID:
 07S1E07M03F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07M03 Oversite Agency: SCVWD

Date Listed: 1994-05-13 00:00:00 Closed Date: 1996-01-08 00:00:00

HIST CORTESE:

Region: CORTESE Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1987

CERS TANKS:

Site ID: 237465 CERS ID: 70608501831

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

DIOCESE OF SAN JOSE (Continued)

S102428828

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

AQ228 SAN JOSE FIRE STATION #1 HIST CORTESE S102429918

201 MARKET N/A

ENE 201 MARKET 1/4-1/2 SAN JOSE, CA 95110

0.458 mi.

2418 ft. Site 1 of 2 in cluster AQ

Relative: HIST CORTESE:

 Higher
 Region:
 CORTESE

 Actual:
 Facility County Code:
 43

 87 ft.
 Reg By:
 LTNKA

 Reg Id:
 43-1671

AQ229 SAN JOSE FIRE STATION #1 LUST S111760455 ENE 201 N MARKET ST N/A

ENE 201 N MARKET ST 1/4-1/2 SAN JOSE, CA 95110

0.458 mi.

2418 ft. Site 2 of 2 in cluster AQ

Relative: LUST:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Actual: Case Type: LUST Cleanup Site

87 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501618

 Global Id:
 T0608501618

 Latitude:
 37.3387559057364

 Longitude:
 -121.894834041595

 Status:
 Completed - Case Closed

Status Date: 04/03/2000
Case Worker: UST
RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Gasoline Site History: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN JOSE FIRE STATION #1 (Continued)

S111760455

EDR ID Number

LUST:

Global Id: T0608501618

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501618

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608501618

 Action Type:
 Other

 Date:
 05/21/1993

 Action:
 Leak Reported

 Global Id:
 T0608501618

 Action Type:
 ENFORCEMENT

 Date:
 11/17/1992

Action: Staff Letter - #26875

 Global Id:
 T0608501618

 Action Type:
 ENFORCEMENT

 Date:
 12/18/1998

 Action:
 Staff Letter - #26878

Global Id: T0608501618
Action Type: ENFORCEMENT
Date: 03/07/1995

Action: Notice of Responsibility - #39870

 Global Id:
 T0608501618

 Action Type:
 REMEDIATION

 Date:
 05/20/1993

 Action:
 Excavation

Global Id: T0608501618
Action Type: ENFORCEMENT
Date: 04/03/2000

Action: Closure/No Further Action Letter

 Global Id:
 T0608501618

 Action Type:
 RESPONSE

 Date:
 01/01/1993

Action: Soil and Water Investigation Workplan

Global Id: T0608501618

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE FIRE STATION #1 (Continued)

S111760455

Action Type: **RESPONSE** Date: 02/25/1999

Other Report / Document Action:

Global Id: T0608501618 Action Type: **RESPONSE** Date: 04/03/2000

Action: Other Report / Document

LUST:

Global Id: T0608501618

Status: Completed - Case Closed

04/03/2000 Status Date:

Global Id: T0608501618

Open - Case Begin Date Status:

06/21/1992 Status Date:

Global Id: T0608501618

Status: Open - Site Assessment

06/21/1992 Status Date:

Global Id: T0608501618

Status: Open - Site Assessment

06/24/1994 Status Date:

LUST S102435153 **PG & E SUBSTATION A**

AN230 South 17 OTTERSON **HIST CORTESE** N/A 1/4-1/2 SAN JOSE, CA 95110 **CERS**

0.468 mi.

Site 2 of 2 in cluster AN 2470 ft.

LUST: Relative:

Higher Lead Agency: SANTA CLARA COUNTY LOP

Case Type: LUST Cleanup Site Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608521441 98 ft.

T0608521441 Global Id: Latitude: 37.3281417495494 Longitude: -121.902186273819 Status: Completed - Case Closed

Status Date: 07/31/2001 UST Case Worker:

RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Site History: Not reported

LUST:

T0608521441 Global Id:

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

SAN FRANCISCO BAY RWQCB (REGION 2) Organization Name:

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND

Distance

Elevation Site Database(s) EPA ID Number

PG & E SUBSTATION A (Continued)

S102435153

EDR ID Number

Email: Not reported Phone Number: Not reported

Global Id: T0608521441

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 04/26/1989

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608521441

 Action Type:
 Other

 Date:
 05/01/1989

 Action:
 Leak Reported

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 03/01/1989

Action: Other Report / Document

Global Id: T0608521441
Action Type: ENFORCEMENT
Date: 11/19/1996

Action: Notice of Responsibility - #39847

 Global Id:
 T0608521441

 Action Type:
 REMEDIATION

 Date:
 03/01/1989

 Action:
 Excavation

 Global Id:
 T0608521441

 Action Type:
 ENFORCEMENT

 Date:
 06/03/2005

 Action:
 Other Report

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 03/09/1989

Action: Other Report / Document

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

Direction Distance

Elevation Site Database(s) EPA ID Number

PG & E SUBSTATION A (Continued)

S102435153

EDR ID Number

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 05/01/1989

Action: Unauthorized Release Form

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 01/01/1988

 Action:
 Correspondence

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 03/20/1989

Action: Tank Removal Report / UST Sampling Report

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 06/03/2005

Action: Other Report / Document

 Global Id:
 T0608521441

 Action Type:
 RESPONSE

 Date:
 04/03/1989

Action: Other Report / Document

LUST:

Global Id: T0608521441

Status: Completed - Case Closed

Status Date: 07/31/2001

Global Id: T0608521441

Status: Open - Case Begin Date

Status Date: 03/01/1989

Global Id: T0608521441

Status: Open - Site Assessment

Status Date: 03/01/1989

HIST CORTESE:

Region: CORTESE Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1058

CERS TANKS:

 Site ID:
 198023

 CERS ID:
 T0608521441

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

PG & E SUBSTATION A (Continued)

S102435153

HIST CORTESE

CERS

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Regional Board Caseworker Affiliation Type Desc:

Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2) Entity Name:

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

231 **FALSTAFF BREWERY** LUST S102597063 wsw **HIST LUST** 1330 THE ALAMEDA N/A

1/4-1/2 SAN JOSE, CA 95126 0.470 mi.

2482 ft.

LUST: Relative:

Higher SANTA CLARA COUNTY LOP Lead Agency:

Case Type: **LUST Cleanup Site** Actual:

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608562859 95 ft.

Global Id: T0608562859 Latitude: 37.333509 Longitude: -121.911364

Status: Completed - Case Closed

Status Date: 06/03/1997 Case Worker: UST

RB Case Number: Not reported

SANTA CLARA COUNTY LOP Local Agency:

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Diesel Site History: Not reported

LUST:

Global Id: T0608562859

Regional Board Caseworker Contact Type: Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND Email: Not reported Phone Number: Not reported

Global Id: T0608562859

Local Agency Caseworker Contact Type: **UST CASE WORKER** Contact Name: SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Email: Not reported Phone Number: 4089183400

Direction Distance Elevation

on Site Database(s) EPA ID Number

FALSTAFF BREWERY (Continued)

S102597063

EDR ID Number

LUST:

 Global Id:
 T0608562859

 Action Type:
 Other

 Date:
 04/07/1997

 Action:
 Leak Reported

 Global Id:
 T0608562859

 Action Type:
 ENFORCEMENT

 Date:
 06/03/1997

Action: Closure/No Further Action Letter

Global Id: T0608562859
Action Type: RESPONSE
Date: 02/03/1997

Action: Other Report / Document

 Global Id:
 T0608562859

 Action Type:
 RESPONSE

 Date:
 01/07/1997

Action: Other Report / Document

Global Id: T0608562859
Action Type: RESPONSE
Date: 04/28/1997

Action: Other Report / Document

 Global Id:
 T0608562859

 Action Type:
 RESPONSE

 Date:
 04/07/1997

Action: Other Report / Document

LUST:

Global Id: T0608562859

Status: Completed - Case Closed

Status Date: 06/03/1997

Global Id: T0608562859

Status: Open - Case Begin Date

Status Date: 04/07/1997

LUST REG 2:

Region: 2 Facility Id: No

Facility Id:

Facility Status:

Case Closed
Case Number:

O7S1E07N04f
How Discovered:

Leak Cause:

Leak Cause:

Leak Source:

Date Leak Confirmed:

Oversight Program:

Not reported

Not reported

Not reported

LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

FALSTAFF BREWERY (Continued)

S102597063

EDR ID Number

Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E07N04F

 Date Closed:
 06/03/1997

 EDR Link ID:
 07S1E07N04F

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code: 2

SCVWD ID: 07S1E07N04 Oversite Agency: SCVWD

Date Listed: 1997-05-07 00:00:00 Closed Date: 1997-06-03 00:00:00

HIST CORTESE:

Region: CORTESE Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-2167

CERS TANKS:

 Site ID:
 197059

 CERS ID:
 T0608562859

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300
Affiliation City: SAN JOSE

Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

232 HARDCASTLE AUTOTHON RCRA-SQG 1000185161 NNW **590 COLEMAN AVENUE** LUST CAD029290467

1/4-1/2 SAN JOSE, CA 95110 0.473 mi.

2498 ft. Relative:

Lower Actual: 77 ft.

FINDS ECHO EMI HAZNET HIST CORTESE SAN JOSE HAZMAT CERS

HIST LUST

EDR ID Number

RCRA-SQG:

Date form received by agency: 07/08/1986

HARDCASTLE AUTOTHON Facility name: Facility address: 590 COLEMAN AVE

SAN JOSE, CA 95110

EPA ID: CAD029290467

Contact: ENVIRONMENTAL MANAGER

Contact address: 590 COLEMAN AVE SAN JOSE, CA 95110

Contact country: US

408-292-1488 Contact telephone: Contact email: Not reported

EPA Region: 09

Small Small Quantity Generator Classification:

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

NOT REQUIRED Owner/operator name: Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Not reported Owner/operator fax: Owner/operator extension: Not reported Legal status: Private Operator Owner/Operator Type: Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: JAMES ALVES Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported 415-555-1212 Owner/operator telephone: Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

HARDCASTLE AUTOTHON (Continued)

1000185161

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

LUST:

Lead Agency: SANTA CLARA COUNTY LOP

Case Type: **LUST Cleanup Site**

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500708

T0608500708 Global Id: 37.341018 Latitude: -121.90614 Longitude:

Status: Completed - Case Closed

Status Date: 12/29/1995 Case Worker: UST RB Case Number: Not reported

Local Agency: SANTA CLARA COUNTY LOP

File Location: All Files are on GeoTracker or in the Local Agency Database

Local Case Number: Not reported Potential Media Affect: Soil Potential Contaminants of Concern: Gasoline Not reported Site History:

LUST:

Global Id: T0608500708

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: **OAKLAND** Email: Not reported Phone Number: Not reported

Global Id: T0608500708

Contact Type: Local Agency Caseworker **UST CASE WORKER** Contact Name: SANTA CLARA COUNTY LOP Organization Name: Address: 1555 Berger Drive, Suite 300

City: SAN JOSE Not reported Email: Phone Number: 4089183400

LUST:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

HARDCASTLE AUTOTHON (Continued)

1000185161

Global Id: T0608500708 Action Type: Other 11/29/1995 Date: Action: Leak Reported

Global Id: T0608500708 Action Type: **ENFORCEMENT** Date: 12/29/1995

Action: Closure/No Further Action Letter

Global Id: T0608500708 **RESPONSE** Action Type: Date: 12/29/1995

Action: Other Report / Document

LUST:

T0608500708 Global Id:

Status: Completed - Case Closed

Status Date: 12/29/1995

Global Id: T0608500708

Status: Open - Case Begin Date

Status Date: 11/29/1995

LUST REG 2:

Region:

Facility Id: Not reported Facility Status: Case Closed Case Number: 07S1E07F01f How Discovered: Not reported Leak Cause: Not reported Leak Source: Not reported Not reported Date Leak Confirmed: LUST Oversight Program:

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: Not reported Pollution Characterization Began: Not reported Pollution Remediation Plan Submitted: Not reported Date Remediation Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:

Region: SANTA CLARA SCVWD ID: 07S1E07F01F Date Closed: 12/29/1995 07S1E07F01F EDR Link ID:

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E07F01 Oversite Agency: SCVWD

1995-12-29 00:00:00 Date Listed: Closed Date: 1995-12-29 00:00:00

Direction Distance Elevation

on Site Database(s) EPA ID Number

HARDCASTLE AUTOTHON (Continued)

1000185161

EDR ID Number

FINDS:

Registry ID: 110001152314

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS AIR POLLUTANT MAJOR

STATE MASTER

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000185161 Registry ID: 110001152314

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110001152314

EMI:

 Year:
 1990

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 2
Reactive Organic Gases Tons/Yr: 2
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1995

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0

Direction Distance Elevation

on Site Database(s) EPA ID Number

HARDCASTLE AUTOTHON (Continued)

1000185161

EDR ID Number

SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1996

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

BAY AREA AQMD

Not reported

Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 1
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1997

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 1998

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr:

Reactive Organic Gases Tons/Yr:

Carbon Monoxide Emissions Tons/Yr:

0

NOX - Oxides of Nitrogen Tons/Yr:

0

SOX - Oxides of Sulphur Tons/Yr:

0

Particulate Matter Tons/Yr:

0

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1999 County Code: 43

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

HARDCASTLE AUTOTHON (Continued)

1000185161

Air Basin: SF Facility ID: 5959 Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 1 Carbon Monoxide Emissions Tons/Yr: 0 0 NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2000 County Code: 43 SF Air Basin: Facility ID: 5959 Air District Name: BA SIC Code: 7532

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 1 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2001 Year: County Code: 43 SF Air Basin: 5959 Facility ID: Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 1 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2003 Year: County Code: 43 Air Basin: SF Facility ID: 5959 Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported

Direction Distance Elevation

n Site Database(s) EPA ID Number

HARDCASTLE AUTOTHON (Continued)

1000185161

EDR ID Number

Consolidated Emission Reporting Rule:

Total Organic Hydrocarbon Gases Tons/Yr:

Reactive Organic Gases Tons/Yr:

Carbon Monoxide Emissions Tons/Yr:

NOX - Oxides of Nitrogen Tons/Yr:

SOX - Oxides of Sulphur Tons/Yr:

Particulate Matter Tons/Yr:

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2004

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:

Not reported
Not reported
0.16
0.1489904

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2005

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2006

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Not reported
Not reported
Total Organic Hydrocarbon Gases Tons/Yr:
Reactive Organic Gases Tons/Yr:
171
1608946

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

HARDCASTLE AUTOTHON (Continued)

1000185161

Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

2007 County Code: 43 Air Basin: SF Facility ID: 5959 Air District Name: BA SIC Code: 7532

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: .171 Reactive Organic Gases Tons/Yr: .1608946 Carbon Monoxide Emissions Tons/Yr:

NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2008 County Code: 43 Air Basin: SF Facility ID: 5959 Air District Name: BA SIC Code: 7532

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: .171 Reactive Organic Gases Tons/Yr: .1608946

Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2009 County Code: 43 SF Air Basin: Facility ID: 5959 Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 0.17100000000000001

Reactive Organic Gases Tons/Yr: 0.1608946

Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2010 County Code: 43 Air Basin: SF

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

HARDCASTLE AUTOTHON (Continued)

1000185161

Facility ID: 5959 Air District Name: BA SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

0.11700000000000001 Total Organic Hydrocarbon Gases Tons/Yr:

Reactive Organic Gases Tons/Yr: 0.1106818

Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 0 SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2011 County Code: 43 SF Air Basin: Facility ID: 5959 Air District Name: ВА SIC Code: 7532

BAY AREA AQMD Air District Name: Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 0.117 Reactive Organic Gases Tons/Yr: 0.1106818

Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2012 County Code: 43 Air Basin: SF Facility ID: 5959 Air District Name: BA 7532 SIC Code:

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported Total Organic Hydrocarbon Gases Tons/Yr: 0.117 Reactive Organic Gases Tons/Yr: 0.1106818

Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2013 County Code: 43 Air Basin: SF Facility ID: 5959 Air District Name: BA 7532 SIC Code:

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

HARDCASTLE AUTOTHON (Continued)

1000185161

Total Organic Hydrocarbon Gases Tons/Yr: 0.117
Reactive Organic Gases Tons/Yr: 0.1106818

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2014

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:

Consolidated Emission Reporting Rule:

Total Organic Hydrocarbon Gases Tons/Yr:

BAY AREA AQMD

Not reported

Not reported

0.102589739

Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

 Year:
 2015

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 5959

 Air District Name:
 BA

 SIC Code:
 7532

Air District Name:

Community Health Air Pollution Info System:
Consolidated Emission Reporting Rule:
Total Organic Hydrocarbon Gases Tons/Yr:

Not reported
Not reported
0.10258974
0.09896342

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

HAZNET:

envid: 1000185161 Year: 2015

GEPAID: CAD029290467
Contact: JAY BURNETTE
Telephone: 4082921490
Mailing Name: Not reported
Mailing Address: 590 COLEMAN AVE
Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD008252405
TSD County: Los Angeles

Waste Category: Aqueous solution with total organic residues 10 percent or more Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

Tons: 0.1251

Direction
Distance

Elevation Site Database(s) EPA ID Number

HARDCASTLE AUTOTHON (Continued)

1000185161

EDR ID Number

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

envid: 1000185161 Year: 2015

GEPAID: CAD029290467
Contact: JAY BURNETTE
Telephone: 4082921490
Mailing Name: Not reported
Mailing Address: 590 COLEMAN AVE
Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD008252405
TSD County: Los Angeles

Waste Category: Unspecified solvent mixture

Disposal Method: Solvents Recovery

Tons: 0.018
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: 1000185161 Year: 2015 GEPAID: CAD029290467 Contact: JAY BURNETTE

Telephone: 4082921490
Mailing Name: Not reported
Mailing Address: 590 COLEMAN AVE

Mailing City, St, Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD008252405
TSD County: Los Angeles

Waste Category: Unspecified solvent mixture

Disposal Method: Solvents Recovery

Tons: 0.018
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: 1000185161 Year: 2015

GEPAID: CAD029290467
Contact: JAY BURNETTE
Telephone: 4082921490
Mailing Name: Not reported

Mailing Address: 590 COLEMAN AVE
Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara
TSD EPA ID: CAD008252405
TSD County: Los Angeles

Waste Category: Aqueous solution with total organic residues 10 percent or more

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site

Tons: 0.1251
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

HARDCASTLE AUTOTHON (Continued)

1000185161

envid: 1000185161 Year: 2012

GEPAID: CAD029290467 Contact: JAY BURNETTE Telephone: 4082921490 Mailing Name: Not reported Mailing Address: 590 COLEMAN AVE Mailing City,St,Zip: SAN JOSE, CA 951100000

Gen County: Santa Clara TSD EPA ID: CAD008252405 Los Angeles TSD County: Not reported Waste Category: Disposal Method: Solvents Recovery

Tons: 0.1008 Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

> Click this hyperlink while viewing on your computer to access 5 additional CA_HAZNET: record(s) in the EDR Site Report.

HIST CORTESE:

Region: CORTESE Facility County Code: 43 **LTNKA** Reg By: Reg Id: 43-0677

SAN JOSE HAZMAT:

SAN JOSE Region: File Num: 410229 Class: Auto Repair

Region: SAN JOSE File Num: 401114

Class: Auto Body and Paint

CERS TANKS:

252764 Site ID: T0608500708 CERS ID:

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Local Agency Caseworker Affiliation Type Desc:

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City: Affiliation State: CA

Affiliation Country: Not reported Not reported Affiliation Zip: 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Direction Distance

Elevation Site Database(s) EPA ID Number

HARDCASTLE AUTOTHON (Continued)

1000185161

EDR ID Number

Affiliation City:

Affiliation State:

CA

Affiliation Country:

Not reported

Affiliation Zip:

Affiliation Phone:

Not reported
Not reported

AO233 SCVTA RYLAND STREET PROPERTY LUST S106163440
NNE UNKNOWN RYLAND ST CERS N/A

NNE UNKNOWN RYLAND ST 1/4-1/2 SAN JOSE, CA 95110

0.482 mi.

2547 ft. Site 2 of 2 in cluster AO

Relative: LUST:

Higher Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Actual: Case Type: LUST Cleanup Site

92 ft. Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501218

 Global Id:
 T0608501218

 Latitude:
 37.34185

 Longitude:
 -121.89815

Status: Completed - Case Closed

 Status Date:
 06/27/1996

 Case Worker:
 UUU

 RB Case Number:
 43-1240

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported Local Case Number: Not reported Potential Media Affect: Soil

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating

Site History: Not reported

LUST:

Global Id: T0608501218

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501218

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

 Global Id:
 T0608501218

 Action Type:
 Other

 Date:
 01/13/1987

 Action:
 Leak Reported

Global Id: T0608501218
Action Type: RESPONSE

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCVTA RYLAND STREET PROPERTY (Continued)

S106163440

Date: 06/27/1996

Other Report / Document Action:

Global Id: T0608501218 Action Type: **ENFORCEMENT** Date: 06/27/1996

Action: Closure/No Further Action Letter

Global Id: T0608501218 Action Type: Other 05/17/1986 Date: Action: Leak Discovery

Global Id: T0608501218 Action Type: Other 05/17/1986 Date: Action: Leak Stopped

LUST:

T0608501218 Global Id:

Completed - Case Closed Status:

06/27/1996 Status Date:

Global Id: T0608501218

Open - Case Begin Date Status:

05/17/1986 Status Date:

Global Id: T0608501218 Status: Open - Remediation

08/16/1988 Status Date:

Global Id: T0608501218 Open - Remediation Status:

12/05/1988 Status Date:

Global Id: T0608501218

Status: Open - Site Assessment

Status Date: 09/28/1987

Global Id: T0608501218

Open - Site Assessment Status:

Status Date: 05/17/1988

LUST REG 2:

Region:

Facility Id: 43-1240 Facility Status: Case Closed Case Number: 07S1E07H01 How Discovered: Tank Closure Leak Cause: Structure Failure

Leak Source: Tank Date Leak Confirmed: Not reported Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted: Not reported Preliminary Site Assesment Began: 9/28/1987

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SCVTA RYLAND STREET PROPERTY (Continued)

S106163440

Pollution Characterization Began: 5/17/1988 Pollution Remediation Plan Submitted: 8/16/1988 Date Remediation Action Underway: 12/5/1988 Date Post Remedial Action Monitoring Began: Not reported

CERS TANKS:

Site ID: 228731 CERS ID: T0608501218

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

UST CASE WORKER - SANTA CLARA COUNTY LOP Entity Name:

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

SAN JOSE Affiliation City:

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported 4089183400 Affiliation Phone:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

234 **SJRA - VILLA TORINO** S103881009 LUST 340 N MARKET ST **HIST LUST** N/A

1/4-1/2 0.495 mi.

2615 ft.

NE

LUST SANTA CLARA: Relative:

SAN JOSE, CA

Higher SANTA CLARA Region: SCVWD ID: 07S1E08E01F Actual: Date Closed: Not reported 91 ft.

07S1E08E01F EDR Link ID:

HIST LUST SANTA CLARA:

Region: SANTA CLARA

Region Code:

SCVWD ID: 07S1E08E01 Oversite Agency: SFRWQCB

Date Listed: 1988-01-08 00:00:00

Closed Date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

235 LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SE ENVIROSTOR S118757327
South 298 LAUREL GROVE LAND AND 370 LAUREL GROVE LAND VCP N/A

1/2-1 SAN JOSE, CA 95126 CUPA Listings 0.542 mi. CUPA Listings

2861 ft.

Relative: ENVIROSTOR:

 Higher
 Facility ID:
 60002378

 Actual:
 Status:
 No Further Action

 99 ft.
 Status Date:
 01/20/2017

 Site Code:
 202100

Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup

Acres: 2.19

NPL: NO

Regulatory Agencies: SMBRP

Lead Agency: SMBRP

Program Manager: Nicole Yuen

Supervisor: Mark Piros

Division Branch: Cleanup Berkeley

Assembly: , 27 Senate: , 15

Special Program: Voluntary Cleanup Program

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Responsible Party Latitude: 37.32679

Latitude: 37.32679 Longitude: -121.9040

APN: 26136062, 26136070, 26136071, 26136091, 26136092, 26136093

Past Use: UNKNOWN
Potential COC: Lead
Confirmed COC: Lead
Potential Description: SOIL

Alias Name: 26136062 Alias Type: APN Alias Name: 26136070 Alias Type: APN Alias Name: 26136071 Alias Type: APN Alias Name: 26136091 Alias Type: APN Alias Name: 26136092 APN Alias Type: Alias Name: 26136093 Alias Type: APN Alias Name: 202100

Alias Type: Project Code (Site Code)

Alias Name: 60002378

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 06/16/2016

Comments: Request for Agency Oversight Application.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Endangerment Assessment Report

EDR ID Number

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SENIOR APART (Continued)

S118757327

Completed Date: 01/20/2017

Comments: DTSC reviewed several Phase I Environmental Site Assessment reports

as well as Limited Soil Sampling and Analysis Reports prepared for the site. Organochlorine pesticides and metals were detected at relatively low concentrations in soil samples collected from the site in June 2016. Lead was detected in 8 soil samples at concentrations greater than DTSC's screening level for residential land use. The lead screening exceedances were localized and limited in extent, with most of the exceedances at 1.5 feet below ground surface (bgs), with one exceedance at 3 feet bgs. The lead-impacted soil was removed when excavation for the construction of an underground parking garage occurred. The lead- and arsenic-impacted soil was disposed at Republic Services Newby Island Landfill in Milpitas, California. DTSC concluded that no further action is required at the Site and that the planned residential development is acceptable.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Correspondence Completed Date: 06/21/2016

Comments: Lead Agency Determination Letter.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Voluntary Cleanup Agreement Completed Document Type:

Completed Date: 06/28/2016

Laurel Grove Lane LP entered into a Voluntary Cleanup Agreement for Comments:

DTSC to oversee a Preliminary Endangerment Assessment.

Future Area Name: Not reported Not reported Future Sub Area Name: Future Document Type: Not reported Future Due Date: Not reported Schedule Area Name: Not reported Not reported Schedule Sub Area Name: Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

VCP:

60002378 Facility ID: Site Type: Voluntary Cleanup Site Type Detail: Voluntary Cleanup Site Mgmt. Req.: NONE SPECIFIED

2.19 Acres: National Priorities List: NO Cleanup Oversight Agencies: **SMBRP SMBRP** Lead Agency:

DTSC - Site Cleanup Program Lead Agency Description:

Project Manager: Nicole Yuen Supervisor: Mark Piros Division Branch: Cleanup Berkeley

Site Code: 202100 , 27 Assembly: Senate: , 15

Special Programs Code: Voluntary Cleanup Program

Status: No Further Action

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SENIOR APART (Continued)

S118757327

Status Date: 01/20/2017

Restricted Use: NO

Funding: Responsible Party 37.32679 / -121.9040 Lat/Long:

26136062, 26136070, 26136071, 26136091, 26136092, 26136093 APN:

Past Use: **UNKNOWN** Potential COC: 30013 Confirmed COC: 30013 Potential Description: SOIL Alias Name: 26136062 Alias Type: APN Alias Name: 26136070 Alias Type: APN Alias Name: 26136071 Alias Type: APN Alias Name: 26136091 Alias Type: APN Alias Name: 26136092 Alias Type: APN 26136093 Alias Name: Alias Type: APN Alias Name: 202100

Project Code (Site Code) Alias Type:

Alias Name: 60002378

Envirostor ID Number Alias Type:

Completed Info:

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Application Completed Date: 06/16/2016

Comments: Request for Agency Oversight Application.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Endangerment Assessment Report

Completed Date: 01/20/2017

Comments: DTSC reviewed several Phase I Environmental Site Assessment reports

as well as Limited Soil Sampling and Analysis Reports prepared for the site. Organochlorine pesticides and metals were detected at relatively low concentrations in soil samples collected from the site in June 2016. Lead was detected in 8 soil samples at concentrations greater than DTSC's screening level for residential land use. The lead screening exceedances were localized and limited in extent, with most of the exceedances at 1.5 feet below ground surface (bgs), with one exceedance at 3 feet bgs. The lead-impacted soil was removed when excavation for the construction of an underground parking garage occurred. The lead- and arsenic-impacted soil was disposed at Republic Services Newby Island Landfill in Milpitas, California. DTSC concluded that no further action is required at the Site and that the

planned residential development is acceptable.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Correspondence Completed Date: 06/21/2016

Comments: Lead Agency Determination Letter.

Direction Distance

Elevation Site Database(s) EPA ID Number

LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SENIOR APART (Continued)

S118757327

EDR ID Number

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Voluntary Cleanup Agreement

Completed Date: 06/28/2016

Comments: Laurel Grove Lane LP entered into a Voluntary Cleanup Agreement for

DTSC to oversee a Preliminary Endangerment Assessment.

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Not reported Schedule Area Name: Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 1-3 CHEMICALS

 Latitude:
 37.3272089

 Longitude:
 -121.904346

 Record ID:
 PR0432233

 Facility ID:
 FA0283416

HAZNET:

envid: \$118757327 Year: 2016

GEPAID: CAC002878237
Contact: VIANEY NAVA
Telephone: 4089932980
Mailing Name: Not reported

Mailing Address: 505 W JULIAN STREET Mailing City,St,Zip: SAN JOSE, CA 95110

Gen County: Santa Clara
TSD EPA ID: CAD028409019
TSD County: Los Angeles

Waste Category: Aqueous solution with total organic residues less than 10 percent Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

(H010-H129) Or (H131-H135)

Tons: 0.504
Cat Decode: Not reported
Method Decode: Not reported
Facility County: Santa Clara

envid: \$118757327 Year: 2016

GEPAID: CAC002878237
Contact: VIANEY NAVA
Telephone: 4089932980
Mailing Name: Not reported

Mailing Address: 505 W JULIAN STREET Mailing City, St, Zip: SAN JOSE, CA 95110

Gen County: Santa Clara
TSD EPA ID: CAD009466392

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

LAUREL GROVE FAMILY APARTMENTS AND THE PARK AVE SENIOR APART (Continued)

S118757327

TSD County: Contra Costa

Waste Category: Other empty containers 30 gallons or more

Disposal Method: Other Treatment

Tons: 0.25

Cat Decode: Not reported Method Decode: Not reported Facility County: Santa Clara

AR236 MISSION VILLAS ENVIROSTOR S109422407
NE 44 EAST JULIAN STREET N/A

NE 44 EAST JULIAN STREET 1/2-1 SAN JOSE, CA 95113

0.629 mi.

3319 ft. Site 1 of 2 in cluster AR

Relative: ENVIROSTOR:
Lower Facility ID:

 Lower
 Facility ID:
 60001042

 Actual:
 Status:
 Refer: 1248 Local Agency

83 ft. Status Date: 01/22/2001

Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation

Acres: 1
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported

Supervisor: Referred - Not Assigned Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Not reported

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Not Applicable Latitude: 37.34099 Longitude: -121.8928

APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 60001042

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/22/2001
Comments: Not reported

Future Area Name:

Future Sub Area Name:

Future Document Type:

Future Due Date:

Schedule Area Name:

Schedule Sub Area Name:

Schedule Document Type:

Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

MISSION VILLAS (Continued) S109422407

Schedule Due Date: Not reported Schedule Revised Date: Not reported

AS237 OUT OF BUSINESS ENVIROSTOR S107149875 SSW 810 PARK AV SUITE STE. A SAN JOSE HAZMAT N/A

1/2-1 SAN JOSE, CA 95126

0.633 mi.

3344 ft. Site 1 of 3 in cluster AS

Relative: ENVIROSTOR: Higher Facility ID:

Higher Facility ID: 71003686

Actual: Status: Inactive - Needs Evaluation

Actual: Status: Inactive - Needs Evaluation 103 ft. Status Date: Not reported

Site Code: Not reported
Site Type: Tiered Permit
Site Type Detailed: Tiered Permit
Acres: Not reported

NPL: NO

Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Not reported
Division Branch: Cleanup Berkeley

Assembly: 28 Senate: 15

Special Program: Not reported

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Not reported Latitude: 37.32578 Longitude: -121.9048

APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAR000013052

Alias Type: EPA Identification Number

Alias Name: 71003686

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name:
Completed Sub Area Name:
Completed Document Type:
Completed Date:
Comments:
Not reported
Not reported
Not reported
Not reported

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported **EDR ID Number**

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

OUT OF BUSINESS (Continued)

S107149875

S104574732

N/A

ENVIROSTOR

EMI

SAN JOSE HAZMAT:

AS OF 02/07/2014 Date of Data: Region: SAN JOSE File Num: 407005 Class: Not reported

AS238 CIRCUIT LINK 804 A PARK AVENUE SSW 1/2-1 SAN JOSE, CA 95126

0.633 mi. 3344 ft.

Site 2 of 3 in cluster AS

ENVIROSTOR: Relative:

Higher Facility ID: 71003660 No Further Action Status: Actual: Status Date: 07/26/2001 103 ft. Site Code: Not reported Site Type: Tiered Permit

> Site Type Detailed: Tiered Permit Acres: 0

NPL: NO

Regulatory Agencies: NONE SPECIFIED NONE SPECIFIED Lead Agency: Program Manager: Not reported Supervisor: Mark Piros Division Branch: Cleanup Berkeley

Assembly: 28 Senate: 15

Special Program: Not reported

Restricted Use: NO

Site Mamt Reg: NONE SPECIFIED Funding: Not reported 37.32549 Latitude: Longitude: -121.9052 APN: NONE SPECIFIED

Past Use: NONE SPECIFIED Potential COC: NONE SPECIFIED Confirmed COC: NONE SPECIFIED Potential Description: NONE SPECIFIED Alias Name: CAD982351264

Alias Type: **EPA Identification Number**

Alias Name: 71003660

Alias Type: **Envirostor ID Number**

Completed Info:

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Phase 1 Completed Date: 07/26/2001 Comments: Not reported

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Other Completed Date: 09/15/2004

Comments: Inspection report sent on 9/15/2004

Completed Area Name: **PROJECT WIDE**

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

CIRCUIT LINK (Continued) S104574732

Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 06/30/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase I Verification
Completed Date: 09/18/2001

Comments: Inspection report sent on 9/18/2001

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 06/27/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 11/09/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other
Completed Date: 02/09/2005

Comments: Inspection report sent on 2/9/2005

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase I Verification
Completed Date: 09/18/2001

Comments: Inspection report sent on 9/18/2001

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Corrective Action Completion Determination

Completed Date: 12/16/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: No Further Action Letter

Completed Date: 12/20/2005 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Order
Completed Date: 11/09/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Order
Completed Date: 03/26/2003

Direction Distance

Elevation Site Database(s) EPA ID Number

CIRCUIT LINK (Continued) S104574732

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 11/15/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Acknowledgement of Satisfaction

Completed Date: 12/16/2005 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 11/15/2004

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Endangerment Assessment Report

Not reported

Completed Date: 12/20/2005 Comments: Not reported

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Not reported Schedule Area Name: Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

EMI:

Comments:

 Year:
 1998

 County Code:
 43

 Air Basin:
 SF

 Facility ID:
 12028

 Air District Name:
 BA

 SIC Code:
 3672

Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 4
Reactive Organic Gases Tons/Yr: 2
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 1999
County Code: 43
Air Basin: SF

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

CIRCUIT LINK (Continued) S104574732

Facility ID: 12028 Air District Name: BA 3672 SIC Code:

Air District Name: **BAY AREA AQMD** Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 3 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 0 SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year: 2000 County Code: 43 Air Basin: SF Facility ID: 12028 Air District Name: ВА SIC Code: 3672

Air District Name: BAY AREA AQMD Community Health Air Pollution Info System: Not reported Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: 3 Carbon Monoxide Emissions Tons/Yr: 0 NOX - Oxides of Nitrogen Tons/Yr: 0 SOX - Oxides of Sulphur Tons/Yr: 0 Particulate Matter Tons/Yr: 0 Part. Matter 10 Micrometers and Smllr Tons/Yr:0

239 SAFE-WAY CHEMICAL CO INC **HWP** S107144590 N/A

NW **664 STOCKTON AVE** 1/2-1 SAN JOSE, CA 95126

0.639 mi. 3373 ft.

HWP: Relative: Lower CAD042345884 EPA Id: CLOSED Cleanup Status: Actual: Latitude: 37.34044 80 ft. Longitude: -121.9124

> Facility Type: Historical - Non-Operating

Facility Size: Not reported Team: Not reported Supervisor: Not reported 200555 Site Code: Assembly District: 28 Senate District: 15

Public Information Officer: Not reported Public Information Officer: Not reported

Activities:

EPA Id: CAD042345884

Historical - Non-Operating Facility Type:

Unit Names: Not reported

New Operating Permit - FINAL PERMIT (EFFECTIVE) **Event Description:**

12/19/1997 Actual Date:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAFE-WAY CHEMICAL CO INC (Continued)

S107144590

EPA Id: CAD042345884

Facility Type: Historical - Non-Operating

Unit Names: Not reported

Event Description: New Operating Permit - APPLICATION PART B RECEIVED

Actual Date: 07/26/1996

Closure:

EPA Id: CAD042345884

Facility Type: Historical - Non-Operating

Unit Names: Unit 1

Closure Final - CLOSURE PLAN APPROVED **Event Description:**

Actual Date: 10/10/2002

EPA Id: CAD042345884

Facility Type: Historical - Non-Operating

Unit Names: Unit 1

Closure Final - ISSUE CLOSURE VERIFICATION **Event Description:**

Actual Date: 10/15/2004

EPA Id: CAD042345884

Facility Type: Historical - Non-Operating

Unit Names: Unit 1

Closure Final - RECEIVE CLOSURE CERTIFICATION **Event Description:**

Actual Date: 12/29/2003

Alias:

EPA Id: CAD042345884

Facility Type: Historical - Non-Operating Alias Type: Project Code (Site Code)

200555 Alias:

AS240 IONIZATION RESEARCH CO INC/ECOSOLUTIONS

ICE S102332192 SSW 820 PARK AVE **HWP** N/A

1/2-1 SAN JOSE, CA 95126

0.640 mi.

3378 ft. Site 3 of 3 in cluster AS

ICE: Relative:

Higher **Envirostor ID:** 3001004 CAL000082530 EPA ID: Actual: Site Type: INSPECTION 104 ft. Facility Status: No Action

Enforcement:

Action Type: Enforcement Order Issued (210)

Action Date: 09/25/1998

Action Type: Final Administrative Settlement (310)

Action Date: 01/07/1999

Inspection:

Action Type: Compliance Evaluation Inspection - Standardized Permit

Action Date: 04/21/1999 Violation Class: No Violations RTC Date: Not reported

CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

IONIZATION RESEARCH CO INC/ECOSOLUTIONS (Continued)

S102332192

EDR ID Number

Action Type: Compliance Evaluation Inspection - Standardized Permit

Action Date: 05/22/1997

Violation Class: Class 1, Class 2, Minor

RTC Date: 08/21/1997

Action Type: Financial Records Review - Standardized Permit

 Action Date:
 06/06/2003

 Violation Class:
 Class 2

 RTC Date:
 09/29/2004

HWP:

EPA Id: CAL000082530
Cleanup Status: CLOSED
Latitude: 37.32594
Longitude: -121.9057

Facility Type: Historical - Non-Operating

Facility Size: Not reported Team: Not reported Supervisor: Not reported Site Code: Not reported Not reported Assembly District: Senate District: Not reported Public Information Officer: Not reported Public Information Officer: Not reported

Closure:

EPA ld: CAL000082530

Facility Type: Historical - Non-Operating

Unit Names: IR1, IR2, IR3

Event Description: Closure Final - RECEIVE CLOSURE CERTIFICATION

Actual Date: 06/21/1999

EPA ld: CAL000082530

Facility Type: Historical - Non-Operating

Unit Names: IR1, IR2, IR3

Event Description: Closure Final - ISSUE CLOSURE VERIFICATION

Actual Date: 09/13/1999

CERS TANKS:

Site ID: 251356
CERS ID: CAL000082530
CERS Description: Hazardous Waste

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 04-21-1999

Violations Found: No

Eval Type: DTSC Compliance Evaluation Inspection

Eval Notes: Compliance Evaluation Inspection - Standardized Permit

Eval Division: Department of Toxic Substances Control

Eval Program: DTSC_ENF Eval Source: ENVSTORHAZ

Eval General Type: Compliance Evaluation Inspection

Eval Date: 05-22-1997

Direction Distance

Elevation Site Database(s) EPA ID Number

IONIZATION RESEARCH CO INC/ECOSOLUTIONS (Continued)

S102332192

EDR ID Number

Violations Found: Yes

Eval Type: DTSC Compliance Evaluation Inspection

Eval Notes: Compliance Evaluation Inspection - Standardized Permit Return To

Compliance: 1997-08-21 00:00:00

Eval Division: Department of Toxic Substances Control

Eval Program: DTSC_ENF Eval Source: ENVSTORHAZ

Eval General Type: Information Request

Eval Date: 06-06-2003 Violations Found: Yes

Eval Type: DTSC Financial Records Review

Eval Notes: Financial Records Review - Standardized Permit Return To Compliance:

2004-09-29 00:00:00

Eval Division: Department of Toxic Substances Control

Eval Program: DTSC_ENF Eval Source: ENVSTORHAZ

Enforcement Action:

Site ID: 251356

Site Name: IONIZATION RESEARCH CO INC/ECOSOLUTIONS

 Site Address:
 820 PARK AVE

 Site City:
 SAN JOSE

 Site Zip:
 951260000

 Enf Action Date:
 01-07-1999

Enf Action Type: Final Administrative Settlement
Enf Action Description: Final Administrative Settlement

Enf Action Notes: Not reported

Enf Action Division: Department of Toxic Substances Control

Enf Action Program: DTSC_ENF Enf Action Source: ENVSTORHAZ

Site ID: 251356

Site Name: IONIZATION RESEARCH CO INC/ECOSOLUTIONS

 Site Address:
 820 PARK AVE

 Site City:
 SAN JOSE

 Site Zip:
 951260000

 Enf Action Date:
 09-25-1998

Enf Action Type: Enforcement Order Issued Enf Action Description: Enforcement Order Issued

Enf Action Notes: Not reported

Enf Action Division: Department of Toxic Substances Control

Enf Action Program: DTSC_ENF Enf Action Source: ENVSTORHAZ

Affiliation:

Affiliation Type Desc: Facility Contact
Entity Name: TONY WALI
Entity Title: Not reported
Affiliation Address: 1823 HOUNT CT

Affiliation City: MILPITAS
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 950350000 Affiliation Phone: 4089358051

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

IONIZATION RESEARCH CO INC/ECOSOLUTIONS (Continued)

S102332192

Affiliation Type Desc: **Facility Owner**

IONIZATION RESEARCH INC **Entity Name:**

Entity Title: Not reported Affiliation Address: 820 PARK AVE Affiliation City: **MILPITAS** Affiliation State: CA

Affiliation Country: Not reported 950350000 Affiliation Zip: Affiliation Phone: 4082411764

AR241 FAMILY HEALTH FOUND. OF ALVISO ST. JAMES ENVIROSTOR S118756959

N/A

55 E. JULIAN STREET ΝE 1/2-1 SAN JOSE, CA 95112

0.643 mi.

Site 2 of 2 in cluster AR 3396 ft.

Relative: **ENVIROSTOR:**

43800004 Lower Facility ID:

No Action Required Status: Actual: Status Date: 06/14/1994 83 ft.

Site Code: Not reported Site Type: Calmortgage Site Type Detailed: Calmortgage Acres: O

NO NPL: Regulatory Agencies: **SMBRP** Lead Agency: **SMBRP** Sandra Karinen Program Manager: Supervisor: William Beckman Division Branch: Cleanup Sacramento

Assembly: 27 Senate: 15

Special Program: Not reported

Restricted Use: NO

NONE SPECIFIED Site Mamt Reg: Funding: CalMortgage Latitude: 37.34111 Longitude: -121.8927 NONE SPECIFIED APN:

Past Use: NONE

Potential COC: NONE SPECIFIED No Contaminants found

Confirmed COC: No Contaminants found

Potential Description: NMA

43800004 Alias Name:

Alias Type: **Envirostor ID Number**

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Phase 1 Completed Date: 06/14/1994

Comments: Pursuant to the MOU, DTSC has reviewed a Phase I Environmental Site

Assessment and other documents for the Family Health Foundation of Alviso, Inc., St. James Health Center (FHFA), The subject property is an existing health clinic which is owned and operated by FHFA. No change in use is being proposed. A Supplemental Phase I Environmental Assessment Report was prepared by DTSC and concluded that no action

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FAMILY HEALTH FOUND. OF ALVISO ST. JAMES (Continued)

S118756959

CERS

was needed for this property there is no contamination on the

property.

Future Area Name: Not reported Future Sub Area Name: Not reported Not reported Future Document Type: Not reported Future Due Date: Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

RIVER PARK DEVEL LINCOLN PROPERTIES 242 **ENVIROSTOR** S101542345 SE 333 SAN CARLOS ST W **CPS-SLIC** N/A **SAN JOSE, CA 95126 CHMIRS** 1/2-1

0.653 mi. 3449 ft.

ENVIROSTOR: Relative:

Higher Facility ID: 43150003 Status: Refer: RWQCB Actual: Status Date: 07/15/1998 90 ft. Site Code: Not reported Evaluation

Site Type: Site Type Detailed: Evaluation Acres: 0.5 NPL: NO

Regulatory Agencies: RWQCB 2 - San Francisco Bay Lead Agency: RWQCB 2 - San Francisco Bay

Program Manager: Not reported

Supervisor: Referred - Not Assigned Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Not reported

Restricted Use: NO

NONE SPECIFIED Site Mgmt Req: Responsible Party Funding: Latitude: 37.32870

Longitude: -121.8941 APN: 259-43-072

ENGINE TESTING/REPAIR, LAUNDRY SERVICES, RESIDENTIAL AREA Past Use:

Potential COC: Tetrachloroethylene (PCE Confirmed COC: Tetrachloroethylene (PCE

Potential Description: OTH, SOIL

RED STAR LAUNDRY Alias Name: Alias Type: Alternate Name Alias Name: 259-43-072 Alias Type: APN

Alias Name: CAD981676430

Alias Type: **EPA Identification Number**

Alias Name: 43150003

Alias Type: **Envirostor ID Number**

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

RIVER PARK DEVEL LINCOLN PROPERTIES (Continued)

S101542345

EDR ID Number

Completed Document Type: * Discovery Completed Date: 08/09/1989

Facility Identified: EPA Federal Investigation Team (FIT) Screening Comments: Site Inspection (SSI). EPA completed SSI and recommend Listing Site

Inspection (LSI).

Future Area Name: Not reported Not reported Future Sub Area Name: Not reported Future Document Type: Future Due Date: Not reported Not reported Schedule Area Name: Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

CPS-SLIC:

STATE Region:

Facility Status: Completed - Case Closed

Status Date: 05/23/2017 T0608591617 Global Id:

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Lead Agency Case Number: Not reported Latitude: 37.328803 Longitude: -121.893063

Case Type: Cleanup Program Site

Case Worker: UUU Local Agency: Not reported RB Case Number: 43S0161 File Location: Not reported

Potential Media Affected: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: * Solvents Site History: Not reported

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region: Facility ID: 43S0161

Facility Status: Preliminary site assessment workplan submitted

Date Closed: Not reported Local Case #: Not reported How Discovered: Tank Closure Leak Cause: UNK UNK Leak Source:

Date Confirmed: Not reported

Date Prelim Site Assmnt Workplan Submitted: 5/22/1995 Date Preliminary Site Assessment Began: Not reported Date Pollution Characterization Began: Not reported Date Remediation Plan Submitted: Not reported Date Remedial Action Underway: Not reported Date Post Remedial Action Monitoring Began: Not reported

CHMIRS:

OES Incident Number: 4-3798 **OES** notification: 07/05/2014

Distance Elevation

Site Database(s) EPA ID Number

RIVER PARK DEVEL LINCOLN PROPERTIES (Continued)

S101542345

EDR ID Number

OES Date: Not reported **OES Time:** Not reported **Date Completed:** Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Not reported Time Notified: Time Completed: Not reported Surrounding Area: Not reported **Estimated Temperature:** Not reported Property Management: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities: Not reported Others Number Of Decontaminated: Not reported Not reported Others Number Of Injuries: Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported Not reported CA DOT PUC/ICC Number: Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Facility Telephone: Not reported Waterway Involved: Yes

Waterway: Guadalupe River
Spill Site: Merchant/Business

Cleanup By: No

Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: SEWAGE Type: Measure: Gal(s) Other: Not reported Date/Time: 1444 2014 Year:

Agency: City of San Jose
Incident Date: 7/5/2014
Admin Agency: Not reported
Amount: Not reported
Contained: Yes

Contained: Yes
Site Type: Guadalupe River

E Date: Not reported Substance: Sewage Quantity Released: 600 Unknown: Not reported Substance #2: Not reported Not reported Substance #3: Evacuations: Not reported Number of Injuries: Not reported

Not reported

#1 Pipeline: No

Number of Fatalities:

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

RIVER PARK DEVEL LINCOLN PROPERTIES (Continued)

S101542345

#2 Pipeline: No #3 Pipeline: No #1 Vessel >= 300 Tons: No #2 Vessel >= 300 Tons: No #3 Vessel >= 300 Tons: No Evacs: No Injuries: Blockage Fatals: No

Comments: Not reported

Description: RP states blockage in the city main caused a release out a manhole. Cleanup is in progress. RP

states that approximately 5 gallons entered the

Guadalupe River.

CERS TANKS:

 Site ID:
 422609

 CERS ID:
 T0608591617

 CERS Description:
 Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country:

Affiliation Zip:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

AT243 CHESTNUT STREET

NW CHESTNUT AND TAYLOR STREETS

1/2-1 SAN JOSE, CA 95110

0.695 mi.

3669 ft. Site 1 of 2 in cluster AT

Relative: ENVIROSTOR:

 Lower
 Facility ID:
 60000431

 Actual:
 Status:
 Active

 81 ft.
 Status Date:
 09/01/2006

 Site Code:
 201721

Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup

Acres: 1.15
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Nicole Yuen
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Voluntary Cleanup Program

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Responsible Party

Latitude: 37.34193

ENVIROSTOR

VCP

S108195956

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Longitude: -121.9130 APN: 259-09-049

Past Use: DISTRIBUTOR - CHEMICAL, RAILROAD RIGHT OF WAY, VEHICLE MAINTENANCE,

TRANSPORTATION - WAREHOUSING

Potential COC: Under Investigation Freon 113 Tetrachloroethylene (PCE

1,1,1-Trichloroethane (TCA Trichloroethylene (TCE Vinyl chloride

1,1-Dichloroethane 1,2-Dichloroethane (EDC Toluene

1,2,4-Trimethylbenzene

Confirmed COC: Freon 113 Tetrachloroethylene (PCE 1,1,1-Trichloroethane (TCA

Trichloroethylene (TCE Vinyl chloride 1,1-Dichloroethane 1,2-Dichloroethane (EDC Toluene 1,2,4-Trimethylbenzene Under

Investigation

Potential Description: OTH, SOIL, SV

Alias Name: Chestnut Street Formerly Leased

Alias Type: Alternate Name
Alias Name: Chestnut Street Leased
Alias Type: Alternate Name
Alias Name: 259-09-049
Alias Type: APN

Alias Name: 110033620357 Alias Type: EPA (FRS #) Alias Name: 201721

Alias Type: Project Code (Site Code)

Alias Name: 60000431

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 08/18/2008

Comments: Received the signed copy of the Community profile.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Workplan

Completed Date: 05/02/2008

Comments: Workplan approved to do additional off site soil gas and ground water

sampling.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 07/06/2012

Comments: The Phase IV field investigation was completed.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Workplan

Completed Date: 11/21/2011 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Voluntary Cleanup Agreement

Completed Date: 02/20/2007

Comments: VCA for site characterization and removal action under DTSC's

oversight.

Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/28/2009

Comments: Annual cost estimate letter for July 2009 to June 30, 2010

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/01/2010 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 12/14/2011 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/18/2013

Comments: Cost estimate letter sent to RP.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/15/2014

Comments: DTSC letter with oversight cost estimate for fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/21/2015 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Workplan

Completed Date: 12/02/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 05/01/2017

Comments: The fieldwork involved installing three shallow groundwater wells and

two deeper wells onsite. CPT logs and grab groundwater samples were

collected as well.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Report

Completed Date: 09/27/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE

Direction Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Workplan

Completed Date: 09/25/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 12/22/2017

Comments: Cone penetrometer testing was performed at the site. The work was

associated with the Downgradient Groundwater Investigation Work Plan.

The vertical aquifer profiling included in the Work Plan is to take

place in 2018.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 09/26/2016

Comments: DTSC letter with oversight cost estimate for fiscal year 2016/2017

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/18/2017

Comments: DTSC annual oversight cost estimate letter for fiscal year 2017/2018.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 03/29/2017

Comments: Pre-HARP form completed and signed prior to site visit on 3/28/2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 05/31/2018

Comments: DTSC sent letters to 597 Chestnut Street, 730 Chestnut Street, and

738 Chestnut Street explaining that DTSC is overseeing a remedial investigation at 725 Chestnut Street (the Site) and Arcadis and UPRR wish to have access to these private properties to conduct further

remedial investigation activities.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Report

Completed Date: 07/24/2015 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 12/20/2013

Comments: The sampling that was included in the Soil Vapor Probe Installation

and Sampling Work Plan Revision II, approved by DTSC on October 30,

2013, was completed.

Completed Area Name: PROJECT WIDE

Direction Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Report

Completed Date: 09/15/2016 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 11/29/2011

Comments: Work notice announcing Remedial Investigation field work sent to

surrounding areas and posted on the week of November 22, 2011.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Workplan

Completed Date: 05/17/2012 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan

Completed Date: 10/30/2013 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 12/09/2013

Comments: The work notice was distributed to inform the community about soil

and soil vapor sampling activities to be conducted at and in the

immediate vicinity of the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 07/19/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 04/22/2015

Comments: The Upgradient Groundwater Investigation Workplan outlines a scope of

work primarily for the purpose of determining the presence or absence of volatile organic compounds upgradient of the Site. The scope of work consists of three mobilizations along three subsurface boring transects (upgradient, along Asbury Street and Coleman Avenue). The August 29, 2014 Workplan was modified by a March 17, 2015 Response to Comments document submitted by ARCADIS to address DTSC's comments on

the Workplan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 06/19/2015

Comments: The field investigation activities included in the Upgradient

Groundwater Investigation Workplan were started on June 19, 2015.

Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 06/12/2015

Comments: A work notice was distributed to inform the community about drilling

and groundwater sampling to be conducted at 22 locations along Asbury Street and Coleman Avenue, and which was to scheduled to begin on

June 19, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 07/07/2016

Comments: The Additional Soil Vapor Investigation Work Plan outlines additional

investigation activities to delineate the occurrence and

concentrations of volatile organic compounds in shallow soil vapor near occupied properties across Chestnut Street, immediately east of

the site. The additional investigation activities include the installation of four additional nested soil vapor probes, with two to three probes in each boring. An additional round of soil vapor sampling is to be performed in 32 existing soil vapor probes (16 locations at 2 depths) and in the new soil vapor probes that are to

be installed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 03/14/2017

Comments: Soil gas sampling that was included in scope of the Additional Soil

Vapor Investigation Work Plan approved by DTSC on July 7, 2016 was

completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 01/17/2017

Comments: Work notice providing for the soil gas and groundwater sampling that

is to take place for 4-5 weeks starting at the end of January 2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Completed Date: 02/02/2016
Comments: Not reported

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Remedial Action Completion Report

Future Due Date: 2023
Future Area Name: PROJI

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported

Future Document Type: Operations and Maintenance Plan

Future Due Date: 2023

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Fact Sheets
Future Due Date: 2021

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Public Notice

Future Due Date: 2021

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Remedial Action Plan

Future Due Date: 2021

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Feasibility Study Report

Future Due Date: 2020

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Remedial Investigation Report

Future Due Date: 2021

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2020

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2019
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2019

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2020

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction

Future Due Date: 2023

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2024

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: CEQA - Notice of Exemption

Future Due Date: 2022

Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

VCP:

Facility ID: 60000431

Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED

Acres: 1.15
National Priorities List: NO

Direction Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Cleanup Oversight Agencies: SMBRP Lead Agency: SMBRP

Lead Agency Description: DTSC - Site Cleanup Program

Project Manager: Nicole Yuen
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley

 Site Code:
 201721

 Assembly:
 27

 Senate:
 15

Special Programs Code: Voluntary Cleanup Program

Status: Active
Status Date: 09/01/2006
Restricted Use: NO

Funding: Responsible Party Lat/Long: 37.34193 / -121.9130

APN: 259-09-049

Past Use: DISTRIBUTOR - CHEMICAL, RAILROAD RIGHT OF WAY, VEHICLE MAINTENANCE,

TRANSPORTATION - WAREHOUSING

Potential COC: 31001, 30012, 30022, 30026, 30027, 30028, 30192, 30193, 30550, 30577 Confirmed COC: 30012,30022,30026,30027,30028,30192,30193,30550,30577,31001

Potential Description: OTH, SOIL, SV

Alias Name: Chestnut Street Formerly Leased

Alias Type: Alternate Name
Alias Name: Chestnut Street Leased
Alias Type: Alternate Name
Alias Name: 259-09-049
Alias Type: APN
Alias Name: 110033620357
Alias Type: EPA (FRS #)

Alias Type: Project Code (Site Code)

201721

Alias Name: 60000431

Alias Type: Envirostor ID Number

Completed Info:

Alias Name:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile

Completed Date: 08/18/2008

Comments: Received the signed copy of the Community profile.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Workplan

Completed Date: 05/02/2008

Comments: Workplan approved to do additional off site soil gas and ground water

sampling.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 07/06/2012

Comments: The Phase IV field investigation was completed.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Workplan

Completed Date: 11/21/2011

Distance Flevation Site

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Voluntary Cleanup Agreement

Completed Date: 02/20/2007

Comments: VCA for site characterization and removal action under DTSC's

oversight.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/28/2009

Comments: Annual cost estimate letter for July 2009 to June 30, 2010

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/01/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 12/14/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/18/2013

Comments: Cost estimate letter sent to RP.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/15/2014

Comments: DTSC letter with oversight cost estimate for fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/21/2015 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Workplan

Completed Date: 12/02/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 05/01/2017

Comments: The fieldwork involved installing three shallow groundwater wells and

two deeper wells onsite. CPT logs and grab groundwater samples were

Direction Distance

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

collected as well.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Report

Completed Date: 09/27/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Workplan

Completed Date: 09/25/2018 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 12/22/2017

Comments: Cone penetrometer testing was performed at the site. The work was

associated with the Downgradient Groundwater Investigation Work Plan.

The vertical aquifer profiling included in the Work Plan is to take

place in 2018.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 09/26/2016

Comments: DTSC letter with oversight cost estimate for fiscal year 2016/2017

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Annual Oversight Cost Estimate

Completed Date: 10/18/2017

Comments: DTSC annual oversight cost estimate letter for fiscal year 2017/2018.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 03/29/2017

Comments: Pre-HARP form completed and signed prior to site visit on 3/28/2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 05/31/2018

Comments: DTSC sent letters to 597 Chestnut Street, 730 Chestnut Street, and

738 Chestnut Street explaining that DTSC is overseeing a remedial investigation at 725 Chestnut Street (the Site) and Arcadis and UPRR wish to have access to these private properties to conduct further

remedial investigation activities.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Report

Completed Date: 07/24/2015
Comments: Not reported

Distance
Elevation Site

Database(s)

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

EPA ID Number

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 12/20/2013

Comments: The sampling that was included in the Soil Vapor Probe Installation

and Sampling Work Plan Revision II, approved by DTSC on October 30,

2013, was completed.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Characterization Report

Completed Date: 09/15/2016 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 11/29/2011

Comments: Work notice announcing Remedial Investigation field work sent to

surrounding areas and posted on the week of November 22, 2011.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation Workplan

Completed Date: 05/17/2012 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
10/30/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 12/09/2013

Comments: The work notice was distributed to inform the community about soil

and soil vapor sampling activities to be conducted at and in the

immediate vicinity of the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 07/19/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 04/22/2015

Comments: The Upgradient Groundwater Investigation Workplan outlines a scope of

work primarily for the purpose of determining the presence or absence of volatile organic compounds upgradient of the Site. The scope of work consists of three mobilizations along three subsurface boring transects (upgradient, along Asbury Street and Coleman Avenue). The August 29, 2014 Workplan was modified by a March 17, 2015 Response to

Distance

Elevation Site **EPA ID Number** Database(s)

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Comments document submitted by ARCADIS to address DTSC's comments on

the Workplan.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Fieldwork Completed Date: 06/19/2015

Comments: The field investigation activities included in the Upgradient

Groundwater Investigation Workplan were started on June 19, 2015.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Work Notice Completed Date: 06/12/2015

Comments: A work notice was distributed to inform the community about drilling

> and groundwater sampling to be conducted at 22 locations along Asbury Street and Coleman Avenue, and which was to scheduled to begin on

June 19, 2015.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Technical Workplan Completed Date: 07/07/2016

Comments:

The Additional Soil Vapor Investigation Work Plan outlines additional

investigation activities to delineate the occurrence and

concentrations of volatile organic compounds in shallow soil vapor near occupied properties across Chestnut Street, immediately east of

the site. The additional investigation activities include the installation of four additional nested soil vapor probes, with two to three probes in each boring. An additional round of soil vapor sampling is to be performed in 32 existing soil vapor probes (16 locations at 2 depths) and in the new soil vapor probes that are to

be installed.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Fieldwork Completed Date:

Comments: Soil gas sampling that was included in scope of the Additional Soil

Vapor Investigation Work Plan approved by DTSC on July 7, 2016 was

completed.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Work Notice Completed Document Type: Completed Date: 01/17/2017

Comments: Work notice providing for the soil gas and groundwater sampling that

is to take place for 4-5 weeks starting at the end of January 2017.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: **Technical Report** Completed Date: 02/02/2016 Comments: Not reported

PROJECT WIDE Future Area Name: Future Sub Area Name: Not reported

Distance Elevation Site

Elevation Site Database(s) EPA ID Number

CHESTNUT STREET (Continued)

S108195956

EDR ID Number

Future Document Type: Remedial Action Completion Report

Future Due Date: 2023

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Operations and Maintenance Plan

Future Due Date: 2023

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Fact Sheets
Future Due Date: 2021

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Public Notice

Future Due Date: 2021

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Remedial Action Plan

Future Due Date: 2021

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Feasibility Study Report

Future Due Date: 2020

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Remedial Investigation Report

Future Due Date: 2021

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2020

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2019

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2019

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: Site Characterization Report

Future Due Date: 2020

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction
Future Due Date: 2023

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2024
Future Area Name: PROJECT WIDE

Future Area Name: PROJECT WIDE Future Sub Area Name: Not reported

Future Document Type: CEQA - Notice of Exemption

Future Due Date: 2022
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

CHESTNUT STREET (Continued) S108195956

Schedule Due Date: Not reported Schedule Revised Date: Not reported

244 SAN JOSE STATE UNIVERSITY CHEMICAL DEPT ENVIROSTOR 1000121113
East 125 SOUTH 7TH ST N/A

1/2-1 SAN JOSE, CA 95112

NPL:

0.712 mi. 3759 ft.

Relative: ENVIROSTOR:

Higher 43820001 Facility ID: No Further Action Status: Actual: Status Date: 10/08/2001 92 ft. Site Code: Not reported Evaluation Site Type: Site Type Detailed: Evaluation Acres: 0.02

Regulatory Agencies: SANTA CLARA COUNTY Lead Agency: SANTA CLARA COUNTY

NO

Program Manager: Not reported
Supervisor: Karen Toth
Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: * Site Char & Assess Grant (CERCLA 104)

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.33193
Longitude: -121.8827
APN: NONE SPECIFIED
Past Use: SCHOOL - COLLEGE

Potential COC: NONE SPECIFIED No Contaminants found

Confirmed COC: No Contaminants found

Potential Description: NMA

Alias Name: CAD050520840

Alias Type: EPA Identification Number

Alias Name: 43820001

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 10/12/1983

Comments: DISC - FACILITY IDENTIFIED ID FROM ERRIS

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Preliminary Assessment Report

Completed Date: 08/31/1985

Comments: All documented PCB contamination has been cleaned up, the storage

unit is presently permitted, and the University is following a standard operating procedure for disposal of chemical wastes.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

SAN JOSE STATE UNIVERSITY CHEMICAL DEPT (Continued)

1000121113

S103653353

N/A

ENVIROSTOR

LUST

Completed Document Type: Site Screening Completed Date: 04/21/1987

Comments: There are no documents that match this date or activity in the

current files.

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Site Screening Completed Date: 10/08/2001

Comments: This site is regulated as a hazardous materials storage area by the

Santa Clara County Health Services as the local Certified Unified

Program Agency. There are no records of releases.

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Not reported Future Due Date: Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Not reported Schedule Due Date: Schedule Revised Date: Not reported

245 STATE RADIATOR SJ REDEVEL SSE 331 GIFFORD AVE 1/2-1

SAN JOSE, CA 95126 **HIST CORTESE SAN JOSE HAZMAT CERS**

ENVIROSTOR: Relative:

0.712 mi.

3762 ft.

Higher Facility ID: 43750007 Status: Refer: RWQCB Actual: 06/27/1995 97 ft. Status Date: Site Code: Not reported Site Type: Evaluation Site Type Detailed: Evaluation

> Acres: NPL: NO

Regulatory Agencies: SMBRP, RWQCB 2 - San Francisco Bay

Lead Agency: RWQCB 2 - San Francisco Bay

Program Manager: Claude Jemison Supervisor: Karen Toth Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Not reported

Restricted Use: NO

NONE SPECIFIED Site Mgmt Req: Funding: Responsible Party Latitude: 37.32574

Longitude: -121.8967 APN: 264-20-089 Past Use: NONE SPECIFIED

Potential COC: * CONTAMINATED SOIL * UNSPECIFIED OIL CONTAINING WASTE * WASTE OIL &

MIXED OIL Lead

Confirmed COC: NONE SPECIFIED NONE SPECIFIED Potential Description: Alias Name: 331 GIFFORD AVE.

Direction Distance

Elevation Site Database(s) EPA ID Number

STATE RADIATOR SJ REDEVEL (Continued)

S103653353

EDR ID Number

Alias Type: Alternate Name

Alias Name: SANTA CLARA AUTO BODY

Alias Type: Alternate Name
Alias Name: YAK GRAPHIC
Alias Type: Alternate Name
Alias Name: 264-20-089
Alias Type: APN
Alias Name: 43750007

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 12/27/1991

Comments: Completed Site Screening. In January 1989, additional sampling was

conducted at the site. Soil boring results detected total oil and grease (TOG) and total petroleum hydrocarbons as diesel (TPHd) in excess of 1000 ppm. Lead was detected at 938 ppm. In May 1989, two groundwater monitoring wells (MW-1 and MW-2) were installed at the property. Lead was detected in groundwater at a concentration of 0.181 ppm. In May 1989, contaminated soil was removed from the previous sampled area. Final soil sample results indicated only one sample contained TOG at 780 ppm and lead at 191 ppm. The sample that contained the TOG and lead was collected beneath the foundation of the building. The excavations were backfilled with clean, imported

fill.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 12/18/2001

Comments: Site cleaned up under RWQCB Oversight

Future Area Name: Not reported Not reported Future Sub Area Name: Future Document Type: Not reported Not reported Future Due Date: Schedule Area Name: Not reported Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Schedule Due Date: Not reported Schedule Revised Date: Not reported

LUST:

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: LUST Cleanup Site

Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501373

Global Id: T0608501373
Latitude: 37.326128
Longitude: -121.895805

Status: Completed - Case Closed

Status Date: 06/27/1995 Case Worker: UUU RB Case Number: 43-1398

Local Agency: SANTA CLARA COUNTY LOP

File Location: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

STATE RADIATOR SJ REDEVEL (Continued)

Local Case Number: Not reported

Potential Media Affect: Other Groundwater (uses other than drinking water)

Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating

Site History: Not reported

LUST:

Global Id: T0608501373

Contact Type: Regional Board Caseworker Contact Name: Regional Water Board

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Address: 1515 CLAY ST SUITE 1400

City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501373

Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300

City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:

Global Id: T0608501373
Action Type: RESPONSE
Date: 07/19/1990

Action: Other Report / Document

 Global Id:
 T0608501373

 Action Type:
 Other

 Date:
 04/18/1990

 Action:
 Leak Reported

 Global Id:
 T0608501373

 Action Type:
 ENFORCEMENT

 Date:
 06/27/1995

Action: Closure/No Further Action Letter

 Global Id:
 T0608501373

 Action Type:
 Other

 Date:
 04/18/1990

 Action:
 Leak Discovery

 Global Id:
 T0608501373

 Action Type:
 Other

 Date:
 04/18/1990

 Action:
 Leak Stopped

LUST:

Global Id: T0608501373

Status: Completed - Case Closed

Status Date: 06/27/1995

Global Id: T0608501373

Status: Open - Case Begin Date

EDR ID Number

S103653353

Direction Distance

Elevation Site Database(s) EPA ID Number

STATE RADIATOR SJ REDEVEL (Continued)

S103653353

EDR ID Number

Status Date: 08/24/1989

Global Id: T0608501373

Status: Open - Site Assessment

Status Date: 08/24/1989

LUST REG 2:

Region:

Facility Id: 43-1398
Facility Status: Case Closed
Case Number: 07S1E18H01
How Discovered: Tank Closure
Leak Cause: Structure Failure

Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST

Prelim. Site Assesment Wokplan Submitted:
Preliminary Site Assesment Began:
Pollution Characterization Began:
Pollution Remediation Plan Submitted:
Date Remediation Action Underway:
Not reported

LUST SANTA CLARA:

 Region:
 SANTA CLARA

 SCVWD ID:
 07S1E18H01F

 Date Closed:
 06/27/1995

 EDR Link ID:
 07S1E18H01F

HIST CORTESE:

Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1398

Region: CORTESE
Facility County Code: 43
Reg By: CALSI
Reg Id: 43750007

SAN JOSE HAZMAT:

 Date of Data:
 AS OF 02/07/2014

 Region:
 SAN JOSE

 File Num:
 405558

Class: Auto Wrecking/Misc Simple Facility

CERS TANKS:

Site ID: 244550 CERS ID: T0608501373

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc: Local Agency Caseworker

Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

STATE RADIATOR SJ REDEVEL (Continued)

S103653353

S103961881

N/A

ENVIROSTOR

CUPA Listings SAN JOSE HAZMAT

CERS

CERS HAZ WASTE

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: SAN JOSE Affiliation State: CA Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker

Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 CLAY ST SUITE 1400

Affiliation City: OAKLAND Affiliation State: CA Affiliation Country: Not reported

Affiliation Zip: Not reported Affiliation Phone: Not reported

AT246 **DU ALL ANODIZING CO** NW 730 CHESTNUT ST 1/2-1 SAN JOSE, CA 95110 0.718 mi.

3793 ft.

Relative:

Site 2 of 2 in cluster AT

ENVIROSTOR:

Lower Facility ID: 60002626 Status: Active Actual: Status Date: 03/22/2018 79 ft.

Site Code: Not reported Site Type: **Tiered Permit** Site Type Detailed: Tiered Permit

Acres: 0.75 NPL: NO Regulatory Agencies: **SMBRP** Lead Agency: **SMBRP** Program Manager: Not reported Supervisor: Robert Senga Division Branch: Cleanup Cypress Not reported Assembly: Senate: Not reported Special Program: Not reported Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Responsible Party

Latitude: Longitude:

NONE SPECIFIED APN: NONE SPECIFIED Past Use: Potential COC: NONE SPECIFIED Confirmed COC: NONE SPECIFIED NONE SPECIFIED Potential Description: Alias Name: 60002626

Alias Type: **Envirostor ID Number**

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Completed Document Type: Phase 1
Completed Date: 03/22/2018
Comments: Not reported

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Not reported Schedule Area Name: Schedule Sub Area Name: Not reported Not reported Schedule Document Type: Not reported Schedule Due Date: Schedule Revised Date: Not reported

CERS HAZ WASTE:

Site ID: 112809 CERS ID: 10355425

CERS Description: Hazardous Waste Onsite Treatment

Violations:

Site ID:

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: As of 1/1/15, annual HMBP training must be provided and documented.

Please provide this training to all personnel and document that it was

provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete and accurate on or before the annual due

date.

Violation Notes: The facility has not submitted an annual certification since

5/10/2012. This is a repeat, uncorrected violation from the 6/8/2015 Official Notice of Inspection and has subsequently been escalated to a

Class II violation.

Violation Division: Santa Clara County Environmental Health

112809

Violation Program: HMRRP
Violation Source: CERS

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a

hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Mr. Athans stated that emergency response and safety procedures

training is provided upon hire and refreshed at least annually and observations are consistent with this statement, but the training is

not documented.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

hazardous waste.

Violation Notes: The facility has a California EPA ID Number: CAL000066905, but the ID

number has been inactive since 6/30/2015. A copy of DTSC FORM 1358

will be provided with this inspection report [HSC 25205.16(c)].

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.16

Violation Description: Failure to provide employees with hazardous waste training within the

first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the

facility.

Violation Notes: Per Mr. Athans, hazardous waste management training is provided at the

time of hire and refreshed at least annually and observations are consistent with this statement, but employee training is not documented in accordance with the requirements below.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.2(b)(2) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(b)(2)

Violation Description: Failure to submit the signature page for the onsite treatment

notification.

Violation Notes: The facility performs hazardous waste treatment under a Permit by

Rule, but has not properly notified HMCD.

Violation Division: Santa Clara County Environmental Health

Distance
Elevation Site Database(s)

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

EPA ID Number

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.192(k) - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.192(k)

Violation Description: Failure to include all required information in the new tank system

assessment

Violation Notes: The 600 gallon hazardous waste neutralization tank and filter press do

not have a tank system assessment.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.7 - California Code of Regulations, Title 22, Chapter

45, Section(s) 67450.7

Violation Description: Failure of the owner or operator of a facility who operates a

transportable treatment unit (TTU) or fixed treatment unit (FTU) under $\,$

a permit by rule to complete a corrective action program at the

facility. The corrective action shall consist of a phase 1

environmental assessment, which shall be submitted within one year of the initial notification of permit by rule treatment, and a subsequent corrective action conducted as necessary to protect human health and the environment for all releases of hazardous waste or constituents from any solid or hazardous waste management unit at the facility, regardless of the time at which waste was placed in the unit.

Violation Notes: A Phase I Environmental Assessment has not been completed and

submitted to DTSC and HMCD.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting - Administration/Documentation - General

Violation Notes: The facility does not have a financial mechanism to cover the estimate

costs of closure or provided a self-certification that the closure

cost estimate is less than \$10,000.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

Violation Notes:

Violation Division:

S103961881

unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)).
A Closure Cost Estimate has not been prepared.
Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.11

Violation Description: Failure to determine if wastes generated are hazardous waste by using

generator knowledge or applying testing method.

Violation Notes: The wastewater treatment sludge waste is currently manifested as waste

code: 181 and identified as UN3262 Corrosive, Solid, Basic, Inorganic, n.o.s. (Sodium Hydroxide). Provide documentation as to why waste code F019 is not applied to the sludge waste as the waste appears to be "wastewater treatment sludges from the chemical conversion coating of

aluminum."

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and

portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical

characteristics of the Hazardous Waste, and starting accumulation

date.

Violation Notes: The wastewater treatment sludge accumulation container under the

filter press is un-labeled. A completed hazardous waste label was

provided at the time of inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include one or more elements in the Contingency Plan

including but not limited to the following: description of actions personnel will take in response to a release or emergency, arrangements with local authorities, list of emergency coordinators

including name, addresses & phone numbers, list of emergency equipment and their physical description, location and capabilities, evacuation

Direction Distance Elevation

tion Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

plan, and OES phone number. (If the owner or operator has already prepared a Spill Prevention, Control, and Countermeasures (SPCC) Plan or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management provisions.)

Violation Notes: The facility's contingency plan is on-site, but does not include the

following required information: - Actions to be taken in response to fires, explosions, and unplanned releases of hazardous waste - Arrangements agreed to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services or if they have been deemed not necessary - The location and a physical description of each item on the list, and a brief outline of its capabilities - An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary, including signals to be used to begin evacuation, evacuation routes, and alternate evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or

fires

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility has not prepared a written waste analysis plan for

hazardous waste treated on-site.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.14 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.14

Violation Description: Failure to provide either a posted sign stating "Danger Hazardous

Waste Area - Keep Out" or to provide one of the following means of security to the active hazardous waste portion of the facility: 1) A 24-hour surveillance system (e.g., television monitoring or surveillance by guards or facility personnel) which continuously monitors and controls entry; or 2) A) An artificial or natural barrier (e.g., a fence in good repair or a fence combined with a cliff), which completely surrounds area; and B) A means to control entry, at all times, through the gates or other entrances (e.g., an attendant, television monitors, locked entrance, or controlled roadway access to

the facility)

Violation Notes: While a fence is used to prevent and control entry into the facility,

security signage as identified below is not posted.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act.

Violation Notes: Facility was determined to be subject to regulation as a Permit By

Rule (PRR) treatment facility in 2012. In 2014 the facility was noted

Rule (PBR) treatment facility in 2012. In 2014 the facility was noted to have modified its operations so to be eligible for onsite recycling exemptions, which removed the PBR operating requirements The facility asked for and was granted (by DEH) "deferred closure" of the wastewater treatment system to allow for continued use of the system in the ongoing recycling activities. Because the system was once determined to be be subject to PBR, facility must generate and maintain a closure plan to be followed at the time of its closure.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility does not have a current copy of the San Jose Industrial

Wastewater Discharge Permit available for review.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: The facility's most recent HMBP submitted on January 1, 2009 and

certified on 5/10/2012 does not address the recyclable material.

Violation Division: Santa Clara County Environmental Health

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Violation Program: HWRecycler Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

Genera

Violation Notes: An Official Notice of Inspection Report was issued on 6/8/2015, but no

written response with the corrective actions taken for each violation

was provided to HMCD.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: No HMBP submittal noted on CERS. Facility must submit information

electronically instead of in hard copy and must ensure that

information is up to date, taking into account changes to information

to be reported.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Non-full drum of sludge had lid off.
Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General Violation Notes: Records of recycling not available during inspeciton. PLEASE PROVIDE

DOCUMENTATION SHOWING AMOUNTS OF WATER TREATED THROUGH SYSTEM AND

AMOUNT OF WATER DISCHARGED TO SEWER/RETURNED FOR RINSEWATER.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWRecycler Violation Source: CERS

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility has not prepared a Closure Plan.
Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: HMBP has not been submitted since 2012 recertification of 2009 plan.

No CERS submittal noted as of 6/8/15. Santa Clara County Environmental Health

Violation Division: Santa Clara
Violation Program: HMRRP

Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter

1, Section(s) 265.173

Violation Description: Failure to meet the following container management requirements: (a) A

container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to

leak.

Violation Notes: 1 x 55 gallon drum of wastewater treatment sludge is open when no

waste is being added or removed

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 25143.10 - California Health and Safety Code, Chapter 6.5,

Section(s) 25143.10

Violation Description: Failure of any person who recycles more than 100 kilograms per month

of recyclable material under a claim that the material qualifies for exclusion or exemption, to submit recyclable materials report every

two years.

Violation Notes: The facility recycles more than 100kg of recycled rinsewater per

month, but a Recyclable Materials Report was not submitted to HMCD by

July 1, 2016.

Violation Division: Santa Clara County Environmental Health

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Violation Program: HWRecycler Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: Daily inspection records with all required information are logged and

retained for 3 years, but a written inspection schedule has not been

prepared.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Evaluation:

Eval Division:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10355425. No submittals as of 6/8/15. Noted materials in baths

in processing area as well as the following materials, all of which need to be reported on inventory: 1000 lb waste sludge 55 gal phosphoric acid containing triple clean 55 gal chem alum deox (nitric/HF) 55 Bonderite (Alumaseal) 55 ferrous sulfate 55 polymer

(diluted) 60 Sodium hydroxide 60 sulfuric acid Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 06-08-2015

Violations Found: Yes

Eval Type: Other, not routine, done by local agency

Eval Notes: Facility noted as being subject to PBR in 2012. In 2014 determined to be recycling, and no longer regulated under PBR. Facility requested

"delayed closure" of the PBR unit to allow for continued use. AS A

FACILITY WHICH HAD A WASTE TREATMENT UNIT THAT WAS REGULATED UNDER

PBR, YOU MUST ENSURE THAT AT THE TIME OF CLOSURE THAT ALL PBR CONDITIONS ARE MET FOR THE CLOSURE OF THE UNIT. THIS INCLUDES

FOLLOWING THE CLOSURE PLAN, APPLYING FOR A PERMIT WITH DEH FOR CLOSURE

OF A PBR UNIT AND SIGN-OFF OF THE CLOSURE OF THE UNIT BY A CERTIFIED

INDEPENDENT PE.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous materials business plan (HMBP)

inpection. The following hazardous materials/wastes were observed in quantities at or above HMBP-reportable thresholds: 1) Nickel Acetate

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

Eval Division:

S103961881

Tank: 1600 gallons 2) 2 x 5% Black Dye Tanks: 500 gallons, 550 gallons: 1050 gallons total 3) 5% Red Dye Tank: 500 gallons 4) 5% Gold Dye Tank: 150 gallons 5) Ferrous Sulfate Container for Treatment: 55 gallons 6) ABCO AC 2 Soap Tank: 100 gallons 7) 5% Sodium Hydroxide Tank: 1600 gallons 8) 17% Sulfuric Acid Tanks: 1700 gallons, 600 gallons: 2300 gallons 9) CED 5% Deox, 5% Nitric Tank: 150 gallons 10) Brite Dip: 500 gallons 11) Alumatte Etch Solid: 500 lb 12) 2 x 55 gallons Triple Clean: 110 gallons 13) Aero Bonderaite Anodize Aero 1000: 55 gallons 14) 3 x 55 gallon drums and 1 x 8 gallon container for hazardous waste sludge accumulation: 1500 lb 15) Rinse Water Tanks and Treatment Tanks: 3 x 200 gallons, 4 x 250 gallon, 750 gallons, 600 gallons 16) [Truncated]

Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous waste inspection. The facility

is an aluminum parts anodizer that conducts Type II, passivation, chemical film processes. The facility generates between 11-12,000 gallons of hazardous waste per month from corrosive rinsewaters and wet floor aqueous wastes. All hazardous waste is "immediately" treated in an on-site hazardous waste treatment system and is excluded from RCRA waste counting per 40 CFR 261.5(c)(2), but is counted when determining California ("non-RCRA") generator status. Therefore, the facility is a non-RCRA large quantity generator. The following hazardous wastes are accumulating at the time of inspection: - 2 x 55 gallon drums of wastewater treatment sludge (Accumulation Dates: 8/13/2016, 10/8/2016) - 1 x approximately 8 gallon container accumulating filter press sludge (Empty Daily) - 1 x 600 gallon

wastewater treatment tank (elementary neutralization) NOTES: - Sludge

waste generated from on-site treatment [Truncated]

Eval Division: Santa Clara County Environmental Health Eval Program: HW

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine inspection of an on-site hazardous waste treatment system deemed to have a Permit by Rule (PBR). Wastewaters

treatment system deemed to have a Permit by Rule (PBR). Wastewaters generated from the rinsewater wastes, container rinsing residuals, and "wet floor" aqueous wastes are automatically directed to treatment system for on-site treatment. The "in-use" rinsewater baths were pH strip tested during the inspection: acidic rinsewater bath's pH = 1-2, caustic rinsewater bath's pH = 11-12, soap rinsewater bath's pH = 6-7. Two Fixed Treatment Units (FTUs) operate under Permit by Rule: All wastestreams* are combined and directed to Unit 1, "Mixer Tank," for elementary neutralization batch treatment (FTU "Unit 1"). The pH of the influent wastewater is monitored by a continuous pH meter and logged on a chart recorder. Depending on the pH of the influent wastewater, the wastewater is automatically neutralized with 30% sodium hydroxide or 50% sulfuric acid. *55 gallon drums are triple

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

rinsed for the purpose of [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is recycling treated rinsewaters for reuse as rinse water.

Recyclable materials report is required to be filed by July 1 of each even numbered year. Believe that facility qualifies for recycling under HSC 25143.2(d) "reuse in place of commercial product".

Eval Division: Santa Clara County Environmental Health

Eval Program: HWRecycler Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is anodizer, providing surface finishing to aluminum parts.

Does Type II , passivation, and chem film processes along with small pallette of dyes. Generate waste from onsite waste water treatment system. Three steps- pH adjust, floc/polymer and press dry. --Water from system is routed to a "final to city" tank which is valved to allow reuse of water in shop for static "fresh water" rinses or discharge to sanitary sewer. -- Have permit to discharge with city of San Jose, maintain quarterly discharge sample results, tested for pH, metals, organics, CN. Shop is operated as a wet floor operation. Per

Mr. Athans, floor is drained daily through lift station pump in

processing area, pumped to treatment system. STRONGLY RECOMMEND

FOLLOWING THE DTSC WET FLOOR GUIDANCE DOCUMENT. -do have procedures

calling for inspection of floors, but no documentation of doing such. Sludge, once pressed, is placed in drums and lid is set on, but ring

is not affixed or locked. Per [Truncated]
Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval Division:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site for a routine excluded recyclable material inspection. The

facility operates a wastewater treatment system (see Permit by Rule Inspection Report) and a portion of the treated wastewater is reclaimed and re-used as "clean" rinse water pursuant to HSC 25143.2(d)(6). NOTES: - Tanks that reclaim the recyclable rinsewater are inspected daily and the inspections are logged. - A flow meter is

installed on the ancillary piping that returns the reclaimed

rinsewater to the rinsewater baths. The flow meter volumes are logged in the daily inspection log. RECOMMEND ACQUIRING ADDITIONAL

INFORMATION AS TO WHAT "TTL1" AND "TTL2" REFER TO ON THE FLOW METER, SO A MORE DETAILED RECORD OF RECYCLABLE MATERIAL COMPLIANCE CAN BE

MAINTAINED [HSC 25143.2(f)].

Eval Division: Santa Clara County Environmental Health

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DU ALL ANODIZING CO (Continued)

S103961881

Eval Program: **HWRecycler CERS** Eval Source:

Enforcement Action:

Site ID: 112809

Du-All Anodizing Corporation Site Name: 730 CHESTNUT STREET Site Address:

SAN JOSE Site City: Site Zip: 95110-1803 Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

HMRRP Enf Action Program: **CERS** Enf Action Source:

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** 730 CHESTNUT STREET Site Address:

Site City: SAN JOSE Site Zip: 95110-1803 Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: HW Enf Action Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** 730 CHESTNUT STREET Site Address:

Site City: SAN JOSE 95110-1803 Site Zip: Enf Action Date: 06-08-2015

Notice of Violation (Unified Program) Enf Action Type:

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: **HWRecycler** Enf Action Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** 730 CHESTNUT STREET Site Address:

Site City: SAN JOSE Site Zip: 95110-1803 Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: **PBR** Enf Action Source: **CERS**

Distance Elevation Site

Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Affiliation:

Affiliation Type Desc: Document Preparer

Entity Name: Amanda Emery, Chemical Data Management Systems

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact

Entity Name: Greg Marchand
Entity Title: Not reported
Affiliation Address: PO Box 21510
Affiliation City: Bakersfield

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 93390-1510
Affiliation Phone: (408) 275-6694

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: PO Box 21510
Affiliation City: Bakersfield

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 93390-1510
Affiliation Phone: Not reported

Affiliation Type Desc: Operator **Entity Name:** Greg Marchand Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 275-6694

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reporte

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer
Entity Name: Greg Marchand
Entity Title: President
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: DU ALL ANODIZING CO

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc:
Entity Name:
Entity Title:
Affiliation Address:
Affiliation City:
Legal Owner
Greg Marchand
Not reported
PO Box 21510
Bakersfield

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 93390-1510
Affiliation Phone: (408) 275-6694

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: Greg Marchand **Entity Title:** President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: Jeffrey Marchand
Entity Title: Not reported

Affiliation Address: 16651 Dog Valley Road

Affiliation City: Truckee Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 96161-2622
Affiliation Phone: (530) 320-7889

Site ID: 112809 CERS ID: 10355425

CERS Description: Hazardous Waste Generator

Violations:

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

records for a minimum of three years.

Violation Notes: As of 1/1/15, annual HMBP training must be provided and documented.

Please provide this training to all personnel and document that it was

provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete and accurate on or before the annual due

date.

Violation Notes: The facility has not submitted an annual certification since

5/10/2012. This is a repeat, uncorrected violation from the 6/8/2015 Official Notice of Inspection and has subsequently been escalated to a

Class II violation.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Mr. Athans stated that emergency response and safety procedures

training is provided upon hire and refreshed at least annually and observations are consistent with this statement, but the training is

not documented.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

hazardous waste.

Violation Notes: The facility has a California EPA ID Number: CAL000066905, but the ID

number has been inactive since 6/30/2015. A copy of DTSC FORM 1358

will be provided with this inspection report [HSC 25205.16(c)].

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.16

Violation Description: Failure to provide employees with hazardous waste training within the

first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the

facility.

Violation Notes: Per Mr. Athans, hazardous waste management training is provided at the

time of hire and refreshed at least annually and observations are consistent with this statement, but employee training is not documented in accordance with the requirements below.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.2(b)(2) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(b)(2)

Violation Description: Failure to submit the signature page for the onsite treatment

notification.

Violation Notes: The facility performs hazardous waste treatment under a Permit by

Rule, but has not properly notified HMCD. Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Violation Division:

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.192(k) - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.192(k)

Violation Description: Failure to include all required information in the new tank system

assessment.

Violation Notes: The 600 gallon hazardous waste neutralization tank and filter press do

not have a tank system assessment.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.7 - California Code of Regulations, Title 22, Chapter

45, Section(s) 67450.7

Violation Description: Failure of the owner or operator of a facility who operates a

transportable treatment unit (TTU) or fixed treatment unit (FTU) under $\,$

a permit by rule to complete a corrective action program at the

facility. The corrective action shall consist of a phase 1

environmental assessment, which shall be submitted within one year of the initial notification of permit by rule treatment, and a subsequent corrective action conducted as necessary to protect human health and

Distance EDR ID Number
Elevation Site EPA ID Number

DU ALL ANODIZING CO (Continued)

Violation Notes:

Violation Division:

S103961881

the environment for all releases of hazardous waste or constituents from any solid or hazardous waste management unit at the facility, regardless of the time at which waste was placed in the unit.

A Phase I Environmental Assessment has not been completed and

A Phase i Environmental Assessment has not been complete

submitted to DTSC and HMCD.
Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting - Administration/Documentation - General

Violation Notes: The facility does not have a financial mechanism to cover the estimate

costs of closure or provided a self-certification that the closure

cost estimate is less than \$10,000.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)).

Violation Notes: A Closure Cost Estimate has not been prepared.
Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.11

Violation Description: Failure to determine if wastes generated are hazardous waste by using

generator knowledge or applying testing method.

Violation Notes: The wastewater treatment sludge waste is currently manifested as waste

code: 181 and identified as UN3262 Corrosive, Solid, Basic, Inorganic, n.o.s. (Sodium Hydroxide). Provide documentation as to why waste code F019 is not applied to the sludge waste as the waste appears to be "wastewater treatment sludges from the chemical conversion coating of

aluminum."

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and

portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical

characteristics of the Hazardous Waste, and starting accumulation

date.

Violation Notes: The wastewater treatment sludge accumulation container under the

filter press is un-labeled. A completed hazardous waste label was

provided at the time of inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include one or more elements in the Contingency Plan

including but not limited to the following: description of actions personnel will take in response to a release or emergency, arrangements with local authorities, list of emergency coordinators

analgements with local authorities, list of emergency coordinators including name, addresses & phone numbers, list of emergency equipment and their physical description, location and capabilities, evacuation plan, and OES phone number. (If the owner or operator has already prepared a Spill Prevention, Control, and Countermeasures (SPCC) Plan or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management

provisions.)

Violation Notes: The facility's contingency plan is on-site, but does not include the

following required information: - Actions to be taken in response to fires, explosions, and unplanned releases of hazardous waste - Arrangements agreed to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services or if they have been deemed not necessary - The location and a physical description of each item on the list, and a brief outline of its capabilities - An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary, including signals to be used to begin evacuation, evacuation routes, and alternate evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or

fires

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility has not prepared a written waste analysis plan for

hazardous waste treated on-site.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.14 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.14

Violation Description: Failure to provide either a posted sign stating "Danger Hazardous

Waste Area - Keep Out" or to provide one of the following means of security to the active hazardous waste portion of the facility: 1) A 24-hour surveillance system (e.g., television monitoring or surveillance by guards or facility personnel) which continuously monitors and controls entry; or 2) A) An artificial or natural barrier (e.g., a fence in good repair or a fence combined with a cliff), which completely surrounds area; and B) A means to control entry, at all times, through the gates or other entrances (e.g., an attendant, television monitors, locked entrance, or controlled roadway access to

the facility).

Violation Notes: While a fence is used to prevent and control entry into the facility,

security signage as identified below is not posted.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act.

Violation Notes: Facility was determined to be subject to regulation as a Permit By

Rule (PBR) treatment facility in 2012. In 2014 the facility was noted to have modified its operations so to be eligible for onsite recycling exemptions, which removed the PBR operating requirements The facility

asked for and was granted (by DEH) "deferred closure" of the wastewater treatment system to allow for continued use of the system in the ongoing recycling activities. Because the system was once

determined to be be subject to PBR, facility must generate and

Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

maintain a closure plan to be followed at the time of its closure.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility does not have a current copy of the San Jose Industrial

Wastewater Discharge Permit available for review.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: The facility's most recent HMBP submitted on January 1, 2009 and

certified on 5/10/2012 does not address the recyclable material.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWRecycler Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

General

Violation Notes: An Official Notice of Inspection Report was issued on 6/8/2015, but no

written response with the corrective actions taken for each violation

was provided to HMCD.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: No HMBP submittal noted on CERS. Facility must submit information

electronically instead of in hard copy and must ensure that

information is up to date, taking into account changes to information

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

to be reported.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Non-full drum of sludge had lid off.
Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Notes: Records of recycling not available during inspeciton. PLEASE PROVIDE
DOCUMENTATION SHOWING AMOUNTS OF WATER TREATED THROUGH SYSTEM AND

AMOUNT OF WATER DISCHARGED TO SEWER/RETURNED FOR RINSEWATER.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWRecycler Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility has not prepared a Closure Plan.
Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: HMBP has not been submitted since 2012 recertification of 2009 plan.

No CERS submittal noted as of 6/8/15. Santa Clara County Environmental Health

Violation Division: Santa Clare
Violation Program: HMRRP
Violation Source: CERS

Site ID: 112809

Distance EDR ID Number
Elevation Site EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter

1, Section(s) 265.173

Violation Description: Failure to meet the following container management requirements: (a) A

container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to

leak

Violation Notes: 1 x 55 gallon drum of wastewater treatment sludge is open when no

waste is being added or removed

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 25143.10 - California Health and Safety Code, Chapter 6.5,

Section(s) 25143.10

Violation Description: Failure of any person who recycles more than 100 kilograms per month

of recyclable material under a claim that the material qualifies for exclusion or exemption, to submit recyclable materials report every

two years.

Violation Notes: The facility recycles more than 100kg of recycled rinsewater per

month, but a Recyclable Materials Report was not submitted to HMCD by

July 1, 2016.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWRecycler Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: Daily inspection records with all required information are logged and

retained for 3 years, but a written inspection schedule has not been

prepared.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10355425. No submittals as of 6/8/15. Noted materials in baths

in processing area as well as the following materials, all of which need to be reported on inventory: 1000 lb waste sludge 55 gal phosphoric acid containing triple clean 55 gal chem alum deox (nitric/HF) 55 Bonderite (Alumaseal) 55 ferrous sulfate 55 polymer

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

Eval Division:

S103961881

EDR ID Number

(diluted) 60 Sodium hydroxide 60 sulfuric acid Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 06-08-2015
Violations Found: Yes

Eval Type: Other, not routine, done by local agency

Eval Notes: Facility noted as being subject to PBR in 2012. In 2014 determined to

be recycling, and no longer regulated under PBR. Facility requested "delayed closure" of the PBR unit to allow for continued use. AS A

FACILITY WHICH HAD A WASTE TREATMENT UNIT THAT WAS REGULATED UNDER

PBR, YOU MUST ENSURE THAT AT THE TIME OF CLOSURE THAT ALL PBR CONDITIONS ARE MET FOR THE CLOSURE OF THE UNIT. THIS INCLUDES

FOLLOWING THE CLOSURE PLAN, APPLYING FOR A PERMIT WITH DEH FOR CLOSURE

OF A PBR UNIT AND SIGN-OFF OF THE CLOSURE OF THE UNIT BY A CERTIFIED

INDEPENDENT PE.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous materials business plan (HMBP)

inpection. The following hazardous materials/wastes were observed in quantities at or above HMBP-reportable thresholds: 1) Nickel Acetate Tank: 1600 gallons 2) 2 x 5% Black Dye Tanks: 500 gallons, 550 gallons: 1050 gallons total 3) 5% Red Dye Tank: 500 gallons 4) 5% Gold Dye Tank: 150 gallons 5) Ferrous Sulfate Container for Treatment: 55 gallons 6) ABCO AC 2 Soap Tank: 100 gallons 7) 5% Sodium Hydroxide Tank: 1600 gallons 8) 17% Sulfuric Acid Tanks: 1700 gallons, 600 gallons: 2300 gallons 9) CED 5% Deox, 5% Nitric Tank: 150 gallons 10) Brite Dip: 500 gallons 11) Alumatte Etch Solid: 500 lb 12) 2 x 55 gallons Triple Clean: 110 gallons 13) Aero Bonderaite Anodize Aero 1000: 55 gallons 14) 3 x 55 gallon drums and 1 x 8 gallon container for hazardous waste sludge accumulation: 1500 lb 15) Rinse Water Tanks and Treatment Tanks: 3 x 200 gallons, 4 x 250 gallon, 750 gallons, 600

gallons 16) [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous waste inspection. The facility

is an aluminum parts anodizer that conducts Type II, passivation, chemical film processes. The facility generates between 11-12,000 gallons of hazardous waste per month from corrosive rinsewaters and wet floor aqueous wastes. All hazardous waste is "immediately" treated in an on-site hazardous waste treatment system and is excluded from RCRA waste counting per 40 CFR 261.5(c)(2), but is counted when determining California ("non-RCRA") generator status. Therefore, the

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

facility is a non-RCRA large quantity generator. The following hazardous wastes are accumulating at the time of inspection: - 2 x 55 gallon drums of wastewater treatment sludge (Accumulation Dates: 8/13/2016, 10/8/2016) - 1 x approximately 8 gallon container accumulating filter press sludge (Empty Daily) - 1 x 600 gallon

wastewater treatment tank (elementary neutralization) NOTES: - Sludge

waste generated from on-site treatment [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine inspection of an on-site hazardous waste

treatment system deemed to have a Permit by Rule (PBR). Wastewaters generated from the rinsewater wastes, container rinsing residuals, and "wet floor" aqueous wastes are automatically directed to treatment system for on-site treatment. The "in-use" rinsewater baths were pH strip tested during the inspection: acidic rinsewater bath's pH = 1-2, caustic rinsewater bath's pH = 11-12, soap rinsewater bath's pH = 6-7. Two Fixed Treatment Units (FTUs) operate under Permit by Rule: All wastestreams* are combined and directed to Unit 1, "Mixer Tank," for elementary neutralization batch treatment (FTU "Unit 1"). The pH of the influent wastewater is monitored by a continuous pH meter and logged on a chart recorder. Depending on the pH of the influent wastewater, the wastewater is automatically neutralized with 30% sodium hydroxide or 50% sulfuric acid. *55 gallon drums are triple

rinsed for the purpose of [Truncated]
Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval Division:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is recycling treated rinsewaters for reuse as rinse water.

Recyclable materials report is required to be filed by July 1 of each even numbered year. Believe that facility qualifies for recycling under HSC 25143.2(d) "reuse in place of commercial product".

Eval Division: Santa Clara County Environmental Health

Eval Program: HWRecycler Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is anodizer, providing surface finishing to aluminum parts.

Does Type II , passivation, and chem film processes along with small pallette of dyes. Generate waste from onsite waste water treatment system. Three steps- pH adjust, floc/polymer and press dry. --Water from system is routed to a "final to city" tank which is valved to allow reuse of water in shop for static "fresh water" rinses or discharge to sanitary sewer. -- Have permit to discharge with city of

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

Eval Division:

S103961881

EDR ID Number

San Jose, maintain quarterly discharge sample results, tested for pH, metals, organics, CN. Shop is operated as a wet floor operation. Per

Mr. Athans, floor is drained daily through lift station pump in

processing area, pumped to treatment system. STRONGLY RECOMMEND

FOLLOWING THE DTSC WET FLOOR GUIDANCE DOCUMENT. -do have procedures

calling for inspection of floors, but no documentation of doing such. Sludge, once pressed, is placed in drums and lid is set on, but ring

is not affixed or locked. Per [Truncated]
Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site for a routine excluded recyclable material inspection. The

facility operates a wastewater treatment system (see Permit by Rule Inspection Report) and a portion of the treated wastewater is reclaimed and re-used as "clean" rinse water pursuant to HSC 25143.2(d)(6). NOTES: - Tanks that reclaim the recyclable rinsewater are inspected daily and the inspections are logged. - A flow meter is installed on the ancillary piping that returns the reclaimed

rinsewater to the rinsewater baths. The flow meter volumes are logged

in the daily inspection log. RECOMMEND ACQUIRING ADDITIONAL INTERPRETATION AS TO MULAT "TTI 4" AND "TTI 2" REFER TO ON THE

INFORMATION AS TO WHAT "TTL1" AND "TTL2" REFER TO ON THE FLOW METER, SO A MORE DETAILED RECORD OF RECYCLABLE MATERIAL COMPLIANCE CAN BE

MAINTAINED [HSC 25143.2(f)].

Eval Division: Santa Clara County Environmental Health

Eval Program: HWRecycler Eval Source: CERS

Enforcement Action:

Site ID: 112809

Site Name: Du-All Anodizing Corporation
Site Address: 730 CHESTNUT STREET

 Site City:
 SAN JOSE

 Site Zip:
 95110-1803

 Enf Action Date:
 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP Enf Action Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation Site Address: 730 CHESTNUT STREET

 Site City:
 SAN JOSE

 Site Zip:
 95110-1803

 Enf Action Date:
 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HW

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DU ALL ANODIZING CO (Continued)

S103961881

Enf Action Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** Site Address: 730 CHESTNUT STREET

SAN JOSE Site City: Site Zip: 95110-1803 Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: **HWRecycler** Enf Action Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** 730 CHESTNUT STREET Site Address:

Site City: SAN JOSE Site Zip: 95110-1803 Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: PBR Enf Action Source: **CERS**

Affiliation:

Affiliation Type Desc: **Document Preparer**

Entity Name: Amanda Emery, Chemical Data Management Systems

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact** Entity Name: Greg Marchand **Entity Title:** Not reported Affiliation Address: PO Box 21510 Affiliation City: Bakersfield

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 93390-1510 Affiliation Phone: (408) 275-6694

Affiliation Type Desc: Facility Mailing Address

Entity Name: Mailing Address **Entity Title:** Not reported Affiliation Address: PO Box 21510 Affiliation City: Bakersfield

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 93390-1510

Elevation Site

Distance

Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Affiliation Phone: Not reported

Affiliation Type Desc: Operator Entity Name: Greg Marchand **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported (408) 275-6694 Affiliation Phone:

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer Entity Name: Greg Marchand Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Not reported Affiliation Phone:

Affiliation Type Desc: Parent Corporation
Entity Name: DU ALL ANODIZING CO

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Affiliation Type Desc: Legal Owner **Entity Name: Greg Marchand** Entity Title: Not reported Affiliation Address: PO Box 21510 Affiliation City: Bakersfield Affiliation State: CA Affiliation Country: **United States** Affiliation Zip: 93390-1510 Affiliation Phone: (408) 275-6694

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: Greg Marchand
Entity Title: President
Affiliation Address: Not reported
Affiliation City: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: Jeffrey Marchand
Entity Title: Not reported

Affiliation Address: 16651 Dog Valley Road

Affiliation City: Truckee
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 96161-2622
Affiliation Phone: (530) 320-7889

CUPA SANTA CLARA:

Region: SANTA CLARA

PE#: 2205

Program Description: GENERATES 100 KG YR TO <5 TONS/YR

 Latitude:
 37.342186

 Longitude:
 -121.912628

 Record ID:
 PR0313471

 Facility ID:
 FA0210774

Region: SANTA CLARA PE#: Not reported

Program Description: HMBP FACILITY, 16-21 CHEMICALS

 Latitude:
 37.342186

 Longitude:
 -121.912628

 Record ID:
 PR0396620

 Facility ID:
 FA0210774

Region: SANTA CLARA

PE#: 2225

Program Description: ONSITE HAZ WASTE RECYCLER > 100 KG/MO

 Latitude:
 37.342186

 Longitude:
 -121.912628

 Record ID:
 PR0415386

 Facility ID:
 FA0210774

Region: SANTA CLARA

PE#: 2261

Program Description: PERMIT BY RULE (PBR)

 Latitude:
 37.342186

 Longitude:
 -121.912628

 Record ID:
 PR0402618

 Facility ID:
 FA0210774

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 401369

Class: Metal Plating and Fabrication

CERS TANKS:

Site ID: 112809

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

CERS ID: 10355425

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: As of 1/1/15, annual HMBP training must be provided and documented.

Please provide this training to all personnel and document that it was

provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95,

Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the

business plan is complete and accurate on or before the annual due

date.

Violation Notes: The facility has not submitted an annual certification since

5/10/2012. This is a repeat, uncorrected violation from the 6/8/2015 Official Notice of Inspection and has subsequently been escalated to a

Class II violation.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter

6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

records for a minimum of three years.

Violation Notes: Mr. Athans stated that emergency response and safety procedures

training is provided upon hire and refreshed at least annually and observations are consistent with this statement, but the training is

not documented.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.12

Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Violation Description: Failure to obtain an Identification Number prior to treating, storing,

disposing of, transporting or offering for transportation any

hazardous waste.

Violation Notes: The facility has a California EPA ID Number: CAL000066905, but the ID

number has been inactive since 6/30/2015. A copy of DTSC FORM 1358

will be provided with this inspection report [HSC 25205.16(c)].

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.16

Violation Description: Failure to provide employees with hazardous waste training within the

first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the

facility.

Violation Notes: Per Mr. Athans, hazardous waste management training is provided at the

time of hire and refreshed at least annually and observations are consistent with this statement, but employee training is not documented in accordance with the requirements below.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.2(b)(2) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(b)(2)

Violation Description: Failure to submit the signature page for the onsite treatment

notification.

Violation Notes: The facility performs hazardous waste treatment under a Permit by

Rule, but has not properly notified HMCD.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.192(k) - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.192(k)

Violation Description: Failure to include all required information in the new tank system

assessment.

Violation Notes: The 600 gallon hazardous waste neutralization tank and filter press do

not have a tank system assessment.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.7 - California Code of Regulations, Title 22, Chapter

45, Section(s) 67450.7

Violation Description: Failure of the owner or operator of a facility who operates a

transportable treatment unit (TTU) or fixed treatment unit (FTU) under a permit by rule to complete a corrective action program at the

facility. The corrective action shall consist of a phase 1

environmental assessment, which shall be submitted within one year of the initial notification of permit by rule treatment, and a subsequent corrective action conducted as necessary to protect human health and the environment for all releases of hazardous waste or constituents from any solid or hazardous waste management unit at the facility, regardless of the time at which waste was placed in the unit.

Violation Notes: A Phase I Environmental Assessment has not been completed and

submitted to DTSC and HMCD.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting - Administration/Documentation - General

Violation Notes: The facility does not have a financial mechanism to cover the estimate

costs of closure or provided a self-certification that the closure

cost estimate is less than \$10,000.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)). A Closure Cost Estimate has not been prepared. Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS
Site ID: 112809

Violation Notes:

Violation Division:

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter

12, Section(s) 66262.11

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Violation Description: Failure to determine if wastes generated are hazardous waste by using

generator knowledge or applying testing method.

Violation Notes: The wastewater treatment sludge waste is currently manifested as waste

code: 181 and identified as UN3262 Corrosive, Solid, Basic, Inorganic, n.o.s. (Sodium Hydroxide). Provide documentation as to why waste code F019 is not applied to the sludge waste as the waste appears to be "wastewater treatment sludges from the chemical conversion coating of

aluminum."

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and

portable tanks with the following requirements: "Hazardous Waste",

name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation

date.

Violation Notes: The wastewater treatment sludge accumulation container under the

filter press is un-labeled. A completed hazardous waste label was

provided at the time of inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include one or more elements in the Contingency Plan

including but not limited to the following: description of actions personnel will take in response to a release or emergency, arrangements with local authorities, list of emergency coordinators

including name, addresses & phone numbers, list of emergency equipment and their physical description, location and capabilities, evacuation

plan, and OES phone number. (If the owner or operator has already prepared a Spill Prevention, Control, and Countermeasures (SPCC) Plan or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management

provisions.)

Violation Notes: The facility's contingency plan is on-site, but does not include the

following required information: - Actions to be taken in response to fires, explosions, and unplanned releases of hazardous waste - Arrangements agreed to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services or if they have been deemed not necessary - The location and a physical description of each item on the list, and a brief outline of its capabilities - An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary, including signals to be used to begin evacuation,

evacuation routes, and alternate evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

DU ALL ANODIZING CO (Continued)

S103961881

fires

Violation Division: Santa Clara County Environmental Health

Violation Program: PRR Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Failure to maintain the required documents at the facility where the Violation Description:

> FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility has not prepared a written waste analysis plan for

hazardous waste treated on-site.

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

Violation Date: 11-08-2016

22 CCR 15 66265.14 - California Code of Regulations, Title 22, Chapter Citation:

15, Section(s) 66265.14

Violation Description: Failure to provide either a posted sign stating "Danger Hazardous

Waste Area - Keep Out" or to provide one of the following means of security to the active hazardous waste portion of the facility: 1) A 24-hour surveillance system (e.g., television monitoring or surveillance by guards or facility personnel) which continuously monitors and controls entry; or 2) A) An artificial or natural barrier (e.g., a fence in good repair or a fence combined with a cliff), which completely surrounds area; and B) A means to control entry, at all times, through the gates or other entrances (e.g., an attendant, television monitors, locked entrance, or controlled roadway access to

the facility).

Violation Notes: While a fence is used to prevent and control entry into the facility,

security signage as identified below is not posted.

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

Violation Date: 06-08-2015

22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22, Citation:

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

> the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

Distance

EDR ID Number Elevation **EPA ID Number** Site Database(s)

DU ALL ANODIZING CO (Continued)

Violation Notes:

Violation Description:

S103961881

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act. Facility was determined to be subject to regulation as a Permit By

Rule (PBR) treatment facility in 2012. In 2014 the facility was noted to have modified its operations so to be eligible for onsite recycling exemptions, which removed the PBR operating requirements The facility

asked for and was granted (by DEH) "deferred closure" of the wastewater treatment system to allow for continued use of the system in the ongoing recycling activities. Because the system was once determined to be be subject to PBR, facility must generate and

maintain a closure plan to be followed at the time of its closure.

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

Violation Date: 11-08-2016

22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22, Citation:

Chapter 45, Section(s) 67450.3(c)(8)

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Failure to maintain the required documents at the facility where the

Violation Notes: The facility does not have a current copy of the San Jose Industrial

Wastewater Discharge Permit available for review.

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Site ID: 112809

Du-All Anodizing Corporation Site Name:

Violation Date: 11-08-2016

HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Citation:

Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation -

Violation Notes: The facility's most recent HMBP submitted on January 1, 2009 and

certified on 5/10/2012 does not address the recyclable material.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HWRecycler** Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

11-08-2016 Violation Date:

HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Citation:

Section(s) Multiple

Hazardous Waste Generator Program - Administration/Documentation -Violation Description:

General

Violation Notes: An Official Notice of Inspection Report was issued on 6/8/2015, but no

written response with the corrective actions taken for each violation

was provided to HMCD.

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

quantities.

Violation Notes: No HMBP submittal noted on CERS. Facility must submit information

electronically instead of in hard copy and must ensure that

information is up to date, taking into account changes to information

to be reported.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter

6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Notes: Non-full drum of sludge had lid off.
Violation Division: Santa Clara County Environmental Health

Violation Program: HW
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General Violation Notes: Records of recycling not available during inspeciton. PLEASE PROVIDE

DOCUMENTATION SHOWING AMOUNTS OF WATER TREATED THROUGH SYSTEM AND

AMOUNT OF WATER DISCHARGED TO SEWER/RETURNED FOR RINSEWATER.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWRecycler Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 11-08-2016

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: The facility has not prepared a Closure Plan.
Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 112809

Site Name: Du-All Anodizing Corporation

Violation Date: 06-08-2015

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

Direction Distance

Elevation **EPA ID Number** Site Database(s)

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when

storing/handling a hazardous material at or above reportable

Violation Notes: HMBP has not been submitted since 2012 recertification of 2009 plan.

No CERS submittal noted as of 6/8/15.

Violation Division: Santa Clara County Environmental Health

HMRRP Violation Program: Violation Source: **CERS**

Site ID: 112809

Du-All Anodizing Corporation Site Name:

Violation Date: 11-08-2016

40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter Citation:

1, Section(s) 265.173

Violation Description: Failure to meet the following container management requirements: (a) A

> container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to

leak.

Violation Notes: 1 x 55 gallon drum of wastewater treatment sludge is open when no

waste is being added or removed

Violation Division: Santa Clara County Environmental Health

Violation Program: HW Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

11-08-2016 Violation Date:

HSC 6.5 25143.10 - California Health and Safety Code, Chapter 6.5, Citation:

Section(s) 25143.10

Failure of any person who recycles more than 100 kilograms per month Violation Description:

> of recyclable material under a claim that the material qualifies for exclusion or exemption, to submit recyclable materials report every

two years.

Violation Notes: The facility recycles more than 100kg of recycled rinsewater per

month, but a Recyclable Materials Report was not submitted to HMCD by

July 1, 2016.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HWRecycler** Violation Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation**

Violation Date: 11-08-2016

22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22, Citation:

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain the required documents at the facility where the

FTU is operating and upon request make these documents available to authorized agency, DTSC, the CUPA, or EPA, or local government agency.

Violation Notes: Daily inspection records with all required information are logged and

retained for 3 years, but a written inspection schedule has not been

prepared.

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Distance Elevation

vation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10355425. No submittals as of 6/8/15. Noted materials in baths

in processing area as well as the following materials, all of which need to be reported on inventory: 1000 lb waste sludge 55 gal phosphoric acid containing triple clean 55 gal chem alum deox (nitric/HF) 55 Bonderite (Alumaseal) 55 ferrous sulfate 55 polymer

(diluted) 60 Sodium hydroxide 60 sulfuric acid Santa Clara County Environmental Health

Eval Division: Santa Clara C Eval Program: HMRRP Eval Source: CERS

Eval General Type: Other/Unknown Eval Date: 06-08-2015

Violations Found: Yes

Eval Type: Other, not routine, done by local agency

Eval Notes: Facility noted as being subject to PBR in 2012. In 2014 determined to

be recycling, and no longer regulated under PBR. Facility requested "delayed closure" of the PBR unit to allow for continued use. AS A

FACILITY WHICH HAD A WASTE TREATMENT UNIT THAT WAS REGULATED UNDER

PBR, YOU MUST ENSURE THAT AT THE TIME OF CLOSURE THAT ALL PBR CONDITIONS ARE MET FOR THE CLOSURE OF THE UNIT. THIS INCLUDES

FOLLOWING THE CLOSURE PLAN, APPLYING FOR A PERMIT WITH DEH FOR CLOSURE

OF A PBR UNIT AND SIGN-OFF OF THE CLOSURE OF THE UNIT BY A CERTIFIED

INDEPENDENT PE.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous materials business plan (HMBP)

inpection. The following hazardous materials/wastes were observed in quantities at or above HMBP-reportable thresholds: 1) Nickel Acetate Tank: 1600 gallons 2) 2 x 5% Black Dye Tanks: 500 gallons, 550 gallons: 1050 gallons total 3) 5% Red Dye Tank: 500 gallons 4) 5% Gold Dye Tank: 150 gallons 5) Ferrous Sulfate Container for Treatment: 55 gallons 6) ABCO AC 2 Soap Tank: 100 gallons 7) 5% Sodium Hydroxide Tank: 1600 gallons 8) 17% Sulfuric Acid Tanks: 1700 gallons, 600 gallons: 2300 gallons 9) CED 5% Deox, 5% Nitric Tank: 150 gallons 10) Brite Dip: 500 gallons 11) Alumatte Etch Solid: 500 lb 12) 2 x 55 gallons Triple Clean: 110 gallons 13) Aero Bonderaite Anodize Aero 1000: 55 gallons 14) 3 x 55 gallon drums and 1 x 8 gallon container for hazardous waste sludge accumulation: 1500 lb 15) Rinse Water Tanks and Treatment Tanks: 3 x 200 gallons, 4 x 250 gallon, 750 gallons, 600

gallons 16) [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine hazardous waste inspection. The facility

is an aluminum parts anodizer that conducts Type II, passivation, chemical film processes. The facility generates between 11-12,000 gallons of hazardous waste per month from corrosive rinsewaters and wet floor aqueous wastes. All hazardous waste is "immediately" treated in an on-site hazardous waste treatment system and is excluded from RCRA waste counting per 40 CFR 261.5(c)(2), but is counted when determining California ("non-RCRA") generator status. Therefore, the facility is a non-RCRA large quantity generator. The following hazardous wastes are accumulating at the time of inspection: - 2 x 55 gallon drums of wastewater treatment sludge (Accumulation Dates:

8/13/2016, 10/8/2016) - 1 x approximately 8 gallon container accumulating filter press sludge (Empty Daily) - 1 x 600 gallon

wastewater treatment tank (elementary neutralization) NOTES: - Sludge

waste generated from on-site treatment [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site to conduct a routine inspection of an on-site hazardous waste

treatment system deemed to have a Permit by Rule (PBR). Wastewaters generated from the rinsewater wastes, container rinsing residuals, and "wet floor" aqueous wastes are automatically directed to treatment system for on-site treatment. The "in-use" rinsewater baths were pH strip tested during the inspection: acidic rinsewater bath's pH = 1-2, caustic rinsewater bath's pH = 11-12, soap rinsewater bath's pH = 6-7. Two Fixed Treatment Units (FTUs) operate under Permit by Rule: All wastestreams* are combined and directed to Unit 1, "Mixer Tank," for elementary neutralization batch treatment (FTU "Unit 1"). The pH of the influent wastewater is monitored by a continuous pH meter and logged on a chart recorder. Depending on the pH of the influent wastewater, the wastewater is automatically neutralized with 30% sodium hydroxide or 50% sulfuric acid. *55 gallon drums are triple

rinsed for the purpose of [Truncated]
Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval Division:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 06-08-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is recycling treated rinsewaters for reuse as rinse water.

Recyclable materials report is required to be filed by July 1 of each even numbered year. Believe that facility qualifies for recycling under HSC 25143.2(d) "reuse in place of commercial product".

Eval Division: Santa Clara County Environmental Health

Eval Program: HWRecycler Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Eval Date: 06-08-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is anodizer, providing surface finishing to aluminum parts.

Does Type II , passivation, and chem film processes along with small pallette of dyes. Generate waste from onsite waste water treatment system. Three steps- pH adjust, floc/polymer and press dry. --Water from system is routed to a "final to city" tank which is valved to allow reuse of water in shop for static "fresh water" rinses or discharge to sanitary sewer. -- Have permit to discharge with city of San Jose, maintain quarterly discharge sample results, tested for pH, metals, organics, CN. Shop is operated as a wet floor operation. Per

Mr. Athans, floor is drained daily through lift station pump in

processing area, pumped to treatment system. STRONGLY RECOMMEND

FOLLOWING THE DTSC WET FLOOR GUIDANCE DOCUMENT. -do have procedures

calling for inspection of floors, but no documentation of doing such. Sludge, once pressed, is placed in drums and lid is set on, but ring

is not affixed or locked. Per [Truncated]
Santa Clara County Environmental Health

Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-08-2016

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: On-site for a routine excluded recyclable material inspection. The

facility operates a wastewater treatment system (see Permit by Rule Inspection Report) and a portion of the treated wastewater is reclaimed and re-used as "clean" rinse water pursuant to HSC 25143.2(d)(6). NOTES: - Tanks that reclaim the recyclable rinsewater are inspected daily and the inspections are logged. - A flow meter is

installed on the ancillary piping that returns the reclaimed

rinsewater to the rinsewater baths. The flow meter volumes are logged in the daily inspection log. RECOMMEND ACQUIRING ADDITIONAL

INFORMATION AS TO WHAT "TTL1" AND "TTL2" REFER TO ON THE FLOW METER, SO A MORE DETAILED RECORD OF RECYCLABLE MATERIAL COMPLIANCE CAN BE

MAINTAINED [HSC 25143.2(f)].

Eval Division: Santa Clara County Environmental Health

Eval Program: HWRecycler Eval Source: CERS

Enforcement Action:

Eval Division:

Site ID: 112809

Site Name: Du-All Anodizing Corporation Site Address: 730 CHESTNUT STREET

 Site City:
 SAN JOSE

 Site Zip:
 95110-1803

 Enf Action Date:
 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

Enf Action Program: HMRRP Enf Action Source: CERS

Site ID: 112809

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DU ALL ANODIZING CO (Continued)

S103961881

Site Name: **Du-All Anodizing Corporation** 730 CHESTNUT STREET Site Address:

SAN JOSE Site City: 95110-1803 Site Zip: Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

Enf Action Program: HW **CERS** Enf Action Source:

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** 730 CHESTNUT STREET Site Address:

Site City: SAN JOSE 95110-1803 Site Zip: Enf Action Date: 06-08-2015

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Enf Action Division: Santa Clara County Environmental Health

HWRecycler Enf Action Program: Enf Action Source: **CERS**

Site ID: 112809

Site Name: **Du-All Anodizing Corporation** Site Address: 730 CHESTNUT STREET

Site City: SAN JOSE Site Zip: 95110-1803 06-08-2015 Enf Action Date:

Enf Action Type: Notice of Violation (Unified Program)

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes: Not reported

Santa Clara County Environmental Health Enf Action Division:

PBR Enf Action Program: **CERS** Enf Action Source:

Affiliation:

Affiliation Type Desc: **Document Preparer**

Entity Name: Amanda Emery, Chemical Data Management Systems

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Not reported Affiliation Phone:

Affiliation Type Desc: **Environmental Contact Entity Name:** Greg Marchand **Entity Title:** Not reported Affiliation Address: PO Box 21510 Affiliation City: Bakersfield

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 93390-1510

Direction Distance Elevation

tion Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Affiliation Phone: (408) 275-6694

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: PO Box 21510
Affiliation City: Bakersfield

Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 93390-1510 Affiliation Phone: Not reported

Affiliation Type Desc: Operator **Entity Name:** Greg Marchand Entity Title: Not reported Not reported Affiliation Address: Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: (408) 275-6694

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Identification Signer **Entity Name:** Greg Marchand Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: DU ALL ANODIZING CO

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Affiliation City:

Legal Owner

Greg Marchand

Not reported

PO Box 21510

Bakersfield

Direction Distance

Elevation Site Database(s) EPA ID Number

DU ALL ANODIZING CO (Continued)

S103961881

EDR ID Number

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 93390-1510
Affiliation Phone: (408) 275-6694

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: Greg Marchand **Entity Title:** President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: Jeffrey Marchand
Entity Title: Not reported

Affiliation Address: 16651 Dog Valley Road

Affiliation City: Truckee
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 96161-2622
Affiliation Phone: (530) 320-7889

247 WILLIAMS MANUFACTURING CPS-SLIC S109850922
NW 560-595 EMORY ST BROWNFIELDS N/A

1/2-1 SAN JOSE, CA 95110

0.830 mi. 4382 ft.

Relative: CPS-SLIC: Lower Region:

 Lower
 Region:
 STATE

 Actual:
 Facility Status:
 Open - Assessment & Interim Remedial Action

75 ft. Status Date: 02/20/2018 Global Id: SL0608583805

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Type: Cleanup Programmer Cl

File Location:

All Files are on GeoTracker or in the Local Agency Database

Potential Media Affected:

Other Groundwater (uses other than drinking water), Soil, Soil Vapor

Potential Contaminants of Concern:

1,1,1-Trichloroethane (TCA), Other Chlorinated Hydrocarbons,

Tetrachloroethylene (PCE), Trichloroethylene (TCE)

Site History: The Williams Manufacturing Facility encompasses 560 - 595 Emory

Street and 790 Chestnut Street parcels. The site is a former metal stamping facility family owned and operated since 1942. The facility ceased operations in 2003. The site comprises several buildings on

either side of Emory Street and is rented to different

commercial/industrial users. Soil, soil vapor, and GW sampling

results show elevated concentrations of TPG and VOCs (PCE & TCE) are present in all media. 790 Chestnut Street property- a former UST at this location; that case (43-3139) was closed in December 2008.

Notify 65

CERS

Direction Distance Elevation

evation Site Database(s) EPA ID Number

WILLIAMS MANUFACTURING (Continued)

S109850922

EDR ID Number

Partial closure by RWQCB for the 760 Emory Street parcel - NFA letter 6/30/2014 (APN 259-09-020). One groundwater monitoring well MW-1 and 16 soil vapor extraction wells were decommissioned in October 2014. The NW corner of Chestnut and Emory St. remains open for solvent release; additional site characterization and recommendations for corrective action are required. Phase II Environmental Site Assessment for the property located at 561- 595 Emory Street (1-ac) was conducted in 2015; elevated concentrations of TCE up to 1,200 ug/L in the GW sample (B-1).

Click here to access the California GeoTracker records for this facility:

BROWNFIELDS:

 Global ID:
 SL0608583805

 Latitude:
 37.343948443

 Longitude:
 -121.91404402

 Project Type:
 Cleanup Program Site

Status: Open - Assessment & Interim Remedial Action

Status Date: 02/20/2018

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Last Correspondence Date: 09/05/2018 Release Type: Unknown

Contaminant(s) of Concern: 1,1,1-Trichloroethane (TCA), Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Tri

Media of Concern: Other Groundwater (uses other than drinking water), Soil, Soil Vapor

Past Use(s) that Caused Contamination: MANUFACTURING - METAL

Human Health Exposure Controlled: NO
Human Health Exposure Controlled Date: 05/19/2017
Groundwater Migration Controlled: NO
Groundwater Migration Controlled Date: 01/01/2018
Primary Caseworker Name: RON GOLOUBOW

Primary Caseworker Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

Primary Caseworker Phone Number: 510-622-2442

Primary Caseworker Address: 1515 CLAY STREET SUITE 1400

Primary Caseworker Address: OAKLAND

Primary Caseworker Address: CA

Primary Caseworker Email: ron.goloubow@waterboards.ca.gov

NOTIFY 65:

Date Reported: Not reported Staff Initials: Not reported Board File Number: Not reported Facility Type: Not reported Discharge Date: Not reported Incident Description: Not reported Not reported Not reported Not reported Incident Description: Not reported

Date Reported:
Staff Initials:

Board File Number:
Facility Type:
Discharge Date:
Issue Date:
Not reported

CERS TANKS:

Site ID: 253897

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

WILLIAMS MANUFACTURING (Continued)

S109850922

CERS ID: SL0608583805
CERS Description: Cleanup Program Site

Affiliation:

Affiliation Type Desc: Regional Board Caseworker

Entity Name: RON GOLOUBOW - SAN FRANCISCO BAY RWQCB (REGION 2)

Entity Title: Not reported

Affiliation Address: 1515 Clay Street Suite 1400

Affiliation City: OAKLAND
Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: 5106222442

AU248 SAN JOSE GAS WORKS EDR MGP 1008407765

East E. SAN FERNANDO AND S. 4TH N/A

1/2-1 SAN JOSE, CA 95112

0.865 mi.

4569 ft. Site 1 of 2 in cluster AU

Relative: Manufactured Gas Plants:

Higher Alternate Name:SAN JOSE LIGHT AND POWER CO. No additional information available

Actual: 87 ft.

AU249 SAN ANTONIO PLAZA BLOCK 4 NORTH ENVIROSTOR S106568336
East WEST SAN FERNANDO ST & 4TH STREET VCP N/A

1/2-1 SAN JOSE, CA 95113

0.878 mi.

4634 ft. Site 2 of 2 in cluster AU

Relative: ENVIROSTOR:

 Higher
 Facility ID:
 43490065

 Actual:
 Status:
 Certified

 87 ft.
 Status Date:
 06/26/1995

 Site Code:
 200528

Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup

Acres: 1.7
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Barbara Cook
Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Voluntary Cleanup Program

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: Responsible Party

Latitude: 37.33555 Longitude: -121.8861

APN: NONE SPECIFIED

Past Use: MANUFACTURED GAS PLANT

Potential COC: Polynuclear aromatic hydrocarbons (PAHs

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN ANTONIO PLAZA BLOCK 4 NORTH (Continued)

S106568336

EDR ID Number

Confirmed COC: Polynuclear aromatic hydrocarbons (PAHs

Potential Description: SOIL

Alias Name: BLOCK FOUR: ANTONIO PLAZA

 Alias Type:
 Alternate Name

 Alias Name:
 110033609021

 Alias Type:
 EPA (FRS #)

 Alias Name:
 200528

Alias Type: Project Code (Site Code)

Alias Name: 43490065

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Removal Action Completion Report

Completed Date: 06/26/1995 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation / Feasibility Study

Completed Date: 06/30/1994
Comments: Completed RIFS.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 10/20/1992

Comments: Completed Site Screening.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: *Voluntary Cleanup Agreement Completion

Completed Date: 06/30/1995 Comments: Completed PEA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Completed Date: 06/26/1995
Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Voluntary Cleanup Agreement

Completed Date: 10/25/1994 Comments: Signed a VCA

Not reported Future Area Name: Not reported Future Sub Area Name: Future Document Type: Not reported Not reported Future Due Date: Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Not reported Schedule Document Type: Schedule Due Date: Not reported Schedule Revised Date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

SAN ANTONIO PLAZA BLOCK 4 NORTH (Continued)

S106568336

EDR ID Number

VCP:

Facility ID: 43490065
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED

Acres: 1.7
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP

Lead Agency Description: DTSC - Site Cleanup Program

Project Manager: Not reported
Supervisor: Barbara Cook
Division Branch: Cleanup Berkeley

 Site Code:
 200528

 Assembly:
 27

 Senate:
 15

Special Programs Code: Voluntary Cleanup Program

Status: Certified
Status Date: 06/26/1995
Restricted Use: NO

Funding: Responsible Party
Lat/Long: 37.33555 / -121.8861
APN: NONE SPECIFIED

Past Use: MANUFACTURED GAS PLANT

Potential COC: 30019 Confirmed COC: 30019 Potential Description: SOIL

Alias Name: BLOCK FOUR: ANTONIO PLAZA

 Alias Type:
 Alternate Name

 Alias Name:
 110033609021

 Alias Type:
 EPA (FRS #)

 Alias Name:
 200528

Alias Type: Project Code (Site Code)

Alias Name: 43490065

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Removal Action Completion Report

Completed Date: 06/26/1995 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Remedial Investigation / Feasibility Study

Completed Date: 06/30/1994 Comments: Completed RIFS.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 10/20/1992

Comments: Completed Site Screening.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

SAN ANTONIO PLAZA BLOCK 4 NORTH (Continued)

S106568336

Completed Document Type: *Voluntary Cleanup Agreement Completion

06/30/1995 Completed Date: Comments: Completed PEA.

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Certification Completed Document Type: Completed Date: 06/26/1995 Comments: Not reported

PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported

Completed Document Type: Voluntary Cleanup Agreement

Completed Date: 10/25/1994 Comments: Signed a VCA

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

UNIVERSITY PLATING CO RCRA-LQG 1000431658 **650 UNIVERSITY AVE ENVIROSTOR** CAD009112269

NW SAN JOSE, CA 95110 1/2-1 0.931 mi.

CUPA Listings NPDES SAN JOSE HAZMAT CIWQS

Relative: Lower

4915 ft.

250

Actual: RCRA-LQG: 78 ft.

Date form received by agency: 05/19/2016

UNIVERSITY PLATING CO Facility name: Facility address: 650 UNIVERSITY AVE

SAN JOSE, CA 95110 EPA ID: CAD009112269 Mailing address: **UNIVERSITY AVE**

SAN JOSE, CA 95110

CARTER HANE Contact: Contact address: **UNIVERSITY AVE** SAN JOSE, CA 95110

Contact country: US

Contact telephone: 408-292-2140

CARTERHANE@HOTMAIL.COM Contact email:

EPA Region: 09 Land type:

Classification: Large Quantity Generator

Description: Handler: generates 1,000 kg or more of hazardous waste during any

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely

CERS HAZ WASTE

CERS

Direction Distance Elevation

Site Database(s) **EPA ID Number**

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: HANE & HANE Owner/operator address: NOT REQUIRED

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Not reported Owner/operator extension: Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: CARTER HANE Owner/operator address: UNIVERSITY AVE

SAN JOSE, CA 95110

Owner/operator country: US

Owner/operator telephone: 408-292-2140 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 01/01/1978 Owner/Op end date: Not reported

Owner/operator name: CARTER HANE Owner/operator address: Not reported Not reported Owner/operator country: Not reported Owner/operator telephone: Not reported

Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Operator 01/01/1978 Owner/Op start date: Owner/Op end date: Not reported

NOT REQUIRED Owner/operator name: Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported Owner/operator telephone: 415-555-1212 Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private

Owner/Operator Type: Operator

Distance Floration Site

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: Yes Underground injection activity: No On-site burner exemption: No Furnace exemption: Nο Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

. Waste code: 171

Waste name: Metal sludge (see 121)

. Waste code: 792

. Waste name: Liquids with pH < 2 with metals

Waste code: D002

. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

. Waste code: F006

Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT

FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF

ALUMINUM.

Historical Generators:

Date form received by agency: 01/04/2006

Site name: UNIVERSITY PLATING COMPANY

Classification: Large Quantity Generator

. Waste code: F006

. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT

FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS)

Direction Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Date form received by agency: 02/13/2002

Site name: UNIVERSITY PLATING COMPANY

Classification: Large Quantity Generator

Date form received by agency: 10/12/2000

Site name: UNIVERSITY PLATING COMPANY

Classification: Large Quantity Generator

Date form received by agency: 09/01/1996

Site name: UNIVERSITY PLATING CO
Classification: Small Quantity Generator

Date form received by agency: 04/01/1992

Site name: UNIVERSITY PLATING
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980

Site name: UNIVERSITY PLATING CO
Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 22888.8

Waste code: F006

Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT

FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM;

(2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF

ALUMINUM.

Amount (Lbs): 22888.8

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 11/09/2015
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: Not reported

Enforcement action.

Enforcement action date:

Enf. disposition status:

Enf. disp. status date:

Enforcement lead agency:

Proposed penalty amount:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Direction Distance Elevation

ion Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - Records/Reporting
Date violation determined: 11/09/2015

Date violation determined: Date achieved compliance: Not reported State Violation lead agency: Enforcement action: Not reported Enforcement action date: Not reported Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: Not reported Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - Pre-transport

Date violation determined: 11/09/2015
Date achieved compliance: Not reported Violation lead agency: State

Enforcement action: Not reported Enforcement action date: Not reported Enf. disposition status: Not reported Not reported Enf. disp. status date: Enforcement lead agency: Not reported Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 03/08/2006
Date achieved compliance: 03/29/2006
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/08/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Paid penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 07/14/2003
Date achieved compliance: 07/24/2003
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 07/14/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 11/09/2015

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 11/09/2015

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: Not reported

Evaluation lead agency: State

Evaluation date: 11/09/2015

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Records/Reporting

Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 03/08/2006

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 03/29/2006

Evaluation lead agency: State Contractor/Grantee

Evaluation date: 07/14/2003

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 07/24/2003

Evaluation lead agency: State Contractor/Grantee

ENVIROSTOR:

Facility ID: 71002255

Status: Inactive - Needs Evaluation

Status Date: Not reported
Site Code: Not reported
Site Type: Tiered Permit
Site Type Detailed: Tiered Permit
Acres: Not reported

NPL: NO

Regulatory Agencies: NONE SPECIFIED NONE SPECIFIED NONE SPECIFIED Not reported Supervisor: Not reported Division Branch: Cleanup Berkeley

Assembly: 27 Senate: 15

Special Program: Not reported

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.34370
Longitude: -121.9161

APN: NONE SPECIFIED Past Use: NONE SPECIFIED

Direction Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAD009112269

Alias Type: EPA Identification Number

Alias Name: 110002634944
Alias Type: EPA (FRS #)
Alias Name: 71002255

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: Not reported
Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Comments: Not reported
Not reported
Not reported

Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Not reported Schedule Area Name: Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

CERS HAZ WASTE:

 Site ID:
 79175

 CERS ID:
 10354795

CERS Description: Hazardous Waste Onsite Treatment

Violations:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.173

Violation Description: Failure to properly close hazardous waste containers when not in

active use.

Violation Notes: Bucket of waste in lab is open.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include all of the following in the Contingency Plan: 1) A

description of actions the facility personnel shall take response to fires, explosions, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water at the facility; 2) A description of arrangements agreed

to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services; 3) All names, addresses, and phone

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

numbers (office and home) of all persons qualified to act as emergency coordinator and this list shall be kept up to date. Where more than one person is listed, one shall be named as primary emergency coordinator and others shall be listed in the order in which they will assume responsibility as alternates; 4) A list of all emergency equipment at the facility (such as fire extinguishing systems, spill control equipment, communications and alarm systems (internal and external), and decontamination equipment), where this equipment is required. This list shall be kept up to date. In addition, the plan shall include the location and a physical description of each item on the list, and a brief outline of its capabilities; 5) An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary. This plan is to describe signal(s) to be used to begin evacuation, evacuation routes, and alternate evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or fires); 6) The current telephone number of the California Emergency Management Agency; and 7) If the owner or operator has already prepared a Spill Prevention, Control, and Countermeasures (SPCC) or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management provisions that are sufficient to comply with the requirements of this chapter.

Violation Notes: Facility could not produce a complete contingency plan. Portions of

the plan were available but a complete plan was not available. Unidocs version of the Contingency plan from 2012 was onsite, but was incomplete in that it did not have updated phone numbers for the CUPA

or the names or emergency contacts.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HWLQG** Violation Source: **CERS**

Site ID: 79175

UNIVERSITY PLATING Site Name:

Violation Date: 11-09-2015

HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Citation:

Section(s) Multiple

Violation Description: Tiered Permitting Program - Administration/Documentation - General Violation Notes:

Tank assessment provided did not include all elements required by

Title 22, section 66265.192(h).

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR Violation Source: **CERS**

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

22 CCR 15 66265.194 - California Code of Regulations, Title 22, Citation:

Chapter 15, Section(s) 66265.194

Violation Description: Failure to maintain the following general tank operating requirements:

a) Hazardous wastes or treatment reagents shall not be placed in a tank system if they could cause the tank, its ancillary equipment, or the secondary containment system to rupture, leak, corrode, or otherwise fail. b) The owner or operator shall use appropriate controls and practices to prevent spills and overflows from tank or secondary containment systems. These include at a minimum: 1) Spill prevention controls (e.g., check valves, dry discount couplings): 2) Overfill prevention controls (e.g., level sensing devices, high level

Map ID
Direction
Distance

Site

Elevation

MAP FINDINGS

EDR ID Number
Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

alarms, automatic feed cutoff, or bypass to a standby tank); and 3) Maintenance of sufficient freeboard in uncovered tanks to prevent overtopping by wave or wind action or by precipitation. Uncovered tanks shall be operated to ensure at least 60 centimeters (2 feet) of freeboard, unless the tank is equipped with a containment structure (e.g., dike or trench), a drainage control system or a diversion structure (e.g., standby tank) with a capacity that equals or exceeds

the volume of the top 60 centimeters (2 feet) of the tank.

Violation Notes: Tanks are indicated as being 350 gallons in size and are operated with

an open top. Logs of treatment quantities indicate batches of 350 gallons routinely treated. Tanks area not equipped with overfill prevention and do not appear to have at least two feet of freeboard

maintained while waste is in the tanks.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)).

Violation Notes: Closure cost estimate for 2015 was incomplete in that it does not

reflect the following: - The cost of a PE certification that the closure is completed in accordance with the facility s Closure Plan and the requirements of Chapter 45, Title 22, CCR [67450.3(c)(11)(G)]. - The cost of sampling at the time of closure. - A PBR Closure permit required by HMCD (\$2598.00). - The final hazardous waste pick-up to occur. - Costs associated with the decontamination of the filter press. - Additionally, the Closure Cost Estimate accounts for the decontamination of 5x55 gallon containers, but 7x55 gallon and 1 x 100

gallon containers (zinc strip) are used for onsite treatment.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: RCRA Large Quantity Generator Program - Administration/Documentation -

General

Violation Notes: Facility generated over 12,000kg of hazardous waste in a reporting

year and failed to conduct a source reduction evaluation review and plan pursuant to CCR 67100.5. Facility stated that they do not meet the requirements to create a Waste Minimization Plan, because the facility shipped less than 12,000 kg of waste in 2006, 2010 and 2014.

Distance EDR ID Number
Elevation Site EDA ID Number

UNIVERSITY PLATING CO (Continued)

Violation Division:

1000431658

Facility s waste generation calculation is only based on the amount of waste shipped offsite and not based on the amount of waste generated prior to treatment. Treatment logs indicated that >12,000kg of waste were treated in 2014. Complete a source reduction evaluation review and plan pursuant the plan format requirements of CCR 67100.5, including but not limited to 1) the name and location of the site, phone number, and identification number, 2) SIC codes, 3) type of business or activity conducted, 4) length of time the company has been in business, 5) products manufactured and services provided, 6) number

of employees, 7) description [Truncated]
Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.2(c)(10) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(c)(10)

Violation Description: Failure of the generator to prepare, maintain, and submit to CUPA an

annual report containing the following information: (A) The serial number(s) of the FTU(s) involved in treatment; (B) The physical and mailing address of the business entity which owns or operates the FTU(s); (C) The name, title and telephone number of each FTU contact person; (D) The name and address or legal description of the facility; (E) The facility identification number; (F) The number of days each FTU was operated; (G) The quantity of hazardous waste(s) treated by each FTU; (H) The composition and hazardous characteristics of the influent hazardous waste(s); (I) The treatment method(s) used for each hazardous waste treated by each FTU; (J) The quantity, composition and hazardous characteristic(s) of any treatment effluent or residual

discharged from each FTU to a POTW, if applicable; and (K) The quantity, composition, hazardous characteristic(s) and disposition of any FTU treatment effluent or residual that was not discharged to a

POTW, if applicable.

Violation Notes: Annual treatment renewal submitted 2/2015 includes additional

information not pertinent to the system. Marked up copy of

notification provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.23(a)(4) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.23(a)(4)

Violation Description: Failure to send hazardous waste manifest copies to DTSC.

Violation Notes: Both the TSDF and Generator copy of Manifest #013367497JJK (Ship Date:

9/29/2014) were reviewed at the facility, but a copy of the manifest

was not submitted to DTSC.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Distance EDR ID Number
Elevation Site EPA ID Number

UNIVERSITY PLATING CO (Continued)

Violation Date: 11-09-2015
Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act. Waste analysis plan was not available on day of inspection. This was a

repeat violation from the prior inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Violation Notes:

Site ID: 79175
Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Last HMBP information submitted accounts only for materials stored in

the waste treatment area. A complete HMBP must account for all materials stored onsite at or above reporting thresholds (including

all plating and rinse baths).

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting Program - Operations/Maintenance - General Violation Notes: Chromate system utilizes addition of metabisulfite to reduce Cr6+ to

Cr3+. Addition of chemicals is done manually, where regulations

require automated addition.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

1000431658

Distance
Elevation Site Database(s)

UNIVERSITY PLATING CO (Continued)

Violation Notes:

1000431658

EDR ID Number

EPA ID Number

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the operation of the facility within the last three years, as the

documents would be available under the California Public Records Act.

Closure plan is incomplete in that it does not address the following:

- When each FTU will be closed and the maximum extent of operation during the life of the FTUs. - Closure Plan states that all FTU

containment system will be washed, decontaminated, and inspected, but a description of the steps that will be required to remove hazardous waste and decontaminate the equipment, containers, tank systems, and contaminated soils is not provided. - Closure Plan states that it will continue to decontaminate the treatment system until the samples taken of wash down solutions and the unit are rendered non-hazardous, but the how the facility will demonstrate that the solutions and unit are non-hazardous in accordance with CCR 66261.3(d)-(e) is not addressed. - An expected year of closure is not included in the Closure Plan. - A

broad schedule for final closure activities is provided, but a schedule for final closure of each FTU, including the total time

requirement to close [Truncated]

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all

required content.

Violation Notes: Site map submitted 7/1/15 is incomplete. CERS response on 8/2/15 asked

for map to be revised prior to next inspection. Map does not indicate storage areas 8, 2, 3, or 5 or the oxidizer shed. It also is missing the locations of local water and gas shut-offs, locations of emergency

equipment or the location of University Avenue.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.197 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.197

Violation Description: Failure to properly close a hazardous waste tank system ensuring the

Map ID Direction Distance Elevation MAP FINDINGS

EDR ID Number EPA ID Number Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

minimization of further maintenance and that the following requirements are met: a) The owner or operator shall remove or decontaminate all waste residues, contaminated containment system components (liners, etc.), contaminated soils, and structures and equipment contaminated with waste, and manage them as hazardous waste. The closure plan, closure activities, cost estimates for closure, and financial responsibility for tank systems shall meet all of the requirements specified in articles 7 and 8 of this chapter. b) If the owner or operator demonstrates that not all contaminated soils can be practicably removed or decontaminated as required in subsection (a) of this section, then the owner or operator shall close the tank system and perform post-closure care in accordance with the closure and post-closure care requirements that apply to landfills (section 66265.310). In addition, for the purposes of closure, post-closure, and financial responsibility, such a tank system is then considered to be a landfill, and the owner or operator shall meet all of the requirements for landfills specified in articles 7 and 8 of this chapter. c) If an owner or operator has a tank system which does not have secondary containment that meets the requirements of section 66265.193(b) through (f) and which has not been granted a variance from the secondary containment requirements in accordance with section 66265.193(g), then: 1) The closure plan for the tank system shall include both a plan for complying with subsection (a) of this section and a contingent plan for complying with subsection b) of this section; 2) A contingent post-closure plan for complying with subsection (b) of this section shall be prepared and submitted as part of the permit application; 3) The cost estimates calculated for closure and post-closure care shall reflect the costs of complying with the contingent closure plan and the contingent post-closure plan, if these costs are greater than the

Violation Notes:

Three tanks used for the treatment of hazardous waste were replaced in 2015 but documentation of proper closure and disposal of the tanks was not available. Corrective Action: Please explain how these tanks were closed and were disposed of. Tanks must either be managed as hazardous

wastes or must be certified as clean according to Title 22, CCR,

section 67383.3 standards.

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Site ID: 79175

UNIVERSITY PLATING Site Name:

Violation Date: 11-09-2015

22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter Citation:

15, Section(s) 66265.16

Violation Description: Failure to provide employees within the first six months after the

date of their employment, or assignment to the facility, or to work unsupervised, or to a new position at a facility with hazardous waste training to ensure employees are competent in the following areas: hazardous waste management procedures (including contingency plan implementation) relevant to the positions in which they are employed, emergency response and emergency equipment, and procedures for using, inspecting, repairing, and replacing facility emergency and monitoring equipment. In addition, the owner/operator shall ensure facility personnel take part in an annual review of the initial training and training records training records on current personnel shall be kept until closure of the facility. Training records on former employees

Direction Distance Elevation

vation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel

assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given

to each person filling a position.

Violation Notes: Training record indicates that hazardous waste training will be

provided by an outside vendor every 3 years. last noted exterior

provider training was by Du-All Safety in 2009.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.40(a)

Violation Description: Failure to maintain uniform hazardous waste manifest, consolidated

manifest, or bills of lading copies for three years.

Violation Notes: The TSDF copy of Manifest #012207871JJK (Ship Date: 11/27/2013) was

not retained onsite. If facility did not receive a TSDF copy, an

exception report is required to be submitted to DTSC within 45 days of

the waste shipment [CCR 66262.42].

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Chromate treatment System is a batch treatment system consisting of one 350 gallon batch treatment tank, two sludge holding tanks, and one

filter press. (WT2, WT4A, WT4B, Filter Press) Receive wastes from the clear zinc processes, alodining processes and associated rinses and floor drain system along alodine/anodize line. All wastes are manually pumped to the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to the press for de watering. Water removed by the press is routed back into tank WT9 (Neutralization tank) Tank WT2 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10354795 Last submittal 7/1/15. Administratively accepted by

HMCD 8/2/15.

Direction Distance Flevation

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Zinc treatment System is a batch treatment system consisting of one

350 gallon batch treatment tank and sludge holding tank.(WT7, WT6A) Filter Press is shared with chromate treatment system and is notified for as part of that system. Receive wastes from the zinc rinses and floor drain system along zinc line. All wastes are manually pumped to

the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to

the press for de watering. Tank WT7 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is job plating shop that does zinc plating, alodine/dying and

anodizing. Rinses are managed as counter-current with primary rinse used as much as needed to make up water for plating solutions. Most rinses are static. Do have some spray rinsing stations, with spray rinse taking place in the aisles between bath/rinse tanks. Floors are "dry floors" with liner system above floors which routes all dragout and rinse to a collection point from which it is transferred to a waste treatment area. -Facility has received training on and states that is practices MFA Nor Cal floor management practices. -have inspection logs noting the daily inspection of plating area floors. Sludge from treatment process is drained to hopper which is labeled as HW, and then transferred to 55 gallon drums for disposal. --PPE used on the plating line as well as blast media are also added to these drums. Onsite lab waste is added to waste treatment system. Have blast

cabinet used to [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HWLQG Eval Source: CERS

Affiliation:

Affiliation Type Desc: **Document Preparer** Entity Name: Sharon Hane **Entity Title:** Not reported Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: Not reported

Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: Sharon Hane Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: UNIVERSITY PLATING CO.

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation City:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

(408) 292-2140

Affiliation Type Desc: Property Owner
Entity Name: Sharon Hane
Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 292-2140

Affiliation Type Desc: Legal Owner

Entity Name: UNIVERSITY PLATING

Entity Title: Not reported

Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110
Affiliation Phone: (408) 292-2140

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported

Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: carter hane **Entity Title:** president Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact

Entity Name: Edgar parra Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 836-5158

Affiliation Type Desc: Parent Corporation
Entity Name: UNIVERSITY PLATING

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

 Site ID:
 79175

 CERS ID:
 10354795

CERS Description: RCRA LQ HW Generator

Violations:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.173

Violation Description: Failure to properly close hazardous waste containers when not in

active use.

Violation Notes: Bucket of waste in lab is open.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include all of the following in the Contingency Plan: 1) A

description of actions the facility personnel shall take response to

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

fires, explosions, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water at the facility; 2) A description of arrangements agreed to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services; 3) All names, addresses, and phone numbers (office and home) of all persons qualified to act as emergency coordinator and this list shall be kept up to date. Where more than one person is listed, one shall be named as primary emergency coordinator and others shall be listed in the order in which they will assume responsibility as alternates; 4) A list of all emergency equipment at the facility (such as fire extinguishing systems, spill control equipment, communications and alarm systems (internal and external), and decontamination equipment), where this equipment is required. This list shall be kept up to date. In addition, the plan shall include the location and a physical description of each item on the list, and a brief outline of its capabilities; 5) An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary. This plan is to describe signal(s) to be used to begin evacuation, evacuation routes, and alternate evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or fires); 6) The current telephone number of the California Emergency Management Agency: and 7) If the owner or operator has already prepared a Spill Prevention, Control, and Countermeasures (SPCC) or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management provisions that are sufficient to comply with the requirements of this chapter.

Violation Notes: Facility could not produce a complete contingency plan. Portions of

> the plan were available but a complete plan was not available. Unidocs version of the Contingency plan from 2012 was onsite, but was

> incomplete in that it did not have updated phone numbers for the CUPA

or the names or emergency contacts.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HWLQG** Violation Source: **CERS**

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting Program - Administration/Documentation - General Violation Notes:

Tank assessment provided did not include all elements required by

Title 22, section 66265.192(h).

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR** Violation Source: **CERS**

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

22 CCR 15 66265.194 - California Code of Regulations, Title 22, Citation:

Chapter 15, Section(s) 66265.194

Violation Description: Failure to maintain the following general tank operating requirements:

a) Hazardous wastes or treatment reagents shall not be placed in a tank system if they could cause the tank, its ancillary equipment, or

Distance Elevation

Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

the secondary containment system to rupture, leak, corrode, or otherwise fail. b) The owner or operator shall use appropriate controls and practices to prevent spills and overflows from tank or secondary containment systems. These include at a minimum: 1) Spill prevention controls (e.g., check valves, dry discount couplings); 2) Overfill prevention controls (e.g., level sensing devices, high level alarms, automatic feed cutoff, or bypass to a standby tank); and 3) Maintenance of sufficient freeboard in uncovered tanks to prevent overtopping by wave or wind action or by precipitation. Uncovered tanks shall be operated to ensure at least 60 centimeters (2 feet) of freeboard, unless the tank is equipped with a containment structure (e.g., dike or trench), a drainage control system or a diversion structure (e.g., standby tank) with a capacity that equals or exceeds

the volume of the top 60 centimeters (2 feet) of the tank.

Violation Notes: Tanks are indicated as being 350 gallons in size and are operated with

an open top. Logs of treatment quantities indicate batches of 350 gallons routinely treated. Tanks area not equipped with overfill prevention and do not appear to have at least two feet of freeboard maintained while waste is in the tanks.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)).

Violation Notes: Closure cost estimate for 2015 was incomplete in that it does not

reflect the following: - The cost of a PE certification that the closure is completed in accordance with the facility s Closure Plan and the requirements of Chapter 45, Title 22, CCR [67450.3(c)(11)(G)]. - The cost of sampling at the time of closure. - A PBR Closure permit required by HMCD (\$2598.00). - The final hazardous waste pick-up to occur. - Costs associated with the decontamination of the filter press. - Additionally, the Closure Cost Estimate accounts for the decontamination of 5x55 gallon containers, but 7x55 gallon and 1 x 100

gallon containers (zinc strip) are used for onsite treatment.

Violation Division: Santa Clara County Environmental Health Violation Program: PBR

79175

Violation Program: PBR
Violation Source: CERS

Site ID:

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: RCRA Large Quantity Generator Program - Administration/Documentation -

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

General

Violation Notes: Facility generated over 12,000kg of hazardous waste in a reporting

year and failed to conduct a source reduction evaluation review and plan pursuant to CCR 67100.5. Facility stated that they do not meet the requirements to create a Waste Minimization Plan, because the facility shipped less than 12,000 kg of waste in 2006, 2010 and 2014. Facility s waste generation calculation is only based on the amount of waste shipped offsite and not based on the amount of waste generated prior to treatment. Treatment logs indicated that >12,000kg of waste were treated in 2014. Complete a source reduction evaluation review and plan pursuant the plan format requirements of CCR 67100.5, including but not limited to 1) the name and location of the site, phone number, and identification number, 2) SIC codes, 3) type of business or activity conducted, 4) length of time the company has been in business, 5) products manufactured and services provided, 6) number

of employees, 7) description [Truncated]
Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Violation Division:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.2(c)(10) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(c)(10)

Violation Description: Failure of the generator to prepare, maintain, and submit to CUPA an

annual report containing the following information: (A) The serial number(s) of the FTU(s) involved in treatment; (B) The physical and mailing address of the business entity which owns or operates the FTU(s); (C) The name, title and telephone number of each FTU contact person; (D) The name and address or legal description of the facility; (E) The facility identification number; (F) The number of days each FTU was operated; (G) The quantity of hazardous waste(s) treated by each FTU; (H) The composition and hazardous characteristics of the influent hazardous waste(s); (I) The treatment method(s) used for each hazardous waste treated by each FTU; (J) The quantity, composition and

hazardous characteristic(s) of any treatment effluent or residual discharged from each FTU to a POTW, if applicable; and (K) The quantity, composition, hazardous characteristic(s) and disposition of any FTU treatment effluent or residual that was not discharged to a

POTW, if applicable.

Violation Notes: Annual treatment renewal submitted 2/2015 includes additional

information not pertinent to the system. Marked up copy of

notification provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.23(a)(4) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.23(a)(4)

Violation Description: Failure to send hazardous waste manifest copies to DTSC.

Violation Notes: Both the TSDF and Generator copy of Manifest #013367497JJK (Ship Date:

9/29/2014) were reviewed at the facility, but a copy of the manifest

was not submitted to DTSC.

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act. Waste analysis plan was not available on day of inspection. This was a

repeat violation from the prior inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Violation Notes:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Last HMBP information submitted accounts only for materials stored in

the waste treatment area. A complete HMBP must account for all materials stored onsite at or above reporting thresholds (including

all plating and rinse baths).

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting Program - Operations/Maintenance - General

Violation Notes: Chromate system utilizes addition of metabisulfite to reduce Cr6+ to

Cr3+. Addition of chemicals is done manually, where regulations

require automated addition.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

Violation Notes:

1000431658

Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the documents would be available under the California Public Records Act.

Closure plan is incomplete in that it does not address the following:

- When each FTU will be closed and the maximum extent of operation

during the life of the FTUs. - Closure Plan states that all FTU

containment system will be washed, decontaminated, and inspected, but a description of the steps that will be required to remove hazardous waste and decontaminate the equipment, containers, tank systems, and contaminated soils is not provided. - Closure Plan states that it will continue to decontaminate the treatment system until the samples taken of wash down solutions and the unit are rendered non-hazardous, but the how the facility will demonstrate that the solutions and unit are non-hazardous in accordance with CCR 66261.3(d)-(e) is not addressed. - An expected year of closure is not included in the Closure Plan. - A

broad schedule for final closure activities is provided, but a schedule for final closure of each FTU, including the total time

requirement to close [Truncated]

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all

required content.

Violation Notes: Site map submitted 7/1/15 is incomplete. CERS response on 8/2/15 asked

for map to be revised prior to next inspection. Map does not indicate storage areas 8, 2, 3, or 5 or the oxidizer shed. It also is missing the locations of local water and gas shut-offs, locations of emergency

equipment or the location of University Avenue.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Map ID
Direction
Distance

Elevation

Site

MAP FINDINGS

EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.197 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.197

Violation Description: Failure to properly close a hazardous waste tank system ensuring the

minimization of further maintenance and that the following requirements are met: a) The owner or operator shall remove or decontaminate all waste residues, contaminated containment system components (liners, etc.), contaminated soils, and structures and

equipment contaminated with waste, and manage them as hazardous waste.

The closure plan, closure activities, cost estimates for closure, and financial responsibility for tank systems shall meet all of the requirements specified in articles 7 and 8 of this chapter. b) If the owner or operator demonstrates that not all contaminated soils can be practicably removed or decontaminated as required in subsection (a) of this section, then the owner or operator shall close the tank system and perform post-closure care in accordance with the closure and post-closure care requirements that apply to landfills (section 66265.310). In addition, for the purposes of closure, post-closure, and financial responsibility, such a tank system is then considered to be a landfill, and the owner or operator shall meet all of the

requirements for landfills specified in articles 7 and 8 of this chapter. c) If an owner or operator has a tank system which does not have secondary containment that meets the requirements of section 66265.193(b) through (f) and which has not been granted a variance from the secondary containment requirements in accordance with section 66265.193(g), then: 1) The closure plan for the tank system shall include both a plan for complying with subsection (a) of this section

and a contingent plan for complying with subsection b) of this section; 2) A contingent post-closure plan for complying with subsection (b) of this section shall be prepared and submitted as part of the permit application; 3) The cost estimates calculated for closure and post-closure care shall reflect the costs of complying with the contingent closure plan and the contingent post-closure plan,

if these costs are greater than the

Violation Notes: Three tanks used for the treatment of hazardous waste were replaced in

2015 but documentation of proper closure and disposal of the tanks was not available. Corrective Action: Please explain how these tanks were closed and were disposed of. Tanks must either be managed as hazardous

wastes or must be certified as clean according to Title 22, CCR,

section 67383.3 standards.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.16

Violation Description: Failure to provide employees within the first six months after the

date of their employment, or assignment to the facility, or to work unsupervised, or to a new position at a facility with hazardous waste training to ensure employees are competent in the following areas: hazardous waste management procedures (including contingency plan implementation) relevant to the positions in which they are employed,

Distance Elevation

EPA ID Number Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

emergency response and emergency equipment, and procedures for using, inspecting, repairing, and replacing facility emergency and monitoring equipment. In addition, the owner/operator shall ensure facility personnel take part in an annual review of the initial training and training records training records on current personnel shall be kept until closure of the facility. Training records on former employees shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel

assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given

to each person filling a position.

Violation Notes: Training record indicates that hazardous waste training will be

provided by an outside vendor every 3 years. last noted exterior

provider training was by Du-All Safety in 2009.

Violation Division: Santa Clara County Environmental Health

Violation Program: **HWLQG** Violation Source: CERS

Site ID: 79175

UNIVERSITY PLATING Site Name:

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.40(a)

Violation Description: Failure to maintain uniform hazardous waste manifest, consolidated

manifest, or bills of lading copies for three years.

The TSDF copy of Manifest #012207871JJK (Ship Date: 11/27/2013) was Violation Notes:

> not retained onsite. If facility did not receive a TSDF copy, an exception report is required to be submitted to DTSC within 45 days of

the waste shipment [CCR 66262.42].

Violation Division: Santa Clara County Environmental Health

Violation Program: **HWLQG** Violation Source: **CERS**

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Chromate treatment System is a batch treatment system consisting of

one 350 gallon batch treatment tank, two sludge holding tanks, and one filter press.(WT2, WT4A, WT4B, Filter Press) Receive wastes from the clear zinc processes, alodining processes and associated rinses and floor drain system along alodine/anodize line. All wastes are manually pumped to the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to the press for de watering. Water removed by the press is routed back into tank WT9 (Neutralization tank) Tank WT2 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: **PBR** Eval Source: **CERS**

Direction Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015

Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10354795 Last submittal 7/1/15. Administratively accepted by

HMCD 8/2/15.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Zinc treatment System is a batch treatment system consisting of one

350 gallon batch treatment tank and sludge holding tank.(WT7, WT6A) Filter Press is shared with chromate treatment system and is notified for as part of that system. Receive wastes from the zinc rinses and floor drain system along zinc line. All wastes are manually pumped to

the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to

the press for de watering. Tank WT7 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is job plating shop that does zinc plating, alodine/dying and

anodizing. Rinses are managed as counter-current with primary rinse used as much as needed to make up water for plating solutions. Most rinses are static. Do have some spray rinsing stations, with spray rinse taking place in the aisles between bath/rinse tanks. Floors are "dry floors" with liner system above floors which routes all dragout and rinse to a collection point from which it is transferred to a waste treatment area. -Facility has received training on and states that is practices MFA Nor Cal floor management practices. -have inspection logs noting the daily inspection of plating area floors. Sludge from treatment process is drained to hopper which is labeled as HW, and then transferred to 55 gallon drums for disposal. --PPE used on the plating line as well as blast media are also added to these drums. Onsite lab waste is added to waste treatment system. Have blast

cabinet used to [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HWLQG Eval Source: CERS

Affiliation:

Affiliation Type Desc:

Entity Name:

Entity Title:

Affiliation Address:

Document Preparer

Sharon Hane

Not reported

Not reported

Distance Elevation

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer **Entity Name:** Sharon Hane Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: UNIVERSITY PLATING CO.

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 292-2140

Affiliation Type Desc: Property Owner
Entity Name: Sharon Hane
Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 292-2140

Affiliation Type Desc: Legal Owner

Entity Name: UNIVERSITY PLATING

Entity Title: Not reported

Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 292-2140

Affiliation Type Desc: CUPA District

Direction Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: carter hane Entity Title: president Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact

Entity Name: Edgar parra Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: (408) 836-5158

Affiliation Type Desc: Parent Corporation
Entity Name: UNIVERSITY PLATING

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

 Site ID:
 79175

 CERS ID:
 10354795

CERS Description: Hazardous Waste Generator

Violations:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.173

Violation Description: Failure to properly close hazardous waste containers when not in

active use.

Violation Notes: Bucket of waste in lab is open.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include all of the following in the Contingency Plan: 1) A

description of actions the facility personnel shall take response to fires, explosions, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water at the facility; 2) A description of arrangements agreed to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services; 3) All names, addresses, and phone numbers (office and home) of all persons qualified to act as emergency coordinator and this list shall be kept up to date. Where more than one person is listed, one shall be named as primary emergency coordinator and others shall be listed in the order in which they will assume responsibility as alternates; 4) A list of all emergency equipment at the facility (such as fire extinguishing systems, spill control equipment, communications and alarm systems (internal and external), and decontamination equipment), where this equipment is required. This list shall be kept up to date. In addition, the plan shall include the location and a physical description of each item on the list, and a brief outline of its capabilities: 5) An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary. This plan is to describe signal(s) to be used to begin evacuation, evacuation routes, and alternate evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or fires); 6) The current telephone number of the California Emergency Management Agency; and 7) If the owner or operator has already prepared a Spill Prevention, Control,

with the requirements of this chapter.

Violation Notes: Facility could not produce a complete contingency plan. Portions of

> the plan were available but a complete plan was not available. Unidocs version of the Contingency plan from 2012 was onsite, but was

and Countermeasures (SPCC) or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management provisions that are sufficient to comply

incomplete in that it did not have updated phone numbers for the CUPA or the names or emergency contacts.

Santa Clara County Environmental Health

Violation Program: **HWLQG** Violation Source: **CERS**

Violation Division:

Site ID: 79175

UNIVERSITY PLATING Site Name:

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting Program - Administration/Documentation - General Violation Notes:

Tank assessment provided did not include all elements required by

Title 22, section 66265.192(h).

Violation Division: Santa Clara County Environmental Health

Violation Program: **PBR CERS** Violation Source:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

Violation Date: 11-09-2015
Citation: 22 CCR 15 66265.194 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.194

Violation Description: Failure to maintain the following general tank operating requirements:

a) Hazardous wastes or treatment reagents shall not be placed in a tank system if they could cause the tank, its ancillary equipment, or the secondary containment system to rupture, leak, corrode, or otherwise fail. b) The owner or operator shall use appropriate controls and practices to prevent spills and overflows from tank or secondary containment systems. These include at a minimum: 1) Spill prevention controls (e.g., check valves, dry discount couplings); 2) Overfill prevention controls (e.g., level sensing devices, high level alarms, automatic feed cutoff, or bypass to a standby tank); and 3) Maintenance of sufficient freeboard in uncovered tanks to prevent overtopping by wave or wind action or by precipitation. Uncovered tanks shall be operated to ensure at least 60 centimeters (2 feet) of freeboard, unless the tank is equipped with a containment structure (e.g., dike or trench), a drainage control system or a diversion structure (e.g., standby tank) with a capacity that equals or exceeds

the volume of the top 60 centimeters (2 feet) of the tank.

Violation Notes: Tanks are indicated as being 350 gallons in size and are operated with

an open top. Logs of treatment quantities indicate batches of 350 gallons routinely treated. Tanks area not equipped with overfill prevention and do not appear to have at least two feet of freeboard

maintained while waste is in the tanks.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)).

Violation Notes: Closure cost estimate for 2015 was incomplete in that it does not

reflect the following: - The cost of a PE certification that the closure is completed in accordance with the facility s Closure Plan and the requirements of Chapter 45, Title 22, CCR [67450.3(c)(11)(G)]. - The cost of sampling at the time of closure. - A PBR Closure permit required by HMCD (\$2598.00). - The final hazardous waste pick-up to occur. - Costs associated with the decontamination of the filter press. - Additionally, the Closure Cost Estimate accounts for the decontamination of 5x55 gallon containers, but 7x55 gallon and 1 x 100

gallon containers (zinc strip) are used for onsite treatment.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

1000431658

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: RCRA Large Quantity Generator Program - Administration/Documentation -

General

Violation Notes: Facility generated over 12,000kg of hazardous waste in a reporting

year and failed to conduct a source reduction evaluation review and plan pursuant to CCR 67100.5. Facility stated that they do not meet the requirements to create a Waste Minimization Plan, because the facility shipped less than 12,000 kg of waste in 2006, 2010 and 2014. Facility s waste generation calculation is only based on the amount of waste shipped offsite and not based on the amount of waste generated prior to treatment. Treatment logs indicated that >12,000kg of waste were treated in 2014. Complete a source reduction evaluation review and plan pursuant the plan format requirements of CCR 67100.5, including but not limited to 1) the name and location of the site, phone number, and identification number, 2) SIC codes, 3) type of business or activity conducted, 4) length of time the company has been in business, 5) products manufactured and services provided, 6) number

of employees, 7) description [Truncated]
Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Violation Division:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.2(c)(10) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(c)(10)

Violation Description: Failure of the generator to prepare, maintain, and submit to CUPA an

annual report containing the following information: (A) The serial number(s) of the FTU(s) involved in treatment; (B) The physical and mailing address of the business entity which owns or operates the FTU(s); (C) The name, title and telephone number of each FTU contact person; (D) The name and address or legal description of the facility; (E) The facility identification number; (F) The number of days each FTU was operated; (G) The quantity of hazardous waste(s) treated by each FTU; (H) The composition and hazardous characteristics of the influent hazardous waste(s); (I) The treatment method(s) used for each hazardous waste treated by each FTU; (J) The quantity, composition and

hazardous characteristic(s) of any treatment effluent or residual discharged from each FTU to a POTW, if applicable; and (K) The quantity, composition, hazardous characteristic(s) and disposition of any FTU treatment effluent or residual that was not discharged to a

POTW, if applicable.

Violation Notes: Annual treatment renewal submitted 2/2015 includes additional

information not pertinent to the system. Marked up copy of

notification provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Citation: 22 CCR 12 66262.23(a)(4) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.23(a)(4)

Chapter 12, Section(s) 00202.23(a)(4)

Violation Description: Failure to send hazardous waste manifest copies to DTSC.

Violation Notes: Both the TSDF and Generator copy of Manifest #013367497JJK (Ship Date:

9/29/2014) were reviewed at the facility, but a copy of the manifest

was not submitted to DTSC.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act. Waste analysis plan was not available on day of inspection. This was a

repeat violation from the prior inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Violation Notes:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Last HMBP information submitted accounts only for materials stored in

the waste treatment area. A complete HMBP must account for all materials stored onsite at or above reporting thresholds (including $\,$

all plating and rinse baths).

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Violation Description: Tiered Permitting Program - Operations/Maintenance - General Violation Notes: Chromate system utilizes addition of metabisulfite to reduce Cr6+ to

Cr3+. Addition of chemicals is done manually, where regulations

require automated addition.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the documents would be available under the California Public Records Act. Closure plan is incomplete in that it does not address the following:

- When each FTU will be closed and the maximum extent of operation

during the life of the FTUs. - Closure Plan states that all FTU

containment system will be washed, decontaminated, and inspected, but a description of the steps that will be required to remove hazardous waste and decontaminate the equipment, containers, tank systems, and contaminated soils is not provided. - Closure Plan states that it will continue to decontaminate the treatment system until the samples taken of wash down solutions and the unit are rendered non-hazardous, but the how the facility will demonstrate that the solutions and unit are non-hazardous in accordance with CCR 66261.3(d)-(e) is not addressed. - An expected year of closure is not included in the Closure Plan. - A

broad schedule for final closure activities is provided, but a schedule for final closure of each FTU, including the total time

requirement to close [Truncated]

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Violation Notes:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all

required content.

Violation Notes: Site map submitted 7/1/15 is incomplete. CERS response on 8/2/15 asked

for map to be revised prior to next inspection. Map does not indicate storage areas 8, 2, 3, or 5 or the oxidizer shed. It also is missing

Distance Elevation Site

Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

the locations of local water and gas shut-offs, locations of emergency

equipment or the location of University Avenue.

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.197 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.197

Violation Description: Failure to properly close a hazardous waste tank system ensuring the

minimization of further maintenance and that the following requirements are met: a) The owner or operator shall remove or decontaminate all waste residues, contaminated containment system components (liners, etc.), contaminated soils, and structures and

equipment contaminated with waste, and manage them as hazardous waste.

The closure plan, closure activities, cost estimates for closure, and financial responsibility for tank systems shall meet all of the requirements specified in articles 7 and 8 of this chapter. b) If the owner or operator demonstrates that not all contaminated soils can be practicably removed or decontaminated as required in subsection (a) of this section, then the owner or operator shall close the tank system and perform post-closure care in accordance with the closure and post-closure care requirements that apply to landfills (section 66265.310). In addition, for the purposes of closure, post-closure, and financial responsibility, such a tank system is then considered to be a landfill, and the owner or operator shall meet all of the requirements for landfills specified in articles 7 and 8 of this

chapter. c) If an owner or operator has a tank system which does not have secondary containment that meets the requirements of section 66265.193(b) through (f) and which has not been granted a variance from the secondary containment requirements in accordance with section 66265.193(g), then: 1) The closure plan for the tank system shall include both a plan for complying with subsection (a) of this section

and a contingent plan for complying with subsection b) of this section; 2) A contingent post-closure plan for complying with subsection (b) of this section shall be prepared and submitted as part of the permit application; 3) The cost estimates calculated for closure and post-closure care shall reflect the costs of complying with the contingent closure plan and the contingent post-closure plan,

if these costs are greater than the

Violation Notes: Three tanks used for the treatment of hazardous waste were replaced in

2015 but documentation of proper closure and disposal of the tanks was not available. Corrective Action: Please explain how these tanks were closed and were disposed of. Tanks must either be managed as hazardous

wastes or must be certified as clean according to Title 22, CCR,

section 67383.3 standards.

Violation Division: Santa Clara County Environmental Health

79175

Violation Program: PBR
Violation Source: CERS

Site ID:

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.16

Distance
Elevation Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

EPA ID Number

Violation Description:

Failure to provide employees within the first six months after the date of their employment, or assignment to the facility, or to work unsupervised, or to a new position at a facility with hazardous waste training to ensure employees are competent in the following areas: hazardous waste management procedures (including contingency plan implementation) relevant to the positions in which they are employed, emergency response and emergency equipment, and procedures for using, inspecting, repairing, and replacing facility emergency and monitoring equipment. In addition, the owner/operator shall ensure facility personnel take part in an annual review of the initial training and training records training records on current personnel shall be kept until closure of the facility. Training records on former employees shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel

assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given

to each person filling a position.

Violation Notes: Training record indicates that hazardous waste training will be

provided by an outside vendor every 3 years. last noted exterior provider training was by Du-All Safety in 2009.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.40(a)

Violation Description: Failure to maintain uniform hazardous waste manifest, consolidated

manifest, or bills of lading copies for three years.

Violation Notes: The TSDF copy of Manifest #012207871JJK (Ship Date: 11/27/2013) was

not retained onsite. If facility did not receive a TSDF copy, an exception report is required to be submitted to DTSC within 45 days of

the waste shipment [CCR 66262.42].

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Chromate treatment System is a batch treatment system consisting of

one 350 gallon batch treatment tank, two sludge holding tanks, and one filter press.(WT2, WT4A, WT4B, Filter Press) Receive wastes from the clear zinc processes, alodining processes and associated rinses and floor drain system along alodine/anodize line. All wastes are manually pumped to the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to

Direction Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

the press for de watering. Water removed by the press is routed back into tank WT9 (Neutralization tank) Tank WT2 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10354795 Last submittal 7/1/15. Administratively accepted by

HMCD 8/2/15.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Zinc treatment System is a batch treatment system consisting of one

350 gallon batch treatment tank and sludge holding tank.(WT7, WT6A) Filter Press is shared with chromate treatment system and is notified for as part of that system. Receive wastes from the zinc rinses and floor drain system along zinc line. All wastes are manually pumped to the batch treatment tank and treated according to energing.

the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to

the press for de watering. Tank WT7 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is job plating shop that does zinc plating, alodine/dying and

anodizing. Rinses are managed as counter-current with primary rinse used as much as needed to make up water for plating solutions. Most rinses are static. Do have some spray rinsing stations, with spray rinse taking place in the aisles between bath/rinse tanks. Floors are "dry floors" with liner system above floors which routes all dragout and rinse to a collection point from which it is transferred to a waste treatment area. -Facility has received training on and states that is practices MFA Nor Cal floor management practices. -have inspection logs noting the daily inspection of plating area floors. Sludge from treatment process is drained to hopper which is labeled as HW, and then transferred to 55 gallon drums for disposal. --PPE used on the plating line as well as blast media are also added to these drums. Onsite lab waste is added to waste treatment system. Have blast

cabinet used to [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HWLQG
Eval Source: CERS

Distance Elevation

vation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Affiliation:

Affiliation Type Desc: **Document Preparer** Entity Name: Sharon Hane Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: Sharon Hane Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: UNIVERSITY PLATING CO.

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (408) 292-2140

Affiliation Type Desc: Property Owner
Entity Name: Sharon Hane
Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 292-2140

Affiliation Type Desc: Legal Owner

Entity Name: UNIVERSITY PLATING

Entity Title: Not reported

Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE Affiliation State: CA

Direction Distance Elevation

vation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Affiliation Country: United States
Affiliation Zip: 95110
Affiliation Phone: (408) 292-2140

Affiliation Type Desc: CUPA District

Entity Name: Santa Clara County Environmental Health

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

San Jose
CA
Not reported
95112-2716
(408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: carter hane Entity Title: president Affiliation Address: Not reported Affiliation City: Not reported Not reported Affiliation State: Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact

Entity Name: Edgar parra Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 836-5158

Affiliation Type Desc: Parent Corporation
Entity Name: UNIVERSITY PLATING

Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

CUPA SANTA CLARA:

Region: SANTA CLARA
PE#: Not reported

Program Description: HMBP FACILITY, 10-15 CHEMICALS

 Latitude:
 37.343856

 Longitude:
 -121.915824

 Record ID:
 PR0396605

 Facility ID:
 FA0210518

Region: SANTA CLARA

PE#: 2261

Program Description: PERMIT BY RULE (PBR)

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

UNIVERSITY PLATING CO (Continued)

1000431658

Latitude: 37.343856 Longitude: -121.915824 Record ID: PR0364987 Facility ID: FA0210518

Region: SANTA CLARA

PE#: 2261

Program Description: PERMIT BY RULE (PBR)

Latitude: 37.343856 Longitude: -121.915824 Record ID: PR0402342 FA0210518 Facility ID:

Region: SANTA CLARA PE#: Not reported

Program Description: GENERATES 5 TO <25 TONS/YR (RCRA LQG)

Not reported

Latitude: 37.343856 -121.915824 Longitude: Record ID: PR0313137 FA0210518 Facility ID:

NPDES:

Facility Status:

NPDES Number: Not reported Not reported Region: Agency Number: Not reported Regulatory Measure ID: Not reported Place ID: Not reported Order Number: Not reported 2 43NEC004517 WDID: Regulatory Measure Type: Industrial Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Not reported Discharge Address: Discharge Name: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Status: Active Status Date: 09/20/2018

Operator Name: University Plating Co Operator Address: 650 University Ave

Operator City: San Jose Operator State: California 95110 Operator Zip:

Facility Status: Active NPDES Number: CAS000001

Region: Agency Number: 0 Regulatory Measure ID: 501775 Place ID: Not reported Order Number: 97-03-DWQ 2 43NEC004517 WDID:

Direction Distance Elevation

Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Regulatory Measure Type: Enrollee Program Type: Industrial Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: 09/20/2018 Termination Date Of Regulatory Measure: Not reported **Expiration Date Of Regulatory Measure:** Not reported Discharge Address: 650 University Ave Discharge Name: University Plating Co

Discharge City: San Jose Discharge State: California Discharge Zip: 95110 Not reported Status: Status Date: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Not reported Operator State: Operator Zip: Not reported

Not reported Facility Status: NPDES Number: Not reported Region: Not reported Agency Number: Not reported Regulatory Measure ID: Not reported Place ID: Not reported Order Number: Not reported WDID: 2 431023029 Regulatory Measure Type: Industrial Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Discharge Address: Not reported Discharge Name: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Status: Active Status Date: 02/23/2011

Operator Name: University Plating Co Operator Address: 650 University Ave

Operator City: San Jose
Operator State: California
Operator Zip: 95110

NPDES as of 03/2018:

NPDES Number: Not reported Status: Not reported Agency Number: Not reported

Region: 2 Regulatory Measure ID: 412287 Order Number: Not reported Regulatory Measure Type: Industrial Place ID: Not reported WDID: 2 431023029 Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Effective Date Of Regulatory Measure: Not reported Not reported Expiration Date Of Regulatory Measure: Termination Date Of Regulatory Measure: Not reported Not reported Discharge Name: Discharge Address: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Received Date: 02/23/2011 Processed Date: 02/23/2011 Active Status: Status Date: 02/23/2011 Place Size: 6500 Place Size Unit: SqFt Contact: Carter Hane Contact Title: President 408-292-2140 Contact Phone: Contact Phone Ext: Not reported

Contact Email: carterhane@hotmail.com
Operator Name: University Plating Co
Operator Address: 650 University Ave

Operator City:
Operator State:
California
Operator Zip:
Operator Contact:
Operator Contact:
Operator Contact Title:
Operator Contact Phone:
Operator Contact Phone Ext:
Not reported

Operator Contact Email: carterhane@hotmail.com

Operator Type: **Private Business** Developer: Not reported Developer Address: Not reported Developer City: Not reported Developer State: California Developer Zip: Not reported **Developer Contact:** Not reported **Developer Contact Title:** Not reported Constype Linear Utility Ind: Not reported **Emergency Phone:** Not reported Emergency Phone Ext: Not reported Constype Above Ground Ind: Not reported Constype Below Ground Ind: Not reported Constype Cable Line Ind: Not reported Constype Comm Line Ind: Not reported Constype Commertial Ind: Not reported Constype Electrical Line Ind: Not reported Constype Gas Line Ind: Not reported Constype Industrial Ind: Not reported Constype Other Description: Not reported Constype Other Ind: Not reported Constype Recons Ind: Not reported Constype Residential Ind: Not reported Not reported Constype Transport Ind: Constype Utility Description: Not reported Constype Utility Ind: Not reported Constype Water Sewer Ind: Not reported

Dir Discharge Uswater Ind: N

MAP FINDINGS Map ID Direction

Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

UNIVERSITY PLATING CO (Continued)

1000431658

Receiving Water Name: San Francisco Bay Certifier: Carter Hane Certifier Title: President Certification Date: 05-MAY-15

Primary Sic: 3471-Electroplating, Plating, Polishing, Anodizing, and Coloring

Secondary Sic: Not reported **Tertiary Sic:** Not reported

NPDES Number: CAS000001 Status: Active Agency Number: 0 Region: 2 Regulatory Measure ID: 412287 Order Number: 97-03-DWQ Regulatory Measure Type: Enrollee Place ID: Not reported WDID: 2 431023029 Program Type: Industrial Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: 02/23/2011 Expiration Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported

Discharge Name: University Plating Co Discharge Address: 650 University Ave

Discharge City: San Jose Discharge State: California Discharge Zip: 95110 Received Date: Not reported Processed Date: Not reported Not reported Status: Not reported Status Date: Place Size: Not reported Place Size Unit: Not reported Contact: Not reported Not reported Contact Title: Not reported Contact Phone: Contact Phone Ext: Not reported Contact Email: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported **Operator Contact:** Not reported Operator Contact Title: Not reported Operator Contact Phone: Not reported Operator Contact Phone Ext: Not reported Operator Contact Email: Not reported Operator Type: Not reported Developer: Not reported Developer Address: Not reported Developer City: Not reported Not reported Developer State: Developer Zip: Not reported **Developer Contact:** Not reported **Developer Contact Title:** Not reported

Not reported

Constype Linear Utility Ind:

Direction
Distance
Elevation

Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Emergency Phone: Not reported Emergency Phone Ext: Not reported Constype Above Ground Ind: Not reported Constype Below Ground Ind: Not reported Constype Cable Line Ind: Not reported Constype Comm Line Ind: Not reported Not reported Constype Commertial Ind: Constype Electrical Line Ind: Not reported Constype Gas Line Ind: Not reported Constype Industrial Ind: Not reported Constype Other Description: Not reported Constype Other Ind: Not reported Constype Recons Ind: Not reported Constype Residential Ind: Not reported Constype Transport Ind: Not reported Constype Utility Description: Not reported Constype Utility Ind: Not reported Constype Water Sewer Ind: Not reported Dir Discharge Uswater Ind: Not reported Receiving Water Name: Not reported Certifier: Not reported Certifier Title: Not reported Certification Date: Not reported Primary Sic: Not reported Secondary Sic: Not reported Tertiary Sic: Not reported

Facility Status: Active NPDES Number: CAS000001

Region: Agency Number: 0 Regulatory Measure ID: 412287 Place ID: Not reported Order Number: 97-03-DWQ WDID: 2 431023029 Regulatory Measure Type: Enrollee Program Type: Industrial Adoption Date Of Regulatory Measure: Not reported 02/23/2011 Effective Date Of Regulatory Measure: Termination Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Discharge Address: 650 University Ave Discharge Name: University Plating Co

Discharge City: San Jose Discharge State: California Discharge Zip: 95110 Status: Not reported Status Date: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported

NPDES as of 03/2018:

NPDES Number: Not reported Status: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Agency Number: Not reported Region: Regulatory Measure ID: 412287 Order Number: Not reported Regulatory Measure Type: Industrial Place ID: Not reported WDID: 2 431023029 Program Type: Not reported Adoption Date Of Regulatory Measure: Not reported Effective Date Of Regulatory Measure: Not reported Expiration Date Of Regulatory Measure: Not reported Termination Date Of Regulatory Measure: Not reported Discharge Name: Not reported Discharge Address: Not reported Discharge City: Not reported Discharge State: Not reported Discharge Zip: Not reported Received Date: 02/23/2011 Processed Date: 02/23/2011 Status: Active Status Date: 02/23/2011 Place Size: 6500 Place Size Unit: SaFt Contact: Carter Hane Contact Title: President Contact Phone: 408-292-2140 Contact Phone Ext: Not reported

Contact Email: carterhane@hotmail.com
Operator Name: University Plating Co
Operator Address: 650 University Ave

Operator City:
Operator State:
Operator Zip:
Operator Contact:
Operator Contact:
Operator Contact Title:
Operator Contact Phone:
Operator Contact Phone Ext:
Operator Cont

Operator Contact Email: carterhane@hotmail.com

Operator Type: **Private Business** Developer: Not reported Developer Address: Not reported Developer City: Not reported Developer State: California Developer Zip: Not reported **Developer Contact:** Not reported **Developer Contact Title:** Not reported Constype Linear Utility Ind: Not reported **Emergency Phone:** Not reported Emergency Phone Ext: Not reported Constype Above Ground Ind: Not reported Constype Below Ground Ind: Not reported Constype Cable Line Ind: Not reported Constype Comm Line Ind: Not reported Constype Commertial Ind: Not reported Constype Electrical Line Ind: Not reported Constype Gas Line Ind: Not reported Constype Industrial Ind: Not reported

Distance
Elevation Site

EDR ID Number
Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Constype Other Description: Not reported Not reported Constype Other Ind: Constype Recons Ind: Not reported Constype Residential Ind: Not reported Constype Transport Ind: Not reported Constype Utility Description: Not reported Not reported Constype Utility Ind: Constype Water Sewer Ind: Not reported Dir Discharge Uswater Ind:

Receiving Water Name:

Certifier:

Certifier Title:

Certification Date:

San Francisco Bay
Carter Hane
President
05-MAY-15

Primary Sic: 3471-Electroplating, Plating, Polishing, Anodizing, and Coloring

Secondary Sic: Not reported Tertiary Sic: Not reported

NPDES Number: CAS000001 Status: Active Agency Number: 0 Region: 2 Regulatory Measure ID: 412287 97-03-DWQ Order Number: Regulatory Measure Type: Enrollee Place ID: Not reported WDID: 2 431023029 Program Type: Industrial Adoption Date Of Regulatory Measure: Not reported

Effective Date Of Regulatory Measure: 02/23/2011

Expiration Date Of Regulatory Measure: Not reported

Termination Date Of Regulatory Measure: Not reported

Discharge Name: University Plating Co

Discharge Address:

University Plating Co

Discharge City: San Jose Discharge State: California Discharge Zip: 95110 Received Date: Not reported Processed Date: Not reported Status: Not reported Status Date: Not reported Place Size: Not reported Not reported Place Size Unit: Contact: Not reported Not reported Contact Title: Contact Phone: Not reported Contact Phone Ext: Not reported Contact Email: Not reported Operator Name: Not reported Operator Address: Not reported Operator City: Not reported Operator State: Not reported Operator Zip: Not reported Not reported **Operator Contact:** Operator Contact Title: Not reported **Operator Contact Phone:** Not reported Not reported Operator Contact Phone Ext: Operator Contact Email: Not reported

Direction Distance Elevation

levation Site Database(s) EPA ID Number

Not reported

UNIVERSITY PLATING CO (Continued)

Operator Type:

1000431658

EDR ID Number

Developer: Not reported Developer Address: Not reported Developer City: Not reported Developer State: Not reported Developer Zip: Not reported Developer Contact: Not reported **Developer Contact Title:** Not reported Constype Linear Utility Ind: Not reported **Emergency Phone:** Not reported Emergency Phone Ext: Not reported Constype Above Ground Ind: Not reported Constype Below Ground Ind: Not reported Constype Cable Line Ind: Not reported Constype Comm Line Ind: Not reported Constype Commertial Ind: Not reported Constype Electrical Line Ind: Not reported Constype Gas Line Ind: Not reported Constype Industrial Ind: Not reported Constype Other Description: Not reported Constype Other Ind: Not reported Constype Recons Ind: Not reported Constype Residential Ind: Not reported Constype Transport Ind: Not reported Constype Utility Description: Not reported Constype Utility Ind: Not reported Constype Water Sewer Ind: Not reported Dir Discharge Uswater Ind: Not reported Receiving Water Name: Not reported Certifier: Not reported Certifier Title: Not reported Certification Date: Not reported Primary Sic: Not reported Secondary Sic: Not reported **Tertiary Sic:** Not reported

SAN JOSE HAZMAT:

Region: SAN JOSE File Num: 401563

Class: Metal Plating and Fabrication

CIWQS:

Agency: University Plating Co

Agency Address: 650 University Ave, San Jose, CA 95110

Place/Project Type: Industrial - Electroplating, Plating, Polishing, Anodizing, and

Coloring

SIC/NAICS: 3471
Region: 2
Program: INDSTW
Regulatory Measure Status: Active

Regulatory Measure Type:

Order Number:

WDID:

NPDES Number:

Adoption Date:

Storm water industrial
2014-0057-DWQ
2 43I023029
CAS000001
Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

UNIVERSITY PLATING CO (Continued)

1000431658

Effective Date: 02/23/2011 Termination Date: Not reported Expiration/Review Date: Not reported Design Flow: Not reported Major/Minor: Not reported Complexity: Not reported TTWQ: Not reported

Enforcement Actions within 5 years: Violations within 5 years: Latitude: 37.34397 Longitude: -121.91594

University Plating Co Agency:

Agency Address: 650 University Ave, San Jose, CA 95110

Place/Project Type: Industrial - Electroplating, Plating, Polishing, Anodizing, and

Coloring

SIC/NAICS: 3471 Region: 2 **INDSTW** Program: Regulatory Measure Status: Active

Regulatory Measure Type: Storm water industrial Order Number: 2014-0057-DWQ WDID: 2 43NEC004517 NPDES Number: CAS000001 Adoption Date: Not reported Effective Date: 09/20/2018 Termination Date: Not reported Expiration/Review Date: Not reported Design Flow: Not reported Major/Minor: Not reported Complexity: Not reported TTWQ: Not reported

Enforcement Actions within 5 years: Violations within 5 years: Latitude: 37.34372 -121.91553 Longitude:

CERS TANKS:

79175 Site ID: 10354795 CERS ID:

CERS Description: Chemical Storage Facilities

Violations:

Site ID: 79175

UNIVERSITY PLATING Site Name:

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.173

Violation Description: Failure to properly close hazardous waste containers when not in

active use.

Violation Notes: Bucket of waste in lab is open.

Violation Division: Santa Clara County Environmental Health

HWLQG Violation Program: Violation Source: **CERS**

Site ID: 79175

Site Name: UNIVERSITY PLATING

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.52 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.52

Violation Description: Failure to include all of the following in the Contingency Plan: 1) A

description of actions the facility personnel shall take response to fires, explosions, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water at the facility; 2) A description of arrangements agreed to by local police departments, fire departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services; 3) All names, addresses, and phone numbers (office and home) of all persons qualified to act as emergency coordinator and this list shall be kept up to date. Where more than

coordinator and this list shall be kept up to date. Where more than one person is listed, one shall be named as primary emergency coordinator and others shall be listed in the order in which they will assume responsibility as alternates; 4) A list of all emergency equipment at the facility (such as fire extinguishing systems, spill control equipment, communications and alarm systems (internal and external), and decontamination equipment), where this equipment is required. This list shall be kept up to date. In addition, the plan shall include the location and a physical description of each item on

the list, and a brief outline of its capabilities; 5) An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary. This plan is to describe signal(s) to be used to begin evacuation, evacuation routes, and alternate

evacuation routes (in cases where the primary routes could be blocked by releases of hazardous waste or fires); 6) The current telephone number of the California Emergency Management Agency; and 7) If the owner or operator has already prepared a Spill Prevention, Control, and Countermeasures (SPCC) or some other emergency or contingency plan, the owner or operator need only amend that plan to incorporate hazardous waste management provisions that are sufficient to comply

with the requirements of this chapter.

Violation Notes: Facility could not produce a complete contingency plan. Portions of

the plan were available but a complete plan was not available. Unidocs version of the Contingency plan from 2012 was onsite, but was incomplete in that it did not have updated phone numbers for the CUPA

or the names or emergency contacts.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting Program - Administration/Documentation - General

Violation Notes: Tank assessment provided did not include all elements required by

Title 22, section 66265.192(h).

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Citation: 22 CCR 15 66265.194 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.194

Violation Description: Failure to maintain the following general tank operating requirements:

a) Hazardous wastes or treatment reagents shall not be placed in a tank system if they could cause the tank, its ancillary equipment, or the secondary containment system to rupture, leak, corrode, or otherwise fail. b) The owner or operator shall use appropriate controls and practices to prevent spills and overflows from tank or secondary containment systems. These include at a minimum: 1) Spill prevention controls (e.g., check valves, dry discount couplings); 2) Overfill prevention controls (e.g., level sensing devices, high level alarms, automatic feed cutoff, or bypass to a standby tank); and 3) Maintenance of sufficient freeboard in uncovered tanks to prevent overtopping by wave or wind action or by precipitation. Uncovered tanks shall be operated to ensure at least 60 centimeters (2 feet) of freeboard, unless the tank is equipped with a containment structure (e.g., dike or trench), a drainage control system or a diversion structure (e.g., standby tank) with a capacity that equals or exceeds the volume of the top 60 centimeters (2 feet) of the tank.

Violation Notes: Tanks are indicated as being 350 gallons in size and are operated with

an open top. Logs of treatment quantities indicate batches of 350 gallons routinely treated. Tanks area not equipped with overfill prevention and do not appear to have at least two feet of freeboard

maintained while waste is in the tanks.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.13(a)(1) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.13(a)(1)

Violation Description: Failure to prepare a written estimate of the cost of closing each unit

which includes the cost that would be incurred for closing a treatment unit when using the owner or operator or generator's own staff and/or personal equipment taking into account any salvage value that may be realized from the sale of wastes, facility structure or equipment, land or other facility assets. This estimate shall be submitted as an attachment to the Certification of Financial Assurance for Permit by Rule and Conditionally Authorized Operations/ Maintenance page(s) of

the Unified Program Consolidated Form (x/99)).

Violation Notes: Closure cost estimate for 2015 was incomplete in that it does not

reflect the following: - The cost of a PE certification that the closure is completed in accordance with the facility s Closure Plan and the requirements of Chapter 45, Title 22, CCR [67450.3(c)(11)(G)]. - The cost of sampling at the time of closure. - A PBR Closure permit required by HMCD (\$2598.00). - The final hazardous waste pick-up to occur. - Costs associated with the decontamination of the filter press. - Additionally, the Closure Cost Estimate accounts for the decontamination of 5x55 gallon containers, but 7x55 gallon and 1 x 100 $\,$

gallon containers (zinc strip) are used for onsite treatment.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: RCRA Large Quantity Generator Program - Administration/Documentation -

General

Violation Notes: Facility generated over 12,000kg of hazardous waste in a reporting

year and failed to conduct a source reduction evaluation review and plan pursuant to CCR 67100.5. Facility stated that they do not meet the requirements to create a Waste Minimization Plan, because the facility shipped less than 12,000 kg of waste in 2006, 2010 and 2014. Facility s waste generation calculation is only based on the amount of waste shipped offsite and not based on the amount of waste generated prior to treatment. Treatment logs indicated that >12,000kg of waste were treated in 2014. Complete a source reduction evaluation review and plan pursuant the plan format requirements of CCR 67100.5, including but not limited to 1) the name and location of the site, phone number, and identification number, 2) SIC codes, 3) type of business or activity conducted, 4) length of time the company has been in business, 5) products manufactured and services provided, 6) number

of employees, 7) description [Truncated]
Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Violation Division:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.2(c)(10) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.2(c)(10)

Violation Description: Failure of the generator to prepare, maintain, and submit to CUPA an

annual report containing the following information: (A) The serial number(s) of the FTU(s) involved in treatment; (B) The physical and mailing address of the business entity which owns or operates the FTU(s); (C) The name, title and telephone number of each FTU contact person; (D) The name and address or legal description of the facility; (E) The facility identification number; (F) The number of days each FTU was operated; (G) The quantity of hazardous waste(s) treated by each FTU; (H) The composition and hazardous characteristics of the influent hazardous waste(s); (I) The treatment method(s) used for each hazardous waste treated by each FTU; (J) The quantity, composition and

hazardous characteristic(s) of any treatment effluent or residual discharged from each FTU to a POTW, if applicable; and (K) The quantity, composition, hazardous characteristic(s) and disposition of any FTU treatment effluent or residual that was not discharged to a

POTW, if applicable.

Violation Notes: Annual treatment renewal submitted 2/2015 includes additional

information not pertinent to the system. Marked up copy of

notification provided.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.23(a)(4) - California Code of Regulations, Title 22,

Distance
Elevation Site Database(s)

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

EPA ID Number

Chapter 12, Section(s) 66262.23(a)(4)

Violation Description: Failure to send hazardous waste manifest copies to DTSC.

Violation Notes: Both the TSDF and Generator copy of Manifest #013367497JJK (Ship Date:

9/29/2014) were reviewed at the facility, but a copy of the manifest

was not submitted to DTSC.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders

resulting from any action by any local, State, or federal

environmental or public health enforcement agency concerning the

operation of the facility within the last three years, as the

documents would be available under the California Public Records Act. Waste analysis plan was not available on day of inspection. This was a

repeat violation from the prior inspection.

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Violation Notes:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material

inventory information for all reportable hazardous materials on site

at or above reportable quantities.

Violation Notes: Last HMBP information submitted accounts only for materials stored in

the waste treatment area. A complete HMBP must account for all materials stored onsite at or above reporting thresholds (including

all plating and rinse baths).

Violation Division: Santa Clara County Environmental Health

Violation Program: HMRRP
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

Section(s) Multiple

Violation Description: Tiered Permitting Program - Operations/Maintenance - General

Distance Elevation Sit

on Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

Violation Division:

Violation Notes:

1000431658

EDR ID Number

Violation Notes: Chromate system utilizes addition of metabisulfite to reduce Cr6+ to

Cr3+. Addition of chemicals is done manually, where regulations

require automated addition.

Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 45 67450.3(c)(8) - California Code of Regulations, Title 22,

Chapter 45, Section(s) 67450.3(c)(8)

Violation Description: Failure to maintain, reproduce, and provide the following documents at

the facility where the FTU is operating: 1) The waste analysis plan for the treatment operation; 2) The written inspection schedule; 3) All training documents; 4) The contingency plan; 5) A copy of the most

recent treatment notification and a copy of the most recent

acknowledgement received from the Department, CUPA or authorized agency; 6) A copy of any local Air District permit and other permits required for the operation of the FTU; 7) A copy of the closure plan; 8) A copy of documents related to the environmental investigation and any cleanup, abatement or other necessary remedial action taken; and 9) Documentation of any convictions, judgments, settlements, or orders resulting from any action by any local. State, or federal

resulting from any action by any local, State, or federal environmental or public health enforcement agency concerning the operation of the facility within the last three years, as the

documents would be available under the California Public Records Act.

Closure plan is incomplete in that it does not address the following:

- When each FTU will be closed and the maximum extent of operation

during the life of the FTUs. - Closure Plan states that all FTU

containment system will be washed, decontaminated, and inspected, but a description of the steps that will be required to remove hazardous waste and decontaminate the equipment, containers, tank systems, and contaminated soils is not provided. - Closure Plan states that it will continue to decontaminate the treatment system until the samples taken of wash down solutions and the unit are rendered non-hazardous, but the how the facility will demonstrate that the solutions and unit are non-hazardous in accordance with CCR 66261.3(d)-(e) is not addressed.

An expected year of closure is not included in the Closure Plan.
 A broad schedule for final closure activities is provided, but a schedule for final closure of each FTU, including the total time

requirement to close [Truncated]

Violation Division: Santa Clara County Environmental Health

Violation Program: PBR
Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter

6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all

required content.

Violation Notes: Site map submitted 7/1/15 is incomplete. CERS response on 8/2/15 asked

for map to be revised prior to next inspection. Map does not indicate storage areas 8, 2, 3, or 5 or the oxidizer shed. It also is missing the locations of local water and gas shut-offs, locations of emergency

Distance EDR ID Number
Elevation Site EPA ID Number

UNIVERSITY PLATING CO (Continued)

Violation Division:

1000431658

equipment or the location of University Avenue. Santa Clara County Environmental Health

Violation Program: HMRRP Violation Source: CERS

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.197 - California Code of Regulations, Title 22,

Chapter 15, Section(s) 66265.197

Violation Description: Failure to properly close a hazardous waste tank system ensuring the

minimization of further maintenance and that the following requirements are met: a) The owner or operator shall remove or decontaminate all waste residues, contaminated containment system components (liners, etc.), contaminated soils, and structures and

equipment contaminated with waste, and manage them as hazardous waste.

The closure plan, closure activities, cost estimates for closure, and financial responsibility for tank systems shall meet all of the requirements specified in articles 7 and 8 of this chapter. b) If the owner or operator demonstrates that not all contaminated soils can be practicably removed or decontaminated as required in subsection (a) of this section, then the owner or operator shall close the tank system and perform post-closure care in accordance with the closure and post-closure care requirements that apply to landfills (section 66265.310). In addition, for the purposes of closure, post-closure, and financial responsibility, such a tank system is then considered to be a landfill, and the owner or operator shall meet all of the requirements for landfills specified in articles 7 and 8 of this

chapter. c) If an owner or operator has a tank system which does not have secondary containment that meets the requirements of section 66265.193(b) through (f) and which has not been granted a variance from the secondary containment requirements in accordance with section 66265.193(g), then: 1) The closure plan for the tank system shall include both a plan for complying with subsection (a) of this section

include both a plan for complying with subsection (a) of this section and a contingent plan for complying with subsection b) of this section; 2) A contingent post-closure plan for complying with subsection (b) of this section shall be prepared and submitted as part of the permit application; 3) The cost estimates calculated for closure and post-closure care shall reflect the costs of complying with the contingent closure plan and the contingent post-closure plan,

if these costs are greater than the

Violation Notes: Three tanks used for the treatment of hazardous waste were replaced in

2015 but documentation of proper closure and disposal of the tanks was not available. Corrective Action: Please explain how these tanks were closed and were disposed of. Tanks must either be managed as hazardous

wastes or must be certified as clean according to Title 22, CCR,

section 67383.3 standards.

Violation Division: Santa Clara County Environmental Health

79175

Violation Program: PBR
Violation Source: CERS

Site ID:

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter

15, Section(s) 66265.16

Violation Description: Failure to provide employees within the first six months after the

Distance

Elevation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

date of their employment, or assignment to the facility, or to work unsupervised, or to a new position at a facility with hazardous waste training to ensure employees are competent in the following areas: hazardous waste management procedures (including contingency plan implementation) relevant to the positions in which they are employed, emergency response and emergency equipment, and procedures for using, inspecting, repairing, and replacing facility emergency and monitoring equipment. In addition, the owner/operator shall ensure facility personnel take part in an annual review of the initial training and training records training records on current personnel shall be kept until closure of the facility. Training records on former employees shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given

to each person filling a position.

Training record indicates that hazardous waste training will be

provided by an outside vendor every 3 years. last noted exterior

provider training was by Du-All Safety in 2009.

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Violation Notes:

Site ID: 79175

Site Name: UNIVERSITY PLATING

Violation Date: 11-09-2015

Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22,

Chapter 12, Section(s) 66262.40(a)

Violation Description: Failure to maintain uniform hazardous waste manifest, consolidated

manifest, or bills of lading copies for three years.

Violation Notes: The TSDF copy of Manifest #012207871JJK (Ship Date: 11/27/2013) was

not retained onsite. If facility did not receive a TSDF copy, an

exception report is required to be submitted to DTSC within 45 days of

the waste shipment [CCR 66262.42].

Violation Division: Santa Clara County Environmental Health

Violation Program: HWLQG Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Chromate treatment System is a batch treatment system consisting of

one 350 gallon batch treatment tank, two sludge holding tanks, and one filter press. (WT2, WT4A, WT4B, Filter Press) Receive wastes from the clear zinc processes, alodining processes and associated rinses and floor drain system along alodine/anodize line. All wastes are manually pumped to the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to the press for de watering. Water removed by the press is routed back

Direction Distance Elevation

evation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

into tank WT9 (Neutralization tank) Tank WT2 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: CERS ID 10354795 Last submittal 7/1/15. Administratively accepted by

HMCD 8/2/15.

Eval Division: Santa Clara County Environmental Health

Eval Program: HMRRP Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Zinc treatment System is a batch treatment system consisting of one

350 gallon batch treatment tank and sludge holding tank.(WT7, WT6A) Filter Press is shared with chromate treatment system and is notified for as part of that system. Receive wastes from the zinc rinses and floor drain system along zinc line. All wastes are manually pumped to the batch treatment tank and treated according to operating instructions (similar to a recipe). Agitation is done via air bubbling from bottom of tank. At end of batch, water is drained via valve to pipe which delivers it to the "pH adjust tank" for final polish/pH adjust prior to sewer. At end of batch, sludge is manually pumped to

the press for de watering. Tank WT7 was replaced in 2015.

Eval Division: Santa Clara County Environmental Health

Eval Program: PBR Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

Eval Date: 11-09-2015 Violations Found: Yes

Eval Type: Routine done by local agency

Eval Notes: Facility is job plating shop that does zinc plating, alodine/dying and

anodizing. Rinses are managed as counter-current with primary rinse used as much as needed to make up water for plating solutions. Most rinses are static. Do have some spray rinsing stations, with spray rinse taking place in the aisles between bath/rinse tanks. Floors are "dry floors" with liner system above floors which routes all dragout and rinse to a collection point from which it is transferred to a waste treatment area. -Facility has received training on and states that is practices MFA Nor Cal floor management practices. -have inspection logs noting the daily inspection of plating area floors. Sludge from treatment process is drained to hopper which is labeled as HW, and then transferred to 55 gallon drums for disposal. --PPE used on the plating line as well as blast media are also added to these drums. Onsite lab waste is added to waste treatment system. Have blast

cabinet used to [Truncated]

Eval Division: Santa Clara County Environmental Health

Eval Program: HWLQG Eval Source: CERS

Distance Elevation

vation Site Database(s) EPA ID Number

UNIVERSITY PLATING CO (Continued)

1000431658

EDR ID Number

Affiliation:

Affiliation Type Desc: **Document Preparer** Entity Name: Sharon Hane Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Not reported Affiliation Country: Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE

Affiliation State: CA

Affiliation Country: Not reported
Affiliation Zip: 95110
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer Entity Name: Sharon Hane Entity Title: President Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: Operator

Entity Name: UNIVERSITY PLATING CO.

Entity Title:

Affiliation Address:

Affiliation City:

Affiliation State:

Affiliation Country:

Affiliation City:

Affiliation Country:

Affiliation Zip:

Affiliation Phone:

Not reported

Not reported

(408) 292-2140

Affiliation Type Desc: Property Owner
Entity Name: Sharon Hane
Entity Title: Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose
Affiliation State: CA

Affiliation Country: United States
Affiliation Zip: 95110

Affiliation Phone: (408) 292-2140

Affiliation Type Desc: Legal Owner

Entity Name: UNIVERSITY PLATING

Entity Title: Not reported

Affiliation Address: 650 UNIVERSITY AV

Affiliation City: SAN JOSE Affiliation State: CA

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

UNIVERSITY PLATING CO (Continued)

1000431658

Affiliation Country: **United States** Affiliation Zip: 95110 Affiliation Phone: (408) 292-2140

Affiliation Type Desc: **CUPA District**

Santa Clara County Environmental Health **Entity Name:**

Entity Title: Not reported

Affiliation Address: 1555 Berger Drive, Suite 300

Affiliation City: San Jose Affiliation State: CA Affiliation Country: Not reported 95112-2716 Affiliation Zip: Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Onsite Treatment Unit Owner Operator

Entity Name: carter hane Entity Title: president Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

Affiliation Type Desc: **Environmental Contact**

Entity Name: Edgar parra **Entity Title:** Not reported

Affiliation Address: 650 University Avenue

Affiliation City: San Jose Affiliation State: CA

Affiliation Country: Not reported Affiliation Zip: 95110

Affiliation Phone: (408) 836-5158

Affiliation Type Desc: Parent Corporation Entity Name: UNIVERSITY PLATING

Entity Title: Not reported Affiliation Address: Not reported Affiliation City: Not reported Affiliation State: Not reported Affiliation Country: Not reported Affiliation Zip: Not reported Affiliation Phone: Not reported

HORACE MANN ELEMENTARY SCHOOL SITE 251

55 NORTH SEVENTH STREET ENE

SAN JOSE, CA 95112 1/2-1

0.992 mi. 5236 ft.

Relative: **ENVIROSTOR:**

Higher Facility ID: 43820007

Status: No Action Required Actual:

Status Date: 02/28/2002 84 ft. 204093 Site Code:

> Site Type: School Investigation

Site Type Detailed: School

TC05569778.2r Page 727

S118756962

N/A

ENVIROSTOR

SCH

Direction Distance

Elevation Site Database(s) EPA ID Number

HORACE MANN ELEMENTARY SCHOOL SITE (Continued)

S118756962

EDR ID Number

Acres: 2.8
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Mark Malinowski

Division Branch: Northern California Schools & Santa Susana

Assembly: 27 Senate: 15

Special Program: Not reported

Restricted Use: NO

Site Mgmt Req: NONE SPECIFIED Funding: School District Latitude: 37.3393 Longitude: -121.8851

APN: NONE SPECIFIED

Past Use: * EDUCATIONAL SERVICES

Potential COC: NONE SPECIFIED No Contaminants found

Confirmed COC: NONE SPECIFIED

Potential Description: NMA

Alias Name: HORACE MANN ELEMENTARY SCHOOL SITE

Alias Type: Alternate Name
Alias Name: SAN JOSE USD
Alias Type: Alternate Name

Alias Name: SAN JOSE USD-HORACE MANN ELEM

Alias Type: Alternate Name

Alias Name: 204093

Alias Type: Project Code (Site Code)

Alias Name: 43820007

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Cost Recovery Closeout Memo

Completed Date: 10/28/2002 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Inspections/Visit (Non LUR)

Completed Date: 02/15/2002 Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 02/28/2002

Comments: Phase 1 - Pursuant to an agreement between the Department of Toxic

Substances Control (DTSC) and the California Department of Education, DTSC's Site Mitigation Program completed a review of a Phase 1 Environmental Assessment and has made a "No Action" determination for

this Site.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

HORACE MANN ELEMENTARY SCHOOL SITE (Continued)

S118756962

EDR ID Number

Schedule Area Name:
Schedule Sub Area Name:
Schedule Document Type:
Schedule Due Date:
Schedule Revised Date:
Not reported
Not reported
Not reported
Not reported
Not reported

SCH:

Facility ID: 43820007

Site Type: School Investigation
Site Type Detail: School
Site Mgmt. Req.: NONE SPECIFIED

Acres: 2.8
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP

Lead Agency Description: DTSC - Site Cleanup Program

Project Manager: Not reported Supervisor: Mark Malinowski

Division Branch: Northern California Schools & Santa Susana

 Site Code:
 204093

 Assembly:
 27

 Senate:
 15

Special Program Status: Not reported Status: No Action Required

Status Date: 02/28/2002

Restricted Use: NO

Funding: School District Latitude: 37.3393 Longitude: -121.8851

APN: NONE SPECIFIED

Past Use: * EDUCATIONAL SERVICES

Potential COC: NONE SPECIFIED, No Contaminants found

Confirmed COC: NONE SPECIFIED

Potential Description: NMA

Alias Name: HORACE MANN ELEMENTARY SCHOOL SITE

Alias Type: Alternate Name
Alias Name: SAN JOSE USD
Alias Type: Alternate Name

Alias Name: SAN JOSE USD-HORACE MANN ELEM

Alias Type: Alternate Name

Alias Name: 204093

Alias Type: Project Code (Site Code)

Alias Name: 43820007

Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Cost Recovery Closeout Memo

Completed Date: 10/28/2002 Comments: Not reported

Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported

Completed Document Type: Site Inspections/Visit (Non LUR)

Completed Date: 02/15/2002

Distance Elevation Site

tion Site Database(s) EPA ID Number

HORACE MANN ELEMENTARY SCHOOL SITE (Continued)

S118756962

EDR ID Number

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 02/28/2002

Comments: Phase 1 - Pursuant to an agreement between the Department of Toxic

Substances Control (DTSC) and the California Department of Education, DTSC's Site Mitigation Program completed a review of a Phase 1 Environmental Assessment and has made a "No Action" determination for

this Site.

Future Area Name: Not reported Future Sub Area Name: Not reported Not reported Future Document Type: Not reported Future Due Date: Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported

Count: 2 records. ORPHAN SUMMARY

City	EDR ID Site Name	Site Address	Zip Database(s)
SAN JOSE	S109254214	MONTGOMERY & SAN CARLOS RD (UN	95126 CDL
SAN JOSE	S107996778 SCVTA - RYLAND STREET PROPERTY	RYLAND ST	LUST

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/12/2018 Source: EPA
Date Data Arrived at EDR: 12/28/2018 Telephone: N/A

Date Made Active in Reports: 01/11/2019 Last EDR Contact: 02/15/2019

Number of Days to Update: 14 Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1 EPA Region 6

Telephone 617-918-1143 Telephone: 214-655-6659

EPA Region 3 EPA Region 7

Telephone 215-814-5418 Telephone: 913-551-7247

EPA Region 4 EPA Region 8

Telephone 404-562-8033 Telephone: 303-312-6774

EPA Region 5 EPA Region 9

Telephone 312-886-6686 Telephone: 415-947-4246

EPA Region 10

Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/12/2018 Source: EPA
Date Data Arrived at EDR: 12/28/2018 Telephone: N/A

Date Made Active in Reports: 01/11/2019 Last EDR Contact: 02/15/2019

Number of Days to Update: 14 Next Scheduled EDR Contact:

Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Source: EPA

Telephone: 202-564-4267 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/12/2018 Date Data Arrived at EDR: 12/28/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 14

Source: EPA Telephone: N/A

Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016 Date Data Arrived at EDR: 01/05/2017 Date Made Active in Reports: 04/07/2017

Number of Days to Update: 92

Source: Environmental Protection Agency Telephone: 703-603-8704

Last EDR Contact: 01/04/2019

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 12/12/2018 Date Data Arrived at EDR: 12/28/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 14

Source: EPA Telephone: 800-424-9346 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 12/13/2018 Date Data Arrived at EDR: 12/28/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 14

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/01/2018 Date Data Arrived at EDR: 03/28/2018 Date Made Active in Reports: 06/22/2018

Number of Days to Update: 86

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/01/2018 Date Data Arrived at EDR: 03/28/2018 Date Made Active in Reports: 06/22/2018

Number of Days to Update: 86

Source: Environmental Protection Agency

Telephone: (415) 495-8895 Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018 Date Data Arrived at EDR: 03/28/2018 Date Made Active in Reports: 06/22/2018

Number of Days to Update: 86

Source: Environmental Protection Agency

Telephone: (415) 495-8895 Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/01/2018 Date Data Arrived at EDR: 03/28/2018 Date Made Active in Reports: 06/22/2018

Number of Days to Update: 86

Source: Environmental Protection Agency

Telephone: (415) 495-8895 Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 04/08/2019
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018 Date Data Arrived at EDR: 03/28/2018 Date Made Active in Reports: 06/22/2018

Number of Days to Update: 86

Source: Environmental Protection Agency

Telephone: (415) 495-8895 Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 10/17/2018 Date Data Arrived at EDR: 10/25/2018 Date Made Active in Reports: 12/07/2018

Number of Days to Update: 43

Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 02/07/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 07/31/2018 Date Data Arrived at EDR: 08/28/2018 Date Made Active in Reports: 09/14/2018

Number of Days to Update: 17

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 02/04/2019

Next Scheduled EDR Contact: 03/11/2019 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 07/31/2018 Date Data Arrived at EDR: 08/28/2018 Date Made Active in Reports: 09/14/2018

Number of Days to Update: 17

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 02/04/2019

Next Scheduled EDR Contact: 03/11/2019

Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/24/2018 Date Data Arrived at EDR: 09/25/2018

Date Made Active in Reports: 11/09/2018 Number of Days to Update: 45 Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180 Last EDR Contact: 02/08/2019

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity.

These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 10/29/2018 Date Data Arrived at EDR: 10/30/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 44

Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 01/29/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 10/29/2018 Date Data Arrived at EDR: 10/30/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 44

Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 01/29/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inventory of solid waste disposal facilities or landfills. These may be active or inactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/13/2018

Number of Days to Update: 29

Source: Department of Resources Recycling and Recovery

Telephone: 916-341-6320 Last EDR Contact: 02/12/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 9: Leaking Underground Storage Tank Report

Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources

Control Board's LUST database.

Date of Government Version: 03/01/2001 Date Data Arrived at EDR: 04/23/2001 Date Made Active in Reports: 05/21/2001

Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)

Telephone: 858-637-5595 Last EDR Contact: 09/26/2011

Next Scheduled EDR Contact: 01/09/2012 Data Release Frequency: No Update Planned

LUST REG 7: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004 Date Data Arrived at EDR: 02/26/2004 Date Made Active in Reports: 03/24/2004

Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)

Telephone: 760-776-8943 Last EDR Contact: 08/01/2011

Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005 Date Data Arrived at EDR: 06/07/2005 Date Made Active in Reports: 06/29/2005

Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)

Telephone: 760-241-7365 Last EDR Contact: 09/12/2011

Next Scheduled EDR Contact: 12/26/2011 Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008 Date Data Arrived at EDR: 07/22/2008 Date Made Active in Reports: 07/31/2008

Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)

Telephone: 916-464-4834 Last EDR Contact: 07/01/2011

Next Scheduled EDR Contact: 10/17/2011 Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)

Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/10/2018
Date Data Arrived at EDR: 12/11/2018
Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: see region list Last EDR Contact: 12/11/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

LUST REG 1: Active Toxic Site Investigation

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001 Date Data Arrived at EDR: 02/28/2001 Date Made Active in Reports: 03/29/2001

Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)

Telephone: 707-570-3769 Last EDR Contact: 08/01/2011

Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa

Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004 Date Data Arrived at EDR: 10/20/2004 Date Made Active in Reports: 11/19/2004

Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)

Telephone: 510-622-2433 Last EDR Contact: 09/19/2011

Next Scheduled EDR Contact: 01/02/2012 Data Release Frequency: Quarterly

LUST REG 3: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003 Date Made Active in Reports: 06/02/2003

Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)

Telephone: 805-542-4786 Last EDR Contact: 07/18/2011

Next Scheduled EDR Contact: 10/31/2011 Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control

Board's LUST database.

Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004

Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)

Telephone: 213-576-6710 Last EDR Contact: 09/06/2011

Next Scheduled EDR Contact: 12/19/2011 Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks

California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer

to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005 Date Data Arrived at EDR: 02/15/2005 Date Made Active in Reports: 03/28/2005

Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)

Telephone: 909-782-4496 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: Varies

LUST REG 6L: Leaking Underground Storage Tank Case Listing

For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003 Date Data Arrived at EDR: 09/10/2003 Date Made Active in Reports: 10/07/2003

Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)

Telephone: 530-542-5572 Last EDR Contact: 09/12/2011

Next Scheduled EDR Contact: 12/26/2011 Data Release Frequency: No Update Planned

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/12/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/10/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: Environmental Protection Agency

Telephone: 415-972-3372 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/25/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/24/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/08/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/01/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/12/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA, Region 5 Telephone: 312-886-7439 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019

Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)

Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003 Date Data Arrived at EDR: 04/07/2003 Date Made Active in Reports: 04/25/2003

Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)

Telephone: 707-576-2220 Last EDR Contact: 08/01/2011

Next Scheduled EDR Contact: 11/14/2011 Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004 Date Data Arrived at EDR: 10/20/2004 Date Made Active in Reports: 11/19/2004

Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)

Telephone: 510-286-0457 Last EDR Contact: 09/19/2011

Next Scheduled EDR Contact: 01/02/2012 Data Release Frequency: Quarterly

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006 Date Data Arrived at EDR: 05/18/2006 Date Made Active in Reports: 06/15/2006

Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)

Telephone: 805-549-3147 Last EDR Contact: 07/18/2011

Next Scheduled EDR Contact: 10/31/2011 Data Release Frequency: Semi-Annually

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004 Date Data Arrived at EDR: 11/18/2004 Date Made Active in Reports: 01/04/2005

Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)

Telephone: 213-576-6600 Last EDR Contact: 07/01/2011

Next Scheduled EDR Contact: 10/17/2011 Data Release Frequency: Varies

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005 Date Data Arrived at EDR: 04/05/2005 Date Made Active in Reports: 04/21/2005

Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)

Telephone: 916-464-3291 Last EDR Contact: 09/12/2011

Next Scheduled EDR Contact: 12/26/2011 Data Release Frequency: Semi-Annually

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005 Date Data Arrived at EDR: 05/25/2005 Date Made Active in Reports: 06/16/2005

Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch

Telephone: 619-241-6583 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: Semi-Annually

SLIC REG 6L: SLIC Sites

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004

Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region

Telephone: 530-542-5574 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004 Date Data Arrived at EDR: 11/29/2004 Date Made Active in Reports: 01/04/2005

Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region

Telephone: 760-346-7491 Last EDR Contact: 08/01/2011

Next Scheduled EDR Contact: 11/14/2011 Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008 Date Data Arrived at EDR: 04/03/2008 Date Made Active in Reports: 04/14/2008

Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)

Telephone: 951-782-3298 Last EDR Contact: 09/12/2011

Next Scheduled EDR Contact: 12/26/2011 Data Release Frequency: Semi-Annually

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality

from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007 Date Data Arrived at EDR: 09/11/2007 Date Made Active in Reports: 09/28/2007

Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)

Telephone: 858-467-2980 Last EDR Contact: 08/08/2011

Next Scheduled EDR Contact: 11/21/2011 Data Release Frequency: Annually

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017 Date Data Arrived at EDR: 05/30/2017 Date Made Active in Reports: 10/13/2017

Number of Days to Update: 136

Source: FEMA

Telephone: 202-646-5797 Last EDR Contact: 01/08/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Varies

MILITARY UST SITES: Military UST Sites (GEOTRACKER)

Military ust sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases

UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/12/2018 Date Made Active in Reports: 01/16/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 916-327-7844 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

UST: Active UST Facilities

Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: SWRCB Telephone: 916-341-5851 Last EDR Contact: 12/11/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Semi-Annually

AST: Aboveground Petroleum Storage Tank Facilities

A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016 Date Data Arrived at EDR: 07/12/2016 Date Made Active in Reports: 09/19/2016

Number of Days to Update: 69

Source: California Environmental Protection Agency

Telephone: 916-327-5092 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/25/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/13/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/10/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/24/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/12/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/12/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/08/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/01/2018 Date Data Arrived at EDR: 05/18/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 63

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 10/29/2018 Date Data Arrived at EDR: 10/30/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 44

Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 01/29/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015 Date Data Arrived at EDR: 09/29/2015 Date Made Active in Reports: 02/18/2016

Number of Days to Update: 142

Source: EPA, Region 1 Telephone: 617-918-1102 Last EDR Contact: 12/19/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 7 Telephone: 913-551-7365 Last EDR Contact: 04/20/2009

Next Scheduled EDR Contact: 07/20/2009

Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Considered Brownfieds Sites Listing

A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 09/24/2018 Date Data Arrived at EDR: 09/25/2018 Date Made Active in Reports: 10/15/2018

Number of Days to Update: 20

Source: State Water Resources Control Board

Telephone: 916-323-7905 Last EDR Contact: 12/21/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/17/2018 Date Data Arrived at EDR: 12/18/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 24

Source: Environmental Protection Agency

Telephone: 202-566-2777 Last EDR Contact: 12/18/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000 Date Data Arrived at EDR: 04/10/2000 Date Made Active in Reports: 05/10/2000

Number of Days to Update: 30

Source: State Water Resources Control Board

Telephone: 916-227-4448 Last EDR Contact: 01/28/2019

Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: No Update Planned

SWRCY: Recycler Database

A listing of recycling facilities in California.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/12/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 34

Source: Department of Conservation

Telephone: 916-323-3836 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing A listing of registered waste tire haulers.

Date of Government Version: 09/26/2018 Date Data Arrived at EDR: 09/28/2018 Date Made Active in Reports: 11/01/2018

Number of Days to Update: 34

Source: Integrated Waste Management Board

Telephone: 916-341-6422 Last EDR Contact: 02/12/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 12/03/2007 Date Made Active in Reports: 01/24/2008

Number of Days to Update: 52

Source: Environmental Protection Agency

Telephone: 703-308-8245 Last EDR Contact: 01/29/2019

Next Scheduled EDR Contact: 05/13/2019 Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 137

Source: EPA, Region 9 Telephone: 415-947-4219 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States

Date of Government Version: 04/01/2014 Date Data Arrived at EDR: 08/06/2014 Date Made Active in Reports: 01/29/2015 Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service Telephone: 301-443-1452

Last EDR Contact: 02/01/2019 Next Scheduled EDR Contact: 05/13/2019

Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 09/21/2018 Date Data Arrived at EDR: 09/21/2018 Date Made Active in Reports: 11/09/2018 Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 02/21/2019

Number of Days to Update: 49 Next Scheduled EDR Contact: 06/10/2019

Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005 Date Data Arrived at EDR: 08/03/2006 Date Made Active in Reports: 08/24/2006 Source: Department of Toxic Substance Control

Telephone: 916-323-3400 Last EDR Contact: 02/23/2009

Number of Days to Update: 21

Next Scheduled EDR Contact: 05/25/2009 Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 10/29/2018 Date Data Arrived at EDR: 10/30/2018 Date Made Active in Reports: 12/13/2018 Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 01/29/2019

Number of Days to Update: 44

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 06/12/2018 Date Made Active in Reports: 08/06/2018 Source: Department of Toxic Substances Control

Telephone: 916-255-6504 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 04/22/2019

Data Release Frequency: Varies

TOXIC PITS: Toxic Pits Cleanup Act Sites

Number of Days to Update: 55

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995 Date Data Arrived at EDR: 08/30/1995 Date Made Active in Reports: 09/26/1995 Source: State Water Resources Control Board

Telephone: 916-227-4364 Last EDR Contact: 01/26/2009

Number of Days to Update: 27

Next Scheduled EDR Contact: 04/27/2009 Data Release Frequency: No Update Planned

CERS HAZ WASTE: CERS HAZ WASTE

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 10/22/2018 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 38

Source: CalEPA Telephone: 916-323-2514 Last EDR Contact: 01/24/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/21/2018 Date Data Arrived at EDR: 09/21/2018 Date Made Active in Reports: 11/09/2018

Number of Days to Update: 49

Source: Drug Enforcement Administration Telephone: 202-307-1000

Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/10/2019 Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994 Date Data Arrived at EDR: 07/07/2005 Date Made Active in Reports: 08/11/2005

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: N/A

Last EDR Contact: 06/03/2005 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

UST MENDOCINO: Mendocino County UST Database

A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 12/04/2018 Date Data Arrived at EDR: 12/06/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 8

Source: Department of Public Health

Telephone: 707-463-4466 Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/10/2019 Data Release Frequency: Annually

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990 Date Data Arrived at EDR: 01/25/1991 Date Made Active in Reports: 02/12/1991

Number of Days to Update: 18

Source: State Water Resources Control Board

Telephone: 916-341-5851 Last EDR Contact: 07/26/2001 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing

Aboveground storage tank sites

Date of Government Version: 09/11/2018 Date Data Arrived at EDR: 09/12/2018 Date Made Active in Reports: 10/11/2018

Number of Days to Update: 29

Source: San Francisco County Department of Public Health

Telephone: 415-252-3896 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Varies

CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994 Date Data Arrived at EDR: 09/05/1995 Date Made Active in Reports: 09/29/1995

Number of Days to Update: 24

Source: California Environmental Protection Agency

Telephone: 916-341-5851 Last EDR Contact: 12/28/1998 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

CERS TANKS: California Environmental Reporting System (CERS) Tanks

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 10/22/2018 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 38

Source: California Environmental Protection Agency

Telephone: 916-323-2514 Last EDR Contact: 01/24/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Quarterly

Local Land Records

LIENS: Environmental Liens Listing

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 11/29/2018 Date Data Arrived at EDR: 12/04/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 38

Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 12/12/2018 Date Data Arrived at EDR: 12/28/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 14

Source: Environmental Protection Agency

Telephone: 202-564-6023 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 12/03/2018 Date Data Arrived at EDR: 12/05/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 37

Source: DTSC and SWRCB Telephone: 916-323-3400 Last EDR Contact: 12/05/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/26/2018 Date Data Arrived at EDR: 03/27/2018 Date Made Active in Reports: 06/08/2018

Number of Days to Update: 73

Source: U.S. Department of Transportation

Telephone: 202-366-4555 Last EDR Contact: 02/08/2019

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 04/06/2018 Date Data Arrived at EDR: 04/24/2018 Date Made Active in Reports: 06/14/2018

Number of Days to Update: 51

Source: Office of Emergency Services

Telephone: 916-845-8400 Last EDR Contact: 01/24/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)

Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Qualilty Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)

Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 02/22/2013

Number of Days to Update: 50

Source: FirstSearch Telephone: N/A

Last EDR Contact: 01/03/2013 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/01/2018 Date Data Arrived at EDR: 03/28/2018 Date Made Active in Reports: 06/22/2018

Number of Days to Update: 86

Source: Environmental Protection Agency

Telephone: (415) 495-8895 Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015 Date Data Arrived at EDR: 07/08/2015 Date Made Active in Reports: 10/13/2015

Number of Days to Update: 97

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 11/19/2018

Next Scheduled EDR Contact: 03/04/2019 Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Source: USGS

Telephone: 888-275-8747 Last EDR Contact: 01/11/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/06/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 339

Source: U.S. Geological Survey Telephone: 888-275-8747 Last EDR Contact: 01/11/2019

Next Scheduled EDR Contact: 04/22/2019

Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017 Date Data Arrived at EDR: 02/03/2017 Date Made Active in Reports: 04/07/2017

Number of Days to Update: 63

Source: Environmental Protection Agency

Telephone: 615-532-8599 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 08/31/2018 Date Data Arrived at EDR: 09/25/2018 Date Made Active in Reports: 11/09/2018

Number of Days to Update: 45

Source: Environmental Protection Agency

Telephone: 202-566-1917 Last EDR Contact: 02/04/2019

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013 Date Data Arrived at EDR: 03/21/2014 Date Made Active in Reports: 06/17/2014

Number of Days to Update: 88

Source: Environmental Protection Agency

Telephone: 617-520-3000 Last EDR Contact: 02/08/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017 Date Data Arrived at EDR: 05/08/2018 Date Made Active in Reports: 07/20/2018

Number of Days to Update: 73

Source: Environmental Protection Agency

Telephone: 703-308-4044 Last EDR Contact: 02/08/2019

Next Scheduled EDR Contact: 05/20/2019

Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016 Date Data Arrived at EDR: 06/21/2017 Date Made Active in Reports: 01/05/2018

Number of Days to Update: 198

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 12/21/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016 Date Data Arrived at EDR: 01/10/2018 Date Made Active in Reports: 01/12/2018

Number of Days to Update: 2

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 02/20/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 12/10/2010 Date Made Active in Reports: 02/25/2011

Number of Days to Update: 77

Source: EPA Telephone: 202-564-4203 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/12/2018 Date Data Arrived at EDR: 12/28/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 14

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 10/26/2018 Date Data Arrived at EDR: 11/06/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 66

Source: Environmental Protection Agency

Telephone: 202-564-8600 Last EDR Contact: 01/22/2019

Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 06/02/2008

Next Scheduled EDR Contact: 09/01/2008 Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 08/13/2018 Date Data Arrived at EDR: 10/04/2018 Date Made Active in Reports: 11/09/2018

Number of Days to Update: 36

Source: EPA

Telephone: 202-564-6023 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/14/2018 Date Data Arrived at EDR: 10/11/2018 Date Made Active in Reports: 12/07/2018

Number of Days to Update: 57

Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 01/11/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016 Date Data Arrived at EDR: 11/23/2016 Date Made Active in Reports: 02/10/2017

Number of Days to Update: 79

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 08/18/2017

Next Scheduled EDR Contact: 12/04/2017 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA

Telephone: 202-566-1667 Last EDR Contact: 08/18/2017

Next Scheduled EDR Contact: 12/04/2017 Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016 Date Data Arrived at EDR: 09/08/2016 Date Made Active in Reports: 10/21/2016

Number of Days to Update: 43

Source: Nuclear Regulatory Commission Telephone: 301-415-7169

Last EDR Contact: 01/22/2019 Next Scheduled EDR Contact: 05/06/2019

Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 08/07/2009 Date Made Active in Reports: 10/22/2009

Number of Days to Update: 76

Source: Department of Energy Telephone: 202-586-8719 Last EDR Contact: 12/05/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014 Date Data Arrived at EDR: 09/10/2014 Date Made Active in Reports: 10/20/2014

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: N/A

Last EDR Contact: 12/03/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017 Date Data Arrived at EDR: 11/30/2017 Date Made Active in Reports: 12/15/2017

Number of Days to Update: 15

Source: Environmental Protection Agency

Telephone: 202-566-0517 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 05/06/2019

Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/02/2018 Date Data Arrived at EDR: 10/03/2018 Date Made Active in Reports: 11/09/2018

Number of Days to Update: 37

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 01/03/2019

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2007

Next Scheduled EDR Contact: 03/17/2008

Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2008

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 10/01/2018 Date Data Arrived at EDR: 10/30/2018 Date Made Active in Reports: 01/18/2019

Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 01/29/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2018 Date Data Arrived at EDR: 10/12/2018 Date Made Active in Reports: 12/07/2018

Number of Days to Update: 56

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019

Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015 Date Data Arrived at EDR: 02/22/2017 Date Made Active in Reports: 09/28/2017

Number of Days to Update: 218

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014 Date Data Arrived at EDR: 07/14/2015 Date Made Active in Reports: 01/10/2017

Number of Days to Update: 546

Source: USGS

Telephone: 202-208-3710 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017 Date Data Arrived at EDR: 09/11/2018 Date Made Active in Reports: 09/14/2018

Number of Days to Update: 3

Source: Department of Energy Telephone: 202-586-3559 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017 Date Data Arrived at EDR: 10/11/2017 Date Made Active in Reports: 11/03/2017

Number of Days to Update: 23

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 12/14/2018

Next Scheduled EDR Contact: 03/04/2019 Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/12/2018 Date Data Arrived at EDR: 12/28/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 14

Source: Environmental Protection Agency

Telephone: 703-603-8787 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001 Date Data Arrived at EDR: 10/27/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 36

Source: American Journal of Public Health Telephone: 703-305-6451

Last EDR Contact: 12/02/2009 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016 Date Data Arrived at EDR: 10/26/2016 Date Made Active in Reports: 02/03/2017

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-2496 Last EDR Contact: 09/26/2017

Next Scheduled EDR Contact: 01/08/2018 Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data A listing of minor source facilities.

> Date of Government Version: 10/12/2016 Date Data Arrived at EDR: 10/26/2016 Date Made Active in Reports: 02/03/2017

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-2496 Last EDR Contact: 09/26/2017

Next Scheduled EDR Contact: 01/08/2018 Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2018 Date Data Arrived at EDR: 08/29/2018 Date Made Active in Reports: 10/05/2018

Number of Days to Update: 37

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 11/30/2018

Next Scheduled EDR Contact: 03/11/2019 Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005 Date Data Arrived at EDR: 02/29/2008 Date Made Active in Reports: 04/18/2008

Number of Days to Update: 49

Source: USGS

Telephone: 703-648-7709 Last EDR Contact: 11/30/2018

Next Scheduled EDR Contact: 03/11/2019 Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011 Date Data Arrived at EDR: 06/08/2011 Date Made Active in Reports: 09/13/2011

Number of Days to Update: 97

Source: USGS

Telephone: 703-648-7709 Last EDR Contact: 11/30/2018

Next Scheduled EDR Contact: 03/11/2019 Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/10/2018 Date Data Arrived at EDR: 09/11/2018 Date Made Active in Reports: 09/14/2018

Number of Days to Update: 3

Source: Department of Interior Telephone: 202-208-2609 Last EDR Contact: 12/19/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/15/2018 Date Data Arrived at EDR: 12/05/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 37

Source: EPA

Telephone: (415) 947-8000 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/02/2018 Date Data Arrived at EDR: 09/05/2018 Date Made Active in Reports: 09/14/2018

Number of Days to Update: 9

Source: Environmental Protection Agency

Telephone: 202-564-2280 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018 Date Data Arrived at EDR: 07/26/2018 Date Made Active in Reports: 10/05/2018

Number of Days to Update: 71

Source: Environmental Protection Agency

Telephone: 202-564-0527 Last EDR Contact: 11/30/2018

Next Scheduled EDR Contact: 03/11/2019 Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2017 Date Data Arrived at EDR: 06/19/2018 Date Made Active in Reports: 09/14/2018

Number of Days to Update: 87

Source: Department of Defense Telephone: 703-704-1564 Last EDR Contact: 01/14/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels

Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/22/2018 Date Data Arrived at EDR: 08/22/2018 Date Made Active in Reports: 10/05/2018

Number of Days to Update: 44

Source: EPA

Telephone: 800-385-6164 Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Quarterly

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of

Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989 Date Data Arrived at EDR: 07/27/1994 Date Made Active in Reports: 08/02/1994

Number of Days to Update: 6

Source: Department of Health Services

Telephone: 916-255-2118 Last EDR Contact: 05/31/1994 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List

The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste

Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 09/24/2018 Date Data Arrived at EDR: 09/25/2018 Date Made Active in Reports: 10/16/2018

Number of Days to Update: 21

Source: CAL EPA/Office of Emergency Information

Telephone: 916-323-3400 Last EDR Contact: 12/21/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

CUPA LIVERMORE-PLEASANTON: CUPA Facility Listing

list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 08/28/2018 Date Data Arrived at EDR: 08/30/2018 Date Made Active in Reports: 11/01/2018

Number of Days to Update: 63

Source: Livermore-Pleasanton Fire Department

Telephone: 925-454-2361 Last EDR Contact: 02/11/2019

Next Scheduled EDR Contact: 05/27/2019

Data Release Frequency: Varies

CUPA SAN FRANCISCO CO: CUPA Facility Listing

Cupa facilities

Date of Government Version: 09/11/2018 Date Data Arrived at EDR: 09/12/2018 Date Made Active in Reports: 09/19/2018

Number of Days to Update: 7

Source: San Francisco County Department of Environmental Health

Telephone: 415-252-3896 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Varies

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 11/13/2018 Date Data Arrived at EDR: 12/04/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 42

Source: Antelope Valley Air Quality Management District

Telephone: 661-723-8070 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Varies

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing

A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 10/04/2018 Date Data Arrived at EDR: 10/05/2018 Date Made Active in Reports: 11/01/2018

Number of Days to Update: 27

Source: South Coast Air Quality Management District

Telephone: 909-396-3211 Last EDR Contact: 02/07/2019

Next Scheduled EDR Contact: 06/10/2019 Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 08/30/2018 Date Data Arrived at EDR: 09/27/2018 Date Made Active in Reports: 11/01/2018

Number of Days to Update: 35

Source: Department of Toxic Substance Control

Telephone: 916-327-4498 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Annually

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 06/20/2018 Date Made Active in Reports: 08/06/2018

Number of Days to Update: 47

Source: California Air Resources Board

Telephone: 916-322-2990 Last EDR Contact: 12/21/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Varies

ENF: Enforcement Action Listing

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 11/01/2018 Date Data Arrived at EDR: 11/02/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 41

Source: State Water Resoruces Control Board

Telephone: 916-445-9379 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial Assurance information

Date of Government Version: 10/19/2018 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 38

Source: Department of Toxic Substances Control

Telephone: 916-255-3628 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 11/18/2018 Date Data Arrived at EDR: 11/19/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 53

Source: California Integrated Waste Management Board

Telephone: 916-341-6066 Last EDR Contact: 02/11/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 10/10/2018 Date Made Active in Reports: 11/16/2018

Number of Days to Update: 37

Source: California Environmental Protection Agency

Telephone: 916-255-1136 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Annually

ICE: ICE

Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 11/19/2018 Date Data Arrived at EDR: 11/19/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 53

Source: Department of Toxic Subsances Control

Telephone: 877-786-9427 Last EDR Contact: 02/20/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001 Date Data Arrived at EDR: 01/22/2009 Date Made Active in Reports: 04/08/2009

Number of Days to Update: 76

Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 01/22/2009 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 11/19/2018 Date Data Arrived at EDR: 11/19/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 53

Source: Department of Toxic Substances Control

Telephone: 916-323-3400 Last EDR Contact: 02/20/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 10/09/2018 Date Data Arrived at EDR: 10/10/2018 Date Made Active in Reports: 11/16/2018

Number of Days to Update: 37

Source: Department of Toxic Substances Control

Telephone: 916-440-7145 Last EDR Contact: 01/08/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Quarterly

MINES: Mines Site Location Listing

A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/12/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 34

Source: Department of Conservation Telephone: 916-322-1080

Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing

The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the

state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 11/09/2018 Date Data Arrived at EDR: 12/05/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 37

Source: Department of Public Health

Telephone: 916-558-1784 Last EDR Contact: 12/05/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Varies

NPDES: NPDES Permits Listing

A listing of NPDES permits, including stormwater.

Date of Government Version: 11/12/2018 Date Data Arrived at EDR: 11/14/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 29

Source: State Water Resources Control Board

Telephone: 916-445-9379 Last EDR Contact: 02/12/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing

A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 12/03/2018 Date Data Arrived at EDR: 12/05/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 37

Source: Department of Pesticide Regulation

Telephone: 916-445-4038 Last EDR Contact: 12/05/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Quarterly

PROC: Certified Processors Database A listing of certified processors.

Date of Government Version: 12/10/2018
Date Data Arrived at EDR: 12/12/2018
Date Made Active in Reports: 01/15/2019

Number of Days to Update: 34

Source: Department of Conservation

Telephone: 916-323-3836 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records

Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 09/19/2018 Date Data Arrived at EDR: 09/20/2018 Date Made Active in Reports: 10/19/2018

Number of Days to Update: 29

Source: State Water Resources Control Board

Telephone: 916-445-3846 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 04/01/2019
Data Release Frequency: No Update Planned

UIC: UIC Listing

A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 04/27/2018 Date Data Arrived at EDR: 06/13/2018 Date Made Active in Reports: 07/17/2018

Number of Days to Update: 34

Source: Deaprtment of Conservation

Telephone: 916-445-2408 Last EDR Contact: 01/25/2019

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)

Underground control injection sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resource Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing

Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 05/08/2018 Date Data Arrived at EDR: 07/11/2018 Date Made Active in Reports: 09/13/2018

Number of Days to Update: 64

Source: RWQCB, Central Valley Region

Telephone: 559-445-5577 Last EDR Contact: 01/11/2019

Next Scheduled EDR Contact: 04/22/2019

Data Release Frequency: Varies

WDS: Waste Discharge System

Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007 Date Data Arrived at EDR: 06/20/2007 Date Made Active in Reports: 06/29/2007

Number of Days to Update: 9

Source: State Water Resources Control Board

Telephone: 916-341-5227 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Quarterly

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)

Military privatized sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)

Projects sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing

In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/12/2018 Date Made Active in Reports: 01/18/2019

Number of Days to Update: 37

Source: State Water Resources Control Board

Telephone: 916-341-5810 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System

The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 12/03/2018
Date Data Arrived at EDR: 12/04/2018
Date Made Active in Reports: 01/11/2019

Number of Days to Update: 38

Source: State Water Resources Control Board

Telephone: 866-794-4977 Last EDR Contact: 12/04/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 10/22/2018 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 38

Source: California Environmental Protection Agency

Telephone: 916-323-2514 Last EDR Contact: 01/24/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

WIP: Well Investigation Program Case List

Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009 Date Data Arrived at EDR: 07/21/2009 Date Made Active in Reports: 08/03/2009

Number of Days to Update: 13

Source: Los Angeles Water Quality Control Board

Telephone: 213-576-6726 Last EDR Contact: 12/19/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)

Non-Case Information sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)

Other Oil & Gas Projects sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019

Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)

Produced water ponds sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)

Sampling point - public sites

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)

Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC

wells, water supply wells, etc?) being monitored

Date of Government Version: 12/10/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 35

Source: State Water Resources Control Board

Telephone: 866-480-1028 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019

Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A Number of Days to Update: N/A Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A Number of Days to Update: N/A Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc. Date Data Arrived at EDR: N/A Telephone: N/A Date Made Active in Reports: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A Number of Days to Update: N/A Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 01/13/2014

Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery

Telephone: N/A

Last EDR Contact: 06/01/2012 Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 12/30/2013

Number of Days to Update: 182

Source: State Water Resources Control Board

Telephone: N/A

Last EDR Contact: 06/01/2012 Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 10/05/2018 Date Data Arrived at EDR: 10/10/2018 Date Made Active in Reports: 11/01/2018

Number of Days to Update: 22

Source: Alameda County Environmental Health Services

Telephone: 510-567-6700 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 10/05/2018 Date Data Arrived at EDR: 10/10/2018 Date Made Active in Reports: 11/02/2018

Number of Days to Update: 23

Source: Alameda County Environmental Health Services

Telephone: 510-567-6700 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/24/2047 Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List

Cupa Facility List

Date of Government Version: 07/01/2018 Date Data Arrived at EDR: 07/24/2018 Date Made Active in Reports: 08/20/2018

Number of Days to Update: 27

Source: Amador County Environmental Health

Telephone: 209-223-6439 Last EDR Contact: 01/04/2019

Next Scheduled EDR Contact: 03/18/2019

Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing

Cupa facility list.

Date of Government Version: 04/21/2017 Date Data Arrived at EDR: 04/25/2017 Date Made Active in Reports: 08/09/2017

Number of Days to Update: 106

Source: Public Health Department Telephone: 530-538-7149 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing

Cupa Facility Listing

Date of Government Version: 10/31/2018 Date Data Arrived at EDR: 12/04/2018 Date Made Active in Reports: 12/12/2018

Number of Days to Update: 8

Source: Calveras County Environmental Health

Telephone: 209-754-6399 Last EDR Contact: 12/21/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List

Cupa facility list.

Date of Government Version: 05/23/2018 Date Data Arrived at EDR: 05/24/2018 Date Made Active in Reports: 07/13/2018

Number of Days to Update: 50

Source: Health & Human Services Telephone: 530-458-0396 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List

List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 11/26/2018 Date Data Arrived at EDR: 11/30/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 46

Source: Contra Costa Health Services Department

Telephone: 925-646-2286 Last EDR Contact: 01/28/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List

Cupa Facility list

Date of Government Version: 08/16/2018 Date Data Arrived at EDR: 11/06/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 8

Source: Del Norte County Environmental Health Division

Telephone: 707-465-0426 Last EDR Contact: 01/28/2019

Next Scheduled EDR Contact: 05/11/2019

Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List

CUPA facility list.

Date of Government Version: 12/13/2018 Date Data Arrived at EDR: 12/18/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 28

Source: El Dorado County Environmental Management Department

Telephone: 530-621-6623 Last EDR Contact: 01/28/2019

Next Scheduled EDR Contact: 05/11/2019

Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List

Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 10/16/2018 Date Data Arrived at EDR: 10/18/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 27

Source: Dept. of Community Health Telephone: 559-445-3271 Last EDR Contact: 12/26/2018

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Semi-Annually

GLENN COUNTY:

CUPA GLENN: CUPA Facility List

Cupa facility list

Date of Government Version: 01/22/2018 Date Data Arrived at EDR: 01/24/2018 Date Made Active in Reports: 03/14/2018

Number of Days to Update: 49

Source: Glenn County Air Pollution Control District

Telephone: 830-934-6500 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019

Data Release Frequency: Varies

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List

CUPA facility list.

Date of Government Version: 12/11/2018 Date Data Arrived at EDR: 12/13/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 33

Source: Humboldt County Environmental Health

Telephone: N/A

Last EDR Contact: 11/19/2018

Next Scheduled EDR Contact: 03/04/2019 Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List

Cupa facility list.

Date of Government Version: 10/22/2018 Date Data Arrived at EDR: 10/25/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 20

Source: San Diego Border Field Office

Telephone: 760-339-2777 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List

Cupa facility list.

Date of Government Version: 04/02/2018 Date Data Arrived at EDR: 04/03/2018 Date Made Active in Reports: 06/14/2018

Number of Days to Update: 72

Source: Inyo County Environmental Health Services

Telephone: 760-878-0238 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019

Data Release Frequency: Varies

KERN COUNTY:

UST KERN: Underground Storage Tank Sites & Tank Listing

Kern County Sites and Tanks Listing.

Date of Government Version: 11/02/2018 Date Data Arrived at EDR: 11/07/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 37

Source: Kern County Environment Health Services Department

Telephone: 661-862-8700 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List

A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 11/21/2018 Date Data Arrived at EDR: 11/27/2018 Date Made Active in Reports: 12/12/2018

Number of Days to Update: 15

Source: Kings County Department of Public Health

Telephone: 559-584-1411 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List

Cupa facility list

Date of Government Version: 11/07/2018 Date Data Arrived at EDR: 11/08/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 6

Source: Lake County Environmental Health

Telephone: 707-263-1164 Last EDR Contact: 01/14/2019

Next Scheduled EDR Contact: 04/29/2019

Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List

Cupa facility list

Date of Government Version: 10/15/2018 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 22

Source: Lassen County Environmental Health

Telephone: 530-251-8528 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former

Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009 Date Data Arrived at EDR: 03/31/2009 Date Made Active in Reports: 10/23/2009

Number of Days to Update: 206

Source: N/A Telephone: N/A

Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: No Update Planned

HMS LOS ANGELES: HMS: Street Number List

Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 09/20/2018 Date Data Arrived at EDR: 10/12/2018 Date Made Active in Reports: 11/16/2018

Number of Days to Update: 35

Source: Department of Public Works

Telephone: 626-458-3517 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities Solid Waste Facilities in Los Angeles County.

> Date of Government Version: 10/15/2018 Date Data Arrived at EDR: 10/16/2018 Date Made Active in Reports: 11/16/2018

Number of Days to Update: 31

Source: La County Department of Public Works

Telephone: 818-458-5185 Last EDR Contact: 01/15/2019

Next Scheduled EDR Contact: 04/29/2019

Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills

Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 01/01/2018 Date Data Arrived at EDR: 05/01/2018 Date Made Active in Reports: 05/14/2018

Number of Days to Update: 13

Source: Engineering & Construction Division

Telephone: 213-473-7869 Last EDR Contact: 01/15/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation List

Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 07/01/2018 Date Data Arrived at EDR: 10/16/2018 Date Made Active in Reports: 11/16/2018

Number of Days to Update: 31

Source: Community Health Services Telephone: 323-890-7806 Last EDR Contact: 02/01/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017 Date Data Arrived at EDR: 04/19/2017 Date Made Active in Reports: 05/10/2017

Number of Days to Update: 21

Source: City of El Segundo Fire Department

Telephone: 310-524-2236 Last EDR Contact: 01/14/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Semi-Annually

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 03/09/2017 Date Data Arrived at EDR: 03/10/2017 Date Made Active in Reports: 05/03/2017

Number of Days to Update: 54

Source: City of Long Beach Fire Department

Telephone: 562-570-2563 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Annually

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 10/02/2018 Date Data Arrived at EDR: 10/05/2018 Date Made Active in Reports: 11/02/2018

Number of Days to Update: 28

Source: City of Torrance Fire Department

Telephone: 310-618-2973 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List

A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 11/26/2018 Date Data Arrived at EDR: 11/27/2018 Date Made Active in Reports: 12/12/2018

Number of Days to Update: 15

Source: Madera County Environmental Health

Telephone: 559-675-7823 Last EDR Contact: 02/15/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites Currently permitted USTs in Marin County.

> Date of Government Version: 09/26/2018 Date Data Arrived at EDR: 10/04/2018 Date Made Active in Reports: 11/02/2018

Number of Days to Update: 29

Source: Public Works Department Waste Management

Telephone: 415-473-6647 Last EDR Contact: 01/14/2019

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Semi-Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List CUPA facility list.

Date of Government Version: 08/29/2018 Date Data Arrived at EDR: 08/31/2018 Date Made Active in Reports: 09/19/2018

Number of Days to Update: 19

Source: Merced County Environmental Health

Telephone: 209-381-1094 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List CUPA Facility List

> Date of Government Version: 12/07/2018 Date Data Arrived at EDR: 12/11/2018 Date Made Active in Reports: 01/24/2019

Number of Days to Update: 44

Source: Mono County Health Department

Telephone: 760-932-5580 Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/10/2019

Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing

CUPA Program listing from the Environmental Health Division.

Date of Government Version: 10/29/2018 Date Data Arrived at EDR: 11/01/2018 Date Made Active in Reports: 11/16/2018

Number of Days to Update: 15

Source: Monterey County Health Department

Telephone: 831-796-1297 Last EDR Contact: 12/27/2018

Next Scheduled EDR Contact: 04/15/2019

Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination

A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017 Date Data Arrived at EDR: 01/11/2017 Date Made Active in Reports: 03/02/2017

Number of Days to Update: 50

Source: Napa County Department of Environmental Management

Telephone: 707-253-4269 Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites Underground storage tank sites located in Napa county.

Date of Government Version: 11/28/2018 Date Data Arrived at EDR: 11/30/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 14

Source: Napa County Department of Environmental Management

Telephone: 707-253-4269 Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/10/2019 Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List

CUPA facility list.

Date of Government Version: 11/06/2018 Date Data Arrived at EDR: 11/08/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 6

Source: Community Development Agency

Telephone: 530-265-1467 Last EDR Contact: 01/28/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups

Petroleum and non-petroleum spills.

Date of Government Version: 10/04/2018 Date Data Arrived at EDR: 11/14/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 29

Source: Health Care Agency Telephone: 714-834-3446 Last EDR Contact: 02/04/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 10/04/2018 Date Data Arrived at EDR: 11/14/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 29

Source: Health Care Agency Telephone: 714-834-3446 Last EDR Contact: 02/04/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 10/04/2018 Date Data Arrived at EDR: 11/06/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 38

Source: Health Care Agency Telephone: 714-834-3446 Last EDR Contact: 02/05/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

PLACER COUNTY:

MS PLACER: Master List of Facilities

List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 11/29/2018 Date Data Arrived at EDR: 12/04/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 38

Source: Placer County Health and Human Services

Telephone: 530-745-2363 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List

Plumas County CUPA Program facilities.

Date of Government Version: 07/19/2018 Date Data Arrived at EDR: 07/25/2018 Date Made Active in Reports: 09/05/2018

Number of Days to Update: 42

Source: Plumas County Environmental Health

Telephone: 530-283-6355 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites

Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 10/10/2018 Date Data Arrived at EDR: 10/12/2018 Date Made Active in Reports: 10/16/2018

Number of Days to Update: 4

Source: Department of Environmental Health

Telephone: 951-358-5055 Last EDR Contact: 12/17/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List

Underground storage tank sites located in Riverside county.

Date of Government Version: 10/10/2018 Date Data Arrived at EDR: 10/12/2018 Date Made Active in Reports: 11/05/2018

Number of Days to Update: 24

Source: Department of Environmental Health

Telephone: 951-358-5055 Last EDR Contact: 12/17/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List

List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 08/03/2018 Date Data Arrived at EDR: 10/02/2018 Date Made Active in Reports: 11/01/2018

Number of Days to Update: 30

Source: Sacramento County Environmental Management

Telephone: 916-875-8406 Last EDR Contact: 01/04/2019

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List

Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks,

waste generators.

Date of Government Version: 08/23/2018 Date Data Arrived at EDR: 10/02/2018 Date Made Active in Reports: 11/02/2018

Number of Days to Update: 31

Source: Sacramento County Environmental Management

Telephone: 916-875-8406 Last EDR Contact: 12/28/2018

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List

Cupa facility list

Date of Government Version: 11/15/2018 Date Data Arrived at EDR: 11/16/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 27

Source: San Benito County Environmental Health

Telephone: N/A

Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits

This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 11/28/2018 Date Data Arrived at EDR: 11/30/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 42

Source: San Bernardino County Fire Department Hazardous Materials Division

Telephone: 909-387-3041 Last EDR Contact: 02/19/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 12/03/2018 Date Data Arrived at EDR: 12/05/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 37

Source: Hazardous Materials Management Division

Telephone: 619-338-2268 Last EDR Contact: 12/05/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities
San Diego County Solid Waste Facilities.

Date of Government Version: 04/18/2018 Date Data Arrived at EDR: 04/24/2018 Date Made Active in Reports: 06/19/2018

Number of Days to Update: 56

Source: Department of Health Services

Telephone: 619-338-2209 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing

A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 10/22/2018 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 38

Source: Department of Environmental Health

Telephone: 858-505-6874 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

SAN DIEGO CO. SAM: Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010 Date Data Arrived at EDR: 06/15/2010 Date Made Active in Reports: 07/09/2010

Number of Days to Update: 24

Source: San Diego County Department of Environmental Health

Telephone: 619-338-2371 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

LUST SAN FRANCISCO: Local Oversite Facilities

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008 Date Data Arrived at EDR: 09/19/2008 Date Made Active in Reports: 09/29/2008

Number of Days to Update: 10

Source: Department Of Public Health San Francisco County

Telephone: 415-252-3920 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

UST SAN FRANCISCO: Underground Storage Tank Information

Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/05/2018 Date Data Arrived at EDR: 11/06/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 38

Source: Department of Public Health Telephone: 415-252-3920 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST

A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018 Date Data Arrived at EDR: 06/26/2018 Date Made Active in Reports: 07/11/2018

Number of Days to Update: 15

Source: Environmental Health Department

Telephone: N/A

Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 04/01/2019 Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List Cupa Facility List.

> Date of Government Version: 11/14/2018 Date Data Arrived at EDR: 11/15/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 28

Source: San Luis Obispo County Public Health Department

Telephone: 805-781-5596 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory

List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 12/03/2018 Date Data Arrived at EDR: 12/12/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 34

Source: San Mateo County Environmental Health Services Division

Telephone: 650-363-1921 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List

A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 12/13/2018 Date Data Arrived at EDR: 12/18/2018 Date Made Active in Reports: 01/23/2019

Number of Days to Update: 36

Source: San Mateo County Environmental Health Services Division

Telephone: 650-363-1921 Last EDR Contact: 09/10/2018

Next Scheduled EDR Contact: 12/24/2018 Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing

CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011 Date Data Arrived at EDR: 09/09/2011 Date Made Active in Reports: 10/07/2011

Number of Days to Update: 28

Source: Santa Barbara County Public Health Department

Telephone: 805-686-8167 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019

Data Release Frequency: Varies

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List

Cupa facility list

Date of Government Version: 11/16/2018 Date Data Arrived at EDR: 11/16/2018 Date Made Active in Reports: 12/13/2018

Number of Days to Update: 27

Source: Department of Environmental Health

Telephone: 408-918-1973 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report

A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county.

Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005 Date Data Arrived at EDR: 03/30/2005 Date Made Active in Reports: 04/21/2005

Number of Days to Update: 22

Source: Santa Clara Valley Water District

Telephone: 408-265-2600 Last EDR Contact: 03/23/2009

Next Scheduled EDR Contact: 06/22/2009 Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing

A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014 Date Data Arrived at EDR: 03/05/2014 Date Made Active in Reports: 03/18/2014

Number of Days to Update: 13

Source: Department of Environmental Health

Telephone: 408-918-3417 Last EDR Contact: 02/21/2019

Next Scheduled EDR Contact: 06/10/2019 Data Release Frequency: Annually

SAN JOSE HAZMAT: Hazardous Material Facilities

Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 11/01/2018 Date Data Arrived at EDR: 11/06/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 38

Source: City of San Jose Fire Department

Telephone: 408-535-7694 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List

CUPA facility listing.

Date of Government Version: 01/21/2017 Date Data Arrived at EDR: 02/22/2017 Date Made Active in Reports: 05/23/2017

Number of Days to Update: 90

Source: Santa Cruz County Environmental Health

Telephone: 831-464-2761 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List

Cupa Facility List.

Date of Government Version: 06/15/2017 Date Data Arrived at EDR: 06/19/2017 Date Made Active in Reports: 08/09/2017

Number of Days to Update: 51

Source: Shasta County Department of Resource Management

Telephone: 530-225-5789 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks

A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 11/29/2018 Date Data Arrived at EDR: 12/04/2018 Date Made Active in Reports: 01/11/2019

Number of Days to Update: 38

Source: Solano County Department of Environmental Management

Telephone: 707-784-6770 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Quarterly

UST SOLANO: Underground Storage Tanks

Underground storage tank sites located in Solano county.

Date of Government Version: 11/29/2018 Date Data Arrived at EDR: 12/04/2018 Date Made Active in Reports: 12/14/2018

Number of Days to Update: 10

Source: Solano County Department of Environmental Management

Telephone: 707-784-6770 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List

Cupa Facility list

Date of Government Version: 12/21/2018 Date Data Arrived at EDR: 12/27/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 19

Source: County of Sonoma Fire & Emergency Services Department

Telephone: 707-565-1174 Last EDR Contact: 12/19/2018

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites

A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 10/02/2018 Date Data Arrived at EDR: 10/04/2018 Date Made Active in Reports: 10/25/2018

Number of Days to Update: 21

Source: Department of Health Services

Telephone: 707-565-6565 Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/08/2019 Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List

Cupa facility list

Date of Government Version: 12/11/2018 Date Data Arrived at EDR: 12/13/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 33

Source: Stanislaus County Department of Ennvironmental Protection

Telephone: 209-525-6751 Last EDR Contact: 12/13/2018

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks

Underground storage tank sites located in Sutter county.

Date of Government Version: 09/18/2018 Date Data Arrived at EDR: 09/20/2018 Date Made Active in Reports: 10/25/2018

Number of Days to Update: 35

Source: Sutter County Environmental Health Services

Telephone: 530-822-7500 Last EDR Contact: 11/29/2018

Next Scheduled EDR Contact: 03/18/2019 Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List

Cupa facilities

Date of Government Version: 12/13/2018 Date Data Arrived at EDR: 12/18/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 28

Source: Tehama County Department of Environmental Health

Telephone: 530-527-8020 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019 Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List

Cupa facility list

Date of Government Version: 10/22/2018 Date Data Arrived at EDR: 10/25/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 20

Source: Department of Toxic Substances Control

Telephone: 760-352-0381 Last EDR Contact: 01/17/2019

Next Scheduled EDR Contact: 05/06/2019

Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List Cupa program facilities

> Date of Government Version: 12/26/2018 Date Data Arrived at EDR: 12/27/2018 Date Made Active in Reports: 01/15/2019

Number of Days to Update: 19

Source: Tulare County Environmental Health Services Division

Telephone: 559-624-7400 Last EDR Contact: 01/31/2019

Next Scheduled EDR Contact: 05/20/2019

Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List

Cupa facility list

Date of Government Version: 04/23/2018 Date Data Arrived at EDR: 04/25/2018 Date Made Active in Reports: 06/25/2018

Number of Days to Update: 61

Source: Divison of Environmental Health

Telephone: 209-533-5633 Last EDR Contact: 02/13/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks

The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 09/26/2018 Date Data Arrived at EDR: 10/25/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 36

Source: Ventura County Environmental Health Division

Telephone: 805-654-2813 Last EDR Contact: 01/22/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites

Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011 Date Data Arrived at EDR: 12/01/2011 Date Made Active in Reports: 01/19/2012

Number of Days to Update: 49

Source: Environmental Health Division Telephone: 805-654-2813

Last EDR Contact: 12/26/2018

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Annually

LUST VENTURA: Listing of Underground Tank Cleanup Sites

Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008 Date Data Arrived at EDR: 06/24/2008 Date Made Active in Reports: 07/31/2008

Number of Days to Update: 37

Source: Environmental Health Division

Telephone: 805-654-2813 Last EDR Contact: 02/07/2019

Next Scheduled EDR Contact: 05/27/2019 Data Release Frequency: Quarterly

MED WASTE VENTURA: Medical Waste Program List

To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and

disposal of medical waste throughout the County.

Date of Government Version: 09/25/2018 Date Data Arrived at EDR: 10/25/2018 Date Made Active in Reports: 11/30/2018

Number of Days to Update: 36

Source: Ventura County Resource Management Agency

Telephone: 805-654-2813 Last EDR Contact: 01/22/2019

Next Scheduled EDR Contact: 05/06/2019 Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List

Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 11/26/2018 Date Data Arrived at EDR: 12/12/2018 Date Made Active in Reports: 01/16/2019

Number of Days to Update: 35

Source: Environmental Health Division

Telephone: 805-654-2813 Last EDR Contact: 12/12/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report Underground storage tank sites located in Yolo county.

Date of Government Version: 12/26/2018 Date Data Arrived at EDR: 01/03/2019 Date Made Active in Reports: 01/16/2019

Number of Days to Update: 13

Source: Yolo County Department of Health

Telephone: 530-666-8646 Last EDR Contact: 12/26/2018

Next Scheduled EDR Contact: 04/15/2019 Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List

CUPA facility listing for Yuba County.

Date of Government Version: 11/05/2018 Date Data Arrived at EDR: 11/07/2018 Date Made Active in Reports: 11/14/2018

Number of Days to Update: 7

Source: Yuba County Environmental Health Department

Telephone: 530-749-7523 Last EDR Contact: 01/28/2019

Next Scheduled EDR Contact: 05/11/2019

Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/12/2018 Date Data Arrived at EDR: 11/14/2018 Date Made Active in Reports: 12/04/2018

Number of Days to Update: 20

Telephone: 860-424-3375 Last EDR Contact: 02/12/2019

Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: No Update Planned

Source: Department of Energy & Environmental Protection

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 07/13/2018 Date Made Active in Reports: 08/01/2018

Number of Days to Update: 19

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 01/07/2019

Next Scheduled EDR Contact: 04/22/2019 Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

lacility

Date of Government Version: 01/01/2019 Date Data Arrived at EDR: 01/30/2019 Date Made Active in Reports: 02/14/2019

Number of Days to Update: 15

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 01/30/2019

Next Scheduled EDR Contact: 05/11/2019 Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 10/23/2018 Date Made Active in Reports: 11/27/2018

Number of Days to Update: 35

Source: Department of Environmental Protection

Telephone: 717-783-8990 Last EDR Contact: 01/11/2019

Next Scheduled EDR Contact: 04/29/2019 Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 02/23/2018 Date Made Active in Reports: 04/09/2018

Number of Days to Update: 45

Source: Department of Environmental Management

Telephone: 401-222-2797 Last EDR Contact: 02/19/2019

Next Scheduled EDR Contact: 06/03/2019 Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2017 Date Data Arrived at EDR: 06/15/2018 Date Made Active in Reports: 07/09/2018

Number of Days to Update: 24

Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 12/07/2018

Next Scheduled EDR Contact: 03/25/2019 Data Release Frequency: Annually

Oil/Gas Pipelines

Source: PennWell Corporation

Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data

Source: PennWell Corporation

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities Source: Department of Social Services

Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory Source: Department of Fish and Wildlife

Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK®-PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

260 N. MONTGOMERY STREET 260 N. MONTGOMERY STREET SAN JOSE, CA 95110

TARGET PROPERTY COORDINATES

Latitude (North): 37.335085 - 37° 20' 6.31" Longitude (West): 121.902651 - 121° 54' 9.54"

Universal Tranverse Mercator: Zone 10 UTM X (Meters): 597211.6 UTM Y (Meters): 4132406.0

Elevation: 84 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map: 5640416 SAN JOSE WEST, CA

Version Date: 2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property FEMA Source Type

06085C0234H FEMA FIRM Flood data

Additional Panels in search area: FEMA Source Type

06085C0231H FEMA FIRM Flood data 06085C0232H FEMA FIRM Flood data 06085C0233H FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Electronic

NWI Quad at Target Property

Data Coverage

SAN JOSE WEST YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles
Location Relative to TP: 0 - 1/8 Mile North

Site Name: Fmc Corp San Jose Ordnance Plt

Site EPA ID Number: CAD009146952

Surficial Aquifer Flow Dir.: NE. THIS FLOW APPLIES TO THE "A" AQUIFER THAT IS PRESENT AT 15 FEET TO

30 FEET DEEP.

Measured Depth to Water: 15 feet.

Hydraulic Connection: A silty and clay aquitard separates the "A" and "B" aquifers. A

separate aquitard underlies the "B" aquifer.

Sole Source Aquifer: No information about a sole source aquifer is available
Data Quality: Information based on site-specific subsurface investigations is

documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

LOCATION GENERAL DIRECTION

MAP ID FROM TP GROUNDWATER FLOW

Not Reported

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

GEOLOGIC AGE IDENTIFICATION

Era: Cenozoic Category: Stratifed Sequence

System: Quaternary Series: Quaternary

Code: Q (decoded above as Era, System & Series)

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: BOTELLA
Soil Surface Texture: clay loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep,

moderately well and well drained soils with moderately coarse

textures.

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: MODERATE

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

Soil Layer Information							
Boundary			Classification				
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	9 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 7.30 Min: 5.60
2	9 inches	41 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 7.80 Min: 5.60
3	41 inches	76 inches	sandy clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 0.60 Min: 0.20	Max: 7.80 Min: 5.60

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: No Other Soil Types

Surficial Soil Types: No Other Soil Types

Shallow Soil Types: No Other Soil Types

Deeper Soil Types: No Other Soil Types

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE SEARCH DISTANCE (miles)

Federal USGS 1.000

Federal FRDS PWS Nearest PWS within 0.001 miles

State Database 1.000

FEDERAL USGS WELL INFORMATION

MAP ID WELL ID EROM TP

8 USGS40000182252 1/4 - 1/2 Mile SE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID WELL ID FROM TP


No PWS System Found

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
	7678	1/8 - 1/4 Mile SE
A2	7679	1/8 - 1/4 Mile SE
A3	7652	1/8 - 1/4 Mile SE
A4	6829	1/8 - 1/4 Mile SE
A5	6823	1/8 - 1/4 Mile SE
A6	7650	1/8 - 1/4 Mile SE
A7	7649	1/8 - 1/4 Mile SE
B9	7743	1/2 - 1 Mile West
B10	7744	1/2 - 1 Mile West

PHYSICAL SETTING SOURCE MAP - 05569778.2r



SITE NAME: 260 N. MONTGOMERY STREET ADDRESS: 260 N. MONTGOMERY STREET

SAN JOSE CA 95110 LAT/LONG: 37.335085 / 121.902651 CLIENT: Engeo Inc. CONTACT: DIVYA BHARGAVA

INQUIRY#: 05569778.2r

DATE: February 22, 2019 11:44 am

Map ID Direction Distance

Elevation Database EDR ID Number

CA WELLS 7678

1/8 - 1/4 Mile Higher

> Seq: 7678 Prim sta c: 07S/01E-18A01 M

Frds no: 4310011064 County: 43 District: User id: HEN 05 System no: 4310011 Water type:

Source nam: MAIN STATION-R - STANDBY Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY

Latitude: 372000.0 Longitude: 1215400.0 Precision: Status: SU 4 Not Reported Not Reported Comment 1: Comment 2: Comment 3: Not Reported Comment 4: Not Reported Comment 5: Not Reported Comment 6: Not Reported

Not Reported Comment 7:

System no: 4310011 System nam: San Jose Water Company Hqname: Not Reported Address: 1221 S. Bascom Avenue

City: San Jose State: CA

Zip: 95128 Zip ext: Not Reported Connection: 206890 Pop serv: 944000

Area serve: SAN JOSE VICINITY

SE **CA WELLS** 7679

1/8 - 1/4 Mile Higher

Comment 7:

07S/01E-18A02 M 7679 Seq: Prim sta c:

4310011041 County: Frds no: 43 District: 05 User id: HEN System no: 4310011 Water type:

DELMAS WELL 02 - STANDBY Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY Source nam:

Latitude: 372000.0 Longitude: 1215400.0 Precision: Status: SU 8 Comment 1: Not Reported Comment 2: Not Reported Comment 3: Not Reported Comment 4: Not Reported Not Reported Not Reported Comment 5: Comment 6:

System no: 4310011 System nam: San Jose Water Company

Hqname: Not Reported Address: 1221 S. Bascom Avenue City: San Jose State: CA

Not Reported Zip: 95128 Zip ext: 206890 Pop serv: 944000 Connection:

Area serve: SAN JOSE VICINITY

Not Reported

CA WELLS 7652

1/8 - 1/4 Mile Higher

> 7652 Prim sta c: 07S/01E-07R08 M Seq:

Frds no: 4310011066 County: 43 District: 05 User id: HEN 4310011 Water type: System no: G

Source nam: MAIN STATION-T Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY

372000.0 1215400.0 Latitude: Longitude: Precision: Status: ΑU

Comment 1: Not Reported Comment 2: Not Reported Not Reported Comment 3: Comment 4: Not Reported Comment 5: Not Reported Comment 6: Not Reported

Comment 7: Not Reported

System no: 4310011 System nam: San Jose Water Company Not Reported Address: 1221 S. Bascom Avenue Hqname:

San Jose State: City: CA

Not Reported Zip: 95128 Zip ext: 944000 Connection: 206890 Pop serv:

Area serve: SAN JOSE VICINITY

CA WELLS 6829

1/8 - 1/4 Mile Higher

> 6829 Prim sta c: 06S/01E-17G06 M Seq:

Frds no: 4310011049 County: 43 District: 05 User id: HEN System no: Water type: 4310011

Source nam: FLEURY WELL 03 - STANDBY Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY

Latitude: 372000.0 Longitude: 1215400.0 Precision: Status: SU

Not Reported Not Reported Comment 1: Comment 2: Comment 3: Not Reported Comment 4: Not Reported Comment 5: Not Reported Comment 6: Not Reported

Not Reported Comment 7:

System no: 4310011 System nam: San Jose Water Company Address: 1221 S. Bascom Avenue Hqname: Not Reported

City: San Jose State: CA

Zip: 95128 Zip ext: Not Reported Pop serv: 944000 Connection: 206890 SAN JOSE VICINITY

A5 SE **CA WELLS** 6823

1/8 - 1/4 Mile Higher

Area serve:

Seq: 6823 Prim sta c: 06S/01E-16K03 M

4310011035 Frds no: County: 43 District: HEN 05 User id: Water type: System no: 4310011

Source nam: CROPLEY WELL 01 - STANDBY Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY

372000.0 1215400.0 Latitude: Longitude: Precision: 5 Status: SR

Comment 1: Not Reported Comment 2: Not Reported Comment 3: Not Reported Comment 4: Not Reported Comment 5: Not Reported Comment 6: Not Reported Comment 7: Not Reported

System no: 4310011 System nam: San Jose Water Company Hqname: Not Reported Address: 1221 S. Bascom Avenue

City: San Jose State: CA

95128 Not Reported Zip: Zip ext: Pop serv: 944000 Connection: 206890

Area serve: SAN JOSE VICINITY

A6 SE CA WELLS 7650

1/8 - 1/4 Mile Higher

Seq: 7650 Prim sta c: 07S/01E-07R04 M

 Frds no:
 4310011063
 County:
 43

 District:
 05
 User id:
 HEN

 System no:
 4310011
 Water type:
 G

Source nam: MAIN STATION-P Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY

Latitude: 372000.0 Longitude: 1215400.0 Precision: Status: ΑU Comment 1: Not Reported Comment 2: Not Reported Comment 3: Not Reported Comment 4: Not Reported Not Reported Not Reported Comment 5: Comment 6:

Comment 7: Not Reported

System no: 4310011 System nam: San Jose Water Company Hqname: Not Reported Address: 1221 S. Bascom Avenue

City: San Jose State: CA

 Zip:
 95128
 Zip ext:
 Not Reported

 Pop serv:
 944000
 Connection:
 206890

Area serve: SAN JOSE VICINITY

A7 SE CA WELLS 7649

1/8 - 1/4 Mile Higher

Seq: 7649 Prim sta c: 07S/01E-07R02 M

 Frds no:
 4310011062
 County:
 43

 District:
 05
 User id:
 HEN

 System no:
 4310011
 Water type:
 G

Source nam: MAIN STATION-M - INACTIVE Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY

Latitude: 372000.0 Longitude: 1215400.0 Status: Precision: Comment 1: Not Reported Comment 2: Not Reported Not Reported Not Reported Comment 3: Comment 4: Not Reported Not Reported Comment 5: Comment 6:

System no: 4310011 System nam: San Jose Water Company Hqname: Not Reported Address: 1221 S. Bascom Avenue

City: San Jose State: CA

 Zip:
 95128
 Zip ext:
 Not Reported

 Pop serv:
 944000
 Connection:
 206890

Area serve: SAN JOSE VICINITY

Not Reported

8 SE FED USGS USGS40000182252

1/4 - 1/2 Mile Higher

Comment 7:

Organization ID: USGS-CA

Organization Name: USGS California Water Science Center

Monitor Location: 007S001E07R004M Type: Well

Description: Not Reported HUC: Not Reported

Drainage Area: Not Reported Drainage Area Units: Not Reported Contrib Drainage Area: Not Reported Contrib Drainage Area Unts: Not Reported

Aquifer: California Coastal Basin aquifers

Formation Type: Aquifer Type: Not Reported Not Reported Construction Date: Well Depth: Not Reported 800

Well Hole Depth: Well Depth Units:

Not Reported Not Reported Well Hole Depth Units:

В9 West **CA WELLS** 7743 1/2 - 1 Mile

Higher

DIr:

07S/01W-13E02 M Seq: 7743 Prim sta c:

4310011002 Frds no: County: 43 District: User id: HEN 05 Water type: System no: 4310011 G

BASCOM WELL 03 WELL/AMBNT/MUN/INTAKE/SUPPLY Source nam: Station ty:

Latitude: 372000.0 Longitude: 1215500.0 Precision: Status: ΑU

Comment 1: Not Reported Comment 2: Not Reported Not Reported Not Reported Comment 3: Comment 4: Comment 5: Not Reported Comment 6: Not Reported

Comment 7: Not Reported

System no: 4310011 San Jose Water Company System nam: Hqname: Not Reported Address: 1221 S. Bascom Avenue

City: San Jose State: CA

95128 Zip ext: Not Reported Zip: Pop serv: 944000 Connection: 206890

SAN JOSE VICINITY Area serve:

Sample date: 17-JAN-18 Finding: 1.6

TOTAL ORGANIC CARBON (TOC) Chemical: Report units: MG/L DIr:

0.3

Sample date: 09-JAN-18 Finding: 1.1 NITRATE (AS N) Chemical: Report units: MG/L

DIr: 0.4

Sample date: 12-JAN-17 Finding: COLOR **UNITS** Chemical: Report units:

12-JAN-17 Sample date: Finding: 2.8 Chemical: NITRATE (AS N) Report units: MG/L

DIr: 0.4

Sample date: 12-JAN-17 Finding: 4.2 Chemical: NITRATE (AS N) Report units: MG/L

DIr: 0.4

Sample date: 12-JAN-17 Finding: 0.97

Chemical: NITRATE + NITRITE (AS N) Report units: MG/L DIr: 0.4

Sample date: 12-JAN-17 Finding: 10.62

AGGRSSIVE INDEX (CORROSIVITY) Chemical: Report units: Not Reported DIr: 0.

Sample date: Chemical: Dlr:	12-JAN-17 TURBIDITY, LABORATORY 0.1	Finding: Report units:	0.5 NTU
Sample date: Chemical: Dlr:	12-JAN-17 CARBON DIOXIDE 0.	Finding: Report units:	120. UG/L
Sample date: Chemical: Dlr:	12-JAN-17 TOTAL DISSOLVED SOLIDS 0.	Finding: Report units:	340. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 FLUORIDE (F) (NATURAL-SOURCE) 0.1	Finding: Report units:	0.14 MG/L
Sample date: Chemical: Dlr:	12-JAN-17 SULFATE 0.5	Finding: Report units:	42. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 CHLORIDE 0.	Finding: Report units:	42. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 POTASSIUM 0.	Finding: Report units:	1.2 MG/L
Sample date: Chemical: Dlr:	12-JAN-17 SODIUM 0.	Finding: Report units:	19. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 MAGNESIUM 0.	Finding: Report units:	17. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 CALCIUM 0.	Finding: Report units:	50. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 HARDNESS (TOTAL) AS CACO3 0.	Finding: Report units:	196. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 NITRATE (AS N) 0.4	Finding: Report units:	0.97 MG/L
Sample date: Chemical: Dlr:	12-JAN-17 BICARBONATE ALKALINITY 0.	Finding: Report units:	170. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 ALKALINITY (TOTAL) AS CACO3 0.	Finding: Report units:	140. MG/L
Sample date: Chemical: Dlr:	12-JAN-17 PH, LABORATORY 0.	Finding: Report units:	6.38 Not Reported
Sample date: Chemical:	12-JAN-17 SPECIFIC CONDUCTANCE	Finding: Report units:	450. US

Dlr: 0.

Sample date: 10-JUN-16 Finding: 2.9 CHROMIUM, HEXAVALENT Chemical: Report units: UG/L

DIr:

Sample date: 02-FEB-16 Finding: 0.99 Chemical: NITRATE (AS N) Report units: MG/L

DIr: 0.4

Sample date: 04-FEB-15 Finding: 4.1 Chemical: NITRATE (AS NO3) Report units: MG/L

DIr:

Sample date: 04-FEB-14 330. Finding:

TOTAL DISSOLVED SOLIDS Chemical: Report units: MG/L DIr:

04-FEB-14 7.05 Sample date: Finding:

PH, LABORATORY Chemical: Report units: Not Reported

DIr:

04-FEB-14 Sample date: Finding: 140.

ALKALINITY (TOTAL) AS CACO3 Chemical: Report units: MG/L

DIr:

04-FEB-14 900. Sample date: Finding:

Chemical: NITRATE + NITRITE (AS N) Report units: MG/L DIr: 0.4

Sample date: 04-FEB-14 Finding: 11.27

Chemical: AGGRSSIVE INDEX (CORROSIVITY) Report units: Not Reported

DIr:

Sample date: 04-FEB-14 Finding: 0.16

TURBIDITY, LABORATORY Chemical: Report units: NTU

DIr: 0.1

04-FEB-14 Finding: 32000. Sample date: Chemical: **CARBON DIOXIDE** Report units: UG/L

DIr:

Sample date: 04-FEB-14 Finding: 4.

Report units: MG/L Chemical: NITRATE (AS NO3) DIr:

04-FEB-14 Sample date: Finding: 460.

SPECIFIC CONDUCTANCE Chemical: Report units: US

DIr:

Sample date: 04-FEB-14 Finding: 43. Chemical: SULFATE Report units: MG/L DIr: 0.5

Sample date: 04-FEB-14 Finding: 38.

Chemical: **CHLORIDE** Report units: MG/L DIr: 0.

Sample date: 04-FEB-14 Finding: 1.3

Report units: Chemical: **POTASSIUM** MG/L 0. DIr:

04-FEB-14 20. Sample date: Finding: Chemical: SODIUM Report units: MG/L

DIr:

04-FEB-14 Sample date: Finding: 16. Chemical: **MAGNESIUM** Report units: MG/L

DIr:

Sample date: 04-FEB-14 Finding: 48. CALCIUM Chemical: Report units: MG/L

DIr:

Sample date: 04-FEB-14 Finding: 187.

Chemical: HARDNESS (TOTAL) AS CACO3 Report units: MG/L

DIr:

04-FEB-14 Sample date: Finding: 170.

BICARBONATE ALKALINITY Chemical: Report units: MG/L

DIr:

Sample date: 05-FEB-13 3.9 Finding:

Chemical: NITRATE (AS NO3) Report units: MG/L

DIr:

Finding: Sample date: 09-JAN-13 2.6

Chemical: CHROMIUM, HEXAVALENT Report units: UG/L

DIr:

Sample date: 06-FEB-12 Finding: 4.

Chemical: NITRATE (AS NO3) Report units: MG/L

DIr:

B10 West 1/2 - 1 Mile **CA WELLS** 7744

Higher 07S/01W-13E03 M Seq: 7744 Prim sta c:

Frds no: 4310011003 County: 43 District: 05 User id: HEN System no: 4310011 Water type: G

BASCOM WELL 04 Station ty: WELL/AMBNT/MUN/INTAKE/SUPPLY Source nam:

372000.0 Longitude: Latitude: 1215500.0 Precision: Status: ΑU

Comment 1: Not Reported Comment 2: Not Reported Not Reported Comment 4: Not Reported Comment 3:

Not Reported Comment 6: Not Reported Comment 5: Not Reported Comment 7:

4310011 San Jose Water Company System no: System nam: Hqname: Not Reported Address: 1221 S. Bascom Avenue

City: San Jose State: CA

95128 Zip ext: Not Reported Zip: Pop serv: 944000 Connection: 206890

SAN JOSE VICINITY Area serve:

Sample date: 09-JAN-18 1.5 Finding: Chemical: NITRATE (AS N) Report units: MG/L

DIr: 0.4

Sample date: 29-NOV-17 Finding: 1.2

GROSS ALPHA MDA95 PCI/L Chemical: Report units:

DIr:

29-NOV-17 Sample date: Finding: 0.893 GROSS ALPHA COUNTING ERROR Chemical: Report units: PCI/L

DIr:

Sample date: 10-MAY-17 Finding: 6.28

PH, LABORATORY Chemical: Report units: Not Reported

DIr:

Sample date: 10-MAY-17 Finding: 1.25

Chemical: **GROSS ALPHA MDA95** Report units: PCI/L

DIr:

10-MAY-17 Sample date: Finding: 1.09

Chemical: **GROSS ALPHA COUNTING ERROR** Report units: PCI/L DIr: 0.

Sample date: 10-MAY-17 Finding: 1.5 Chemical: NITRATE + NITRITE (AS N) Report units: MG/L

DIr: 0.4

Sample date: 10-MAY-17 Finding: 10.75

Chemical: AGGRSSIVE INDEX (CORROSIVITY) Report units: Not Reported

DIr:

Sample date: 10-MAY-17 Finding: 1.3 Chemical: Report units: NTU

TURBIDITY, LABORATORY DIr: 0.1

Sample date: 10-MAY-17 Finding: 200.

Chemical: CARBON DIOXIDE Report units: UG/L

Dlr: 0.

Sample date: 10-MAY-17 Finding: 350.

TOTAL DISSOLVED SOLIDS Chemical: Report units: MG/L

DIr: 0.

Sample date: 10-MAY-17 Finding: 3.7

Chemical: CHROMIUM, HEXAVALENT Report units: UG/L DIr:

10-MAY-17 40. Sample date: Finding: Chemical: **SULFATE** Report units: MG/L

0.5

Sample date: 10-MAY-17 Finding: 36.

CHLORIDE Report units: Chemical: MG/L DIr:

Sample date: 10-MAY-17 Finding: 1.3

Chemical: **POTASSIUM** Report units: MG/L DIr:

10-MAY-17 Sample date: Finding: 17.

Chemical: SODIUM Report units: MG/L DIr: 0.

Sample date: 10-MAY-17 Finding: 22.

Chemical: MAGNESIUM Report units: MG/L DIr: 0.

Sample date: Chemical: Dlr:	10-MAY-17 CALCIUM 0.	Finding: Report units:	51. MG/L
Sample date: Chemical: Dlr:	10-MAY-17 HARDNESS (TOTAL) AS CACO3 0.	Finding: Report units:	217. MG/L
Sample date: Chemical: Dlr:	10-MAY-17 NITRATE (AS N) 0.4	Finding: Report units:	1.5 MG/L
Sample date: Chemical: Dlr:	10-MAY-17 BICARBONATE ALKALINITY 0.	Finding: Report units:	230. MG/L
Sample date: Chemical: Dlr:	10-MAY-17 ALKALINITY (TOTAL) AS CACO3 0.	Finding: Report units:	180. MG/L
Sample date: Chemical: Dlr:	10-MAY-17 SPECIFIC CONDUCTANCE 0.	Finding: Report units:	510. US
Sample date: Chemical: Dlr:	10-MAY-17 COLOR 0.	Finding: Report units:	6. UNITS
Sample date: Chemical: Dlr:	10-JUN-16 CHROMIUM, HEXAVALENT 1.	Finding: Report units:	3.6 UG/L
Sample date: Chemical: Dlr:	11-JAN-16 NITRATE (AS N) 0.4	Finding: Report units:	1.8 MG/L
Sample date: Chemical: Dlr:	08-JAN-15 NITRATE (AS NO3) 2.	Finding: Report units:	7.1 MG/L
Sample date: Chemical: Dlr:	06-AUG-14 SPECIFIC CONDUCTANCE 0.	Finding: Report units:	480. US
Sample date: Chemical: Dlr:	06-AUG-14 NITRATE (AS NO3) 2.	Finding: Report units:	5.3 MG/L
Sample date: Chemical: Dlr:	06-AUG-14 ALKALINITY (TOTAL) AS CACO3 0.	Finding: Report units:	150. MG/L
Sample date: Chemical: Dlr:	06-AUG-14 BICARBONATE ALKALINITY 0.	Finding: Report units:	180. MG/L
Sample date: Chemical: Dlr:	06-AUG-14 HARDNESS (TOTAL) AS CACO3 0.	Finding: Report units:	208. MG/L
Sample date: Chemical:	06-AUG-14 NITRATE + NITRITE (AS N)	Finding: Report units:	1200. MG/L

DIr: 0.4

Sample date: 06-AUG-14 Finding: 11.54
Chemical: AGGRSSIVE INDEX (CORROSIVITY) Report units: Not Reported

Dlr: 0

Sample date: 06-AUG-14 Finding: 17000. Chemical: CARBON DIOXIDE Report units: UG/L

Dlr: 0.

Sample date: 06-AUG-14 Finding: 7.25

Chemical: PH, LABORATORY Report units: Not Reported

Dlr: 0.

Sample date: 06-AUG-14 Finding: 310.

Chemical: TOTAL DISSOLVED SOLIDS Report units: MG/L DIr: 0.

Sample date: 06-AUG-14 Finding: 45.

Chemical: SULFATE Report units: MG/L Dlr: 0.5

Sample date: 06-AUG-14 Finding: 36.

Chemical: CHLORIDE Report units: MG/L DIr: 0.

Sample date: 06-AUG-14 Finding: 1.3

Chemical: POTASSIUM Report units: MG/L DIr: 0.

Sample date: 06-AUG-14 Finding: 21.

Chemical: SODIUM Report units: MG/L DIr: 0.

Sample date: 06-AUG-14 Finding: 19.

Sample date: 06-AUG-14 Finding: 19.
Chemical: MAGNESIUM Report units: MG/L
DIr: 0.

Sample date: 06-AUG-14 Finding: 53.

Chemical: CALCIUM Report units: MG/L DIr: 0.

Sample date: 07-JAN-14 Finding: 6.

Chemical: NITRATE (AS NO3) Report units: MG/L DIr: 2.

Sample date: 09-JAN-13 Finding: 6.3
Chemical: NITRATE (AS NO3) Report units: MG/L

Chemical: NTRATE (AS NO3) Report units: MG/L
DIr: 2.

Sample date: 09-JAN-13 Finding: 3.9

Chemical: CHROMIUM, HEXAVALENT Report units: UG/L DIr: 1.

Sample date: 09-JAN-12 Finding: 6.7

Chemical: NITRATE (AS NO3) Report units: MG/L DIr: 2.

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
		
95110	4	0

Federal EPA Radon Zone for SANTA CLARA County: 2

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SANTA CLARA COUNTY, CA

Number of sites tested: 70

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L	
Living Area - 1st Floor	1.363 pCi/L	91%	9%	0%	
Living Area - 2nd Floor	2.100 pCi/L	100%	0%	0%	
Basement	2.300 pCi/L	100%	0%	0%	

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory Source: Department of Fish and Wildlife

Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Database

Source: Department of Water Resources

Telephone: 916-651-9648

California Drinking Water Quality Database Source: Department of Public Health

Telephone: 916-324-2319

The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

OTHER STATE DATABASE INFORMATION

California Oil and Gas Well Locations Source: Department of Conservation

Telephone: 916-323-1779

Oil and Gas well locations in the state.

California Earthquake Fault Lines

Source: California Division of Mines and Geology

The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon

Source: Department of Public Health

Telephone: 916-210-8558 Radon Database for California

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency

(USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at

private sources such as universities and research institutions.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

EPA Radon Zones Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor

radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

